

#### HISTORIC PRESERVATION COMMISSION

Mark Elrich
County Executive

William Kirwan

Date: February 21, 2020

#### **MEMORANDUM**

TO: Diane Schwartz Jones

Department of Permitting Services

FROM: Dan Bruechert

**Historic Preservation Section** 

Maryland-National Capital Park & Planning Commission Historic Area Work Permit: 846182: Building Additions

SUBJECT: Historic Area Work Permit: 846182: Building Additions

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **Approved** at the October 24, 2018 Historic Preservation Commission meeting with revised plans approved at the September 11, 2019 HPC meeting and the February 12, 2020 HPC meeting.

The HPC staff has reviewed and stamped the attached revised construction drawings.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HAWP CONDITIONS AND MAY REQUIRE APPROVAL BY DPS OR ANOTHER LOCAL OFFICE BEFORE WORK CAN BEGIN.

Applicant: David O'Neil and Laura Billings Address: 5904 Cedar Parkway, Chevy Chase

This HAWP approval is subject to the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made. Once work is complete the applicant will contact Dan Bruechert at 301.563.3408 or dan.bruechert@montgomeryplanning.org to schedule a follow-up site visit.



# JONES & BOER ARCHITEC

APPROVED

Montgomery County

**Historic Preservation Commission** 

22 January 2020

### **Billings O'Neil Residence HAWP Revision 2**

Sandrad. Kkiler

We request approval to replace the following existing window

### REVIEWED

By Dan.Bruechert at 9:58 am, Feb 21, 2020

#### Sunroom 1<sup>st</sup> Floor – East and South Elevations

We have evidence that this room was originally a porch. The wood floor has been removed and there is clay tile on concrete with a step-down from the dining room (photo 4). This clay tile matches the tile on the front terrace. The walls beneath the windows are stone, matching the stone on the exterior of the house (photo 3, 4, 5). There are windows and French doors between this room and the dining room indicating it was originally a porch. Therefore, we do not believe these windows are original.

The existing windows in this room have deteriorated to the point that they do not operate. They cannot be repaired. We propose to replace these windows with custom units sized to fit the existing jamb openings.

#### Study 2<sup>nd</sup> Floor – East, South and West Elevations

We have evidence that this room was added at a later date. All of the framing in this room is newer than that in the rest of the house, evidenced by a clear difference in color (photo 6, 7). The steel windows do not match the other windows in the house (photo 8, 9).

The existing steel windows are in disrepair, have been modified in places and do not operate. We propose to replace these with wood framed windows with similar pattern.

#### Dining Room 1st Floor – East Elevation

The original approved plans call for replacing the center sash. However, after further inspection, the two flanking sashes are rotted and will not close fully (photo 10). We propose to replace this window with a custom unit to match the existing details and frame dimensions.

#### Living Room 1st Floor - North Elevation


This window is rotted and will not operate (photo 11). We propose to replace with a custom unit to fit the opening and match the details of the Living Room window on the east elevation.


#### Bedroom 1 on 2<sup>nd</sup> Floor – North Elevation


This window is rotted and will not operate (photo 12). We propose to replace with an operable window to match.

#### Bath 3 on 3<sup>rd</sup> Floor – North Elevation

This window is rotted and cannot open without failing (photo 13). We propose to replace with an operable window to match.







APPROVED **Montgomery County** Historic Preservation Commission

Sandrad. Kkiler

# **REVIEWED**

By Dan.Bruechert at 9:59 am, Feb 21, 2020



APPROVED


**Montgomery County** 

**Historic Preservation Commission** 









## WINDOW SCHEDULE

SYM.	FRAME SIZE (WXH) U.N.O.	TYPE	MANUF. #	REMARKS	
(A)	(3) $2'-3\frac{1}{2}"\pm \times 5'-2"\pm (SASH)$	PTD. WD. CASEMENT	MASTER'S	CUSTOM WINDOW TO FIT EXIST'G	
	·		WOODSHOP	OPENING, MATCH EXIST. DETAILS	
P	4'-6"± X 5'-2"± (SASH)	PTD. WD. CASEMENT	MASTER'S	CUSTOM WINDOW TO FIT EXIST'G	
			WOODSHOP	OPENING, MATCH EXIST. DETAILS	
(Q)	5'-5"± X 4'-7"± (SASH)	PTD. WD. CASEMENT	CUSTOM	CUSTOM WIN. TO FIT EXIST'G. OPENIN	G
R	1'-6"± X 4'-0"± (SASH)	PTD. WD. CASEMENT	CUSTOM	CUSTOM WIN. TO FIT EXIST'G. OPENIN	G
(SI)	$9'-1\frac{1}{2}" \times 5'-0\frac{1}{2}" $ (SASH)	PTD. WD. CASEMENT	MASTER'S	CUSTOM WINDOW TO FIT EXIST'G	
			WOODSHOP	OPENING, MATCH EXIST. DETAILS	
<b>(52)</b>	$1'-7" \times 5'-0\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	п	II .	
(53)	$8'-3" \times 5'-0^{1}_{2}" (SASH)$	PTD. WD. CASEMENT	II	ĮI	
<b>(54)</b>	$1'-7" \times 5'-0\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	II	ĮI	
<b>S4</b>	$1'-7" \times 5'-0^{\frac{1}{2}}" (SASH)$	PTD. WD. CASEMENT	II	II.	
<b>(55)</b>	$3'-2" \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. FRENCH CASEMENT	CUSTOM	CUSTOM WIN. TO FIT EXIST'G. OPENIN	G
<b>(56)</b>	$1'-6\frac{7}{8}" \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	II	п	
<b>(57</b> )	$3'-2" \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. FRENCH CASEMENT	II	п	
<b>(58)</b>	$1'-7"\pm \times 3'-11\frac{1}{2}"$ (SASH)	PTD. WD. CASEMENT	II	II	
<b>(59)</b>	$3'-2\frac{1}{2}" \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	II	п	
(510)	$1'-7"\pm \times 3'-11\frac{1}{2}"$ (SASH)	PTD. WD. CASEMENT	II	"	
(SII)	$3'-2\frac{1}{2}" \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	II	II	
<b>(512)</b>	$1'-7"\pm \times 3'-11\frac{1}{2}"$ (SASH)	PTD. WD. CASEMENT	II	II	
(513)	$1'-6\frac{3}{8}" \pm \times 3'-11\frac{1}{2}" (SASH)$	PTD. WD. CASEMENT	П	II.	His

MASTER'S WOODSHOP OR LEPAGE CUSTOM, SIZED TO FIT OPENINGS

#### NOTES.

- MANUFACTURER #S LISTED ARE LEPAGE U.N.O.
- SEE ELEVATIONS FOR MUNTIN PATTERNS
- PROVIDE SAFETY GLASS WHERE REQUIRED BY CODE
- ALL FENESTRATION TO HAVE MAX. U-FACTOR = 0.35, MAX SHGC = 0.40
- MUNTIN PROFILE \$ WIDTH TO MATCH EXISTING 5/8"
- SEE PLANS & ELEVATIONS FOR FIXED WINDOW LOCATIONS
- ALL FENESTRATION WILL BE CERTIFIED AND LABELED IN ACCORDANCE WITH NFRC
- CUSTOM REPLACEMENT WINDOWS BY THE MASTER'S WOODSHOP TO MATCH STILE AND RAIL DIMENSIONS AND MUNTIN BAR WIDTHS AND PROFILES OF EXISTING WINDOWS.
- DIMENSIONS FOR WINDOWS TO FIT EXISTING OPENINGS ALL EXISTING OPENINGS TO BE VERIFIED IN THE FIELD.

APPROVED

Montgomery County


**Historic Preservation Commission** 

Sandral. Kkiler

### **REVIEWED**

By Dan.Bruechert at 9:59 am, Feb 21, 2020

BILLINGS-O'NEIL RESIDENCE REPLACEMENT WINDOW SCHEDULE JONES & BOER ARCHITECTS



 $\frac{1}{2}$ " = 1'-0"