S417 MOHICAN ROAD, BETHESDA MASTER PLAN SITE * 35/29-2 R.A. CHARLES CASTLE 2nd PRELIMINARY CONSULTATION

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION **STAFF REPORT**

Address: 5417 Mohican Road, Bethesda Meeting Date: 7/10/13

Applicant:

Ross McNair

Report Date:

7/3/13

Resource:

Master Plan Site #35/29-2, R.A. Charles Castle

Public Notice: 6/26/13

Review:

Preliminary Consultation

Tax Credit:

Partial

Case Number: N/A

Staff:

Josh Silver

PROPOSAL: Construction of rear addition, enclosure of front porch, construction of new carport and

other alterations

STAFF RECOMMENDATION

The HPC must determine if design option A or B is more compatible with the resource and provide the applicant with feedback on items (1-5) below:

- 1. Construction of a two-story rear addition
- 2. Materials treatments and details for the addition
- 3. Enclosure of front porch and left (north) elevation tower entrance
- 4. Construction of a two-bay carport in the rear yard
- 5. Installation of cobblestone court entryway at the rear of the property.

PROPERTY DESCRIPTION

SIGNIFICANCE:

Master Plan Site #35/29-2, R.A. Charles Castle

STYLE:

Eclectic

DATE:

1890

ARCHITECTURAL HISTORY

The following was excerpted from Places from the Past: The Tradition of Gardez Bien in Montgomery County, Maryland.

This residence was built the same year as the more elaborate and larger scale Baltzley Castle, (located on the adjacent property), yet was also built of locally quarried stone, continuing the theme of the envisioned Rhineland on the Potomac. Both residences were built to take advantage of a dramatic view of the Potomac River. With its multi- and diamond-pane windows, hipped roof polygonal wing, and turned porch posts, the Charles Castle is essentially a Queen Anne style house sheathed in stone. R.A. Charles, an employee of the Treasury Department, bought land from Edward Baltzley in February 1890 and built the house soon thereafter. The Manufacturer's Record of 1891 stated that Mindeleff designed a Glen Echo Heights house for Edwin Baltzley for \$7,000.

ARCHITECTURAL DESCRIPTION

The subject property is a three bay by one bay, two and half story stone "castle" that faces south (west), and much smaller than the adjacent Baltzley Castle at 5415 Mohican Road.

Constructed of bluestone, the house has a two story screened porch with a flat roof at the southeast corner



of the south elevation. The enclosed second level is supported by three columns at the first level.

There is a screen porch on the north elevation that wraps around to the west elevation. Six columns support the half-hipped porch roof. A two story tower is located at the northwest corner of the west elevation with a conical roof.

There are 1/1, double-hung windows with stone lintels, and a variety of multi-paned transom or upper sashes above single light lower sashes. The south elevation has a hipped dormer window. The house has a hipped roof with red slate covering. There are two interior chimneys with corbelled caps.

BACKGROUND

The HPC held a preliminary consultation hearing on January 23, 2013 where they considered a proposal for construction of a rear addition and new garage, roof replacement, construction of a side porch roof and enclosure, demolition, and rehabilitation and infill construction at the right (south) elevation.

The HPC offered the following comments in response to the applicant's proposal:

- The existing open porch at the front-right corner of the primary façade is a character-defining feature. Construction of new roof over the open porch and its enclosure with glass would have an adverse impact to this character-defining feature. Enclosure of an existing covered porch at the front elevation was encouraged to create additional habitable space.
- The proposed rear elevation (both options A & B), read to primary in nature and included a prominent entrance that detracted from recognizing the building's primary entrance located in the left elevation tower section.
- The scale and massing of the proposed addition was found to be incompatible with the historic massing. Recommendations for reducing the scale and massing included, construction of a one or two story addition at the rear with hyphen connector, elimination of the staircase tower, justification of the addition toward the proposed garage, and simplification of materials and details (e.g., more contemporary building elements and glazing).
- The proposed garage location and design could be approved if submitted as a HAWP.
- The proposed removal of the non-historic screen porch element, enclosure of the lower-level and rehabilitation of the 2nd story, flared, shingle feature could be approved if submitted as a HAWP.
- The preservation of existing trees within the vicinity of the existing resource and proposed addition was encouraged. The further examination of trees and potential impacts of new construction was recommended to determine site limitations for construction of an addition, garage and parking court area. [The full HPC meeting transcript begins on page _____]

PROPOSAL

In response the HPC comments at the 1st preliminary consultation, the applicant is again providing two different design options (A and B). The proposal remains relatively unchanged in terms of the applicant's intentions for constructing an addition, adding a parking feature and creating additional habitable living space. The revised design includes more detail and floor plans to help the HPC better understand the interior program and how these spaces relate to one another.

Notable changes from the 1st preliminary consultation include the following:

The applicant has withdrawn their proposal to replace the roof on the historic massing, add a new porch roof with glass enclosure below at the front-right elevation, and construct a one story, two bay garage in

right-rear corner of the property.

The revised proposal includes the following:

Rear addition:

• Construct a two-story, (18' 10" x 20'), addition at the rear of the existing structure. The addition will connect to the primary structure via a glass and metal hyphen (12' x 8'). The proposed materials include a combination of flat roof stone and painted steel beams for the exterior, cooper seamed roofing and casement and fixed window sashes.

Front porch roof replacement and enclosure:

• Remove and replace a non-original asphalt roof with a seamed copper roof. Enclose the existing front porch by adding full view, fixed, reflective glass. The original wooden porch columns and stone piers will be preserved. A porch glazing detail can be found on page _______ of the staff report packet.

Right (south) elevation alterations:

• Remove a non-historic (c.1980s), one-story, shed roof screen porch extension. The existing wooden shingled, 2nd story flared massing with steep sloped roof will be preserved, new windows added, and the 1st story below (which currently is a screened porch) will be infilled to create a habitable interior space. The proposed infill is based on physical structural evidence on the interior and maintains the original porch footprint.

Construction of two car detached carport and cobblestone entry court:

• Construct a one-story, two-car, 24' x 24', detached, carport at the rear, right corner of the lot. The carport location is consistent with the garage the HPC reviewed and supported at the 1st preliminary consultation. The location complies with the county's setback requirements for accessory structures. Materials for the carport consist of a seamed copper roof and metal structural framing and posts consistent with the materials and details proposed for the addition section. A cobblestone entry court set in bluestone is proposed at the rear of the addition and in front of the proposed carport. The carport will be accessed via an existing driveway from Mohican Road.

Other alterations:

- Reset all loose stone work and repoint all mortar joints (No HAWP required)
- Rebuild front porch stone walls, remove and replace floor and roof framing, install new porch ceiling board, remove, strip and reinstall the existing wooden columns (No HAWP required)
- Strip, reglaze, and paint all existing wooden windows. Replace sash weights and chain as needed. Replace broken glass and rehabilitate existing window sashes, framing and trim as needed using salvaged lumber. (No HAWP required).

The HPC is encouraged to provide the applicant with feedback on both options A & B.

APPLICABLE GUIDELINES

When reviewing alterations and new construction to a Master Plan site several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A-8:

(a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.



- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
- (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any one period or architectural style.
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation:

Standard #1: A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces and spatial relationships.

Standard #9: New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.

Standard #10: New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

Two story rear addition

Staff finds that the applicant's revised proposal (both design options A & B), responds to the HPC's feedback at the 1st preliminary consultation hearing. The proposed addition, located entirely at the rear and connected to the primary structure by a glazed hyphen does not substantially alter historic features that are important to defining the character of the site. The massing and scale of the addition, lower, inset and smaller are compatible in character with the primary resource. The use of metal structural features,

extensive glazing and stone both complement and express differentiation between the addition and primary

structure.

In response to the HPC's feedback, the applicant investigated locating an addition further toward the right rear of the property (toward the proposed carport location). Due to the presence of 40" White Oak tree, locating an addition in this location is not possible without impacting the tree, which the applicant would like to preserve. Staff supports the location as proposed finding it responds to HPC's feedback and is in keeping with the guidance found in <u>The Design Guidelines for Historic Sites and Districts in Montgomery County, Maryland</u>, which recommend:

18.3 An addition should be compatible in scale with the primary structure.

- An addition should relate to the historic house in mass, scale and form. Is should be designed to remain subordinate to the main structure.
- One option to help visually separate an addition from the primary building is to link the primary structure with a smaller breezeway.
- For a larger addition, break up the mass of the addition into smaller modules that relate to the historic house.
- An addition should be simple in design to prevent it from competing with the primary structure.

The applicant has not specified a window and door material for the proposed addition. Staff recommends a metal frame or clad windows for all new window locations throughout the addition.

Porch roof replacement and enclosure of existing front porch

Staff finds the replacement of the existing front porch roof with a copper roof as being consistent with Chapter 24A-8 (b) (1) & (2). The existing porch roof is not original to the house and therefore the proposal does not substantially alter an original exterior material. The use of a copper standing seam roofing material is compatible in character with the resource type and style. The HPC supported the applicant's proposal to remove and replace the porch roof with red slate at the 1st preliminary consultation.

Staff finds enclosure of the existing front porch with fixed glass as being consistent with Standards # 1, 9 and 10 above. The proposal requires minimal change to distinctive materials and features and does not destroy historic materials that characterize the property, and if removed in the future, the essential form and integrity of the property would be unimpaired. The proposal involves installing glass in front of the existing wooden porch columns that are original to the structure. The design preserves the porch columns and requires minimal impact to the stone piers which the column bases engage at the bottom. The porch roof form will not be impacted and the changes are reversible if removed in the future.


Staff supports enclosing the arched entry way with full-light, outward swinging, metal frame doors with transom above at the left (north) elevation entry. Staff finds this alteration as having minimal impact to the resource and as being reversible [Standards #1, 9 and 10]. The applicant is proposing this alteration to increase the habitable area of the proposed front porch glass enclosure.

Right (south) elevation alterations

Staff supports the removal of the non-historic porch, infill below and rehabilitation of the 2nd story. The applicant has based construction of the infill location on physical structural evidence on the interior. The proposal maintains the original porch footprint. The HPC supported this part of the proposal when it was reviewed at the 1st preliminary consultation, which involved a similar plan.

Construction of two bay detached carport

Staff supports the proposed construction of a two bay detached carport set off the rear and right side property lines. The proposed size and location is consistent with the garage which the HPC supported at the 1st preliminary consultation.





Staff supports the proposed installation of a cobblestone entry court as shown on the plans. The applicant is working closely with a landscape architect and arborist and verbally stated to HPC staff the proposal as shown will not impact the trees.

Other alterations:

Staff supports the proposed maintenance and rehabilitation projects identified in the proposal section. The applicant is encouraged to apply for a county historic perseveration tax credit for eligible expenses associated with the project.

STAFF RECOMMENDATIONS

The HPC must determine if design option A or B is more compatible with the resource and provide the applicant with feedback on items (1-5) below.

- 1. Construction of a two-story rear addition
- 2. Materials treatments and details for the addition.
- 3. Enclosure of front porch and left (north) elevation tower entrance
- 4. Construction of a two-bay carport in the rear yard
- 5. Installation of cobblestone court entryway at the rear of the property.

Staff recommends that the applicants make revisions to the plans based on comments and feedback from the HPC and staff and return for a Historic Area Work Permit.

DP8-#8



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

_	Y	255 M	unair100	annin um	Contact Person: VD55 V	nchau
Co	ntact Email:	<u> </u>	evilla 1.1 & C	Alvace.com	Daytime Phone No.: 361	219-0380
Tax	Ascount No.:	0509	312		<u></u>	•
			mcnai	5-	_ Osytime Phone No.: 301 6	119-0380
24	me 5415	Mal	ilan 12d	Bethes	ila moi c	20816
						Ze Cade
	tractorn:				Phone Ne.:	
Cor	tractor Registration A	Vo.:				
	ent for Owner:				Daytime Phone No.:	
r Te	ATION OF BUILDS	10.2.5			·····	
_					Marchail Com	0 4
					Monican	
					maccorthur	
					cho Highes	Se i Uin 1
Libi	r. <u>40753</u>	_Folio:	45 Parcel	·		
殏	TONE TYPE	PER TAS	TOWARDUSE		•	······································
	CHECK ALL APPLICA			CHECK ALL	VPPLICABLE:	
	Construct C		Altar/Renovate	X AC C	Slab 7 Room Addition	전 Porch 口 Deck 口 Shed
	• •	install	☐ Wreck/Raza	•	Fireplace	•
•		3 Repair	Revocable.		nell (complete Section 4) Dother	
	Construction cost or	•	_ noocean.	C results	en (muchano socialis) C. com	· quality
		•		can Darmin di		
16.	II UES IS & I EVIDION C	a breviously	approved active permit,	300 F G I I II F	_ · .	
PΑ	ALLANDS CONTRA	TERO, IN	A CONSTRUCTION V	MD Strick Walling	NS	
ZA.	Type of sewage dis	sposak	01 🗹 WSSC	02 🖾 Septic	03 🖸 Other:	
28.	Type of water supp	ły:	01 🖼 WSSC	02 🗇 Well	03 🖸 Other:	
8 8	O WILLIAM CONTROL	EVENIEV)	ON THE PARTAMEN	EWAIT	'	
				a HALL		L.
	Height					
38.	Indicate whether th	ne fence or re	taining wall is to be cons	tructed an one of the fo	lowing locations:	
	() On party line/pro	oparty line	☐ Entirely on I	and of owner	On public right of way/easemen	•
_	nhe corite that I have	e the system	is to make the foressine	application that the ar	plication is correct, and that the cons	musica will samaly with store
					ndition for the issuance of this permit	
	10		_		١.,	
_	W/ /C	020	Work	Du		56-15
	Sig	nature of own	er or authorized egent		,	Dete
Δρρ	oved:			For Chairpe	rson, Historic Preservation Commissio	n
)isa	pproved:		Signature: 🚤		e e Cumi	•
			CARLO		11/2/1/10	·

SEE REVERSE SIDE FOR INSTRUCTIONS



(dete

	•	i, action is the second of the
1.	Name: R.A. Charles' Castle	
~5.	Planning Area/Site Number: 35/29/2	3. M-NCPPC Atlas Reference: Map 20 Coordinate J-15
4.	Address: 5417 Mohican Road Glen Echo Heights	. Coolumate to 19
5.	Classification Summary	
•	Category building Ownership private Public Acquisition N/A Status occupied	Previous Survey Recording MNCPPC Title and Date: Historic Sites Inventory 1976
	Accessible <u>no</u> Present use <u>private residence</u>	Federal State x County x Local
6.	Date: 1890 7. Orig	inal Owner: R.A. Charles
8.	Apparent Condition	
	a. good b. altered	c. original site
9.	Description: This three bay by one ces south, and is smaller than #5415	bay, two and a half story stone "castle"
а	Constructed of bluestone, the house flat roof at the southeast corner of	se has a two story screened porch with the south elevation. The enclosed second
le	vel is supported by three columns at There is a screened porch on the	the first level. north elevation that wraps around to the
we	st elevation. Six columns support the	ne half-hipped porch roof. A two story er of the west elevation with a conical
ro	of.	
Th	riety of multi-paned transoms or uppe e south elevation has a hipped dormer	y windows with stone lintels, and a er sashes above single light lower sashes. I window. The house has a hipped roof interior chimneys with corbelled caps.
Cre Bal Cha Wel of in The	eate a Washington "Rhineland of the latzley bought 516 acres of land in 18 autauqua, and sold lots for a planned re to be of brick, stone or metal, but fering stone delivered at quarry cost 1890 and was the second of two "cast	g is a reminder of a grandiose scheme to Potomac". Twin brothers Edwin and Edward 388, built the Glen Echo National development across the street. Houses at the use of granite was encouraged by this house was built for R.A. Charles cles" built in the planned development. Its one and was probably intended as a
rur	A disastrous fire at the Glen Echo mors of malarial mosquitoes, put an a	Cafe in November, 1890, coupled with brupt end not only to the Glen Echo
	utauqua, but also to the Baltzleys' r The Charles family owned this hous rchased the "castle" in 1962, and ren	le for many years. The present owners
P 4.3	- Canada Che Canada In 1902, and Tel	ic ic out.
•	•	
	•	
.1.	Can Researcher and date researched: Car	dy Reed/Architectural Description
.2. (Compiler: Peg Coleman 13, Dat	e Compiled: 6/79 14. Designation
	15. Acr	eage: 54,572 sq. ft.

ĻĻ

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING

11/26/2012

OWNER'S MAILING ADDRESS

HISTORIC SITE ADDRESS

J. Ross McNair 5415 Mohican Rd Bethesda Md 20816

5417 Mohican Rd Bethesda Md 20816

ADJACENT AND CONFRONTING PROPERTY OWNERS MAILING ADDRESSES

Miguel Otero 5301 Mohican Rd Bethesda MD 20816 Chris White 5409 Mohican Rd Bethesda MD 20816

Maureen Jeffreys and Michael Bergsman

5303 Mohican Rd Bethesda MD 20816 Miklos Gaal 5407 Mohican Rd Bethesda MD 20816

Matthew Byrne 5405 Mohican Rd Bethesda MD 20816 Stephen Seeber 5309 Mohican Rd Bethesda MD 20816

William Barlow 5311 Mohican Rd Bethesda MD 20816

Patrick Gates 5421 Mohican Rd Bethesda MD 20816

Ned Miltenberg 5410 Mohican Rd Bethesda MD 20816 John Lentz 5424 Mohican Rd Bethesda MD 20816


Joy Brown 5408 Mohican Rd Bethesda MD 20816 Whittington Lewis 5404 Mohican Rd Bethesda MD 20816

Nathaniel Kendall 5420 Mohican Rd Bethesda MD 20816 William Coolidge 5423 Mohican Rd Bethesda MD 20816

James Ross 5425 Mohican Rd Bethesda MD 20816 Philip Warker 5428 Mohican Rd Bethesda MD 20816








tymd.gov/ims/mcgmaps/viewer.htm

5/28/2011



2nd Preliminary Consultation Options A & B




Pollock Dickerson Associates, PC PDA 5640 Nicholson Lane Suite 300 Rockville, Maryland 20852 Tel 301.237.7542 Basement Plan Scale: 3/16"= 1-0" Architect: Existing Bass Loundry/ Utility Mechanical Area


McNair Residence


13 June 2013 **B.100**


Menair
Residence
Owner:
Ross Methair
Sats Mohitean Road
Baltheada, MD 20816
Countent tawar:
Rovisad Historic
Submitteal
Revisad Historic
Submitteal
Revision Historic
Submitteal
Revision Historic
Submitteal
Revision 1000
Receiving Manyland 20852
To 1301.2377.542
Consultants: TBD


Protessional Conflication:
Receiving Manyland 20852
To 1301.2377.542
Consultants: TBD



















PDA. 5840 Nicholson Lane Suite 300 Rockville, Maryland 20852 Tel 301.237.7542

Architect:


Note; Metal Roofs on Extering Pourth Roof


Consultants: TBD


Pollock Dickerson Associates, PC


Ross McNair 5415 Mohican Road Belhasda, MD 20816 Curent taxo: Revised Historic Submittal


McNair Residence














1st Preliminary Consultation Option A



































1st Preliminary Consultation Option B






Boale: 3/16"= 1:0"

McNair Residence





McNair
Residence
owner:
Ress Montain Read
dien Echo, MD 20816
ouner two:
Prelim Hetoric
Resultates
Resultates
Resultates New Entry Room (Strtp Oak Floor) Entry Court (Pee Gravel)












Owner:
6415 Mohten Road
Gen Echo, MD 20016
Carret Bus:
Prubin Helecto

McNair Residence


















McNair Cottage Existing Condition Photo 3- East Side




McNair Cottage Existing Condition Photo 4-View of Existing Drive and Storage Bldg




McNair Cottage Existing Condition Photo 5-North and West Sides









McNair Cottage Existing Condition Photo 8-West Side View @ Porch



THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION PRELIMINARY CONSULTATIONS -5417 Mohican Road 7500 Carroll Avenue A meeting in the above-entitled matters was held on January 23, 2013, commencing at 7:34 p.m., in the MRO

COMMITTEE MEMBERS

Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland

Leslie Miles, Chair William Kirwan, Vice Chair Sandra Heiler Paul Treseder Joe Coratola M=Lisa Whitney Craig Swift Max van Balgooy

Deposition Services, Inc.

12321 Middlebrook Road, Suite 210 Germantown, MD 20874 Tel: (301) 881-3344 Fax: (301) 881-3338 info@DepositionServices.com www.DepositionServices.com



20910, before:

23

24

25

ALSO PRESENT:

Scott Whipple

Karen Theimer Brown

Joshua Silver

STATEMENT OF:

Staff Items

APPEARANCES

PAGE

None

	
Ross McNair	16
Erik Leibmann	64
·	
TABLE OF CONTENTS	
HISTORIC AREA WORK PERMITS	PAGE
Case A	4
Case B	4
Case C	4
PRELIMINARY CONSULTATION	
Case A	Postponed
Case A Case B	Postponed 5
·	_
Case B	5
Case B Case C	5
Case B Case C MINUTES	5 58
Case B Case C MINUTES December 5, 2012	5 58 81
Case B Case C MINUTES December 5, 2012 December 19, 2012	5 58 81
Case B Case C MINUTES December 5, 2012 December 19, 2012 OTHER BUSINESS	5 58 81 81

PROCEEDINGS

MS. MILES: Good evening. Welcome to the January 23rd, 2013, despite what it says on your agenda, meeting of the Montgomery County Historic Preservation Commission. My name is Leslie Miles. I'm the Chair. I'm going to ask all the members of the Commission and staff to introduce themselves starting at my left end.

MR. VAN BALGOOY: Max van Balgooy, Rockville.

MR. SWIFT: Craig Swift from Rockville.

MR. TRESEDER: Paul Treseder from Bethesda.

MR. KIRWAN: Bill Kirwan, Silver Spring.

MS. WHITNEY: M'Lisa Whitney, Burtonsville.

MR. CORATOLA: Joe Coratola, Gaithersburg.

MS. HEILER: Sandra Heiler, Brookeville.

MR. WHIPPLE: Scott Whipple, Historic Preservation Staff.

MS. THEIMER BROWN: Karen Theimer Brown, Historic Preservation Staff.

MR. SILVER: Joshua Silver, Historic Preservation Staff.

MS. MILES: Thank you, and welcome to Karen. Thi is her first meeting with us. We're going to begin with those matters that we believe can be handled on an expeditious basis. Have these Historic Area Work Permits been duly advertised?

They were advertised in the MR. SILVER: Yes. 1 2 January 9th, 2013 edition of the Washington Examiner. 3 MS. MILES: Thank you. If you are here in opposition to any of these HAWPs, please do indicate. 4 anyone here in opposition to the permit for 3904 Washington Street in Kensington, for 5 Newlands Street in Chevy Chase, 6 or for 222 Park Avenue in Takoma Park? MR. KIRWAN: Madame Chair, hearing none, I move 8 9 that we approve the following Historic Area Work Permits in 10 accordance with the staff reports, based upon the record 11 before us, and in consideration of the recommendations of the Local Advisory Panels, when those have been provided, 12 HPC Case No. 36/02-13B at 3904 Washington Street in 13 Kensington; HPC Case No. 35/13-13D at 5 Newlands Street in 14 15 Chevy Chase, including the condition recommended by staff; and HPC Case No. 37/03-13B at 222 Park Avenue in Takoma 16 Park, including the conditions recommended by staff and with 17 18 the added condition that staff also review a sample of the 19 steel carriage house style door that is being submitted by 20 the applicant. 21 Is there a second? MS. MILES: 22 MR. CORATOLA: I second. 23 MS. MILES: Thank you. All in favor, please raise

VOTE.

your right hand.

24

25

MS. MILES: It's unanimous. If this is your
Historic Area Work Permit, please see staff tomorrow. Thank
you for providing us with easily approvable permit requests.

We're now going to hear preliminary consultations first for 5417 Mohican Road, the R.A. Charles Castle, and the applicant can come forward and join us at the table.

And do we have a staff report?

MR. SILVER: Yes, we do. 5417 Mohican Road in Bethesda is an individually designated master plan site, the R.A. Charles Castle. This is a preliminary consultation. I've outlined a recommendation on page 1, and I'll go into this a little bit more but there are two design options that were submitted by the applicant included with the staff report packet, and I've included items 1 through 5 for which the HPC should provide comments and feedback on.

The proposal, again, includes two different design options, A and B. Staff's evaluation of the application focused on design option B. Staff met with the applicant initially for an initial consultation meeting and staff recommended some changes to the plans which the applicant responded to by providing option B.

The proposal is for construction of a two-story addition at the rear of the structure, the installation of a side porch roof and enclosure of the porch on the front and right side elevations of the subject property, removal and

replacement of an existing three-tab tab asphalt shingle roof and installation of a red slate. It is referred to in the architectural description from the designation file, the original roofing material on the house was red slate.

On the right south elevation, alterations include removal of a non-historic one-story shed roof screen porch extension, and an infill below the existing second-story flared roof massing will be added on that side. Also, construction of a two-car, a one-story two-car garage at the property as well as some other alterations which, for the most part, constitute routine or ordinary maintenance and would not require a Historic Area Work Permit such as repointing and rehabilitation repair of stone work, stripping and re-glazing of windows sash weights and other trim details.

Staff supports design option B moving forward from both the detail and massing perspective. With respect to the two-story rear addition, staff supports the construction of a two-story addition. I indicated that we had met and the applicant responded by providing option B. What staff sees as a more favorable aspect of option B is that it eliminated the two-story conical roof addition and there is a simplified hipped roof tower at the south right elevation. I recognize that the existing tower on the historic massing is a character-defined feature and repeating this feature as

a new construction at the larger scale could diminish the predominance of the existing tower feature which characterizes the property.

I've outlined a few section, or a section from the district, historic district and individual site district guidelines for Montgomery County and consistent with the guidelines, I've pointed out in the staff report that I am recommending a hyphen where the addition meets the historic massing. A hyphen in this location would aid in differentiating the historic massing in the addition, B, preserve the stone corners of the historic massing and C, preserve the south right elevation second story wooden shingle flare wall section. It should be clear that that would be the right section of that flared section.

I would also support a small increase to the square footage of the addition by extending it further into the rear yard to accommodate the insertion of a hyphen, and I know that the applicant is going to want to talk to you a little bit about his approach to sort of preserving the legibility of the corners and how one experiences the property but I will let him go into that a little bit more sort of when you all go down the line about the points. I have outlined a couple possible, or a possible hyphen design at the top of page 5.

I also recommend removing the circle window from

the north left elevation. I find that a round window is not in keeping with the characteristics of the primary structure. I also recommend reducing the width of the addition to be coplanar of the existing building footprint, not the portraits but the building footprint itself, to help preserve the basic rectilinear building form. Modest reduction of the width of the addition at the north and south sides would better integrate the addition with that form of the historic building footprint. However, the HPC could find that by adding a hyphen and/or through the introduction of a material change, that a reduction in the width of the addition might not be necessary.

The applicant has not spelled out window and door materials in any great detail but we've had a sort of preliminary conversation about that. I recommended, made a few recommendations with respect to that north left elevation stair tower. They should have like a metal frame window and the rest should be a wood, wood window. I know the applicant is looking for guidance on that. Support the roof treatments. I've already pointed out that the house had red slate based on the designation file. I also am recommending the applicant explore other materials for the exterior cladding as the design evolves. I certainly hope that the Commission is in a position to provide some guidance to the applicant in that area. I know that he is,

2

3

4

5

6

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

would like to talk a little bit about that as well.

As the staff report points out, the stone exterior is a defining element of the house. Redundancy of a similar or matching stone as the primary building material for the addition would compete with the historic massing whereas an addition should read separate and subordinate. Certainly, there's a number of different material options to do this. This does not completely suggest that stone be eliminated from this addition section completely but perhaps, as the dominant material in this case, perhaps it needs to be reduced to avoid this competing and perhaps there's a balance too, as well, between adding a hyphen or some other differentiation in stone could continue via the primary building material. I've laid out some recommendations for the addition inset plus use of stone and elimination of the round window for the northwest elevation.

Moving onto the side porch roof enclosure, I've cited the Secretary of Interior standards. I'd call them 1 through 4 but they are the standards and basically, I've laid out that the Commission should test this design aspect of the proposal against 1, 2, 3 and 4. I'm not going to go into reading those but as I pointed out, the intent here is for construction of a new low-pitched roof over the north and west, front right elevations of the existing porch and the installation of a full view fixed glass between vertical

support columns. That's something that the Commission reviewed and approved over on the Baltzley Castle, the adjacent property, last year, year before.

If the HPC does determine construction of the porch roof and the fixed glass is consistent with any of the review criteria that I put on page 5, I do recommend that terminating the porch roof at the right side of the chimney versus extending it to meet the wall point of the existing tower feature. And again, I identified that feature, that tower as a character-defining feature and I feel that in order to preserve that feature, you know, the new porch and roof should not engage the tower to preserve its legibility.

So roof replacement, I've already gone over that twice. I support that. The proposal is consistent with what the designation has called. I would recommend that the Commission approve that as submitted as a HAWP. I support the removal of the non-historic porch, infill below and rehabilitation of the second story on the right south elevation. The applicant has based construction of the infill location on physical structural evidence on the interior and the porch maintains the, the proposal, excuse me, maintains the original porch footprint. I would recommend that the Commission approve that as submitted as a HAWP.

And then the garage and other alterations, I've

already talked about the other alterations so I'm just going to go with the garage, that I support the construction of a two-car detached garage. It's set off to the right of the rear, right side property line so I believe as close as possible. I support the garage size, location and I do recommend materials for the garage take cues from the final material treatments that are selected for the addition to the main house.

So with that said, I again, I've recommended that the Commission must determine if design A, option A or B is more compatible with the resource and provide the applicant with feedback on the items below, construction of a two-story addition, construction of the side porch roof enclosure, roof replacement, demolition, rehabilitation and infill construction at the right south elevation and construction of a two-story garage, and that the applicant make revisions to the plan based on the comments and feedback from the Commission as well as the HPC in return for Historic Area Work Permit.

I can walk you through a couple quick photos.

Obviously, Baltzley is on the left. The arrow is pointing to R.A. Charles. That's the rear elevation. You can see the screened porch on the left and that flared roof section. The second story, west and south. Where you see that open section there to the right of the porch roof, that would be

the section where the roof which is proposed to be added and the glass infill. That's the tower that I've referred to four times.

That wasn't supposed to do that. There we go.

South right side elevation. Just sort of give you a little bit of, bring you around the right side of the house. Those stairs are going to be maintained, repaired, rehabilitated.

Some different angles of that porch and flared roof section to be infilled. And then sort of this would be looking from the rear of the house towards the front showing you that left elevation. And as I told you upstairs, the garage driveway location. So Mr. McNair, you can correct me if I'm wrong but I believe sort of where the tarp is, is the approximate area for the garage. We can come back to that if necessary.

And then here are some things, more just to sort of inform you of what's going on there with the addition. The glass enclosure and sort of how it's coming along. There's still some work to be done but it's looking quite nice having just been out there. And you can also see the garage that is set into the slope there as well. So that's all I have.

MS. MILES: Thank you, Josh. Would you address the new entry porch that's on circle 27 on the east elevation and just how it's going to possibly compete with

the existing entry?

MR. SILVER: Well, let's see if I can specifically answer your question. But actually, hold on a second. I think it might be more helpful for me to look at actually the floor plan on page 25. But I mean, in terms of -- you used the word compete, right, with the existing entry? Is that the word that you used?

MS. MILES: You're right. Let's just discuss the new entry porch.

MR. SILVER: Okay. Well, I think it's the intent to sort of create this additional, I mean, I'll say this and, you know, not verbatim but sort of paraphrasing the conversation I had with Mr. McNair is that he, you know, he wanted to create some, obviously, additional habitable space. He wanted to use a similar methodology as was used at Baltzley but in this case, creating sort of a new space. It's a stone building. It's a dark building. I know that he, you know, was looking at having a space with some additional light to it but I think, you know, it is maintaining the existing porch stairs that are there as I showed you in the photo or I can go back to so it's not, it's not changing that particular aspect of it there.

There is no new, you know, door piercing into the historic massing there. There's the chimney that's staying and then, you know, you had, I think there was some, a space

constraint with respect to getting toward, to talk about why 1 2 this can't be done with the existing L porch space there, and I think the applicant can probably better respond to that but that's sort of what I can tell you. 5 MS. MILES: Okay. Does anyone have any questions for staff? 6 7 I have one. Josh, if you could go MR. CORATOLA: 8 -- well, in this photo you have up now, the extended sloping 9 roof on the far right side, is that original or is that the 10 addition you were talking about? MR. SILVER: That's the 19, circa 1980s addition 11 12 that, the first level, the first level -- there's a better 13 photo here actually. Yeah. Look at the bottom left photo 14 there that you're looking at. That section there is an 15 addition. 16 MR. CORATOLA: That, the porch component. 17 MR. SILVER: That screened porch section is an 18 addition, yeah. 19 So the upper level is original. MR. CORATOLA: 20 MR. SILVER: Original, historic, older, yeah. 21 MR. CORATOLA: Okay. 22 MR. SILVER: Yes. 23 The first floor extended out a little MR. MCNAIR: 24 bit more.

MS. MILES: Mr. McNair, please turn on your

microphone. 1 2 MR. MCNAIR: Hi Ross McNair. If you, you can see one of those earlier pictures. If you look at the framing, you see that angled line that starts to come down and then it cuts across. So the first floor was slightly bigger than 5 the second floor. 6 7 Where was the original entry for the MR. KIRWAN: 8 house? 9 MR. MCNAIR: It's over --10 MR. SILVER: It's a little bit hard to see I guess Well, let's see. 11 here. 12 MR. KIRWAN: The stone arch right there on the 13 side of the house? 14 MR. SILVER: Let me try to get to another side on 15 the front. 16 MR. MCNAIR: Right there. MR. SILVER: 17 Yeah. Right there. 18 MR. KIRWAN: And, Josh, you don't have any 19 interior floor plans for the existing? 20 MR. SILVER: I don't, no. What you have is what was submitted with the application package. 21 22 MS. MILES: Okay. Any other questions for Josh?

MR. VAN BALGOOY: Madam Chair. For the side porch, Josh, could you just clarify for me? You mentioned you don't want the side porch to engage with the bay tower.

2

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Is it the intent of the applicant to, looking at circle 26 where the side porch engages with that tower, is the intent of the applicant to turn that window into a door so they can walk out there or not?

MR. SILVER: I don't, I don't believe so, right?

MR. VAN BALGOOY: Thank you. That's it. Thank
you.

MS. MILES: Okay. Mr. McNair, you can either make a presentation, show us scheme B, talk about scheme A, answer questions, however you'd like to use your time.

Okay. Thank you. MR. MCNAIR: Ross McNair. Ιf you have circled page 29, this is a more, a little bit larger version of the same house that the same architect designed so what we did is we put a lot of research into finding different designs that Chandler's done and we've been in touch with his collection up in Pennsylvania. So we've taken a lot of cues from, from a house that he designed and then this house was more cottage style. you know, we originally put in for a faceted bay much mimicking this and then Josh had said that he wanted to have that, that squared addition which really matches what one of the original designs would have been.

You can see over on the left side this porch we're talking about. It has the wrap-around porch that comes over and fully engages with the bay projection. What, what our

thought was if -- we can use any kind of skin material on this. We could use a different kind of stone which I think would, would look better, but we could use brick like the Kimmel House that's about four houses around the corner that has an HAWP approval on it and it was all done in red brick.

So we could use a red brick, we could use siding, we could use panelized systems but if all of the new work is clearly differentiated from the old work by having a different color or a different type of skin and everything that is new is a flat copper roof as opposed to a sloped roof, then it would be very easy to be able to see where the original house is and where the, where the new construction is.

One of the thoughts that we had, if you go to page 28, is the stair tower addition would be 100 percent glass. And then, Josh, could you go to the back of the house? So this wall, we've already repointed that wall so we're going to leave that wall like it is so that as you enter into the addition, you're going to see that. So where the stair tower goes, which actually projects out from the face of that building, all of that is glass, so you can look through this, this glass stair tower and see, see the corner, see everything that is there.

I think there was a question on the windows. My understanding is this is kind of a preliminary hearing.

What I would like to do is I'd like to have a finalized set of drawings which kind of incorporates most of the opinions of most of the people. We can do it as a wood window. We can do it as an aluminum clad window like the addition that we did next door at Baltzley. So because the two houses are, have a very strong presence together, there may be a benefit of having some similar materials used, so we used a lot of, we used a lot of copper in this and we used red clad windows so with the addition, we could use a red clad window, we could use a wood window. I don't have a strong preference. So it's really whatever, you know, you all think would look best.

There's a couple things with, with the historic write-up that I'm not sure about. When this property, it was, I guess it was identified and then designated, they were talking about a two-story porch and then they were talking about a wrapped porch. The way that I'm reading this is the two-story porch was where we're wanting to build that glass enclosure but I don't have — there are very few photos of this property. One of the nice things on working with Baltzley is there was a tremendous amount of information we could get and we could replicate things. This house is like the little brother house and it kind of got forgotten about so I don't have a lot of photos that are historic photos of this property so if there's something

that historic has on a two-story porch or a wrap-around porch, if we could get that.

MR. SILVER: Unfortunately, we don't. I'm holding the designation file here which contains that narrative piece that you're referring to, which is part of the staff report, but it is very thin in contents in terms of photos and those things and so I looked around a little bit more. I know that you've already looked at this at one point as well but, yeah. We don't have anything.

MR. MCNAIR: It's kind of similar to everything that I found. There's just so much information on Baltzley and so little information on Charles. So what I'd like to do is kind of turn it over and try to get some feedback and see what your thoughts and ideas are.

MS. MILES: Okay. I would just comment initially that of course I drive by your property every day and I'm very happy with the way the addition looks on Baltzley. I think that's exactly how I thought it would look and I'm very pleased with how it's coming along.

MR. MCNAIR: Thank you.

MS. MILES: Are there any questions from the Commission for the applicant? I know there are.

MR. TRESEDER: Real quick. On the site plan, you're entering through the existing drive and you're making a right angle turn toward the garage. Am I reading that

line.

correctly? 1 2 MR. MCNAIR: Which page is this? I have --3 MR. TRESEDER: Well, let me see if I can find it. Hold on. 4 5 MR. WHIPPLE: I think I see it at circle 15. MR. TRESEDER: I had it but now I've lost it. 6 7 MS. WHITNEY: Circle 23. 8 MR. WHIPPLE: 15 and 23. MR. TRESEDER: Okay. Circle 15. 9 MR. MCNAIR: All right. 10 11 MR. TRESEDER: Just so I understand, you're coming 12 in from the back through that existing drive easement or 13 something, correct? And then you're making a 90 degree turn to get into the garage. Is that how, is that the path? 14 15 that the --MR. MCNAIR: Yeah. Right now, there is, there's a 16 17 wooden one-story garage that was built, I don't know the 18 date but it was, it would have been built by the Shaffers 19 probably in the '60s or '70s and then, and then the driveway 20 loops around there. What we would like to do is take down the one-story garage and have the driveway go where it used 21 22 to go. 23 MR. TRESEDER: Okay. I'm reading it --MR. MCNAIR: Right along, right along the property 24

MR. TRESEDER: Right. But then you're taking a left turn down a paved area. That whole area would be like a paved courtyard in front of the house with a garage at the end, and I guess my main question is, is that indeed what I'm reading? Is that, is that all area proposed to be paved and if so, I see there is a major tree there. Is that being proposed, is there a proposal to protect that or what is the, what is the story in general with the paving in that area?

MR. MCNAIR: What I'd like to do with the hardscape is follow the same pattern that we got our approval on for Baltzley which is going to be a combination of granite Belgian block and travertine to create some courtyards, and then having some granite block pavers set in a mud set with, with gravel. So we've gone to a lot of historic sites, like Tudor Place and Dumbarton Oaks and a lot of places, and one of the things that you'll see a lot with these is a big use of gravel that has a border to contain the gravel and then in high-use areas, they'll have more of a hardscape. So in turnaround areas or right in front of the garage where tires would be scrubbing and stuff, we would have more of a hardscape plan and then where it's a straight shot, then we'll have, we'll have gravel.

MR. TRESEDER: So you're thinking that that system would protect the tree. The tree would not need any

additional protection? 2 MR. MCNAIR: Which tree are we talking about, the 20-inch tree or --3 4 MR. TRESEDER: Yeah. The 20 --5 MR. MCNAIR: -- the 40-inch tree? 6 MR. TRESEDER: I'm seeing a 20-inch tree here that's in the middle of, within the paved area. 8 MR. MCNAIR: Oh. 9 MR. TRESEDER: Is that being proposed to be 10 removed or --11 MR. MCNAIR: No, no, no. That's, that's this 12 walnut tree right here. 13 MR. TRESEDER: Okay. 14 MR. MCNAIR: No. We want to preserve the trees so 15 we'd have a big area around it. 16 MR. TRESEDER: Okay. So you would, you would use the same kind of system to create a sort of little tree 17 18 protection area around it. 19 MR. MCNAIR: Yeah. 20 MR. TRESEDER: To protect the roots. Good. Thank you. 21 22 MR. KIRWAN: Just to clarify, are you, is the 23 driveway coming, is it hugging that property line --24 MR. MCNATR: Yes. 25 MR. KIRWAN: -- that we're seeing at the bottom of

the page and you're going to be entering between the 40-inch and the 20-inch trees? You're sort of coming in between those trees to get into the drive court?

MR. MCNAIR: Yes.

MR. KIRWAN: Or are you driving --

MR. MCNAIR: Yeah.

MR. KIRWAN: Okay.

MR. MCNAIR: So what this shows is the drive that goes down to Baltzley and I guess what it really doesn't show is how that drive would loop around to get, get to the garage.

MR. KIRWAN: I've got a couple more questions.

What's happening to the stair in the existing house? Why
the need for a new stair?

MR. MCNAIR: It's going to be a lot more dramatic having the stair where it is in the proposed location. The existing stair bites into -- this is a modest house. The living room is fairly small and it's got bite where this L-shaped stair goes. The master bedroom has the stair interrupting into that space. By removing the stair and then having one, one flight of steps -- right now, there's a flight of steps outside to go to the basement, there's a flight of steps from the living room to go up to the second floor and then there's a separate flight of steps to go from the second floor up to the third floor, so this house has

three flights of stairs.

MR. KIRWAN: And going to the porch, the porch addition, why not enclose the existing porch like you did at Baltzley instead of adding this porch to the resource?

MR. MCNAIR: A couple reasons. I didn't think that you all would want that because that would have been the main entrance to the house. Two, that, the footprint is six-and-a-half feet so if we enclose it, all we're getting is a glorified hallway. So where that entrance comes in and then the doors come into the back and then the door that would then go onto this side area, by the time you discount for the pedestrian traffic flow areas, where are you going to put furniture, whereas if we fill this space in and then that gives you a dead end location so it's a destination room. It would be a glass room with beautiful views and you could really furnish the space.

MR. KIRWAN: But you get to that space by going outside to get back into it?

MR. MCNAIR: Uh-huh.

MR. KIRWAN: Why is that? Why not connect it internally?

MR. MCNAIR: Okay. Can we connect it internally?

I would love to. Just like your recommendation on getting

rid of the screened in porch that used to be at Baltzley and
then we could have one integrated structure, so I would love

23

24

25

Baltzley --

to hear some more comments from you. It would work a lot 1 better having an internal access. 2 MS. MILES: Any other questions? 3 MR. VAN BALGOOY: Madam Chair? 4 MS. MILES: Yes. 5 MR. VAN BALGOOY: Mr. McNair, I don't have any 6 questions about or concerns about any of the areas of your 7 8 proposal except for the two-story rear addition and the side 9 porch roof so if that, if that helps. I will say I'm very pleased with the work you're doing and you are going where 10 angels fear to tread by tackling a house like this so I 11 12 appreciate your courage in tackling this very, very 13 important building. On the side porch, I mean, I'm looking at the 14 original summary form and they refer to a two-story screen 15 porch and I assume that was on that location which is now 16 17 empty, is that correct? MR. MCNAIR: I have no evidence of a two-story 18 porch. I have not been able to find any photographs. 19 20 Anything. As I said, there are not, this is not a highly photographed house. I have found photographs of the other 21

MR. VAN BALGOOY: Baltzley. In the background.

MR. MCNAIR: -- and it just happens to be, you

side of the house and it's really, it's a photograph of

24

25

know, close by. I have not found any photographs of this 1 side. 2 MR. WHIPPLE: Commissioner --3 4 MR. VAN BALGOOY: Any evidence of --I apologize. It's my reading that 5 MR. WHIPPLE: the two-story porch is that, is that section that we had an 6 7 earlier question about where there's a screened in, a later 8 screened in porch below. 9 MR. VAN BALGOOY: To the rear. MR. WHIPPLE: It's not the section that we're 10 seeing here. I think that that was the porch. It's 11 12 attached. It's sort of a secondary space and it's framed 13 attachments to this heavily, this heavy masonry building. And so that's, that's my reading is that this was the 14 15 screen, the two-story porch. MR. VAN BALGOOY: Okay, because on circle 18 and 16 17 19, these floor plans refer to it as a restored porch. that incorrect then? It's not --18 19 MR. MCNAIR: Well, this is the north side of the 20 house where, on the lower picture. The south/southeast is that, is the other side so I don't, I don't know what was 21 22 there.

MR. WHIPPLE: Having been briefly inside this house, this has, that is off of a bedroom and it almost has the feel of a sleeping porch.

MR. VAN BALGOOY: Okay.

MR. WHIPPLE: That's sort of how I interpreted that space when I was there.

MR. VAN BALGOOY: So that's what we believe in the ACHS summary form when it refers to a two-story porch.

That's the two-story porch.

MR. WHIPPLE: That's my reading of it.

MR. VAN BALGOOY: Okay.

MS. MILES: Do you think the glazing is later on the second floor there, that it was originally open or, because it looks like that's fixed.

MR. WHIPPLE: When I was there, I wasn't trying to figure that out and so I don't know. It, it's a bit of a hodgepodge and so it wouldn't surprise me if it was originally a sleeping porch and then later enclosed with those, with that glazing. Relatively early but later.

MR. MCNAIR: All the glass is the historic glass, and we've been researching a lot of stuff with historic glass for making all the repairs everywhere but every pane in that window, those windows are constructed the same way, the glass is the same kind of glass. This is, this is not new glass. The third paragraph on this architectural description calls for a screened porch on the north side that wraps around to the west elevation and then six columns support the half-hipped porch roof.

So there's a description of two porches, two separate porches, one on, one on the north elevation and one on the southeast of the, southeast corner of the south elevation, so the descriptions clearly calling out for two porch, one of them being a two-story, one of them being a one-story but the framing for this, the floor joists for the second floor, the ceiling joists for the first floor, extend out and pick up that wooden structure and then there's sloped framing that ties into those floor framing. So the floor framing stagger so it's 1, 3, 5, 7.

So that, that structure is original to the house. It's got, it's got the original wood, original floor joists, the original knob and tube where they would have the, the casing sleeves where and knob and tube wiring would go through. So because it's, it's the same material that they've built the rest of the house with, I would not think that that would have been an open porch.

MS. MILES: Commissioner Van Balgooy?

MR. VAN BALGOOY: Okay. Putting aside that porch, I'm, let's talk about the one that's where the porch currently exists and it's covered. That portion is what I really want to talk about to keep this straight. I'll just note on your plans, there's no north arrow so I have no idea. When I refer to them, I have to refer to them in this orientation so --

MR. MCNAIR: Okay.

MR. VAN BALGOOY: -- I hope you can follow along as I do this. I'm looking at plan on sheet 18, and this is at the top right side. This is back porch is what I want to talk about. It says here it's restored porch. Is that referring to the covering? Is there any evidence that that porch was covered?

MR. MCNAIR: Sheet 18.

MR. VAN BALGOOY: Well, circle 18 to be clear.

MR. MCNAIR: So we're talking about on, without, on the front of the house.

MR. VAN BALGOOY: Yes.

MR. MCNAIR: Up to the right side of the page.

MR. VAN BALGOOY: Yes.

MR. MCNAIR: Okay. This is where this whole thing, was there a two-story screened in porch there, what was there. This -- it's kind of odd that they would have this open element there. Right now, there is no structure so then if it says restored, that writing is so small I can barely read it, proposed glass enclosed porch, restore, restore existing porch. It is not, it is not enclosed right now. We would like to enclose it.

MR. VAN BALGOOY: Okay.

MR. SILVER: I think, if I may, I think,
Commissioner Van Balgooy, I think that perhaps some of the

restoration refers to some of the things, you know, such as -- I understand where you're going. I think. I think I understand where you're going. There's this careful usage of words here, restore, rehabilitate, preserve, but I think that it may be like restoring some of the features like repairing, repairing, not restoring, the stonework so I think it's maybe just not notated correctly.

MR. VAN BALGOOY: What I want to clarify is was there a covered porch at that location originally. It doesn't sound - I'm looking at your photographs, I haven't been on site, I don't see any evidence of it tying into the wall or that, that the existing porch roof had been modified in some way. It is not unusual in late 19th Century houses though to find a portion of a porch like this covered and portions uncovered. I can give you plenty of examples like that. So that's why I'm a little hesitant about, because it is the front side of the house, this is a character defining feature, to cover that porch and enclose it in glass. I'm just hesitant about that. I just want to lay that out.

I understand you'd like to have an enclosed area that's sort of weather protective, because the views. I'm a little hesitant because of the location on this property.

And I have no evidence, unless you can give it to me, that there was a porch and you're actually trying to restore something. Then, then I'm going to be much more, I can

accept that.

On the addition to the rear, I do agree with staff about a hyphen or some distinction. I do have just some questions and maybe you can just explain your thinking. The stair tower does have this very large window or windows in it, a lot of light to bring into that space. I believe I understand you want to do that. It's very common to have stairways with windows on them. It does strike me as being quite different than the rest of the house and how windows are used in the sort of ratio between windows and walls, so can you talk a little bit more about that, why you chose that or do you have some evidence to, on what you're basing your decision?

MR. MCNAIR: I mean, this whole process is trying to second-guess what, what we can get the historic approval on. Baltzley, it took me four complete sets of drawings at 400 percent of my architectural budget. What I'm trying to do here is, is, you know, what direction is the wind blowing. What, what do I think you all might want. So I think that a glass-enclosed stair tower is an attractive feature. I think that it telegraphs through your site lines, you can see what the original house is. So I was thinking with the combination of those two things, it would be something that would be positive.

On a living in the house standpoint, to climb up

those stairs, having all that glass around with the river views that are looking down river, it's a gorgeous setting. So, you know, it would be the type of setting that every single time you traversed the first floor to the second floor and you're getting this solid glass wall with the views that it has, its spectacular.

MR. VAN BALGOOY: Well, I'm going to have my doubts about, I understand the views would be beautiful, it would be great to have light in that space but in terms of this building and in keeping and being compatible, it doesn't strike me as being correct.

MR. MCNAIR: Well --

MR. VAN BALGOOY: Typically, I see in stair towers like this where they have a lot of windows to add light is that they're stained glass windows or they're somewhat broken up with framed views through windows.

MR. MCNAIR: Okay, but I thought we were supposed to differentiate the addition from the existing so that you look at it and you see here is the new and here is the old.

MR. VAN BALGOOY: Yes. It's always a balance.

You need to distinguish but be compatible, and there's a lot
of leeway in that to make that happen so.

MR. MCNAIR: If --

MR. VAN BALGOOY: Maybe the other Commissioners have other suggestions to help us get there. I feel

uncomfortable with what you're proposing here.

MR. MCNAIR: Okay.

MS. MILES: Are there any other questions?

MR. CORATOLA: Can we go back to -- there is a photograph, Josh, of the south elevation showing -- yeah. I was looking, the previous photograph shows on the front porch, you can see where the wood column hits a stone pediment at the base and then as you're following that porch line to the open area, there appears to be that same type of pediment at the top of the wall. I don't know if that's a corner of the wall or if -- can you go back to that other photograph because it doesn't show the stones that we're seeing at the, where the stair intersects, that wall on the left and right. Are those just stones sitting on top of the wall or is that constructed?

MR. MCNAIR: That's the same thing that happens as you wrap around. So you can see where the posts, where you have the wood posts, the wood posts come down and there's an elevated stone and then there's a flat and --

MR. CORATOLA: Then it goes up again on the open area and around, same thing. It goes up by where the stair intersects.

MR. MCNAIR: Correct.

MR. CORATOLA: I'm not versed that well in this style but that says, I don't know if that is just the style

or if that triggers that there were columns sitting on top of those piers.

MR. VAN BALGOOY: Based on my experience, it's common in that style to have piers without columns on them so.

MR. TRESEDER: Actually, I do, I have a question about this since we're talking about stone. What is -- you've been working now on both of these houses for a while. What has been your experience with being able to match the stone and the style of the grout and the stonework? Have you had good luck with that and do you feel that if you did indeed use stone in the addition, that you could get a good match to it?

MR. MCNAIR: We've been able to use all stone from the houses. All the stone that had fallen out of the houses we were able to put back in place. The house had, it was really built more of a river silt so there, especially with Baltzley. Baltzley was more fine-crafted stone that was set together. It was really sand. It did have a beautiful extended joint line so we, we were able to match that. Because the stone is so hard, we were able, I think it's granite, so we used a stronger mortar and we did, we did the joint. So we really didn't have to find stone. We were able to use stone.

From the Chandler collection, we got some high

definition JPEGs of these glass negatives. There were three photographs that they have. He founded the School of Architecture and they have a Chandler collection that has all of these houses to be designed. So there were three photographs of Baltzley, so we were able to get those photographs and then blow those up and see exactly what that detail was and then we matched that detail. We did the same thing on the columns that — see those wooden brackets? We blew those columns up. We could, we could measure the difference and they're beautiful, beautiful columns with all of the detailing.

We have really restored this house. Painstakingly restored it. We would like to do the same thing with Charles. One of the things that, you know, that -- this has probably the ugliest roof that you can imagine on it. The house would have had a red slate roof. It would have had, you know, a decorative copper hipped coverings. It would have had some ornamental copper pieces with probably some weathervanes and stuff on it. We, you know, we can restore this house. A red slate roof is a ridiculously expensive roof so, you know, hopefully, there's a little bit of horse trading that we can do here.

I would like to restore this house. You know, we're matching the mortar joints that were there, we can fix the slate the way that was there, I could put all the

details that were there, we can preserve all these windows,

I can find the historic glass. We can do everything on this
thing so it looks like it did when it was built. It would
probably be better built when we finish it than it was when
it was built.

What we'd like to do is we'd like to have a glass porch that's not too different from the original design that Chandler did but differentiated as a flat roof and not a sloped roof, put some additional spaces on it that aren't that different form a Chandler design but have a different color stone or different colored material or something and have a flat roof so that all of the new work is differentiated but you have a painstakingly restored house with some modern amenities.

MS. MILES: If there are no other questions, I'm going to ask that we begin deliberations, but I don't want to cut anybody off.

MR. VAN BALGOOY: Madam Chair?

MS. MILES: Yes.

MR. VAN BALGOOY: Mr. McNair, can you just clarify who the architect, the historic architect was on this building? Is it Chandler or Mindeleff?

MR. MCNAIR: All the designs that I -- there's no reference to who the architect is. There's, there's a big reference to Mindeleff that it Baltzley paid him \$7,000.

- Baltzley didn't have anything to do with the construction of his home. Baltzley owned the land but he owned all the land from the Sycamore Store to the one-lane bridge. He sold land. In more of the things that I've read, Chandler designed it. When I found this design, this design looks exactly like this house except it's a smaller version. Things that I've read on the Kimmel House referenced Chandler designing it. So Chandler designed maybe half of the stuff at Glen Echo and then there were some other architects involved. But, you know, one of the problems on this house is it's, it's the step-child house. It's not the main house so it does not have all of the information.
- MR. VAN BALGOOY: So you believe it's done by Chandler but there's no, we have no documentation.
- MR. MCNAIR: I, I think that this, this looks exactly like a Chandler design that we found.
- MR. VAN BALGOOY: Okay, great. But if not, Mindeleff definitely not.
- MR. MCNAIR: I would not be able to say he did or he didn't. I think that he, he designed houses in a cottage style. I think most of the stuff that he did was more commercial and industrial. I don't think that he was a big house designer. Chandler was a prolific architect. He designed hundreds of houses.
- MR. VAN BALGOOY: Well, what you say sounds

reasonable to me so.

MS. MILES: All right. If anyone would like to go first or I'm just going to start calling on you all. It looks like Commissioner Kirwan is willing to bear the burden.

MR. KIRWAN: Not a problem. Mr. McNair, first of all, I want to thank you for coming to a preliminary and being as open as you are about, you know, wanting to hear what we have to say and getting our, getting our help and creating a direction for this and also, for coming to preliminary with a couple of options. I mean, that's something I've been encouraging for a long time. I think it's really helpful for us to see different ways to approach it so we can help sort of, you know, find the pros and cons of the approaches.

Unfortunately in this case, I can't support either A or B. I think there needs to be a C and possibly a D option that we'd see in the future, and I'll sort of start with my, my more specific concerns. And all of this is sort of being influenced by 24A-8(b)(1) of the Montgomery County Code is where I'm sort of coming from on this.

I think the, the placement of the addition is going to end up obscuring much too much of this resource from Mohican Road. I think there are two important sides to this house. I think the more important side is MacArthur

but I also think the Mohican Road side is important because that's really where the public will see that there are these wonderful historic resources sitting up on that hill as they drive through the neighborhood and see it up close.

And one of the things that concerns me about positioning the additions, the addition where you have it, the future addition where you have it in option A and B, is exactly what happened at the Kimmel House. I think that the Kimmel House is actually an unfortunate occurrence that that happened there. I think the additions there so obscure the original resource, from the street, I think that that's, that was a mistake in my, in my opinion. So I think an approach, an approach here has to somehow preserve the visibility of the resource from Mohican Road.

I also don't support the porch. I think that when you drive along the MacArthur Boulevard side, that is such an important view of that house, and the fact that we don't have any evidence that any porch ever existed there before, and I do believe it's very feasible that that was just an open terrace, and the way the corner of that house comes down to that terrace or the chimney comes down that terrace, the visibility of the turret that you get from MacArthur Boulevard, I think it would be a shame to lose a lot of that, and for it to be concealed by this porch addition. I know you're doing glass and you're trying to make it

transparent but it's still, you know, the glass would be, nonetheless would be reflective and it will lose that sort of exposure on that side that we'd get.

So, so I can't, I sort of start with the premise on this project that I really can't support any kind of change to that corner of the house. I think that's too significant. I, as I mentioned in the questions, I could support possibly enclosing that existing porch. I think that's a less evasive affect to the existing resource, like you did on the Baltzley Castle but building a new porch there, I would have a problem with that.

So and also, when I studied the addition -- it would also be very helpful for you to come to the, to, hopefully, a future preliminary, in my opinion, with, allow us a better understanding of what's happening inside the house. I know we don't have the ability to comment and render any opinion about the entry of the house but it would help us understand some of the need for the additions and what is creating it for instance. That's why I asked the question about the stair and what's wrong with keeping it. I have to imagine with a house like this, it must have had a pretty decent stair inside. At least one stair going from the first floor to the second.

So understanding the need to add such an evasive element to the addition and to this house, this sort of

major two-story element that this house never had, also concerns me because as you described in your, in your upfront testimony, this is a very modest house and I think we have to be very careful going forward that we sort of maintain the modesty that this house has. As you said, it's sort of the step-child to the Baltzley Castle and I think that's an important thing to preserve here nonetheless. So your analysis and the floor plans of a very large foyer space and a very large home office, I see basically two program elements in addition to the stair and I'm not convinced that that necessarily has to be in a two-story addition on the, on the Mohican Road side of this house.

And to sort of begin to head toward what I think might be a possible option C or option D, and one of the successes of Baltzley Castle is the fact that you kept the additions there one-story in nature. I mean, they're two-story including the basement on one side but they're one-story in nature. They really allow the house to be exposed on really all four sides as you go up from the second floor up to the roofline and there is very minimal sort of affect to the rest of the house, and I think that's a, that's a very, that's an approach that I think we should maybe begin to think about with this resource as well.

So, you know, a possible thing I see as a solution is to take that addition and sort of -- and I think I would

really encourage you to keep it one-story if you can. I think the stair can just be, do a new stair inside the existing house, you know. Either restore the existing stair or do a great new one inside the house. But take those what appear to be two program elements, you have. You can probably work that into a nice one-story addition that maybe is behind the garage and off that corner of the house where we have that sort of odd two-story element there now, and you can still create that entry court.

That addition would begin to, it would, of course couldn't be connected to the garage because of your setbacks but would begin to help form that courtyard including the garage, the addition of the two-story element on the Mohican Road side of that house. I think that, that, to me, would be a more acceptable way to approach this project would be sort of keep the additions, to really downplay it, very modest in nature and not to sort of create this new front for the house.

And coupled with that, I would also encourage you to, you know, again, because we don't have the floor plans, we can't really tell whether this would work or not but I think this door in the front, the original front door of this house, the original front entry of the house would be a real plus as well. That's one of the concerns I have about this is you're creating this new front door to the house and

I think this resource, and it really takes away from the, from the original importance of that sort of northwest facade.

So I think, you know, a combination of doing a much more similar addition, putting the stair inside the house and restore it, looking at restoring the original front entry to the house I think would go a long way for me for an approvable solution. Thank you.

MS. MILES: Commissioner, could you just comment on whether you think the garage is acceptable in design, location, whatever comments you can make?

MR. KIRWAN: Yeah. I think the garage is, as I sort of mentioned, I think the garage is well-placed. I think an addition sort of behind it would be worthwhile with it. I think the material choices I'm not quite so far from being able to get to a sort of a massing solution that works. I think material choices would come to me at another preliminary. I think stone could probably work into a solution.

I think one of the things that might be helpful with a one-story addition is you could maybe take your clues from the, from that two-story porch piece we were talking a lot about earlier with the shingle elements, and a shingled one-story and shingled garage might be a very nice thing to, again, differentiate but you're using a material that's

already been used to sort of differentiate on that house and I think that could be a, a material to think about and maybe with, incorporate that with a stone base for the, for the addition.

MS. MILES: Thank you. Who would like to go second? If nobody volunteers, it is going to be Max.

MR. VAN BALGOOY: Well, Mr. McNair, again, I appreciate you taking this on, and I'll just give you my comments again. I think you know sort of where I'm heading. On the two-story rear addition, I also have still questions about the size and the massing. I think the option B is reducing the scale a little bit. I have concerns about the windows on the stairs because it doesn't seem to be, you know, additions need to be simple in design according to our guidelines and need to be subordinate to the main structure. It seems to, when you look at that side of the house, it seems to instead, you're calling attention to that side so maybe think about that.

I like the idea of the hyphen. That might give you that way to differentiate it and still, and still allow you to use the space as you want. I'm intrigued by Commissioner Kirwan's suggestion to maybe make it a onestory. I can understand why you may want to make it have an entry to the house instead of going all the way around because that's where the car is parked but maybe there's a

1.0

way to make it a little smaller. I don't know. I'm not here to design a solution. I would agree with staff that the circle window on north elevation isn't in keeping with the house.

On the side porch and the enclosure proposing, I also feel uncomfortable putting a porch there when none ever existed on a primary facade like that unless you can provide some evidence of that, then we can talk about it. And it may be by actually going physically on site and looking to see if there's any previous evidence of construction or attachment, but it doesn't look like it on the pictures and certainly for this time period so all these terraces were not necessarily covered even though they have piers on them.

The garage I think is in a good location. I can't figure out a better place to put it. You don't have much space actually. And I agree as well. I can't really think about materials until we get a little farther down the road and figure out sort of how things fit together. That's all.

MS. MILES: Thank you. Commissioner Swift?

MR. SWIFT: This house confuses me. It feels like there are a lot of fronts to it and that puts you in a tough spot as far as how to add onto it, and I think you're hearing that from everyone here. I think I would be open to something along the solution you proposed, which is an addition potentially two stories on this face of the

building that we're looking at, but I really think it needs to be a very open transparent addition that almost frames the house with glass, and I'd be interested to see what that looks like. You'd have to do the visualizing for me before I could approve it so I think that's one possibility.

I understand the challenge of going back to the, to the original entry, as it's essentially in the Baltzley Castle's backyard and doesn't serve as, to me as well, as a main entrance to this, to this property. So I guess I'm open to seeing some more development of a two-story rear addition but I think if you look at this, this elevation, I think it would need to be transparent and I think keeping the roof flat and below the cornice line here would be something that might be worth looking at.

I also agree, as far as the porches, I don't think putting in a new porch at the current terrace is appropriate. I would be willing to look at enclosing the existing porch. I think the roof replacement would be a great addition here or a great change, and I think the garage is in an appropriate location. I think that being out of stone and a heavier material is appropriate because it's already set apart from the house against the, with a little bit different detailing, it would clearly be separate and not competing.

So I do think you're doing great, making a great

2

4

5

6

7

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

effort on this property. It's one of the more challenging ones I feel like I have looked at. I don't think there's any very clear solutions.

MS. MILES: Commissioner Treseder?

MR. TRESEDER: Okay. It helps to have people gone before me because I can say -- I think one thing that I think that you're hearing and I'll make a point is that I would not recommend taking the approach that you took with that historic photograph that you included in the package because even though it is sort of an interesting coincidence that adding this on would create a similar pattern, that would really be, I think all these proposals you're showing really are stuck on that idea of making it very much like the existing house and I think that it might be more important to really make this material-wise and stylistically different than the existing house even though you've, you know, come to really love the details of this work.

So I could be supportive of a two-story addition in the rear. I understand it obscures the house from Mohican Road but I just think that you don't have all that many options and I think that it is technically the rear of the house and so I would be more supportive of that.

Perhaps if -- I definitely agree that there should be a hyphen. In fact, I think the stair tower is sort of the

beginning of a hyphen on the one side and a similar kind of transparent structure on the other could, I think, go a long ways toward, toward letting the original house read better.

So I think there are some pieces here that could be incorporated in a scheme C personally. I think -- but this particular scheme B, scheme A doesn't fly because that's, I think, trying to do too much what the historic photograph is doing, the historic drawing.

I think scheme B has some pieces that can be recycled if you will. Perhaps if there is a hyphen, it's less critical to maintain the setback. I know you've been very careful on this scheme B to hold to the side, that the projection lines carry through from the bays by making your addition no wider than the existing house but actually, Commissioner Kirwan's idea is actually, you know, suggested maybe offsetting it more and not necessarily holding to that line might actually be more deferential to the existing resource so I think maybe you, there might be support on the Commission for actually more latitude on those particular, that particular issue.

I too support the garage location where it is. As far as the porch in the front is concerned, I feel that what you've designed meets the, meets the four tests that the Secretary of Interior guidelines lays out. I'm not sure that I'm thrilled with it but at the same time, it's

reversible and if it's transparent and done well with a flat roof, I could accept it.

MS. MILES: Commissioner Whitney?

MS. WHITNEY: I don't have really have too much at all to offer that's different from everything that you are hearing. I would like to comment that this is a cottage and is intentionally, by landscape and design, subordinate to the castle so the more it is, more additions we add to this and the more grandiose, the less it maintains subordination to the castle. So with that said, I could, I would rather entertain an addition of just one level and not, and not two, much as you may like the additional space. Again, with the different material, I can't envision at the moment other materials, as was said before, until I see a little more about the design.

I would like to see that corner of the screened in porch with the half addition over there joined together a little better. They're two jigsaw pieces that just simply do not, not fit together there. The garage seems fine. I'm sure you will be happy to have a garage on site there. And other than that, my comments are more the same with the things that you have heard before.

MR. MCNAIR: What was the jigsaw part?

MS. WHITNEY: Oh, the screened in porch there.
We've called it so many different things. We've got it up

on the screen right there. That. Those are two pieces of a jigsaw puzzle which they just, they don't fit together.

They don't work. I would like to see that attended to which I know you have plans to do so. Those two pieces just don't fit to me, so that's the jigsaw puzzle pieces that I'm referring to.

MS. MILES: Commissioner Coratola?

MR. CORATOLA: I'm actually headed towards the direction of Commissioner Swift. I don't have, I don't have a real issue with a two-story addition if it's read as a lighter addition rather than such a heavy component. And if it had, like you did before, more contemporary flair to it, more glass and possibly pulling it, like Commissioner Kirwan says, more towards the garage. You know, I don't understand your whole program and the spaces you're trying to achieve but I, you know, if it's a two-story space that you need to pull that off, I think it can be done gracefully in a more contemporary flair, more glass.

I think that the garage is in a correct placement and maybe the, where you're sort of creating a new front entrance, that becomes a secondary entrance and maybe pull it towards the garage side, so that might even give you direct connection to the garage. I'm pretty sure you can't physically make a connection to the garage because of setback requirements but if you pull that, that entrance

piece there and then tucked, if you're trying to create a stair, a new stair, maybe that stair is tucked into that, that left side as I'm looking at the plan, towards the garage side.

I'll go into, because I sort of started picturing a design as Commissioner Swift started talking about it, if it were less engaged, in this photograph here, if it was less engaged from the right side of that chimney and more engaged to the left-hand side and it became a, like I said, a more open piece, with a one-story, that could go all the way across the base, but having that entrance more towards the garage side rather than smack in the middle.

As far as materials, you know, again, if we're trying to create this layer, stone is probably not appropriate going all the way up. If you created sort of a stone plinth that pulled off of what's there and then built more of an open structure above it, I think you can pull off a two-story addition in that scenario.

As far as the front porch extension, I haven't seen enough to say, yes, I can go forward to that. Right now what I'm seeing, design-wise, it's not pulling it off so I don't feel strongly that, that that will help the front facade. So I'm leaning more towards not recommending enclosing that porch and more towards enclosing the existing porch. Did I forget that? Yeah. I'm in favor of the roof

component that you're restoring the roof material.

And then the garage piece. The garage sort of takes a lot of cues from what staff was talking about where you have the stone piers and then the infill component. I think you might be able to pull that off with the addition where you had some stone pieces and then a lot of glass inset because you're, from what I'm looking at in the plans, these are entry components and home office so they would lend themselves to being an open, open space and that would allow for, you know, the view, if this were a glass component, the view of the existing house. That's about all I -- I don't know if I missed any points, the five points.

No. That's it.

MS. MILES: Thank you. Commissioner Heiler?

MR. MCNAIR: Could I add one thing?

MS. MILES: Of course.

MR. MCNAIR: A problem on shifting everything over is there's a beautiful 40-inch oak tree that is to the right side so what we did on the basement is we, we brought the foundation walls back farther away than we did the first floor and second floor walls. So I was going to build this so that the foundation -- if you look at 15, you see where this 40-inch oak is so to have, have the addition more, grow in that direction, presents a problem with that, that oak tree.

MR. CORATOLA: Well, when I was saying growing that, I was talking more of the two-story aspect. So not actually pushing the whole footprint in that direction but more of, you know, your one-story component could go similar in the footprint that you have but the two-story doesn't go all the way up on that footprint. That's what I, really what I was trying to get at.

MS. MILES: Commissioner Heiler?

MS. HEILER: I have little to add to what

Commissioner Swift and Coratola said. I do agree that it's,

with Commissioner Kirwan that it's a problem that it's so

visible, it will be so visible from MacArthur but I think

you don't have any other choices. Certainly, by process of

elimination, this looks like the only place to build the

addition if you need an addition. And I agree. If you put

an extensive red slate roof, you can't have a cottage

anymore. I do think the hyphen would help, and I agree that

enclosing that place that looks like there never was a

porch, where it was an open terrace, I think will lose a lot

and you should avoid that.

I think the garage is in the right place and I would agree with everyone that anything, the more you could move toward the garage, the better it is. Possibly, you can't get very close because of this 40-inch oak tree but you may be able to move off the corner that you were

intending to build on and move toward the garage and that would help. The hyphen will also help. The materials, I think can't really comment on them until we see a design. You know, certainly the use of stone ties it together. On the other hand, it diminishes the ability to distinguish between the old and the new.

MS. MILES: Well, I would agree with Commissioner Swift that this house is confusing, that it's hard to know where the front is, and I've seen this house a lot and I've even been in this house. I would largely agree with Commissioner Kirwan. I think that the, although I think we all are in agreement that this is the only side of the house where you could put an addition that -- I don't want to see an entirely new house, essentially, from Mohican Road and I think that's what your two-story completely across the entire east elevation addition would do.

I could not support a bay that would compete with the existing bay. I could not support an entry of such substance that would compete with the existing entrance. I could not support enclosing or creating a porch where there is not one and certainly not one that infringes on the existing bay. I don't think it should be constructed there. I do think that it's possible that we could enclose the existing porch and its existing footprint.

I would agree that the more you could shift the

addition towards the garage to the south, that would improve it. I think the garage is fine where you placed it. And although I think it is too early to talk about materials, I would tend to concur with Commissioner Heiler that I think it would be, although stone ties it together, perhaps a band of stone at the base or foundation or something that ties it but not to give it such heavy, strong appearance. I do think it's still a cottage. I think even with the red slate roof, it's going to read as a cottage and we shouldn't try to turn it into something more grandiose than that.

So I think you've heard fairly consistent views actually across the Commission with some variation of level but I think you've gotten some pretty clear guidance. Do you have any questions for us, or you don't want to, you just want to cut your losses and walk away now.

MR. MCNAIR: Well, as I understand, it is part of the preliminary where we're just kind of batting ideas around and what, what would work. The bedrooms are small. The bathrooms are tiny. We really do need to get some more space on the second floor. If, if this volume space were to grow more, if the garage wasn't a garage, if I found another spot for a garage on here, if the structure which is the garage maybe came a little bit closer and there's a connector link and that's a two-story volume, is, is that kind of the direction that some of you are heading to?

MS. MILES: Can I suggest that rather than, you know, I think we don't want to kind of get into the let's redesign your whole project here. I would suggest that you, I think staff understands where we're going and I would suggest that you talk to Josh and have some better understanding of, you know, maybe what we mean and sit down and hash out some ideas but we really, we could be here all night batting back and forth ideas. I think that's probably a little further out than we're prepared to respond to.

MR. KIRWAN: Could I just sort of --

MR. MCNAIR: Sure.

MR. KIRWAN: I mean, just follow up on that. I think that thought's intriguing so I would, I would encourage you to go on design. What I don't quite understand though, is the property boundary flexible? Has it not yet been -- when you say put the garage somewhere else, how would you do that? It seems to be right at the back end of your property right now, or the front end from Mohican Road.

MR. MCNAIR: Garage space is important but habitable space is more so, you know, if there's a way to preserve more of the historic resource but still get the habitable space that a property like this needs, it would be important.

MR. KIRWAN: Well, I think I would encourage you

to pursue that option you began to talk about it. I'm not quite sure I'm, I can only speak for myself, I'm not sure I'm comfortable with a two-story addition yet but so I would encourage it to stay one-story along those lines because I think it gives you a lot more floor area to work with. It gives you, it can give you a much larger first floor in that regard but, you know, I think that's something that's certainly worth exploring.

MR. TRESEDER: Could I just make two suggestions?

One is to -- it looks to me like this tree is actually going to be a pretty important thing so I would consult with an arborist and really find out truly how much you can encroach, what kind of, perhaps, you know, pier footings and things like that because that will really help us in helping you.

And secondly, just in general, the drawings, I feel we have a hard time reading them. One thing, they've been reduced, they're very small but also, they're very hard-edged and they don't communicate the softness of the, you know, the flexibility which I think you have at this time, at this stage of the job. And to the extent that your presentation can clearly, you know, reflect sort of what is known and what is unknown I think would be because these kind of computerized drawings look very sharp or hard-edged and it's hard, for instance, just the way the stone is

rendered, it's hard to get a feeling for it. And so that might help, help us review it.

MS. MILES: Thank you. We will look forward to seeing you again. You don't look quite as enthusiastic about the idea but we will look forward to seeing you again.

MR. MCNAIR: Okay. Thank you.

MS. MILES: Thank you, Mr. McNair. Just to repeat what was said, if the plans show the direction of north and if we had interiors, it just would help us to gather our bearings because as everyone has agreed, it's a hard house to understand and somehow, knowing what we're looking at, the stairs that go up to bedroom three or whatever, something that made it easier to read what's going on would also help us to understand what's feasible.

MR. MCNAIR: Okay.

MS. MILES: Agreed. All right. We have another preliminary consultation for 7500 Carroll Avenue for exterior alterations. The applicant can come forward, and do we have a staff report?

MR. LEIBMANN: I have a much easier problem. I hope, I hope.

MS. MILES: We're very relieved.

MS. THEIMER BROWN: All right. The applicant is proposing to add painted wood brackets on the first and second story gable rooflines on the front facade and a

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 5417 Mohican Road, Bethesda Meeting Date: 1/23/13

Applicant: Ross McNair Report Date: 1/16/13

Resource: Master Plan Site #35/29-2, R.A. Charles Castle Public Notice: 1/9/13

Review: Preliminary Consultation Tax Credit: Partial

Case Number: N/A Staff: Josh Silver

PROPOSAL: Construction of rear addition, replacement of roof, enclosure of side porch, construction

of new garage and other alterations

STAFF RECOMMENDATION

The HPC must determine if design option A or B is more compatible with the resource and provide the applicant with feedback on items (1-5) below.

- 1. Construction of a two-story rear addition
- 2. Construction of side porch roof and enclosure
- 3. Roof replacement
- 4. Demolition, rehabilitation and infill construction at the right (south) elevation
- 5. Construction of a two-car garage.

PROPERTY DESCRIPTION

SIGNIFICANCE: Master Plan Site #35/29-2, R.A. Charles Castle

STYLE: Eclectic
DATE: 1890

ARCHITECTURAL HISTORY

The following was excerpted from Places from the Past: The Tradition of Gardez Bien in Montgomery County, Maryland.

This residence was built the same year as the more elaborate and larger scale Baltzley Castle, (located on the adjacent property), yet was also built of locally quarried stone, continuing the theme of the envisioned Rhineland on the Potomac. Both residences were built to take advantage of a dramatic view of the Potomac River. With its multi- and diamond-pane windows, hipped roof polygonal wing, and turned porch posts, the Charles Castle is essentially a Queen Anne style house sheathed in stone. R.A. Charles, an employee of the Treasury Department, bought land from Edward Baltzley in February 1890 and built the house soon thereafter. The *Manufacturer's Record* of 1891 stated that Mindeleff designed a Glen Echo Heights house for Edwin Baltzley for \$7,000.

ARCHITECTURAL DESCRIPTION

The subject property is a three bay by one bay, two and half story stone "castle" that faces south (west), and much smaller than the adjacent Baltzley Castle at 5415 Mohican Road.

Constructed of bluestone, the house has a two story screened porch with a flat roof at the southeast corner of the south elevation. The enclosed second level is supported by three columns at the first level.

There is a screen porch on the north elevation that wraps around to the west elevation. Six columns support the half-hipped porch roof. A two story tower is located at the northwest corner of the west elevation with a conical roof.

There are 1/1, double-hung windows with stone lintels, and a variety of multi-paned transom or upper sashes above single light lower sashes. The south elevation has a hipped dormer window. The house has a hipped roof with red slate covering. There are two interior chimneys with corbelled caps.

PROPOSAL

The applicant's submission includes two different design options (A and B) for construction of a two-story rear addition, enclosure of an existing side porch, removal and replacement of a 3-tab asphalt shingle roof with red slate, and construction of one-story, two-car garage at the subject property.

The HPC is encouraged to provide the applicant with feedback on both options A & B. Staff's evaluation of the application focused on design option B.

Rear addition:

• Construct a two-story, approximately 15' x 31', addition at the rear of the existing structure. The addition is essentially concentrated at the rear of the structure, with the north and south elevation walls extending slightly beyond the historic building footprint. The proposed materials include a combination of stone, wood shingles, and flat seam cooper roofing.

Side porch roof and enclosure:

• Install a low-pitched, flat seam copper, roof over an existing open style porch. Enclose the porch by adding full view, fixed, reflective glass between new vertical support columns. All existing stone will be cleaned and repointed. An existing (historic) side loading stair unit will remain.

Roof replacement:

• Remove and replace an existing 3-tab asphalt shingle roof on the historic massing with red slate.

As referred to in the architectural description above, the original roofing material on the house was red slate.

Right (south) elevation alterations:

• Remove a non-historic (c.1980s), one-story, shed roof screen porch extension. The existing wooden shingled, 2nd story flared massing with steep sloped roof will be preserved, new windows added, and the 1st story below (which currently is a screened porch) will be infilled to create a habitable interior space. The proposed infill is based on physical structural evidence on the interior and maintains the original porch footprint.

Construction of two car detached garage:

Construct a one-story, two car, 24' x 24', detached, framed garage at the rear, right corner of the

lot set 5' off from the property line setbacks. Materials for the garage consist of a stone foundation, wooden siding and wooden swinging carriage doors, and a flat seam copper roof.

Other alterations:

- Reset all loose stone work and repoint all mortar joints (No HAWP required)
- Rebuild front porch stone walls, remove and replace floor and roof framing, install new porch ceiling board, remove, strip and reinstall the existing wooden columns, and install red slate roof. (HAWP required)
- Strip, reglaze, and paint all existing wooden windows. Replace sash weights and chain as needed.
 Replace broken glass and rehabilitate existing window sashes, framing and trim as needed using salvaged lumber. (No HAWP required).

APPLICABLE GUIDELINES

When reviewing alterations and new construction to a Master Plan site several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A-8:

- (a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.
- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
- (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any one period or architectural style.
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little

historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation:

Standard #1: A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces and spatial relationships.

Standard #9: New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.

Standard #10: New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

Staff supports design option B moving forward from both a detail and massing perspective.

Two story rear addition:

Staff supports the construction of a 2 story addition at the rear of the historic massing. Staff met with the applicant last year who presented design option A at which time staff recommended an overall simplification of the details, materials and roof forms. Subsequent to this meeting, the applicant presented revised design option (B), to respond to staff's comments. Option B eliminates the two story conical roof addition and introduces a simplified hipped roof tower at the south (right) elevation. Staff recognizes the existing conical tower on the historic massing as a character-defining feature, repeating this feature as new construction and at a larger scale diminishes the predominance of the existing tower feature, which characterizes this elevation of the structure.

The Design Guidelines for Historic Sites and Districts in Montgomery County, Maryland recommend:

18.3 An addition should be compatible in scale with the primary structure.

- An addition should relate to the historic house in mass, scale and form. Is should be designed to remain subordinate to the main structure.
- One option to help visually separate an addition from the primary building is to link the primary structure with a smaller breezeway.
- For a larger addition, break up the mass of the addition into smaller modules that relate to the historic house.
- An addition should be simple in design to prevent it from competing with the primary structure.

Consistent with the guidelines above staff recommends a hyphen where the addition meets the historic massing. A hyphen in this location would: a.) aid in differentiating the historic massing and addition, b.) preserve the stone corners of the historic massing, and c.) preserve the south (right) elevation 2nd story, wooden shingle, flared wall section. Staff would support an increase to the square footage of the addition by extending it further into the rear yard to accommodate the insertion of a hyphen. This recommendation should not be interpreted as requiring any sacrifice of habitable interior space.

A possible design for the hyphen could include adding one additional bay of glass along the north elevation where the addition meets the historic massing. Staff recommends a lower and recessed hyphen where the addition and historic massing meet to define the connection. Staff would support an alternative hyphen design at the south (right) elevation that does not include a lower and recessed glass bay feature as described above for the south (right) elevation. This assumes any hyphen at the south (right) elevation would preserve the original stone corner of the historic massing.

Staff recommends removing the circle window from the north (left) elevation. A round window is not in keeping with the characteristics of the primary structure.

Staff recommends reducing the width of the addition to be coplanar with the existing building footprint, (i.e., the conical bay on the south (right) elevation and squared two-story tower with hipped roof on the north (left) elevation) to preserve the basic rectilinear building form (less porches and projecting bays/towers). A modest reduction to the width of the addition at the north and south sides would better integrate the addition with the rectilinear form of the historic building footprint.

The HPC could find that by adding a hyphen, staff's recommendation to reduce the width of the addition would not be necessary.

The applicant has not specified a window and door material for the proposed addition. Staff recommends a metal frame window for the north (left) elevation stair tower and all wood windows in other locations. Staff supports the proposed roofing treatments. Staff recommends exploring other materials for the exterior cladding as the design evolves. The stone exterior is a defining element of the main house, the redundancy of a similar or matching stone as the primary building material for the addition would compete with the historic massing, whereas an addition should read separate and subordinate; materials such as composite panels, metal cladding or combination of metal and glass where feasible should all be considered. Staff would support a stone material at the foundation/grade sections of the addition.

Staff recommendations:

- Inset addition by adding a hyphen where the addition meets the historic massing
- Less use of stone exterior materials. Exterior materials such as composite panels, metal with glass or others should be considered where feasible
- Eliminate round window from north (left) elevation.

Side porch roof and enclosure:

The HPC must determine if construction of a new low-pitched roof over the north and west (front and right) elevations of the existing porch and installation of a full view, fixed glass between new vertical support columns is consistent with the following *Standards*:

- 1. If the property would be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces and spatial relationships.
- 2. If the alteration would destroy historic materials, features, and spatial relationships that characterize the property.
- 3. If the proposed work is differentiated from the old and is compatible with the historic materials, features, size, scale and proportion, and massing and protects the integrity of the property and its environment.
- 4. If the new construction would be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

If the HPC determines construction of a porch roof and installation of fixed glass is consistent with any of review criteria 1 -4 above, staff recommends terminating the porch roof at the right side of the chimney versus extending it to meet the wall plane of the existing conical tower feature. Staff identified the tower as a character-defining feature above. To preserve this feature staff finds it necessary that a new porch roof not engage the tower to preserve its legibility.

Staff recommendation:

Determine if construction of a new roof and enclosure of the side porch is consistent with any of review criteria 1 -4 above. If the HPC determines the proposal is inconsistent with the review criteria above, but it could support an alternative design, it must recommend changes to the plans to make it approvable if submitted as part of a HAWP application proposal.

Roof replacement:

The designation file refers to the structure as originally having a red slate roof, as such staff supports the proposed roof replacement.

Staff recommendation:

Approve if submitted as a HAWP.

Right (south) elevation alterations:

Staff supports the removal of the non-historic porch, infill below and rehabilitation of the 2nd story. The applicant has based construction of the infill location on physical structural evidence on the interior. The proposal maintains the original porch footprint.

Staff recommendation:

Approve if submitted as a HAWP.

Construction of two car detached garage:

Staff supports the proposed construction of a two car detached garage set off the rear and right side property lines. Staff supports the proposed garage size and location. Staff recommends materials for the garage take cues from the final material treatments that are selected for the proposed addition to the main house.

Staff recommendation:

Approve size and location of garage if submitted as a HAWP. Revise material treatments to match those for the proposed addition after consulting with the HPC.

Other alterations:

Staff supports the proposed maintenance and rehabilitation projects identified in the proposal section. The applicant is encouraged to apply for a county historic perseveration tax credit for eligible expenses associated with the project.

Staff recommendation:

Approve if submitted as a HAWP.

STAFF RECOMMENDATIONS

The HPC must determine if design option A or B is more compatible with the resource and provide the applicant with feedback on items (1-5) below.

- 1. Construction of a two-story rear addition
- 2. Construction of side porch roof and enclosure
- 3. Roof replacement
- 4. Demolition, rehabilitation and infill construction at the right (south) elevation
- 5. Construction of a two-car garage.

Staff recommends that the applicants make revisions to the plans based on comments and feedback from the HPC and staff and return for a Historic Area Work Permit.



HISTORIC PRESERVATION COMMISSION 301/563-3400

DP8 -#1

APPLICATION FOR HISTORIC AREA WORK PERMIT

	V~	44 W 1	wal. 16	amail, un	Contact Person:	ross mc	naux
Con	tact Email: 10	33116	4,00116	gruce, an	<u>n </u>	301-219	1-0380
Tax /	Account No.: _ O O	508	312				
	ne of Property Owner:		_	ic	Osytime Phone No.	301-219	-0380
	**** 5415 T				sila m		
~~	Street	Number		Crty	Star	rt	Zip Cado
Cont	sactors:				Phone Ne.:	·	
Cont	ractor Registration No.:	:					
Ager	nt for Owner:	 			Daytime Phone Ne.:		
755	ATTEN OF BUILDING	70 march 20			· · · · · · · · · · · · · · · · · · ·		
			_	Street	14000	10 m 0	1
				Nearest Cross Street			
		Cinz	7	nearest Cross Street:	wacur	oute 5	tin 1
	Part C BA				CAU HUY	Sur 2	i um 1
Liber	r. <u>40953</u> f	olio:	<u> </u>	scat			
刄	100 4 19-4042	4.1° 17.55	ENTANDES.	····	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
14.	CHECK ALL APPLICABL	E		CHECK ALL	APPLICABLE:		
	Construct 🗆	Extend	Alter/Renovate	≥ 1ac	ŻKŚlub	Addition X Po	rch Deck D Sheet
	O Move O I		☐ Wreck/Raze		☐ Fireplace ☐ Wood	- •	Single Femily
•	☐ Revision ☐ 1	Repair	Revocable.		Vall (complete Section 4)	•	
18.	Construction cost estim	mete: S				_	
	If this is a revision of a	•	approved active per	mit, see Permit #			
				White See allowed in			
ZA.	Type of sewage dispo-	sak	01 Ø WSSC	02 🗀 Septe	03 🖸 Other:		
28.	Type of water supply:		01 (3) WSSC	02 🗇 Well	03 🗆 Other:		·····
PAR	THE GIVE	TEOL VE	OR FENCE / SET AN	NINE WALL		 	
		et .	inches				
			taining wall is to be	constructed on one of the f	plovino locations:		
	13 On party line/prope		_	on land of owner	On public right o	f wav/sesement	
		,	<u> </u>		C) on passes right o	· · · · · · · · · · · · · · · · · · ·	
				oing application, that the o			on will comply with plans
appri		stea ena i i	neredy acidiowiadge	and accept this to be a c	onardan for the issuance	e or una permet.	
	18	·~~	mark	2.0		11-21	17
_	Signet	true of one	or authorized egent	talle		11 20	Dete
_						······································	
Appr	oved:			For Chairp	erson, Historic Preserve	tion Commission	
	pproved:		Signature:	•		. Date:	
	ication/Permit No.:	101	19/122	Deta Fi	et 11/27/	20m (550m)	
,,,							

SEE REVERSE SIDE FOR INSTRUCTIONS

Edit 6/21/99

WRITTEN DESCRIPTION OF THE WORK R. A. CHARLES CASTLE 5417 MOHICAN RD

ROOF

Remove the 3 tab asphalt shingle roofing material and replace with red slate to replicate the original roof. This red slate will match the roofing material on the Baltzley Castle next door. The proposed work includes the removal of the asphalt shingle, stripping all underlayment and flashings, replace damaged framing / sheathing, installation of snow and ice shield, titanium underlayment, new copper flashing, copper gutters & downspouts.

STONE

Reset all loose stone and repoint all mortar joints

ONE STORY ENCLOSED SIDE PORCH

Install flat seam copper roof structure and enclosed the side porch with full view, fixed, low reflective glass.

FRONT PORCH

Rebuild the stone walls, remove and replace floor and roof framing, install porch ceiling board, remove / strip / reinstall the existing wood columns, install a red slate roof

WINDOWS

Strip, reglaze, prime and paint existing wood windows. Replace sash weights & chain as needed. Replace broken glass with matching historic single pane glass. Rebuild window sash / frame and trim as needed using salvaged lumber.

CONSTRUCT A TWO STORY REAR ADDITION

Construct a two story 15ft x 31ft addition on the rear - north east elevation. Building materials to be a combination of stone and wood shingles, with a flat seam copper roof.

2 CAR GARAGE

Construct a 2 car 24ft x 24ft detached garage set off the rear and left side property lines 5 ft. Stone foundation with wood siding and wood posts, wood swinging carriage doors with a flat seam copper roof.

(date

	(cover						
1. Name: R.A. Charles' Castle							
_2. Planning Area/Site Number: 35/29/2	3. M-NCPPC Atlas Reference: Map 20 Coordinate J-15						
4. Address: 5417 Mohican Road Glen Echo Heights							
5. Classification Summary							
Category building Ownership private Public Acquisition N/A Status occupied Accessible no	Previous Survey Recording MNCPPC Title and Date: Historic Sites Inventory 1976 Federal State x County x Local						
Present use private residence	The state of the s						
6. Date: 1890 7. Orig	inal Owner: R.A. Charles						
8. Apparent Condition							
a. <u>good</u> b. <u>altered</u>	c. original site						
9. Description: This three bay by one	bay, two and a half story stone "castle"						
faces south, and is smaller than #5415. Constructed of bluestone, the house has a two story screened porch with a flat roof at the southeast corner of the south elevation. The enclosed second level is supported by three columns at the first level. There is a screened porch on the north elevation that wraps around to the west elevation. Six columns support the half-hipped porch roof. A two story—tower is located at the northwest corner of the west elevation with a conical							
variety of multi-paned transoms or upp The south elevation has a hipped dorme	g windows with stone lintels, and a er sashes above single light lower sashes. r window. The house has a hipped roof o interior chimneys with corbelled caps.						
Create a washington "Rhineland of the Baltzley bought 516 acres of land in 1 Chautauqua, and sold lots for a planne were to be of brick, stone or metal, but offering stone delivered at quarry cost	d development across the street. Houses ut the use of granite was encouraged by t. This house was built for R.A. Charles tles" built in the planned development						
Chautauqua, but also to the Baltzleys'	real estate business. Se for many years The present owners						
Car 11. Researcher and date researched: Car	ndy Reed/Architectural Description rlotta Anderson 4/79						
	te Compiled: 6/79 14. Designation						
	Approval						
I). ACI	Ougo Day Die Sq. It.						

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING

11/26/2012

OWNER'S MAILING ADDRESS

HISTORIC SITE ADDRESS

J. Ross McNair 5415 Mohican Rd Bethesda Md 20816

5417 Mohican Rd Bethesda Md 20816

ADJACENT AND CONFRONTING PROPERTY OWNERS MAILING ADDRESSES

Miguel Otero

5301 Mohican Rd Bethesda MD 20816 Chris White 5409 Mohican Rd Bethesda MD 20816

Maureen Jeffreys and Michael Bergsman

5303 Mohican Rd Bethesda MD 20816 Miklos Gaal 5407 Mohican Rd Bethesda MD 20816

Matthew Byrne 5405 Mohican Rd Bethesda MD 20816 Stephen Seeber 5309 Mohican Rd Bethesda MD 20816

William Barlow 5311 Mohican Rd Bethesda MD 20816 Patrick Gates 5421 Mohican Rd Bethesda MD 20816


Ned Miltenberg 5410 Mohican Rd Bethesda MD 20816

John Lentz 5424 Mohican Rd Bethesda MD 20816

Joy Brown 5408 Mohican Rd Bethesda MD 20816 Whittington Lewis 5404 Mohican Rd Bethesda MD 20816


Nathaniel Kendall 5420 Mohican Rd Bethesda MD 20816 William Coolidge 5423 Mohican Rd Bethesda MD 20816

James Ross 5425 Mohican Rd Bethesda MD 20816 Philip Warker 5428 Mohican Rd Bethesda MD 20816 e found





tymd.gov/ims/mcgmaps/viewer.htm


5/28/2011





Option A






















Option B



McNair Residence

McNair Residence





McNair Residence


Elevations Scate: 3/18"=1"-0"


Potlock Dickerson
Associates, PC
Archibad:
PArchibad:
PSA Oktobach Lane
Salda SA Oktobach Lane
Salda SA Oktobach Lane
Salda SA Oktobach Lane
Postorial Margana 28822
Tel 301.237.7542
Consultantis: TBD
Professional Certification:
Investing Margana Saldaman Consultantis: TBD
Professional Certification:
Investing Margana Saldaman Consultantis
Investing Margana Saldama

Replace Current Main Roof Grey Asphalt Shigkes with New Red State Shingles with Copper Gutters & Flashings (typ) South Elevation 3/16"=1:.0" Proposed New Gargage Nets: Metal Rook Valenty Destroyates New Gargage Ston On High Pethed Red Straits Rook of the Hight Restricts

McNair Residence

(23)







עם אוווים, שווא ב אוטונטם טב טוט טווע ב שוווים, אוווים לבוווונה ב

טוי כוטייים בועונוים איזו איזיא מ ואיזו בעוושי הוווישוויים איזוים וייים איזוים ווייים ווייים ווייים ווייים ווייים


Proposed Historic Restoration & Additions MeNair Cottage




Presentation of Selvements Options November 2002













McNair Cottage Existing Condition Photo 4-View of Existing Drive and Storage Bldg













McNair Cottage Existing Condition Photo 3- East Side



McNair Cottage Existing Condition Photo 4-View of Existing Drive and Storage Bldg




Proposed Elistoric Restoration & Additions MeNair Cottage



Presentation of Schomatic Options November 2002









McNair Cottage Existing Condition Photo 7-West and East Side







MeNair Cottage