7213 Cedar Avenus, Takoma Park THPC Case # 37/03-11 R] Takoma Park Histori Sistrict



HISTORIC PRESERVATION COMMISSION

Isiah Leggett County Executive

Leslie Miles
Chairperson

Date: February 21, 2012

MEMORANDUM

TO:

Diane R. Schwartz Jones, Director

Department of Permitting Services

FROM:

Josh Silver, Senior Planner

Historic Preservation Section

Maryland-National Capital Park & Planning Commission

SUBJECT:

Historic Area Work Permit #565295 & 581291, garage demolition and new garage construction

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached applications for a Historic Area Work Permit (HAWP). These applications were <u>approved</u> at the May 11, 2011 and October 26, 2011 meetings.

The HPC staff has reviewed and stamped the attached construction drawings.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HAWP CONDITIONS AND MAY REQUIRE APPROVAL BY DPS OR ANOTHER LOCAL OFFICE BEFORE WORK CAN BEGIN.

Applicant:

Catherine Forster and James Clark

Address:

7213 Cedar Avenue, Takoma Park

This HAWP approval is subject to the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made. Once the work is complete the applicant will contact the staff person assigned to this application at 301-563-3400 or joshua.silver@mncppcmc.org to schedule a follow-up site visit.





For the first of the property of the proper

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: Catherine Forster Daytime Phone No.: 202.994.1008 Name of Property Owner: Catherine, Forster + James Clark
Daytime Phone No.: 202.994.1008 Phone No.: 301.602.7174 House Number: 7213 PART ONE: TYPE OF PERMIT ACTION AND USE 1A. CHECK ALL APPLICABLE: CHECK ALL APPLICABLE Construct ☐ A/C ☐ Slab ☐ Room Addition ☐ Porch ☐ Deck ☐ Shed ☐ Move ☐ Install Wreck/Raze ☐ Solar ☐ Fireplace ☐ Woodburning Stove ☐ Revision ☐ Repair ☐ Fence/Wall (complete Section 4) 1B. Construction cost estimate: \$ 1C. If this is a revision of a previously approved active permit, see Permit # PARAMOR COMPLRICATION NAMED MAIN DESCRIPTION AND ENGINEERING DESCRIPTIONS 2A. Type of sewage disposal: 01 - WSSC 02 C Septic 03 🗆 Other: 2B. Type of water supply: · 01 D WSSC 02 | Well PART HIRES COMPLETE ONLY FOR FEMERAL AIRLING WALL dicate whether the fence or retaining wall is to be constructed on one of the following locations: On party line/property line ☐ Entirely on land of owner ☐ On public right of way/easement I hereby certify that I have the authority to make the foregoing application, that the application is correct, and that the construction will comply with plans Date Received in DPS: ___Mail Log # _27 1925 Signature APR - 4 2011 Application/Permit No.: Edit 6/21/99 **SEE REVERSE SIDE FOR INSTRUCTIONS** Assigned To Sue He Cooke







HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

contact mail: dhaden Qerols.co	Contact Person: DANA HADEN
	Daytime Phone No.: 301.270.5811
Tax Account No.: 01068950	
Name of Property Owner: JIM CLATEK, CATHY FORS	TER Daytime Phone No.: 301.585.6201
Address: 7213 CEDAR AVE,	TAKOMA PARK, dID ZO91Z
Street Number / City	Start Zip Code
Contractorr:	Phone No.:
Contractor Registration No.:	201 070 544
Agent for Owner: DANA HADEN	Daytime Phone No.:
ONATION OF BUILDING ASSESSED.	
House Number: 72/3	Street CEDAR
TOWN/City: TAKOMA PARK Nearest Cros	a Street: TUUP
Lot: 8 Block: 5 Subdivision: 25	•
Liber: Folio: Parcelt	
	_
PANY ONE: TYPE OF PERMIT ACTION AND USE	·
-	IECK ALL APPLICABLE:
☐ Construct ☐ Extend ☐ Alter/Renovate ☐	A/C State Room Addition Print Deck State
☐ Move ☐ Install - ☐ Wreck/Raze ☐	Solar
•	Fence/Well (complete Section 4)
18. Construction cost estimate: \$ 66,000	
IC. If this is a revision of a previously approved active permit, see Permit #	
PART I WOO COMPLETE FOR NEW CONSTRUCTION AND EXTEND	/hhhm/h2ts
	oric 03 🖸 Other:
IB. Type of water suppry: 01 B/FWSSC 02 🗆 We	03 🗋 Other:
ZANATHREE GOMPLETE ONLY FOR FENGERICATINING WALL	
IA. Heightinches	
18. Indicate whether the fence or retaining wall is to be constructed on on	of the following locations:
C) On party line/property line C) Entirely on land of owner	On public right of way/essement
hereby certify that I have the authority to make the foregoing application.	het the application is correct, and that the construction will comply with plans
pproved by all agencies listed and I hereby actnowledge and accept this	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	10/2/11
Jan Jaden	10/3/11
Signature of owner of authorized agent	/ 044
	adain la viene oma disconsission //
	M. Chairperson, Historic Preservation Commission
isapproved: Signature:	
	1 Date: 2/2/12

SEE REVERSE SIDE FOR INSTRUCTIONS

Edit 6/21/99

EXPEDITED

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

7213 Cedar Avenue, Takoma Park

Meeting Date:

5/11/2011

Resource:

Contributing Resource

Report Date:

5/4/2011

Takoma Park Historic District

Public Notice:

4/27/2011

Applicant:

Catherine Forster and Jame Clark

Tax Credit:

N/A

Review:

HAWP

Staff:

Josh Silver


Case Number:

37/03-11R

PROPOSAL:

Garage demolition and new garage construction

STAFF RECOMMENDATION:



ARCHITECTURAL DESCRIPTION

SIGNIFICANCE: Contributing Resource within the Takoma Park Historic District

STYLE:

Bungalow

DATE:

c1915-20

PROPOSAL:

The applicant is proposing to demolish a 209 square foot, 1 story garage in the rear yard of the property and construct a 1 story, garage with the same building footprint. If practicable the applicants intend to repair and reuse the existing foundation for the proposed garage.

Material specifications for the proposed garage include wooden lap siding and shingles, asphalt shingle roofing and wooden double-hung windows. The existing double outward swinging garage doors will be repaired and reused for the new garage.

APPLICABLE GUIDELINES:

Montgomery County Code; Chapter 24A-8

(a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.

- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
 - (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any 1 period or architectural style.
 - (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

STAFF RECOMMENDATION:

Staff recommends that the Commission <u>approve the HAWP application</u> as being consistent with Chapter 24A-8(b), (1) and (2):

and with the general condition that the applicant shall present the 3 permit sets of drawings, if applicable, to Historic Preservation Commission (HPC) staff for review and stamping prior to submission for the Montgomery County Department of Permitting Services (DPS) building permits;

and with the general condition that the applicant shall notify the Historic Preservation Staff if they propose to make **any alterations** to the approved plans. Once the work is completed the applicant will <u>contact the staff person</u> assigned to this application at 301-563-3400 or <u>joshua.silver@mncppc-mc.org</u> to schedule a follow-up site visit.



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

All

	Contact Person: CUTTIETING FOYSTEC
010,0000	Daytime Phone No.: 202.994.1008
Tax Account No.: 0/068750	· Clark
	Daytime Phone No.: 202.794.1008
Address: 7213 Cedar Ave. Takoma Par	<u>k MD 20912</u>
Contractor: David Hoskins	Phone No.: 301.602.7174
Contractor Registration No.: 46783	
Agent for Owner:	Daytime Phone No.:
OF ANOTHER REPORT OF STREET	
House Number: 72/3 Street	Cedar Ave.
Town/City: Takoma Park Newrest Cross Street	Tulio
Lot: 3 Block: 5 Subdivision: Gilbert's	Addition
Liber: Parcel:	
PART ONE: TYPE OF PERMIT ACTION AND USE	
<u> </u>	APPLICABLE:
<u> </u>	Fireplace Woodburning Stove Single Family/
18. Construction cost estimate: \$	all (complete Section 4) \(\sum \text{Other: } \frac{\text{Garage / S}}{\text{Dec}}\)
1C. If this is a revision of a previously approved active permit, see Permit #	·
PARTA (WO) COMPLETE FOR NAW CORE TRUCK (ON TANDESCREEN WARD INTO	HIS .
2A. Type of sewage disposel: 01 WSSC 02 Septic	03 🗆 Other:
2B. Type of water supply: , 01 □ WSSC 02 □ Well	03 Dther:
ANATHMATER COMPLETED IN MOTHER CANCER SERVICE AND ANALYSIS	
3A. Heightfeetinches	
3B. Indicate whether the fence or retaining wall is to be constructed on one of the fo	Rowing locations:
☐ On party line/property line ☐ Entirely on land of owner	On public right of way/essament
Chamber and is that I have the authority to make the foreign and its control of	
I hereby certify that I have the authority to make the foregoing application, that the aj approved by all agencies listed and I hereby acknowledge and accept this to be a co	
Dotte Kladas	
Signature of owner or suthdrived agent	Date Received in DPS:
Signature of owner or authorized ogen	Date Received in DPS: Date Received in DPS:
Approved: For Chairpe	rson, Historic Preservation Commission
Disapproved: Signature:	Onto: APR - 4 2011
Application/Permit No.: 565295 Date File	· · · · · · · · · · · · · · · · · · ·
Edit 6/21/99 SEE REVERSE SIDE FOR	INSTRUCTIONS Assigned Toute He Cook
	Assigned 10-2
	· · · · · · · · · · · · · · · · · · ·

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address		
7213 Cedar Ave.	g		
Takoma Park MD			
20912			
Adjacent and confronting Property Owners mailing addresses			
7211 Cedar Ave. Takoma Pk MD 20912 Till Morningstar + Alistair Etyphyne			
7215 Odan Ave. Toroma Park MD 20012 Robert Lunga + Firmy Steinberg			
F212 (Prior Ave. Takoma Priok MD 20912 Tearre Fearur	·		

1. Written Description of Project

a. Description of existing structure, setting, historical features

The structure was originally built as a single car garage, but is now used as a garden shed (too small for most modern cars, driveway does not extend back to the structure).

Building sits to the side and rear of the house. Roof has a very low pitch- we don't know if this is the original roof. There are two types of siding on the structure- one probably original, the other replacement material. The only sheathing on the building is the siding. Interior of structure has been re-supported with new framing inside the original framing (photos-3, top). A plywood ceiling was added to the interior. Floor is dirt. The two front doors are in decent condition.

- 1. The cement foundation on the right side is crumbling and fractured (photos-3, bottom).
- 2. Original framing is water and termite damaged, particularly on the right side (left side is in better condition). Window frame (on right) is eaten away and racked (photos-3, photos-4).
- 3. Roof is caved in at its center so that water pools and slowly leaks through ceiling and onto building floor (photos-2 bottom). Roof rafters are broken and eaves are rotted (photos-2, top). The plywood ceiling is severely water damaged and moldy (photos-4, top left).
- 4. Despite an attempt to shore-up the structure by adding interior framing, the entire structure leans to the right and to the rear (photos 5, top left; photo-1, bottom).

b. General description of project, effects

The roof and rafters are unsalvageable. The foundation and wood structure are water damaged and termite eaten in part (left side is in better condition than the right). The cement foundation is crumbling on the right.

Because of these extensive problems we would like to:

1. raze the structure, salvaging the two large front doors (photos-5, top right, bottom).

2. repair the foundation (or replace it if it is too damaged)

and pour a cement floor

3. rebuild the structure but with a more steeply pitched roof (as seen on many other similar structures on the block)


4. restore and reuse the original front doors



Materials

- -Foundation repair, floor, ramp to front doors: poured concrete
- -Standard 2 x 4 framing, 16" OC
- -6 in 12 roof pitch, standard stick framing using rafters (16" OC), ridge board, ceiling joists, and collar beams; rafter ends open to match existing
- -double 2 x 8 headers over windows; double 2 x 12 headers over door on gable end
- -1/2" plywood sheathing on walls and roof
- -German siding on walls to match existing
- -cedar shingles on front and back gable ends to match house
- -two wood double hung windows to match house
- -two original, restored wood entry doors with hinges
- -asphalt roofing shingles
- -garage will be painted to match house

The plat is of benefit to a consumer only insofar as it is required by a lender or a title insurance company or its agent in connection with contemplated transfer, financing or re-financing. The plat is not to be relied upon for the establishment or location of fences, garages, buildings, or other existing or future improvements. The plat does not provide for the accurate identification of property boundary lines, but such identification may not be required for the transfer of title or securing financing or re-financing.



CEDAR AVENUE

LOCATION DRAWING

LOT 8 BLOCK 5

B.F. GILBERT'S ADDITION

TO TAKOMA PARK

MONTGOMERY COUNTY, MARYLAND

THIS SURVEY IS FOR TITLE PURPOSES ONLY

JOB# 10.0015H	DATE 2-19-2010	
FIELD JDH	DRAFT JDH	
	P.B. "A" PL. 3	
	SCALE: 1" = 30'	

NOTES:

(1) The lot shown hereon does not lie within the limits of the 100 year flood plain as shown on FIRM Panel No. 200

Date of Map: 8-5-91 Flood Zone: "C"

- (2) No property corners found or set unless otherwise noted.
- (3) The accuracy of this survey and the apparent setback distances is 2'±



SURVEYOR'S CERTIFICATE

I hereby certify that the property delineated hereon is in accordance with the plat of subdivision and/or deed of record, that the improvements were located by accepted field practices and include permanent visible structures, if any. This PLAT is NOT FOR DETERMINING PROPERTY LINES OR FOR CONSTRUCTION OF IMPROVEMENTS, but prepared for exclusive use of present owners of property and also those who purchase, mortgage, or guarantee the title thereto, within six months from date hereof, and as to them I warrant the accuracy of this plat.


Michael J. Bazis RPLS #10956


R.C. KELLY & ASSOCIATES, INC.

PROFESSIONAL LAND SURVEYORS

10801 LOCKWOOD DRIVE, SUITE 190 SILVER SPRING, MARYLAND 20901 (301)593-8005 FAX (301)681-7216 E-MAIL: rckelly@cavtel.net www.rcklandsurveyors.com

Firster - Cherk






1 inch = 3ft.

FRONT

ORIGINAL DOORS RESTORED SIDING TO MATCH ORIGINAL GERMAN SIDING CEDAR SHINGLES ON TOP TO MATCH HOUSE

REAR ELELATION: IDENTICAL EXCEPT NO DOORS OR WINDOWS






1 inch = 3 ft.


DOUBLE HUNG WINDOWS SALVAGED + RESTORED FROM HOUSE RENOVATION PROJECT SIDING TO MATCH ORIGINAL CERMAN SIDING RIGHT SIDE

LEFT THE ELEVATION: IDENTIFEL EXCEPT NO WINDOWS



1 inch = 3 ft.


RIGHT SIDE DOUBLE HUNG WINDOWS SALVAGED + RESTORED DOUBLE HUNG WINDOWS SALVAGED + RESTORED FROM HOUSE RENOVATION PROJECT SIDING TO MATCH ORIGINAL GERMAN SIDING




1 inch = 3ft.


FRONT

ORIGINAL DOORS RESTORED SIDING TO MATCH ORIGINAL GERMAN SIDING CEDAR SHINGLES ON TOP TO MATCH HOUSE




(14)






front of shed




rear of shed



left side of shed





roof from right rear of shed



interior, left side



interior, right side




foundation, right side




water damage, ceiling



water and termite damage




more water and termite damage




level held vertically, left side

interior, door



doors, exterior





front of shed



rear of shed



left side of shed



eaves, right side



eaves, left side



roof from right rear of shed




interior, left side



interior, right side




foundation, right side




water damage, ceiling



water and termite damage



more water and termite damage





doors, exterior