35/13-00G 5912 Cedar Parkway (Chevy Chase Village HD)

Jour WESV. 301-803 3331 -ne state to per Hold for Kensel 14205 Patinum Moiling Garthysburg address MD 208787

#### HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 5912 Cedar Parkway Meeting Date: 04/12/00

Resource: Chevy Chase Village Historic District Report Date: 04/05/00

Review: HAWP Public Notice: 03/29/00

Case Number: 35/13-00G Tax Credit: Partial

Applicant: Catherine West (Howard Kandel, Agent) Staff: Robin Ziek

**PROPOSAL:** Alterations and new addition **RECOMMEND:** Approval

w/Conditions

#### PROJECT DESCRIPTION

RESOURCE: Contributing Resource in the Chevy Chase Village Historic District

STYLE: Colonial Revival DATE: 1916-1927

The subject property is a wood framed structure with 2-1/2 stories. The foundation is brick, the first floor is covered with stucco, and the 2<sup>nd</sup> story and attic are sided with wood shingles. The main block of the house has been augmented with several additions, including a small side addition which matches the main block (this appears to be original). The remaining additions are at the rear, and do not match the main structure in style or details. The house sits on a wide lot (c100' road frontage along Cedar Parkway), and has a narrow driveway along the south property line, leading back to what appears to be an original, and matching, garage.

#### PROJECT PROPOSAL

The applicant proposes to remove the rear back wall at the first floor level, and expand the rear/central room towards the back yard. A small two-story addition would be added along the north side of the house, which is set back from the from elevation so that the side window in the living room would still receive natural light. The new work would match the original in terms of massing and materials. Differences include the use of paired front windows at the first floor level and 6/1 fenestration pattern (where the existing windows are 6/6). Staff assumes that the applicant is proposing wood windows with insulated glass. The rear central room would be entirely glazed with french doors to be compatible with the original scale. The second story rear porch would remain unchanged. In addition, the applicant proposes adding a circular driveway in the front yard with a location which has been reviewed by a certified arborist (see Circle 6-10).

#### STAFF DISCUSSION

The front yard is a generous space with many mature trees. With careful placement of the new drive and with the tree-save measures proposed by the applicant's arborist, staff feels that this will be a compatible change within the district. The existing driveway will be retained, as will the existing front walk leading from the public street to the front entrance.

The proposed addition is modest, and appears to be compatible in terms of massing, scale and materials. While the side addition is using the original house for the basic design, there will be sufficient differences, including the groupings of windows and the fenestration pattern, which will serve to differentiate the construction. With the new addition held back from the front elevation even more than the existing side elevation, staff feels that it helps to reduce the impact of the new addition on the existing front elevation.

The applicant is retaining the rear kitchen addition, while increasing the first floor space to join the rear projections. None of this will be visible from the public right-of-way, but staff feels that the new proposal is an improvement over the existing non-original additions by respecting the scale of the original house.

#### STAFF RECOMMENDATION

Staff recommends, with the following conditions, that the Commission find this proposal consistent with the purposes of Chapter 24A-8(b)2:

The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site, or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;


and with Secretary of the Interior's Standards for Rehabilitation #2:

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.


#### **CONDITIONS:**

- 1) The applicant shall undertake all the tree-save measures outlined in the arborist's report, as submitted (see Circle & -9).
- 2) All the wood trim and railings will be painted.
- 3) All the new windows will be wood, with true divided light windows or approved equal.


and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work and not more than two weeks following completion of work.








(7)








(j)

Existing Front Elevation


Existing Left Side Elevation


145 19




and the second of the complete and approximate the second of the second

## PRO DOSED PARTIAL FRONT ELEVATION





PLEPOSED LEFT ELEVATION



e Residence dar Parkway hase, Maryland k 2 Plat #106



#### Studio Z Design Concepts, LLC

6917 Arlington Road Suite 351 Bethesda, Maryland 20814

301-951-4391 Fax 301-951-1913

		DATE:		3-17-2000	DATE:
		REVISION			SUBMISSION
•					





DPS -#8

DO MOT Sound to

#### HISTORIC PRESERVATION COMMISSION 301/563-3400

## **APPLICATION FOR HISTORIC AREA WORK PERMIT**

		Contact Person: 1-10wwd Rance	
		Daytime Phone No.: 301.775-772	_
Tax Account No.:			
Name of Property Dwner: Camerine wes	+2		9
Address: 5912 Certar Parkus Street Number			
Contractor: KANdel Construction	on Grou	Pri/ Phone No.: 301. 214. 9099	
Contractor Registration No.: 36644			
Agent for Owner: Howard Kandel		Daytime Phone No.: 301-775-77	<u>J</u>
LOCATION OF BUILDING/PREMISE			
House Number: 5917			
Town/City: Chery Chase N			
Lot: Block Subdivision:	Cherry	Chase	
Liber: (O48 Folio: 125 Parcel: _	Section		
PART ONE: TYPE OF PERMIT ACTION AND USE	lat 12	106	
	CHECK ALL	APPLICABLE:	
1A. CHECK ALL APPLICABLE:	□ A/C □		اع ٦
☐ Construct ☐ Extend ☐ Alter/Renovate			
☐ Move ☐ Install ☐ Wreck/Raze	☐ 2018L F	Fireplace	11111119
	C) 5	till (see and the Constiant 4)	
☐ Revision ☐ Repair ☐ Revocable	☐ Fence/W	fall (complete Section 4)	
1B. Construction cost estimate: \$ 300,000		(all (complete Section 4)	
		fall (complete Section 4)	
1B. Construction cost estimate: \$ 300,000	Permit #		
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND	Permit #		
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC	e Permit #	<u>DNS</u>	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC	Permit #  EXTEND/ADDITION 02   Septic 02   Well	ONS 03  Other:	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC	Permit #  EXTEND/ADDITION 02   Septic 02   Well	ONS 03  Other:	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING VALUE of the service of the	Permit #	ONS  03   Other:  03   Other:	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WATER  1B. Construction cost estimate: \$ 300.000  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WATER  1C. If this is a revision of a previously approved active permit, see	Permit #	ONS  03   Other:  03   Other:	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING VALUE of the service of the	Permit #	ONS  03   Other:  03   Other:	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASA. Height	Permit #	ONS  03  Other:  03  Other:  Illowing locations:  On public right of way/easement	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASA. Height feet inches  3B. Indicate whether the fence or retaining wall is to be constru	PETMIN #	ONS  03  Other:  03  Other:  03  Other:  Ollowing locations:  On public right of way/easement  publication is correct, and that the construction will comply we	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASSC  3A. Height feet inches  3B. Indicate whether the fence or retaining wall is to be construed on party line/property line Entirely on land	PETMIN #	ONS  03  Other:  03  Other:  03  Other:  Ollowing locations:  On public right of way/easement  publication is correct, and that the construction will comply we	
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASSC  3A. Height feet inches  3B. Indicate whether the fence or retaining wall is to be construed on party line/property line Entirely on land	PETMIN #	ONS  03  Other:	th pi
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASSC  3A. Height feet inches  3B. Indicate whether the fence or retaining wall is to be construed on party line/property line Entirely on land	PETMIN #	ONS  03  Other:  03  Other:  03  Other:  Ollowing locations:  On public right of way/easement  publication is correct, and that the construction will comply we	th pi
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASSC  3A. Height feet inches  3B. Indicate whether the fence or retaining wall is to be construed on party line/property line Entirely on land approved by all agencies listed and I hereby acknowledge and a	PETMIN #	ONS  03  Other:	th pi
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WASSC  3A. Height feet inches  3B. Indicate whether the fence or retaining wall is to be construed on party line/property line Entirely on land approved by all agencies listed and I hereby acknowledge and a	Permit #  DEXTEND/ADDITION  O2 Septic  O2 Well  WALL  ucted on one of the following polication, that the a concept this to be a concept	ONS  03  Other:	th pla
1B. Construction cost estimate: \$ 300.000  1C. If this is a revision of a previously approved active permit, see  PART TWO: COMPLETE FOR NEW CONSTRUCTION AND  2A. Type of sewage disposal: 01 WSSC  2B. Type of water supply: 01 WSSC  PART THREE: COMPLETE ONLY FOR FENCE/RETAINING V  3A. Height	Permit #  DEXTEND/ADDITION  O2 Septic  O2 Well  WALL  Licted on one of the following of the following polication, that the a concept this to be a concept th	ONS  03  Other:  03  Other:  09  Other:  On public right of way/easement  On public right of way/easement  pplication is correct, and that the construction will comply who andition for the issuance of this permit.  May 22, 2  Date  erson, Historic Preservation Commission  Date:	th pl

SEE REVERSE SIDE FOR INSTRUCTIONS

35/13-00G



Neighbors

S910 - Michael Cedu Pkuny McCa

5914 - Jan

Cedar PKary Montgomer


33 W. Kirke St.

#### Written Description of Project

1A. 5912 Cedar Parkway sits on a gently sloping lot adjacent to Chevy Chase Country Club. It's location, set well back from the street, provides beautiful curb appeal and stately presence. The original home a center hall two story colonial has first floor living, dining rooms with kitchen and second floor bedrooms and bath. Two additions have been constructed over the years. One was a kitchen renovation and breakfast area which wrapped the left side of the home and the second was a prefabricated sunroom area to the rear of the residence. A one story, one car garage structure originally stood to the rear of the lot and later a small addition was completed to be used as a changing room when the pool was added.

1B. 5912 Cedar Parkway is a two story colonial, center hall home with partial basement and partial crawl space. The exterior finishes are natural stucco and horizontal wood siding at the first floor and cedar shakes at the second floor.

The proposed project compliments the existing home by featuring genuine cedar shakes, wood siding and brick base. The existing sunroom is to be removed and new family room added in its place to become the new heart of this home. The existing second floor veranda will be kept in tact. The new addition to the right side of the residence will be unobtrusive by being set back from the front plane of the house similar to the existing left hand addition. First floor plan will include den, full bath, and rear open porch and second floor to be a new master bedroom suite. By creating this addition the circulation has been greatly improved and views to the rear yard have been opened up for all new rooms to enjoy.



E; SURVEYED IN ORDANCE WITH ED

CEDAR PARKWAY

BOOK Nº 2

SURVEYORS (ERTIFICATE: 1 HEREBY CERTIFY THAT THE POSITION ALL THE EXISTING IMPROVEMENTS ON A BOVE DESCRIBED PRODUCTION OF CAREFULLY ESTABLISHED BY A TRANSIT-TANE SURVITHAT UNLESS OTHERWISE SHOWN, THERE ARE HO ENCROACH

LOCATION SURVEY:

MONTGOMERY COUNTY, MARY

SUBDIVISION

SUBDIVISION

AB 125 2 CHEVY CHASE

E: 1"=30"

LAND SURVEYOR, MD. REG. Nº 2234

BETHESDA, MD. 20034

NCE OF PROPERTY CORNER MARKERS

GUAPANTSED BY THIS SURVEY

MONTGOMERY COUNTY, MARY

SUBDIVISION

CERTIFIED LAND SURVEY

Existing Ste Han
1"=301.0"

# M-NCPPC

#### MONTGOMERY COUNTY DEPARTMENT OF PARK & PLANNING

### THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

8787 Georgia Avenue Silver Spring, Maryland 20910-3760

Date: Agril 12, 2000

•	
MEMORANDUM	
	Hubbard, Director ment of Permitting Services  35/13 -00 G
FROM: WGwen Histori	Wright, Coordinator c Preservation
SUBJECT: Histori	c Area Work Permit
• •	anty Historic Preservation Commission has reviewed the attached toric Area Work Permit. This application was:
Approved	
Approved w	vith Conditions: (1) Follow all tree-Save measures as described in
arborist's report	vith Conditions: (1) Follow all thee-Save measures as described in (attached); (2) All The word trim and railings shall be painted
	now undoing will be word true - divided light (TDL) or
Simulate	J TDL.
and HPC Staff will re- for a building permit v	view and stamp the construction drawings prior to the applicant's applying with DPS; and
	RMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON HE APPROVED HISTORIC AREA WORK PERMIT (HAWP).
Applicant: Co heri	ne West (Howard Kandel, Agent)
Address:	
of Permitting Services Montgomery County	neral condition that, after issuance of the Montgomery County Department is (DPS) permit, the applicant arrange for a field inspection by calling the DPS Field Services Office at 240-777-6210 prior to commencement of its two weeks following completion of work.

c:\dps.frm.wpd

RE: 5912 Cedar Parkway, Chery Chase Village H.D.

Re: 5912 Cedar Parkway Chevy Chase, MD.

As you requested, on March 20, 2000 I made a site visit with you to inspect certain trees at the above address. The purpose of this inspection was to ascertain the impact of a proposed new driveway on the health of these trees.

A not-to-scale sketch of the area involved with the trees and the proposed new 10-foot wide asphalt on gravel driveway is attached to this report.

In my professional opinion, the 30" diameter Beech Tree in the center of the area will not be impacted by the construction. The 27" diameter White Oak tree will have some minor damage to its critical root zone. The 34" diameter Tulip Poplar on the next door neighbors' property and the 8" diameter street tree will have more root damage.

In order to minimize the damages, I offer the following procedures;

- The driveway area that is shown as shaded on the sketch is the most important in root damage. This area should be excavated no more than 4 inches deep for the gravel base. The asphalt layer may be placed on top of this.
- ♦ The driveway pavement can be held in place with steel edging or additional gravel built against the sides of the paving. This can then be landscaped with ground cover plants.
- The subject trees should be deep root fertilized/aerated according to the following. Drill or auger 2-inch diameter holes, 24 inches apart, approximately 10 to 15 inches deep in concentric rings in the area of the drip line of the trees. In the case of the Poplar Tree, much of this operation will be on the neighbors' property. These holes

are then filled to within 4-inches of the top with a mixture of half 10-10-10 granular fertilizer (or approved equal) and half humus (or approved equal). This work should be done within the next four weeks, and be done by a certified arborist.

• If there are drought conditions this summer, these trees should be irrigated on a regulated basis. The holes that were drilled will act as channels for the water to enter the critical root zone.

Although there can be no guarantees, if the above steps are implemented, it is my professional opinion that these trees can survive this construction work.

Thank you for the opportunity to be of service, and if you have any questions, do not he sitate to call.

Sincerely.

Lew Bloch, Registered consulting Arborist

Enclosures: Sketch

Disclosure statement





DPS - #8

#### HISTORIC PRESERVATION COMMISSION 301/563-3400

Ton sol . d 40 A010111

## **APPLICATION FOR HISTORIC AREA WORK PERMIT**

	Contact Person: 1-Counted Kanade
	Daytime Phone No.: 301-775-7727
	Tax Account No.:
	Name of Property Owner: Commercial West Daytime Phone No.: 301.502.4559
	Address: 5912 Cedas Parkway Chase 2013 Street Number City Steet Zip Code
	Contractor: KANCEL CONSTRUCTION Group 11: Phone No.: 301-214-9099
X	Contractor Registration No.: 36644  Agent for Owner: Howard Kandel Daytime Phone No.: 301-775-7727
	LOCATION OF BUILDING/PREMISE
	House Number: 5912 Street: Codar Parkway
	Town/City: Chey Chase Nearest Cross Street:
	Town/City: Chey Chase Nearest Cross Street:  Lot: Block: Subdivision: Chey Chase
	Liber: (OUE) Folio: 125 Parcel: Section 2
	PART ONE: TYPE OF PERMIT ACTION AND USE
	☐ Move ☐ Install ☐ Wreck/Raze ☐ Solar ☐ Fireplace ☐ Woodburning Stove ☐ Single Family
	□ Revision □ Repair □ Revocable □ Fence/Wall (complete Section 4) □ Other:
	1B. Construction cost estimate: \$ 300.000
	1C. If this is a revision of a previously approved active permit, see Permit #
	PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITIONS
	2A. Type of sewage disposal: 01 WSSC 02 Septic 03 Other:
	2B. Type of water supply: 01 WSSC 02 Well 03 Other:
	PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL
	3A. Height feet inches
	3B. Indicate whether the fence or retaining wall is to be constructed on one of the following locations:
	☐ On party line/property line ☐ Entirely on land of owner ☐ On public right of way/easement
	I hereby certify that I have the authority to make the foregoing application, that the application is correct, and that the construction will comply with plans
	approved by all agencies listed and I hereby acknowledge and accept this to be a condition for the issuance of this permit.
	Signature of owner or euthorized agent  Date  Date
	Signature or owner or outhorized agent
	Approved: U (Aud Trous or Chairpers A, Historic Preservation Commission
1	Disapproved: Signature: New American Date: 4/10/00
	Application/Permit No.: 314314 Date Filed: 3 21200 Date Issued:

**SEE REVERSE SIDE FOR INSTRUCTIONS** 



#### MONTGOMERY COUNTY DEPARTMENT OF PARK AND PLANNING

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

8787 Georgia Avenue Silver Spring, Maryland 20910-3760

35/13-006

#### **MEMORANDUM**

DATE:

April 12, 2000

TO:

Local Advisory Panel/Town Government

Village of Chery Chase

FROM:


Historic Preservation Section, M-NCPPC Robin D. Ziek, Historic Preservation Planner Perry Kephart, Historic Preservation Planner Michele Naru, Historic Preservation Planner

SUBJECT:

Historic Area Work Permit Application - HPC Decision


The Historic Preservation Commission reviewed this project on Acopy of the HPC decision is enclosed for your information.

Thank you for providing your comments to the HPC. Community involvement is a key component of historic preservation in Montgomery County. If you have any questions, please do not hesitate to call this office at (301) 563-3400.



1": 30 -0"

# ECHEMATIC for KANDEL CONSTRUCTION



NEW DRIVEWAY



March 20, 2000

Mr. Howard Kandel Kandel Construction Group, Inc. 8926 Abbey Terrace Potomac, MD. 20854

Re: 5912 Cedar Parkway Chevy Chase, MD.

As you requested, on March 20, 2000 I made a site visit with you to inspect certain trees at the above address. The purpose of this inspection was to ascertain the impact of a proposed new driveway on the health of these trees.

A not-to-scale sketch of the area involved with the trees and the proposed new 10-foot wide asphalt on gravel driveway is attached to this report.

In my professional opinion, the 30" diameter Beech Tree in the center of the area will not be impacted by the construction. The 27" diameter White Oak tree will have some minor damage to its critical root zone. The 34" diameter Tulip Poplar on the next door neighbors' property and the 8" diameter street tree will have more root damage.

In order to minimize the damages, I offer the following procedures;

- ♦ The driveway area that is shown as shaded on the sketch is the most important in root damage. This area should be excavated no more than 4 inches deep for the gravel base. The asphalt layer may be placed on top of this.
- The driveway pavement can be held in place with steel edging or additional gravel built against the sides of the paving. This can then be landscaped with ground cover plants.
- The subject trees should be deep root fertilized/aerated according to the following. Drill or auger 2-inch diameter holes, 24 inches apart, approximately 10 to 15 inches deep in concentric rings in the area of the drip line of the trees. In the case of the Poplar Tree, much of this operation will be on the neighbors' property. These holes



- are then filled to within 4-inches of the top with a mixture of half 10-10-10 granular fertilizer (or approved equal) and half humus (or approved equal). This work should be done within the next four weeks, and be done by a certified arborist.
- ♦ If there are drought conditions this summer, these trees should be irrigated on a regulated basis. The holes that were drilled will act as channels for the water to enter the critical root zone.

Although there can be no guarantees, if the above steps are implemented, it is my professional opinion that these trees can survive this construction work.

Thank you for the opportunity to be of service, and if you have any questions, do not hesitate to call.

Sincerely,

Yew Bloch, Registered consulting Arborist

Enclosures: Sketch

Disclosure statement

#### **DISCLOSURE STATEMENT**

As an arborist, I am a tree specialist and use my knowledge, education, training and experience to examine trees, recommend measures to enhance their beauty and health, and attempt to reduce the risk of living near trees. As the client, you may choose to accept or disregard these recommendations, or seek additional advice.

An arborist cannot detect every condition that could possibly lead to a tree or limb failure. Trees are living organisms that may fail in many ways we do not fully understand. Conditions are often hidden within the trees and below the ground. As arborists, we cannot guarantee that a tree will be healthy or safe under all circumstances, or for a specified period of time. Sometimes trees may appear "healthy," but may be structurally unsound. Likewise, remedial treatment, like any medicine, cannot be guaranteed.

Furthermore, certain trees are borderline cases as to whether they should remain or be removed. Also conditions change, and a tree may need further monitoring in the future to determine its health and structure. Of course the only really safe option is removal.

Trees can be managed, but they cannot be controlled, and to live near a tree is to accept some degree of risk. The only way to eliminate all risks is to remove all trees.

Lew Bloch, Registered Consulting Arborist

(Date)



Front Elevation

Front Elevation - Area of Addition



Front Elevation - Cedar Parkway


















Front Elevation

Front Elevation - Area of Addition




Front Elevation - Cedar Parkway













4/12/00

4/12/00 Date:

Sender: "Bourke Tom" <tom.bourke@whihomes.com>

HPC fax <IMCEAFAX-301-563-3412@weyerhaeuser.com>, KEPHART, "Naru Michele To:

(M-NCPPC)" <narum@smtplink.mncppc.state.md.us>, Wright, Ziek

'Jerry Schiro' <jms@erols.com>, "Elliott Bob" <bob-elliott@worldnet.att.com>, "Feldman Gail" cc:

<Gailivy@aol.com>, Jacobs c/o angela mcfuckenfuss <cfmuck@erols.com>, "Marsh Joan" <r.marshes@erols.com>, "Stephens Betsy" <bstephens@ibm.net>, "Wellington Peter"

<pwellington@steptoe.com>

**Priority:** Normal

```
Subject: CCV LAP Comments Wednesday 4/12 hearing
```

```
> Chevy Chase Village, Local Advisory Panel Comments for HPC Hearing April
> The following are the comments of the LAP on these Historic Area Work
> Permit Applications:
> Colby residence, 6000 Connecticut Ave:
> Outstanding resource,
> Porch Alteration, window replacement
> Staff recommendation: Approval
> The LAP concurs with the staff recommendation to approve without
> conditions. The addition appears to be well thought-out, and the removal
> of out-of-period prior work is to be commended
> Ruesch residence, 1 Primrose St:
> Outstanding resource
> Rear addition
> Staff recommendation: Approval.
> The LAP concurs with the staff recommendation for approval without
> conditions.
> The addition is well-designed and sits far back from Primrose St;
> therefore it has no significant impact on the streetscape. The LAP fully
> agrees with the approval.
> West residence, 5912 Cedar Parkway
                                                    # 35/13-00G
> Contributing resource
```

> Alterations and addition (to side of house)

> Staff recommendation: Approval with conditions

> The LAP concurs with the approval of the proposed work. The addition at > the side is set back from the front façade even more than the existing > addition on the other side of the front elevation. Staff conditions for > painted trim and tree-save measures are entirely reasonable. Several > members of the LAP expressed concern for the trees to be removed or > endangered by the new driveway construction. We believe this issue is > already sufficiently covered by the Village permit review process, but the > applicant should be reminded that approval from the Village will be > required: The Village Building Code states, Section 8-17: " Unless a > special permit has been obtained from the Board of Managers, no permit > shall be issued for the construction of any improvement which may > reasonably be expected to injure a tree of any size on an abutting or > nearby property, unless the owner of such property grants written > permission; or the removal of which is regulated by Chapter 17."

> The staff also requires that all new windows be wood with true divided > light construction. The LAP would generally agree with this for the > street elevation, but suggests if the resident so requests, that



March 20, 2000

Mr. Howard Kandel Kandel Construction Group, Inc. 8926 Abbey Terrace Potomac, MD. 20854

Re: 5912 Cedar Parkway Chevy Chase, MD.

As you requested, on March 20, 2000 I made a site visit with you to inspect certain trees at the above address. The purpose of this inspection was to ascertain the impact of a proposed new driveway on the health of these trees.

A not-to-scale sketch of the area involved with the trees and the proposed new 10-foot wide asphalt on gravel driveway is attached to this report.

In my professional opinion, the 30" diameter Beech Tree in the center of the area will not be impacted by the construction. The 27" diameter White Oak tree will have some minor damage to its critical root zone. The 34" diameter Tulip Poplar on the next door neighbors' property and the 8" diameter street tree will have more root damage.

In order to minimize the damages, I offer the following procedures;

- ♦ The driveway area that is shown as shaded on the sketch is the most important in root damage. This area should be excavated no more than 4 inches deep for the gravel base. The asphalt layer may be placed on top of this.
- ♦ The driveway pavement can be held in place with steel edging or additional gravel built against the sides of the paving. This can then be landscaped with ground cover plants.
- ♦ The subject trees should be deep root fertilized/aerated according to the following. Drill or auger 2-inch diameter holes, 24 inches apart, approximately 10 to 15 inches deep in concentric rings in the area of the drip line of the trees. In the case of the Poplar Tree, much of this operation will be on the neighbors' property. These holes

are then filled to within 4-inches of the top with a mixture of half 10-10-10 granular fertilizer (or approved equal) and half humus (or approved equal). This work should be done within the next four weeks, and be done by a certified arborist.

♦ If there are drought conditions this summer, these trees should be irrigated on a regulated basis. The holes that were drilled will act as channels for the water to enter the critical root zone.

Although there can be no guarantees, if the above steps are implemented, it is my professional opinion that these trees can survive this construction work.

Thank you for the opportunity to be of service, and if you have any questions, do not hesitate to call.


Sincerely,

Lew Bloch, Registered consulting Arborist

Enclosures: Sketch

Disclosure statement

# ECHEMATIC for KANDEL CONSTRUCTION



NOSCALE

#### **DISCLOSURE STATEMENT**

As an arborist, I am a tree specialist and use my knowledge, education, training and experience to examine trees, recommend measures to enhance their beauty and health, and attempt to reduce the risk of living near trees. As the client, you may choose to accept or disregard these recommendations, or seek additional advice.

An arborist cannot detect every condition that could possibly lead to a tree or limb failure. Trees are living organisms that may fail in many ways we do not fully understand. Conditions are often hidden within the trees and below the ground. As arborists, we cannot guarantee that a tree will be healthy or safe under all circumstances, or for a specified period of time. Sometimes trees may appear "healthy," but may be structurally unsound. Likewise, remedial treatment, like any medicine, cannot be guaranteed.

Furthermore, certain trees are borderline cases as to whether they should remain or be removed. Also conditions change, and a tree may need further monitoring in the future to determine its health and structure. Of course the only really safe option is removal.

Trees can be managed, but they cannot be controlled, and to live near a tree is to accept some degree of risk. The only way to eliminate all risks is to remove all trees.

Lew Bloch, Registered Consulting Arborist

(Date)

Felo16	2000
1	



Ray Sobrino, AIA

PRINCIPAL ARCHITECT


Ray Sobrino Associates PA.

11

Architecture/Land Planning
5917 CEDAK PARKWAY

15825 Shady Grove Road, Suite 180 Rockville, MD 20850

Phone: 301 258-3744 Fax: 301 258-3745



Side Elevation - Area of Addition



Rear Elevation - Area to be Removed



Rear Elevation



Rear Elevation - Area of Addition