31/7 10112 Capitol View Ave. 31/7-89J May 2, 1989

Resident 10112 Capitol View Drive Silver Spring, Maryland 20910

Dear Resident of the Capitol View Historic District:

As the historic preservation specialist for Montgomery County, I was recently driving through the Capitol View Historic District and noticed that you were in the process of constructing a front porch or deck.

All exterior work on buildings within a County historic district must be reviewed and approved by the Historic Preservation Commission. Having no records on file for the work in progress (or recently completed), I am assuming that you have not applied for approval.

I have enclosed a Historic Area Work Permit (HAWP) application. At your earliest convenience, would you please complete the application and return it. Include a brief description of <u>all</u> exterior work completed or in progress, including alterations, additions, demolition, new construction, and removal of trees.

There should not be any trouble in getting the work approved; however, every resident in the district where you live is required to apply for a HAWP unless the project involves minor maintenance.

Thank you very much for your cooperation. If you have any further questions, please feel free to contact me at 217-3625.

Sincerely.

Jared B. Cooper

Historic Preservation Specialist

**Enclosure** 

JBC:av 1095E Was this approved by the HPC?

Lucia YES - ON JUNE 1, 1989

#### HISTORIC PRESERVATION COMMISSION STAFF REPORT

PREPARED BY: Jared B. Cooper

DATE: May 23, 1989

CASE NUMBER: 31/7 - 89J

TYPE OF REVIEW: Retroactive HAWP

SITE/DISTRICT NAME: Capitol View Park PROPERTY ADDRESS: 10112 Capitol View

Ave.

#### DISCUSSION:

At staff's request, the applicant is seeking retroactive approval of work which was completed earlier in the year on this mid 20th century cottage. The work includes a number of things which fall into the following three categories: 1), minor maintenance, 2), replacement or removal of items damaged in storm; and 3), other items. All of these work items, with the exception of the front porch replacement, are listed on page two of the attached letter from the applicant. Staff has inspected the work, and feels that none of it constitutes a negative impact in the Historic District.

#### STAFF RECOMMENDATION:

Staff recommends approval of the application as submitted. The LAC did not review the application, but is aware of the circumstances.

#### ATTACHMENTS:

1. HAWP Application

2. Staff Letter to Applicant

3. Letter from Applicant

4. Photograph

#### COMMISSION ACTION:

JBC:av 1149E



#### भारतका अभागाता Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Mary 217-3625



# APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCUUNT #	· ·	
NAME OF PROPERTY OWNER DR. C. MICHAEL FORDIS 4ND (Controct/Purchaser) MS. JEAN B. FORDIS ADDRESS 10112 CAPITOL VIEW AVE. SILVER SPRING	TELEPHONE NO. ろいーSSS( (Include Area Code)	20910
CONTRACTOR MR. RONALD CARLSON (RONCA CONSTRUCT	. STATE	ZIP
	<u>CA)</u> TELEPHONENO. <u>301-699-</u> INUMBER <u>29547</u>	
PLANS PREPARED BYCONTRACTOR REGISTRATION	TELEPHONE NO	
	(Include Area Code)	
REGISTRATION NUMBER		
LOCATION OF BUILDING/PREMISE	•	
House Number 10112 Street CAPITOL UL	EW AVE.	
Town/City SILVER SPRING TO THE HOLD BENEFIT Election	on District <u>13</u>	
Nearest Cross Street LEE STREET  P+22, PT23  Lot P+24 Block  Block  P 24 Block		
Liber Folio Show Description of the selective of the sele		
1A. TYPE OF PERMIT ACTION: (circle one)  Construct Extend/Add Alter/Renovate Repair  Wreck/Raze Move Install Revocable Revision	Circle One: A/C Slab Porch Deck Fireplace Shed Fence/Wall (complete Section 4) Othe	
1B. CONSTRUCTION COSTS ESTIMATE \$ 12,400  1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTIVE PE  1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY PEPCO  1E. IS THIS PROPERTY A HISTORICAL SITE? NO	RMIT SEE PERMIT # NO	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITION AND EX	ONS AAA 2B. TYPE OF WATER SUPPLY 01 ( ) WSSC 02 ( ) Well 03 ( ) Other	
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL		
4A. HEIGHTfeetinches  4B. Indicate whether the fance or retaining well is to be constructed on one of the constructed one of the constructed on one of the constr	_	
Entirely on land of owner      On public right of way/easement		
I hereby certify that I have the authority to make the foregoing application, plans approved by all agencies listed and I hereby acknowledge and accept this to		• •
Signature of owner or authorized agent (agent must have signature notarized on	May 16, 198	9
APPROVED For Chairperson, Historic Preserve		
DISAPPROVED Signature	Date	
APPLICATION/PERMIT NO:	FILING FEE:\$	
DATE FILED:	PERMIT FEE: \$	
OATE ISSUED:OWNERSHIP CODE:	BALANCE \$ FEE W.	ΔIVFD·
		ATT LU



May 2, 1989

Resident 10112 Capitol View Drive Silver Spring, Maryland 20910

Dear Resident of the Capitol View Historic District:

As the historic preservation specialist for Montgomery County, I was recently driving through the Capitol View Historic District and noticed that you were in the process of constructing a front porch or deck.

All exterior work on buildings within a County historic district must be reviewed and approved by the Historic Preservation Commission. Having no records on file for the work in progress (or recently completed), I am assuming that you have not applied for approval.

I have enclosed a Historic Area Work Permit (HAWP) application. At your earliest convenience, would you please complete the application and return it. Include a brief description of <u>all</u> exterior work completed or in progress, including alterations, additions, demolition, new construction, and removal of trees.

There should not be any trouble in getting the work approved; however, every resident in the district where you live is required to apply for a HAWP unless the project involves minor maintenance.

Thank you very much for your cooperation. If you have any further questions, please feel free to contact me at 217-3625.

Sincerely,

Jared B. Cooper

Historic Preservation Specialist

**Enclosure** 


JBC:av 1095E

Historic Preservation Commission

51 Monroe Street, Rockville, Maryland 20850-2419, 301/217-3625

May 16, 1989

Mr. Jared B. Cooper Historic Preservation Specialist Historic Preservation Commission 51 Monroe Street Rockville, MD 20850-2419



Dear Mr. Cooper,

Thank you for your letter of May 2, 1989 detailing the indications for application for a Historic Area Work Permit (HAWP). I am more than happy to cooperate in providing the information you require.

All of the construction on my property at 10112 Capitol View Ave. was related to windstorm damage or maintenance as enumerated below. With the exception of a few remaining repairs and final touches, the bulk of the work had been completed by the time I received your letter on May 8 or 9, 1969.

Late in the afternoon of December 28, 1988 a windstorm struck the Washington metropolitan area with gusts of better than 75 mph. That evening my wife and I arrived home to discover that a large tulip poplar tree in the rear yard (the tree was better than 120 feet in height) had split at a fork 20 feet above ground, struck the house, and left us in the dead of winter with a new skylight, other unrequested renovations (including extensive plaster cracks on the interior surfaces that had been repainted only months before) and a lifetime supply of firewood. As we have neither basement nor garage, we had formerly used two sheds for storage. The poplar flattened one, an aluminum shed, and the second, a wooden shed recently refurbished with a new roof, floor and door, was destroyed by a locust tree that fell in the same storm.

Portions of the interior of the house were exposed to the elements and required emergency repairs to minimize further damage from the numerous storms that passed through the region at the end of December and early January. Many of our personal possessions were trapped in the ruptured aluminum shed beneath an enormous trunk. We could only cover them with a tarp until the tree could be cut into sections to permit access. Repairs have continued throughout the spring and as mentioned above are nearly completed.

All materials used for repairs of storm damage to the residence were chosen to reproduce as closely as possible the appearance of the house before the damage was sustained.

Summary of Repairs

(Maint.)

Maint.) Replacement of complete roof on main structure

Maint.) Replacement of gutters

Replacement of rake and fascia on side of house

(Maint.) Replacement of electric service from fuse box to PEPCO cable

Reattachment of electric meter to house by PEPCO

// Replacement of PEPCO cable from street to house

" Replacement of severed phone line

Replacement of side window destroyed by falling limbs

Replace Repair and replacement of fence and gate

Meint. Repainting of exterior

Reduce Repair of opening through roof into second story

N.A. Repair of master bedroom, plaster and repaint

N.A. Repair of living room, plaster and repaint

N.A. Repair of study, plaster and repaint

Repair of family room, plaster and repaint N.A.

N.A. Repair of stairwell, plaster and repaint

N.A. Removal from premises of debris from the sheds, house, fence

Remove Removal of failer trees and limbs

Replace Replacement of wooden shed

OTHER ITEMS NOT RELATED To STOKE

DAMAGE

**During the reconstruction**, I requested that the contractor complete other necessary repairs that were unrelated to the storm damage. On the exterior the additional repairs included the replacement of rear steps which were unsound and the repair of a large brick and cement slab porch in the front of the house. The slab on the front porch had cracked and settled 6-8" down from the door. Water on the slanted surface drained back toward the house so that, in winter, ice formation on the inclined cement made the surface treacherous to cross. Rather than to replace the slab with a second one that might again crack, we elected to use a wooden deck that would permit drainage and avert possible injury from falls on an uneven or icy surface. The contractor informed us that the porch, as it then stood without a protective railing, represented a technical violation of the building code. To comply with the code when the porch was repaired, a protective railing was installed and I assume that this is the structure you noticed in your trip through the area. We used high quality, treated wood of natural color to blend in with our structure and the surroundings.

With respect to the trees we sought professional assistance. Where I grew up the worst damage a storm inflicted on a tall tree was to tear off a frond or two. Indeed, it was the heavily wooded lots in Capital View that particularly attracted us to the area. For that reason we hoped to salvage and repair as much as possible the damage done to trees on the premises. We searched for a licensed and bonded arborist who by reputation was particularly conservative in treatment. After speaking with a number of firms, we selected an arborist trained at the University of Wisconsin and who held memberships in the International Society of Arboriculture, the National Arborist Association, the American Forestry Association, and the Society of American Foresters. He explained to us in consultation that the remaining portion of the poplar was unsalvageable, represented an imminent hazard to our neighbor's residence and should be removed forthwith. The standing trunk of the locust was dead and should be removed. All of the remaining trees with damaged limbs should have those limbs appropriately treated save a spruce which was so severely diseased that he could not in conscience advise our investing in it further. We accepted his recommendations and he expeditiously implemented them before arrival of the next storm forecast to strike the area a few days later.

Enclosed is the completed application for the Historic Area Work Permit and a photograph of the exterior of the house with most of the repairs completed. If you need additional documentation of these events, I can provide copies of damage estimates and claims. I also have photographs of the damage which you are welcome to view but which I must keep for insurance reasons. You can also verify the emergency power and phone line repairs with PEPCO and C&P Telephone. The total cost for all construction outlined above, treatment for damaged trees, and debris removal came to \$12,400 not including loss of personal property.

In closing I must mention that the hardships we faced in this ordeal were mitigated in large part by the generous assistance and support of neighbors in this community. We are forever in their debt. If I can be of any further service in this matter, please do not hesitate to contact me.

Sincerely,

C. michae Fordis

C. Michael Fordis, Jr., M.D. 10112 Capitol View Ave. Silver Spring, MQ. 20910 (301) 588-9654

enclosures: 2



10112 CapitOL VIEW AND SILUGE SPRING, MD



### **Historic Preservation Commission**

51 Monroe Street, Suite 1001, Rockville, Maryland 20850, 217-3625

PLEASE SEE ATTACHED LETTER

## APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	
NAME OF PROPERTY OWNER'S, C. MICHAEL FOROIS 4ND (Gentract/Purchaser) MS. JEAN B. FORDIS	TELEPHONE NO. 301-588-9654 (Include Area Code)
ADDRESSO112 CAPITOL VIEW AVE. SILVER SPRING	MD 20910
CONTRACTORME, RONALD CARLSON (RONCA CONSTRUCT)	ON) TELEPHONE NO. 301 -699-0885
	ON NUMBER 27547
PLANS PREPARED BY	TELEPHONE NO
REGISTRATION NUMBER _	(Include Area Code)
LOCATION OF BUILDING/PREMISE	
House Number 10112 Street CAPITOL VI	EW AVE.
Town/City SILVER SPRING Elec	ction District 13
Nearest Cross Street LEE STREET	
Loft 24 Block A Subdivision	the control of Marie (1994) and the control of the
Liber Folio Parcel	and the first the design of the second of th
1A. TYPE DF PERMIT ACTION: (circle one)	Circle One: A/C Slab Room Addition
Construct Extend/Add Alter/Renovate Repair	Porch Deck Fireplace Shed Solar Woodburning Stove
Wreck/Raze Move Install Revocable Revision	Fence/Wall (complete Section 4) Other E. ATTACHED
10000	LETTER
1B. CONSTRUCTION COSTS ESTIMATE \$ 12,400	NOW TOP DEDUCT A NO
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTIVE	PERMIT SEE PERMIT # 100
1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY PEPCO  1E. IS THIS PROPERTY A HISTORICAL SITE? NO.	
1E. IS THIS PROPERTY A HISTORICAL SITE?	March March March 1997 Control of the Control of
PART TWD: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDI	TIONS 1
	2B. TYPE OF WATER SUPPLY
2A. TYPE OF SEWAGE DISPOSAL  01 () WSSC 02 () Septic	26. THE OF WATER SOFFET
03 ( ) Other	03 ( ) Other
	<u> </u>
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
4A. HEIGHTfeetinches	
4B. Indicate whether the fence or retaining wall is to be constructed on one	e of the following locations:
1. On party line/Property line	
2. Entirely on land of owner	(0 1) (1 1)
	_ (Revocable Letter Required).
I hereby certify that I have the authority to make the foregoing application	The second secon
I hereby certify that I have the authority to make the foregoing application	n, that the application is correct, and that the construction will comply with
plans approved by all agencies listed and 4-hereby acknowledge and accept this	to be a condition for the issuance of this permit was a few
Michael Inder M.D. &	May 16, 1989
Signature of owner or authorized agent (agent must have signature notarized of	
***************	
APPROVED For Chairperson, Historic Prese	
DISAPPROVED Signature	Date to 17 139
APPLICATION/PERMIT NO:	FILING FEE:\$
DATE FILED:	PERMIT FEE: \$
DATE ISSUED:	BALANCE \$
OWNERSHIP CODE:	RECEIPT NO: FEE WAIVED:

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION PERFORMS OF THE LANGUAGE CONTRIBUTION DESCRIPTION OF PROPOSED WORK: (including composition, color and texture of materials to be used:) PLEASE SEE ATTACHED LETTER 394743 b. the company of the second Both of the out to be the Salah ing S. 1949 av Tenvita . ... THE STREET STATES OF Star commence within (If more space is needed, attach additional sheets on plain or lined paper to this application) ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work. on Normal Out on his by the MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE HISTORIC PRESERVATION COMMISSION 100 MARYLAND AVENUE THE PROPERTY OF THE SEASON OF THE PARTY. ROCKVILLE, MARYLAND 20850 医强力性的 经制度销售的 医克克斯氏病 Marian and Color of State of the Color of th The strong same of the THE LANGE AT

> general to the second to the s the constant in the many many that which in

Carrat Name Last doe. What I have not be

្រំ ស្វាក្សសម្រា

to the control of the control of the control of the control of the first of the control of the c The stray parties of the manufactor of the second control of the second of the second of the second control of

个研究的最近的1分以2000年,以2年间5月的15月的15月的15日的

2007年 - 1000年 - 1000年 - 100年 - 100年

The second of th

10112 Capilieur Are



South+ west 1004 Capital H.D.

South+ west 1004 Capital Video Part

Charterins 4/14/86 H.D.



Gyital View Park
10011 Capital
View Park HD

South elevation

4/14/86



Capital View Park H.O.

1011 Cerpital View Are 31/7

South election

4/14/86



Capital View Park M.O. 31/7 104 Capital View Are North + East Eductions 9/14/86



Capital View Pouh H.D. 31/7
1011 Capital View Acre
North + Est Elevations 1916
4/14/86