37/3 7106 Poplar Ave. SA 27-88

	6-4 	•	
· _	Mo	ntgo	mery
(nty∜	
(Ð	<i>icin</i>	ment

Historic Preservation Commission

3

31

100 Maryland Avenue, Rockville, Maryland 20850 279-1327

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	ϕ_{i} and ϕ_{i
NAME OF PROPERTY OWNER Hichard & Marcia DalB	Bello TELEPHONE NO. (301) 270-5429
(Contract/Purchaser)	(Include Area Code) Marvland © 20912
ADDRESS <u>7106 Poplar Ave.</u> Takoma Park	
CONTRACTORCONTRACTOR REGISTRA	TELEPHONE NO
PLANSPREPARED BY Charles G. Poor & Joan Du	ncan TELEPHONE NO. (301) 270-9221
Studio Partnership Archit REGISTRATION NUMBER	
HEGISTRATION NUMBER	0007-n
LOCATION OF BUILDING/PREMISE	
House Number Street Poplar Ave	enue 🗸
Town/City Takoma Park	
Nearest Cross Street Columbia Avenue	
Lot _21_ Block _20 Subdivision _B.F. Gi	lbert
Liber Folio Parcel	
1A. TYPE OF PERMIT ACTION: (circle one)	Circle One: A/C Slab <u>Boom Addition</u> Porch Deck Fireplace Shed Solar Woodburning Stove
Construct Extend/Add Alter/Renovate Repair Wreck/Raze Move Install Revocable Revision	
and the second secon	
1B CONSTRUCTION COSTS ESTIMATE \$ 15.000.00	
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTIV 1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY <u>PEPC</u>	
1E. IS THIS PROPERTY A HISTORICAL SITE?	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/AD 2A: TYPE OF SEWAGE DISPOSAL 01 (X) WSSC 02 () Septic 03 (*) Other	
PART THREE: COMPLETE ONLY FOR FENCE RETAINING WALL	
 4A. HEIGHT feet inches 4B. Indicate whether the fence or retaining wall is to be constructed on 	one of the following locations:
1. On party line/Property line	
2. Entirely on land of owner	
3. On public right of way/easement	(Revocable Letter Required).
I hereby certify that I have the authority to make the foregoing applicat	tion, that the application is correct, and that the construction will comply with
plans approved by all agencies listed and I hereby acknowledge and accept th	
PI INAL ALIAN	$\left(\left \left \mathcal{D} \right \right) \right)$
Kevn / al all M Maller M	<u>N/al BC/10_November 9. 1988</u>
Signature of owner of authorized agent (agent must have signature notarize	
S. Kon I	
APPROVED For Chairperson, Historic Pri Willh Conditions	eservation Commission APPROVED AT 11/8/88 MEETING Caroline Alterson to notify Mont.(
DISAPPROVED Signature	Date
11 77 08	
APPLICATION/PERMIT NO: SH-2/-88	FILING FEE: \$
DATE FILED:	BALANCE\$
OWNERSHIP CODE:	RECEIPT NO: FEE WAIVED:
SEE REVERSE SIDI	E FOR INSTRUCTIONS
Conditions: Original window on s	south elevation
	ad stored on the premises,
20 CO NG TEPTAGEL AL	a stored on the premises.

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION

DESCRIPTION OF PROPOSED WORK: (including composition, color and texture of materials to be used:)

 <u></u>
<u>, , , , , , , , , , , , , , , , , , , </u>
 -

(If more space is needed, attach additional sheets on plain or lined paper to this application)

ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.

MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE: HISTORIC PRESERVATION COMMISSION 100 MARYLAND AVENUE ROCKVILLE, MARYLAND 20850



1

Historic Preservation Commission

100 Maryland Avenue, Rockville, Maryland 20850 279-1327

.

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	
NAME OF PROPERTY OWNER <u>Richard & Marcia DalBel</u> (Contract/Purchaser)	La TELEPHONE NO. <u>(301) 270-5429</u> (Include Area Code)
(Contract/Purchaser)	Maryland 20912
CONTRACTOR	TELEPHONE NO
CONTRACTOR REGISTRATIO	N NUMBER
PLANSPREPARED BY Charles G. Poor & Joan Dunc	
Studio Partnership Architec	ts (Include Area Code)
REGISTRATION NUMBER	<u>6869-R</u>
LOCATION OF BUILDING/PREMISE	
House Number 7106 Street Poplar Avenu	e
Town/City Takoma Park Elect	ion District
Nearest Cross Street _ Columbia Avenue	
Lot 24 Block 20 Subdivision B.F. Gilb	
Liber Folio Parcel	
1A. TYPE OF PERMIT ACTION: (circle one) Construct <u>Extend/Add</u> <u>Alter/Renovate</u> Repair	Circle One: A/C Slab Room Addition Porch Deck Fireplace Shed Solar Woodburning Stove
	Fence/Wall (complete Section 4) Other
1B. CONSTRUCTION COSTS ESTIMATE \$ 15,000,00	
	ERMIT SEE PERMIT #
	Internet with a communication of the communication of the communication of the communication of the communication
1E. IS THIS PROPERTY A HISTORICAL SITE? <u>yes</u>	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDIT 2A. TYPE OF SEWAGE DISPOSAL 01 (X) WSSC 02 () Septic 03 () Other	ONS 28. TYPE OF WATER SUPPLY 01 (X) WSSC 02 () Well 03 () Other
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL 4A. HEIGHT feet inches 4B. Indicate whether the fence or retaining wall is to be constructed on one of 1. On party line/Property line 2. Entirely on land of owner	
I hereby certify that I have the authority to make the foregoing application, plans approved by all agencies listed and I hereby acknowledge and accept this to <u>CUMADADADADADADADADADADADADA</u> Signature of owner of authorized agent (agent must have signature notarized on APPROVED	ation Commission APPROVED AT 11/8/88 MEETING
APPLICATION/PERMIT NO:	FILING FEE: \$
DATE FILED:	PERMIT FEE: \$
DATE 1350ED.	BALANCE \$
OWNERSHIP CODE:	RECEIPT NO: Office of BowhivEry Development
SEE REVERSE SIDE FO	
Conditions: Original window on sou	in the second
This does not include	

Application for Historic Area Work Permit 7106 Poplar Ave, Takoma Park, MD 20912

Proposed Work:

1) REPLACE ADDITION -- Owners recently purchased a home at 7106 Poplar Ave. Takoma Park, that had been operated as an illegal, multi-family dwelling. Owners are reconverting the home to a single family residence. The existing addition to this home had been allowed to deteriorate to the point that repair to the structure was no longer practical. The Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. This application describes in detail the proposed replacement addition.

2) ALTER/RENOVATE WINDOWS -- In converting subject house to an illegal, multifamily dwelling, previous owners added several windows that mar the historic appearance of the house. These are to be removed. As a result of an almost complete lack of normal upkeep, several windows have rotted the point where replacement is the only option. These windows are to be replaced in a manner that is sensitive to the historical exterior appearance of the house, yet creates a harmonious visual impression .

DETAILED DESCRIPTION OF THE EFFECT OF PROPOSED ADDITIONS AND RENOVATIONS ON EXISTING ELEVATIONS:

1) EAST ELEVATION (visible from the street) -- Previous owners had added a small third story window to allow light into an illegal third floor apartment. An examination of the window clearly indications that it is a recent, and not A^+B particularly graceful, addition (see photos). Jo Ellen Freese, Assistant Administrator, Maryland Historic Trust, has examined the house and agrees with

this assessment. Owners intend to remove the new window to revert the house to its original appearance. Window area to be closed and covered with stucco to match existing exterior.

2) WEST ELEVATION (Not visible from the street) -- The West elevation is currently dominated by the existing 2-story addition (see photo C). Because of its advanced state of deterioration, the Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. The replacement addition is to be a one-story addition designed to echo the "mission style" appearance created by the existing house, and in particular, the existing front porch. The exterior of the addition will be stucco to match the existing exterior. The north and south walls of the new addition will have the same dimensions as the old addition, but the west wall will be three foot longer (see plat map). The west wall of the addition will contain six casement windows, framed to match the existing wooden window frames. The roof of the addition will also function as a deck. The deck will be enclosed by stucco walls topped with planter boxes designed identically to the planter boxes that are on the front porch.

There are two means of entry into the second story of the existing addition -- a doorway (originally an exterior door to a porch) and a broad opening (not original, added to allow kitchen access to an illegal apartment). The doorway will be reconverted to its original function as an exterior door. The broad opening will be closed to the exterior using glass block. The glass block will be partially obscured by the stucco walls of the deck.

3) SOUTH ELEVATION (<u>Not</u> visible from street because of unique orientation of and photo J house [see plot map]) - The existing two casement windows in the south elevation (first floor, lower left) are in an advanced state of disrepair and D,E, FtLmust be replaced (see photo5). Owner intends to replace these rotten windows with casement windows to match those to be used in the new addition. New addition to contain a group of 4 casement windows. All casement windows to be framed to match the existing wooden window frames.

An examination of the framing and trim indicate that the existing doublehung window (first floor, lower left) does not appear to be original (see G, H+M photos). In addition, the condition of the stucco indicates a recent and major alteration to that wall -- specifically around the area of the double D+I hung window -- has occurred (see photo>).* Owner intends to replace this window with a casement window that will match both those in the new addition and on the first floor. Using one type of window in this area, gives the first floor of the south elevation a visual harmony that it currently lacks (compare existing south elevation drawing with proposed south elevation drawing) but does not disturb the house's unique style.

4) NORTH ELEVATION (House visible from street, addition not visible from see photo K street) -- Owners currently intend no change to the north elevation of the house. The north view of the proposed addition will contain double french doors. Because addition is flush with the south wall of the house, but not the north wall (see plot map and photo C), the addition will not be visible from street.

* This area was originally covered by a wrap-around porch (see 1937 plot map). The double-hung window in question is 4 inches off center (unlike all other windows which are aligned), leading the architects to believe that it is not original and that perhaps the opening was a door to the porch.

MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION

LOCAL ADVISORY COMMITTEE REVIEW FORM

EXTERIOR ALTERATIONS

- I. Location of property
 - a. Located within the <u>Takoma Park</u> historic district.
 - b. This is a Master Plan/Atlas historic district (circle one).
 - c. Address of Property: <u>7106 Poplar Avenue</u> <u>Takoma Park, Maryland</u>
 - d. Property owner's name, address and phone number:

Richard and Marma Dalbello

7106 Poplar Avenue, Takoma Park

(h) 270-5429 (w)

- e. Is this property a contributing resource within the historic district? Yes No_____.
- f. On a map of the district locate this property and any adjacent historic resources. Will this work impact other contributing historic resources? Yes No

II. Description of work proposed.

a. Briefly describe proposed work:

Construct new rear addition (styled to match present porch on house) to replace previous addition (demo previously approved); remove inappropriately added front attic window; remove rear side windows and add new casement windows to make kitchen renovation possible.

b. Is this work on the front, rear, or side of the structure?

Sides and rear. (Addition is on rear)

c. Is the work visible from the street?

Only removal of attic window.

d. What are the materials to be used?

Addition will be stucco with a deck for roof.

4

e. Are these materials compatible with existing materials? How? If not, why?

Yes, present house finish is stucco.

III.Recommendations of the Local Advisory Committee

a. Approval of Work

1. Which criteria found in the Ordinance for Historic Preservation (Sec. 24A-8-b of the Montgomery County Code) does this work meet?

Criteria 2 - work is compatible with the historic character of the house and with the surrounding neighborhood.

2. What conditions, if any, must be met in order for the proposed work to meet the above criteria? (example: the proposed windows should be double hung to conform with existing windows)

One condition - orginal (but deteriorated) window on south elevation (left side) is to be replaced and stored on the premises.

b. Disapproval of Work


1. On what grounds is disapproval recommended? Refer to Sec. 24A-8.


2. How could this proposal be altered so as to be approved?

IV. Additional comments

Date on which application received: 11-10-88

Date of LAC meeting at which application was reviewed: <u>11-10-88</u> Form completed by: <u>Douglas A. Dunn</u> Title: <u>Member LAC</u> Member of: <u>Takoma Park Local Advisory Committee</u> Date: <u>11-11-88</u>






CERTIFICATE	REFERENCES	
I HEREBY CERTIFY THAT THE POSITION OF ALL THE EXISTING IMPROVEMENTS ON THE ABOVE DESCHIBED	PLAT BK A	Bull & Associates
PROPERTY HAS BEEN CAREFULLY ESTABLISHED BY A TRANSIT - TAPE SURVEY.	PLAT NO 2	LAND SURVEYORSGONSULTANTS (301) 428-9111 P.O. Box 346 GERMANTOWN, MARYLAND 2087
	LIBER	DATE OF SURVEYS
DAVID I, HALLER MARYLAND P L.S. NO. 240	FOLIO	WALL CHECK: HOE, LTC.: 6.24-84 BOUNDARY: JOB NO: 812536


SHALF BRU Jaharman and shakama and a shakar shakar shakar

96+1-21026 · 6661 '87 779 Dan Marshinevm holden by Prese אר איז בואיבר אמא מכובים אומשליגן ויאבי אין איז בואיבר איז בעיביע געוב איז איז איז איז איז איז איז איז איז בארפרים ג איז איז הרביע איז באיני איז ג אימיב במוביניווא בעיריאבין איז איזריב איד איזריב איד איזריב איד איזרי **3**8/M . P**P** AUNIVA artapa Columbia di Areni · Mo LI'N Q. 61.00 4890 - 21992d 8.61 X 9.4 ę7 77 97 77 10.02 Lans #1.001 - W OZ .N 1 11 Ó/ ANNTERN CO. MO. YARY AMONAT सः लारहरू इन्स्य प्रवेभः भव ह सः वर्षर्भः इन्स्य glat map 52 PNY 72 5407 SUCATION - HOUTADA 1931



Double hung windows with original trim






south wall (interior) new boards beneath replaced stucco





M interior views SOUTH WALL WINDOWS -



Addition not visible from street









(inside view) B recent window EAST- 3rd Story





430773 most addition cannot be seen trank zwarts along zint ->

JAW HTUOR D

(compare trim with photo H)

Brund -sldcod Wobriu

SHAPELLO TIDE POPLAR AVE. TAKOMA PARK

shoddia TUZHZZAJ (CUSIL SKIRI) JUAM HTUDZ E \mathcal{C} TUODA -TOAA H

Application for Historic Area Work Permit 7106 Poplar Ave, Takoma Park, MD 20912

Proposed Work:

1) REPLACE ADDITION -- Owners recently purchased a home at 7106 Poplar Ave. Takoma Park, that had been operated as an illegal, multi-family dwelling. Owners are reconverting the home to a single family residence. The existing addition to this home had been allowed to deteriorate to the point that repair to the structure was no longer practical. The Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. This application describes in detail the proposed replacement addition.

2) ALTER/RENOVATE WINDOWS -- In converting subject house to an illegal, multifamily dwelling, previous owners added several windows that mar the historic appearance of the house. These are to be removed. As a result of an almost complete lack of normal upkeep, several windows have rotted the point where replacement is the only option. These windows are to be replaced in a manner that is sensitive to the historical exterior appearance of the house, yet creates a harmonious visual impression .

DETAILED DESCRIPTION OF THE EFFECT OF PROPOSED ADDITIONS AND RENOVATIONS ON EXISTING ELEVATIONS:

1) EAST ELEVATION (visible from the street) -- Previous owners had added a small third story window to allow light into an illegal third floor apartment. An examination of the window clearly indications that it is a recent, and not A+B particularly graceful, addition (see photos). Jo Ellen Freese, Assistant Administrator, Maryland Historic Trust, has examined the house and agrees with

this assessment. Owners intend to remove the new window to revert the house to its original appearance. Window area to be closed and covered with stucco to match existing exterior.

2) WEST ELEVATION (Not visible from the street) -- The West elevation is currently dominated by the existing 2-story addition (see photo \mathbb{C}). Because of its advanced state of deterioration, the Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. The replacement addition is to be a one-story addition designed to echo the "mission style" appearance created by the existing house, and in particular, the existing front porch. The exterior of the addition will be stucco to match the existing exterior. The north and south walls of the new addition will have the same dimensions as the old addition, but the west wall will be three feet longer (see plat map). The west wall of the addition will contain six casement windows, framed to match the existing wooden window frames. The roof of the addition will also function as a deck. The deck will be enclosed by stucco walls topped with planter boxes designed identically to the planter boxes that are on the front porch.

There are two means of entry into the second story of the existing addition -- a doorway (originally an exterior door to a porch) and a broad opening (not original, added to allow kitchen access to an illegal apartment). The doorway will be reconverted to its original function as an exterior door. The broad opening will be closed to the exterior using glass block. The glass block will be partially obscured by the stucco walls of the deck.

3) SOUTH ELEVATION (Not visible from street because of unique orientation of and photo J house [see plot map]) - The existing two casement windows in the south elevation (first floor, lower left) are in an advanced state of disrepair and must be replaced (see photo5). Owner intends to replace these rotten windows with casement windows to match those to be used in the new addition. New addition to contain a group of 4 casement windows. All casement windows to be framed to match the existing wooden window frames.

یک میں ا

An examination of the framing and trim indicate that the existing doublehung window (first floor, lower left) does not appear to be original (see G_1 , H^+M photos). In addition, the condition of the stucco indicates a recent and major alteration to that wall -- specifically around the area of the double $D^+ \mathfrak{l}$ hung window -- has occurred (see photos).* Owner intends to replace this window with a casement window that will match both those in the new addition and on the first floor. Using one type of window in this area, gives the first floor of the south elevation a visual harmony that it currently lacks (compare existing south elevation drawing with proposed south elevation drawing) but does not disturb the house's unique style.

4.1

4) NORTH ELEVATION (House visible from street, addition not visible from See photo K street) -- Owners currently intend no change to the north elevation of the house. The north view of the proposed addition will contain double french doors. Because addition is flush with the south wall of the house, but not the north wall (see plot map and photo \mathbb{C}), the addition will not be visible from street.

* This area was originally covered by a wrap-around porch (see 1937 plot map). The double-hung window in question is 4 inches off center (unlike all other windows which are aligned), leading the architects to believe that it is not original and that perhaps the opening was a door to the porch.

Application for Historic Area Work Permit 7106 Poplar Ave, Takoma Park, MD 20912

Proposed Work:

1) REPLACE ADDITION -- Owners recently purchased a home at 7106 Poplar Ave. Takoma Park, that had been operated as an illegal, multi-family dwelling. Owners are reconverting the home to a single family residence. The existing addition to this home had been allowed to deteriorate to the point that repair to the structure was no longer practical. The Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. This application describes in detail the proposed replacement addition.

2) ALTER/RENOVATE WINDOWS -- In converting subject house to an illegal, multifamily dwelling, previous owners added several windows that mar the historic appearance of the house. These are to be removed. As a result of an almost complete lack of normal upkeep, several windows have rotted the point where replacement is the only option. These windows are to be replaced in a manner that is sensitive to the historical exterior appearance of the house, yet creates a harmonious visual impression .

DETAILED DESCRIPTION OF THE EFFECT OF PROPOSED ADDITIONS AND RENOVATIONS ON EXISTING ELEVATIONS:

1) EAST ELEVATION (visible from the street) -- Previous owners had added a small third story window to allow light into an illegal third floor apartment. An examination of the window clearly indications that it is a recent, and not A + B particularly graceful, addition (see photos). Jo Ellen Freese, Assistant Administrator, Maryland Historic Trust, has examined the house and agrees with this assessment. Owners intend to remove the new window to revert the house to its original appearance. Window area to be closed and covered with stucco to match existing exterior.

2) WEST ELEVATION (Not visible from the street) -- The West elevation is currently dominated by the existing 2-story addition (see photo \mathbb{C}). Because of its advanced state of deterioration, the Montgomery County Historic Preservation Commission granted permission to demolish this addition on November 3, 1988. The replacement addition is to be a one-story addition designed to echo the "mission style" appearance created by the existing house, and in particular, the existing front porch. The exterior of the addition will be stucco to match the existing exterior. The north and south walls of the new addition will have the same dimensions as the old addition, but the west wall will be three feet longer (see plat map). The west wall of the addition will contain six casement windows, framed to match the existing wooden window frames. The roof of the addition will also function as a deck. The deck will be enclosed by stucco walls topped with planter boxes designed identically to the planter boxes that are on the front porch.

There are two means of entry into the second story of the existing addition -- a doorway (originally an exterior door to a porch) and a broad opening (not original, added to allow kitchen access to an illegal apartment). The doorway will be reconverted to its original function as an exterior door. The broad opening will be closed to the exterior using glass block. The glass block will be partially obscured by the stucco walls of the deck.

3) SOUTH ELEVATION (Not visible from street because of unique orientation of and photo J house [see plot map]) - The existing two casement windows in the south elevation (first floor, lower left) are in an advanced state of disrepair and must be replaced (see photos). Owner intends to replace these rotten windows with casement windows to match those to be used in the new addition. New addition to contain a group of 4 casement windows. All casement windows to be framed to match the existing wooden window frames.

An examination of the framing and trim indicate that the existing doublehung window (first floor, lower left) does not appear to be original (see G_1 , H^+H photos). In addition, the condition of the stucco indicates a recent and major alteration to that wall -- specifically around the area of the double D+Ihung window -- has occurred (see photos).* Owner intends to replace this window with a casement window that will match both those in the new addition and on the first floor. Using one type of window in this area, gives the first floor of the south elevation a visual harmony that it currently lacks (compare existing south elevation drawing with proposed south elevation drawing) but does not disturb the house's unique style.

4) NORTH ELEVATION (House visible from street, addition <u>not</u> visible from <u>see</u> photo street) -- Owners currently intend no change to the north elevation of the house. The north view of the proposed addition will contain double french doors. Because addition is flush with the south wall of the house, but not the north wall (see plot map and photo \mathbb{C}), the addition will not be visible from street.

* This area was originally covered by a wrap-around porch (see 1937 plot map). The double-hung window in question is 4 inches off center (unlike all other windows which are aligned), leading the architects to believe that it is not original and that perhaps the opening was a door to the porch.



parts, B.B.L. Iphymatical analysis provide the second second

3 0 Ø Ø ° • • • ě. . 1.e 1937 LOGATION OF MOUSE plat map 4078 83 110 25 BLOOK BO BR GROBATS ADOM TO TABOMA PARS Manacontest Confilo Ð Ø B nonti 50.07 5007 B \mathscr{B} Ð ØB ĎО පිහිතු Read ER മള് *4*20-420 ETA face aborto Columbia Are . ROPARS WINTS. ഹിത്രാ ו לא שלים ערבו לא לאמיר שינים אינים אינ אינים אינ אינים אינ ත ශ්ය aplin up Prim AND A WAY AND A WAY



7


-

.



. 🖌

1



.

<u>المر.</u>

هندر


































photo #5 The DalBellos 7106 Poplar Avenue Takoma Park, MD 20912-4640



photo #4 The DalBellos 7106 Poplar Avenue Takoma Park, MD 20912-4640



