

HISTORIC PRESERVATION COMMISSION

Marc Elrich

County Executive

Robert Sutton *Chairman*

January 8, 2025

MEMORANDUM

TO:	Rabbiah Sabbakhan
	Department of Permitting Services
FROM:	Dan Bruechert
	Historic Preservation Section
	Maryland-National Capital Park & Planning Commission
SUBJECT:	Historic Area Work Permit # 1086783 - Partial Demolition, Two Story Addition, Hardscape Alteration, and Tree Removal

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **Approved** at the December 4, 2024 HPC meeting.

The HPC staff has reviewed and stamped the attached submission materials.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HAWP CONDITIONS AND MAY REQUIRE APPROVAL BY DPS OR ANOTHER LOCAL OFFICE BEFORE WORK CAN BEGIN.

Applicant:Salem BadawyAddress:10012 Menlo Ave., Silver Spring

This HAWP approval is subject to the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made. Once work is complete, the applicant will contact Dan Bruechert at 301-563-3408 or <u>dan.bruechert@montgomeryplanning.org</u> to schedule a follow-up site visit.



ADDITION/ RENOVATION

10012 MENLO AVE SILVER SPRING MD

A.F.F. ALT. b/o BTU BW.T. CFM C.M. CONC. CONCONC. CONC. CONC ABOVE I EXPANSION ALTERNAME ALTERNAME BRITISH BEARLOAD CONTRELECTION CONTRELECTION CONTRELECTION EACH ELECTING ELECTING CONVERTING C GENERAL NOTES 1. All Contractors shall be licensed and bonded for work in Montgomery County Maryland 2. Construction work shall conform to all applicable building codes for Montgomery County MD, including International Residential Code 2018 3. Contractor shall be responsible for obtaining all necessary building permits. Architectural and Structural drawings will be provided. 4. All dimensions are to face of finish, unless otherwise noted. 5. Contractor shall verify all field conditions prior to construction. The Contractor shall check, coordinate and verify all dimensions and construction details before starting any construction. **SYMBO** Written dimensions on the drawing shall have precedence over scaled dimensions. The contractor shall not scale dimensions from any drawing or detail. If a dimension is not provided PLAN DETAL the contractor shall notify Designer for clarification. 6. Contractor shall keep the construction site in an orderly manner and provide daily clean-up of construction debris. 7. All contractors working or contracted to have work preformed on the job site shall be licensed and bonded and carry Liability and worker's compensation insurance. 8. The Contractor shall be solely responsible for all construction means, methods, techniques, sequences and procedures and for coordinating all portions of the work under contract. (XX) 000 XX NNC CODE INFORMATION XXXX ROOM GOVERNING BUILDING CODES: ALL CONSTRUCTION SHALL COMPLY WITH THE FOLLOWING CODES AND AMENDMENTS PER ELEV. THEIR ADOPTING ORDINANCES: $\widehat{}$ 2021 IRC RESIDENTIAL ×-----ICC RESIDENTIAL CODE 2018 INTERNATIONAL MECHANICAL CODE 2018 ç NATIONAL ELECTRICAL CODE 2018 2021 ICC PLUMBING CODE MATERIA 2021 ICC FIRE CODE 2021 ICC ENERGY CONSERVATION CODE 2021 ICC GREEN CONSTRUCTION CODE LOT/SQUARE: ____ ZONING CLASSIFICATION: CURRENT USE CODE: RESIDENTIAL 700000 PROPOSED USE CODE: RESIDENTIAL - SINGLE FAMILY SWAR PROPERTY. ALLOWED (CODE) PROVIDED (PROPOSED) CARGONICARDON GROSS SQ. FOOTAGE . FT. (EXISTING) 11/1/1/1/1/1/ LOT AREA MIN. 5,000 SQ. FT. LOT WIDTH MIN. 50 FT. www.www SIDE YARD SETBACK 7' FT' MIN +/- 15' EAST, +/-15' WEST 20000000 30 FT MIN. REAR YARD SETBACK +/- 141' LOT OCCUPANCY / COVERAGE LESS THAN 40% 40 % HEIGHT OF BUILDING 40 FT MAX LESS THAN 40 FT NUMBER OF STORIES 2 STORY 2 STORY

STANDARD ABBREVIATIONS ATT MORE TRADE ATT LOC MORE TRADE LOC Martineza Martineza Martineza	Image: series of the series
	INDEX OF DRAVNINGS A1 - COVER SHEET A2 - SITE FLAN A3 - EXIST FLOOR PLAN A3 - EXIST FLOOR PLAN A4 - FIRST FLOOR PLAN A5 - SECOND FLOOR PLAN A6 - ELEVATIONS A7 - ELEVATIONS A1 - CROSS SECTION AA, NALL SECTION A12 - CROSS SECTION AA, NALL SECTION A13 BRACED WALL PLAN A14 - STRUCTURAL NOTES BRACED WALL DETAILS A15 - THERMAL ENVELOPE A16 - THERMAL ENVELOPE A16 - THERMAL NOTES BRACED FLOOR ADDITION SCOPE OF WORK SECOND FLOOR ADDITION REMODEL FIRST FLOOR, AND ADDITION REMODEL FIRST FLOOR, AND ADDITION REMODEL FIRST FLOOR, AND ADDITION
MATERIALS LEGEND	LOCATION Image: Constraint of the second state system required for addition and existing house 10012 MENLO AVE SILVER SPRING MD SQUARE FOOTAGE SUMMARY FIRST FLOOR REMODEL - 11740 SF SECOND FLOOR ADDITION - 1465 SF FRONT PORCHES - 160 SF PROPOSED NEW HOUSE NOTE: FIRE SPRINKLER SYSTEM REQUIRED FOR ADDITION AND EXISTING HOUSE
REVIEWED By Dan Bruechert at 2:07 pm, Jan 08,	2025



REVIEWED By Dan Bruechert at 2:10 pm, Jan 08, 2025



WINDOW SCHEDULE							
NUMBER	QTY	SIZE	R/0	EGRESS	DESCRIPTION	COMMENTS	
W01	8	2660SC	31"X 73"		CASEMENT		
W02	12	2466SC	29"X 67"		CASEMENT		
W03	1	2-2660SC	61"X 73"		DBL CASEMENT		
W04	1	6040FX	73"X 49"		FIXED GLASS		
W05	3	4016FX	49"X 19"		FIXED GLASS	TEMPERED	
W06	1	5016FX	61"X 19"		FIXED GLASS	TEMPERED	
W07	1	2-2466SC	58"X 67"		DBL CASEMENT		
W08	1	6060FX	73"X 73"		FIXED GLASS	TEMPERED	

GENERAL NOTES:

 VALES INDUCTED OTHERVISE, DIVERSIONS ARE FACE TO FACE OF FRAMMO.
 VIEW, ALL LOTTING'S BEER AND TALKAD INVERSIONS IN THE VIEW, ALL LOTTING'S BEER AND TALKAD INVESTIGATIONS VIEW, ALL LOTTING'S BEER AND TALKAD INVESTIGATIONS VIEW AND TALKAD INVESTIGATIONS AND TALKAD INVESTIGATION AND TALKAD INVESTIGATION AND

MALL TYPES

TYPICAL EXTERIOR WALL: 2% WOOD STUDS @ 16° OC WITH R-21 OPEN CELL FOAM INSULATION OR FIERSALASS BATT INSULATION TIS' OBS HEATING TYPES BUILDING WARF AND BRICK VENEER OR SIDBO. SEE ELEVATIONS. INTERIOR FINISH TO BE 12° SYP. BO. TYPICAL INTERIOR WALL: 24 WOOD STUDS @ 16° OC WITH 12° SYP. BO. EACH SIDE, UNLESS OTHERWISE NOTED

DENOTES PROPOSED WALLS

DENOTES REMOVED WALLS

APPROVED

Montgomery County

Historic Preservation Commission

Ramen home

REVIEWED By Dan Bruechert at 2:10 pm, Jan 08, 2025



NUMBER	QTY	SIZE	R/0	EGRESS	DESCRIPTION	COMMENTS
W01	8	2660SC	31"X 73"		CASEMENT	
W02	12	2466SC	29"X 67"		CASEMENT	
W03	1	2-2660SC	61"X 73"		DBL CASEMENT	
W04	1	6040FX	73"X 49"		FIXED GLASS	
W05	3	4016FX	49"X 19"		FIXED GLASS	
W06	1	6016FX	73"X 19"		FIXED GLASS	
W07	1	2-2466SC	58"X 67"		DBL CASEMENT	
W08	1	6060FX	73"X 73"		FIXED GLASS	

GENERAL NOTES:

1. UNLESS INDICATED OTHERINISE, DIMENSIONS ARE FACE TO FACE OF FRAMING
2. VERIFY ALL EXTERIOR RISER AND TREAD DIMENSIONS IN THE FIFLD
3. ALL SMOKE/GARBON MOXOXIDE DETECTORS TO BE HARD-WIRED
TO DEDICATED CIRCUT, INTERCONNECTED & PROVIDED
WITH BATTERY BACKUP, OR 10 YEAR BATTERY
4. PROVIDE CARBON MOXOXIDE ALARMS PER R315.1
 ALL STAIRS HANDRAILS AND CAURDS SHALL BE CONSTRUCTED IN ACCORDANCE WITH SECTION R311 AND R312 OF THE 2018 IRC.
 SEE FRAMING PLANS FOR COORDINATION OF POST REQUIREMENTS.
1. ALL INTERIOR PARTITIONS NOT DIMENSIONED SHALL BE 3 1/2"
8. ALL ANGLES ARE 40 AND OR 45 UNLESS NOTED OTHERWISE.
9. REFER TO EXTERIOR ELEVATIONS & DOOR/ WINDOW SCHEDULE
FOR WINDOW HEAD HEIGHTS.
10. ALL DOORS DIMENSIONS GIVEN IN FEET AND INCHES.

WALL TYPES

TYPICAL EXTERIOR INALL 3:4 WOOD STUDS ()) IS '0 CHITH R.1 OPEN CELL FORM INSULATION OR REBERGUES BATT INSULATION 11/6' 055 SHEATHING TYVER BUILDING WRAP AND BRICK VENEER OR SIDINS' SEE ELEVATIONS, INTERIOR FINISH TO BE 12' OYF. BD. TYPICAL INTERIOR INALL 3:4 WOOD STUDS ()) IS '0 CHITH 12' OYF. BD. EACH SIDE, UNLESS OTHERWISE NOTED

DENOTES REMOVED WALLS
 DENOTES EXISTING WALLS
 DENOTES EXISTING WALLS

APPROVED

Montgomery County Historic Preservation Commission

Route h. Matter

REVIEWED By Dan Bruechert at 2:10 pm, Jan 08, 2025





By Dan Bruechert at 2:10 pm, Jan 08, 2025



















All construction shall meet the 2021 IRC &2021 IECC Energy Codes, 2021 IRC Wall Bracing requirements, and the Building Thermal Envelope design plans & cross section(s).

Line of Thermal Building Envelope There are NO crawlspace areas.

INSULATION & FENESTRATION BY COMPONENT

	- V	alue		
Component	U	SHGC	R	×
Windows/transoms	0.34	0.31		
Sliding glass doors/transoms	0.34	0.31		
Skylights - Dbl glazed	0.60	0.00		
French doors	0.46	0.50	0.50	
Solid doors	0.40			
Roof raftered ceiling			30.0	
Roof trussed ceiling			38.0	
Cathedral ceiling			30.0	
2x6 wood frame wall			19.0	
2x4 wood frame wall			13.0	
Basement wall above grade			13.0	
Basement wall below grade			13.0	
Crawl space (unheated) walls			0.00	
Floors over unconditioned spa	ce		30.0	
Floors over garage			30.0	
Floors over outside air			30.0	
Floors cantilevered outside			30.0	
Concrete slab near grade			10 @ 2	ft depth
Elevator shaft into attic			13.0	

AIR LEAKAGE:

All areas of the building thermal envelope shall be durably sealed against air leakage. The following areas shall be sealed against air leakage by caulked, gasketed, weatherstripped, or otherwise sealed with an air barrier material, suitable film, or solid material to allow for differential expansion or

1. All joints, seams, and penetrations.

- 2. Site-built windows, doors, and skylights. 3. Openings between window and door assemblies and their respective jambs
- framing.
- Utility penetrations.
 Dropped ceilings or chases adjacent to the thermal envelope.
- 6. Knee walls.
- Walls and ceilings separating a garage from conditioned spaces.
- Behind tubs and showers on exterior walls.
- Common walls between dwelling units. 10. Attic access openings,
- Rim joist junction.
 Other sources of infiltration.

LIGHTING FIXTURES:

Recessed lighting fixtures installed in the thermal envelope shall be sealed to limit leakage between conditioned and unconditioned spaces. All recessed lighting fixtures shall be IC listed. Seal all recessed lighting fixtures shall be sealed with a gasket or caulk between the housing and the interior wall or ceiling covering. between the housing and the interior wall or ceiling covering. A minimum of 50% of the lamps in permanently installed light fixtures shall be high efficiency lamps.

Apolicant Name:

GLAZED

KYLIGHTS

MASS WALLS

FLOORS SLAB PERIMETER

CEILINGS

CRITERIA

HVAC DUCT SEALING:

All joints of duct systems shall be made substantially airtight by means of All pinits of ouch systems afon be mode subschroundy ortginght by means of tipes, mostics, liquid selonts, geaketing, or other approved closure systems. Closure systems used with rigid fibrous glass ducts shall comply with ULBIA and shall be morted as required by 2020 rIKC Sect. MIGDI.4.1. Closure systems used with fieldbe or auccs and fieldbe of connectors shall comply with ULBIB and shall be marked as required by 2021 KC Sect. M1601 4 1

MIG01.4.1. Duct connections to flanges of air distribution system equipment or sheet metal fittings shall be mechanically fastmed. Mechanically distreted pints shall be as specified by the 2021 IRC Sect. Cosure systems used to seel metal ductanck shall be installed per the monufacture? installation instructions.

Exceptions:

1. Spray polyurethane foam shall be permitted to be applied without additional inint seals

point seais. 2. Where a duct connection is made that is partially inaccessible, three screws or rivets shall be equally spaced on the exposed partion of the joint so as to prevent a hinge effect.

Continuously welded and locking type longitudinal joints and seams in ducts operating at static pressures less than 2 inches of water column pressure classification shall not require additional closure systems.



By Dan Bruechert at 2:10 pm, Jan 08, 2025

Memorandum



Date: 20 December 2024

To: Salem Badawy, Alpha Houses LLC

From: Young Kim

Project #: 24-508DL_10012 Menlo Ave

Subject: Evaluation of existing foundation - 10012 Menlo Ave, Silver Spring, MD 20902

Objective:

Evaluate the existing foundation to confirm its capacity to support a new one-story addition to the existing house. See figure 1 for the existing house foundation to remain and figure 2 for the floor framing of new addition.

Methodology & Assumption:

- Review of building drawings dated September 2024 and provided by JDK Design.
- Total estimated wall loading for new addition: 1934 PLF for the front wall and 600 PLF for the side walls.
- Total estimated column loading for 6x6 post: 6900 LBS
- Assumed soil bearing pressure of 1500 PSF is used to evaluate the existing foundation.
- On-site investigation, including excavation of two test pits at the front and side walls of the existing house, to measure the existing footing size. See figure 1 for the location of the test pit.

Findings:

We visited the site on December 19, 2024, and verified that the existing footing has a min 4" toe from the exterior face of 8" CMU wall and a thickness over 12". Hence, the total width of the existing footing is at least 16" wide based on the assumption that the interior has same 4" toe. See figures 3 & 4.

Conclusion:

Based on the measurements obtained from the test pits and the review of the building drawings, the existing wall foundation is adequate to support the additional load from the one-story addition.

However, the existing wall footing is not adequate for the 6x6 post. Underpinning with a 2'-6"x2'-6" footing is required to support the estimated column load of 6900 LBS.

Sincerely,

TEC



Young Kim, P.E.

"Professional Certification. I hereby certify that these documents were prepared or approved by me, and that I am a duly licensed professional engineer under the laws of the state of Maryland, License No.41399 Expiration Date: 1/5/26"

APPROVED

Montgomery County

Historic Preservation Commission

amen./h

REVIEWED By Dan Bruechert at 2:23 pm, Jan 08, 2025



Figure 1 - Foundation Plan



Figure 2 - 2nd floor framing plan



Figure 3 - Test Pit 1



Figure 4 - Test Pit 2

New Thuja Green Giant Aborative 5x

12' x 16' BLUESTONE PATIO-

CONC PAVERS-

3.5' HIGH CEDAR FENCE (from front porch to back wall)

> EXIST PORCH_ TO REMAIN

New power service line connection

CONC PAVERS-

2' HIGH RETAINING WALL STONE VENEER

APPROVED Montgomery County Historic Preservation Commission

REVIEWED By Dan Bruechert at 2:29 pm, Jan 08, 2025



			REVISIONS 6/23/24
OOD FENCE			
RETAINING WALL			
			OMES OHNS LANE CITY MD
ED NEW HOUSE			ALPHA HC 3901 ST.J ELLICOTT
G HOUSE			
H RETAINING WALL E VENEER			ADDITION / RENOVATION 10012 MENLO AVENUE SILVER SPRING MD 2090
porch to back wall)			
ERS			4BER 2024 4S NOTED
PORCH OND FLR ABOVE			AN SEPTEN SCALE
CONC DRIVEWAY IAIN	Evicting Law	so footonint. 1625	SITE PL
nection	Proposed hou	se footprint: 1825 se footprint: 1826	05ED
MIN. 5,000 S MIN. 50 FT.	 Q. FT.	EXIST/ PROPOSED 8,710 SF +/- 60'	a a b a b a b a b a b a b a b a b a b a
15 FT' TOT. 30 FT MIN 40 % 40 FT MAX 2 STORY	AL	+/- 8' EAST, +/-7' WEST +/- 54' LESS THAN 40% LESS THAN 40 FT 2 STORY	A-2
E		38335F	



Salem Badawy 10012 Menlo Avenue Silver Spring, MD 20910 Mobile Phone: 301-401-6662 E-Mail Address: salem.dmv@gmail.com Printed on: 9/13/2024 Created on: 8/27/2024

Bartlett Tree Experts Christopher Larkin - Representative 1 Metropolitan Court Gaithersburg, MD 20878 Business: 301-881-8550 Mobile Phone: 240-447-0837 E-Mail Address: CLarkin@Bartlett.com Bus. Reg. ID: MDA-1329

MD Applicator Certification No.: 7261 / LTE616

The following program is recommended for certain trees and shrubs on your property. In addition to a thorough plant health care program, or the specific services recommended, Bartlett Tree Experts also recommends having a tree risk assessment qualified arborist conduct a tree risk assessment on your property periodically to assist you in identifying potential risks of tree or limb failure and the potential consequences of such tree or limb failure relating to your trees and shrubs. An inspection of trees or shrubs for the purpose of writing a recommendation or conducting plant health care or tree care services is not a tree risk assessment. THIS IS NOT AN INVOICE.

Tree and Shrub Work:

Removal

Remove the following foundation encroaching property items:

- (9") double stem Hemlock (ID# 2) located at the right front of house
- + (12'') double stem Hemlock (ID# 3) located at the center front of house
- (22") Hemlock (ID# 4) located at the left front house corner
- (10'') Cedar (ID# 9) located at the left side of house

Leave stumps as close to grade as possible. Remove resulting debris.

Estimated Completion Date: 10/1/2024 thru 10/30/2024

Arborist Notes:

• Four trees encroach on the foundation the largest only 12 inches away. These trees were planted as accents to the house but now, disproportionately tower over the house and can threaten the foundation exploiting any existing flaws.

REVIEWED

The health of the hemlocks has been affected by the weather, spider mites and the the overall vigor fair to poor. The Cedar, is in fair health with sparse foliage, spider

Montgomery County Historic Preservation Commission

APPROVED

RAMEL. MA

Removal is recommended for these trees to protect the foundation.

By Dan Bruechert at 2:29 pm, Jan 08, 2025

Page **23**f 4

Printed on: 9/13/2024 Created on: 8/27/2024

Please review the terms and conditions attached, which become part of the agreement, and sign and return one copy authorizing the program.

(Customer Signature) Larkin

(Bartlett Representative - Christopher Larkin)

(Date)

9/13/2024 (Date)

Prices are guaranteed if accepted within thirty days. All accounts are net payable upon receipt of invoice. Work is done in accordance with ANSI A300 Tree Care Standards.

To access a certificate of liability insurance for Bartlett Tree Experts, please navigate to http://www.bartlett.com/BartlettCOI.pdf

A Job Site Safety Analysis was completed for your property, please contact your arborist for further details.

APPROVED Montgomery County **Historic Preservation Commission** RAMEL

REVIEWED By Dan Bruechert at 2:29 pm, Jan 08, 2025

Removal

Two mature Hemlocks 18" from the foundation. Too close to the foundation.



APPROVED Montgomery County Historic Preservation Commission

amen home

REVIEWED By Dan Bruechert at 2:29 pm, Jan 08, 2025

Removal

Massive Hemlock 12 inches from the foundation and Cedar 24 inches from foundation.





Salem Badawy 10012 Menlo Avenue Silver Spring, MD 20910 Mobile Phone: 301-401-6662 E-Mail Address: salem.dmv@gmail.com Printed on: 9/13/2024 Created on: 8/27/2024

Bartlett Tree Experts Christopher Larkin - Representative 1 Metropolitan Court Gaithersburg, MD 20878 Business: 301-881-8550 Mobile Phone: 240-447-0837 E-Mail Address: CLarkin@Bartlett.com Bus. Reg. ID: MDA-1329

MD Applicator Certification No.: 7261 / LTE616

The following program is recommended for certain trees and shrubs on your property. In addition to a thorough plant health care program, or the specific services recommended, Bartlett Tree Experts also recommends having a tree risk assessment qualified arborist conduct a tree risk assessment on your property periodically to assist you in identifying potential risks of tree or limb failure and the potential consequences of such tree or limb failure relating to your trees and shrubs. An inspection of trees or shrubs for the purpose of writing a recommendation or conducting plant health care or tree care services is not a tree risk assessment. THIS IS NOT AN INVOICE.

Tree and Shrub Work:

Removal

Remove the leaning with limited root (41") Red Oak (ID# 1) located at the back of house. Leave stump as close to grade as possible. Remove resulting debris.

Estimated Completion Date: 10/1/2024 thru 10/30/2024

Arborist Notes:

• The 41" diameter Red Oak in the rear has a pronounce lean toward the rear neighboring house. No counterbalancing limbs are present to offset the gravitational pull on this tree. The stem is 17 inches from the decaying timber wall and 39 inches from the house. Replacement of the timber wall has a high risk of causing failure of the root system with severe results. Removal is recommended.

Please review the terms and conditions attached, which become part of the agree authorizing the program.

(Customer Signature)

Christighoankin

(Bartlett Representative - Christopher Larkin)

APPROVED

Montgomery County

Historic Preservation Commission

(Dat MEL 9/13(Dat



Printed on: 9/13/2024 Created on: 8/27/2024

Prices are guaranteed if accepted within thirty days. All accounts are net payable upon receipt of invoice. Work is done in accordance with ANSI A300 Tree Care Standards.

To access a certificate of liability insurance for Bartlett Tree Experts, please navigate to http://www.bartlett.com/BartlettCOI.pdf

A Job Site Safety Analysis was completed for your property, please contact your arborist for further details.

APPROVED

Montgomery County Historic Preservation Commission

amth. M

REVIEWED By Dan Bruechert at 2:29 pm, Jan 08, 2025

Removal

Red Oak rear leaning away from the house all weight is unbalanced over the rear of the property.



Removal

Red Oak rear 17" from the timber wall 39" from the house.





Salem Badawy 10012 Menlo Avenue Silver Spring, MD 20910 Mobile Phone: 301-401-6662 E-Mail Address: salem.dmv@gmail.com Printed on: 9/17/2024 Created on: 8/27/2024

Bartlett Tree Experts Christopher Larkin - Representative 1 Metropolitan Court Gaithersburg, MD 20878 Business: 301-881-8550 Mobile Phone: 240-447-0837 E-Mail Address: CLarkin@Bartlett.com Bus. Reg. ID: MDA-1329

MD Applicator Certification No.: 7261 / LTE616

The following program is recommended for certain trees and shrubs on your property. In addition to a thorough plant health care program, or the specific services recommended, Bartlett Tree Experts also recommends having a tree risk assessment qualified arborist conduct a tree risk assessment on your property periodically to assist you in identifying potential risks of tree or limb failure and the potential consequences of such tree or limb failure relating to your trees and shrubs. An inspection of trees or shrubs for the purpose of writing a recommendation or conducting plant health care or tree care services is not a tree risk assessment. THIS IS NOT AN INVOICE.

Tree and Shrub Work:

Removal

Remove the large (29'') White Oak (ID# 5) located at the right front of house. Leave stump as close to grade as possible. Remove resulting debris. Estimated Completion Date: 10/1/2024 thru 10/30/2024

Arborist Notes:

• The 30 inch diameter White Oak in front is in a raised planter 6 to 14 inches above grade and 24 inches away from the driveway. The driveway new or refurbished impacted the root system when it was installed.

The edge of the planter and the driveway, less than 1 tree diameter away from the tree, well within the structural root zone (3 times the tree diameter at 4.5 feet above grade) of the of the white oak, potentially compromise its stability.

The unnatural elevation of the tree above the existing yard grade adds to the risk of failur existing grade to sharply bend which is not as structurally supportive as an unbent root.

This tree has a moderate to high risk of failure with severe consequences.

APPROVED

Montgomery County

Historic Preservation Commission

RAMEL. M.

REVIEWED By Dan Bruechert at 2:30 pm, Jan 08, 2025

Printed on: 9/17/2024 Created on: 8/27/2024

Please review the terms and conditions attached, which become part of the agreement, and sign and return one copy authorizing the program.

(Customer Signature) Larkin

(Bartlett Representative - Christopher Larkin)

(Date)

9/17/2024

(Date)

Prices are guaranteed if accepted within thirty days. All accounts are net payable upon receipt of invoice. Work is done in accordance with ANSI A300 Tree Care Standards.

To access a certificate of liability insurance for Bartlett Tree Experts, please navigate to http://www.bartlett.com/BartlettCOI.pdf

A Job Site Safety Analysis was completed for your property, please contact your arborist for further details.

APPROVED Montgomery County Historic Preservation Commission MACH REVIEWED By Dan Bruechert at 2:30 pm, Jan 08, 2025

Printed on: 9/17/2024 Created on: 8/27/2024

Removal

White Oak if front 24 inches from the driveway





PRODUCT: Horizontal Bead Reveal

ITEM ID: BRH516, BRH716

Designed to work as part of a system with Vertical Bead Reveal. XtremeTrim® Horizontal Bead Reveal provides a minimal exposure while providing protection for the top edge of the lower panel.





REVIEWED By Dan Bruechert at 2:30 pm, Jan 08, 2025



ITEM ID	"A"	"B"	"C"
BRH516	1/8"	3/8"	1-1/8"
BRH716	1/8"	1/2"	1-1/8"

AVAILABLE COLORS:

Horizontal Z trim ... installed between new Hardie panels and existing block walls. No. 13 on the elevations



LEDGER FLASHING

PRODUCT: Stone Ledger Flashing

ITEM ID: BL

Designed to prevent siding and trim being butted directly against mortar or masonry, including stone and brick.

*Hem Available upon request with primed. *All standard colors with hem.



Fascia

1x6 Pine Trim fascia Board covered with aluminum fascia

Windows

A combination of fixed and casement windows. All windows are aluminum clad windows.

Brand: Andersen E-Series casement windows - Aluminum-Clad Wood Or PLY GEM MIRA Series Windows - Aluminum-Clad Wood



A solid wood core and extruded aluminum cladding give E-Series windows both strength and flexibility in many design applications.

> E-Series casement window with Terratone exterior color



REVIEWED By Dan Bruechert at 2:30 pm, Jan 08, 2025





Ply Gem MIRA Series

Aluminum-clad wood windows that offer the timeless beauty of wood windows with durable aluminum clad exterior.



MIRA Fixed Windows in Black

MIRA Series - Casement Windows





MIRA WINDOWS

FEATURES & BENEFITS

From natural shades to vibrant colors, an extensive portfolio of 46 exterior colors allows you to truly set your home apart.

APPROVED

Solid wood interiors can be stained or painted to match other finishes inside your home.

Durable extruded aluminum exterior protects wood from the elements while offering low maintenance and long-lasting beauty.

Experience more natural light and wide open views

with a large glass area.

Montgomery County Historic Preservation Commission

Rame h. Matta

REVIEWED By Dan Bruechert at 2:30 pm, Jan 08, 2025

MIRA Series						
Glass Package	R-Value	U-Factor	Solar Heat Gain Coefficient (SHGC)	Visible Transmittance (VT)		
		Awning				
НР	3.13	0.32	0.27	0.48		
HPSC	3.13	0.32	0.20	0.38		
HP2+	3.45	0.29	0.26	0.47		
HP2+ ^{SC}	3.45	0.29	0.20	0.37		
		Casement				
НР	3.13	0.32	0.27	0.48		
HPSC	3.13	0.32	0.20	0.38		
HP2+	3.57	0.28	0.26	0.47		
HP2+ ^{SC}	3.57	0.28	0.19	0.37		

Window Trim

1 x 2 Pine wood trim board (Actual: 3/4 in. x 1-1/2 in.)





Window Sill on Block/Stucco Walls





Entry doors:

Main entry door: right porch, Glazed full light door Andersen 102 Straightline Glass Panel

Panel Style 102 Straightline Glass Panel



Panel style: Traditional aluminum-clad wood Traditional panels feature 4 11/16" stiles with a choice of 4 11/16", 8" or 12" bottom rail heights.



Entry door: Left porch

Glazed full light door



Traditional aluminum-clad wood

Traditional panels feature 4 11/16" stiles with a choice of 4 11/16", 8" or 12" bottom rail heights.

8" bottom rail height shown



REVIEWED

By Dan Bruechert at 2:30 pm, Jan 08, 2025

Panel Style 102 Straightline Glass Panel



Notes:

Actual wood is sapele, a non-endangered species of mahogany, grown in Africa, with color and characteristics similar to American mahoganies.



Back patio door

MIRA Aluminum-Clad Wood Bi-Parting Patio Doors

Material: Aluminum Clad - Wood protected by aluminum exterior



BI-PARTING SLIDING PATIO DOOR



STANDARD FEATURES

- Stainless steel rollers for smooth operation and long lasting performance
- Aluminum sill deck in medium bronze with durable stainless steel track on interior of sill for smooth sliding operation
- Dual finseal weatherstripping over the full height of the door and ½" tall finseal weatherstripping for increased protection against leaks for reduced air infiltration
- Durable .080 extruded aluminum cladding on exterior surface of panels and .050 extruded aluminum cladding on frames resists dings and dents while providing structural integrity
- Multi-point lock system
- 1³/₄" panels with wide stiles and rails for an authentic French look
- Select clear wood interior ready for paint or stain to match any interior décor (also available primed or prefinished in white, black or off-white)
- Integral face groove allows for easy mulling and exterior accessory application
- Energy-efficient Warm Edge insulating tempered HP glass (Low-E/argon gas fill) helps reduce energy costs and fabric fading
- AAMA 2604 paint finish provides superior resistance to chalking and fading

HP glass combines Low-E with argon gas fill for high performance
 Impact Rated units are available in select sizes and configurations.

Rear Terrace Door



Ply Gem Mira Aluminium-Clad Wood French Outswing Door.

APPROVED Montgomery County Historic Preservation Commission

Rame h. Motton







- Aluminum sill deck to prevent sag and residents
- Aluminum astragal with stainable wood interior
- Full-perimeter weatherstripping for air-tight performance and smooth operation
- Multi-point lock system
- 1³/₄" panels with wide stiles and rails for a true French look
- 4 %₁₆" jambs made of clear wood eliminate extensive drywall work
- Select clear wood ready for paint or stain t match any interior décor
- Integral face groove allows for easy mullin and exterior accessory application
- Pre-punched nailing fin for simple installat
- AAMA 2604 paint finish provides superior resistance to chalking and fading
- Energy-efficient Warm Edge insulating tempered HP glass helps reduce energy costs and fabric fading – optional HP^{sc}, HP HP2+^{sc}, HP2_{MAX}, HP2_{MAX}^{sc}, HP3_{MAX} or HP3_M
- Vacuum-treated, solid wood components
 resist damage from water and fungus
- Durable .050 extruded aluminum cladding on exterior surfaces of frame and .080" on panels resists dings and dents while providing structural integrity. Available with ADA compliant sill

Proposed fencing

Fence to be installed along the sides of the house

3-1/2 ft. high Western Red Cedar Spaced Picket Flat Top Fence



Fence to be installed in the backyard. Materials: 6 ft. H Pressure-Treated Pine Dog-Ear Fence Panel.



Retaining walls

Existing walls will be replaced using Pewter Concrete Retaining Wall Block (4 in. x 11.75 in. x 6.75 in.).

Locations: front, rear, and along the right (northeastern) side of the property.





APPROVED Montgomery County Historic Preservation Commission

REVIEWED By Dan Bruechert at 2:31 pm, Jan 08, 2025

Patio Images

