23/46 Greenwood 23/46-89A

February 1, 1990

Mrs. Faith S. Vredenburgh 21315 Georgia Avenue Brookeville, Maryland 20833

RE:

Greenwood (HPC Case No. 23/46-89A)

Dear Mrs. Vredenburgh:

I would like to take this opportunity to formally thank you for your patient cooperation with the design review process and the Historic Preservation Commission. I enjoyed meeting with you, and having the opportunity to see Greenwood firsthand.

At its January 24 meeting, the Historic Preservation Commission (HPC) approved your applications to demolish the blacksmith shop, the oxen shed and the hog-house (exclusive of the stone wall). You may proceed with demolition as soon as you have obtained all necessary permits. However, the approval was granted conditional upon submission and adherence to an approved work program for the remainder of the outbuildings. As you know, the approved work program was submitted and approved. It included an outline and time schedule drafted by John Abernethy as well as a report prepared by Preservation Associates, Inc. (dated November 16, 1989). You will be expected to adhere to the work program as closely as possible and allow periodic inspections by County staff. If for any reason, at any time, you are not able to abide by the schedule, or any portion of it, please notify the HPC office at once. Adherence to the work program will be enforced under terms of the existing Demolition by Neglect citation. Please keep in mind that all exterior work (with the exception of ordinary maintenance) on the remaining outbuildings must be reviewed and approved by the HPC prior to commencement of work. If, at any point in time, you are not sure whether a project would require HPC approval, please contact the HPC office before starting.

Mrs. Faith S. Vredenburgh Page Two February 1, 1990

I have enclosed a copy of the minutes from the December 7, 1989 HPC meeting. With the exception of the condition regarding bonding, the motion from that meeting, including all other conditions, stands. If desired, a copy of the minutes from the January 24, 1990 meeting will be sent to you when they are completed and approved by the HPC. I have also enclosed your copies of the approved Historic Area Work Permits.

Thank you once again for your cooperation. Should you have any questions, please do not hesitate to contact me at 217-3625.

Sincerely,

Jared B. Cooper

Historic Preservation Specialist

Attachment

JBC:av 1600E

MEMORANDUM

TO: .

Historic Preservation Commission

FROM:

Jared B. Cooper

Historic Preservation Specialist

SUBJECT:

Greenwood (HPC Case No. 23/46-89A)

DATE:

January 17, 1990

Attached please find a memorandum from Eddie Lattner regarding the conditions of approval placed on the above referenced application. This memorandum and related issues will be the subject of the work-session scheduled for the January 24th meeting.

Also, please note that the case will be re-heard on the 24th in order to remove, replace, or alter the existing conditions of approval.

Attachments

1. Memorandum from E. Lattner (January 4, 1990)

2. Memorandum from Melvin Tull (February 22, 1989)

3. Staff Reports/Memoranda

a. August 7, 1989 b. November 29, 1989

JAB:bc

1571E

CONFIDENTIAL

MEMORANDUM

January 4, 1990

TO:

All Commissioners

Edward B. Lattner Edward B. Lattner Assistant County Attorney

RE:

Approval of Historic Area Work Permit Applications Conditioned Upon the Restoration of Other Structures;

Performance Bonds

At its August 17, 1989, meeting, the Historic Preservation Commission considered the application of Faith Vrendenburgh for the issuance of an historic area work permit The application was filed on July 27, 1989. Ms. Vrendenburgh sought to demolish four of approximately 15 outbuildings on Greenwood Farm (Master Plan Site No. 23/46). The tortuous history of Greenwood Farm was outlined in Mel Tull's February 22, 1989, memorandum to the Commission, a copy of which was included in the Commission's August 7, 1989, pre-meeting packet. Suffice it to say that the owner(s) of Greenwood Farm have apparently been under long-standing notice to stabilize most, if not all, of the outbuildings, pursuant to § 24A-9(a) of the Montgomery County Code (1984), as amended ("demolition by neglect"). The Commission recommended approval of the HAWP application as to one of the four outbuildings, but reached no decision on the other three outbuildings. Instead, the applicant was asked to return with a stabilization/restoration plan for the approximately 11 remaining outbuildings, at which time the Commission would consider the HAWP application as to the other three outbuildings.

On December 7, 1989, Ms. Vrendenburgh returned with a stabilization/restoration plan that met with the Commission's approval. The Commission indicated that it would recommend approval of the HAWP application as to the other three outbuildings after (1) the Commission approved the stabilization/restoration plan and (2) Ms. Vrendenburgh posted a \$40,000.00 performance bond, ostensibly to assure her compliance with the stabilization/restoration plan.

In my opinion, the Commission has exceeded its grant of authority under by Chapter 24A. As to the first condition, the Commission cannot condition its affirmative recommendation on an HAWP application upon the applicant's performance of work on a structure other than the one for which the HAWP was sought in the first place. With regard to Ms. Vrendenburgh's HAWP application, the basic question before the Commission was whether those three outbuildings could be demolished, consistent with the purposes and requirements of Chapter 24A. While the Commission may also, independently, be interested in the stabilization of the other outbuildings, the ordinance provides the Commission with a separate and distinct avenue to ensure their stabilization -- demolition by neglect. The Commission may not withhold its affirmative recommendation on the HAWP application for demolition of the three outbuildings as a means of insuring Ms. Vrendenburgh's compliance with a stabilization/restoration plan for other outbuildings. Commission felt, for whatever reason, that the three outbuildings were no longer historically or architecturally significant, and may therefore be demolished, then the Commission should have granted the HAWP application.

I am aware that § 24A-7(f)(2)(b) provides that the Commission may instruct the director of the Department of Environmental Protection to issue an HAWP "subject to such conditions as are necessary to ensure conformity with the provisions and purposes of this chapter." The "conditions" that this provision of the ordinance refers to are those which may reasonably be applied to the structure for which the HAWP is sought. Thus, if an applicant wishes to build a fence around an historic master plan site, the Commission might grant the HAWP subject to the condition that the fence be a picket fence, stockade fence, or whatever. The condition cannot be applied to a structure other than that for which the HAWP is sought.

As to the second condition, the Commission does not have the power to require HAWP applicants to post a performance bond. As noted above, the Commission may attach certain conditions to the affirmative recommendation of an HAWP. However, this does not include the posting of a performance bond, even if that bond is related to the structure for which the HAWP is sought. In various places throughout the Montgomery County Code, the County Council has seen fit to require the posting of a performance bond before certain activities may be undertaken. In each

instance, the County legislature has expressly required the posting of a performance bond. Thus, for example, an applicant for a license to operate a quarry must file and renew annually a performance bond, § 38-6; an applicant for a solid waste collector's license must file a performance bond, § 48-19(b)(2)(a); a performance bond must be posted before certain building and demolition permits may be issued, §§ 8-26(j)(1), 8-27(b); and a performance bond is required before certain cable communication operations may be undertaken, § 8A-6(g). Nowhere in Chapter 24A do the words "performance" or "bond" appear. I do not believe the County Council wished to empower an all-volunteer commission with the ability to require HAWP applicants to post a performance bond.

I understand the Commission's desire to ensure the stabilization of certain outbuildings on Greenwood Farm. While it is beyond the power of the Commission to order the restoration of an historic site, the director of the Department of Environmental Protection may issue a notice to the owner of the site, directing that certain action be taken to correct or prevent further deterioration or demolition by neglect. § 24A-9(a). Apparently, the owner(s) of Greenwood Farm have received such notice at least three times, although I do not know if the procedures outlined in § 24A-9(a) were followed. any event, it appears that Ms. Vrendenburgh has come forward with a stabilization/restoration plan that is to the Commission's liking. I believe the Commission may ensure her compliance with the stabilization/restoration plan by issuing a written decision, pursuant to § 24A-9, approving the plan and ordering the applicant to follow through with it. The Commission might require periodic (perhaps monthly) reports to check on the applicant's progress. Enforcement of the Commission's order might be had through the issuance of civil citations, pursuant to §§ 24A-9(a)(3) and 24A-11.

I believe that the Commission should reconsider its December 7, 1989, decision on the HAWP application for demolition of the three outbuildings. If the Commission merely wishes to sever the illegal conditions and grant the permit, it may do so without the necessity of a public appearance. As noted earlier, the Commission may ensure Ms. Vrendenburgh's compliance with the stabilization/restoration plan without the necessity of imposing illegal conditions on the HAWP. However, if the Commission wishes to impose different conditions on the

HAWP, I suggest that it schedule a public appearance. Jared Cooper has informed me that the next available meeting for a public appearance is January 24, 1990, but he must set the agenda by January 5, 1990, in order to mail/publish timely notice.

0290.EBL:89.00662

MEMORANDUM

February 22, 1989

TO:

Steven Karr, Chairperson

Historic Preservation Commission

FROM:

Melvin E. Tull, Chief

Division of Code Enforcement

Department of Housing and Community Development

SUBJECT:

Greenwood, Master Plan Site No. 23/46

You have inquired about efforts to prevent demolition by neglect of the outbuildings at Greenwood. In addition, you requested a chronology of actions taken in that effort. You are aware that ownership changed last year. I hope you are also aware that the previous owner had made modest repairs and that the new owner has also been repairing some outbuildings. The new owner, Faith Vredenburgh, is now under notice, deadlines are scheduled, and she has applied for a work permit to demolish certain outbuildings.

The most notable progress to date is the change of ownership. I believe that change was prompted by the inspector when he established that Dr. Frankel was unable or unwilling to act to prevent demolition by neglect. Dr. Frankel apparently choose to sell the farm rather than face enforcement action. Because Greenwood was being sold to someone who would invest in stabilization, it did not appear necessary or appropriate for the county to contract for repairs. The new owner, Mrs. Vredenburgh, committed to a schedule of investment and rehabilitation, has been making repairs, and has applied for a work permit to demolish certain buildings. Stabilization of the weakest structures is required by early spring.

The following chronology of historic preservation actions affecting Greenwood begins 13 years ago with several significant steps during the late 1970s that provided the foundation for all later actions:

October 1976

Publication of the Locational Atlas & Index of Historic Sites. Greenwood identified as site

23-46.

May 1979

Planning Board recommendation of Greenwood as a

historic site along with 60 others in the original Preliminary Draft Master Plan.

July 24, 1979

Adoption of Chapter 24A, Historic Resources

Preservation Code.

Steven Karr February 22, 1989 Page 2 of 4

September 12, 1979

District Council adoption of the master plan for historic preservation, including Greenwood.

May 22 & July 22 1986

HPC requests investigation of possible demolition by neglect and provided copies of 1974 photographs showing leaning buildings, missing sections of roof and siding, and other severe deterioration.

November 10, 1986

After many attempts to inspect, our inspector met James Panek, the owner's son-in-law, at the property. After a brief discussion the inspector was told to leave.

November 17, 1986

Inspector met with Dr. Frankel, the property owner and inspected the buildings with him.

November 24, 1986

A notice and order to stabilize the outbuildings was sent to Dr. Frankel.

December 15, 1986

Dr. Frankel wrote to express willingness to stabilize the buildings and to propose a plan of action that included demolition of several outbuildings.

February 2, 1987

The inspector wrote to Dr. Frankel extending the deadline to June 15, 1987 and notifying him that he must apply for a Historic Area Work Permit for buildings he hoped to demolish rather than repair.

HPC was given Dr. Frankels letter about the plan to demolish certain buildings and the inspectors response referring the matter to the HPC.

May 6, 1987

The inspector learned that Greenwood was for sale and notified the real estate agent of the demolition by neglect order.

May 14, 1987

Dr. Frankels attorney, Robert A. Gingell, wrote to inquire about the process that designated Greenwood as a historic site and whether Dr. Frankel had received notice and opportunity to comment.

June 5, 1987

Mr. Gingell was advised by letters to contact the HPC.

Steven Karr February 22, 1989 Page 3 of 4

November 22, 1988

June 12, 1987	John E. Beckman, Jr., attorney for Dr. Frankel negotiated directly with the HPC regarding demolition of certain buildings and delay of repairs until the summer of 1988.
June 16, 1987	The inspector sent a Final Notice to Dr. Frankel stating that the County would make repairs and charge the cost to him if he delayed beyond July 17, 1987.
June 23, 1987	Dr. Frankel called the inspector to report that he planned to begin on repairs by August 7, 1987.
July 21, 1987	The HPC representative advised the inspector that Greenwood had been sold.
August 3, 1987	Dr. Frankel advised the inspector that Greenwood had been sold and settlement was scheduled for September 17, 1987.
September 22, 1987	Settlement rescheduled for October 1, 1987.
December 14, 1987	The inspector notified the new owner, Mrs. Vredenburgh, even though the deed still was not recorded.
January 7, 1988	The inspector reported that repairs had begun on the ice house and the coach house.
February 9, 1988	The inspector reported work continuing on the barn and ice house.
April 21 & 28, 1988	The inspector reported rehabilitation is underway and progressing.
July 15, 1988	The inspector and an HPC representative met owners on site and reviewed conditions.
July 28, 1988	The owner's representative (John Abernathy, a son-in-law) proposed a workable schedule for renovations.
August 19, 1988	A notice and order was sent to Mrs. Vredenburgh establishing deadlines.

The inspector found ice house repairs were not

complete but were underway, and extended the deadline to January 1, 1989.

Steven Karr February 22, 1989 Page 4 of 4

November 30, 1988

Mrs. Vredenburgh applied for a Historic Area Work Permit to "wreck or raize" (sp) the cornshed, hog house, blacksmith house and oxen shed.

January 5, 1989

HPC denied the application.

February 3, 1989

Assistant County Ed Lattner notified Mrs. Vredenburgh's attorney that the HPC will reconsider and entertain a new application: noting that the HPC has a long history of working with the owners of historic resources he recommended that she meet with the HPC.

At various times, both Dr. Frankel and Mrs. Vredenburgh expressed a desire to clarify the extent of their responsibilities for maintaining and restoring various outbuildings. We have no record of a response from the HPC to Dr. Frankel's request of December 15, 1986, forwarded on February 2, 1987, or to his attorney's proposal of June 12, 1987. With these requests pending and unresolved throughout the remainder of 1987 it appeared that the HPC was reconsidering whether those structures should be stabilized and restored.

There are 5 distinct phases in the events listed above:

- Initial delays while the inspector was unable to arrange an inspection because Dr. Frankel was living in California and the occupants were uncooperative. This lasted 4 months.
- 2. Dr. Frankel was in the process of planning to make necessary repairs and determining, with the HPC, whether certain outbuildings could be demolished. His proposal to the HPC for demolition of certain buildings was not rejected and it was never certain that he would have to repair those outbuildings. This consumed 7 months.
- 3. The property was in a state of imminent transfer of ownership, during which it was not prudent to issue tickets or initiate repairs. That state lasted 5 months.
- 4. The new owner, Mrs. Vredenburgh, was making repairs and establishing plans for 11 months.
- 5. Mrs. Vredenburgh's application to clarify whether she must repair certain buildings or whether they can be demolished has taken more than 2 months and remains an open question.

MET:mmr:06601 cc: Jared Cooper

Historic Preservation Specialist

HISTORIC PRESERVATION COMMISSION STAFF REPORT

PREPARED BY: Jared B. Cooper

DATE: August 7, 1989

CASE NUMBER: 23/46-89A

TYPE OF REVIEW: HAWP

SITE/DISTRICT NAME: "Greenwood"

PROPERTY ADDRESS: 21315 Georgia Avenue

Brookeville, MD 20833

<u>DISCUSSION:</u> As you will recall, a representative of the owners of Greenwood Farm came before the Commission on January 5, 1989, in order to request the demolition of four outbuildings (see "chronology of events" memo, Attachment #3). At that time, the Commission denied the request (see Stephen Johnson letter, Attachment #2).

Since that time, staff has visited the site, conducted a thorough inspection of the buildings in question, and met with the applicant and her representatives.

STAFF RECOMMENDATION: Staff recommends the following:

- 1. "Corn Shed": Of the four buildings in question, this appears to be the earliest (late 19th century) and best constructed, although parts of the "oxen shed" are probably earlier. Unfortunately, the corn shed is in an advanced state of deterioration, and has all but fallen down. Staff recommends approval of the request for demolition for the following reasons:
 - A. by most standards, it is well past the point of restorability, and;
 - B. even though it "was" a well-constructed and designed structure, it does not exhibit any unusual architectural features or construction techniques which would render it worthy of a monumental restoration project.
- 2. "Hog House": This structure appears to have been constructed during the early 20th century. It was never very outstanding in terms of design or construction techniques, although it certainly contributes to the "farmscape." It is in relatively good condition, with a fairly good roof. Its worst problem is that the foundation, along two sides, has settled into the ground. However, the building is, by no means, falling down and the foundation problems could be halted by use of a combination of shoring, minor grading, and installation of a guttering system.

Staff recommends that the applicant be denied permission to raze the "hog house." There don't seem to be any sound reasons to demolish this structure, and it would be fairly easy and inexpensive to maintain it. Staff also recommends that the applicant be asked to take measures to protect the building from further deterioration. Such measures would include installation of gutters; minor grading, to pull away some of the buildup caused by excessive runoff, and to deter continued runoff damage; shoring up the settled portions of the foundation, utilizing the pier and beam system (as original); and roof maintenance. There is no danger of rapid deterioration, and the applicant could be given as much as a year or two to complete the work, as long as progress was being made on other more significant outbuildings during that time.

3. "Oxen Shed": This building, dubbed "Oxen Shed" by a former owner, appears to have been designed as what would commonly be known as a machinery/implement shed. Apparently, it was constructed during the 20th century. For the most part, it is constructed of tongue-and-groove rail car siding. One side of the roof rests on a pre-existing stone wall (approx. 7' high), which appears to have been constructed during the mid-nineteenth century, (possibly earlier) although it would be difficult to document. It is joined at both ends by a continuous stone fence which traverses the farmstead, separating the barnyard, residential yard, and cemetery.

The stone wall was probably part of the foundation of an earlier, perhaps larger, agricultural building. It has a doorway in the center, flanked by a series of small vent openings in the wall. The weight of the building, along with poor construction technique and footing problems, is causing the wall to bow outward. This movement has been temporarily halted by a previous owner through the installation of wooden buttresses. The building itself, while it has a good roof, is in poor structural condition. Some of the problems could probably be corrected, but the building (with the exception of the stone wall) hardly warrants salvation.

Staff recommends approval of the request for demolition of the wooden portion of the structure, for the following reasons: a) It is not architecturally significant; b) it is in poor structural condition; and c) it appears to be causing stress to the stone wall on which it rests.

However, staff recommends that approval be granted with the condition that measures (approved by the Commission) be taken to protect and preserve the stone wall. Such measures might include a thin troweled "soft mortar" cap, or even construction of an appropriate building, replacing the existing. Also staff recommends that the applicant be encouraged to "right" the leaning section of the wall if the building is removed.

4. "Blacksmith shop": This structure appears to have been constructed during the early 20th century, at or about the time of construction of the "hog house." It may have served as a blacksmith shop at one time, although, if that was the case, it has long since lost all fixtures and appurtenances which would have been associated with that use. Most recently, it appears to have served as a tool shed or workshop. It is in poor condition, as a result of poor original design and a bad roof. It is situated in a row of three buildings which includes the ice house and a carriage house. Both of these other buildings date from an earlier period and are in better condition. The applicant has been slowly restoring them.

Staff recommends that the applicant be permitted to raze the "blacksmith shop." In staff's opinion, it is not significant in terms of age, design, or construction technique. While it would be possible to restore the structure, staff recommends that, instead, the applicant be enouraged to complete the restoration and repair of the flanking structures.

In summary, staff recommends that the applicant be permitted to raze the following three structures:

- 1) "Corn Shed" (based on criterion 24A-8(b)(4))
- 2) "Oxen Shed" (based on criteria 24A-8(b)(1) and (4)
- 3) "Blacksmith Shop" (based on criteria 24A-8(b)(1) and (4)

Staff recommends that the applicant be denied permission to raze the "hog house." Although its foundation is in poor condition it could be repaired and stabilized relatively easily. However, like the "blacksmith shop," staff feels that it is not a particularly early or outstanding structure.

ATTACHMENTS:

- 1. HAWP Application
- Letter from Applicant's Attorney (and attachments)
- 3. Memorandum from Mel Tull
- 4. Photographs (slides will be shown at the meeting)

MEMORANDUM

T0:

Historic Preservation Commissioners

FROM:

Jared B. Cooper

DATE:

November 29, 1989

SÜBJECT: Application of Faith Vredenburgh for Historic Area Work Permit at 21315 Georgia Avenue, Brookeville, Maryland (HPC Case No. 23/46 -

89A) (Master Plan Site #23/46)

You will probably recall that owners and representatives of Greenwood (MP Site #23/46) came before the Commission on August 17, 1989, requesting permission to raze four outbuildings. Following deliberation, the Commission moved 1) to approve the removal of the corn crib with the condition that, within 60 days, the applicant return to the Commission with an acceptable written plan and schedule for the stabilization/restoration of the remaining outbuildings, and 2) to keep the record open on the request to demolish the other three buildings until after the plan had been submitted.

The applicant returned to the Commission with such a plan on November 2, 1989 (see attached). The Commission reviewed the plan and determined that it was incomplete in several ways, specifically: 1) overall statement of intent/vision: 2) cost estimates: 3) County inspection schedule; 4) organization/prioritization of tasks. Subsequently, in order to assist with redrafting the plan, the applicant hired Preservation Associates, Inc. (PAI) (Douglas Reed, President), of Hagerstown. PAI drafted a plan for the applicant, which addresses the above concerns, with the exception of the County inspection schedule. Mr. Abernethy has agreed verbally that a 6-month inspection schedule would be acceptable.

The applicant has also provided a chart detailing the various projects, completion dates, cost estimates, and who will complete the work (see attached).

As a side note, the applicant plans to hire PAI to complete much of the work. If you are not familiar with the firm, it has a great reputation, and is very highly recommended by the Maryland Historical Trust.

At this point, I would recommend that this material, in addition to the original plan and letter dated October 19, 1989, be accepted by the Commission and included as part of the official record of Case No. 23/46 - 89A.

Historic Preservation Commissioners Grnenwood Page Two November 29, 1989

In terms of the applicant's request to demolish certain outbuildings, my recommendations remain as presented in a staff report dated August 7, 1989 (see attachment).

Should you have questions or comments, please contact me at 217-3625 prior to the December 7 meeting.

Attachments

JBC:av 1442E

CONFIDENTIAL

MEMORANDUM

January 4, 1990

TO:

All Commissioners

FROM:

Edward B. Lattner Edward B. Kathe

Assistant County Attorn

RE:

Approval of Historic Area Work Permit Applications Conditioned Upon the Restoration of Other Structures;

Performance Bonds

At its August 17, 1989, meeting, the Historic Preservation Commission considered the application of Faith Vrendenburgh for the issuance of an historic area work permit (HAWP). The application was filed on July 27, 1989. Ms. Vrendenburgh sought to demolish four of approximately 15 outbuildings on Greenwood Farm (Master Plan Site No. 23/46). The tortuous history of Greenwood Farm was outlined in Mel Tull's February 22, 1989, memorandum to the Commission, a copy of which was included in the Commission's August 7, 1989, pre-meeting packet. Suffice it to say that the owner(s) of Greenwood Farm have apparently been under long-standing notice to stabilize most, if not all, of the outbuildings, pursuant to § 24A-9(a) of the Montgomery County Code (1984), as amended ("demolition by neglect"). The Commission recommended approval of the HAWP application as to one of the four outbuildings, but reached no decision on the other three outbuildings. Instead, the applicant was asked to return with a stabilization/restoration plan for the approximately 11 remaining outbuildings, at which time the Commission would consider the HAWP application as to the other three outbuildings.

On December 7, 1989, Ms. Vrendenburgh returned with a stabilization/restoration plan that met with the Commission's approval. The Commission indicated that it would recommend approval of the HAWP application as to the other three outbuildings after (1) the Commission approved the stabilization/restoration plan and (2) Ms. Vrendenburgh posted a \$40,000.00 performance bond, ostensibly to assure her compliance with the stabilization/restoration plan.

In my opinion, the Commission has exceeded its grant of authority under by Chapter 24A. As to the first condition, the Commission cannot condition its affirmative recommendation on an HAWP application upon the applicant's performance of work on a structure other than the one for which the HAWP was sought in the first place. With regard to Ms. Vrendenburgh's HAWP application, the basic question before the Commission was whether those three outbuildings could be demolished, consistent with the purposes and requirements of Chapter 24A. While the Commission may also, independently, be interested in the stabilization of the other outbuildings, the ordinance provides the Commission with a separate and distinct avenue to ensure their stabilization -- demolition by neglect. The Commission may not withhold its affirmative recommendation on the HAWP application for demolition of the three outbuildings as a means of insuring Ms. Vrendenburgh's compliance with a stabilization/restoration plan for other outbuildings. Commission felt, for whatever reason, that the three outbuildings were no longer historically or architecturally significant, and may therefore be demolished, then the Commission should have granted the HAWP application.

I am aware that § 24A-7(f)(2)(b) provides that the Commission may instruct the director of the Department of Environmental Protection to issue an HAWP "subject to such conditions as are necessary to ensure conformity with the provisions and purposes of this chapter." The "conditions" that this provision of the ordinance refers to are those which may reasonably be applied to the structure for which the HAWP is sought. Thus, if an applicant wishes to build a fence around an historic master plan site, the Commission might grant the HAWP subject to the condition that the fence be a picket fence, stockade fence, or whatever. The condition cannot be applied to a structure other than that for which the HAWP is sought.

As to the second condition, the Commission does not have the power to require HAWP applicants to post a performance bond. As noted above, the Commission may attach certain conditions to the affirmative recommendation of an HAWP. However, this does not include the posting of a performance bond, even if that bond is related to the structure for which the HAWP is sought. In various places throughout the Montgomery County Code, the County Council has seen fit to require the posting of a performance bond before certain activities may be undertaken. In each





instance, the County legislature has expressly required the posting of a performance bond. Thus, for example, an applicanty for a license to operate a quarry must file and renew annually apperformance bond, \$38-6; an applicant for a solid waste? (collector s license must file a performance bond, \$48-19(b).(2)(a); ca-performance bond must be posted before certain (building and demolition permits may be issued, §§-8-26(j).(1), (8-27(b);) (and a performance bond is required before certain cable (communication operations may be undertaken, §-8A-6(g)). Nowhere in Chapter 24A do the words "performance" or "bond" appear. I do not believe the County Council wished to empower an all-volunteer commission with the ability to require HAWP applicants to post a performance bond.


I understand the Commission's desire to ensure the stabilization of certain outbuildings on Greenwood Farm. While it is beyond the power of the Commission to order the restoration of an historic site, the director of the Department of Environmental Protection may issue a notice to the owner of the site, directing that certain action be taken to correct or prevent further deterioration or demolition by neglect. 24A-9(a). Apparently, the owner(s) of Greenwood Farm have received such notice at least three times, although I do not know if the procedures outlined in § 24A-9(a) were followed. In any event, it appears that Ms. Vrendenburgh has come forward with a stabilization/restoration plan that is to the Commission's liking. I believe the Commission may ensure her compliance with the stabilization/restoration plan by issuing a written decision, pursuant to § 24A-9, approving the plan and ordering the applicant to follow through with it. Commission might require periodic (perhaps monthly) reports to check on the applicant's progress. Enforcement of the Commission's order might be had through the issuance of civil citations, pursuant to §§ 24A-9(a)(3) and 24A-11.

I believe that the Commission should reconsider its December 7, 1989, decision on the HAWP application for demolition of the three outbuildings. If the Commission merely wishes to sever the illegal conditions and grant the permit, it may do so without the necessity of a public appearance. As noted earlier, the Commission may ensure Ms. Vrendenburgh's compliance with the stabilization/restoration plan without the necessity of imposing illegal conditions on the HAWP. However, if the Commission wishes to impose different conditions on the

HAWP, I suggest that it schedule a public appearance. Jared Cooper has informed me that the next available meeting for a public appearance is January 24, 1990, but he must set the agenda by January 5, 1990, in order to mail/publish timely notice.


0290.EBL:89.00662






Mr. Jeff Miskin Chairman Montgomery County Historic Preservation Commission 51 Monroe Street Suite 1001 Rockville, Maryland 20678

Dear Mr. Miskin:



December 6, 1989



It is a general rule of mine to refrain from interfering in historic district commission affairs. I am of the opinion that commissions have a tough enough time dealing with the issues at hand to have to worry about the state looking over their shoulder at every turn. However, there are times when a situation warrants action by this office and therefore, I am offering the following comments with most sincere intentions.

I have recently been made aware of a project that your commission has been reviewing for quite some time. The project is "Greenwood" located just beyond the town of Brookeville. Although I have definite opinions on the proper approach for dealing with the final issues concerning this property, I am more concerned with the tone of the commission meetings where the issues were discussed.

Needless to say, half of a historic district commission's charge is to protect historic resources. The other half is to educate the general public on the values of historic preservation and the development of good will in the project review process. A key to promoting this sense of good will is for commission members to be well informed about the particulars of any given project, to be understanding, within reason, of an applicant's position and above all to maintain a professional attitude in the presence of the public even though, at times it may be very difficult. Now to my point.

I have had the opportunity to read excerpts from a recent commission meeting in which the "Greenwood" project was discussed. Even if I knew nothing about the project particulars, one thing was apparent. The meeting was not being conducted in a professional manner and certain commission members were speaking in a tone that I would consider abusive and highly unprofessional.

Department of Housing and Community Development
45 Calvert Street, Room 416, Annapolis, Maryland 21401 (301) 974-3642

Mr. Jeff Miskin December 7, 1989 Page 2

40, . 9

I am only bringing your attention to this situation because, in my position here at the Trust, I am constantly aware of the difficulties that historic district commissions, throughout the state, have with maintaining a good public image. It is harder yet, in some cases, to justify their very existence. Your commission is considered, by this office, to be one of the most successful of Maryland's 36 HDCs and as such, you are looked upon as a role model by other, smaller commissions. As one of our eleven Certified Local Governments, you have an even greater responsibility to maintain professionalism and to promote cooperation and good will not only in your county, but throughout the state.

In closing, I would like to urge you to be as concerned about your public image and professional conduct as you are about the historic resources you are charged with protecting. It will make all of our jobs a little easier.

If you would like to discuss this issue further, please feel free to call me at 974-3642.

Sincerely,

Michael K. Day

Michael

Administrator, Local Government

Preservation Programs


MKD/mmc

cc: Mr. Jared B. Cooper

December 2. 1989

Historic Preservation Commission 51 Monroe Street Rockville, Maryland 20850

Commissioners,



I'm addressing the following letter to each of you, on the preservation of "GREENWOOD", at your December 7, 1989 meeting. It is time to take immediate action in enforcing the Demolition by Neglect Law of Montgomery County against Ms. Faith S. Vredenburgh, owner of "GREENWOOD" 21315 Georgia Ave. Brookeville, Md. 20833. Ms. Vredenburgh and Mr. Abernathy, son in law, have been circumventing the law of Montgomery County for over 2 years, during her ownership of the "GREENWOOD" estate in stabilizing and maintaining the barn and outbuildings. Ms. Vredenburgh is pursuing, since January 4, 1989, the demolition of 4 buildings; thereby sidestepping the main issue before the commission of preservation of all the outbuildings. Ms. Vredenburgh has had sufficient time to show good faith in presenting a plan and taking physical action in stabilizing these buildings. The Demolition by Neglect citation was issued by code enforcement in 1985, to previous owner. Mr. Hyman Frankel and is currently active against this property. The Authorities are waiting your decision of December 7, 1989, that a proper plan of stabilization and time work schedule are submitted. Montgomery Co. Code Enforcement has pictures taken in 1985 of all the outbuildings and a letter notifying the Realtor, to inform all buyers of the citation against the property. Ms. Vredenburgh was aware, it was

a historic property with a need of repair and stabilization, when she bought it over 2 years ago. Ms. Vredenburgh has avoided the spirit of the law for over 2 years and the Commission has the responsibility to see the law of Demolition by neglect be reactivated against her, as the new owner.

Reasons for enforcement of the law-

Ms. Vredenburgh and Mr. Abernathy, son-in-law have in the 2 years of ewnership of "GREENWCOD", circumvented the law by (1) tearing down the protective roof over the loafing shed; (2) tearing the northwest exterior wll off the coachhouse and rebuilding same without windows; (3) rebuilt the front doors of ice well building in different manner from its original sliding door construction.; (4) demolished corn shed and removed materials before a plan was approved by commission. Montgomery Code Enforcement has pictures of each of these buildings taken in 1985, that can verify the appearance of each of these buildings and the changes, that have taken place under Ms. Vredenburgh's ownership and direction.

I request, that the buildings requested for demolition not be permitted or used as a smokescreen to cover the main issue of preservation of all the out buildings. Removal of each of these buildings is like amputaing the fingers off my right hand and next the hand, when the main barn goes. The time to enforce the law is now 12/7/1989!

Former resident of "GREENWOOD".

Leenard A. Becraft

15640 Santini Road

Burtonsville, Md. 20833

1-301-421-1117

CC- HPC
Code Enforcement
Sidney Kramer
GOCA

MEMORANDUM

TO: Historic Preservation Commissioners

FROM: Jared B. Cooper

DATE: November 29, 1989

SUBJECT: Application of Faith Vredenburgh for Historic Area Work Permit at

21315 Georgia Avenue, Brookeville, Maryland (HPC Case No. 23/46 -

89A) (Master Plan Site #23/46)

You will probably recall that owners and representatives of Greenwood (MP Site #23/46) came before the Commission on August 17, 1989, requesting permission to raze four outbuildings. Following deliberation, the Commission moved 1) to approve the removal of the corn crib with the condition that, within 60 days, the applicant return to the Commission with an acceptable written plan and schedule for the stabilization/restoration of the remaining outbuildings, and 2) to keep the record open on the request to demolish the other three buildings until after the plan had been submitted.

The applicant returned to the Commission with such a plan on November 2, 1989 (see attached). The Commission reviewed the plan and determined that it was incomplete in several ways, specifically: 1) overall statement of intent/vision; 2) cost estimates; 3) County inspection schedule; 4) organization/prioritization of tasks. Subsequently, in order to assist with redrafting the plan, the applicant hired Preservation Associates, Inc. (PAI) (Douglas Reed, President), of Hagerstown. PAI drafted a plan for the applicant, which addresses the above concerns, with the exception of the County inspection schedule. Mr. Abernethy has agreed verbally that a 6-month inspection schedule would be acceptable.

The applicant has also provided a chart detailing the various projects, completion dates, cost estimates, and who will complete the work (see attached).

As a side note, the applicant plans to hire PAI to complete much of the work. If you are not familiar with the firm, it has a great reputation, and is very highly recommended by the Maryland Historical Trust.

At this point, I would recommend that this material, in addition to the original plan and letter dated October 19, 1989, be accepted by the Commission and included as part of the official record of Case No. 23/46 - 89A.

Historic Preservation Commissioners Greenwood Page Two November 29, 1989

In terms of the applicant's request to demolish certain outbuildings, my recommendations remain as presented in a staff report dated August 7, 1989 (see attachment).

Should you have questions or comments, please contact me at 217-3625 prior to the December 7 meeting.

Attachments

JBC:av 1442E OCTOBER 19 1989

JOHN M ABERNETHY
GREENWOOD FARM
21315 GEORGIA AVE
BROCKEVILLE MARYLAND 20833

HP. JARED GOOPIR, EXECUTIVE DIRECTOR HISTORIC PRESERVATION COMMISSION 51 MOURCE ST HOCHVILLE MARYLAND 20850

DEAR MR. COOPER:

PER CUR FHONE CONVERSATION TWO DAYS AGO, THIS IS A FINAL DRAFT OF CUR FRCFOSAL TO SCHEDULE A TIME FRAME FOR STABILIZATION OR RESTORATION OF CUTEUILDINGS AT THE GREENWOOD SITE, 23 46

THE PROJECT MOULD CONSIST OF SEPERATE SCHEDULES OVER A FIVE YEAR PERIOD. CONTRACT, SUB-CONTRACT AND HOMEOWNER REPAIRS SHALL COMMENCE TO MEET THE REQUIREMENTS OF EACH PROJECT SIMULTAIOUSLY OR INDIVIDUALY BASED ON FOLLOWING THE TIME SCHEDULE FOR EACH YEAR OF THE FIVE YEAR PLAN THAT I HAVE ATTACHED. THIS IS I BELIEVE, THE BEST METHOD FOR STABILIZATION OF PROPERTY 21315 GEORGIA AVE WHITHOUT DISRUPTING THE ACTIVITIES DEEMED MESSESSARY FOR ANY OF THE NORMAL MAINTAINANCE REQUIREMENTS THAT A PROPERTY THIS SIZE HAS.

WHILE A FAIR AMOUNT OF PROGRESS HAS BEEN MADE ON THE SMALLER STRUCTURES AND MAIN BARN, WE ARE STILL IN THE PROCESS OF EVALUATING AND SEEKING THE PROPOSALS NEEDED FOR SOME OF THE MORE COMPLEX JOBS. WITH THIS FIVE YEAR PLAN, A STEADY PROGRESSTION TOWARDS STABILIZATION OF THE OUTBUILDINGS CAN BE ACHEIVED.

TO ASSURE THAT PROJESS IS BEING MADE, WE PROPOSE THAT THE HISTORIC PRESERVATION COMMISSION APPOINT A REPRESENTATIVE OF THE STAJF AND OR A COMMISSIONER, TO ALCHG WITH A REPRESENTATIVE OF CODE ENFORCEMENT, MAKE A YEARLY INSPECTION OF THE TROGRESS OF REPAIRS LISTED FOR EACH YEAR OF THE FIVE YEAR PERIOD. A POSSIBLE STARTING FOINT FOR THIS YEARLY INSPECTION COULD BE THE FALL OF NEXT YEAR 1990. THAT WOULD SIVE US THE TIME NEEDED TO FULFILL THE REQUIREMENTS OF WHAT LOCKS TO BE A HEAVY FIRST YEAR SCHEDULE.

E NOVED LIKE TO THANK YOU FAR ADMITS IN THE WAY YOU HAVE GUIDED NO TO MURILION THIS FRAFF.

SINCERELY

удни к. Авеплетну

CONTRACT, SUB CONTRACTED WORK

MAIN BARN, QUANSET HUT

- 1. STRUCTURAL REPAIRS NEEDED IN EAST AND MEST SIDES
- 2 STRUCTURAL REPAIRS IN NORTH SIDE OF ROOF
- 3. COMPLETE CARPENTRY NEEDED FOR NEW ROOF, NORTH SIDE
- 4. SIDING REPAIRS OR REPLACEMENT AS REQUIRED IN EAST AND WEST SIDES
- 5. HEW METAL ROOF INSTALLED MORTH SIDE
- 6. REPAIRS TO ENTRANCE, ROOF, SIDES, RAMP, NEW TIM ROOF INSTALLED
- 7. SIDING REPAIRS ON SOUTH SIDE
- 8. GUTTERS REPAIRED OR REFLACED DOWN SPOUTS REPAIRED
- 9. PRIME AND PAINT ENTIRE STRUCTURE

CXEN SHED, W STONE WALL

- 1. SUPPORT STONE WALL IN PREPARATION OF REMOVELL OF SHED
- 2. REMOVE EXISTING STRUCTURE IN SECTIONS WHITHOUT DAMAGING WALL
- 3. FURTHER STUDY POSSIBLE METHODS FOR STONE REPAIR

HOG HOUSE

- 1. DISMANTLE, SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP, TRASH REMOVAL, LANDSCAPE

HOME OWNER REPAIRS

CARRIAGE HOUSE

- 1. SIDING REPAIRS OR REPLACEMENT
- 2. WINDOW REFAIRS
- 3. SIDE DOORS REPAIRED OR REPLACED
- 4. MAIN DOORS HUNG FRONT AND BACK
- 5. TRIME PAINT

STONE WALL NEXT TO DRIVEWAY

COMPLETE UNFINISHED REPAIRS FROM DAMAGE THAT OCCURED IN MOTOR VEHICLE ACCIDENT LAST YEAR.

BLACK SMITH SHCP

- 1. DISMANTLE. SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP, LANDSCAFE

CONTRACT, SUB CONTRACT WORK

MADY BARN WANSET HUT

- 1. RE FOINT BARN FOUNDATION WHERE NEEDED
- 2. MASCNARY REPAIRS TO BLOCK ON WEST WALL
- 3. PEPAIR WINDOW LENTILS
- 4. REPLACE GLASS AND RE GLAZE SIX WINDOWS IN BLOCK
- 5. BUTTE HEN GUTTER FOR WEST SIDE OF HUT
- 6. PAINT ENTIRE ROOF

CARRIAGE HOUSE

- 1. STOT REPAIRS OF TEN
- 2. SCRAPE , PAINT ROOF

ICE HOUSE

- 1. REMOVAL OF EXISTING ROOF
- 2. INSTALL NEW METAL ROOF
- 3. INSTALL GUTTERS AND DOWN SPOUTS

HOME OWNER REPAIRS

ICE HOUSE

- 1. SIDING REPAIRED OR REPLACED AS REQUIRED
- 2. WINDOWS REPAIRED NORTH SIDE
- 3. REPAIRED SHUTTER TYPE LOFT DOORS INSTALLED
- 4. FRIME, PAINT STRUCTURE
- 5. GRADE , LANDSCAPE

REPAIR SCHEDULE THIRD YEAR GREENWOOD 21315 GEORGIA AVE ERCCKEVILLE MD

CONTRACT , SUB CONTRACT WORK

CEMETARY MALL

1. REBUILD CEMETARY WALL ON EXISTING FOUNDATION TO MATCH EXISTING

CKEN SHED WALL

- 1. DEGREEARY AUGINEERING AND MACCHAIM REQUIRED TO STABILIZE WALL.
- 2. LANDSCAPE, GRADE FOR BETTER DRAINAGE

BLACK SMITH SITE

1. SUBMIT PROPOSAL AT THIS TIME TO H P C FOR RELOCATING SLAVE CABIN (TOOL SHED)
TO SITE AT WHICH BLACK SMITH SHOP STOOD, BEFORE NEXT YEARS WORK ON SLAVE CABIN
COMMENCES. TO RESTORE AFFEARANCE FROM ROAD, BETTER FACILITATE THE USE OF BUILDING
AND TO EASE CROWDING ON OTHER BUILDINGS.

HOME OWNER REPAIRS

CARRIAGE HOUSE SIDE STRUCTURE (CAR PORT)

- 1, REMOVAL OF TAR SHINGLE ROOF
- 2. REMOVAL OF ALL DETERIORATED/WATER DAMAGED WCOD
- 3. REPLACE ALL DAMAGED WODD
- 4. REPAIR OR REPLACE SIDING WHERE NEEDED
- 5. HEPAIR OR REFLACE ROOF LATHINGWHERE NEEDED
- 6. INSTALL NEW TIN ROOF
- 7. PRIME, PAINT STUCTURE

SUB CONTRACT OR HOMECWNER REFAIRS

SLAVE CABIN (TOOL SHED)

- 1. WITH AFPROVAL, PREPARE SITE OF BLACK SMITH SHOF TO ACCEPT FOUNDATION DIMENTIONS OF SLAVE CABIN. DISMANTLE, OR SECURE TO MOVE WHOLE, WHILE REPLACING NEEDED WOOD IN SILLS TO TRUE UP STRUCTURE.
- 2. REPLACE ALL CTHER WOOD AS REQUIRED
- 3. REPAIR OR REPLACE SIDING AS REQUIRED
- 4. PAINT ROOF
- 5. FRIME PAINT SIDING
- 6. REFLACE DCOR
- 7. WITHOUT APPROVAL, REPLACE STRUCTURAL WOOD WHERE NEEDED
- 8. REPAIR , REPLACE SIDING
- 9. REPLACE DCCR
- O. PAINT ENTIRE STRUCTURE

SUB CONTRACT OR HOMEOWNER REPAIRS

GROUDDS KEEPERS SHED

- 1. RE NATL ALL LOOSE SIDING
- 2. PAINT ROOF
- 3. PAINT SIDING ANDW WINDOW FRAMES

SMALL SHED

- 1. REFAIR SIDING AS REQUIRED
- 2. PAINT ENTIRE STRUCTURE

MISC.

- 1. ALL OTHER UNFINISHED REPAIRS AND PAINTING
- 2. ALL REQUIRED LANDSCAPE NEEDS
- 3. ALL OTHER CLEAN UP, TRASH REMOVAL

207 S. POTOMAC STREET HAGERSTOWN, MARYLAND 21740 PHONE (301) 791-7880 FAX (301) 791-7896

DOUGLASS C. REED PRESIDENT PRESERVATION PLANNING
COMMERCIAL REHABILITATION
RESIDENTIAL REHABILITATION
NATIONAL REGISTER NOMINATIONS

November 16, 1989

Faith S. Vredenburgh 21315 Georgia Ave. Brookeville, MD 20833

RE: Barn and other outbuildings associated with Main House at above listed address

Dear Mrs. Vredenburgh:

Thank you for the opportunity to visit with you and your son-in-law John Abernethy as well as Mr. Farley Warner. As you will recall, the purpose of my visit was to review most of the nine standing buildings associated with the main house. The buildings were to be inspected with an opinion rendered as to whether the buildings could be salvaged, and, if so, which ones and at what cost. The one critical task was to identify immediate stabilization of critical buildings and identify a rough outline for near future work to restore buildings.

Please keep in mind that the estimates offered in this letter are not guaranteed and were arrived at by a brief inspection of each building. Estimates were established on size of building, difficulty of repairs/tasks and on past experience of restoration in similar situations. The estimates are for budgeting and loan application purposes but cannot be considered contract prices. In order to obtain contract prices a detailed analysis of each piece of each building will have to be done and a work description established. Then all bidding parties will know the scope of the work and can submit comparative bids unless you select and negotiate with one contractor.

Page 2 November 16, 1989 Mrs. Faith S. Vredenburgh

Building #1; Hog Barn. Due to the uric acid from the hogs and from negative drainage where water runs off a hill into the footers, the building's foundations have been washed away under the entire northwest half of the building. The bottom members of the frame structure are also extensively rotted that the economics of salvation don't make the building worth saving.

The building as a 20th century hog barn where extensive work was done to the building in the 1930's or 1940's, is not significant to Maryland's agricultural vernacular landscape. There are many remaining examples of this type of structure in the state and either in or in close proximity to Montgomery County.

Due to the cost of saving the building which would entail dismantling and rebuilding a rather insignificant structure, I recommend you sketch the floor plan, make key dimensions of the floor plan on the sketch, take good, clear black and white glossies of the building to include all four exterior sides and other key building details to fully record the building. Once the building has been properly located on a site plan, plot plan or survey plat and has been recorded, raze the building. Cost to record and raze the building would be \$1,000 to \$2,500.

Building #2; The Barn. This is a significant building. The earlier frame section appears to date from the later half of the 19th century. While the round top barn addition is dateable to the mid 20th century, probably 1930's or 1940's. A unique feature of the frame section is the location of the grain rooms under the threshing floor.

The barn frame is very savable. The northwest quadrant has suffered the worst deterioration. The main west roof purlin, the northwest corner post, the west gable top plate, the top plate of the first interior framing bent west of the west wall, five of cantilevered sleepers of the lower west hay mow and the first upright intermediate post of the north wall west of the corner, all are in need of repair. There is roughly about 100 linear feet of post and beam repairs that need to take place through epoxy reconsolidation, replacement with appropriate size materials, or mechanically rekeying worn out mortize and tenon joints.

Page 3 November 16, 1989 Mrs. Faith S. Vredenburgh

Further structural stabilization is required in the northeast corner. There is a need for a new sill to be placed under the sistered intermediate post of the north wall just east of the corner. The northeast corner post needs to be stabilized with new connections at some of the joints.

The roof rafters and lath over the purlin to be replaced in the northwest quadrant will have to be reset in place. The roof on the entire south slope and most of the north slope can be tightened up and kept in place. A new corrugated roof will have to be placed over the area of the purlin repairs. Unfortunately, the new corrugated roofing available does not match the ridge to ridge size of the mid 20th century corrugated roofing in place. However, the difference while noticeable, is minor and should be suitable and appropriate.

All the wooden siding needs to be repaired on the frame barn. Originally the entire barn was sided with vertical boards and battens as found on the south bridge wall side. The other sides are covered with mid 20th century novelty siding. All sides should be repaired in kind.

There are minor masonry repairs needed to the southeast and southwest corners, but otherwise the foundation walls are in very good condition.

The covered entrance bridge-way on the south wall needs to be restructured and kept as a maintained entranceway to the main threshing floor.

The gutters, rakes and barge boards all need to be replaced in kind. The half round metal gutters, 6" galvanized are original and still the most appropriate type.

The site should be cleared of all growth and debris and graded to provide positive drainage away from the structure.

The entire structure should be painted, two coats including roof and all wood and metal.

No work is immediately needed on windows and doors, but in the future these items will need to be addressed. Page 4 November 16, 1989 Mrs. Faith S. Vredenburgh

The following is a recap of speculative estimates:

Demolition and Trash Removal Structural Repairs Carpentry Roofing Metal Siding Repairs and Partial Replacement	\$ 2,000.00 16,000.00 1,000.00 6,000.00 4,500.00
Masonry Repairs	2,000.00
Covered Entranceway Bridge	6,000.00
Gutters	2,000.00
Painting	10,000.00
25% Contingency for Unforseen Conditions	12,875.00
	\$62,375.00

It must be stated that while one category may seem low another may be high. The entire work should cost about \$47,500 to \$58,000.

Building #3; Oxen (Loafing) Shed or now a Wagon/Implement Shed. The condition of this structure is unquestionably poor and in immediate danger of collapse. If the roof framing collapses on its own, it is likely going to upset the stone wall or at least further damage it to the point of no repair.

The building has two noteable parts. The rear, north stone wall is a 19th century stone structure built to terminate at each end in a square column. Along the 80 foot long, 8 foot high wall is an evenly spaced series of ventilators and in the center of the wall is one door. Part of the 19th century door frame still is in place.

The rest of what is left of the building dates from the 1930's to 1940's influence. Virtually all the roof, frame, and cladding is of 20th century manufacture. There are one or two pieces of 19th century framing, but all the framing is salvage lumber from mostly turn of the 20th century buildings.

Page 5 November 16, 1989 Mrs. Faith S. Vredenburgh

The frame structure has completely failed and is beyond salvage. If you wish to even attempt to save the wall, the rest of the building must be removed before the next major wind or snow storm. I strongly recommend the wooden structure be recorded as described under Building #1 and immediately razed. Cost to record and move the structure leaving the wall will be between \$2,000 and \$4,000.

It is in my opinion that the stone wall can be righted, stabilized and underpinned. I would want a structural engineer I know to look at the wall. He is extremely experienced and sympathetic to older, troubled buildings. Even if he says it needs to come down, it can be partially salvaged and the remainder re-erected.

The pricing on this wall could be as low as \$18,000 and run as high as \$28,000. Consulting could be between \$500 and \$1,500.

Building #4; Garage on Ice House. This is another mid 20th century frame structure built over an older, 19th century foundation set deep into the ground and used as an ice house. The building has recently been worked on and is in a good state of stabilization and fairly good repair. No work is needed to immediatly stabilize the building and the remaining repairs can wait for a few years until the more pressing repairs of the other buildings has been accomplished.

A very rough estimate of the work remaining to put the building into an excellent state of repair would run between \$3,500 and \$6,000.

Building #5; known as Blacksmith Shop. Actually is a small workshop built entirely of new materials in the 1930 to 1940's period. With a concrete floor, all circular sawn wood, wire nails and composition shingles. The building was built, used and never maintained.

Page 6 November 16, 1989 Mrs. Faith S. Vredenburgh

Apparently no owner ever felt a need to maintain this structure and it has sort of "melted" away. It literally is being held up by a poplar tree the building is leaning against. There is no structural integrety left of the individual pieces or the component whole of the frame. Even if you wished to save the structure, it would require so much new material, the final result would be more of a new replica of what is there and not a restoration. Far more than 50% of the entire structure would need to be replaced.

As described under Building #1, I recommend this building be recorded, razed and all debris removed. Cost of recording and demolition will range between \$1,000 and \$2,000.

Building #6; Carriage Shed, Corn Crib. This is a good mid 19th century hand hewn frame structure that was refurbished in the 1930 to 1940's period. New horizontal siding, roof, staircase, second floor and new walls, doors and windows were added in the 20th century remodeling.

The building needs the stone piers to be repointed and a little more frame work to be done to fully stabilize the building. Work is currently under way to repair the frame and siding. The work as it was accomplished by November 14, 1989, was sympathetic to the structure and well executed. The final result should present a good interpretive restoration.

The remaining work to the frame, stone piers, doors, siding and windows could range from \$5,000 to \$8,000.

Building #7; pre 1850 Frame Shed. Though probably not a slave quarter, this small shed is a fine little example of the pre 1850 period frame construction for a building of its size. Very rare, it is a significant structure.

There have been many modifications. The siding is 1930's to 1940's as are the top plates and roofing. The single original door and jambs in the northwest wall were removed and a wider opening cut in the 20th century.

While some siding is missing, the foundation is failing and the lower frame is in poor condition, it can be salvaged. Page 7 November 16, 1989 Mrs. Faith S. Vredenburgh

It is recommended that the lower frame be carefully restored, the siding be replaced, the foundation be reset and the roof repaired. This building is not in any immediate danger, but it is in an accelerated state of disrepair. The siding should be repaired enough to protect the frame and it will need no further immediate work until the worst of the problems in the other buildings is addressed.

Repairs to restore the existing frame, siding and a new door would run between \$1,000 and \$2,000.

Building #8; "Slave" Quarters. This building was not inspected and appears to be in sound condition.

Building #9; Small Shed. The stone foundation could be older, but the shed roof and frame upper structure also dates from the 1930's to 1940's period. It is in a fairly stable state of repair and needs no immediate work. Future repairs may cost \$500 to \$800.

Page 8 November 16, 1989 Mrs. Faith S. Vredenburgh

RECAP OF BUILDING RECOMMENDATIONS AND ESTIMATES

1 -					į
1	NO.		RECOMMENDATION	ESTIMATE	
1	1	 	Record and Raze	\$1,000 to \$2,50	O
1 -		 Main Barn-1860's+/1930's-40's	Rehabilitate Shell	\$49,500 to \$62,37	5
1	3	 "Oxen" Shed-1850's/1930's-40's	 Raze Shed/Save Wall	\$20,500 to \$33,50	0
1	4	 Garage on Ice House-1940's 	 Minor Repairs 	\$3,500 to \$6,00	Û
1	5	*Blacksmith Shop*-1940's	Record and Raze	\$1,000 to \$2,00	۵
i	6	Carriage/Corn Crib	Contin. Sensitive Repairs	\$ 5,000 t a \$8,00	O .
1	7	Frame Shed-pre 1850's 	Preserve/Restore	\$1,000 to \$2,00	0
1	8	l*Slave* Quarters 	No Work	N/A	•
i I	9	Small Shed-1930's-40's	Minor Repairs I	\$500 t o \$80 	C .
1		1 1	 	 \$82,000 to \$117,17	5
1			 		L. Lie

Page 9
November 16, 1989
Mrs. Faith S. Vredenburgh

A good budgeting practice for this type of work particularly in the absence of a detailed take off estimate is to include a 25% contingency factor. There will be hidden conditions and the full scope of work is unknown.

The priority work is to unload the building from the stone wall and further stabilize the oxen shed wall. Then the barn should be fully repaired. Next, go back to the wall and either repair or rebuild and cap the wall to prevent deterioration. The two buildings need the immediate attention over all the others.

Considering the virtual onset of winter weather, much of the work can be begun and accomplished during the winter as long as men can stand the cold. However, all epoxy, mortar and paint work will have to wait until April, 1990. Repairs as briefly described could be accomplished by the end of the summer of 1990 provided funding and approvals don't slow down the process.

As weather and time permit, the hog barn and so called blacksmith shop could be recorded and razed. It is best to do this work in winter due to lack of tree foliage and vegetation, insect and snake activity. Also, the men are better padded with clothing which helps to guard against minor injuries.

The next most important structure is the Building #7, Frame Shed. The repairs to this building are relatively small scale and should be done by late 1990 or sometime in 1991.

The rest of the repairs to the other buildings can be accomplished after the other buildings have been stabilzied or restored. A less hectic pace and expenditure of money need occur to those structures requiring minor repairs.

This report is at best brief and hopefully will be useful in planning your work program. Preservation Associates, Inc. would be pleased to assist you with further planning or the actual repairs. Should you wish to check our references please feel free to call the following:

Ms. Jan Wilson, staff architect with the Maryland National Capital Parks and Planning Commission. 301-495-2544.

Page 10 November 16, 1989 Mrs. Faith S. Vredenburgh

Mr. Mike Dwyer, staff historian, Montgomery County. 301-948-1768.

Mr. Robert Seely, Chief of Div. of Construction Codes Enforcement, Montgomery County. 301-738-3140.

Please feel free to call if you have any further need of our services or any questions.

Sincerely,

Douglass C. Reed

President

DCR/11p ·

cc: Mr. Farley W. Warner

PRIORITY	BUILDING	PROJECT	ACCOMPLISHED BY	COST	PROJECTED COMPLETION.
ITEM 1 WINTER '90	OXEN SHED/ STONE WALL	PREPARATION TO WALL FOR REMOVAL OF SHE RECORD SHED RAZE SHED TEMP. COVER TO PROTECT FROM WEATHE	CONTRACTED	Between 2,000.00 4,000.00	WINTER SPRING 190
ITEM 2 WINTER '90	MAIN BARN	PURLIN REPAIRS/ROOF NW CORNER POST W GABLE TOP PLATE INT FRAMING BENT- WEST WALL FIVE CLANTILIVERD - SLEEPERS INT UPRIGHT POST - NORTH WALL W/NEW- SILL PLATE	CONTRACTED	49,000° TO 62,000°	WINTER SPRING 190
SPRING/ 90 Summer 90		NW CORNER POST RAFTERS & LATH OVER PURLIN REPAIRS ALL ROOF TIN REPAIRS NORTH SIDE ENTIRE SIDING REPAIR IN KIND RESTRUCTURE ENTRANCE RAMP & COVER REPLACE GUTTERS & DOWN SPOUTS IN KIN	Z		SPRINE! SUMMER 190

FRI 11:47 Kensinaton Copy Ctr. P. 82	Min Summer 190 OP! LIAN PALL 190	2 ¹ 200'2	CONTRACTED	חבו פוחב	STONE WALL COMMSET HUT COMMSET HUT COMMSET HUT	SWINE , do THEN 2 ZERINE , do THEW H ZERINE , do THEW H ZERINE , do THEW S THEW H ZERINE , do
08189	OP L'AIMIND 2			MASONARY REPAIRS - SEAST / SWEST CORNERS TURE STRUC - TURE TWO COATS		SPRING 90
о Z	COMPLETION PROTECTED	COST ESTIMATE	HCEDMPLISHED P. B.	PPOJECT (BULDING	PRIORITY DA

PRIORITY	9	BUILDING	PROJECT	By	ESTIMATE	COMPLETIONZ
FALLI '90 WINTER '91	7	SLAVE CAGIN PRE 1850 SHED	RESET FOUNDATION RESTORE LOWER FRAN REPLACE SIDING- IN KIND) - CONTRACTED	1,000,00 TO 2,000,00	SPRING 8
			REPLACE DOOR PAINT ENTIRE STRUCTURE	OWNER		Π
FALL '90	8	CEMETARY	REBUILD WALL ON EXISTING FOUNDATION TO MATCH EXISTING	CONTRACTED STONE CRAFT L. BONE	2,200.00	Spring 91
FALLS 90 WINTER	9	CARRIAGE HOUSE	MASONARY REPOINTING ON STONE PIERS REPAIR OR REPLACE SIDING IN KIND	- SUB CONTRACTED	5,000° 8,000°	FALL, 90 W
		į	REPAIR OR REPLACE	NEW TIN ROOF ON SIDE STRUCTURE (COP OR TIN INC)	600.00	0 3
SPRINC! SUMMER , 9	0	ICE HOUSE	PAINT STRUCTURE SIDING REPAIRS IN REPAIR WINDOWS & LOFT DOORS	OWNER	3,500.00 6,00000	FALL 91
-12 A	<i>\\</i>	GROUNDS KEEPE	REPLACE ROOF PAINT STRUCTURE	COPORTIN ING	1,200.00	
SUMMEL 91	12	SMALL SHED	NESS SIOING REPAIRS, PAINT NESS SIDING REPAIRS PAINT	OWNER	500.00 TO 800.00	EALL! WINTER 9!

HISTORIC PRESERVATION COMMISSION STAFF REPORT

PREPARED BY: Jared B. Cooper DATE: August 7, 1989

CASE NUMBER: 23/46-89A TYPE OF REVIEW: HAWP

SITE/DISTRICT NAME: "Greenwood" PROPERTY ADDRESS: 21315 Georgia Avenue Brookeville, MD 20833

DISCUSSION: As you will recall, a representative of the owners of Greenwood Farm came before the Commission on January 5, 1989, in order to request the demolition of four outbuildings (see "chronology of events" memo, Attachment #3). At that time, the Commission denied the request (see Stephen Johnson letter, Attachment #2).

Since that time, staff has visited the site, conducted a thorough inspection of the buildings in question, and met with the applicant and her representatives.

STAFF RECOMMENDATION: Staff recommends the following:

- 1. "Corn Shed": Of the four buildings in question, this appears to be the earliest (late 19th century) and best constructed, although parts of the "oxen shed" are probably earlier. Unfortunately, the corn shed is in an advanced state of deterioration, and has all but fallen down. Staff recommends approval of the request for demolition for the following reasons:
 - A. by most standards, it is well past the point of restorability, and;
 - B. even though it "was" a well-constructed and designed structure, it does not exhibit any unusual architectural features or construction techniques which would render it worthy of a monumental restoration project.
- 2. "Hog House": This structure appears to have been constructed during the early 20th century. It was never very outstanding in terms of design or construction techniques, although it certainly contributes to the "farmscape." It is in relatively good condition, with a fairly good roof. Its worst problem is that the foundation, along two sides, has settled into the ground. However, the building is, by no means, falling down and the foundation problems could be halted by use of a combination of shoring, minor grading, and installation of a guttering system.

Staff recommends that the applicant be denied permission to raze the "hog house." There don't seem to be any sound reasons to demolish this structure, and it would be fairly easy and inexpensive to maintain it. Staff also recommends that the applicant be asked to take measures to protect the building from further deterioration. Such measures would include installation of gutters; minor grading, to pull away some of the buildup caused by excessive runoff, and to deter continued runoff damage; shoring up the settled portions of the foundation, utilizing the pier and beam system (as original); and roof maintenance. There is no danger of rapid deterioration, and the applicant could be given as much as a year or two to complete the work, as long as progress was being made on other more significant outbuildings during that time.

3. "Oxen Shed": This building, dubbed "Oxen Shed" by a former owner, appears to have been designed as what would commonly be known as a machinery/implement shed. Apparently, it was constructed during the 20th century. For the most part, it is constructed of tongue-and-groove rail car siding. One side of the roof rests on a pre-existing stone wall (approx. 7' high), which appears to have been constructed during the mid-nineteenth century, (possibly earlier) although it would be difficult to document. It is joined at both ends by a continuous stone fence which traverses the farmstead, separating the barnyard, residential yard, and cemetery.

The stone wall was probably part of the foundation of an earlier, perhaps larger, agricultural building. It has a doorway in the center, flanked by a series of small vent openings in the wall. The weight of the building, along with poor construction technique and footing problems, is causing the wall to bow outward. This movement has been temporarily halted by a previous owner through the installation of wooden buttresses. The building itself, while it has a good roof, is in poor structural condition. Some of the problems could probably be corrected, but the building (with the exception of the stone wall) hardly warrants salvation.

Staff recommends approval of the request for demolition of the wooden portion of the structure, for the following reasons: a) It is not architecturally significant; b) it is in poor structural condition; and c) it appears to be causing stress to the stone wall on which it rests.

However, staff recommends that approval be granted with the condition that measures (approved by the Commission) be taken to protect and preserve the stone wall. Such measures might include a thin troweled "soft mortar" cap, or even construction of an appropriate building, replacing the existing. Also staff recommends that the applicant be encouraged to "right" the leaning section of the wall if the building is removed.

4. "Blacksmith shop": This structure appears to have been constructed during the early 20th century, at or about the time of construction of the "hog house." It may have served as a blacksmith shop at one time, although, if that was the case, it has long since lost all fixtures and appurtenances which would have been associated with that use. Most recently, it appears to have served as a tool shed or workshop. It is in poor condition, as a result of poor original design and a bad roof. It is situated in a row of three buildings which includes the ice house and a carriage house. Both of these other buildings date from an earlier period and are in better condition. The applicant has been slowly restoring them.

Staff recommends that the applicant be permitted to raze the "blacksmith shop." In staff's opinion, it is not significant in terms of age, design, or construction technique. While it would be possible to restore the structure, staff recommends that, instead, the applicant be enouraged to complete the restoration and repair of the flanking structures.

- 1) "Corn Shed" (based on criterion 24A-8(b)(4))
- 2) "Oxen Shed" (based on criteria 24A-8(b)(1) and (4)
- 3) "Blacksmith Shop" (based on criteria 24A-8(b)(1) and (4)

Staff recommends that the applicant be denied permission to raze the "hog house." Although its foundation is in poor condition it could be repaired and stabilized relatively easily. However, like the "blacksmith shop," staff feels that it is not a particularly early or outstanding structure.

ATTACHMENTS:

1. HAWP Application

2. Letter from Applicant's Attorney (and attachments)

3. Memorandum from Mel Tull

4. Photographs (slides will be shown at the meeting)

JBC:bdm 1284E

PRESERVATION ASSOCIATES, INC.

CONSULTANTS

207 S. POTOMAC STREET HAGERSTOWN, MARYLAND 21740 PHONE (301) 791-7880

PHONE (301) 791-7880 FAX (301) 791-7896

DOUGLASS C. REED PRESIDENT

::

PRESERVATION PLANNING
COMMERCIAL REHABILITATION
RESIDENTIAL REHABILITATION
NATIONAL REGISTER NOMINATIONS

November 16, 1989:

Faith S. Vredenburgh 21315 Georgia Ave. Brookeville, MD 20833

RE: Barn and other outbuildings associated with Main House at above listed address

Dear Mrs. Vredenburgh:

Thank you for the opportunity to visit with you and your son-in-law John Abernethy as well as Mr. Farley Warner. As you will recall, the purpose of my visit was to review most of the nine standing buildings associated with the main house. The buildings were to be inspected with an opinion rendered as to whether the buildings could be salvaged, and, if so, which ones and at what cost. The one critical task was to identify immediate stabilization of critical buildings and identify a rough outline for near future work to restore buildings.

Please keep in mind that the estimates offered in this letter are not guaranteed and were arrived at by a brief inspection of each building. Estimates were established on size of building, difficulty of repairs/tasks and on past experience of restoration in similar situations. The estimates are for budgeting and loan application purposes but cannot be considered contract prices. In order to obtain contract prices a detailed analysis of each piece of each building will have to be done and a work description established. Then all bidding parties will know the scope of the work and can submit comparative bids unless you select and negotiate with one contractor.

Page 2 November 16, 1989 Mrs. Faith S. Vredenburgh

Building #1; Hog Barn. Due to the uric acid from the hogs and from negative drainage where water runs off a hill into the footers, the building's foundations have been washed away under the entire northwest half of the building. The bottom members of the frame structure are also extensively rotted that the economics of salvation don't make the building worth saving.

The building as a 20th century hog barn where extensive work was done to the building in the 1930's or 1940's, is not significant to Maryland's agricultural vernacular landscape. There are many remaining examples of this type of structure in the state and either in or in close proximity to Montgomery County.

Due to the cost of saving the building which would entail dismantling and rebuilding a rather insignificant structure, I recommend you sketch the floor plan, make key dimensions of the floor plan on the sketch, take good, clear black and white glossies of the building to include all four exterior sides and other key building details to fully record the building. Once the building has been properly located on a site plan, plot plan or survey plat and has been recorded, raze the building. Cost to record and raze the building would be \$1,000 to \$2,500.

Building #2; The Barn. This is a significant building. The earlier frame section appears to date from the later half of the 19th century. While the round top barn addition is dateable to the mid 20th century, probably 1930's or 1940's. A unique feature of the frame section is the location of the grain rooms under the threshing floor.

The barn frame is very savable. The northwest quadrant has suffered the worst deterioration. The main west roof purlin, the northwest corner post, the west gable top plate, the top plate of the first interior framing bent west of the west wall, five of cantilevered sleepers of the lower west hay mow and the first upright intermediate post of the north wall west of the corner, all are in need of repair. There is roughly about 100 linear feet of post and beam repairs that need to take place through epoxy reconsolidation, replacement with appropriate size materials, or mechanically rekeying worn out mortize and tenon joints.

Page 3 November 16, 1989 Mrs. Faith S. Vredenburgh

Further structural stabilization is required in the northeast corner. There is a need for a new sill to be placed under the sistered intermediate post of the north wall just east of the corner. The northeast corner post needs to be stabilized with new connections at some of the joints.

The roof rafters and lath over the purlin to be replaced in the northwest quadrant will have to be reset in place. The roof on the entire south slope and most of the north slope can be tightened up and kept in place. A new corrugated roof will have to be placed over the area of the purlin repairs. Unfortunately, the new corrugated roofing available does not match the ridge to ridge size of the mid 20th century corrugated roofing in place. However, the difference while noticeable, is minor and should be suitable and appropriate.

All the wooden siding needs to be repaired on the frame barn. Originally the entire barn was sided with vertical boards and battens as found on the south bridge wall side. The other sides are covered with mid 20th century novelty siding. All sides should be repaired in kind.

There are minor masonry repairs needed to the southeast and southwest corners, but otherwise the foundation walls are in very good condition.

The covered entrance bridge-way on the south wall needs to be restructured and kept as a maintained entranceway to the main threshing floor.

The gutters, rakes and barge boards all need to be replaced in kind. The half round metal gutters, 6" galvanized are original and still the most appropriate type.

The site should be cleared of all growth and debris and graded to provide positive drainage away from the structure.

The entire structure should be painted, two coats including roof and all wood and metal.

No work is immediately needed on windows and doors, but in the future these items will need to be addressed. Page 4 November 16, 1989 Mrs. Faith S. Vredenburgh

The following is a recap of speculative estimates:

Demolition and Trash Removal	\$ 2,000.00
Structural Repairs	16,000.00
Carpentry	1,000.00
Roofing Metal	6,000.00
Siding Repairs and Partial Replacement	4,500.00
Masonry Repairs	2,000.00
Covered Entranceway Bridge	6,000.00
Gutters	2,000.00
Painting	10,000.00
25% Contingency for Unforseen Conditions	12,875.00
	\$62,375.00

It must be stated that while one category may seem low another may be high. The entire work should cost about \$47,500 to \$58,000.

Building #3; Oxen (Loafing) Shed or now a Wagon/Implement Shed. The condition of this structure is unquestionably poor and in immediate danger of collapse. If the roof framing collapses on its own, it is likely going to upset the stone wall or at least further damage it to the point of no repair.

The building has two noteable parts. The rear, north stone wall is a 19th century stone structure built to terminate at each end in a square column. Along the 80 foot long, 8 foot high wall is an evenly spaced series of ventilators and in the center of the wall is one door. Part of the 19th century door frame still is in place.

The rest of what is left of the building dates from the 1930's to 1940's influence. Virtually all the roof, frame, and cladding is of 20th century manufacture. There are one or two pieces of 19th century framing, but all the framing is salvage lumber from mostly turn of the 20th century buildings.

Page 5 November 16, 1989 Mrs. Faith S. Vredenburgh

The frame structure has completely failed and is beyond salvage. If you wish to even attempt to save the wall, the rest of the building must be removed before the next major wind or snow storm. I strongly recommend the wooden structure be recorded as described under Building #1 and immediately razed. Cost to record and move the structure leaving the wall will be between \$2,000 and \$4,000.

It is in my opinion that the stone wall can be righted, stabilized and underpinned. I would want a structural engineer I know to look at the wall. He is extremely experienced and sympathetic to older, troubled buildings. Even if he says it needs to come down, it can be partially salvaged and the remainder re-erected.

The pricing on this wall could be as low as \$18,000 and run as high as \$28,000. Consulting could be between \$500 and \$1,500.

Building #4; Garage on Ice House. This is another mid 20th century frame structure built over an older, 19th century foundation set deep into the ground and used as an ice house. The building has recently been worked on and is in a good state of stabilization and fairly good repair. No work is needed to immediatly stabilize the building and the remaining repairs can wait for a few years until the more pressing repairs of the other buildings has been accomplished.

A very rough estimate of the work remaining to put the building into an excellent state of repair would run between \$3,500 and \$6,000.

Building #5; known as Blacksmith Shop. Actually is a small workshop built entirely of new materials in the 1930 to 1940's period. With a concrete floor, all circular sawn wood, wire nails and composition shingles. The building was built, used and never maintained.

Page 6 November 16, 1989 Mrs. Faith S. Vredenburgh

Apparently no owner ever felt a need to maintain this structure and it has sort of "melted" away. It literally is being held up by a poplar tree the building is leaning against. There is no structural integrety left of the individual pieces or the component whole of the frame. Even if you wished to save the structure, it would require so much new material, the final result would be more of a new replica of what is there and not a restoration. Far more than 50% of the entire structure would need to be replaced.

As described under Building #1, I recommend this building be recorded, razed and all debris removed. Cost of recording and demolition will range between \$1,000 and \$2,000.

Building #6; Carriage Shed, Corn Crib. This is a good mid 19th century hand hewn frame structure that was refurbished in the 1930 to 1940's period. New horizontal siding, roof, staircase, second floor and new walls, doors and windows were added in the 20th century remodeling.

The building needs the stone piers to be repointed and a little more frame work to be done to fully stabilize the building. Work is currently under way to repair the frame and siding. The work as it was accomplished by November 14, 1989, was sympathetic to the structure and well executed. The final result should present a good interpretive restoration.

The remaining work to the frame, stone piers, doors, siding and windows could range from \$5,000 to \$8,000.

Building #7; pre 1850 Frame Shed. Though probably not a slave quarter, this small shed is a fine little example of the pre 1850 period frame construction for a building of its size. Very rare, it is a significant structure.

There have been many modifications. The siding is 1930's to 1940's as are the top plates and roofing. The single original door and jambs in the northwest wall were removed and a wider opening cut in the 20th century.

While some siding is missing, the foundation is failing and the lower frame is in poor condition, it can be salvaged.

Page 7 November 16, 1989 Mrs. Faith S. Vredenburgh

It is recommended that the lower frame be carefully restored, the siding be replaced, the foundation be reset and the roof repaired. This building is not in any immediate danger, but it is in an accelerated state of disrepair. The siding should be repaired enough to protect the frame and it will need no further immediate work until the worst of the problems in the other buildings is addressed.

Repairs to restore the existing frame, siding and a new door would run between \$1,000 and \$2,000.

Building #8; "Slave" Quarters. This building was not inspected and appears to be in sound condition.

Building #9; Small Shed. The stone foundation could be older, but the shed roof and frame upper structure also dates from the 1930's to 1940's period. It is in a fairly stable state of repair and needs no immediate work. Future repairs may cost \$500 to \$800.

Page 8 November 16, 1989 Mrs. Faith S. Vredenburgh

RECAP OF BUILDING RECOMMENDATIONS AND ESTIMATES

1-						
BI	NO.		RECOMMENDATION	ESTIMATE		
1	1	 Hog Barn-1930's-1940's	Record and Raze	 \$1,000 to	\$2,500 I	
	2	Main Barn-1860's+/1930's-40's	Rehabilitate Shell	1\$49,500 to	\$62,375	
1	3	 "Oxen" Shed-1850's/1930's-40's	Raze Shed/Save Wall	 \$20,500 to	\$33,500 l	
l I	4	Garage on Ice House-1940's	Minor Repairs	 \$3,500 to	\$6,000	
1	5 1	"Blacksmith Shop"-1940's	Record and Raze	 \$1,000 to	92,000 I	
1	6	Carriage/Corn Crib	 Contin.Sensitive Repairs	 \$5,000 to	\$8,000	
1	7	Frame Shed-pre 1850's	 Preserve/Restore	 \$1,000 to	\$2,000 i	
1	8	"Slave" Quarters	No Work	I N/A		
l l	9 1	Small Shed-1930's-40's	Minor R e pairs	 \$500.to	! \$800 i	
				 \$82,000 to 	\$117,175	

Page 9 November 16, 1989 Mrs. Faith S. Vredenburgh

A good budgeting practice for this type of work particularly in the absence of a detailed take off estimate is to include a 25% contingency factor. There will be hidden conditions and the full scope of work is unknown.

The priority work is to unload the building from the stone wall and further stabilize the oxen shed wall. Then the barn should be fully repaired. Next, go back to the wall and either repair or rebuild and cap the wall to prevent deterioration. The two buildings need the immediate attention over all the others.

Considering the virtual onset of winter weather, much of the work can be begun and accomplished during the winter as long as men can stand the cold. However, all epoxy, mortar and paint work will have to wait until April, 1990. Repairs as briefly described could be accomplished by the end of the summer of 1990 provided funding and approvals don't slow down the process.

As weather and time permit, the hog barn and so called blacksmith shop could be recorded and razed. It is best to do this work in winter due to lack of tree foliage and vegetation, insect and snake activity. Also, the men are better padded with clothing which helps to guard against minor injuries.

The next most important structure is the Building #7, Frame Shed. The repairs to this building are relatively small scale and should be done by late 1990 or sometime in 1991.

The rest of the repairs to the other buildings can be accomplished after the other buildings have been stabilzied or restored. A less hectic pace and expenditure of money need occur to those structures requiring minor repairs.

This report is at best brief and hopefully will be useful in planning your work program. Preservation Associates, Inc. would be pleased to assist you with further planning or the actual repairs. Should you wish to check our references please feel free to call the following:

Ms. Jan Wilson, staff architect with the Maryland National Capital Parks and Planning Commission. 301-495-2544.

Page 10 November 16, 1989 Mrs. Faith S. Vredenburgh

Mr. Mike Dwyer, staff historian, Montgomery County. 301-948-1768.

Mr. Robert Seely, Chief of Div. of Construction Codes Enforcement, Montgomery County. 301-738-3140.

Please feel free to call if you have any further need of our services or any questions.

Sincerely,

Douglass C. Reed

President

DCR/11p ·

cc: Mr. Farley W. Warner

MEMORANDUM

TO: Historic Preservation Commissioners

FROM:

Jared B. Cooper

DATE:

October 26, 1989

SUBJECT: Greenwood (Master Plan Site #23/46)

You will probably recall that owners and representatives of Greenwood (MP Site #23/46) came before the Commission on August 17, 1989, requesting permission to raze four outbuildings. Following deliberation, the Commission moved 1) to approve the removal of the corn crib with the condition that, within 60 days, the applicant return to the Commission with an acceptable written plan and schedule for the stabilization/restoration of the remaining outbuildings, and 2) to keep the record open on the request to demolish the other three buildings until after the plan had been submitted (see attached excerpt of 8/17/89 minutes).

Now, the applicant is returning to the Commission with such a plan (see attached). Although more than 60 days have elapsed, the applicant had submitted a timely first draft, which staff returned to the applicant along with a request for more information. While the plan is not detailed in terms of methodology, it does at least establish a time-line, broken down by years (5 years total). Staff feels that this is adequate, but that it will be important for the Commission (staff) to inspect the project on an annual basis.

On November 2, if the report is found to be satisfactory, it will be necessary for the Commission to take up the deliberations on the fate of the other three outbuildings targeted for demolition. I will provide slides, engineer's reports, and other information. Please contact me prior to the meeting if you have any questions or comments.

JBC:av

Attachments

1040i

Excerpt: Minutes: 8/17/89

Commissioner Hartman seconded the motion, which passed unanimously.

At this point, Commissioner Karr exited the meeting.

E. Application by Faith Vrendenburgh for Historic Area Work Permit at 21315 Georgia Avenue, Brookeville, MD (HPC Case No. 23/46 - 89A)

Chairperson Miskin opened the public record and requested a staff report. Mr. Cooper noted that the hearing on the above application was advertised in the August 7, 1989 edition of the Montgomery Journal, and presented slides of Greenwood Mansion and its surrounding outbuildings. Mr. Cooper gave a brief background of the case, and explained that the applicant had engaged the services of an engineer to evaluate the outbuildings on the property that she proposed to demolish, those being the corn shed, the oxen shed, the hog house, and the blacksmith shop. Staff recommended that the applicant be permitted to raze the corn shed, the oxen shed (with the exception of the stone wall portion of the structure), and the blacksmith shop, but recommended that the applicant be denied permission to raze the hog house. Although its foundation is in poor condition, staff said, it could be repaired and stabilized relatively easily. However, like the blacksmith shop, staff feels that it is not a particularly early or outstanding structure.

Mr. Stephen Johnson, attorney for the applicant, stated that the applicant, Mrs. Vrendenburgh, wants to preserve the buildings that are preservable. Mr. Johnson said that Mrs. Vrendenburgh is willing and has always been willing, to work with the Commission to resolve the problems at Greenwood, and has gone to great expense to have the buildings surveyed by Mr. Thomas Carcaterra, P.E., who came forward to present his findings to the Commission.

Mr. Carcaterra presented extensive photographs of the subject outbuildings, and stated his recommendation that all four buildings be demolished.

Mr. Johnson presented two estimates, one from Oak Grove Designs and one from UDO Services, for repairing or reconstructing the four structures. Mr. Johnson concluded his presentation by asking that the Commission consider where the money will come from if the buildings must be restored or stabilized, as his client does have, according to him, limited funds.

Mr. Leonard Becraft, former owner and resident of Greenwood, came forward to read a statement dated January 4, 1989, registering his disappointment in the state of the buildings and emphasizing his wish to see all restored and/or stabilized. Mr. Becraft's wife, Betty, also spoke to say that she hoped if the buildings were demolished that the property owner would save the lumber for others to use in restoration projects. Mr. Ted Crystal, a friend of the Becraft family, also spoke in favor of stabilizing or restoring the structures.

Commissioner Cantelon asked Mrs. Vrendenburgh whether she had sought any type of loan or grant to repair or restore the buildings through the Maryland Historical Trust or any other agency that would supply loans. Mrs. Vrendenburgh said she had not, and was not aware of any such programs. Commissioner Cantelon expressed his surprise at this, and Mrs. Vrendenburgh stated that when she became aware of the enormity of the project of restoring Greenwood, she sat down with her representatives and decided what projects were priority. She stated that she would like the Commission to tell her which buildings are priority, as her funds are limited to the point where all of the buildings cannot be addressed at once.

Commissioner Brenneman asked what work has been done on the property since Mrs. Vrendenburgh purchased Greenwood. Mr. Johnson replied that, in addition to heating and air conditioning work on the main house, the barn roof support was repaired at a cost of \$5,000, and the siding on the ice house, while not complete, has cost \$3,000 to date. The carriage house repairs, he said, have cost \$2500, trash removal \$600, and there is an estimate for repair of the main barn in the amount of \$23,000. Commissioner Cantelon asked if a schedule for repair existed. Mr. Johnson that there was no specific schedule, but that Mrs. Vrendenburgh was waiting for the Commission to tell her which buildings must be saved.

Commissioner Cantelon said that he would like to see the applicant formulate a comprehensive plan and timetable for stabilization and protection of the existing buildings with priorities and budgeting specified, and where monies might be raised; he stated he felt this action might resolve the problem that began before Mrs. Vrendenburgh bought the property.

Commissioner Hartman gave Mrs. Vrendenburgh the information on the National Trust for Historic Preservation, and the Maryland Historical Trust.

Commissioner Brenneman stated his disappointment at the weakness of the Demolition By Neglect program, saying that the buildings were in much better shape 10 years ago, and have simply been deteriorating ever since with no strict intervention on the part of the County.

There being no further discussion, Chairperson Miskin closed the record.

Commissioner Cantelon MOTIONED to approve the removal of the corn crib, and as a condition of that approval, that the applicant work with Commission staff and the Maryland Trust and return to this Commission in 60 days with an acceptable plan of stabilization and/or restoration of the remaining outbuildings, during which time the Commission will keep the application on the other 3 buildings open and deliberate on those three requests for demolition after the 60 days. The motion was made on the basis of criterion 24A - 8(b)(4), that the proposal is necessary in order that unsafe conditions or health hazards be remedied. Commissioner Taylor seconded the motion, which passed 6-1, Commissioner Brenneman in dissent.

OCTOBER 19 1989

JOHN M ABERNETHY
GREENWOOD FARM
21315 GEORGIA AVE
BROOKEVILLE MARYLAND 20833

MR. JARED COOPER, EXECUTIVE DIRECTOR HISTORIC PRESERVATION COMMISSION 51 MONROE ST ROCKVILLE MARYLAND 20850

DEAR MR. CCOPER:

PER CUR PHONE CONVERSATION TWO DAYS AGO, THIS IS A FINAL DRAFT OF OUR FROPOSAL TO SCHEDULE A TIME FRAME FOR STABILIZATION OR RESTORATION OF OUTBUILDINGS AT THE GREENWOOD SITE, 23 46

THE PROJECT WOULD CONSIST OF SEPERATE SCHEDULES OVER A FIVE YEAR PERIOD. CONTRACT, SUB CONTRACT AND HOMEOWNER REPAIRS SHALL COMMENCE TO MEET THE REQUIREMENTS OF EACH PROJECT SIMULTAIOUSLY OR INDIVIDUALY BASED ON FOLLOWING THE TIME SCHEDULE FOR EACH YEAR OF THE FIVE YEAR PLAN THAT I HAVE ATTACHED. THIS IS I BELIEVE, THE BEST METHOD FOR STABILIZATION OF PROPERTY 21315 GEORGIA AVE WHITHOUT DISRUPTING THE ACTIVITIES DEEMED NESSESSARY FOR ANY OF THE NORMAL MAINTAINANCE REQUIREMENTS THAT A PROPERTY THIS SIZE HAS.

WHILE A FAIR AMOUNT OF PROGRESS HAS BEEN MADE ON THE SMALLER STRUCTURES AND MAIN BARN, WE ARE STILL IN THE PROCESS OF EVALUATING AND SEEKING THE PROPOSALS NEEDED FOR SCHE OF THE MORE COMPLEX JOBS. WITH THIS FIVE YEAR PLAN, A STEADY PROGRESSTION TOWARDS STABILIZATION OF THE OUTBUILDINGS CAN BE ACHEIVED.

TO ASSURE THAT PROGESS IS BEING MADE, WE PROPOSE THAT THE HISTORIC PRESERVATION COMMISSION APPOINT A REPRESENTATIVE OF THE STAFF AND OR A COMMISSIONER, TO ALCHG WITH A REPRESENTATIVE OF CODE ENFORCEMENT, MAKE A YEARLY INSPECTION OF THE PROGRESS OF REPAIRS LISTED FOR EACH YEAR OF THE FIVE YEAR PERIOD. A POSSIBLE STARTING POINT FOR THIS YEARLY INSPECTION COULD BE THE FALL OF NEXT YEAR 1990. THAT WOULD GIVE US THE TIME NEEDED TO FULFILL THE REQUIREMENTS OF WHAT LOCKS TO BE A HEAVY FIRST YEAR SCHEDULE.

I WOULD LIKE TO THANK YOU FOR ADVICE IN THE WAY YOU HAVE GUIDED US TO ESTABLISH THIS DRAFT.

SINCERELY

JOHN A. ABERNETHY

CONTRACT, SUB CONTRACTED WORK

MAIN BARN. QUANSET HUT

- 1. STRUCTURAL REPAIRS NEEDED IN EAST AND WEST SIDES
- 2. STRUCTURAL REPAIRS IN NORTH SIDE OF ROOF
- 3. COMPLETE CARPENTRY NEEDED FOR NEW ROOF, NORTH SIDE
- 4. SIDING REPAIRS OR REPLACEMENT AS REQUIRED IN EAST AND WEST SIDES
- 5. NEW METAL ROOF INSTALLED NORTH SIDE
- 6. REPAIRS TO ENTRANCE, ROCF, SIDES, RAMP, NEW TIN ROCF INSTALLED
- 7. SIDING REPAIRS ON SOUTH SIDE
- 8. GUTTERS REPAIRED OR REPLACED DOWN SPOUTS REPAIRED
- 9. PRIME AND PAINT ENTIRE STRUCTURE

OXEN SHED, W STONE WALL

- 1. SUPPORT STONE WALL IN PREPARATION OF REMOVELL OF SHED
- 2. REMOVE EXISTING STRUCTURE IN SECTIONS WHITHOUT DAMAGING WALL
- 3. FURTHER STUDY POSSIBLE METHODS FOR STONE REPAIR

HOG HOUSE

- 1. DISMANTLE, SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP, TRASH REMOVAL, LANDSCAPE

HOME OWNER REPAIRS

CARRIAGE HOUSE

- 1. SIDING REPAIRS OR REPLACEMENT
- 2. WINDOW REPAIRS
- 3. SIDE DOORS REPAIRED OR REPLACED
- 4. MAIN DOORS HUNG FRONT AND BACK
- 5. PRIME PAINT

STONE WALL NEXT TO DRIVEWAY

COMPLETE UNFINISHED REPAIRS FROM DAMAGE THAT OCCURED IN MOTOR VEHICLE ACCIDENT LAST YEAR,

BLACK SMITH SHOP

- 1. DISMANTLE, SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP. LANDSCAPE

REFAIR SCHEDULE SECOND YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

CONTRACT, SUB CONTRACT WORK

MAIN BARN QUANSET HUT

- 1. RE POINT BARN FOUNDATION WHERE NEEDED
- 2. MASONARY REPAIRS TO BLOCK ON WEST WALL
- 3. REPAIR WINDOW LENTILS
- 4. REPLACE GLASS AND RE GLAZE SIX WINDOWS IN BLOCK
- 5. BUILD NEW GUTTER FOR WEST SIDE OF HUT
- 6. PAINT ENTIRE RCOF

CARRIAGE HOUSE

- 1. SPOT REPAIRS OF TIN
- 2. SCRAPE , PAINT ROOF

ICE HOUSE

- 1. REMOVAL OF EXISTING ROOF
- 2. INSTALL NEW METAL ROOF
- 3. INSTALL GUTTERS AND DOWN SPOUTS

HOME OWNER REPAIRS

ICE HOUSE

- 1. SIDING REPAIRED OR REPLACED AS REQUIRED
- 2. WINDOWS REPAIRED NORTH SIDE
- 3. REPAIRED SHUTTER TYPE LOFT DOORS INSTALLED
- 4. FRIME PAINT STRUCTURE
- 5. GRADE , LANDSCAPE

REPAIR SCHEDULE THIRD YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

<u>ಇಂಬೆಂಚಿಂ</u>ಂ

CONTRACT , SUB CONTRACT WORK

CEMETARY WALL

1. REBUILD CEMETARY WALL ON EXISTING FOUNDATION TO MATCH EXISTING

OXEN SHED WALL

- 1. NEGESSARY ENGINEERING AND MACCHARY REQUIRED TO STABILIZE WALL.
- 2. LANDSCAPE, GRADE FOR BETTER DRAINAGE

BLACK SMITH SITE

1. SUBMIT PROPOSAL AT THIS TIME TO H P C FOR RELOCATING SLAVE CABIN (TOOL SHED)
TO SITE AT WHICH BLACK SMTTH SHOP STOOD, BEFORE NEXT YEARS WORK ON SLAVE CABIN
GCMMENCES. TO RESTORE AFFEARANCE FROM ROAD, BETTER FACILITATE THE USE OF BUILDING
AND TO EASE CROWDING ON OTHER BUILDINGS.

HOME OWNER REPAIRS

CARRIAGE HOUSE SIDE STRUCTURE (CAR PORT)

- 1. REMOVAL OF TAR SHINGLE ROOF
- 2. REMOVAL OF ALL DETERIORATED/WATER DAMAGED WOOD
- 3. REPLACE ALL DAMAGED WODD
- 4. REPAIR OR REPLACE SIDING WHERE NEEDED
- 5. REPAIR OR REPLACE ROOF LATHINGWHERE NEEDED
- 6. INSTALL NEW TIN ROOF
- .7. PRIME, PAINT STUCTURE

REPAIR SCHEDULE FORTH YEAR GREENWOOD 21315 GEORGIA AVE BROCKEVILLE MD

SUB CONTRACT OR HOMEOWNER REPAIRS

SLAVE CABIN (TOOL SHED)

- 1. WITH APPROVAL, PREPARE SITE OF BLACK SMITH SHOP TO ACCEPT FOUNDATION DIMENTIONS OF SLAVE CABIN. DISMANTLE, OR SECURE TO MOVE WHOLE, WHILE REPLACING NEEDED WOOD IN SILLS TO TRUE UP STRUCTURE.
- 2. REPLACE ALL OTHER WOOD AS REQUIRED
- 3. REPAIR OR REPLACE SIDING AS REQUIRED
- 4. PAINT ROOF
- 5. PRIME PAINT SIDING
- 6. REPLACE DOOR
- 7. WITHOUT APPROVAL, REPLACE STRUCTURAL WOOD WHERE NEEDED
- 8. REPAIR , REPLACE SIDING
- 9. REPLACE DOOR
- 10. PAINT ENTIRE STRUCTURE

SUB CONTRACT OR HOMEOWNER REPAIRS

GROUNDS KEEPERS SHED

- 1. RE NAIL ALL LOOSE SIDING
- 2. PAINT ROOF
- 3. PAINT SIDING ANDW WINDOW FRAMES

SMALL SHED

- 1. REPAIR SIDING AS REQUIRED
- 2. PAINT ENTIRE STRUCTURE

MISC.

- 1. ALL OTHER UNFINISHED REPAIRS AND PAINTING
- 2. ALL REQUIRED LANDSCAPE NEEDS
- 3. ALL OTHER CLEAN UP, TRASH REMOVAL

OCTOBER 19 1989

JOHN M ABERNETHY
GREENWOOD FARM
21315 GEORGIA AVE
BROOKEVILLE MARYLAND 20833

MR. JARED COOPER, EXECUTIVE DIRECTOR HISTORIC PRESERVATION COMMISSION 51 MONROE ST ROCKVILLE MARYLAND 20850

DEAR MR. COOPER:

PER OUR PHONE CONVERSATION TWO DAYS AGO, THIS IS A FINAL DRAFT OF OUR PROPOSAL TO SCHEDULE A TIME FRAME FOR STABILIZATION OR RESTORATION OF OUTBUILDINGS AT THE GREENWOOD SITE. 23 46

THE PROJECT WOULD CONSIST OF SEPERATE SCHEDULES OVER A FIVE YEAR PERIOD. CONTRACT, SUB CONTRACT AND HOMEOWNER REPAIRS SHALL COMMENCE TO MEET THE REQUIREMENTS OF EACH PROJECT SIMULTAIOUSLY OR INDIVIDUALY BASED ON FOLLOWING THE TIME SCHEDULE FOR EACH YEAR OF THE FIVE YEAR PLAN THAT I HAVE ATTACHED. THIS IS I BELIEVE, THE BEST METHOD FOR STABILIZATION OF PROPERTY 21315 GEORGIA AVE WHITHOUT DISRUPTING THE ACTIVITIES DEEMED NESSESSARY FOR ANY OF THE NORMAL MAINTAINANCE REQUIREMENTS THAT A PROPERTY THIS SIZE HAS.

WHILE A FAIR AMOUNT OF PROGRESS HAS BEEN MADE ON THE SMALLER STRUCTURES AND MAIN BARN, WE ARE STILL IN THE PROCESS OF EVALUATING AND SEEKING THE PROPOSALS NEEDED FOR SOME OF THE MORE COMPLEX JOBS. WITH THIS FIVE YEAR PLAN, A STEADY PROGRESSTION TOWARDS STABILIZATION OF THE OUTBUILDINGS CAN BE ACHEIVED.

TO ASSURE THAT PROGESS IS BEING MADE, WE PROPOSE THAT THE HISTORIC PRESERVATION COMMISSION APPOINT A REPRESENTATIVE OF THE STAFF AND OR A COMMISSIONER, TO ALONG WITH A REPRESENTATIVE OF CODE ENFORCEMENT, MAKE A YEARLY INSPECTION OF THE PROGRESS OF REPAIRS LISTED FOR EACH YEAR OF THE FIVE YEAR PERIOD. A POSSIBLE STARTING POINT FOR THIS YEARLY INSPECTION COULD BE THE FALL OF NEXT YEAR 1990. THAT WOULD GIVE US THE TIME NEEDED TO FULFILL THE REQUIREMENTS OF WHAT LOOKS TO BE A HEAVY FIRST YEAR SCHEDULE.

I WOULD LIKE TO THANK YOU FOR ADVICE IN THE WAY YOU HAVE GUIDED US TO ESTABLISH THIS DRAFT.

SINCERELY

JOHN N. ABERNETHY

REPAIR SCHEDULE FIRST YEAR GREENWOOD 21315GEORGIA AVE BROOKEVILLE MD

CONTRACT, SUB CONTRACTED WORK

MAIN BARN, QUANSET HUT

- 1. STRUCTURAL REPAIRS NEEDED IN EAST AND WEST SIDES
- 2. STRUCTURAL REPAIRS IN NORTH SIDE OF ROOF
- 3. COMPLETE CARPENTRY NEEDED FOR NEW ROOF , NORTH SIDE
- 4. SIDING REPAIRS OR REPLACEMENT AS REQUIRED IN EAST AND WEST SIDES
- 5. NEW METAL ROOF INSTALLED NORTH SIDE
- 6. REPAIRS TO ENTRANCE, ROOF, SIDES, RAMP. NEW TIN ROOF INSTALLED
- 7. SIDING REPAIRS ON SOUTH SIDE
- 8. GUTTERS REPAIRED OR REPLACED DOWN SPOUTS REPAIRED
- 9. PRIME AND PAINT ENTIRE STRUCTURE

OXEN SHED, W STONE WALL

- 1. SUPPORT STONE WALL IN PREPARATION OF REMOVELL OF SHED
- 2. REMOVE EXISTING STRUCTURE IN SECTIONS WHITHOUT DAMAGING WALL
- 3. FURTHER STUDY POSSIBLE METHODS FOR STONE REPAIR

HOG HOUSE

- 1. DISMANTLE. SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP, TRASH REMOVAL, LANDSCAPE

HOME OWNER REPAIRS

CARRIAGE HOUSE

- 1. SIDING REPAIRS OR REPLACEMENT
- 2. WINDOW REPAIRS
- 3. SIDE DOORS REPAIRED OR REPLACED
- 4. MAIN DOORS HUNG FRONT AND BACK
- 5. PRIME PAINT

STONE WALL NEXT TO DRIVEWAY

COMPLETE UNFINISHED REPAIRS FROM DAMAGE THAT OCCURED IN MOTOR VEHICLE ACCIDENT LAST YEAR,

BLACK SMITH SHOP

- 1. DISMANTLE, SALVAGE ALL REUSABLE WOOD
- 2. CLEAN UP, LANDSCAPE

REPAIR SCHEDULE SECOND YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

CONTRACT, SUB CONTRACT WORK

MAIN BARN QUANSET HUT

- 11 RE POINT BARN FOUNDATION WHERE NEEDED
- 2. MASONARY REPAIRS TO BLOCK ON WEST WALL
- 3. REPAIR WINDOW LENTILS
- 4. REPLACE GLASS AND RE GLAZE SIX WINDOWS IN BLOCK
- 5. BUILD NEW GUTTER FOR WEST SIDE OF HUT
- 6. PAINT ENTIRE ROOF

CARRIAGE HOUSE

- 1. SPOT REPAIRS OF TIN
- 2. SCRAPE , PAINT ROOF

ICE HOUSE

- 1. REMOVAL OF EXISTING ROOF
- 2. INSTALL NEW METAL ROOF
- 3. INSTALL GUTTERS AND DOWN SPOUTS

HOME OWNER REPAIRS

ICE HOUSE

- 1. SIDING REPAIRED OR REPLACED AS REQUIRED
- 2. WINDOWS REPAIRED NORTH SIDE
- 3. REPAIRED SHUTTER TYPE LOFT DOORS INSTALLED
- 4. PRIME, PAINT STRUCTURE
- 5. GRADE , LANDSCAPE

REPAIR SCHEDULE THIRD YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

CONTRACT , SUB CONTRACT WORK

CEMETARY WALL

1. REBUILD CEMETARY WALL ON EXISTING FOUNDATION TO MATCH EXISTING

OXEN SHED WALL

- 1. MECESSARY ENGINEERING AND MASCHARY REQUIRED TO STABILIZE WALL.
- 2. LANDSCAPE, GRADE FOR BETTER DRAINAGE

BLACK SMITH SITE

1. SUBMIT PROPOSAL AT THIS TIME TO H P C FOR RELOCATING SLAVE CABIN/ (TOOL SHED)
TO SITE AT WHICH BLACK SMTTH SHOP STOOD, BEFORE NEXT YEARS WORK ON SLAVE CABIN
COMMENCES. TO RESTORE APPEARANCE FROM ROAD, BETTER FACILITATE THE USE OF BUILDING
AND TO EASE CROWDING ON OTHER BUILDINGS.

HOME OWNER REPAIRS

CARRIAGE HOUSE SIDE STRUCTURE (CAR PORT)

- 1. REMOVAL OF TAR SHINGLE ROOF
- 2. REMOVAL OF ALL DETERIORATED/WATER DAMAGED WOOD
- 3. REPLACE ALL DAMAGED WOOD
- 4. REPAIR OR REPLACE SIDING WHERE NEEDED
- 5. REPAIR OR REPLACE ROOF LATHINGWHERE NEEDED
- 6. INSTALL NEW TIN ROOF
- 7. PRIME, PAINT STUCTURE

REPAIR SCHEDULE FORTH YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

SUB CONTRACT OR HOMEOWNER REPAIRS

SLAVE CABIN (TOOL SHED)

- 1. WITH APPROVAL, PREPARE SITE OF BLACK SMITH SHOP TO ACCEPT FOUNDATION DIMENTIONS OF SLAVE CABIN. DISMANTLE, OR SECURE TO MOVE WHOLE, WHILE REPLACING NEEDED WOOD IN SILLS TO TRUE UP STRUCTURE.
- 2. REPLACE ALL OTHER WOOD AS REQUIRED
- 3. REPAIR OR REPLACE SIDING AS REQUIRED
- 4. PAINT ROOF
- 5. PRIME PAINT SIDING
- 6. REPLACE DOOR
- 7. WITHOUT APPROVAL, REPLACE STRUCTURAL WOOD WHERE NEEDED
- 8. REPAIR . REPLACE SIDING
- 9. REPLACE DOOR
- 10. PAINT ENTIRE STRUCTURE

REPAIR SCHEDULE FIETH YEAR GREENWOOD 21315 GEORGIA AVE BROOKEVILLE MD

SUB CONTRACT OR HOMEOWNER REPAIRS

GROUNDS KEEPERS SHED

- 1. RE NAIL ALL LOOSE SIDING
- 2. PAINT ROOF
- 3. PAINT SIDING ANDW WINDOW FRAMES

SMALL SHED

- 1. REPAIR SIDING AS REQUIRED
- 2. PAINT ENTIRE STRUCTURE

MISC.

- 1. ALL OTHER UNFINISHED REPAIRS AND PAINTING
- 2. ALL REQUIRED LANDSCAPE NEEDS
- 3. ALL OTHER CLEAN UP, TRASH REMOVAL

STEPHEN P. JOHNSON

ATTORNEY AT LAW
EIGHT BROOKES AVENUE
GAITHERSBURG, MARYLAND 20877

(301) 948-3460

July 26, 1989

Historic Preservation Commission 10th Floor 51 Monroe Street Rockville, Maryland 20850

Attention: Jeffrey Miskan, Chairman

Re: Master Plan Historic Site No. 23/46 "Greenwood"

Dear Mr. Chairman:

Please accept this letter as a part of my client's application for a Historic Area Work Permit to demolish all or part of four (4) outbuildings which are presently located on her property which, as you know, has already been designated as a historic site. The purpose of this letter is to outline for the Commission some of the events that have occurred, especially those after January 5, 1989.

As the record will indicate, a hearing was held on January 5, 1989, before the Commission regarding a similar request to demolish four outbuildings (the names for each of these buildings are of unknown origin). Mrs. Vrendenburgh was unable to attend that hearing because she had been notified of the hearing only the day of the hearing. This may have occurred because the notice was sent to the wrong address. In any event, the presentation made on her behalf, without the benefit of counsel, appears to have been accurate, but incomplete. Hank Handler of Oak Grove Designs, Inc. appeared and testified as to his cost estimates of rebuilding the four buildings in question. However, he did not have other important information at his disposal and was, therefore, unable to convey it to the Commission. Apparently because the presentation was incomplete, and because the Commission had apparently ordered Mrs. Vrendenburgh's predecessor in title, Hyman Frankel to do several things, which he did not do, it concluded the hearing and denied her the relief she was seeking, i.e., permission to demolish the four buildings.

Jeffrey Miskan, Chairman Historic Preservation Commission Re: Greenwood Page 2.

It should be noted that those buildings were in a state of almost total disrepair for many years prior to Mrs. Vrendenburgh's acquisition.

Subsequently, Mrs. Vrendenburgh sought legal advice and I immediately made contact with the staff at the Commission, namely Jared Cooper, to see what could be done to salvage the situation. Through these efforts and the cooperation of the County Attorney's Office, the Commission agreed to entertain a new application for a Historic Area Work Permit. (See attached letter from Edward B. Lattner, Esquire).

Since that time, Mrs. Vrendenburgh and several of her representatives have met with members of your staff to discuss her position with respect to the preservation of Greenwood as a whole. We have also involved members of the Code Enforcement Division of the County Department of Housing and Community Development who will be inspecting the property prior to your August 17, 1989, hearing.

Additionally, we have engaged the services of a qualified structural engineer, Thomas Carcaterra, P.E., to act as a consultant. He has inspected the property, especially the foundations of the four outbuildings in question, and photographed them. He has written an extensive report which will be presented to the Commission along with his testimony. His conclusion is that there are no adequate foundations upon which to attempt reconstruction and, therefore, he recommends demolition. His numerous photographs are especially revealing. We have also gotten another estimate besides Mr. Handler's mentioned above with respect to the cost of restoration of the outbuildings.

While this work preparatory to your August hearing has been going on, Mrs. Vrendenburgh has also engaged several contractors and spent large sums of money doing restoration work on the roof and windows of the main house and other parts of the property.

We trust this explanation will show that we have not been "foot dragging" since the last hearing and we look forward to discussing all of these issues with you and the entire Commission at length at the August hearing.

Jeffrey Miskan, Chairman Historic Preservation Commission Re: Greenwood Page 3.

If you or the staff have any questions or concerns, please do not hesitate to call me, and if there is a problem with the agenda for the August hearing, please let me know because I will need to coordinate with our various expert witnesses.


Thank you for your cooperation.

Very truly yours,

Stephen P. Johnson

SPJ:pc

copies to Faith Vrendenburgh
Farley Warner, Esquire
Code Enforcement Division, County Department
of Housing and Community Development
Thomas A. Caracterra, P.E.





May 18, 1989
MHIC#22543
RE: Scope of Work for the
Blacksmith Shop, Oxenshed,
Hog House, Corn Crib, and
Main Barn

Mr. John Abernethy Greenwood Farm Georgia Avenue Brookeville, MD 20833

THE FOLLOWING IS A COST PROPOSAL BASED ON SITE INSPECTIONS AND SPECIFICS DESIGNATED BY OWNER DURING INSPECTION.

SCOPE OF WORK:

Blacksmith Shop;

- Repair framing were necessary, straighten corner beam, and tighten collar ties in order to shore up building.
- Install new siding where needed.
- Install new roof to include rafters, lath and metal roofing.
- Install new doors to include hardware.

Price

\$19,480.00

Oxenshed;

- Demo existing roof leaving stone wall intact.
- Repair/Reshore stonewall(warrants further study for exact method).
- Install all new 6X12 inch beams around perimeter and on 12' centers.
- Install new rafters, lath, and metal roofing, to include collar ties.

Price

\$31,900.00

Hog House;

- Replace foundation and straighten building.
- Install new floor joists and adjacent supports.
- Install new flooring.
- Replace siding as needed.

Price

\$28,807.50

Page Two Greenwood Farm Scope of Work May 18, 1989

Corn Crib;

 The Corn Crib is beyond repair and would require all new material for its duplication, including stone footings.

Price

\$64,000.00

Main Barn;

- Install new metal roof and wood lath.
- Install new third floor beam at west wall.
- Re-nail and install new siding where necessary on all exterior, using new boards, supplied by owner.
- Repair six windows on block wall.
- Install new Lintels where necessary \$175.00 each.
- Other items to be studied further are beams in North roof and the repair of upper entrance way.

Price

\$27,269.80

Prices do not include painting, back filling, grading or guttering. Prices do include the removal of all debris.

Should there be any questions in concern to the above information, please contact Jon D. Orenstein at (301)774-9478.

Sincerely,

on D. Orenstein

Owner'

cc: file

MEMORANDUM

February 22, 1989

TO:

Steven Karr, Chairperson

Historic Preservation Commission

FROM:

Melvin E. Tull, Chief

Division of Code Enforcement

Department of Housing and Community Development

SUBJECT:

Greenwood, Master Plan Site No. 23/46

You have inquired about efforts to prevent demolition by neglect of the outbuildings at Greenwood. In addition, you requested a chronology of actions taken in that effort. You are aware that ownership changed last year. I hope you are also aware that the previous owner had made modest repairs and that the new owner has also been repairing some outbuildings. The new owner, Faith Vredenburgh, is now under notice, deadlines are scheduled, and she has applied for a work permit to demolish certain outbuildings.

The most notable progress to date is the change of ownership. I believe that change was prompted by the inspector when he established that Dr. Frankel was unable or unwilling to act to prevent demolition by neglect. Dr. Frankel apparently choose to sell the farm rather than face enforcement action. Because Greenwood was being sold to someone who would invest in stabilization, it did not appear necessary or appropriate for the county to contract for repairs. The new owner, Mrs. Vredenburgh, committed to a schedule of investment and rehabilitation, has been making repairs, and has applied for a work permit to demolish certain buildings. Stabilization of the weakest structures is required by early spring.

The following chronology of historic preservation actions affecting Greenwood begins 13 years ago with several significant steps during the late 1970s that provided the foundation for all later actions:

October 1976

Publication of the Locational Atlas & Index of

Historic Sites. Greenwood identified as site

23-46.

May 1979

Planning Board recommendation of Greenwood as a

historic site along with 60 others in the original Preliminary Draft Master Plan.

July 24, 1979

Adoption of Chapter 24A, Historic Resources

Preservation Code.

Steven Karr February 22, 1989 Page 2 of 4

September 12, 1979 District Council adoption of the master plan for historic preservation, including Greenwood.

May 22 & July 22 1986 HPC requests investigation of possible demolition by neglect and provided copies of 1974 photographs showing leaning buildings, missing sections of roof and siding, and other

severe deterioration.

November 10, 1986 After many attempts to inspect, our inspector met James Panek, the owner's son-in-law, at the property. After a brief discussion the

inspector was told to leave.

November 17, 1986 Inspector met with Dr. Frankel, the property owner and inspected the buildings with him.

November 24, 1986 A notice and order to stabilize the outbuildings was sent to Dr. Frankel.

December 15, 1986 Dr. Frankel wrote to express willingness to stabilize the buildings and to propose a plan of action that included demolition of several outbuildings.

The inspector wrote to Dr. Frankel extending the deadline to June 15, 1987 and notifying him that he must apply for a Historic Area Work Permit for buildings he hoped to demolish rather than repair.

HPC was given Dr. Frankels letter about the plan to demolish certain buildings and the inspectors response referring the matter to the HPC.

The inspector learned that Greenwood was for sale and notified the real estate agent of the demolition by neglect order.

Dr. Frankels attorney, Robert A. Gingell, wrote to inquire about the process that designated Greenwood as a historic site and whether Dr. Frankel had received notice and opportunity to comment.

Mr. Gingell was advised by letter to contact the HPC.

February 2, 1987

May 6, 1987

May 14, 1987

June 5, 1987

Steven Karr February 22, 1989 Page 3 of 4

June 12, 1987	John E. Beckman, Jr., attorney for Dr. Frankel negotiated directly with the HPC regarding demolition of certain buildings and delay of repairs until the summer of 1988.
June 16, 1987	The inspector sent a Final Notice to Dr. Frankel stating that the County would make repairs and charge the cost to him if he delayed beyond July 17, 1987.
June 23, 1987	Dr. Frankel called the inspector to report that he planned to begin on repairs by August 7, 1987.
July 21, 1987	The HPC representative advised the inspector that Greenwood had been sold.
August 3, 1987	Dr. Frankel advised the inspector that Greenwood had been sold and settlement was scheduled for September 17, 1987.
September 22, 1987	Settlement rescheduled for October 1, 1987.
December 14, 1987	The inspector notified the new owner, Mrs. Vredenburgh, even though the deed still was not recorded.
January 7, 1988	The inspector reported that repairs had begun on the ice house and the coach house.
February 9, 1988	The inspector reported work continuing on the barn and ice house.
April 21 & 28, 1988	The inspector reported rehabilitation is underway and progressing.
July 15, 1988	The inspector and an HPC representative met owners on site and reviewed conditions.
July 28, 1988	The owner's representative (John Abernathy, a son-in-law) proposed a workable schedule for renovations.
August 19, 1988	A notice and order was sent to Mrs. Vredenburgh establishing deadlines.
November 22, 1988	The inspector found ice house repairs were not complete but were underway, and extended the deadline to January 1, 1989.

Steven Karr February 22, 1989 Page 4 of 4

November 30, 1988

Mrs. Vredenburgh applied for a Historic Area Work Permit to "wreck or raize" (sp) the cornshed, hog house, blacksmith house and oxen shed.

January 5, 1989

HPC denied the application.

February 3, 1989

Assistant County Ed Lattner notified Mrs. Vredenburgh's attorney that the HPC will reconsider and entertain a new application: noting that the HPC has a long history of working with the owners of historic resources he recommended that she meet with the HPC.

At various times, both Dr. Frankel and Mrs. Vredenburgh expressed a desire to clarify the extent of their responsibilities for maintaining and restoring various outbuildings. We have no record of a response from the HPC to Dr. Frankel's request of December 15, 1986, forwarded on February 2, 1987, or to his attorney's proposal of June 12, 1987. With these requests pending and unresolved throughout the remainder of 1987 it appeared that the HPC was reconsidering whether those structures should be stabilized and restored.

There are 5 distinct phases in the events listed above:

- 1. Initial delays while the inspector was unable to arrange an inspection because Dr. Frankel was living in California and the occupants were uncooperative. This lasted 4 months.
- 2. Dr. Frankel was in the process of planning to make necessary repairs and determining, with the HPC, whether certain outbuildings could be demolished. His proposal to the HPC for demolition of certain buildings was not rejected and it was never certain that he would have to repair those outbuildings. This consumed 7 months.
- 3. The property was in a state of imminent transfer of ownership, during which it was not prudent to issue tickets or initiate repairs. That state lasted 5 months.
- 4. The new owner, Mrs. Vredenburgh, was making repairs and establishing plans for 11 months.
- 5. Mrs. Vredenburgh's application to clarify whether she must repair certain buildings or whether they can be demolished has taken more than 2 months and remains an open question.

MET:mmr:06601 cc: Jared Cooper

Historic Preservation Specialist



Mentgomery County Covernment

OFFICE OF THE COUNTY ATTORNEY

Executive Office Building 101 Monroe Street, 3rd Floor Rockville, Maryland 20850-2589 TELEPHONE Area Code 301 217-2600

February 3, 1988ice of Community Development

Stephen Johnson, Esquire 8 Brookes Avenue Gaithersburg, MD 20877

Re: Greenwood

Dear Mr. Johnson:

This letter will serve to confirm our conversation this morning that the Montgomery County Historic Preservation Commission will entertain a new application from your client, Faith Vrendenburgh, for the issuance of an historic area work. permit regarding the above-referenced master plan site. 24A-7(a) of the Montgomery County Code (1984), as amended, provides that applications for the issuance of an historic area work permit shall be filed with the director of the Department of Environmental Protection. However, as we discussed this morning, it would be to everyone's benefit if Ms. Vrendenburgh met with the Commission and sought their advice before filing an application, especially in view of the Commission's past dealings with this §24A-6(d). The Commission has a long history of working with the owners of historic resources and can provide helpful information on the appurtenances and environmental setting appropriate to an historic resource, construction methods and materials, financial information concerning historic preservation, and other relevant matters affecting the issuance of a permit.

If you have any questions or wish to schedule a preliminary meeting with the Commission, please contact Jared Cooper, Historic Preservation Specialist, at 217-3625.

Very truly yours,

CLYDE H. SORRELL COUNTY ATTORNEY

Edward B. Lattner

Assistant County Attorney

EBL:tjs

151L:89.00000

CC: Jared Cooper, Historic Preservation Specialist
Steven Karr, Chairman, Historic Preservation Commission
Melvin E. Tull, Chief, Code Enforcement Division,
Dept. of Housing and Community Development
Sharron Brown, Investigator, Code Enforcement Division,
Dept. of Housing and Community Development

Mr. Beautoft. 301 774-3616

The death of my beloved wife, to whom I had bequeathed the most of my estate, creater the necessity for revision and reconstruction of Therefore, allew Bowie Dairs, of Montgome. County, State of Maryland, being of sound mind, memory and understanding, do make, Will and Vestament. 1th & Principally, I commit ony soul into the hands of Almighty God, and to my most merciful favious The Lord Jesies Christ, and my body to the latth, to be build in the old family Cometery, Greenwood, my firesent residence, and after my just debts and funeral charges are paid, I give devise & bequette as follows; To my beloved daughter, Rebecca Horsey Davis, I ge devise and bequeath my Stofbury form in Howard County, containing about one hundred an sifty acres of land, also my wood lot near Cooksville in said county, containing about one hundred acres of land in fle simple, and Sum of light thousand dollars, also all the article of furniture and books and household goods, which was the property of my fish wife, Rebecca Comfort horsey Wariv.

2% Vo any beloved daughter, Mary Horsey Davin, I give, devine and bequeath that portion The Home farm lying north and last of division line as laid down by Charles of, Townsend, County Surveyor, in the division of my home farm in knowlgomery County, together with about forty acres of the northern and western part of the fifty acre Gartrell lot, to her, her heis forever, Also my home and lot 1403 Madriow arenne in the city of Baltimore, and The sum of six thousand dollars. 39. To my belond daughter, Esther Wilkins Dairs, I give, devise and bequeath in fee simple, my Keome plantation tenown as Gelenwood, togeth with the Mill, Mill dam and lot laid off thereto containing in the aggregate 400 acres onbe or less and the sum of Six thousand dollars, with the expression of my larnest hope that her disters, Mary and Rebecca, may always find a welcome home at the old family enansion, by haying a reasonable compensation therefore, and also to keep in order the old family Cornetery, as more laid off and infrared, which lot of ground with fifty feet outside of the held and enclosure, Parelat to be held laced and fall from sale or alienation 4th and Valer give unto any three daughters my Noch Creek farm, containing about 160 acres

I, MARY DOPSEY DAVIS, unmarried, of the City of Baltimore, State of Maryland, being of sound and disposing mind, memory and understanding, do hereby make, publish and declare this to be my Last Will and Testament, hereby revoking all other wills or codicils by me heretofore made.

In the name of God of whom I have asked direction.

Principally I commit my soul into the hands of Almighty God, and to my most merciful Saviour, the Lord Jesus Christ, and my body to the earth, to be buried in Greenmount Cemetery, Area P, Lot 62, adjoining the Wilkins vault, and I direct that a granite marker be placed at the head of my grave with my name and the dates of my birth and death, such marker to be similar to those placed at the graves of my brother and sisters, and I further direct that ivy be placed on my grave.

After the payment of all of my just debts and funeral expenses, I give, devise and bequeath as follows:

Item 1. At the time when "Greenwood", my old family homestead in Montgomery County, Maryland, was sold, the family cemetery included therein, in accordance with the Last Will and Testament of my father, was not sold, and the deed to said property reserved therefrom the said family cemetery, together with a space of four (4) feet outside the walls thereof, and also reserved an easement of ingress to and egress from the said cemetery through said land so sold.

County, together with all easements and other rights and privileges appurtenant thereto, unto the Rector and Vestry of St. Johns Protestant Episcopal Church, Olney, Montgomery County, State of Maryland, in trust upon the following terms and conditions; to be held by them so long as they shall keep the same in good order and repair and maintain the same as a cemetery. Should said Rector and Vestry of St. Johns Protestant Episcopal Church fail to keep and maintain said cemetery in good order and repair, or at any time attempt to dispose of the same, or use it for any purpose other than that of a cemetery, then I direct that the said cemetery and all easements and other rights and privileges appurtenant thereto shall revert to and become the property absolutely of my heirs



I further give and because the the sum of Two thousand delians (15,000.) to the said Rector and Vestry of St. Johns Protestant Episcopal Church in trust for the following purpose, to wit: such sum to be invested and the income therefrom to be used to care for said cemetery in keeping the grounds, shrubbery and walls in good order and repair. In the event that said cemetery should revert to and become the property of my heirs at law under the terms hereinabove set forth, then I direct that this said sum of Two thousand dellars (\$2,000.) shall likewise revert to and become the property absolutely of my heirs at law.

I further give and bequeath the sum of Five hundred dollars (\$500) to the said Rector and Vestry of St. Johns Protestant Episcopal Church to be held in trust by them, and the income therefrom to be expended in any way that said Rector and Vestry shall deem best.

Should my estate at the time of my death be insufficient to pay all legacies in full, I direct that these legacies to the Rector and Vestry of St. Johns Protestant Episcopal Church be paid in full before the payment of any other legacies.

I direct my Executor hereinafter named to cause the date of my birth and the date of my death to be placed beneath my name which appears on the monument in said cemetery.

Item 2. I give and bequeath to the Convention of the Protestant Episcopal Church of the Diocese of Maryland the sum of Nine hundred dollars (\$900) absolutely, the said sum to be used for Diocesan Missions.

Item 3. I give and bequeath to my cousin, Lucy Leigh Bowie, of Washington, District of Columbia, provided she survive me, the sum of Three thousand six hundred dollars (\$3,600).

Item 4. I give and bequeath to my cousin, Catharine Davis Trundle, of Gaithersburg, Maryland, the sum of One thousand eight hundred dollars (£1,800). In the event my said Cousin, Catharine Davis Trundle, predeceases me, then I give and bequeath the said sum of One thousand eight hundred dollars (£1,800) to her sister, my cousin Maria W. Bowie, of Laltimore, Maryland.

I, MARY DORSEY DAVIS, of the City of Baltimore, State of Maryland, declare this to be a first codicil to my last will and testament bearing date the nineteenth day of March, 1935.

CHEREAS, by my said will, I bequeathed the sum of Two Thousand Dollars (\$2,000.00) to the rector and vestry of St. John's Protestant Episcopal Church, Olney, Maryland, to be held in trust for the perpetual upkeep of my family cemetery, devised in trust to the said rector and Vestry of St. John's Protestant Episcopal Church; and

WHEREAS, it is now my intention to reduce by one-half the amount so bequeathed for the upkeep of said cemetery.

NOW, THEREFORE, I hereby revoke my former bequest of Two Thousand Dollars (\$2,000.00) to the rector and vestry of St. John's Protestant Episcopal Church and in the place and stead thereof, I hereby give and bequeath the sum of One Thousand Dollars (\$1,000.00) to the said rector and vestry of St. John's Protestant Episcopal Church, in trust, for the following purpose - to wit: such sum to be invested and the income there from to be used to care for said cemetery in keeping the grounds, shrubbery, and walls in good order and repair. In the event that said cemetery, under the terms of my will, should revert to and become the property of my heirs at law, then I direct that this said sum of One Thousand Dollars (\$1,000.00) shall likewise revert to and become the property absolutely of my heirs at law. Should my estate, at the time of my death, be insufficient to pay all legacies in full, I direct that this legacy to the rector and vestry of St. John's Protestant Episcopal Church be paid in full before the payment of any other legacies.

In all other respects, I hereby confirm my said last will and testament.

IN TESTIMONY WHEREOF, I have hereunto subscribed my name and affixed my seal this 16th day of December, in the year 1935.

	SZAL)
--	-------

Signed, scaled, published and declared by MARY DORSEY DAVIS, the above-named testatrix, as and for a first codicil to her last will and

testament, bearing date of the 19th day of March, 1935, in the presence of us, who, at her request and in her presence, and in the presence of each other, have hereunto subscribed our names as attesting witnesses.

U. S. F. & G. Co.	W. Page Dane, Jr.
13 South St.	Chas. C. Feinhardt.

ter eligibility of plant and make the size of the property of the contract of

to the treatment of the color o

The most continue to the second property property and the second second and the second second second and the second secon

and the state of t

้างของผู้ จองว่า ที่เดิดขึ้นเห้า จิสุด เอว์ซ์ ซอซ จายว่าวิทยาเลของของ เปอตตรรับการ ซอด เหมือ

THE REPORT THE RESERVE TO BE TO THE REPORT OF THE PROPERTY OF

, "我们就是这个人,我们就是一个人,我们要这个人,我们就是一个人的,我们就是这个人,我们就会会会现在的,这个人<mark>就</mark>

THE RESERVE OF A SECTION ASSESSMENT OF THE SECTION OF THE SECTION

er til i 🗴 gjern i led skriger (b. 1951 fredlig søret 🔾

I I The to to the the to the second of the second of the second

Being the same land which was conveyed to the said John P.Ray, Junior, by Charles

W.Barnsley and wife by deed dated the 27th day of March in the year nineteen hundred
and two and recorded among the Land Records of said County in Liber T.D. No.19 folio

457.

Together with all and singular the buildings and improvements thereon and all the
rights, ways, privileges and appurtenances thereto belonging or in anywise thereto
appertaining.

And the said John P.Ray, Junior and Annie I.Ray, his wife, covenant to warrant
specially the lands and premises hereby conveyed and to execute any and all such further or other assurances as may be requisite or necessary the better to convey the same as aforesaid.

Witness our hands and seals.

Test.

37/
J.P.Ray, Jr. (seal)

State of Maryland, Montgomery County, to wit -:

I hereby certify that on this 2nd day of January in the year nineteen hundred and seven before the subscriber, a Justice of the Peace of the State of Maryland in and for Montgomery County, personally appeared John P.Ray, Junior, and Annie I.Ray, his wife, and did each acknowledge the foregoing and annexed deed to be their respective act.

Clifford H.Robertson, J.P.

At the request of David S.Craver the following Deed was recorded January 2nd A.D.

1907 at 12.55 o'clock P.M., to wit.

WITNESSETH, that for and in consideration of the sum of eleven thousand dollars, we the said Rebecca D.Davis and Mary D.Davis do hereby grant unto David S.Craver of Montgomery County, in the State of Maryland, all those tracts, parts of tracts, pieces or parcels of land situate lying and being in Montgomery County, in the State of Maryland, and described as follows, to wit: and being part of a tract of land called "Hygham" and part of a tract of land called "Golds Branch" and part of a tract of land called "Golds Branch" and part of a tract of land called "The Addition to Brooke Grove", or by whatsoever name or names the same may be known or called,

BEGINNING for the same at a stake at the end of seventeen and one fourth perches of the firstlline of said tract called Hygham said stake being also at the end of the first line of a conveyance from Allen Bowie Davis and wife and Estha W.Davis to Lafayette M.Dwyer for seventeen acres of land by deed bearing date the sixth day of June, 1885, and recorded in Liber J.A. No.1, folios 105 &c. one of the Land Records of Montegomery County and running thence with the first line of said tract called "Hygham", North seventy degrees West, eighty twosand three fourth perches to a stone at the end thereof; still with said tract North twenty degrees East, one hundred and sixty perches

Parkete to harrile and some son harrile

West, mineteen perches to the place of beginning, containing one hundred and ninety three acres, three roods and twenty seven perches (193 acres, 3 roods and 27 perches) pf land, all the bearings by magnetic meridian February 12th, 1859.

Together with a right of way reserved in a deed from the grantors to a certain John W. Whiteside bearing date the 21st day of October, 1905 and duly recorded among the Land Records of said County in Liber 184, folio 333.

Excepting however the graveyardcand a strip of land fourfeet wide on all thessides of said graveyard, it being the intention of the parties to except the graveyard enclosed by a stone wall and a strip of land adjacent to the wall of the width of four feet measuring from the wall on all sides this distance, and reserving to the grantors their and each of their heirs and assigns the right of ingress, egress and regress to and from the same, also excepting a parcel of land from the land above described, being part of the "Home Farm" of the late Allen B.Davis as conveyed by said Allen B.Davis to Hester W.Davis by deed dated the 9th day of February in the year 1862 and recorded among said Land Records in Liber E.B.P. No. 25, folio 408 and bounded as follows,

_____BEGINNING at the beginning of a conveyance from Mary D.Davis and Rebecca D.Davis to Reuben Lynn, it being a large bounded poplar tree near Goulds Branch, and at or near the end of twenty perches on the South fifty nine degrees West, one hundred and sixty three perch line of the whole tract; thence with said conveyance to Reuben Lynn (lines magnetic) North thirteen degrees East, six perches across "Goulds Branch" to a stone; then North seventy eight and one half' degrees West, forty three perches to a stone; then leaving said conveyance and running across hill North seventy three degrees East, ninety one perches to a stone about four feet from the bounding hickory tree with six chops; then South seventy eight and three fourth degrees East, twenty eight and one fourth perches across "Goulds Branch" to the end of thirty one perches on the South fifty nine degrees West, ninety three perch line of the whole tract; then with said outline (four degrees allowance for variation) South fifty nine degrees West sixty two perches to the end of said line; then still with said outline and said four degrees allowance for variation, North twenty two and one half degrees East, one perch to "Goulds Branch"; then South fifty nine degrees West, nineteen perches to the place of beginning, containing twelve and one eighth (12 1/8) acres of land, more or less, being a part of "Goulds Branch" or by whatev r name or names the same may be known, it being the same land which was conveyed by Mary D. Davis and Rebecca D. Davis to John W. Whiteside by deed dated the 21st day of October, in the year 1905 and which is duly recorded among said Land Records in Liber 184, folio 333, and reserving to the said John W.Whiteside, his heirs and assigns, the right of way mentioned in said deed.

And the parcels of land hereby granted are conveyed together with the buildings and improvements thereon and the rights and appurterances thereunto belonging or in anywise appertaining, and the said Rebecca D.Davis and Mary D.Davis hereby covenant that they will warrant specially the land hereby conveyed, except the land conveyed to said John W.Whiteai and the right of way mentioned in the deed for said land.

Witness our hends and seals.

(seal)

Wary D.DEVIS

Geo.B.Gammie

State of Maryland, Montgomery County, to witi

I hereby certify that on this 27th day of December, in the year of our Lord mineteen hundred and six, before me the subscriber a Notary Public of the State of Maryland in and for Baltimore City, personally appeared Rebecca D. Davis and Mary D. Davis and did each acknowledge the aforegoing deed to be their respective act.

	In testimony whereof, I hereunto subscribe my name and affix
George B.Gammie	my Notarial seal.
Notary Public	Geo.B.Gammie
Baltimore	Notary Public.
Md.	· · · · · · · · · · · · · · · · · · ·

At the request of John P.Ray, Jr. and Annie I.Ray, his wife, the following Deed__ was recorded January 2nd A.D.1907 at 2.46 o'clock P.M., to wit.____


THIS DEED, made this 2nd day of January, in the year nineteen hundred end seven, W. md. by Nicholas M. Howes and Bettie M. Howes, his wife, of Montgomery County, in the State 14-1907 of Maryland,

WITNESSETH, that for and in consideration of the sum of (\$1500) fifteen hundred dollars to us in hand paid, we, the said Nicholas M.Howes and Bettie M.Howes, his wife do grant, in fee simple, unto John P.Ray, Junior, and Annie I.Ray, his wife, of said Montgomery County, all that percel of land situate, lying and being in said County, near Norbeck, and containing between two and three acres of land, and which is particularly described in a deed from James Rennie and wife to Frederick L. Bowman, James H.M. Bowman and Margaret Bowman, dated the fifteenth day of November, in the year nineteen ... hundred and one; and recorded among the Land Records of said Montgomery County in Liber T.D. No.19 folio 223, to which deed reference is hereby made for a more full and partic ular description of the landseand premises hereby conveyed.

Also all that other lot, piece, or parcel of ground, also situate, lying and being in said County, contiguous to the parcel of land above described and being part of a tract of land called "Bradford's Rest", or by Whatever name or names the same may be . known or called, and described as follows:-

BEGINNING at a stone planted at the end of the third line of a conveyance from George M. Nicholls, Trustee, to Luther E. Burriss, Trustee, for part of "Bradford's Rest". and running thence, with said line, reversed, North eighty one degrees West, twenty five and three tenths perches to the beginning and to intersect the third line of the conveyance from Mary H. Dorsey to George M. Nicholls at the end of three perches and four links and at the end of the second line of the conveyance from the said George M. Nicholls to the said Luther E. Burriss, thence South nine degrees West, three perches and four links; thence South eighty one degrees East, twenty five and three tenths perches to intersect the first line of the conveyance from said Mary H.Dorsey to said George M. Nicholls at the end of thirty four and nine tenths perches; then North nine degrees East, three perches and four links to the beginning. Containing one half of one acre of land, more or less.

3/6	
EXAMINE	At the request of Wilbur F. Nash, Jr. and Alice Smith Nash, the following
W.	thu Frask Deed was recorded May 20th, A. D. 1938, at 10:21 o'clock, A. M. to w
	37 Buyant St. h.E This Deed made this 19th day of May in the year Nineteen hundred and
. ω	thirty-eight, by and between Wilbur F. Nash, Sr., widower, surviving tenant by the entire
7	-/3-38. of Wilbur F. Nash and Hattle E. Nash, party of the first part; and Wilbur E. Nash, Jr., an
	Alice Smith Nash, his wife, as tenants by the entirety, parties of the second part.
7.6	Witnesseth, that for and in consideration of the sum of Ten (\$10.90)
. •	Dollars, the said party of the first part does grant and convey unto the said parties of +
	aecond part, in fee simple, as tenants by the entirety, the following described land and
	mises, with the improvements, easements and appurtenances thereunto belonging, situate, ly
	and being in Montgomery County, State of Maryland, namely:
` 	All of those trects of land contained in and conveyed by a certain
	from David S. Craver and Joanna M. Craver, his wife to the said Wilbur F. Nash and Hattie
	Nesh, his wife, dated March 1st, 1926 and recorded April 1st, 1926 in Liber 398, Folio 1,
	of the Land Records of said County, reference to which deed is hereby made for a more full
	complete description of the property hereby conveyed.
•	To Have and To Hold the same unto and to the use of the said partie:
	hereto of the second part, in fee simple, as tenants by the entirety,
	And the said party of the first part hereby covenants to warrant spe
	'ly the property hereby conveyed, and to execute such further assurances of said land as me
	requisite.
	Witness his hand and seal on the day and year first hereinbefore wri
•	Signed, sealed and delivered Wilbur F. Nash single (Seal)
	in the presence of -
	Robert S. Beins
•	(Internal Revenue \$21.00)
	(State Tax \$20.90)
	District of Columbia, to wit:
	I hereby certify that on this 19th day of May, 1938, before the sub-
	scriber, a Notary Public in and for the District of Columbia, personally appeared Wilbur F
	Nash, Sr., and acknowledged the aforegoing Deed to be his act.
	In Testimony Whereof, I have affixed my official seal this 19th day
	Mey, 1935.
	Robert S. Bains
	Robert S. Bains Notary Public, D. C.
	Notary Public
	District of
	Columbia
• F/B	
2/6	
mai	Lest to At the request of M. Roger Edwards and Ruth Edwards, the following L
	Roge Edwards was recorded May 20th. A. D. 1938, at 10:24 o'clock, A. M. to witi
	36 Farurence 1t. h. E. This Deed, made this 20th day of May, in the year 1938, by William F
<u> </u>	Brisgs, of the County of Montgomery, State of Maryland, widower.
	Witnesseth that for and in consideration of the sum of ten dollars,
	the covenants hereinafter set forth to run with the land, the said William F. Briggs, does
	grant, bargain and sell unto M. Roger Edwards and Ruth Edwards, his wife, in fee simple, as
	as tenante by the entireties, all of lot eight (8) in a subdivision made by William F. Bri
	called "Fairland Farms", according to a plat thereof duly recorded among the Land Records
	said County in Plat Book 12, plat 840.



DATE:	8/21/89
ТО:	Robert Seely, Chief Department of Environmental Protection Division of Construction Codes Enforcement
FROM:	Jared B. Cooper, Historic Preservation Specialist Department of Housing and Community Development Division of Community Planning and Development
SUBJECT:	Historic Area Work Permit Application
meeting of for an His	The Montgomery County Historic Preservation Commission at their 8/17/89 reviewed the attached application by
	Approved
	Denied
	✓ With Conditions:
CORI	V SHED ONLY TO BE DEMOLISHE
	♦
Attachment	
1. HAu	
2. MO	tograph or Corn Shed
3. <u>Ma</u> f	of Site
4	
5	
JBC:av	
1199E	Historic Preservation Commission
	51 Monroe Street, Rockville, Maryland 20850-2419, 301/217-3625

HISTORIC PRESERVATION COMMISSION STAFF REPORT

PREPARED BY: Jared B. Cooper DATE: August 7, 1989

CASE NUMBER: 23/46-89A TYPE OF REVIEW: HAWP

SITE/DISTRICT NAME: "Greenwood" PROPERTY ADDRESS: 21315 Georgia Avenue Brookeville, MD 20833

DISCUSSION: As you will recall, a representative of the owners of Greenwood Farm came before the Commission on January 5, 1989, in order to request the demolition of four outbuildings (see "chronology of events" memo, Attachment #3). At that time, the Commission denied the request (see Stephen Johnson letter, Attachment #2).

Since that time, staff has visited the site, conducted a thorough inspection of the buildings in question, and met with the applicant and her representatives.

STAFF RECOMMENDATION: Staff recommends the following:

- 1. "Corn Shed": Of the four buildings in question, this appears to be the earliest (late 19th century) and best constructed, although parts of the "oxen shed" are probably earlier. Unfortunately, the corn shed is in an advanced state of deterioration, and has all but fallen down. Staff recommends approval of the request for demolition for the following reasons:
 - A. by most standards, it is well past the point of restorability, and;
 - B. even though it "was" a well-constructed and designed structure, it does not exhibit any unusual architectural features or construction techniques which would render it worthy of a monumental restoration project.
- 2. "Hog House": This structure appears to have been constructed during the early 20th century. It was never very outstanding in terms of design or construction techniques, although it certainly contributes to the "farmscape." It is in relatively good condition, with a fairly good roof. Its worst problem is that the foundation, along two sides, has settled into the ground. However, the building is, by no means, falling down and the foundation problems could be halted by use of a combination of shoring, minor grading, and installation of a guttering system.

Staff recommends that the applicant be denied permission to raze the "hog house." There don't seem to be any sound reasons to demolish this structure, and it would be fairly easy and inexpensive to maintain it. Staff also recommends that the applicant be asked to take measures to protect the building from further deterioration. Such measures would include installation of gutters; minor grading, to pull away some of the buildup caused by excessive runoff, and to deter continued runoff damage; shoring up the settled portions of the foundation, utilizing the pier and beam system (as original); and roof maintenance. There is no danger of rapid deterioration, and the applicant could be given as much as a year or two to complete the work, as long as progress was being made on other more significant outbuildings during that time.

3. "Oxen Shed": This building, dubbed "Oxen Shed" by a former owner, appears to have been designed as what would commonly be known as a machinery/implement shed. Apparently, it was constructed during the 20th century. For the most part, it is constructed of tongue-and-groove rail car siding. One side of the roof rests on a pre-existing stone wall (approx. 7' high), which appears to have been constructed during the mid-nineteenth century, (possibly earlier) although it would be difficult to document. It is joined at both ends by a continuous stone fence which traverses the farmstead, separating the barnyard, residential yard, and cemetery.

The stone wall was probably part of the foundation of an earlier, perhaps larger, agricultural building. It has a doorway in the center, flanked by a series of small vent openings in the wall. The weight of the building, along with poor construction technique and footing problems, is causing the wall to bow outward. This movement has been temporarily halted by a previous owner through the installation of wooden buttresses. The building itself, while it has a good roof, is in poor structural condition. Some of the problems could probably be corrected, but the building (with the exception of the stone wall) hardly warrants salvation.

Staff recommends approval of the request for demolition of the wooden portion of the structure, for the following reasons: a) It is not architecturally significant; b) it is in poor structural condition; and c) it appears to be causing stress to the stone wall on which it rests.

However, staff recommends that approval be granted with the condition that measures (approved by the Commission) be taken to protect and preserve the stone wall. Such measures might include a thin troweled "soft mortar" cap, or even construction of an appropriate building, replacing the existing. Also staff recommends that the applicant be encouraged to "right" the leaning section of the wall if the building is removed.

4. "Blacksmith shop": This structure appears to have been constructed during the early 20th century, at or about the time of construction of the "hog house." It may have served as a blacksmith shop at one time, although, if that was the case, it has long since lost all fixtures and appurtenances which would have been associated with that use. Most recently, it appears to have served as a tool shed or workshop. It is in poor condition, as a result of poor original design and a bad roof. It is situated in a row of three buildings which includes the ice house and a carriage house. Both of these other buildings date from an earlier period and are in better condition. The applicant has been slowly restoring them.

Staff recommends that the applicant be permitted to raze the "blacksmith shop." In staff's opinion, it is not significant in terms of age, design, or construction technique. While it would be possible to restore the structure, staff recommends that, instead, the applicant be enouraged to complete the restoration and repair of the flanking structures.

In summary, staff recommends that the applicant be permitted to raze the following three structures:

- 1) "Corn Shed" (based on criterion 24A-8(b)(4))
- 2) "Oxen Shed" (based on criteria 24A-8(b)(1) and (4)
- 3) "Blacksmith Shop" (based on criteria 24A-8(b)(1) and (4)

Staff recommends that the applicant be denied permission to raze the "hog house." Although its foundation is in poor condition it could be repaired and stabilized relatively easily. However, like the "blacksmith shop," staff feels that it is not a particularly early or outstanding structure.

ATTACHMENTS:

1. HAWP Application

- Letter from Applicant's Attorney (and attachments)
- 3. Memorandum from Mel Tull
- 4. Photographs (slides will be shown at the meeting)

JBC:bdm 1284E



Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Maryland 20850

17-3625 B. B. B. I. V. E. D. L. 2 7 1989

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	1006 (37 to 17 to 17 to 17 to 18 to 19 to 18 to
NAME OF PROPERTY OWNER Faith S. Vrendenburgh	924-3614 TELEPHONE NO
(Contract/Purchaser)	(Include Area Code)
ADDRESS 21315 Georgia Avenue, Brookeville,	Maryland 20033
CONTRACTOR Oak Grove Designs, Inc.	TELEPHONE NO. 921-0254
CONTRACTOR REGIST	RATION NUMBER
PLANS PREPARED BY	TELEPHONE NO.
REGISTRATION NUMB	(Include Area Code) ER <u>11860</u>
LOCATION OF BUILDING/PREMISE	
	a Avenue
	a Avenue
	Election District
Nearest Cross Street Route 650	
Lot Plack Control Subdivision	[132] A. M. C. (1937), a 3000 (2), \$100 (2), \$200 (3), \$100 (4), \$
LOT BIOCK *	the company of the case of the materials and the state of
Liber Folio Parcel	The state of the s
1A. TYPE OF PERMIT ACTION: (circle one)	Circle One: A/C Slab Room Addition
Construct Extend/Add Alter/Renovate , Repa	
* (Wreck/Raze) Move Install Revocable Revis	ion Porch Deck Fireplace Shed Solar Woodburning Stove
	- 日本会社(A) - 東京教育教育教育教育、 - 東京教育、東京教育、大学教育、
1B. CONSTRUCTION COSTS ESTIMATE \$ 7,000	40.5 (4.2)
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED AC	TIVE PERMIT SEE PERMIT #
1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY Ba	altimore Gas & Electric
1E. IS THIS PROPERTY A HISTORICAL SITE? Yes; se	ee attached
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND	/ADDITIONS
2A. TYPE OF SEWAGE DISPOSAL	2B. TYPE OF WATER SUPPLY
01 () WSSC 02 () Septic	01 () WSSC 02 () Well
03 () Other	03 () Other
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
4A. HEIGHTfeetinches	
4B. Indicate whether the fence or retaining wall is to be constructed	on one of the following locations:
1. On party line/Property line	
2. Entirely on land of owner	(D. III) and D. III)
3. On public right of way/easement	(Hevocable Letter Hequired).
I hereby contifu that I have the authority to make the foregoing ann	lication, that the application is correct, and that the construction will comply with
plans approved by all agencies listed and I hereby acknowledge and acce	
prairis approved by an agencies riston and rinorday normalization and a con-	***

	Date.
Signature of owner or authorized agent (agent must have signature not	arized on back)

APPROVED — For Chairperson, Histor	ic Preservation Commission
•	_
DISAPPROVED Signature	Date
ADDI ICATION/DEDMIT NO	FILING FEE:\$
DATE FILED:	
DATE ISSUED:	
HISPORE BOMIE LITTE'	HEURITHO. ILL WAITED.

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION

Applicant req	uests Historic	Area Work	Permit to d	emolish	all or	
part of four	(4) outbuilding	s shown on	attached m	nan:		
	#2 "Corn Shed"	134				. ;
Building	#6 "Hog House"					
Building	#9 "Blacksmith	Shop"			10.40.19.5	
Building	#5 "Oxen Shed"	building o	only, not st	one wall	attached	
See letter at	tached and inco	rporated by	reference	: C'	•	

ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.

MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE:
HISTORIC PRESERVATION COMMISSION
100 MARYLAND AVENUE
ROCKVILLE, MARYLAND 20850

,

etanaci, joga takot apole

romphy (au) competitive

en de Maria (n. 1865). On la Maria (n. 1865).

in the significant property of the state of the significant state of the significant α

i e si<mark>de</mark>esija ess_i

•

.

A CONTRACTOR OF

STEPHEN P. JOHNSON

ATTORNEY AT LAW
EIGHT BROOKES AVENUE
GAITHERSBURG, MARYLAND 20877

(301) 948-3460

July 26, 1989

Historic Preservation Commission 10th Floor 51 Monroe Street Rockville, Maryland 20850

Attention: Jeffrey Miskan, Chairman

Re: Master Plan Historic Site No. 23/46 "Greenwood"

Dear Mr. Chairman:

Please accept this letter as a part of my client's application for a Historic Area Work Permit to demolish all or part of four (4) outbuildings which are presently located on her property which, as you know, has already been designated as a historic site. The purpose of this letter is to outline for the Commission some of the events that have occurred, especially those after January 5, 1989.

As the record will indicate, a hearing was held on January 5, 1989, before the Commission regarding a similar request to demolish four outbuildings (the names for each of these buildings are of unknown origin). Mrs. Vrendenburgh was unable to attend that hearing because she had been notified of the hearing only the day of the hearing. This may have occurred because the notice was sent to the wrong address. In any event, the presentation made on her behalf, without the benefit of counsel, appears to have been accurate, but incomplete. Hank Handler of Oak Grove Designs, Inc. appeared and testified as to his cost estimates of rebuilding the four buildings in question. However, he did not have other important information at his disposal and was, therefore, unable to convey it to the Commission. Apparently because the presentation was incomplete, and because the Commission had apparently ordered Mrs. Vrendenburgh's predecessor in title, Hyman Frankel to do several things, which he did not do, it concluded the hearing and denied her the relief she was seeking, i.e., permission to demolish the four buildings.

Jeffrey Miskan, Chairman Historic Preservation Commission Re: Greenwood Page 2.

It should be noted that those buildings were in a state of almost total disrepair for many years prior to Mrs. Vrendenburgh's acquisition.

Subsequently, Mrs. Vrendenburgh sought legal advice and I immediately made contact with the staff at the Commission, namely Jared Cooper, to see what could be done to salvage the situation. Through these efforts and the cooperation of the County Attorney's Office, the Commission agreed to entertain a new application for a Historic Area Work Permit. (See attached letter from Edward B. Lattner, Esquire).

Since that time, Mrs. Vrendenburgh and several of her representatives have met with members of your staff to discuss her position with respect to the preservation of Greenwood as a whole. We have also involved members of the Code Enforcement Division of the County Department of Housing and Community Development who will be inspecting the property prior to your August 17, 1989, hearing.

Additionally, we have engaged the services of a qualified structural engineer, Thomas Carcaterra, P.E., to act as a consultant. He has inspected the property, especially the foundations of the four outbuildings in question, and photographed them. He has written an extensive report which will be presented to the Commission along with his testimony. His conclusion is that there are no adequate foundations upon which to attempt reconstruction and, therefore, he recommends demolition. His numerous photographs are especially revealing. We have also gotten another estimate besides Mr. Handler's mentioned above with respect to the cost of restoration of the outbuildings.

While this work preparatory to your August hearing has been going on, Mrs. Vrendenburgh has also engaged several contractors and spent large sums of money doing restoration work on the roof and windows of the main house and other parts of the property.

We trust this explanation will show that we have not been "foot dragging" since the last hearing and we look forward to discussing all of these issues with you and the entire Commission at length at the August hearing.

Jeffrey Miskan, Chairman Historic Preservation Commission Re: Greenwood Page 3.

If you or the staff have any questions or concerns, please do not hesitate to call me, and if there is a problem with the agenda for the August hearing, please let me know because I will need to coordinate with our various expert witnesses.

Thank you for your cooperation.

Very truly yours,

o non non esta o a determina a contracta de contratación de desergión de la contracta de la co

Stephen P. Johnson

SPJ:pc

copies to Faith Vrendenburgh
Farley Warner, Esquire
Code Enforcement Division, County Department
of Housing and Community Development
Thomas A. Caracterra, P.E.



1. Somery County Covernme.

OFFICE OF THE COUNTY ATTORNEY

Executive Office Building 101 Monroe Street, 3rd Floor Rockville, Maryland 20850-2589 TELEPHONE Area Code 301 217-2600

February 3, 1989

Stephen Johnson, Esquire 8 Brookes Avenue Gaithersburg, MD 20877

Re: Greenwood

Dear Mr. Johnson:

This letter will serve to confirm our conversation this morning that the Montgomery County Historic Preservation Commission will entertain a new application from your client, Faith Vrendenburgh, for the issuance of an historic area work permit regarding the above-referenced master plan site. 24A-7(a) of the Montgomery County Code (1984), as amended, provides that applications for the issuance of an historic area work permit shall be filed with the director of the Department of Environmental Protection. However, as we discussed this morning, it would be to everyone's benefit if Ms. Vrendenburgh met with the Commission and sought their advice before filing an application, especially in view of the Commission's past dealings with this \$24A-6(d). The Commission has a long history of working with the owners of historic resources and can provide helpful information on the appurtenances and environmental setting appropriate to an historic resource, construction methods and materials, financial information concerning historic preservation, and other relevant matters affecting the issuance of a permit.

If you have any questions or wish to schedule a preliminary meeting with the Commission, please contact Jared Cooper, Historic Preservation Specialist, at 217-3625.

Very truly yours,

CLYDE H. SORRELL COUNTY ATTORNEY


Edward B. Lattner

Assistant County Attorney

EBL:tjs

151L:89.00000

cc: Jared Cooper, Historic Preservation Specialist
Steven Karr, Chairman, Historic Preservation Commission
Melvin E. Tull, Chief, Code Enforcement Division,
Dept. of Housing and Community Development
Sharron Brown, Investigator, Code Enforcement Division,
Dept. of Housing and Community Development



MEMORANDUM

February 22, 1989

T0:

Steven Karr, Chairperson

stat detecti de la celularia in consequentamentamental area de la calenda de la calenda de la compania de la c

Historic Preservation Commission

FROM:

Melvin E. Tull, Chief

Division of Code Enforcement

Department of Housing and Community Development

SUBJECT:

Greenwood, Master Plan Site No. 23/46

You have inquired about efforts to prevent demolition by neglect of the outbuildings at Greenwood. In addition, you requested a chronology of actions taken in that effort. You are aware that ownership changed last year. I hope you are also aware that the previous owner had made modest repairs and that the new owner has also been repairing some outbuildings. The new owner, Faith Vredenburgh, is now under notice, deadlines are scheduled, and she has applied for a work permit to demolish certain outbuildings.

The most notable progress to date is the change of ownership. I believe that change was prompted by the inspector when he established that Dr. Frankel was unable or unwilling to act to prevent demolition by neglect. Dr. Frankel apparently choose to sell the farm rather than face enforcement action. Because Greenwood was being sold to someone who would invest in stabilization, it did not appear necessary or appropriate for the county to contract for repairs. The new owner, Mrs. Vredenburgh, committed to a schedule of investment and rehabilitation, has been making repairs, and has applied for a work permit to demolish certain buildings. Stabilization of the weakest structures is required by early spring.

The following chronology of historic preservation actions affecting Greenwood begins 13 years ago with several significant steps during the late 1970s that provided the foundation for all later actions:

October 1976

Publication of the Locational Atlas & Index of Historic Sites. Greenwood identified as site

23-46.

May 1979

Planning Board recommendation of Greenwood as a historic site along with 60 others in the original Preliminary Draft Master Plan.

July 24, 1979

Adoption of Chapter 24A, Historic Resources

Preservation Code.

Steven Karr February 22, 1989 Page 2 of 4

心解系统 医性病感觉 化 经基础分配 正型表 医神经炎的 化硫烷酸 经加强的现在分词

District Council adoption of the master plan September 12, 1979 for historic preservation, including Greenwood. May 22 & July 22 1986 HPC requests investigation of possible demolition by neglect and provided copies of 1974 photographs showing leaning buildings, missing sections of roof and siding, and other severe deterioration. November 10, 1986 After many attempts to inspect, our inspector met James Panek, the owner's son-in-law, at the property. After a brief discussion the inspector was told to leave. November 17, 1986 Inspector met with Dr. Frankel, the property owner and inspected the buildings with him. November 24, 1986 A notice and order to stabilize the outbuildings was sent to Dr. Frankel. December 15, 1986 Dr. Frankel wrote to express willingness to stabilize the buildings and to propose a plan of action that included demolition of several _outbuildings. February 2, 1987 The inspector wrote to Dr. Frankel extending the deadline to June 15, 1987 and notifying him that he must apply for a Historic Area Work Permit for buildings he hoped to demolish rather than repair. HPC was given Dr. Frankels letter about the plan to demolish certain buildings and the inspectors response referring the matter to the HPC. The inspector learned that Greenwood was for May 6, 1987 sale and notified the real estate agent of the demolition by neglect order. May 14, 1987 Dr. Frankels attorney, Robert A. Gingell, wrote to inquire about the process that designated

Greenwood as a historic site and whether

to comment.

the HPC.

Dr. Frankel had received notice and opportunity

Mr. Gingell was advised by letter to contact

June 5, 1987

Steven Karr February 22, 1989 Page 3 of 4

June 12, 1987	John E. Beckman, Jr., attorney for Dr. Frankel negotiated directly with the HPC regarding demolition of certain buildings and delay of repairs until the summer of 1988.
June 16, 1987	The inspector sent a Final Notice to Dr. Frankel stating that the County would make repairs and charge the cost to him if he delayed beyond July 17, 1987.
June 23, 1987	Dr. Frankel called the inspector to report that he planned to begin on repairs by August 7, 1987.
July 21, 1987	The HPC representative advised the inspector that Greenwood had been sold.
August 3, 1987	Dr. Frankel advised the inspector that Greenwood had been sold and settlement was scheduled for September 17, 1987.
September 22, 1987	Settlement rescheduled for October 1, 1987.
December 14, 1987	The inspector notified the new owner, Mrs. Vredenburgh, even though the deed still was not recorded.
January 7, 1988	The inspector reported that repairs had begun on the ice house and the coach house.
February 9, 1988	The inspector reported work continuing on the barn and ice house.
April 21 & 28, 1988	The inspector reported rehabilitation is underway and progressing.
July 15, 1988	The inspector and an HPC representative met owners on site and reviewed conditions.
July 28, 1988	The owner's representative (John Abernathy, a son-in-law) proposed a workable schedule for renovations.
August 19, 1988	A notice and order was sent to Mrs. Vredenburgh establishing deadlines.
November 22, 1988	The inspector found ice house repairs were not complete but were underway, and extended the deadline to January 1, 1989.

100

Steven Karr February 22, 1989 Page 4 of 4

November 30, 1988

Mrs. Vredenburgh applied for a Historic Area Work Permit to "wreck or raize" (sp) the cornshed, hog house, blacksmith house and oxen shed.

January 5, 1989

HPC denied the application.

February 3, 1989

のでは、「大学者」というでは、大学者である。 1995年 1995年

Assistant County Ed Lattner notified Mrs. Vredenburgh's attorney that the HPC will reconsider and entertain a new application: noting that the HPC has a long history of working with the owners of historic resources he recommended that she meet with the HPC.


At various times, both Dr. Frankel and Mrs. Vredenburgh expressed a desire to clarify the extent of their responsibilities for maintaining and restoring various outbuildings. We have no record of a response from the HPC to Dr. Frankel's request of December 15, 1986, forwarded on February 2, 1987, or to his attorney's proposal of June 12, 1987. With these requests pending and unresolved throughout the remainder of 1987 it appeared that the HPC was reconsidering whether those structures should be stabilized and restored.


There are 5 distinct phases in the events listed above:

- 1. Initial delays while the inspector was unable to arrange an inspection because Dr. Frankel was living in California and the occupants were uncooperative. This lasted 4 months.
- 2. Dr. Frankel was in the process of planning to make necessary repairs and determining, with the HPC, whether certain outbuildings could be demolished. His proposal to the HPC for demolition of certain buildings was not rejected and it was never certain that he would have to repair those outbuildings. This consumed 7 months.
- 3. The property was in a state of imminent transfer of ownership, during which it was not prudent to issue tickets or initiate repairs. That state lasted 5 months.
- 4. The new owner, Mrs. Vredenburgh, was making repairs and establishing plans for 11 months.
- 5. Mrs. Vredenburgh's application to clarify whether she must repair certain buildings or whether they can be demolished has taken more than 2 months and remains an open question.


MET:mmr:06601 cc: Jared Cooper

Historic Preservation Specialist









Blacksmith Shop



Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Maryland 20850, 217,3625

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	924-3614
NAME OF PROPERTY OWNER Faith S. Vrendenburgh	924-3614 TELEPHONE NO
(Contract/Purchaser)	(Include Area Code)
ADDRESS 21315 Georgia Avenue, Brookeville,	Maryland 20833
(Contract/Purchaser) ADDRESS 21315 Georgia Avenue, Brookeville, CONTRACTOR Oak Grove Designs, Inc.	TELEPHONE NO. 921-0254
CONTRACTOR REGISTRATION PLANS PREPARED BY	I NUMBER - TELEBUONE NO
TEAMOTRETANED BT	(Include Area Code)
REGISTRATION NUMBER 1	1860
LOCATION OF BUILDING/PREMISE	
House Number 21315 Street Georgia Ave	nue
Town/City Brookeville Flecti	on Oistrict
Nearest Cross Street Route 650	
positionerinity at the configuration of the configuration of the state position and the state of	
Liber Folio Parcel	A Committee of the Comm
1A. TYPE OF PERMIT ACTION: (circle one)	Circle One: A/C Slab Room Addition
* (Wreck/Raze) Move Install Revocable Revision	Porch Deck Fireplace Shed Solar Woodburning Stove Fence/Wall (complete Section 4) Other
	The state of the s
1B. CONSTRUCTION COSTS ESTIMATE \$ 7,000	
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTIVE PE 1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY BALLIMO	re Gas & Electric
1E. IS THIS PROPERTY A HISTORICAL SITE? Yes; see atta	ached
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITI	ONS
2A. TYPE OF SEWAGE DISPOSAL	2B. TYPE OF WATER SUPPLY
·01 () WSSC 02 () Septic	01 () WSSC 02 () Well
03 () Other	03 () Other
DART TURES COMPLETE ONLY FOR SENCE PETALNING WALL	
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL 4A. HEIGHTfeetinches	
48. Indicate whether the fence or retaining wall is to be constructed on one of	of the following locations:
On party line/Property line	
2. Entirely on land of owner	
3. Dn public right of way/easement	(Revocable Letter Required).
I hereby certify that I have the authority to make the foregoing application,	· · · · · · · · · · · · · · · · · · ·
plans approved by all agencies listed and I hereby acknowledge and accept this to	be a condition for the issuance of this permit.
•	• .
Classical design of a superior of the superior	
Signature of owner or authorized agent (agent must have signature notarized on	back) Date
APPROVED V COON Shed Mill For Chairnerson Historic Present	
APPROVED V CON SNOW (WILL For Chairperson, Historic Preserve	ation Commission
PICADDROVED 2 IMPONT B	VIIII V 2. 9/2/189
Signature 1 KICP OV PT D	Date
APPLICATION/PERMIT NO:	FILING FEE:\$
DATE FILED:	PERMIT FEE:\$
DATE ISSUED:	BALANCE\$
OWNERSHIP CODE: 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	RECEIPT NO: FEE WAIVED:

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION SELECTION CONTROL OF THE PROPERTY OF THE PROP

ينو

	DESCRIPTION OF PROPOSED WORK: (including com		
	Applicant requests Historic Area W	ork Permit to demolish all o	
	part of four (4) outbuildings show	n on attached map:	
	Building #2 "Corn Shed"	THE STATE OF THE S	
	Building #6 "Hog House"		
	Building #9. "Blackswith Shop"		entities of a first participation of the second
		1.1	(
and analysis is	Building #5 "Oxen Shed" build	ing only not stone wall atta	ned
	See letter attached and incorporat	ed by reference.	2. 11 x 13 (x 1)
	(atan troops on the		
	- Comment of the Comm	Company to Major State Company (Company)	
		* *} :	Ellipsi and the second
	(If more space is needed, attach additional sheets on plai	n or lined paper to this application)	,
ATT	TACH TO THIS APPLICATION (2) COPIES OF: SUCH	SITE PLANS (lot dimensions, building	location with dimension
	es; walks, fences; patios, etc. proposed or existing) and DTOGRAPHS OF THE AREA AFFECTED, as are necessar		or plans, elevations, etc
THU	TOGRAPHS OF THE AREA AFFECTED, as are necessar	y to runy describe the proposed work.	esta (il anno 1907)
IVIAI	IL OR DELIVER THE APPLICATION AND ALL REQUI HISTORIC PRESERVATION COMMISSION 100 MARYLAND AVENUE ROCKVILLE, MARYLAND 20850	ELS ES HEIDTEN VOR HEIDTEN ACHTE UN OF À ESEMBNES VOR HEIMENEN ACHTE	र्कारम प्रदेश समाज्ञ ।
n na manda alifera de maganesara at as na antida. Agas de madria distribuida de la m		1 2.3 Comment of the regularity	STATE AND ASSESSED.
	short.		
	28. 190F OF WALER SUPPLY 61 () White \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1 MEST CHMZ ERHCHUNG VID EXTERNÍVADO P.S. (-) - Sacric P.S. (-) - Sacric	STARTON COLE COLE COLE COLE COLE COLE COLE COLE
nasee to engine belonging to the	61 () 97°°C 92 () Well	13P09A1 P2 () Santin	CTOAWIN 40 MAT TO THE MET THE MET TO THE MET THE MET TO THE MET TO THE MET TO THE MET THE MET TO THE MET THE M
	01 () 97% () Well (1) 016w	HSPORAL P2 () Section DULY FOR ESMOS OFFAMINAS MALL SECTIONS	er hinale Canadatha anacareane equal en hin equal en hin astem for 10 astem f
	01 () 97% () Well (1) 016w	P.Z. () Section 1.1LY F.D.D. FSBMLE OF LANGING SWALL 1.1.LY F.D.D. FSBMLE OF LANGING SWALL 1.1.LY F.D.D. FSBMLE OF LANGING CONTINUED ON CO	of the part of the
	01 () 97% () Well (1) 016w	P2 () South P2 () South P1LY FDD FSMCE OFFAINING WALL or you be said and it is to the epostuncted on or party time (person	CHOANTO (B. 1847) DROW (C. 1
	01 () 97% () Well (1) 016w	P2 () South P2 () South P1LY FDD FSMCE OFFAINING WALL or you be said and it is to the epostuncted on or party time (person	Control of the contro
racello viaera	Head of the state	P. J. P. Portion P. J. J. Portion P. J. J. Portion P. J. J. P.	FROME ABOVER ABOVER TO DEPOSE A SECTION OF A
re ylqmes	Both () American	P. A. Sertic P.	CONTROL OF SET OF DEPARTMENT OF SET O
re ylqmes	19 () Ame () Well 19 () Piliper Prof. So following longities; Proposition of the construction will in the construction will be constructed in the construction of the construct	P. A. Sertic P.	CONVINTED SET OF DAY OF SET OF
are yigmen	11 () Pilyon () Well () Pilyon () Well () Pilyon (P.Z. (*) South P.Z. (*) South P.Z. (*) South P. (*) Harder C. Harder and accent this	CONVINTED TO F
ire ylqmed	11 () Pilyon () Well () Pilyon () Well () Pilyon (P. A. Sertic P.	CONVINTED SET OF
iro ylqmea	11 () Other 12 () Other 13 () Other 14 () Other 15 () Other 16 () Other 16 () Other 17 () Other () Other 18 () Other () Other () Other 19 () Other () Other () Other 19 () Other () Other () Other 19 () Other 20 () O	P.Z. (1) South P.Z. (1) South the sea properties of particular and accent this latter and accent this later and accent accent and accent and accent and accent accent and accent accent and accent accent and accent a	CONVINTED SET OF
are yigmen	10 f. he following lauring and that the construction will be been applied for the intermediate of the beautiful to the construction will be been another the intermed this permit. In head the for the intermed this permit. In head the construction of this permit.	P2 (1) Souther indicate of the following special contents of the authority on the following special contents on the authority of the authority	CONVINTED SET DEPM () 100 min () 200 TENTED TO THE TOP TENTED TO THE TOP TENTED TO THE TOP TENTED TO THE TOP TO THE TOP TO THE TO TO THE TOP TO THE TOP TO THE TO THE TOP
in yiqmed	11 () Other 12 () Other 13 () Other 14 () Other 15 () Other 16 () Other 16 () Other 17 () Other () Other 18 () Other () Other () Other 19 () Other () Other () Other 19 () Other () Other () Other 19 () Other 20 () O	P.Z. (1) South P.Z. (1) South the sea properties of particular and accent this latter and accent this later and accent accent and accent and accent and accent accent and accent accent and accent accent and accent a	CONVINTED TO THE CONTROL OF THE CONT
ire yiqines	12 () Simply () Well 13 consequent of the industrial description will be been and the constitution will to be a condition for the imponent this permit. 13 been and the first one of this permit. 15 been and the industrial of the industrial of the constitution will be been and the constitution of the constitution will be been and the constitution of the constitution will be been and the constitution of the c	P. J. Portion 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING BOD OF 1.11.7 F.D.R. ST. S. L. S.	Construction of the control of the c
ire vigines	11 () Simply () Well 12 () Pilper 13 () Pilper 14 () Pilper 15 () Pilper 15 () Pilper 16 () Pi	P. J. Portion 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING WALL 1.11.7 F.D.R. ESBLE OF LANDING BOD OF 1.11.7 F.D.R. ST. S. L. S.	TOAVIO (B. 1) (I) TOAVIO (B. 1) TOATO (B. 1)



Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Maryland 20850 217-3625

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	924-3614
NAME OF PROPERTY OWNER Faith S. Vrendenburgh	
(Contract/Purchaser) 21315 Georgia Avenue, Brookeville,	(Include Area Code) Maryland 20833
CONTRACTOR Oak Grove Designs, Inc.	TELEPHONE NO. 921-0254
CONTRACTOR REGIST	RATION NUMBER TELEPHONE NO
PLANS PREPAREO BY	
REGISTRATION NUMBI	(Include Area Code) ER
LOCATION OF BUILOING/PREMISE	
House Number 21315 Street Georgia	a Avenue
Town/City Brookeville	Election Oistrict
Nearest Cross Street Route 650	
	and the control of the second of the control of the
Liber Folio Parcel	
1A. TYPE OF PERMIT ACTION: (circle one) Construct Extend/Add Alter/Renovate Repa * Wreck/Raze) Move Install Revocable Revisi	Circle One: A/C Slab Room Addition ir Porch Oeck Fireplace Shed Solar Woodburning Si on Fence/Wall (complete Section 4) Other
1B. CONSTRUCTION COSTS ESTIMATE \$ 7,000 1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTION INDICATE NAME OF ELECTRIC UTILITY COMPANY 1E. IS THIS PROPERTY A HISTORICAL SITE? Yes; see	TIVE PERMIT SEE PERMIT #
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ 2A. TYPE OF SEWAGE OISPOSAL 01 () WSSC 02 () Septic 03 () Other	AOOITIONS 2B. TYPE OF WATER SUPPLY 01 () WSSC 02 () Well 03 () Other
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL 4A. HEIGHTinches 4B. Indicate whether the fence or retaining wall is to be constructed 1. On party line/Property line 2. Entirely on land of owner 3. On public right of way/easement	
plans approved by all agencies listed and I hereby acknowledge and accep	orized on back) (late
APPROVEO Virginia IIII For Chairperson, Historic	c Preservation Commission
OISAPPROVEO Signature	Oate
	FILING FEE:\$
OATE FILEO:	PERMIT FEE: \$
OATE ISSUED:	
OWNERS OF F	PECEIDT NO. FFF WAIVEO.


THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION

SCRIPTION OF PROPOSED WORK: (including com	position, color and texture of materials to be used:)
Applicant requests Historic Area W	ork Permit to demolish all or
part of four (4) outbuildings show	m on attached map:
Building #2 "Corn Shed"	
·Building #6 "Hog House"	
_Building #9 "Blacksmith Shop"	
Building #5 "Oxen Shed" build	ing only, not stone wall attached-
See letter attached and incorporat	ed by reference.
•	

ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.

MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE:
HISTORIC PRESERVATION COMMISSION
100 MARYLAND AVENUE
ROCKVILLE, MARYLAND 20850


(If more space is needed, attach additional sheets on plain or lined paper to this application)



SKETCH & HOUSE

CARRIAGO AM MAGRANGTHY Globs?

2000 NO 1914 N




DOHN M ABERNETING 1/17/89

POLA M EDERMENT I IS SP שפחת פין SKETCH #


ב לפרואוונגט דוא תאסף

DOWN BY JOHN M HEERHEILY 1/13/89

SKEICH #



Defining of the fone That I 18 89 SKETCH # GUPHSET HUT



● Fix Greenwood 23/46 89A

January 4, 1989

Members of the Montgomery County Historical Preservation Commission

My name is Leonard Allen Nash Becraft, 4th generation of the

Wilbur F. Nash Sr. family to live at Greenwood and protect the property.

I would like to speak and oppose the action of Ms. Vredenburgh to

demolish the four out buildings and any other buildings or structures

on the 14.34 acres parcel, surrounding the Maryland historical

Greenwood home site.

My main reason for opposing the removal of the listed buildings, would be the continuing destruction of the historical integrity of the Greenwood Plantation home place. Those buildings, which were used by the Davis, Craver and Nash families for 242 years represent the means by which our early settlers in Montgomery Co. developed the land and made a living. Few of these settings, are still available in our great Montgomery Co. and the people, owners and commission must protect and preserve them.

"Greenwood" is one of the counties oldest homesites and most historic. The Property where these buildings are located, dates back to the original land grant January 13, 1720 "Gold's Branch" to Richard Snowden of Laurel, Maryland Rrince George County for 257 acres. Are the members of the commission familiar with "Montpelier" in Prince George Co. It is the homeplace with outbuildings built by Richard Snowden on the Patuxent River and one of the showplaces of the County. "Greenwood" is about 20 miles West of "Montpelier" and the most Western of Snowdens land holdings. A homestead was started at

this time. The Davis family acquired the property in 1747 and five generations of Davis members were instrumental in its development. Ephraim Davis constructed the central brick portion in 1755.

Thomas Davis III, son of Ephraim Davis was born Dec. 10, 1768 and died in 1833. It is reported, that a great deal of the outbuildings were built under the direction of Ephraim and Thomas during this time period. The main barn was built around 1830, after a fire destroyed an earlier constructed barn by the Hawlings River. The complex of buildings near the house and barn are in their original settings and represent the life style of one of the Counties most prominent families, the Davis. The Davis family members are buried near the corn, oxen and Hog house in a family cemetary. They were satisfied to be interred near their life's work. These buildings were like monuments to their physical efforts and lives.

Maryland, Old Homes and History, 1952 gave "Greenwood" a special place in his book— the middle section. He stated the facts available are so volumious and the impact so important on the history of Montgomery Co., that it is necessary to divide the story into two parts to do the subject justice page 177. I will not go into great historical depth, but Thomas Davis III was a patriot, organizing a company and marching to Pennsylvania to help suppress the Whiskey Rebellion, as a commissioned officer under George Washington in 1794. He was in the Maryland House of Delegates, a justice of the Circuit Court, Judge, President of the Executive Council of Maryland, 2nd to the Governor. A founder of the Brookeville Academy, Surveyor and Vestry at St. Bartholomew's Episcopal Church. His son, Allen Bowie Davis, like wise was a prominent leader

in Montgomery County and the state of Maryland. He was President of Trustees at Brookeville Academy, Director of Montgomery Mutual Fire Ins. Co, President of Maryland Agricultural Society (Univ. of Md.), Rockville Fair, School Commissioner and director of the C&O Canal Company. The reputation of these men, make this complex of buildings eligible for the National Register of this nation. However, it was not completed. The information, I submitted in the 170's remain in Annapolis, Md., where it was accepted for the State of Maryland, as a top historic location, but because defanite boundary corners were not available due to subdivision; "Greenwood" was not placed on the National Register. Mr. Hyman Frankel, the new owner in 1980, did not pursue including the 14.34 acres on the National Register. "Greenwood" was chosen in 1979 by Montgomery Co. to be among the first 50 historical sites in the County to be protected. It was agreed by the Nash family, when selling the property to keep the barn building complex together with the mansion, so the buildings and home could be preserved as a historical showplace, as it always had been. "Greenwood" was the showplace of Montgomery Co. in the early 1900's. It was chosen to be displayed on a silver service tray, representing Montgomery Co. used on the Battleship Maryland. This silver service by Kirk is now on display in Annapolis, Md. The homeplace, buildings and ground were open to the public in 1976 for the Bicentennial tour of historic homes, where over 500 people on one day toured the property. I had the opportunity of being the 4th generation of the Wilbur Nash Sr. family to live in the mansion from 1970 to 1979 and protect the Nations historic trust. My Great Grandparents Wilbur Nash Sr. purchased the

property in 1926, transferred to my Grandfather Wilbur Nash Jr. in 1938. who farmed until his passing on March 11, 1966. The farm was continued to be protected by my Grandmother Alice Nash and relatives until 1980. My Great Grandparents and Grandparents maintained and kept the property open to the public. A bronze plaque was placed on the front gate post i n 1960's by D.A.R.honoring Thomas Davis' patriotism and leadership to his country. In the 10 years up to 1980, that I lived in the 17 room Davis mansion, I personally supervised the preservation of the buildings. The farming was handled by Mr. Austin Geisbert. He stored his corn crops in the corn crib, hay in the barn and machinery in oxen building. Hogs were still raised in the hog house up to 1980. The blacksmith shop in the main yard was used as a tool and lawnmower storage area. I have pictures showing they were in usable condition. However, with the change of ownership to Mr. Frankel, very little maintenance, if any was done to the outbuildings. I personally spoke with Mr. Frankel and encouraged repair work in early 1980's by his foreman, Mr. Hank Handler. The front beam in the corn shed was never repaired or replaced, allowing roofing to blow off and wind and rain to destroy front roof section and collapse of front section in May 1988. The corn shed was one of the show pieces (picture with trim) should be repaired and maintained. It stands on unique rock pedestal foundations and has overall withstood natures battering forces; the base and side walls are still firm. The oxen shed next to the barn and corn shed is unique in that it is one of the last in the county with window slits in the back stonewall for animal ventilation. It is said by Mr. Farquhar-" that Mr. Allen Bowie Davis had twelve to fifteen yokes of oxen, hauling dirt to the front lawn and plowing the fields. The loafing shed, follows the long stone wall from

the road, where animals were protected in winter. The hog house was used by Mr. Davis to raise 100 hogs a year to supply his family and slave with winter eats. It is unique in that it has a corn storage area in the second floor level with 4 areas for hogs. With some maintenance and paint this building can be saved. The Blacksmith shops an important part of the yard complex. The Davis family not only used it to repair tools, shoe horses, but use it as a butchering shed, where hogs were cut up to prepare for smoke house. The chicken house north of the homeplace was removed by Mr. Frankel without a permit and current action of bulldozing the concrete foundation appears to be currently underway. The main barn needs work on the siding and front entrance roof or it will rot and cellapse like the corn house.

I realize the repair of these historic buildings takes money, but the current owner was aware the buildings were part of a historic complex and were to be repaired at the time of her buying the estate. A demalition by neglect order had been placed on the previous owner, Mr. Hyman Frankel in mid- 1980's. He was asking \$700,000.00 for the property, which he had paid \$150,000.00 to the Nashs. Ms. Vredenburgh paid \$600,000.00, so a portion of the difference of \$100,000.00 must have been considered into the repair of these buildings.

"GREENWOOD" is not just another property in the County. It is comparable with Mt. Vernon, Monticelle and Montpelier. Where would these National land marks be with out outside buildings. I request these buildings not be demolished and hopefully preserved for the future generations, so the year of 2000 will see, what "Greenwood" families did to promote our nation. "Greenwood" is the main historic

estate on Rt. 97 leading into Montgomery Co. from Heward Co. and Baltimore and should be a show place to all the people. I request the commission to deny this application, for demolition and follow the current law into protecting the "Greenwood" estate! The address for Greenwood of 21312 is incorrect, in the Historic Preservation Commissions notice causing confusion and short time notice of meeting on this action did not give time for others to know or speak.

Thank you,

Leenard A. Becraft 15640 Santini Road

Burtonsville, Maryland 20866

Leonard a. Berraft

301-421-1117

PROPOSAL/CONTRACT

		•
PRESERVATION ASSOCIATES, INC. (CONTRACTOR)	No.	900201B
207 S. Potomac Street		
Hagerstown, Maryland 21740	Date	2/1/90
301-791-7880	Page No.	
501-731-7660	rage no.	•
Proposal Submitted to: (CUSTOMER)	Work To Be Perform	ed At:
115gebel babmitosea to. (obbiomin,	norm to be refreshing	
Name <u>Faith S. Vrendenburgh</u>	Greenwood Farm C	
Street 21315 Georgia Avenue	Street	
City <u>Brookeville</u> State <u>Marvland 20833</u>	CityState	
Phone	Architect	
We hereby propose to furnish the materials and perform the labor	necessary for the complesion o	f the Work:
	•	
Barn Stabilization and Repairs - refer to a	ttached "Description	of Work".
	•	
The Work to be performed under this contract shall be days after Customer has accepted this Proposal and obtained, and Substantial Completion shall be achieved commencement (see Item No. of attached Terms and TERMS AND CONDITIONS ATTACHED HERETO ARE PATTHE above work is to be performed as specifically two thousand four hundred dollars Payment to be made as follows: \$15,000 down fonthly invoices will be submitted for work through the end of each month. The final is obtained to the Work. Payments are due with Respectfully submitted, PRESERVATION ASSOCIATION	after all required permited within approximately (Conditions.) RT OF THIS CONTRACT. ied for the sum of: \$ payment upon accepta performed and materiate and in the submitting the submittent submitted the submittent su	its have been 90 days of 62,400 nce of Proposa al stored ted upon com- of invoice.
Note-This proposal may be withdrawn by us i	f not accepted within	<u>21</u> days.
ACCEPTANCE O	F PROPOSAL	
The above prices, specifications and conditions are	satisfactory and are here	hy accepted Vo
are authorized to do the work as specified. Payment		
Signa Signa	ture	
Data Signa		•
CI AM C	1 117:63	

Page 1 February 1, 1990 Vrendenburgh

DESCRIPTION OF WORK

GREENWOOD FARM COMPLEX

BARN STABILIZATION AND REPAIRS WORK DESCRIPTION

Northwest Quadrant Stabilization/Restoration:

- 1. Prop up the southwest section of roof opposing the northwest section to be dismantled.
- Remove roofing over work area.
- 3. Remove lath over work area.
- 4. Remove 2 28' rafters.
- 5. Remove 1 28' purlin to the pegged joint over threshing floor.
- 6. Remove the rough cribbing at the west hay mow level.
- 7. Remove debris at the west hay mow level.
- 8. Remove existing west interior bent's north 15' of top plate.
- 9. Space loose existing lumber on north half of west hay mow floor. Lay 1/2" CDX plywood over floor and screw/tack corners. Lay 2 2x8 planks stacked one on top of the other under each run of scaffold to be erected. Scaffold must be level.
- 10. Raise scaffold 3 sections long approximately 11 sections high to access purlins.
- 11. Set plywood, planks, level scaffold and raise scaffold 3 sections long, one section at a right angle to the other two to access the purlin and the top plate section to be replaced on the west interior bent.
- Beginning at the ground level, dig two footers to solid undisturbed ground a minimum of 24" below ground unless solid rock is encountered, preferably 36" deep. There is to be one footer inside the barn placed directly under the interior post of the west interior bent. The other footer is to be placed next to the west forebay wing wall to support the post carrying the northwest face of the barn frame. Each footer is to have an anchoring device for the base of the post.

Page 2 February 1, 1990 Vrendenburgh

- 13. The interior ground level post to be added will be an approximately 8"x8" oak post running plumb from ground level to under side of plate of west interior bent at hay mow level.
- 14. Another 8*x8* oak post will rise directly above the ground level post between the hay mow level and the threshing floor level directly under the post supporting the purlin.
- 15. An 8"x8" pressure treated post will be placed from the footer next to the west forebay wing wall up to the northwest face of the barn frame.
- 16. There is a double upright post on the north wall between the west gable end and the west interior bent. The lower end of the scabbed on post needs to be cut to receive a horizontal beam to be placed under the post. The horizontal beam will be an 8"x10"xi9' piece placed from the west gable frame to the west interior bent on top of the cantilevered joists and under the upright post.
- 17. At the northwest corner post 2 2x6x16' pieces will be nailed one each against each of the two interior faces of the post from sill to just under top plates. They will be cut around the wind brace joints to better resupport the wind braces.
- i8. Replace in kind with a new oak 7*x8*x15' piece the rotted top plate section at the north end of the west interior bent. Cut the existing top plate in a new structural scarf joint directly over the first interior post. Add steel web plate bracing up under the joint bolted to the post.
- 19. Cut and make a sawn wood purlin to match the existing in size and joinery.
- 20. Repair/replace two purlin supports, two purlin braces and three wind braces.
- 21. Reerect purlin frame, rafters, lath as originally done.
- 22. Lay new channel drain galvanized pressed steel roofing over repaired area.

Page 3 February 1, 1990 Vrendenburgh

Northeast Post Stabilization:

- 1. Reconsolidate the plates at the corner sills.
- 2. Reestablish two wind braces.
- Sister 2 2"x8"x16', one to each interior faces of the northeast corner post. Carefully cut around each brace notch to preserve integrity of notch and further support the notch.

Interior Ground Floor/Hay Mow Floor Stabilization:

- 1. At the south wall immediately under the west interior bent from the south wall north about 5' add two 8"x8"x8' posts supporting and 8"x8"x5' header.
- 2. Place a footer 1' deep x 2' x 2' under each post on good solid earth.
- 3. Remove one existing wood post on footer supporting a north axis summer beam. The post is severely damaged by termites. Replace with a 10"x10"x7' post at the present footer.
- 4. Attempt to jack up the summer beam, if doing so does not create stress or damage elsewhere.
- 5. Fill in the hole beneath the footer dug by a ground hog.

South Purlin at East End:

- 1. Replace missing brace.
- Plywood floor and raise scaffold.
- 3. Epoxy reconsolidate the base of purlin brace.

Page 4 * February 1, 1990 Vrendenburgh

North Wall @ East Side at the Doubled Post Between the East Gable Frame and East Interior Bent:

- The lower end of the scabbed on post needs to be cut to receive a horizontal beam to be placed under the post.
- The horizontal beam will be an 8"x10"x19' placed from the west gable frame to the west interior bent on top of the cantilevered joists and under the upright post.
- 3. Beginning at the ground level, dig two footers to solid undisturbed ground a minimum of 24" below ground preferably 36" deep unless solid rock is encountered. There is to be one footer placed next the inside face of the east forebay wind wall to support the post carrying the new horizontal beam. The other footer is to be placed under the joist at the opposite end of where the new beam ends. Each footer is to have an anchoring device for the base of the post.
- 4. Place one on each footer an 8"x8"x10' treated post cut to length.

West Gable Frame:

- 1. Repair and sister to the main top plate where it is damaged.
- 2. Repair or reanchor all stud and frame members in the northern half of the frame where loose or deteriorated.
- 3. The vertical light frame pieces of the upper frame all need to be worked on to restore sound structural stability.

Siding, South Wall:

- 1. Repair two louvers, frames and trim.
- 2. Replace 42 linear feet of rough sawn, green 1 x random 8" to 12" wide x 16' long siding of poplar. Use single run boards from top plate to sill.
- 3. Install 1" x 2 1/2" wide poplar battens 16' long.

Page 5 February 1, 1990 Vrendenburgh

Siding, West Wall:

- 1. Remove metal track and braces.
- 2. Set pole jack scaffolding.
- 3. Remove siding barn wall to repair framing.
- 4. Rebuild louver frame and install new louver and trim similar to front/south wall.
- 5. Owner to provide new pattern 105 novelty or German style cove top siding.
- Install new barge boards.

Siding, East Wall:

- 1. Set pole jack scaffolding.
- 2. Remove all warped, twisted siding.
- 3. Up to a maximum 50% of existing siding is to be removed under this proposal.
- 4. Reuse, if possible, any salvaged west wall siding.
- Use new owner supplied siding if salvaged and reusable siding is short.
- Install new barge boards.

East Ground Level Windows:

- Restore existing frames, if possible, epoxy reconsolidate.
- 2. Rebuild new frame parts if needed.
- 3. Build, treat and install new sash.

Page 6 February 1, 1990 Vrendenburgh

Ramp to Threshing Floor (Existing Opening):

- 1. Remove siding and roofing.
- 2. Install new strap braces at rafters to better secure them to the top plate.
- 3. Install new 8x8 treated beams, one under each sill of the side walls.
- Cut the ramp floor back to be independent of the side walls.
- 5. Dig two footers to better support the front corner posts of the ramp.
- 6. Install 2 6"x6"x15' sills, treated.
- 7. Install 2 6"x6"x14' treated front posts.
 - 8. Install 2 2"x8"x16' treated braces.
 - 9. Install new channel drain roofing.
- 10. New 1"x12"x14' poplar siding.
- 11. New 1"x2 1/2"x14' battens.

Masonry:

- West exterior foundation. Repoint no more than 80 SF mostly along top of wall at southwest corner.
- 2. Northwest corner under forebay at inside corner, point and fully bed.
- At the southwest inside corner repoint about 74 SF.
- 4. South wall. Repoint no more than about 20 SF exterior.
- 5. Point inside northwest corner above the west mow floor.
- 6. Repoint areas of south and east wall interior at the grainery floor and east mow level. No more than 70 SF.
- 7. Repoint no more than 50 SF at east wall exterior.

Page 7 February 1, 1990 Vrendenburgh

8. Repair a minor amount of block pointing on west wall of guonset addition.

Painting:

- 1. Paint the roof areas already painted one coat of fibrous roof coating. No new roofing will be painted.
- Paint main barn exterior new wood one coat of oil prime. Paint all wood two coats of NAVAJO RED STAIN, OIL BASE.
- 3. Paint quenset exterior addition two coats.

Gutters:

- Main Frame Barn. Install new 6" half round galvanized steel gutter with 4" down spout.
- 2. Install four pieces of 5" round down spout on quonset addition.
- Build and install a new box gutter similar to existing on west face of block wall of quonset addition where now missing.
- 4. New gutters will not be painted.


February 1, 1990

CHANGE ORDER 1

Replace entire north slope of metal roof of main barn beyond the area being replaced in the northwest corner.

- Remove all remaining corrugated roof from ridge to eave up to and not including quonset roof and gable sheet metal.
- 2. Renail roof lath.
- 3. Install new channel drain metal roof.
- 4. Reinstall ridge caps.

Additional Cost \$3,815.00



PRIORITY GR	EENWOOD FARM BUILDING	PROJECT	ACCOMPLISHED BY		PROJECTED Z-
SPRING/ SUMMER 90	MAIN BARN	MASONARY REPAIRS - SEAST / SWEST CORNERS PAINT ENTIRE STRUC- TURE TWO COATS	1 1		SUMMER 90 01
SPRING 90 TTEM 5 TTEM 5 WINTER 1 SPRING 90	QUANSET HUT HOG HOUSE BLACK SMITH SHOP	RIGHT THE STONE - WALL USING EXISTING BRACING & HYDRAULIC TACKS STABILIZE / UNDERPIN CAP TO PREJENT DETERIOR ATION MASONARY REPAIRS TO BLOCK ON WEST WALL REPLACE GLASS & GLAS SIX WINDOWS IN BLO INSTALL GUTTER WEST SIDE RECORD & RAZE RECORD & RAZE	CONTRACTED CONTRACTED COPORTIN INC -] CONTRACT/REED	2,500,00	MINTER! SPRINK 190

The second of th	A server of the	Commence of the second			Ib. The
of H	\$00°		REPAIRS SIDING		73WWS
a 16 minutes	C. C.	OMNES		SMALL SHED	15
FITTHE			REPAIRS SIDING	SPOUNDS KEEPER	I WALT
•	B++474-34-7	- OUNER			
ere.	00.00,	COPORTIN INE	REPLACE ROOF		
	00009	COMMER	KIND RINDOWS 4		b. yeurnes
7747	3,502,8	<u>C</u>	SIDING REPAIRS IN	ICE HOUSE	TIEW 10
î To	3 (200		DAINT STRUCTURE I PAING	-311117 211	
∤ 0	Topicalise Andrews	ONMER	J 23000 LIATENI		
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	COD OR TINE)	GMIN MI ZWOONIW		
		NEW TIM ROOF	REPAIR OR REPORTEY		
		- COMMER	SIDING IN KIND REPHISOR REPLACE		Ob CANAS
606,778	\$°°°° 2°°°°°°°°°°°°°°°°°°°°°°°°°°°°°°°°	GIGANINGS BUZ -	MASONARY REPORTING ON STONE PIERS	HOOSE	1100
1.Y		3 NOS -7		CARRIAGE	b WELL
Speine 91	27000	CONTRACTED STONE CENTET	SNITSIXE HOTAM OT		
11	The same same	0 225052400	FX ISTING FOUNDATION	MALL ,	06, 710,
# 4 A	Tager et al.	· ·	REBUILD WALL ON	CEMETARY	8 WALT
H. W	TPZZZAMI WARTE	OMMER	PAINT ENTIRE STRUCTURE	g delicities	
<u>-</u> L		OWNER	REPLACE DOOR		
O.	Hermonia.	محمد في المائية	IN KIND		· me de
116.		<i>omine c</i>	REPLACE SIDING-	The state of the s	16, Julys
צמלואר מו	من 000 کے کی 000 کے	- CONTRACTED	RESTORE LOWER FRAM		בשודן , סט
0	1,000,00		RESET FOUNDATION	SLAVE CAGIN	1
PROJECTEU .	COST	ACCOMPLISHED BY	PROJECT	BUILDING 1 MOON EHEN	

CARCATERRA

May 18, 1989 Revised July 31, 1989

Faith Vredenburgh 21315 Georgia Avenue Brookville, Maryland 20729

Re: 3889 Outbuildings Investigation

Greenwood - 21315 Georgia Avenue

Blacksmith Shop

Oxen Shed Hog House Corn Shed

Dear Mrs. Vredenburgh:

At your request, an inspection was made on May 8, 1989, at the referenced site. The purpose of the inspection was to examine and evaluate the structural condition of four outbuildings on the property.

The site has been designated as a historic site. The four buildings are part of a complex of old farm buildings on a 14 acre site. Photographs taken of typical conditions are included and referred to in this report. Throughout this report, descriptive names have been used to designate the buildings. However, the names used may not accurately describe the individual building's former use.

"BLACKSMITH SHOP:"

The "Blacksmith Shop" is located northwest of the main house, with a group of buildings which includes a former ice house, coach house, slave cabins and others. It is a one story shed, with a pitched roof. The ridge of the roof has sagged severely, with the center being about 6" or more below the ends, as seen in Photograph #1. The entire structure has rotated towards the north, with the front walls leaning inward about 10" in four feet, as seen in Photograph #2.

The building is about 27' x 11' wide. The pitched roof has a 1 ft overhang on each side. The structure has rotated and a tree at the rear of building is actually providing lateral support and preventing a total collapse of the structure.

Outbuildings Investigation 21315 Georgia Avenue Page -2-

The deformation of the structure includes the area at a work bench near the southwest corner of the shed, as seen in Photograph #3. At the east end, a decayed timber log was observed to be the foundation for the wall. The bottom of the wood siding is rotten in many places.

The roof framing consists of 2" x 6" roof rafters about three feet on center. Some rafters are missing and many have opened up at the ridge, due to the lateral translation of the structure, as seen in Photograph #4.

The tree which is holding the structure in place is seen in Photograph #5. The amount of lateral movement may also be seen in the loss of support for the roof rafters at the front wall, as shown in Photograph #6.

The asphalt shingles on the roof are extremely deteriorated with many splits and failures, allowing water to penetrate the roof sheathing and the structure. Many openings could be seen through the sheathing. The shingles at the southwest corner were removed and the sheathing was found to be rotten, as seen in Photograph #7.

Photograph #8 shows the interior of the shed. A 6" \times 6" brace at the rear wall does not appear to have any function. Roof sheathing is a mixture of boards of varying widths. There appears to be a complete loss of any connection between the wall and ceiling joists. A 6" \times 6" timber member is located below all walls, serving as the foundation, with most of it decayed. There is a rough dirt and stone floor. The walls are framed with 3" \times 4" vertical studs without any bracing. The whole front wall has pushed in, making the structure unstable and unsafe.

The structure is unsafe and would require extensive shoring to replace foundations and decayed structural elements. Since most of the building is in an advanced state of decay, very little of the original structure could be reused. From an engineering standpoint, demolition of the structure would be the most advisable course of action.

"OXEN SHED:"

The "Oxen Shed" is a one story structure located south of the main house, near the main barn and silo. The front elevation is shown in Photograph #9. Along the front, it is framed with $8" \times 8"$ posts which support $3-3" \times 12"$ beams over spans of 20 feet.

Outbuildings Investigation 21315 Georgia Avenue Page -3-

The width of the shed is about 20'. At the rear, a stone foundation wall supports the roof structure.

3" x 14" ceiling joists frame between the front beam and the rear wall. Roof framing consists of pitched rafters with collar

ties. Ceiling joists are about 3'-8" on center. Many members have split and failed. One post is tilted significantly, with a brace having been added.

Extensive decay was noted in a horizontal member on the east wall. At the west side, the siding was observed to be curled, split and extensively deteriorated. As seen in Photograph #10, the entire frame has translated laterally. Windows are askew and frames are out of plumb. A level placed against the window frame found it to be 6½" out of plumb in four feet.

The stone foundation wall at the rear was also found to be out of plumb, about 7" in four feet. Wood braces and concrete anchors have been added to support the wall, as seen in Photograph #11. The wall is almost plumb at the east end, as seen in Photograph #12. Without the support of the braces, failure of the wall and the entire structure would most likely occur.

Extensive decay has occurred in many elements of the structural framing and foundation. At one column, decay of the member is complete, requiring the addition of another post, as seen in Photograph #13.

West of the post shown in Photograph #13, there are only two 3" x 14" members supporting the roof instead of three. The members have split and are still supported by the decayed post, as seen in Photograph #14. The brace and new post are not adequate and do not appear to have any function in supporting the load of the beam.

A similar condition was observed at the other end of the span, with twisting and failing of the beam over the support, as seen in Photograph #15. Another view of the poor condition of the beam and its support is shown in Photograph #16.

At the east wall, extensive decay was observed in some members, as seen in Photograph #17. The wood used in the roof framing appears to be used lumber from another project. Some roof rafters are tongue and groove boards, as seen in Photograph #18. Decay was observed in several areas of the roof framing.

Outbuildings Investigation 21315 Georgia Avenue Page -4-

Inadequate support was observed for the posts at the front of the building, with no foundation and the post bearing on one corner of a concrete masonry block, as seen in Photograph #19.

The members observed in the roof framing indicate that the "Oxen Shed" may have had its roof replaced in the 1950's, when reportedly, a large concrete masonry unit and steel addition was built next to the main barn. Similar wood beams and joists were used in the floor construction of that addition. The wood members appear to have been reused from another structure. Portions of the shed may have been rebuilt at that time, such as the poured concrete curb at the east end of the shed.

The north stone wall has tilted due to erosion below the footing, loss of equal soil bearing pressure and the inadequate bracing of the roof structure. The wood braces along the wall are providing the lateral support, preventing the total collapse of the building.

The advanced state of decay in some structural elements, inadequate roof framing and lack of any adequate foundations make this building unsuitable for repairs and demolition of the building is recommended. The stone wall and supporting braces may remain.

"HOG HOUSE:"

The "Hog House" is located near the main barn at the end of the stone wall. It is located below a steep slope, as seen in Photograph #20. A view of the building, looking north, is shown in Photograph #21.

Silt and mud carried by the runoff from the adjacent higher ground, south of the "Hog House", has covered much of the crawl space below the first floor. The asphalt paving around the "Hog House" has many fissures and splits, indicating the extensive soil erosion which has occurred. The first floor over the crawl space is decayed and has many deteriorated members, with no support below some posts, as seen in Photograph #22.

The north wall is considerably out of plumb, sloping about 1%" in four feet towards the south. The lateral deformation and lack of adequate vertical support has caused some roof beams to pull away from the post at their connection, as seen in Photograph #23.

A view of the framing above the first floor is shown in Photograph #24. Decay was not as evident in the upper portion of

Outbuildings Investigation 21315 Georgia Avenue Page -5-

the structure.

Severe damage to the framing was noted in the crawl space below the first floor. Some beams rest on rocks, as seen in Photograph #25. Total collapse of support and framing was observed at several areas, as seen in Photographs #26, #27 and #28. Another beam bearing on a large rock is shown in Photograph #29.

A view of the framing above the first floor is shown in Photograph #30.

The poor grading which has caused runoff to pile silt and mud in the crawl space, combined with inadequate foundations makes this building also unsafe. Photographs #31 and #32 show typical bearing of beams on pieces of wood, brick and stone.

At the southeast corner, the wood siding is buried in earth and has areas of decay as seen in Photograph #33. A view of the upper floor framing, looking west from the east end, is shown in Photograph #34.

The span of the openings at the front is ten feet. $8" \times 8"$ posts support $3" \times 8"$ floor joists, 30" on center, which span from the front wall to an interior beam and post. The overall width of the building is 16 feet. The interior beam is about 6' from the rear wall, so span of joists is 10 feet. The wood roof spans across the width of the building. The floor above first floor is rotten in many areas. A sag was observed at an interior post.

Roof rafters are 24" on center, full 2" x 6", butted at ridge; with some collar tries. Rafters sits on vertical wall about 3' above floor line, with outriggers for the overhang at each side of the building.

A substantial settlement was observed along the interior. Photograph #35 shows the depressed area along the roof line. The extensive erosion from the runoff is shown in Photograph #36, looking south.

The roof framing above the first floor ceiling is shown In Photograph #37. Views of the exterior of the building are shown in Photographs #38 and #39.

The structural condition of the building requires the removal of the first floor framing and its replacement upon a properly designed foundation, with regrading of the site around it to eliminate the runoff which presently flows below the crawl space. The entire structure would have to be shored while the foundation Outbuildings Investigation 21315 Georgia Avenue Page -6-

work is being installed. In view of the lack of adequate bracing of the roof structure, decayed portions of the frame and lateral translation which has already occurred, it might be necessary to dismantle large sections of the building. I have reviewed the cost estimates prepared by Oak Grove Designs, Inc and generally concur with them. As a result, the repair of this building may not be economically feasible and its demolition is recommended.

"CORN CRIB:"

As seen in Photographs #40 through #48, this building has totally collapsed and reconstruction of the original structure would be practically impossible. Demolition and removal of the debris, which has no historical value, is recommended.

In summary, the structural condition of the four outbuildings is very poor, and the repair and renovation of the buildings would be extensive. The unsafe condition of the "Blacksmith Shop" and "Oxen Shed", inadequate or non-existent foundations, advanced state of decay, deterioration of many members and inadequate structural framing would require that the buildings be practically totally rebuilt. In the case of the "Hog House", the extensive foundation and shoring which would be needed may be prohibitively expensive. Consequently, it is recommended that all four buildings be demolished and the sites regraded and landscaped.

We are pleased to have been of service. Please call if you have any questions.

Since gely,

Thomas Carcaterra, P.E. Consulting Engineer























































1.03

HISTORIC PRESERVATION COMMISSION 1 MONTGOMERY COUNTY, MARYLAND 2 3 4 5 HISTORIC AREA WORK PERMIT OF FAITH S. VREDENBURGH Case No. 23/46-89A 6 21315 GEORGIA AVENUE BROOKEVILLE, MARYLAND 7 8 9 A hearing in the above-entitled matter was held on Thursday, 10 August 17, 1989, in the Ninth Floor Conference Room of the GBS 11 Building, located at 51 Monroe Street, Rockville, Maryland 12 20850, before: 13 14 15 16 17 18 19 20 21 22 23

Deposition Services, Inc.

"You are our most valued client"

2300 M Street, N.W. Suite 800 Washington, D.C. 20037 (202) 785-1239

24

.

MALE VOICE 1: Okay. The next item on the agenda, Application by Faith Vredenburgh for historic area work permit at 21315 Georgia Avenue, Brookeville, Maryland, HPC Case No. 23/46-89A. Vredenburgh. Do we have a staff presentation? On the wall this time. That place looks familiar. That looks more like it.

MR. COOPER: I don't know how much of the chronology
I mentioned in this staff report, but I spent some time out
at the farm and was out there Saturday -- I believe it was
April 1st, as I recall -- and had to crawl through the farm - or through the buildings, rather -- and around the farm and
it's certainly a fascinating place, but this is the main
house. I think most of you are familiar with it.

This is the house kind of from the rear showing some of the outbuildings. I am just going to do a quick slide or two of all of the outbuildings that are there. This is a little complex that includes a small log structure and little frame structures, the closest to the house of which has been extensively modified.

This is the cemetery surrounded by a stone wall with old --

MALE VOICE: Millstones.

MR. COOPER: -- millstones cut in half for effect.

Thank you. Another part of the stone wall. This is part of the cemetery fence. This gives you an idea of what is

2

3

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

740 07002 Ž BAYONNE,

happening around Greenwood and its environmental setting. Some very large residential structures popping up on the horizon here and there.

This is the main barn. According to some research that has been done in the past, this is purported to have been built in 1858. The main barn showing a mid-twentieth century addition of concrete blocks and lumber.

The first of the four buildings for which the applicant has requested the demolition permit -- this was most recently or it at one time in the more recent past was used as a corn crib with a drive-through, although there is some evidence that it was converted from some other earlier use; that it might have been more of a closed building at one time with a later --

And you will notice in the staff report, based solely on the field inspection, I estimated the date of construction of this building at turn of the century, perhaps late 19th century. There is some post and beam construction. It was a fairly well-built building.

The lean-to addition to the side was built sometime later, perhaps approaching the mid-twentieth century from what I can tell by building materials and construction This building, since this slide was taken on April 1st, has collapsed further. Some of you may know that. Here it is from the other side looking toward the farmhouse.

The lean-to addition. A close up showing the construction method. There is some post and beam. Like I say, there were some alterations to this building. I did not figure out exactly what went on, but it appears that the use was changed when they opened up the center of it. There is a scalloped bargeboard or -- that was a decorative feature.

This is the second building the applicant has applied for demolition for, known as the hog house. I think that is an apt name for it. It looked like it was used as that. One side of it still has a fairly good roof on it.

Reasonably holding together is how I would describe it, although without question it had some foundation problems due to low maintenance over recent years, I would say, and also a real problem with this building with some runoff from a hill that leads up toward were some of those new houses are.

This it the other side of it. You can see its relationship to the main barn. There you see the newer probably 1950s additions to the newer barn and you see a lot of the siding that has deteriorated, but the building is in tact largely because the roof has held up. I don't think the building has been actively used for at least several years.

My estimated date of construction on this is early twentieth century, perhaps 1920, along in there. This is a view of the roof. I feel that the structure of this building is still fairly sound. There was some shoring of the

98/0

BAYONNE, N.J. . 07002 FORM

foundation. It could be brought back.

I did raise the question, you'll remember, in the staff report about how significant the building is, but aside from that I felt that of the four, in practical terms, it was the one that has held together the best and would be easiest to keep standing and to put back together.

This shows some of the flooring. This shows that the floor on the one side of the building has actually hit the ground. Part of that is the runoff problem. The ground has come up to meet the building as much as the building as sunk into the ground.

This is the third of the buildings, what is called the oxen shed. If I dare to speculate, I would think that this probably is an oxen shed, but there is definitely evidence that because of the stone wall -- there is a lot of evidence that there was a structure here over that stone wall perhaps as early as the mid-nineteenth century when I am thinking that this stone wall was built, perhaps about the same time as the barn and a lot of other improvements were made on the farm. Maybe someone else here knows even a little more about that.

There is some evidence in this wall, because of the ventilating slots that are fairly typical of mid-nineteenth century agricultural stone walls and barn walls and foundations that it was a part of the building at one time

10/89

and also the center door, which though I think the framing around it has been changed, it looks like there was always a doorway at that point. There's no sign that the stone was cut at a later time.

So that, yes, what building was here, I don't know, but the structure that's over it now, this wooden part which looks like it has been used as the implement shed, was constructed -- a lot of it was constructed at the same time that addition was built to the main barn. The very same lumber and nails were used. It's what I call railcar siding. It's the very thick tongue-in-groove siding.

One end wall of it is still intact, but even it is -frame with clapboard siding that was put on with what are
known as wire nails commonly, but that doesn't date before
the early twentieth century either. So, the whole point of
all this is the building doesn't relate to the stone wall at
all in terms of age, according to my inspection.

Now here is the end wall I just referred to, the -frame wall. The window sash dates sometime to the early
twentieth century. There is no evidence -- from a distance,
I think they have an appearance of being of a little earlier
origin than they really are upon closer inspection.

Here is an inside shot showing that doorway. Also, if you look at it the right way, you can see that wall is leaning out rather at a rakish angle. Here is the closeup of

10/89

10/89

one of the ventilating slots in the wall.

This is a view of the roof structure showing that not only the roof boards were that railcar siding tongue-in-groove, but some of those were paired together to form makeshift rafters. Fairly heavy duty lumber was used in the structure, but it's very poorly designed and, as you can see by the ridge line in the former slide, it has deteriorated dramatically and is in precarious condition, if that's the right word. And that, also, I recommended removal of the building and retention of the stone wall for the reasons listed in the staff report.

The last building is what is known as the blacksmith's shop. Again, I say that because I didn't see evidence that it was a blacksmith's shop. This appears to have been built roughly around the time when the hog house was built. Again, my guess was 1920 or so.

This building has deteriorated dramatically. One of the reasons is it hasn't had much maintenance over the years.

It's to the point now where it would require a tremendous amount of work to bring it back.

This shows its relationship to some of the other outbuildings, the last few other outbuildings that I haven't mentioned; the one on the right being the carriage house; the one on the left, the ice house.

The blacksmith's shop falls between the two and doesn't date from the same period. Two flanking structures, by all evidence, were built a good several decades earlier than the blacksmith's shop.

Here is kind of looking up the hill toward the house, a rear view of both the ice house and the blacksmith's shop showing that, as someone pointed out somewhere, that this one -- I think it's a poplar tree -- but a couple of trees back there appear to be keeping the blacksmith shop from continuing its way on down the hill.

And this is inside the blacksmith's shop. You don't see a lot there. It looks like it has been used as a workbench area. This is the roofing structure of the framing of the roof, a very simple construction.

This shows the rear of the carriage house, some of the ongoing efforts of the property owner. In summary, as indicated in the staff report, I recommended that permission be granted to remove three of the structures which include the oxen shed, the blacksmith shop, and the corn shed, with retention of the hog house.

MALE VOICE 1: (Inaudible.)

MR. BRENNEMAN: So how many buildings do you recommend leaving?

MR. COOPER: The one, the hog house.

MR. BRENNEMAN: Just the one. And retaining the stone wall.

FEMALE VOICE 1: No. Of the one, two, three, four.

MR. COOPER: That's true. That's a good point. That only the wood portion, the later portion of the oxen shed was recommended. That's fairly obvious.

MR. JOHNSON: Mr. Chairman, my name is Stephen

Johnson. I'm an attorney with offices in Gaithersburg,

Maryland. I represent the property owner, Faith Vredenburgh,

who is here with us in the back corner.

Our purpose here is twofold. An obvious one obviously is to ask for historic area work permits to demolish the four buildings that Mr. Cooper has just described to you. The second is, in a way, to come and make peace with the Commission, to make a reconciliation, I guess.

I have read the transcript of the January '89 hearing. I think it's fair to say that that didn't go too well. Our purpose is to ask that we not be saddled with all of the problems of the past. We're here to start off with a new footing the process that has already begun and, I might suggest, with our many contacts with the staff, I would respectfully suggest cooperation with the staff.

I'm here to state emphatically on Mrs. Vredenburgh's behalf her commitment to the entire concept of historic preservation and, more importantly, historic restoration, if

68/

you will, of Greenwood, Greenwood as a whole. She wants not just to preserve or stabilize these buildings that you've seen, but rather to restore them, to restore all of those that are reasonably restorable or are subject to restoration.

The map that you have I think attached to your packet has the names on it that we so frequently use and that Jared has already used tonight. Quite honestly, we do not know the origin of those names. As he has indicated, the blacksmith's shop could hardly have ever been a blacksmith's shop.

There's no -- there, no fireplace there. No one but a very short person could stand in it. I can't stand in it. The ceiling supports are much too low.

The oxen shed looks like a garage, a 1920 garage.

But we have maintained the use of the names for ease rather than designating buildings one, two or four. We seem to get confused that way. We can all have an image of them by continuing to use those names, so I will.

Mrs. Vredenburgh and her family are in the process of developing an overall plan for, as I said, the restoration of this entire property. Her main focus has been, I would respectfully suggest, the house, the main house, which is, if not the oldest, one of the oldest structures in Montgomery County.

She is committed to saving that which has been called the slave quarters and the main barn. She acquired the

10/89

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

property in June of 1987, took title in October, and acquired The four buildings that we're talking about 14.34 acres. were in bad shape then. They were already the subject of your review, scrutiny, criticism, and justifiably so. were in bad shape.

I think we all must recognize the deterioration shown on those slides didn't occur overnight. It didn't occur just during her ownership period. She was assured by the realtor that the orders of the Commission had, in fact, been modified after they were issued to her predecessor in title, Dr. Frankel.

She worked with the County. Housing inspectors were there and encouraged her in the work that she started. the time she came before you -- or her representative came before you -- in January of this year to ask for the demolition of those buildings, only to be denied quickly, she was shocked, to say the least, simply because of what she had been told, what she had been assured during this whole She told me tonight for the first time that if she process. had known the truth, the reality of the situation, she would never have bought Greenwood in the first place.

A little bit more historic perspective, as best we This property in the 1950s and '60s consisted of over 1,000 acres of land. It was probably a working farm with many of these farm buildings that you have seen in use.

FORM 07002 Ę. BAYONNE.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

740

The parcel was later reduced to 170 plus or minus acres, probably during the '70s sometime. I'm not entirely certain.

But in 1978, that parcel was reduced to its current size of 14-plus acres. That reduction made possible those million dollar homes that you saw that surround Greenwood. That was the land the developers bought that makes up that property.

The 14 acres that were left were the minimum size required to hold the buildings. Nothing else was left. This apparently was done immediately before the adoption of your ordinance in 1979. I don't know whether to posit that sale with suspect motives or not.

They left these buildings and nothing else. Without saying much about it, there can be no farming on this property. There is no farm land available. She can't keep animals in the hog house. She can't keep oxen in the oxen shed. She can't even keep chickens under County law.

She acquired the property, as I said, in 1987 from Dr. Hyman Frankel, who had acquired it in 1980. The property was not in good shape at the time that he bought it. interior of the main house had badly deteriorated at the time he bought it. He apparently bought it as an investment and he had to have spent hundreds of thousands of dollars on the interior of that house.

25

10/89

He installed a brand new HVAC system with duct work running throughout the house, a new electrical system. He restored the trees around the property. He removed stucco from the main portion of the house. He repointed all of the brick.

I've never met Dr. Frankel, but I would respectfully suggest he was in probably the same dilemma that Mrs.

Vredenburgh now finds herself in; namely, having a limited budget and rather unlimited expenses and the absolute necessity for making priority decisions. What comes first?

What must come first in his mind as in Mrs. Vredenburgh's mind? The main house has to come first.

She has received -- and I will be handing to you momentarily some documentation of this -- tell you that she has spent and committed to spend and receive additional estimates with respect to additional repairs on the main house.

She has received recently a repair estimate to paint the roof of the main house at \$3,000. Paint the trim. All of the windows need repainting. She has received an estimate of \$2500. She has increased the size of and done repairs to the air conditioning system, the water heater at the cost of \$5,000.

MALE VOICE 1: I think before the Commission this evening is only the demolition permits, if we could focus on

that.

MR. JOHNSON: Okay. I would just summarize that whole thing to say that she has already spent twenty-three, twenty-four thousand dollars in repairs. As I said earlier, she is committed to making this entire property an historic treasure, as it should be, for all of us, for herself, and for the Commission, and for the historically concerned public of Montgomery County.

However, what she purchased in many ways was an eyesore. You saw the photographs -- corn crib, the oxen shed are clearly visible from Georgia Avenue. That's what the general public sees. Without walking onto her land, that's virtually all they can see. The main house is hidden by trees from the main road.

She is simply asking that she be able to remove those to properly landscape that property, to shore up the wall that is now going over with the oxen shed, and make this a pleasing visual prospect.

As Mr. Cooper has indicated, she wants to remove the corn crib which has now completely collapsed. The oxen shed, she wants to restore that beautiful stone wall and let people see it. She does not have unlimited funds for this restoration. She wants to use her resources wisely.

As I said, the main focus has been the main house and the main barn. She is not anxious to have her money diverted

10/89

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

BAYONNE, PENGAD CO.

from these purposes by rebuilding, if you will -- we will have testimony momentarily from Thomas Carcaterra, our structural engineer/consultant, that the four outbuildings are not possible of stabilization. They must be rebuilt at considerable cost.

I have prepared eight copies of two different cost estimates. Mr. Chairman, if I could get you to pass those around for me, please. One of these you probably have seen That done by Oak Grove Designs, Inc. was submitted to you at the January hearing. We have submitted another, sort of in corroboration for those estimates. They are not They shouldn't be identical, but they are identical. Good. ballpark similar.

This is for the cost, if you will, of restoration of these four buildings and I would respectfully suggest that it makes no economic sense whatsoever, that they are just hideously high and based upon the dubious historical value as outlined to you by Mr. Cooper tonight, simply cannot justify the expenditure of those kinds of funds on those buildings.

I won't insult you by reading these into the record. I would respectfully ask they be included into the record. Both of the repair estimates include, however I would note, repairs to the main barn which she has begun and which she is committed to do. The main barn is not subject to the demolition request, but it is included in both of our

740 ž

10/89

1

2

3

4

5

6

7 8

9

10

11 12

13

14

15

16

17

18

19

20

21

22

23

24

25

estimates to show you what kind of money she is expending.

I would respectfully remind the Commission that the demolition by neglect portion of your ordinance mandates only stabilization, not rebuilding. Since these are not subject to stabilization, rebuilding is the only alternative and that that is not an economically viable one.

As I said, I would like to introduce now, and I have for the record also a resume for Thomas Carcaterra, a professional engineer, who has inspected the property recently and prepared a rather detailed report. Mr. Cooper has five copies of that. I apologize for not having eight. I trust that you can look over each other's shoulders.

They include a set of what I would say are rather telling photographs that he would like to describe to you. So for the record, Mr. Chairman, Mr. Carcaterras' resume and I would ask that he join me here at the table and walk through his report with you.

MR. CANTELA: Excuse me. Before we move away from that --

> MR. JOHNSON: Sure.

-- I would like to ask you a question MR. CANTELA: about the estimates. They seem to be some time apart. Are you aware that these estimates, when they were requested, that it was explained to those estimating that there was no intention to save these houses if they were really intending

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

-- especially with Mr. Yudo services -- that they were coming to be -- asking to be razed? These were estimates that were MR. JOHNSON: No. given in response to the question, what would it cost to put this building back together. We didn't discuss razing with them that I know of. MALE VOICE 1: This is total rehab of the buildings. MR. JOHNSON: Right. MALE VOICE 1: Not stabilization. MR. CANTELA: The question was, when the request for the estimates was made was it part of that discussion also that it was your intention that you would prefer to have the buildings razed? MS. VREDENBURGH: No. No. MALE VOICE: It was basically to restabilize the structure --MR. JOHNSON: Any other questions before we -- okay, It's yours. Tom. MR. CARCATERRA: My name is Thomas Carcaterra.

from Silver Spring, Maryland and I was asked to make an evaluation of these four buildings, which I did on May 8th, and I prepared a report and some photographs.

And in the interest of time, since it's really getting quite late, I thought it might be good if we just go over the photographs and I can give you a brief kind of

740 Ž. BAYONNE.

outline as to what I found.

3

2

4

5

6

7

8 9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

The blacksmith shop. If you'll turn to photograph number one, that's a general view of what you've seen before, the sad state of the roof and the siding. In photograph number two, I took a four-foot carpenter's level, which you'll see standing vertically, and I measured that there was about a 10-inch lateral displacement every four feet, which means that that whole wall must be leaning over a foot which is not a very good structural state of affairs.

There was a lot of evidence of deformed and rotten That bench, which I guess you've seen before, is shown in photograph number three. The framing of the roof looks like they're two by sixes at about three foot on center. There were many that were missing. There were no collar ties. That's shown on number four. So that the structural integrity of the roof would be rather questionable.

And as has been mentioned before, it's my belief that that tree shown in photograph number five at the rear end is what is actually keeping that whole structure from falling down because the tilt of it is so great that it has to have something just to hold it up and that, I think, is What is holding it up.

This lateral displacement has caused the bearing of the roof rafters to slip off the walls, as you'll see in photograph number six, so you really have a very unstable

CO., BAYONNE. N.J. 07002 FORM 740

1 2

structure which under maybe a good strong wind of 70 miles an hour or a slight earthquake which we occasionally have here would bring that down. It's a very unsafe structure the way it is right now.

Number seven shows that the roof itself, the sheathing and all, is just full of holes and rot. There's no question in my mind that the entire thing would have to be torn down and actually built over again. And in number eight, there is decayed timber both in the siding and in a log type of foundation that runs all along the walls which could not be salvaged.

so that from my point of view, my opinion is that the entire structure is not safe; that most of the elements would have to be actually replaced; and if you ever wanted to do something with it, you would wind up with a model. You would have to really get a lot of rafters and beams and siding and actually make a false building which is not the real original building.

On the oxen shed, we have a general view of that in number nine where you can see the defamation in the ridge and the eave. There has been quite a bit of sort of local failure that has occurred there.

And there again, if you take a look at photograph ten, which is the elevation of the side of the building away from where there is a pier -- at the opposite end it doesn't

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

21

22

23

24

25

seem to be so bad -- but here, if you look closely, again I've put a carpenter's level standing up against one post there by the door and I measured that at six and a half inches every four feet. Again, the entire front or side has just kind of swayed over. You can see it from the windows.

And again, when you look at photograph number 11, and I believe what's holding this building up is the stone wall at the rear which tilted by itself and somebody put braces on here in order to keep that from falling down. So, there again, we have something which is very unstable and it's just barely hanging on with these braces. Number 12 --

MR. CANTELA: Do you believe the stone wall should be torn down as well?

MR. CARCATERRA: It depends upon the historical sort of emphasis that you want to maintain.

> Well, you're a structural engineer. MR. CANTELA:

FEMALE VOICE: We don't want to knock down --

MR. CARCATERRA: From the point of view of safety?

That's correct. MR. CANTELA:

MR. CARCATERRA: If you keep the braces in, no. you remove the bracing, it will fall down. So you have two choices. You can keep the wall with these braces or you can spend some money and try to straighten that out, but trying to straighten out a stone wall is not easy because it's brittle. I believe there has been a loss of soil due to

740

07002

ž

PENGAD CO.,

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

down.

MR. CANTELA:

erosion that has caused this distinctive tilt and, you know, it's difficult. MR. CANTELA: Thank you. That's fine. We don't want to take the stone wall MR. JOHNSON:

MR. CARCATERRA: No. As long as it is just properly braced, it will be all right. Twelve shows the opposite end of the building which is not as laterally distorted because of the fact that you have there probably this wall and pier which makes it a little bit stiffer there.

If it's in terms of safety --

And, let's see, number 14. Oh, no. I skipped number 13. Thirteen shows one of these columns which was completely chewed up by rot and decay and somebody put another post behind it supposedly to take its place, but as you'll see further on, they put it in the wrong place and it's not really holding up that beam at all.

Number 14, I believe, shows that. Yes. There you see the two beams which bear on the rotten post and the supposedly good post was put in back of it. All it does is just hold up this brace that was put in, so that's a very precarious situation right there.

Number 15 shows you the amount of twist in the beam and the complete failure of these joints wherever it's supposed to bear upon these posts. There again, it's just

07002 Š 60.

holding on by luck, I think.

3

1

2

Number 16 shows another view of that where the front beam which holds up the edge of the roof is just kind of twisted off the supports and it's most unhealthy.

5

6

4

that I saw in the siding. This was so soft you could take an

Number 17 was a typical example of some rotten wood

7

8 9

10

1.1

12

13

14

15

16

17

18

19

20

21

22 23

24

25

awl and just stick it in and it went all the way through, so that almost all the siding would have to be really checked and just replaced.

Eighteen is the roof and as has been pointed out this is kind of a mixture of old tongue-in-groove material. some areas I could see signs that it looked like it was just decayed.

Number 19. Maybe this will explain why some of the roof seems to have sagged. This is a post and that's the footing that it's sitting on, which is just a piece of cinder block or a piece of wood. Actually, it is not being supported by the dirt. Actually, it is just hanging there.

So, in general, the fact of the decayed roof, the wall members, the lack of an adequate foundation again would require this building be essentially dismantled practically, saving whatever few pieces you can save, but for the most part it would be new members and a rebuilt model.

Now we go to the hog house and number twenty, I think, shows an overall view of that. Right? And the big

11

17

18

19

20

21

22

23

24

25

1 2 3 4 5 to rot. 6 There is some sort of settlement of the roof, but, as 9 10 proper type of foundation. 12 showing this --13 14 15 16

problem with this building is the site, because there is a steep slope that goes towards the right and it goes straight up and for years all the flow of silt and so on has actually flowed underneath the first floor into the crawl space and practically filled it up and caused many of the members there

I'll explain later, from the first floor up, the wood didn't seem to be that decayed, although there would be a major problem in trying to salvage this building by putting in the

Number 21 is another view of it just looking north

MR. CANTELA: What is the proper type of foundation? MR. CARCATERRA: Well, the proper type of foundation would be a concrete footing, you know, a wall footing, a cinder block. It could be a treated lumber, but it would have to be other than what you see right now.

MR. CANTELA: All of those vary considerably in cost, wouldn't they?

> MR. CARCATERRA: They certainly would.

MR. CANTELA I am not sure that I get your point.

MR. CARCATERRA: Well, if you let me continue, maybe it will be self-explanatory. Twenty-two, I believe is similar to a slide that was shown. It's just a view of the

2

3

5

6

. 7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

floor showing extreme state of decay. I believe at the left you'll see a post that is hanging there. It's all decayed there.

Number 23 is a loss of beam support. You can see where that beam has actually pulled away from the post that it was supposed to be bearing on again due to all kinds of lateral movements. Twenty-four is a view of the upper framing --

MR. CANTELA: Lateral movements of what?

MR. CARCATERRA: Of this building due to the overload, due to the proximal vertical settlement of the post which caused it to pull away from the beam. Twenty-four is a view of some of the upper framing above the first floor and that did not seem to be too bad from what I saw in the other areas.

Twenty-five. Now here we go to the severe damage below the first floor and the conditions of framing. Twentyfive shows a beam which is bearing on a big boulder over there. All of these joists on the first floor are all twisted. You can't even say that they're bearing. I would say that the entire first floor down would have to be removed.

Twenty-six, 27, 28 and 29 are all views of this crawl space which show a similar condition. At 27 --

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

MALE VOICE 2: Excuse me. Like the big boulder the beam is resting on, it certainly wasn't built that way, was it? MR. CARCATERRA: I hope not. I mean --MALE VOICE 2: So isn't that all a matter of neglect? I mean -- pointing that out, the fact that it has been allowed to go -- we know that the building is gone. picture 28, there was pillars there, but now they have toppled and -- I guess what I'm getting at, all of this wouldn't have happened just because you left the roof open. If you did it to your house for two or three years, you would have nothing left. It was not poor construction. MR. CARCATERRA: You asked about the rock. That rock is not due to poor maintenance. It was poor design. don't put a --MALE VOICE 2: I doubt that it was designed that way is my point. I don't think anyone built --MR. CARCATERRA: Do you think that somebody just jammed the rock in there to hold it up? MALE VOICE 2: I think the rock was there and this has fallen on it or somebody has put a rock in there to prop

it up at one time. MR. CARCATERRA: It is most unusual, but you have the same thing over here at 26 --

MALE VOICE 2: Thirty-one.

24

20

21

22

23

24

25

MR. CARCATERRA: It seems to be just bearing on the dirt with --

MALE VOICE 2: I mean we were talking about these things being built in 1920. Do you think anybody in 1920 would have built something like that? I would doubt that.

MR. CARCATERRA: Well, I have seen houses that were built by, you know, farmers or local laborers in which you see astounding things. I mean, I don't know.

MALE VOICE 2: But these were well built buildings. I mean this Greenwood is an expensive estate.

MR. CARCATERRA: Well, it doesn't look like it was built as if it were an expensive estate, this particular building. Twenty-seven, I mean, you have these things which have slipped completely off the pier.

Twenty-eight, I mean, you have a brick pier and what looks like a piece of wood blocking just sitting on top of That's not good design. I mean, it's not bolted down or anything.

MALE VOICE 2: My point is it wasn't designed that way, I'm sure. It was never built that way in the beginning.

MR. CARCATERRA: Well, I have no way of knowing. I am just giving my opinion of what I see. Over here at 29, you have a similar situation. See, if you're saying that there may have been something else which failed and then they put a piece of stone in there to take it's place, I mean, I

Ž BAYONNE.

don't know. All I see is that this condition would not be susceptible to any kind of improvement without taking the whole thing out.

Number 30, again a view of the upper framing, which I didn't see any signs of rot. There are a lot of things that have to be braced and tightened up. Thirty-one, again, we have -- here's a good example of -- whoever did it -- and I don't know whether it's the original design or somebody did it -- I mean, there's a stone and then they put in wedges of wood there and the beam sits on top of that and half of the beam is hanging in air.

Similarly, at 32, where you have decayed siding and I don't know what's there, brick, stone, a piece of -- a wedge of wood and then this beam that's probably point bearing on it.

Thirty-three. Another example of decayed siding because that was actually in contact with the ground and the wood behind that was also decayed. Thirty-four, the upper framing, still that looks reasonable in good condition.

Thirty-five. Settlement of the posts, I believe, accounts for that dip that you see all along the beam along the ridge. And 36 is the main culprit in this thing -- the very steep grade which just slopes down right to this place and all the silt and God-knows-what has been flowing into this thing.

1 2 3

And I might mention here that if an attempt was made to rebuild the building, there were two elements that would be very expensive. One would be the fact that you would have to shore up the building essentially from the first floor up and brace the roof and the sides, the walls and everything, while you removed the first floor down and put in new footings, new framings to the first floor and so on.

You also would have to get rid of this site problem, which I don't believe is covered in the -- that I saw, where you would either have to put a retaining wall, you would have to have some kind of a terrace, swales --

MR. CANTELA: In your expert opinion, how long has this wash been occurring?

MR. CARCATERRA: Ever since it was built. I mean, it doesn't look like this is filled ground. I mean, this is the kind of natural grade, I would think.

MR. CANTELA: So you don't believe this is a result of the change in erosion patterns from the new construction at the top of the hill?

MR. CARCATERRA: No. No, no. This looked like it was the old ground. It was the hill. There was a hill --

MR. CANTELA: Oh, it's always going to be the old ground. I just wanted to know if you believe this had occurred recently or has occurred --

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. CARCATERRA: No. This has been going on for No. quite awhile.

> MR. CANTELA: How long would you say?

MR. CARCATERRA: Decades.

MR. CANTELA: Thank you.

MR. CARCATERRA: I mean, you know, in that range. Thirty-seven again is a view of the roof framing and here, again, you would see that if you're going to hold things up, you'd have to really put all kinds of ties because these walls come up higher than the floor, so you've got kind of a thrust of these roof rafters which might be okay just the way it is right now, but if you try to move the building around and hold it up, you had better put some ties across here to brace it together while you're doing that.

And 38, 39 are just exterior views of the same building. So, in essence, as I say, all of the framing and the foundations below the first floor must be rebuilt. side grading should be revised to add a retaining wall to prevent further soil erosion.

The upper portion of the framing is in fair condition, but would have to be shored and braced while the new foundation is being installed. So, economically, this may not be very feasible. It might cost quite a bit of money even if you could save the upper portion. And then we go to the final --

ž BAYONNE.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. CANTELA: In the interests of time, can I say that the last one is pretty self-explanatory? MR. CARCATERRA: Yes. I don't think I have to comment on it. MR. CANTELA: I don't think we have to --MR. CARCATERRA: Right. MR. CANTELA: Thank you. In the interests of time, too, I will MR. JOHNSON: conclude my remarks and respectfully ask for permission to remove these four outbuildings as they simply do not make any economic or engineering sense to rebuild. I can anticipate that there are going to be additional witnesses who are going to oppose our view and oppose our request. Because I probably will not have an opportunity to cross examine them because the rules probably don't provide for it and because none of us could stand to wait that long anyway, I would respectfully ask someone on the Commission to propose to those people who demand restoration the means by which it would be paid for. And, with that, I'll close. MR. CANTELA: May I ask one question --MR. JOHNSON: Surely. -- of your previous witness? MR. CANTELA:

MR. JOHNSON: Yes.

When you talked about restoration, MR. CANTELA: mentioned that it could not be stabilized either and the cost

1 estimates are for restoration, not stabilization. 2 opinion, are there any of these buildings that could be 3 stabilized at a reasonable cost? 4 MR. CARCATERRA: No. Because the actual structure of 5 them is in such an advanced stage of decay that I don't see any way that you could do something to hold it in place 6 7 without removing a large portion of what's there and putting 8 in new material. MR. CANTELA: And yet, the wall could be held up by 9 those braces. 10 MR. CARCATERRA: Yes and --11 And wood is a far more --MR. CANTELA: 12 -- wall. MR. CARCATERRA: 13 MR. CANTELA: Wood is a far more flexible material 14 than the stone wall and you are telling me that you could not 15 brace up to stabilize any of the wooden buildings. 16 MR. CARCATERRA: No, because the wall, the stone 17 wall, is not decayed. 18 MR. CANTELA: I'm asking about the wood. 19 The wood is in --MR. CARCATERRA: 20 MR. CANTELA: Okay. Thank you. 21 MR. JOHNSON: Thank you. 22 MALE VOICE 1: Thank you, Mr. Johnson. 23 point, we'd like to hear from other interested parties. 24

Anyone like to speak?

25

740

10/89

MR. BECRAFT: Good evening, Commissioners. I realized it's late and I'll try to be as brief as I can. My name is Leonard Becraft. My address is 1564 Santini Road, Burtonsville, Maryland 20866.

I had lived in Greenwood Mansion there for a period of 10 years from 1970 to 1980. The property was owned by my great-grandparents and my grandparents and my mother from the period of 1926 through to 1980 when it was sold to a supposed historian that was going to take care, and maintain, and preserve, and had all good intentions.

The situation starting off with going back to the dictionary that preservation -- and this is what I'm speaking on before the Commission -- the Historic Preservation

Commission -- I find it says there to keep it safe, guard, protect, to keep from decaying and maintained.

Nowhere do I see demolition, or destroyed, or knocked down, or bulldozed, or what-have-you. The situation there developed with the prior owner, the same as apparently with the present owner, from the presentation, that concentration was going to be made on the main homeplace.

Well, in living at the property in the '70s, I had the opportunity to be there firsthand in this case with Mr. Mike Dwyer. He toured the property, he made notes, he took pictures with our approval, and he gave us the assurance there that the family would be protected under this

69/0



ordinance; that there would be preservation of this estate.

I have a picture. I realize you have the decayed situation here by the year almost 1990, roughly ten years later. This aerial picture I took myself and this was in a farming state up through 1980. All of you are welcome to look at it.

The buildings are stable. The surrounding property was used. The corn crib was loaded with corn come fall. The buildings, the roofs and so forth were solid. You can see my Herefords here that were close by and my main point with this picture that with the conditions of the buildings now, that there has been actions not only with the prior owner, but with the present owner that concerns the situation with asking for more demolition.

That the chicken house has been removed. The wall around the back of the barn has been removed. The situation was no attempt whatsoever to stabilize on the building that had a weak front timber and that was continued for a two-year period here to go and eventually hear it collapsed in this recent time.

So the point being that several of these buildings have already been eliminated. And there was also a chicken house up here that has gone since this picture was taken. So these are outbuildings of this operating plantation under the Davis family member and they had been here for five

-

PENGAD CO..

generations and are buried right here next to this stone wall and next to this barn and 14 acres that was set aside for this historic preservation.

There has been a lot of comments on buildings and information that's erroneous and in that way by thought of what was used and was not used that I have written documents, there in 1930 with individual -- that the Davis family had owned it up through 1906.

They had their head caretaker, David Craver, work for them from 1886 to 1906 when he bought the property and David Craver carried this from 1906 to 1926, a period of 20 years, under his own ownership and then sold it to my great-grandparents in 1926.

So, the farming operation was continued there in different stages and on any farm there's going to be changes made. This oxen shed that was questioned about the two stone columns in the back and this building was enclosed in the front with doorways, had individual stalls everywhere they kept these oxen.

And in this write-up done by Mr. Roger Brooke

Farquhar that did the historical book, he did this from Lafe

Dwyer. They were in the hospital in Montgomery General at

the time and he recorded his notes on the description of the

Greenwood property.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

He had 10 to 15 yoke of oxen that he operated this farm with and then he had stalls there where they were maintained in the wintertime close to this barn operation that was built roughly in the 1883 period.

Following that, when the Craver family took possession of it, they raised a good many sheep and they used those stalls for sheep-raising. Well after that time period, it deteriorated and there has been work done on it as far as the roof line and the actual outside of the building being reworked in about 1930 when my great-grandmother was alive and it was reconstructed.

The situation with the corn house, the picture i have, it's built on stone column and that poor engineering or poor whatever that it has withstood winds of 70 miles an hour coming across from the west and other violent storms, so it maintained itself. If it had had a little bit of help, it would have still been standing.

The hog house had been used by myself, personally, I raised hogs in there. I had two or three sows up through this 1980 when we had the auction. I can get a documentation of our auction sale handbill when I sold the two sows there at the auction with piglets coming on.

Ground level was there so that they could enter in and go back and forth into the building. It was used for that purpose up through that point in time. The situation

07002 ž BAYONNE.

with the drainage, there has been drainage down through that section around the barn ever since it was constructed.

There is no way that this water off of the main hill here -- unless there is a groove in front of it -- terracing -- that's going to eliminate that. But this building had been used and it's still structurally solid and the loafing shed behind of it also was built with columns on stone thereagain.

The front posts which were torn down here in this last two-year period were maintaining that entire roof line. That also protects this stone wall. And most, I am not sure, are familiar with this, but the stone wall behind the oxen shed, that roof line is draining off of the stone wall, so it's helping -- even though it's leaning, it's protecting the water drainage from that.

The blacksmith's shop that's in the sequence of disrepair has been in that state for quite some time, but there was a chimney on the back side there and was used with a small unit there for shoeing the horses close to the main mansion. The main blacksmith shop was down by the river there across from the mill which was right next to 97, so it was used. It was a portion of this home/estate.

The butchering prior owner, with the two slave cabins that were there -- and they've added occupancy into a structure that had the stone floors -- added a whole unit

3AYONNE, N.J. 07002 FORM 740

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

onto it and changed the front door to the back. All of those complexes -- the ice well -- all of those buildings, there has not been one stitch of paint put on them, no maintenance that can be seen from the road there of stabilizing.

The situation with the coach house, it has been nearly a year that the entire back has been torn off of it and it started with boarding up and there was a sliding set of doors on the back of that. There's no indication that this was being restored in the pattern in which that building was constructed for -- this particular part.

I realize that we're here -- again, I'm confused. The situation in January, the owner did not see fit to come before the Commission to present this case. I'm not sure why. But at that time there I understood that the council voted to not allow demolition of these buildings and since that time they were continued to be let go and they have fallen into greater disrepair and continuing collapse.

So I'm not sure if we're opening up a complete new issue here of going back strictly on the four buildings at this point in time and oppose -- or not even considering by staff's recommendation or their evaluation of the main barn, which in your pictures -- it would take time in going back -we can point to each one of these.

The front roof of that barn, which is a rampway into the barn there that has log structures supporting that.

FORM ž

2

5

6

7

8

9

10

11

12

13

14

15

16

17

18

a unique type barn. It's a three-stage barn with a grain storage in the middle. That roof has not been repaired. new owners painted the new part and the aluminum quonset hut part, but did not stabilize that front part or either end of the barn.

And with these 70 mile per hour winds -- this is an open structure that would hold 10,000 bales of hay in that building -- and the stabilization of it is continuing to cause it and that's one other reason that I'm coming before the Commission -- that time is drawing late, that this building here is the most important part -- the barn.

And that way if this wind is allowed to continue, it will be collapsed and it will be among the missing portions of this Greenwood Estate. And I feel that in two years of time there that the situation I wanted to make known is that the present owners were made aware by the realtor that this had a citation on it -- demolition by neglect.

That the owner was supposed to have been fixing these same buildings at that point five years ago, was not finalized, and the new owner was made aware that this situation existed for their considering that in their purchase to be aware that they would be responsible to maintain and to preserve these structures along with the main homeplace, or to stabilize them, or to paint them, or to do some roof work, even if they didn't rebuild them.

10/89

19

20

21

22 23

24

So, I've more or less closed my case for the situation to the Commission that if all of Greenwood collapses down, I leave it on your shoulders that being the judge or decider of whether the engineering work and the cost effectiveness of it should be a matter to the new owners when they knew about it in trying to preserve this estate.

Which, I throw out a challenge to them that there be a loan, a low interest loan, to preserve all of these structures in some fashion. And I can't see why that they have barn raisings in Pennsylvania where they have Dutch construction barn raisers that I'm sure would be happy to come down here and amass if they knew the story and put this thing together, even if they've using new timbers where there's termites and where there's rot, and where there has been erosion, and whether there has been things.

That these things can be worked on and a loan be worked on for that particular part. And also, I have personally prepared the material on this estate to Annapolis to the State of Maryland to put it on the National Register and I feel that the new owners should be, if they're concerned as they are, to put it on the National Register and all they have to do, which I was not able to do, is have the boundaries.

At the time, my family would not permit the entire 300 acres. There was mention of how many acres it was down

68/0

3

4

5

6

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Originally, my grandparents had 354 acres. It went down to 257 acres and that's 257 acres both sides of Route 97 that was included in this estate and my grandparents -- passing on in 1966 and my grandmother there about 1968, I believe it was.

So that there was more acreage than the figures that have been used and the dates of these constructions in my historical material -- I did 10 years of extensive research on this place while I lived there. I gathered as many pictures as I could. I contacted as many old people that I could.

I have the weakness now that they have all departed us and that they are not here to forward their information on to the Commission. The last of the Craver family passed on this past year, Mr. Howard Craver. All of the Davis family members, the story behind it and the history that they had six children with no male descendants, so Mr. Allen Bowie Davis, who was prominent in this state, passed on 100 years ago this particular year in 1889.

As I was mowing the cemetery there and the gravestone there is April something of 1889, so 100 years ago of his refusing to be buried in Baltimore where he also had an estate, but to be brought back here with Ephraim Davis' grandfather, Thomas Davis, and --

MALE VOICE 1: -- can we again keep it to the --

740 Z BAYONNE,

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. BECRAFT:

Okay. Okay. So that way of trying to get it to the National Register and also there if the Commission can help the owners in finances, the buildings should still not be wiped out with a bulldozer as several of these places have been worked on since the new owners have taken and that particular part stabilized as best they can and maintained without totally destroying them or going through this process of saying they're not worth restoring.

And, also, if the Commission sees fit to allow the demolition, that foundations of these buildings be maintained and not be allowed to be bulldozed out and build other modernistic type buildings in this complex. Thank you.

FEMALE VOICE 1: May I ask a question?

MR. BECRAFT: You have a question?

FEMALE VOICE 1: At what point in time did this stop being a working farm?

> MR. BECRAFT: 1980.

FEMALE VOICE 1: And at what point in time was it reduced to 14 acres?

The date he spoke of there, 19 -- it MR. BECRAFT: The subdivision there was being worked on in was not '78. that time period and that particular subdivision -- original subdivision plat there may have been worked on in 1978, but the final part of its sale to Mr. Frankel was in 1980, so that the subdivided part could have been 14 acres brought

740 07002 ž BAYONNE.

21

22

23

24

25

down to that point. But it was originally offered for 11 acres and the family was going to divide it there into a five acre parcel with the homestead and six acres with the barn. So there was going to be 11 acres they offered to me for sale and Mr. Frankel came along and they offered to him a different --FEMALE VOICE 1: I am not too sure of the relevance of that right now. MR. BECRAFT: Okay. So I'm just giving you the particulars here. FEMALE VOICE 1: No, no, no. That's fine. Thank you. MR. BECRAFT: The subdivision process could have been as early as '78 there, but the sale and all --MR. CANTELA: And the answer is -- do I understand you correctly -- is too small to run as a farm? That you cannot operate any farming activities on that property? MR. JOHNSON: There's no real tillable land and the county prevents you from raising any animals on it. FEMALE VOICE 1: Why?

FEMALE VOICE: It's a covenant of the development --

MR. BECRAFT: And this is wrong. This is definitely wrong, because there is no --

MR. CANTELA: It's a County regulation. Thank you.

10/89

O7/ EX

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. BECRAFT: This is not on the 14 acres. the rest of the farm and not on those particular 14 acres -and there is land --MR. CANTELA: You could have the kennels --MS. VREDENBURGH: What? MR. CANTELA: You could have the kennels. MS. VREDENBURGH: I have one dog. MR. CANTELA: I said you could operate a kennel. MS. VREDENBURGH: Oh, no, I could not --MR. BECRAFT: I worked on the same portion that I rented and I did not rent the whole farm. I had less than 14 I had four cows and I had the pigs. I also had raised sweet corn there behind the blacksmith's shop in that triangle and there was also field corn raised between the spring and the main house. So there is feasible land that can be worked and there's land above the corn house that's also tillable there on that hillside. MALE VOICE 1: Okay. Thank you. MR. BECRAFT: Any more questions? MALE VOICE 1: Maybe that will do it. there anyone else in the general public --

MS. BECRAFT: Can I just -- okay. My name is Betty Becraft and I live at 1564 Santini Road in Burtonsville. just like to say that I hope that the present owner could see what the neighbors and the public could see at the time of

3

4

5

6

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

the sale.

A lot of work and repairs, true, needed to be done and being told by the realtor that it was put on hold didn't mean that nothing would be done for two years. Nothing had been done to stabilize the corn crib, the oxen shed, the hog house or the blacksmith shop.

True, the longer you let things slide the worse they That's why I'm concerned about the other outbuildings having such a small amount accomplished over a period of two I hope she's sincere in expressing her feelings years. through Mr. Johnson for the heritage of our future generations.

If these buildings are allowed to be razed or torn down or whatever, I'm concerned about the wall that they want I'm not really sure about how they plan on stabilizing a stone wall with wood supports. up there now, I believe.

And I'm not so sure that there shouldn't be some kind of a cover over it to keep runoff or to keep freezing weather -- you know water gets in the stone and it freezes and it will deteriorate -- then the wall will be gone.

When we lived there, we had 11 buildings. Two are gone. Four are being requested to be gone. If we permit the razing, will there be any of the buildings left or if the neglect continues will there be any buildings left? It's

you.

3

4

5

6

7

8

9 10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

just some questions I'd like you all to think about.

MALE VOICE 1: Thank you.

I'm just going to take a moment of your MR. CRISTAL: I'm Ted Cristal, 3221 Goldmine Road, Brookeville, Maryland. Myself and my family spent many a fun time at Greenwood with the Becrafts. All I want to say is that if this is, in fact, as you have stated, one of the oldest historical properties in Maryland, then, by golly, I don't think anything else should be razed. I think it should be fixed or stabilized and let it go at that.

I don't think it should be razed. It has to be fixed. Something should be done to keep it the way it is or to make it better, but not to just let it disappear. would be a crime. Thank you.

MALE VOICE 1: Anyone else?

MR. CANTELA: In the period in which you have owned the property, have you sought any loans or grants from the Maryland Trust or any other agency that would supply these loans for grants?

MS. VREDENBURGH: No, I haven't. I never heard of it before.

> MR. CANTELA: Are you aware that any of these exist? MS. VREDENBURGH: No.

MR. CANTELA: Are you aware that Oak Grove Designs

MR. CANTELA: I guess I don't want to scold you, but for someone interested in restoration of a property as important as this one, I guess I'm a bit surprised --

MS. VREDENBURGH: Well, excuse me, sir, but I --

MR. CANTELA: -- that you haven't been interested in

MS. VREDENBURGH: Could I please say something? When I became aware of the enormity of the problem, we all sat down and said, look -- and I think my mother said this point -- what are you going to do first? Now the barn's going to cost this much money. I mean, what is the Historical Commission going to say that I need to do first? If I do this, then I'm in trouble because I haven't done

MR. CANTELA: I just asked if you had

MS. VREDENBURGH: I'm extremely upset because I'm extremely interested in restoring Greenwood and I'm being treated like I'm some kind of criminal.

MR. CANTELA: No, I'm not. I'm asking if you had done that. I'm surprised that you hadn't.

25

24

22

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

I don't

740

MALE VOICE: But how could she learn of Maryland Oak Grove Design's Hank Handler was at the house Trust? several times. He never mentioned it. I'm just curious. MR. CANTELA: Well, it seems to me an easy question to ask. MS. VREDENBURGH: What was I supposed to ask him? MR. CANTELA: Ask anyone. Ask the Commission. MS. VREDENBURGH: I mean, ask them what? Excuse me. MR. CANTELA: Well, your attorney raised the issue this evening of would someone please tell my client -- I'll quote as closely as possible -- where the monies might come from to do that kind of work. Am I correct? MR. JOHNSON: I was asking it rhetorically in the context of she doesn't have all of the money that is needed to do this. MR. CANTELA: I just offer a suggestion, ma'am, that there are available -- funds are available. MALE VOICE 2: What has been done since the purchase of the property? FEMALE VOICE: Okay. Talk to my son-in-law. get out there --I have a list. The air conditioning MR. JOHNSON:

and water heater were repaired and replaced in the main house, \$5,000. The barn roof support was repaired at the cost of \$5,000. Siding on the ice house, albeit not

24

25

complete, has cost \$3,000 to date. Carriage house repairs have cost \$2500.

Trash removal. Dr. Frankel, when he ripped out the furnace and the piping system, left it on the property. Trash removal was over \$600. She has repair estimates that you've seen in your package for the main barn of approximately \$23,000, the sum of which are absolutely essential to be done immediately.

MALE VOICE 2: But it has not been done yet.

MR. JOHNSON: Not done yet. Not of the main barn. It has got to be done right away.

MR. CANTELA: Do you have a schedule for doing this work?

MR. JOHNSON: Not yet. Not until we got resolved where the money was supposed to be spent. If we're going to rebuild these four buildings or --

MR. CANTELA: Well, let me ask you, do you have a plan that -- it costs money to raze these as well. Less than the corn crib now, but you still have got to haul it away.

MS. VREDENBUrGH: -- code violation people who kept telling us that we were doing a fine job and keep it up.

I just asked if you had a plan. I MR. CANTELA: would personally, this Commissioner would like to see a plan with your budget and where monies might be raised that might solve the recurring problem that this Commission has had with

2 0

.

the property, not solely with you, but with the previous owner.

And that is the real concern that this was one of the finest collections of farm outbuildings in the county and it is a fine estate and I think this Commission is certainly willing to work with you to achieve your goals, but I think we'd like to see ours achieved, too, and after five years of frustration over this, you have to understand that we feel the same --

MS. VREDENBURGH: I haven't owned the place for five years.

MR. CANTELA: But this Commission has dealt with it for five years. What I would like to see that I think would solve the problem is a plan for stabilization -- for stabilization -- and protection of the existing buildings and in return for that, I am willing to grant an historic area work permit for certain of the structures that you have asked to be demolished, but I will not do that before I see a reasonable plan in which things can be accomplished and that we can run as a check. Then we will avoid, it seems to me, these recurring clashes that we don't like any more than you do.

MALE VOICE 2: How could code enforcement say you're doing a great job, just keep it up, when nothing has been done? I don't understand.

1 2 MR. JOHNSON: 3 nothing has been done. 5 6 7 MR. CANTELA: 8 9 that? 10 11 house. 12 13 MR. CANTELA: 14 15 16 17 terms of stabilizing them. 18 19 20 21 22 23

MS. VREDENBURGH: Well, they did. I think it is unfair to say that MALE VOICE 2: Well, I mean fix the air conditioning and things like that. That has nothing to do with --MS. VREDENBURGH: No, outside work was done. They've started to do things and certainly a good many more than Mr. Frankel did. FEMALE VOICE 1: Did you want to put a time line on MS. VREDENBURGH: You never talked about the ice That has been completely restored under the ground. Do you think that was easy to do? No, ma'am. But, you see, in having a plan for this Commission, we will see what are the priorities, what are the priorities of the buildings that are in good shape to ensure that we can keep them, that is in Is it more important to stabilize than to restore

initially. Are there certain buildings that you don't set a very high priority. Are there things that this Commission would set a high priority on in terms of stabilization.

Once we see that kind of thing, rather than -- but what we do see now is, yes, we're going to work on this, but we'd like to tear these down. Now that's not real positive

740

24

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

in the terms of, well, what are we going to see preserved or what are we going to see stabilized, what are we going to see protected. And I, for one, would feel just more comfortable seeing that kind of plan.

MALE VOICE: I'm sure she would agree to that and -- we thought we were working toward that common goal with the representatives of the enforcement division with whom there has been a good relationship and they've seen the work in progress.

This -- but always there has been this cloud. These four structures that we know are falling down are terribly expensive. You've seen the estimates. We keep -- but you've got to fix those, too. So that cloud -- what do we do, what do we do.

We have to go back to the board, we have to get a demolition permit if we can. It has been going on. So there has been difficulty knowing exactly where do we put the emphasis and that's why we have so much of this.

MR. CANTELA: And from our point of view, you know, just turn it on your head and --

MALE VOICE: We have no objection. We agree to a That's fine. We'd like to work one out with you. schedule.

MR. CANTELA: Okay.

FEMALE VOICE 1: I think perhaps, too, in developing a plan you might seek the assistance of the Maryland

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Historical Trust. They have a very fine technical field circuit staff and could help you -- I'm not saying that they could write the plan for you, but I'm saying that they could probably point you in the direction of folks that could help you put together a plan --How do we do that? Are they local? MALE VOICE: FEMALE VOICE 1: They are located in Annapolis, but they do have a Washington number on Shaw Place. MS. VREDENBURGH: Is it a government program or is it private? FEMALE VOICE 1: The Maryland Historical Trust is state and federal. They're mandated to carry out the federal preservation laws as well as administer the state laws. MR. CANTELA: You could save all those bills for tax credit if this Commission approves them. MS. VREDENBURGH: Ten percent. Right? On the money that you spend. It's not much --FEMALE VOICE 1: It's better than nothing. MR. CANTELA: Straight against your tax -- your tax bill. You'd be surprised how handy that comes in in September. FEMALE VOICE 1: A name to ask for is Mark Edwards. He's the deputy --

MALE VOICE 1: I'm wondering are we going to keep the record open.

MALE VOICE: Well, can we ask one thing? One of the structures, the corn crib, is already on the ground and it's a very unsightly situation.

MR. CANTELA: I'm willing to approve the corn crib on the basis of safety tonight.

MALE VOICE: -- terrible sight -- we keep talking about saving the stone wall. We'd like to get the structure away from that wall if we're going to try and save the wall, because the wall is going to get -- it ought to be -- those are two fallen down eyesores that ought to be towed away.

MR. CANTELA: I'm sorry. Which? The roof of the oxen shed?

MALE VOICE: It comes right on down. I mean, it's just a matter of time, unfortunately, but that's it.

MR. CANTELA: Well, I tell you what I'd like to do.

I would grant the permit for the corn crib. I would like to see a plan for this within 60 days. If I see an acceptable plan, I'm willing to review with the Commission the other three requests, but I think in terms of immediate safety, I do not have a problem with the corn shed.

MS. VREDENBURGH: Who do we work with in connection with setting up the plan. Jared, for instance, or someone like that?

MR. CANTELA: Jared, Mark Edwards at the Trust.

MS. VREDENBURGH: Okay.

--

4

3

5

6

7

8 9

10

11 12

13

14

15

16

17

18

19

20

21

22 23

24

25

MR. CANTELA: And it's what I would call a carrot and the stick there. I'll give you the corn crib, but I want to reserve the others for right now.

MS. VREDENBURGH: May I suggest something? crib is on the ground. There is no putting it back, but I would like to suggest that the as far as the beams, the big beams that -- we may be able to --

FEMALE VOICE 1: -- we're intending --

MR. CANTELA: It's okay.

MALE VOICE 2: Well, I think we'd look very silly here trying to put back any of the buildings that are in this kind of shape, but I think the whole issue here is this thing of demolition or neglect. And I'm not talking about their property.

I'm talking about other properties around the county that would go the same way and if it's not enforced, I mean we're not protecting these old buildings when people don't want to take care of them. It's strictly a voluntary thing is what it has gotten to be and I admit when you look at these pictures you feel ridiculous to say, hey, you've got to put this back. But here again, these buildings 10 years ago were in great shape or in good shape, reasonable shape.

MALE VOICE: I'm sorry, sir, but I don't think that's a fact. If you could see pictures that we've got -- you've got some of the photographs yourself from 1980 --

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MALE VOICE 2: Mr. Becraft is going to --MALE VOICE 1: I'd like to entertain a motion. FEMALE VOICE 1: I think -- yes. Billy, do you want to make it? MR. CANTELA: I'd like to move that the Commission approve an historic area work permit for the removal -- I don't know if -- is necessary -- removal of the corn crib and as a condition of this, that the applicant work with the Commission staff and the Maryland Trust and return to this Commission in 60 days --FEMALE VOICE: A meeting or --

MR. CANTELA: No. Just with staff. He'll pass it around -- with an acceptable plan of stabilization and/or restoration -- but we're interested in stabilization first -of the remaining outbuildings at which time or during which time the Commission will keep the record open on your application for the three other properties and will make a decision at the meeting regarding those properties at the first meeting after the 60 days.

MALE VOICE: I'll second that.

MALE VOICE 1: I has been moved and seconded. further discussion?

MALE VOICE: I have a question. If this gentleman -speaking from the back, I don't think on the record that he has identified his name there and I would appreciate --

740 BATONNE, M.J.

MR. WARNER: My name is Farley Warner. I'm a lawyer, a member of the District of Columbia Bar. I am Mrs. Vredenburgh's counsel, personal counsel.

MALE VOICE 1: Moved and seconded. Any discussion? MR. CANTELA: I don't recall whether the motion was -- no -- it said it was granted from the basis of public safety, on safety reasons, not on --

MALE VOICE 1: Okay. Then the motion -- there being no further discussion and no question, all those in favor please signify by raising their hand. Opposed? Motion carries, six to one.

(End of requested portion of transcript.)

CERTIFICATE

DEPOSITION SERVICES, INC. hereby certifies that the attached pages represent an accurate transcript of the electronic sound recording of the proceedings before the Montgomery County Historic Preservation Commission in the matter of:

FAITH S. VREDENBURGH

21315 GEORGIA AVENUE, BROOKEVILLE, MARYLAND

CASE NO. 23/46-89A

By:

Victoria Macuch, Transcriber

1	HISTORIC PRESERVATION COMMISSION									
2	MONTGOMERY COUNTY, MARYLAND									
3										
4	x									
5	HISTORIC AREA WORK PERMIT OF :									
6	FAITH S. VREDENBURGH : Case No. 23/46-89A 21315 GEORGIA AVENUE :									
7	BROOKEVILLE, MARYLAND :									
8	x									
9										
10	A hearing in the above-entitled matter was held on Thursday,									
11	November 2, 1989, in the Ninth Floor Conference Room of the GBS									
12	Building, located at 51 Monroe Street, Rockville, Maryland									
13	20850, before:									
14										
15										
16										
17										
18										
19										
20										
21										
22										
23										

Deposition Services, Inc.

24

PROCEEDIN

vm

MALE VOICE 1: The first item on the agenda is historic area work permits and number one of that is the second review of application by Faith Vredenburgh for historic area work permit at 21315 Georgia Avenue, Brookeville. It's our case 23/46-89A. Is there any continuing staff report?

MR. COOPER: Do you want me to bring things up to date?

MALE VOICE 1: And the record is still open.

MR. COOPER: What I'm going to do to kick this off is just read back the motion that the Commission made at the August 17th meeting when this was last heard. And if anyone wasn't here at that meeting and want any further explanation, one of you or I will go into that a little bit, but it reads,

"Commissioner Cantela motioned to approve the removal of the corn crib and as a condition of that approval the applicant work with the Commission staff and the Maryland Historic Trust and return to this Commission in 60 days with an acceptable plan of stabilization and/or restoration of the remaining outbuildings during which time the Commission will keep the application on the other three buildings open and deliberate on those three requests for demolition after the 60 days. The motion was made on the basis

of Criterion 24AB4 that the proposal is necessary in order that unsafe conditions or health hazards be remedied. Commissioner Taylor seconded the motion which passed six-one, Commissioner Brenneman in dissent."

Now, as indicated in the material in the packet, since that time the applicant has been working on this so-called report. There was a first draft submitted to staff.

Basically, at that point, I sent that draft back with the applicant with a number of comments on ways that I thought it would be more acceptable to the Commission.

They included some suggestions as to deadlines, inspection dates, more clarity, specificity, all of those kinds of things.

MR. CANTELA: What was the date of the first draft submission?

FEMALE VOICE: October 16th.

MR. CANTELA: Thank you.

MR. COOPER: In any case, the applicant subsequently came back with this draft that appears in the packet and as the former motion indicated, I think there are two points of order tonight.

One would be to look at that report. Is it acceptable. And acceptable is an adjective that was used in

24

25

the motion, so I think that's something we need to discuss tonight. And then, secondly, if so or not so, how does that relate to the issuance or no issuance of demolition permits on the other three structures.

Now I also have some more background information on

Now I also have some more background information on those structures, if you feel you need refresher slides and also copies of the Carcaterra engineering report that was submitted.

MR. CANTELA: Is the corn crib still there?

MR. COOPER: It's gone.

MR. CANTELA: Fine. When was it torn down?

MR. COOPER: Well, it's --

MR. CANTELA: When was it torn down? When was it removed?

MR. COOPER: Well, it was down --

MR. CANTELA: When was it removed?

MR. COOPER: I don't know. I didn't remove it. Does anybody in the room know?

FEMALE VOICE 1: Well, it was down --

MR. ABERNETHY: As soon as I got the permit --

MR. CANTELA: When did you get the permit?

MR. ABERNETHY: I don't remember the date --

MR. COOPER: Your point is, I think, that the permit should not have been --

24

25

MR. CANTELA: The permit was contingent upon the approved plan.

> MR. COOPER: That's a good point.

It should not have been issued. MR. CANTELA: was the gentleman who spoke who said he removed it? May I have your name, please?

MR. ABERNETHY: John Abernethy.

MR. CANTELA: Thank you. Relation to the property?

MR. ABERNETHY: I'm Mrs. Vredenburgh's son-in-law.

MR. CANTELA: You removed it personally?

MR. COOPER: Has it actually been removed or not?

MR. ABERNETHY: Except for the timbers that I salvaged.

MR. COOPER: Well, I don't think we need to look at the applicant at this point. I mean, I feel to blame over this because, technically, that's exactly -- I see what you're saying -- that it shouldn't have been removed until this report was approved by the Commission and I told the applicant -- or, basically, the permit was signed off through the office.

MALE VOICE 1: I think that this Commission probably should then certainly be more explicit. I know it did say that.

MR. CANTELA: The Commission can't be any more explicit, Mr. Chairman.

MALE VOICE 1: Then let's deal with this oversight and see how we can deal with it in the future. Mr. Cantela, do you have anything else to ask before we proceed?

MR. CANTELA: No.

MALE VOICE 1: Okay. Continue, Mr. Cooper.

MR. COOPER: No, I had come to a conclusion prior to this, unless you have some other questions.

MALE VOICE 1: No, I don't. Do you have some further --

MR. CANTELA: I thought you said you had slides.

MR. COOPER Oh, yes. I'll show them now if you want to see them.

MALE VOICE 1: Please.

MR. COOPER: All right. Now, these are of the other three outbuildings that were in question. In fact, the applicant had initially or originally applied for demolition for the so-called blacksmith's shop. The setting next to the ice house there on the right and just out of the picture on the left is the carriage house.

Here is the carriage house in the foreground, the blacksmith's shop and the ice house. The applicants are currently working on the rear of the carriage house. Inside

10/89

of the blacksmith's shop.

MR. CANTELA: Could you explain the work on the rear of the carriage house?

MR. COOPER: Oh, yes. Now we're going to go back to it. Well, my understanding is that -- obviously, this doesn't show the rear of it -- but they're replacing some siding back there which is German siding. The applicant is here tonight. Maybe he could explain that further.

The roof structure of the blacksmith's shop. Now this is the second of the other three structures, the oxen shed. The other side of the oxen shed. The stone wall. One end of the oxen shed. The stone wall continues over to the righthand side of the slide there and continues on over and joins up to the stone wall that surrounds the cemetery.

Inside the oxen shed showing the doorway that's I think between the stone wall. Ventilating slot in the stone wall. This is the roof structure and I was describing that a little bit last time. It's what I call boxcar siding.

The third structure in question, the hog shed and it's setting from the barn -- actually the rear of the barn, which is a quonset style with a silo and then there's some of the new construction near the environmental setting, the edge of the environmental setting.

This is the other side of the hog shed. One corner of the hog shed which, I guess, used to be part of the core structure and this is also the side -- this is on the downhill slope side where the applicant and the engineer last time described a runoff problem that was causing some deterioration.

The roof structure. Now just a few quick slides of

The roof structure. Now just a few quick slides of the main house, of course. Some of the small outbuildings that aren't part of the application at this point that are near the farmhouse. The main barn and the main or front elevation -- barn -- the side of it. Ah! This is the ongoing work on the back side of the carriage house.

MR. CANTELA: When was that slide taken?

MR. COOPER: This slide was taken on April 1, 1989.

MR. CANTELA: Ongoing work?

MR. COOPER: Well --

MR. CANTELA: How much is going on?

MR. COOPER: I won't -- I don't know how ongoing it

is, but --

MR. CANTELA: Has it changed anything since --

MR. ABERNETHY: Oh, yes.

MR. COOPER: I believe --

MR. CANTELA: What has happened?

MR. COOPER: I believe there has been some fairly recent --

MR. ABERNETHY: Actually, since yesterday or the day before the siding has been completed -- I've installed a ventilation slot and the roof has been painted and that has all been primed.

MR. CANTELA: Thank you. Just on the one end.

MR. ABERNETHY: Yes. So far, that's all I've gotten to.

MR. CANTELA: Since April.

MR. COOPER: Cemetery. Stone wall around the cemetery.

FEMALE VOICE 1: Phil, I have to admit I was kind of -- to the early part of the discussion. You are concerned that the corn crib has been removed and that that was a condition of the plan --

MR. CANTELA: Of the accepted plan.

FEMALE VOICE 1: Of the accepted plan. I guess my recollection of that meeting was that we did approve the corn crib.

MR. CANTELA: Contingent upon --

FEMALE VOICE 1: Well, I guess it's my -- right.

Contingent upon, but it's my recollection that the corn crib

could come down and that the large timbers would be salvaged

and that we would review the other outbuildings after the . plan had come in.

MR. CANTELA: That's right. But the approval for the corn crib was contingent upon a plan, accepted plan, coming within 60 days. That's what the motion said. There before you is the official record and that's what it was.

FEMALE VOICE 1: Right.

MALE VOICE 1: The corn crib was down at that time. Right?

FEMALE VOICE 1: The corn crib was down and I know one of the discussions was salvaging the large beams.

MALE VOICE: It was partially down like some of the other buildings. Partially.

FEMALE VOICE 1: Yes, but more it was more partially than --

MR. KARR: Okay. So the corn crib was down and now you have got the plan before you.

FEMALE VOICE 1: Right.

MR. KARR: Okay. So I have a question to the applicant, if I may, Mr. Chairman.

MALE VOICE 1: Sure. Go ahead.

MR. KARR: In your correspondence to Mr. Cooper of October 19th you say, "While a fair amount of progress has been made on the small structures and the main barn...,"

10/89

ż

3

2

4

5 6

7

8

9 10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

can you describe some of that progress?

MALE VOICE 1: If you would, again, please state your name for the record.

MR. ABERNETHY: Do I have to sign in? My name is John Abernethy. I am Faith Vredenburgh's son-in-law. I currently reside at 21315 Georgia Avenue. I do a great deal of that work that's on the -- let's say the easier part of the jobs, what I can do. Anything else?

MR. KARR: Can you bring me up to date? When you say that there has been a fair amount of progress to the small -what is this progress? What has been done so far?

MR. ABERNETHY: Well, since we moved in, the first thing we took on was the temporary support in the main barn and the back roof which is something that we considered dangerous, mainly because we didn't want the snow to push it in.

Until we could get around to really doing more of that kind of work in the main barn, get somebody in there to really do a good job, we thought that maybe a temporary support would be good. We thought maybe even that that would be a permanent support, but as it worked out, it wasn't. More in terms of the way it goes now, we should probably consider that a temporary support.

PENGAD CO., BAYONNE, N.J. 07002 FORM 740

That was the first thing we did. Next, we took on the ice house cellar which was -- when we moved in, one side, let's say the west side wall where the foundation had collapsed in. At one point -- I don't know how long ago -- someone had started working on that maybe piling rock up next to the foundation or next to the grade.

We went ahead and had that restacked. We put a beam underneath of it to help support it just in case and then we did the other side which was starting to cave in. And, of course, the work that -- I had a door put on there, some siding repaired on that one.

Some of the window frames were tightened up. I, at that point, anticipated boarding them up, but I plastic covered them at that point and the plastic has naturally gone since then.

But other things that we have done, the siding in the back of the carriage house. I removed a great deal of rotted siding there and went up the whole span on the top to protect that section from moisture this winter or whenever. Just had the roof completely painted. That back structure has been primed. I installed a vent which is more or less authentic as it could be. I took it and matched it from one that came from the corn crib.

PENGAD CO., BAYONNE, N.J. 07002 FORM 740

10/89

23\

There was nothing left of any vents that were in that building to begin with, so I copied something that was relatively the same merit and installed that, as well as other little things that we do that I can't really -- another specific thing -- the stone wall along the road.

I personally reconstructed half of that from an accident that was -- well, a hay baler nailed it and pulled out a good section of the stone. I had to reconstruct it and if you know anything about the traffic pattern on that road, it's pretty busy, so I had to wait until mostly evenings and that's when I do most of my work, between 10:00 and 2:00 in the evenings.

MALE VOICE: The cost of the repair was stated in the last report like the temporary support in the barn was \$5,000. Was that something that you had contracted out or how was that cost --

MR. ABERNETHY: The total included a complete painting of the barn roof and that was contracted out.

That's something I couldn't personally handle alone myself.

Besides, I have a regular job.

MR. TAYLOR: Mr. Chairman, as Jared stated, part of our task tonight is to rule on the adequacy of the preservation plan presented and I don't find the plan complete.

10/89

Ž.

I think I would like to see what has been presented as a list of tasks -- it's unclear from the list presented what we're going to have when we're all done, what the overall program -- the big picture, if you will -- for the Greenwood Acre Farm is.

And I, for one, believe that any preservation plan would begin with a vision, and a statement, and a goal and then would proceed to set forth over a period of time how that goal can be accomplished.

And inasmuch as in the course of the discussions of Greenwood that I have attended several have included issues of the cost of repair, and stabilization and renovation, I think not only should the preservation plan include a vision statement, a full description of what we hope to have when we're done, a series of work programs broken out yearly by task, but also some sort of budget proposal and even potentially sources of funds.

picture, it might even talk about where alternate sources or sources of support funds might come from. I think we'd have a better sense that this would really happen if it was more extensive and more thorough. So I tonight, would it come to a vote, would not vote that this be acceptable. Perhaps a good beginning, but I think it needs a great deal more work.

22

23

24

25

FEMALE VOICE 1: Yes. I think we clearly need a better sense of a timetable and the cost estimates for these buildings. Particularly a timetable so that there can be some measurable goals with the preservation efforts at Greenwood.

MALE VOICE 1: I think a clear-cut schedule is in order, along with its --

MALE VOICE: Well, they have a yearly schedule in here.

MALE VOICE 1: Well, I believe that --

FEMALE VOICE 1: I don't think though that --

MALE VOICE 1: Are we saying we need a more detailed schedule?

FEMALE VOICE 1: Well, I would like to feel comfortable that, you know, at six months from now, and a year from now, or 18 months from now, two years from now we'll be able to see progress or a realistic timetable.

I'm not saying it needs to be at six month intervals, but so that there are benchmarks that can be accomplished that are realistic and definable and that there's a cost estimate that is a reasonable estimate and a reasonable --

MALE VOICE: (Inaudible.)

FEMALE VOICE 1: Yes.

BAYONNE,

MR. KARR: One comment I have about it is I notice there is some work identified in the later years -- three, four and five -- that are essentially stabilization efforts and if we wait three or four years to stabilize some items -- in year three you talk about the oxen shed wall, to begin engineering and masonry required to stabilize the wall.

There is one item somewhere in the year five -- I
thought it was year five -- I mean, just thinking out so many
critical things that need to be done further up in the
schedule in year one. Maybe if it's just general
stabilization of all the structures before you worry about
repairing a tin roof in year one.

You know, certain repairs can be pushed off to year five and get the buildings under control in year one because you might not have them by year five. There might be nothing left to stabilize in year three.

MR. ABERNETHY: Most of what I've taken and put into this schedule are things we need to do most to the bigger structures or the stuff that's mostly important. The other stuff I can -- I have a pretty good handle on things. Like the carriage house and the ice house themselves are in pretty good shape.

And since we've done the foundation work on the ice house, I don't see any problem with that as far as, you know,

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

collapsing. A number of other things. As far as roof repairs, a good deal of this will probably go on instantly. I've only put it in the report this way so that in case it doesn't happen instantly, we have a schedule to back it up. MALE VOICE 1: Mr. Cantela? MR. CANTELA: Mr. Cooper, could you refresh the Commission's memory on which structures were under the demolition by neglect citation? MR. COOPER: Not off hand. Let's see. Maybe you need to give me a minute to look through the file here. MR. CANTELA: I don't believe all of the ice house, for example -- I don't believe was under demolition by neglect citation. MR. COOPER: No, I don't think so. FEMALE VOICE 1: No, the hog house was though. MR. CANTELA: Well, the hog house, the oxen shed, the MALE VOICE: (Inaudible.) MR. CANTELA: Well, that's the one I don't remember. carriage house.

FEMALE VOICE 1: No, I don't think it was the house.

MR. CANTELA: The blacksmith's shop.

FEMALE VOICE 1: The blacksmith's shop.

22 23 24

25

MR. CANTELA: The corn crib.

FEMALE VOICE 1: Maybe those were the four.

MR. CANTELA: In a sense, what you're looking at here is that --

MALE VOICE: There's one that has already been taken down.

MR. CANTELA: Down. Right. That collapsed or something. What we have here is a plan that in the first year rids the property of everything this Commission was concerned about, especially Commissioner Brenneman, in the workings of demolition by neglect. There is no concern on the part of the property owner, according to this plan -correct me if I'm wrong -- to work to stabilize or in any way try to save any of those buildings under demolition by neglect. Now, I may be wrong. There may be some that are, so --

FEMALE VOICE 2: For the record, the buildings that were under demolition by neglect were the main barn, the oxen shed, the corn crib, the blacksmith's shop, and the ice house.

The ice house was. Okay. MR. CANTELA: But the carriage house was not. Okay.

> FEMALE VOICE 1: And the hog house wasn't? MR. CANTELA: -- hog house.

24

25

23

FEMALE VOICE 2: Oh.

MR. CANTELA: The hog house I thought was.

It was just for stabilization and MR. ABERNETHY: roof.

MR. CANTELA: So the main barn is one of those where there is concern. So I think that that's an important bit of information for the Commission's consideration.

MR. TAYLOR: Would you read them again, Allison, please?

FEMALE VOICE 2: Yes. And I have something else that might be of some help, too. The main barn, the oxen shed, the corn crib, the blacksmith's shop, and the ice house. there is a letter, dated August 19, 1988, in the record addressed to Mrs. Faith Vredenburgh which lists the code violations and the steps that must be taken to remove the buildings from the demolition by neglect ciation. The hog house is there. I'm sorry.

MR. COOPER: In this letter. Maybe --

FEMALE VOICE: In the letter dated August 19th.

MR. CANTELA: Yes, I think it was.

MR. COOPER: And the coach house and the slave cabin Is that right? All of these were -also.

MR. BRENNEMAN: And I think they called one a loafing shed or something that -- it must be the one that was

98/0

22 23 missing.

FEMALE VOICE 2: Okay.

MR. BRENNEMAN: But there was some confusion, if I remember, if the buildings were named properly.

FEMALE VOICE 2: Yes.

MR. BRENNEMAN: Like I would still question the hog house. I have never seen a hog house with a wood floor in it. Now that doesn't make sense to have hogs where you have -- and maybe this is true --

MR. TAYLOR: But these are Montgomery County pigs.

FEMALE VOICE: Right.

MR. BRENNEMAN: -- but I grew up on a farm and I don't remember seeing hogs on a wood floor.

MR. COOPER: Yes. And also included were the socalled animal loafing shed and the slave cabin, which is one of those small outbuildings right near the house.

MR. CANTELA: Okay. So we've got them all.

MR. COOPER: And the coach house.

MR. KARR: Now the siding work that you've done, that's on the main barn?

MR. ABERNETHY: No, the siding work I've done is on the carriage house.

MR. KARR: Carriage house. Okay.

24

MALE VOICE 1: Then I think that the schedule should really reflect the needs and desires of the code enforcement and the demo by neglect. I think that the priorities should then look at those buildings that we have that. I don't know if this particular -- it looks to me as though the first year is dismantle and remove more than stabilize and fix.

MR. ABERNETHY: Well, there's a great deal of work on the main barn that's --

MALE VOICE 1: No, there is some on the main barn.

MR. ABERNETHY: Well, that's a lot of stuff, yes.

MALE VOICE 1: Don't get me wrong --

MR. CANTELA: Well, I think what my concern would be is that this permit, as you requested here, was to remove the three buildings that you wanted to remove. If you're going to remove those the first year, this Commission has literally no control thereafter over the speed at which you approach this.

Unless you can come up with a penalty that you think would be appropriate for not keeping to the schedule thereafter, I'm sort of reluctant to give away the store before I get paid.

MALE VOICE 1: I think at this point the Commission is probably in somewhat of agreement. I think you see the concerns that we have over the schedule. I don't know --

BAYONNE.

25,

MR. ABERNETHY: I've just tried to lay it out as best I know. I mean, I tried to do it so that I could actually do a good deal of work myself and the stuff that I felt was more important, the bigger jobs, I would have folks come in and do. And I listed them here as more or less in my priorities so that they would be done and out of the way since they were big jobs.

MALE VOICE 1: No, that's fine. I understand, but you can see the concerns of the Commission. At that point then we leave -- can we leave the record open --

MR. KARR: I have one other question. Since the last meeting back in August, have you or Mrs. -- I'm not even going to try to pronounce it --

FEMALE VOICE: Vredenburgh.

MR. KARR: Have you sought any loan assistance programs?

MR. ABERNETHY: We spoke with and met with representatives from the State Historic Trust to get ideas on the easements and he walked around with me and -- well, us -- we spent about five hours with him walking around and discussing things. And at this point, I've expected to hear something from him. I think he said he was going to go ahead and start something on --

FEMALE VOICE 1: Was this Ron Andrews?

MR. ABERNETHY: Father, you may remember his name. don't remember it. FEMALE VOICE 1: Bill Penzer? MR. ABERNETHY: He came in replacement of someone. MALE VOICE: Mark? FEMALE VOICE 1: Mark Edwards. MALE VOICE: Mark Edwards. FEMALE VOICE 1: Okay. MR. ABERNETHY: He was a very nice fellow. We, at length, discussed all of the problems on the property. MR. KARR: But as far as pursuing any loan or grant program --FEMALE VOICE 1: They have it. I mean, they have both loan and grant monies. I'm not too sure specifically what the guidelines are or the --MR. CANTELA: They, being the Trust. FEMALE VOICE 1: They, being the Trust. MR. KARR: Right. FEMALE VOICE 1: Yes --MR. KARR: We know they have it. I'm questioning whether you are investigating or have you made application for that. MR. ABERNETHY: At this point, I am not really sure. He was supposed to look and get back to us with some kind of

idea	of	what	the	whole	proper	cty	the	whole	thing	would
invol	.ve,	but	I ha	ven't	heard	from	him.			

MR. KARR: Have you made an attempt to follow up with him?

MR. ABERNETHY: My only concern at this point was to get something together for this report that I put together.

MR. KARR: This is November. We have August, September, October --

MR. CANTELA: Jared, do you think you could talk to Mark and express the Commission's deep concern about this property and that help from the Trust would really be --

MR. COOPER: We have talked about it, but not actively about this, but I will again, yes.

MR. CANTELA: Okay. Thank you.

FEMALE VOICE 1: I'm pleased that he went out and spent that much time.

MALE VOICE 1: Please do. And I think that --

MALE VOICE 1: I believe that Commissioner Karr's point is that have you some working idea of that perhaps there is something that you might include that might help you to formulate some of the other plans if you think there is something forthcoming -- to help you with that or to see if there is some assistance --

68/0

PENGAD CO., BAYONNE, N.J. 07002

· 7

MR. ABERNETHY: At this point, we still haven't been able to get complete ideas of what the total costs are for some of these projects.

MALE VOICE 1: Understood.

MR. ABERNETHY: That's why we haven't been able to -I talked with someone this evening -- or last Monday and I
was supposed to get back with him this evening about -- it
was a totally separate company who was a full service company
and whose name I got from Jared that I asked for to help with
some of these problems. So I did make -- and Jared did give
me a list of five or six names.

MALE VOICE 1: I'm saying, but when we follow through with this, then perhaps you will have a better idea the next time you come before this Commission.

MR. TAYLOR: I think a good, clear plan for this site, I think is important, not only for the site, but as perhaps a precedent setter for the way the Commission can deal with this. And this certainly isn't the only one. It's just the one that seems to be before us.

Is there any mechanism within the purview of the Commission where the Commission can more actively assist in the development of the plan? Is there money somewhere to help pay a consultant to work with a property owner for this?

1 MALE VOICE 1: Oh, there are seed grants, but I don't 2 know --3 MR. TAYLOR: It seems to me that --4 MALE VOICE 1: -- for renovation. It's generally for 5 architectural --6 MR. TAYLOR: Well, I mean, it seems to me that --7 FEMALE VOICE 1: To a private property owner? 8 MALE VOICE 1: Yes. Aren't there seed monies --9 MR. TAYLOR: And this is a Master Plan site. Right? 10 FEMALE VOICE 1: Right. Oh, yes. It's also on the 11 National Register. 12 MR. TAYLOR: It's a National Register site. 13 Master Plan site. 14 VOICE: (Inaudible.) 15 FEMALE VOICE 1: Oh, it's on the State Registry? 16 It's State. 17 MR. TAYLOR: I'm sorry. It's a state site. Well, in 18 any case, that's my question to the Commission and to the 19 staff. Also recognizing that I'm also concerned -- the plan 20 is important because it will give us some sense of confidence 21 that this stuff might get accomplished. 22 I think Commissioner Cantela's statement that a plan 23 ought to have some teeth in it to ensure that it get done, by 24

the same token, since it has been represented to us that

.. BAYONNE. N.J. 07002 FORM 740

resources are, of course, critical, I question whether it makes sense to spend a great deal of money on a piece of paper -- you know, for the owner to spend a great deal of money on the development of a plan when that money could well go towards actual work. And, see, that's what I'm grappling with. So, that's why I asked the question.

MR. BRENNEMAN: We could check and see if the money for planning, architectural planning and -- is it just planning? I know it's to plan for septic, well and septic, and architectural -- and see if it might be appropriate to this. That's a good idea, but if it's --

FEMALE VOICE 1: Where is that out of? What department? DHCD?

MALE VOICE 1: Yes. I think especially in the fact that when we looked at it and our motion that the unsafe conditions and health hazards be remedied, that perhaps there might be some aid to help them out as well. So perhaps we can look at that as well when you're questioning Mark and when you're questioning what is available.

Also, then you know the concerns of the Commission.

Not only do we need the big picture as well as a detailed -the things that we discussed this evening.

MR. ABERNETHY: I thought this was as big as I could get it.

10/89

1 MALE VOICE 1: Let's leave the record open and then 2 how is our agenda on the 16th? 3 MR. COOPER: Well, very full at this point. We could 4 certainly fit this in --5 MALE VOICE 1: I would like to wrap this up before 6 another winter goes by. 7 FEMALE VOICE 1: Right. I would second that. 8 MR. COOPER: But I'm not sure -- that's only two 9 weeks from now -- that it's realistic to be able to wrap it 10 up on anyone's part by then. 11 MALE VOICE 1: Okay. 12 MR. CANTELA: I would like to make a couple of other 13 suggestions to you in terms of your letter. You suggest --14 and I think it's a good proposal -- to have somebody assign -15 - to check up and sort of see how things are going. I, 16 frankly, don't believe that a yearly inspection is adequate. 17 I think I would work with a half yearly one, six month 18 inspection. MALE VOICE 1: Perhaps stage it. MR. ABERNETHY: Yes. You see, this is new. You 21 know, I've just tried to do --22 MR. CANTELA: Yes. Okay. But I'd like to make some 23

suggestions. And that it would start -- the first inspection, that we get through one, an initial one, a

19

20

24

PENGAD CO., BAYONNE. N.J.- 01002 FORI

photographic inspection that we might do, so that we can keep a photographic history of the work being done and I think this would be important not only for the Commission, but also for you in terms of tax credits which could become available for this work. No small item.

MR. TAYLOR: There's great public relations potential in this project if it goes right.

MALE VOICE: In what respect?

MR. TAYLOR: Well, it's a place where maybe we can -maybe this site can be reclaimed. You know, there is a
piece of history up there on Georgia Avenue that was cited
for demolition by neglect and through the conscientious
effort of a hamstrung commission and an owner whose heart
sounds like it's in the right place, you know, we can pull
this thing around and in five years have a site that will
last another 100 years and have the main house and a
collection of outbuildings that really do represent a genuine
Montgomery County farmstead.

MR. BRENNEMAN: I guess what bothers me in cases like this, do conditions change? Like you bought the property -- or your mother-in-law bought the property -- knowing that it had to be fixed up and it was under citation at that time.

And I think this goes to any property that's on the Master Plan that needs to be done.

If you know you have to spend that much money, has there been some change in your plan since the beginning?

Towards the beginning did you plan on fixing it up or --

MR. ABERNETHY: We could really only go by the list of violations and what I felt, they were inadequate. They just stabilized some of the structures. They were reasonably unsafe. It just didn't make any sense. That's why we decided to consider how a whole of all the property and the buildings which ones were really fit to restore or keep up. I think that's really where we decided. It took awhile to really get a feeling for what we needed to do.

MR. BRENNEMAN: I guess what I'm saying is, I can see where a family has had a property for years, a family property, and they don't have the funds or the provisions to do it. Then I think that's what the grants are for and that sort of thing -- to fix the property.

But what if someone goes out and buys a property full well knowing they must make plans ahead of time. I mean, if you buy a house and you know that it needs a new roof, you try to know can you put the roof on before you buy the house. That's what I'm wondering.

If your plans have changed or do we expect every master site that comes up someone buys and say, well, you know, I don't have the funds. Can the county kick in or can

2

3

4

5

6

7

8

9

10

11

13

14

15

16

17

18

19

20

21

22

23

12

someone come forward with the funds.

MALE VOICE 1: These funds are available to -- you know, to all that apply. Whether they meet those requirements or up to the individual. I believe that any Master Plan homeowner can apply and we should invite them to apply if they so desire.

I believe the object right now is to stabilize and correct these deficiencies on these citations. I understand your point, but I believe at this point right now I think that whatever we do that we can stabilize these structures.

MR. BRENNEMAN: I agree --

MR. KARR: Well, I think you're making a good point. You know, you can go out there and pick up a beat up old Master Plan house, get some easy money from the county and make a killing on it --

MR. BRENNEMAN: -- the county.

MR. KARR: It's a good point. But on the other hand, that's maybe what the money is there for.

MALE VOICE 1: Well, if the end product is historic preservation, then, you know --

MR. BRENNEMAN: I don't think that would be very good publicity if this happens, we spend county money and we say, hey, you know, I made a hundred grand on this property.

24

PENGAD CO., BAYONNE. N.J.

is that there are various stages of repair, too. I mean, there is restoration, which is the purist form of repairing a property and bringing it back, and then there is rehabilitation and renovation, and then there's stabilization.

And at least this Commissioner certainly would not hold that every building on this property should be brought up to its restored -- kind of in the strictest sense of the word, and that there are various levels of work that need to be done on these properties and restoration may not work for all of them, nor should they work for all of them.

MR. ABERNETHY: I have more or less considered that in my preparation with this. I'd like to try to do a good deal of this myself and in the process, I'm learning a great deal. I'm having a good time doing most of the work. Some of the bigger jobs that are just too big — it's been expressed to us that even stabilization can be attractive, although with the state requirements that it be actually proven that it's not restoration, but it is an added on thing. And I think that we would try to go for the best that we can get. But each project, as you say, has a different approach.

MR. KARR: Back to Commissioner Brenneman's point there. If monies are applied for through this whole plan,

there must be ways to structure contingencies wherein if the property owner sells the property within a certain time period, those monies could be paid back with interest or, you know, there are always mechanisms to create a legal structure on how those monies are used.

MALE VOICE 1: Oh, they generally are that way.

MR. KARR: And if they're not, they should be. Like these monies should not be used to fix up a property that's sold the following year at a profit.

MALE VOICE 1: There are generally no pure grants left. You know, they're generally low interest loans that are to be repaid so the money then can be used again. I think it looks like then the December 7th meeting would be the next opportunity and that will give you a little over a month then to prepare and perhaps we can get some information.

MR. COOPER: I would suggest that I am more than willing to spend some time with the applicant working on this report infusing the various comments from this evening. The point being that between now and December 7th, that may be the best help we get.

Now I will go ahead and examine the possibilities in state assistance for a plan like this or some county funds and if we can get them together and get them approved, you

PENGAO CO., BAYONNE. N.J. 07002 FORM 740

know, maybe we could reimburse the applicant later for expenses if a consultant is brought in.

My point is, I think it's critical that we keep moving on this plan, that we're not sitting there waiting for some funding to come through.

FEMALE VOICE 1: I agree.

MALE VOICE 1: And it has been suggested that some Commissioners would be interested in working along with this project. This is a project that everyone is interested in and we'd like to further this at a rapid pace.

MR. KARR: I don't like volunteering people, but I think that Commissioner Brenneman, with all his good hard experience in some of this, if he can keep an eye on that plan, I think he's probably the best one seated on the Commission to do that.

MALE VOICE 1: I think perhaps we can pencil in some suggestions and things on our drafts and for those as well and you can be in touch with Mr. Cooper and work with you actively, but I don't think we're going to draw it up for you.

MR. ABERNETHY: Well, I was told that I had to -well, not necessarily that I had to -- but it should be
coming from me and I tried to do the best that I could.

MALE VOICE 1: Good.

2

4

5

6

7

8

9

10

11

12

13

14

15

16

17

7th.

FEMALE VOICE 1: Well, I think as Commissioner Taylor said, I think it's good for a start. MALE VOICE 1: Yes. MR. ABERNETHY: Yes. I was quite happy with it. MALE VOICE 1: Any commissioners have any comments about this? FEMALE VOICE 1: So the record is kept open? MALE VOICE 1: It will be kept open -- December 7th should be a time that we're going to aim for. I would really rather not keep this open much longer than that. Why don't we have some weekly targets to work on other drafts as well,

FEMALE VOICE 1: I think that's a good idea.

so that we know we're not just going to continue -- to the

MALE VOICE 1: Why don't we have weekly target dates Perhaps by next Thursday we can get together and we can edit the information that we've gleaned from the Trust and from other things. Proceed that way.

Perhaps you can also then even pencil in what you think that you perceive that this Commission discussed this evening and then we'll go from there. And then other Commissioners might even add to that and then the next week we'll be able to refine that. Is that okay?

23

24

MR. ABERNETHY: In other words, I could work with Jared and bounce it back and forth.

MALE VOICE 1: Yes.

MR. COOPER: Then I'll pass it on --

MALE VOICE 1: And we can pass it on during the week.

Okay? At this point then, we will keep the record open.

Anyone from the general public like to comment on this? Is there any problem? I would like to keep our speakers' time to three minutes. Okay. Mr. Becraft?

MR. BECRAFT: My name is Leonard Becraft, 15640

Santini Road, Burtonsville, Maryland. I don't like to be argumentative with the Commission or with the present owners, but just refreshing some of the points that were brought up on the pictures.

In 60 days here of developing a plan, I'm not sure what the report I heard -- the four structures that were brought up for demolition by neglect. I heard main barn and so forth. I understood them to be the hog house, the corn crib, the oxen shed, and the blacksmith's shop. Four. Those were the ones requested.

Now the others were buildings there to be worked on and stabilized. In the meantime, I'm not sure -- there has been two years that the new owners have had possession of the property, eight years before that that the prior owners had

٠ 5

possession, and not one bit of -- very limited -- of stabilization to these structures. So there has been 10 years that this has been going down.

FEMALE VOICE 1: Mr. Becraft, could you keep your comments directly related to the plan at hand?

MR. BECRAFT: Which? The demolition or the overall?

FEMALE VOICE 1: What we were discussing at this

meeting here, the preservation plan. I think we're aware of
the history of ownership of the property.

MR. BECRAFT: Yes, okay. Just refreshing it. But, anyhow, no work at all in stabilization in this two year period at this point. Now, the separate work there going on in the current structures, there's exterior work and my understanding of historic preservation is that they're supposed to be not done as such.

Now the siding -- the young gentleman here working on these projects -- this is more important than just a part time play thing. The back structure -- all of the materials were taken off. There were three windows on that carriage shed. Now it's completely blocked in there.

The ice shed there has been blocked in with siding.

The sliding doors to that. The situation of the roof being removed from the loafing shed. These particular points there have been taken on without any permits, without any

instruction, any direction, so I just feel that there are several things there that have been worked on that the young gentleman here is building it as he sees fit, not restoring even these that are collapsing. I thank you.

MR. KARR: I find that to be a very interesting comment. Thank you. Well, is that verifiable?

MR. COOPER: Well, I don't know if I should answer part of that. I do know a little about the window being blocked in and my understanding is, in talking to the applicant, that their methodology is -- it's not unheard of -- is to put the siding on -- the framing for the old windows is still there and they go back and cut it out later, which they're -- I obviously don't know if that's going to happen, but that was the explanation to me.

MR. CANTELA: Would that be something you would ask to be included in the plan when you discuss it with him?

MALE VOICE 1: I think it should be treated like any other work on it.

MR. COOPER: Well, it should be put -- basically restored the way it was. I think that's the point. And not a creation of something that --

MR. KARR: Unless the applicant desires to create something different and then propose it through an historic work permit.

FEMALE VOICE 1: Right. As a rehab. MR. COOPER: Yes, that's correct. follow when we --MR. BRENNEMAN: changed and that changed. MALE VOICE 1: (Inaudible.) separate partitions in there. maintained instead of destroyed. MALE VOICE 1: Thank you, Mr. Becraft. public comment?

MR. BRENNEMAN: Don't we need a plan of some sort to FEMALE VOICE 1: Right. And I think that's --I mean, we spend an awful lot of time here looking at plans and saying, hey, you know, we want this MR. BECRAFT: And also I wanted to mention the hog house is a unique structure. Most people say the hoq house is nothing much, but it's a two-story unit that had corn storage in the top, that did have wood flooring in it and had And Allen Bowie Davis raised 100 hogs to feed the slaves and so forth and their own particular use. So this particular structure has been an item that has been there and used in a unique setup and that's why I suggested it be MS. ROSENHEIM: My name is Helene Rosenheim. I'm 23 Past President of the Greater Olney Civic Association. 24 You're probably more familiar with seeing Helene Jennings 25

from our organization. She's our reigning expert on historic preservation, but she couldn't' be here this evening.

Basically, all I wanted to say was that we are very supportive of the efforts of the Commission is showing tonight for trying to help them develop a plan and find economic resources to make it come to fruition.

The community would very much like to see this property restored. It was one of the few that was specifically identified in our Master Plan and so it's one that has long been recognized as one that the community has an interest in.

And we don't know what role the community can play,
but if there is any role that they can play, I think there's
a interest there to do it, both monitored -- not monitored -but through our organization. So if there's any way that we
can assist, we'd be glad to help.

MR. KARR: Have you had direct contact with the property owner?

MS. ROSENHEIM: We haven't been able to reach them yet. Mr. Becraft -- well, now we've made our contact. We did try and locate them, but we weren't able to find an address. GOCA has been involved with other historic properties and we'd like to help in any way we can.

MR. KARR: Maybe they can take you up on that offer.

MS. ROSENHEIM: You know, we haven't done much of this, so we're not sure what role we can play. MR. CANTELA: How good are you with a hammer?

MS. ROSENHEIM: Well, I don't know.

MR. KARR: I was just going to say that.

MALE VOICE 1: Thanks for coming. It was nice for you to share those comments.

MS. ROSENHEIM: Thank you, very much.

MALE VOICE 1: Any other public comment? Okay. I'd like then to keep the record open and conclude this. Again, we'll work on a weekly timetable. Perhaps Thursdays would be the times so that we know this is the week. you, very much.

(End requested portion of transcript.)

CERTIFICATE

DEPOSITION SERVICES, INC. hereby certifies that the attached pages represent an accurate transcript of the electronic sound recording of the proceedings before the Montgomery County Historic Preservation Commission in the matter of:

FAITH S. VREDENBURGH

21315 GEORGIA AVENUE, BROOKEVILLE, MARYLAND

CASE NO. 23/46-89A

By:

Victoria Macuch, Transcriber

D CO. BAYONNE, N.J. 07002 FORM