37/3 7320 Willow Ave. SA 21-87



### **Historic Preservation Commission**

-100 Maryland Avenue, Rockville, Maryland 20850 -279-1327 279-80-7

> 51 Monroe Street, Room 1009 Rockvilee, MD 20650

> > 1713

# APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	201 250 250
NAME OF PROPERTY OWNER HN. Young & Suzanne	
ADDRESS 7320 WILLOW AVA TOKOMA	PK. MD 20912
CITY	STATE 270 COCCE ZIP
CONTRACTÓR REGISTRATI	
PLANS PREPARED BY SUZANNO YOUNG	TELEPHONE NO. 270 8121
DECICE DATION NUMBER	(Include Area Code)
REGISTRATION NUMBER	
LOCATION OF BUILDING/PREMISE	
House Number 7320 Street WILLOW	Avenue
	ection District MONT GOMERY
•	Mer View Ave
and the second s	
Liber Folio 4 O Parcel	(4) Problem of the control of the
1A. TYPE OF PERMIT ACTION: (circle one)	Circle One: A/C Slab Room Addition
Construct (Extend/Add) Alter/Renovate Repair	Porch Deck Fireplace Shed Solar Woodburning Stove,
Wreck/Raze Move Install Revocable Revision	Fence/Wall (complete Section 4). Other 4 10010 2001
1B. CONSTRUCTION COSTS ESTIMATE \$ 50 K	
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTIVE	
1D. INDICATE NAME OF ELECTRIC UTILITY COMPANY POPP	0
1E. IS THIS PROPERTY A HISTORICAL SITE? VO C	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDI	TIONS
2A. TYPE OF SEWAGE DISPOSAL	2B. TYPE OF WATER SUPPLY
01 (*) WSSC 02 ( ) Septic 03 ( ) Other	01 ( 03 ( ) Other
05 ( ) Other	os ( ) one
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
4A. HEIGHTfeetinches 4B. Indicate whether the fence or retaining wall is to be constructed on on	e of the following locations:
1. On party line/Property line	<b>G</b>
2. Entirely on land of owner	
3. On public right of way/easement	(Revocable Letter Required).
I hereby certify that I have the authority to make the foregoing application	n, that the application is correct, and that the construction will comply with
plans approved by all agencies listed and I hereby acknowledge and accept this $% \left( \mathbf{r}\right) =\left( \mathbf{r}\right) $	
	4.0.110 1087
Signature of owner or authorized agent (agent must have signature notarized	an hook)  Page  Pa
** * */* * * * * * * * * * * * * * * *	on back)
APPROVED X as make 1 to chairperson, Historic Prese	prostian Cammissian
$3e^{-\epsilon}$	Trailor Continuation
DISAPPROVED Signature // Leading	Date
APPLICATION/PERMIT NO: SA 21-87	FILING FEE:\$
DATE FILED:	
DATE ISSUED:	
OWNERSHIP CODE:	RECEIPT NO: FEE WAIVED:

Permit approved for: SEE REVERSE SIDE FOR INSTRUCTIONS

1. The demolition of the side sumporch

2. Construction of a new rear addition of per attached plane.


THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION


		•	• /				,
			. :				
				,			
		7					
					-		
						( ) ( ) ( ) ( ) ( ) ( )	
		y : •			•		. e
							,
			-	• •			
	•				14		
 	<u>.</u>						
 			*				3 1 1.5 No. 14

(If more space is needed, attach additional sheets on plain or lined paper to this application)


ATTACH TO THIS APPLICATION (2) COPIES OF SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.

MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE:
HISTORIC PRESERVATION COMMISSION
100 MARYLAND AVENUE
ROCKVILLE, MARYLAND, 20850





nedarid Suzi Young



## Description of Proposed Work:

## Young-7320 Willow

## new closet bathroom.

- \* window at front of addition to be moved from rear Ktchen where it will be replaced by a bay window.
  window on side of addition
- will be a new casement 2'x3'
  clapboard on all of addition
  will be from other places on
  house. We have some at rear
  of house and we have some
  on the inside porch side of
  house. We also have salvaged
  additional clapboard siding in
  recent years.

  tin roof—same as kitchen
  interlocking flat seam. Painted
  - Expresso (Tin-a-Lin brand)
    - colonial cream paint with dinger trim. All the same as the rest of the house.
    - · Brown outlers · Shutters parted Espresso

Porch is now falling, it was not properly constructed, it is not tied into house. It is not insulated, not heated and could not be made a usable room. We have tried for ten years when we do our planned work we will have a much, needed second bathroom and closets that are also needed badly. Rear of house. Master bedroom and family room...

· Viny siding on sides of rear addition. Yno windows on sides because they would just look out on neighbors windows. Vinyl for easy maintance for years to come Beige color

\* three door french type center section opening for each room in rear — six total.

\*Deck to be of pressure

Deck to be of pressure treated lumber. Pine with porch railing all around. Steps on rear to lead out to back yard.

## Lower level

- · framed with vinyl siding in beige color.
  - · olass block window for a maintance free, security window, that gives a lot of light. Thermal double doors that
  - Thermal double doors that open to a coment slab ten feet out and the langth of the house.

Allstate Claim when perch.

Shook - floor cause

orattacher

Claim person the Said

dayprais

### Proposal -

#### **ADRIAN N. BISHOP CONSTRUCTIVE PROBLEM SOLVING**

7406 Jackson Ave. TAKOMA PARK, MD 20912

MHIC 12816

APPEA 15AL (301) 27	70-0086
PROPUSAL SUBMITTED TO  Ned 4 Suzi Journs  STREET  7320 Willow Ave  CITY, STATE AND ZIP CODE  Takoma lark 120112  ARCHITECT  DATE OF PLANS	PHONE 270-8121  JOB NAME  Side porch  JOB LOCATION
7320 Willow Ave	JOB NAME Side Porch
CITY, STATE AND ZIP CODE To be much lark Ald 20112	JOB LOCATION
ARCHITECT DATE OF PLANS	JOB PHONE
We hereby submit specifications and estimates for:	
I have inspected the s	ide porch damage of This
address. The porch is in a seve	re state of collapse, apparently
because of questionable construe	tim design and implementation.
by 6 d vails. The place has	I have and the morely has
pulled awa . The joists the s	apporting the line in floor are not
tied into lang main structurel	members. The josts lean
different directions; the retaini	of well on which the posts
rest is collapsing.	
Siven the now visible con	struction methods used I
strongly recommend dismantling rebuilding the porch, being historic character of the	The existing structure and
lishwir ) of war the	e building
Suit file to the second	1
	Janin Dois
Auto die	
<b>யாழ் #ாழ்ர்க்</b> hereby to furnish materia and labor — o	complete in accordance with above specifications, for the sum of:
Payment to be made as follows:	
All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from above specifica-	Authorized Signature
tions involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Owner to carry fire, tornado and other necessary insurance.	Note: This proposal may be
Our workers are fully covered by Workmen's Compensation Insurance.	withdrawn by us if not accepted within days.
Acceptance of Proposal — The above prices, specifications	
and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.	Signature
Date of Acceptance:	Signature

Application for side addition as shown found to be subtantial alteration - 8/20/87 HIE arts.

#### MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION

#### LOCAL ADVISORY COMMITTEE REVIEW FORM

#### EXTERIOR ALTERATIONS

ı.	Location of property
	a. Located within the Takoma Park historic district.
akak	b. This is a Master Plan/Atlas historic district (circle one).
	c. Address of Property: 7320 Willow Avenue  Takoma Park, MD 20912
	d. Property owner's name, address and phone number:
	H. Ned. & Suzanne Young, 7320 Willow Ave.
*	(h) 270-8121 (w) 270-0086 (contractor, Adrian Bishop)
	e. Is this property a contributing resource within the historic district? Yes $No$
II.	f. On a map of the district locate this property and any adjacent historic resources. Will this work impact other contributing historic resources? Yes X No
	a. Briefly describe proposed work:
	Rear addition: frame, vinyl clad, glass block windows at basement level (only, shallow gable roof (asphalt shingle), to intersect with lower portion of existing Dgambrel roof.
ant 2	Structurally unstable side-front sun porch to be replaced by new side addition reusing original clapboard and 6/6 window from real b. Is this work on the front, rear, or side of the structure?
	Front, side, and rear
764, XA <b>AA</b>	c. Is the work visible from the street? Side addition only: rear addition probably not visible at all.
**************************************	d. What are the materials to be used?  Front: wood clapboard, 6/6 sash wimdow (also wood)  Rear: vinyl siding, glass block windows (sides), asphalt shingles e. Are these materials compatible with existing materials? How? If not. why?
	Side: yes; owner has agreed to use historic materials salvaged from rear + additional salvage clapboard removed from similar

No; vinyl will be difficult to match in color and dimension, glass block windows are out of character with Dutch colonial house style, as is broad, shallow roof . However, since work is not visible from street, integrity of historic streetscape will not be affected. Also, shallow roof makes addit. less visible.

house in neighborhood

#### III. Recommendation of the Local Advisory Committee

a.	Ap	pro	val	of	Wor	k
----	----	-----	-----	----	-----	---

- 1. Which criteria found in the Ordinance for Historic Preservation (Sec. 24A-8-b of the Montgomery County Code) does this work meet?
  - 1 (Rear--does not alter exterior streetfront view)
  - 4 (Side front work urgent safety hazard)
- What conditions, if any, must be met in order for the proposed work to meet the above criteria? (example: the proposed windows should be double hung to conform with existing windows)

Front work to use salvaged historic cladding & window as agreed.

and the second of the second o

o. Property caperis name, adunada and phone awabers

#### b. Disapproval of Work

- 1. On what grounds is disapproval recommended? Refer to Sec. 24A-8.
- 2. How could this proposal be altered so as to be approved?

walls talk the william species perchiters so a tripped to be

TANK TERMINATURE WELLOW, 1947

TANK COST TO THE TRANSPORT RESTORMENT OF THE MERCHANIST

#### IV. Additional comments.

See discussion (attached)

Date on which application received: July	10- 1987
Date of LAC meeting at which application	was reviewed: July 14, 1987
Form completed by: Caroline Alderson	Title: Chairman
Member of: Takoma Park LAC	- Caroline Mldeson
Date: 7/16/87	- Committee of the contract of


#### HOUSE LOCATION SURVEY LOT TO BLOCK 9

IPS COMB AND EARNEST, TRUSTEES ADDITION TO TAKOMA PARK

PLAT BOOK | PLAT 46

MONTGOMERY COUNTY, MO.

Note: Lot corners have not been set by this survey unless stated otherwise.




WILLOW

AVENUE

(50 RIW)

I hereby certify that the location of the existing dings shown hereon is correct as made by a transit-survey Aug 31 1976 There are no encroschmente way across property lines unless otherwise shown.



SMITH TEACHER ASSOC, INC. ENGINEERS . PLANNERS . SURVEYORS 6809 Livingston Road Oxon H111, Md. 20021

