13/10-05A 23310 Frederick Rd Clarksburg Historic District



Date: June 10, 2005

MEMORANDUM

TO:

Robert Hubbard, Director

FROM:

Tania Tully, Senior Planner Historic Preservation Section

SUBJECT:

Historic Area Work Permit #383930

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **Approved with Conditions**.

- 1. Staff must approve any additional work on the historic house that includes anything other than repair or replacement in kind. Major changes may require an additional HAWP.
- 2. All windows and doors on the addition will be wood, true- or simulated-divided light windows.
- 3. Details and specs will be approved by staff.
- 4. Additional work on the historic barn that includes anything other than repair or replacement in kind will require an additional HAWP.
- 5. A tree protection plan prepared by a certified arborist will be implemented prior to any work beginning on the property.

The HPC staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Applicant:

Victor Peeke

PO Box 489, Clarksburg

Property Address:

23310 Frederick Road, Clarksburg

This HAWP approval is subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online at http://permits.emontgomery.org prior to commencement of work and not more than two weeks following completion of work

25

- MS. WILLIAMS: No, just the windows.
- MS. BROWN: All right. Thanks.

pear addition 15 ions

- 3 MS. O'MALLEY: All right. Thank you. The next
- 4 case is case E, 23310 Frederick Road, Clarksburg. Victor
- 5 Peeke.

1

- 6 MS. TULLY: The project at 23310 Frederick Road,
- 7 Clarksburg, is an outstanding resource within the Clarksburg
- 8 Historic District. It's a Queen Anne property, circa 1891
- 9 to 1900. The Commission has actually seen this project
- 10 twice now, on two separate preliminaries, and so what is
- 11 brought forward tonight are the changes based on many of,
- 12 based on all of those discussions.
- I mean, I can certainly show the pictures again,
- 14 if you would like, but I thought that in the interest of
- 15 time, and the fact that you've seen it before, I'd just
- 16 briefly go over the proposal and what staff's recommendation
- 17 is.
- MS. O'MALLEY: That would be fine.
- 19 MS. TULLY: The applicants are going be doing a
- 20 number of things including rehabilitating the exterior of
- 21 the historic house. The do wish to replace the asbestos
- 22 shingle roof with a synthetic slate product. They will be
- 23 adding accessible ramp to the historic house, constructing,
- 24 well, removing a rear addition, and constructing a new one
- 25 and a half story wing or addition, also with a synthetic

- 1 slate roof and fire cement, horizontal siding, wood
- 2 simulated divided light windows, as well as wood details and
- 3 trim. They have done a significant redesign of the driveway
- 4 and parking area that will be fully landscaped.
- 5 The material for the driveway proposed is tar and
- 6 chip, as well as the parking. They are proposing minimal
- 7 addition of sidewalks to the neighbors. And they are
- 8 proposing to remove five trees, based on a certified
- 9 arborist's assessment, which is included in the packet.
- They're also proposing to rehabilitate one of the
- 11 historic, well, the historic barn on the property, including
- 12 removing plywood additions, as well as demolishing the non-
- 13 historic outbuildings that are on the property.
- 14 Staff believes that the applicant has, you know,
- 15 worked very well with the staff and with the Commission's
- 16 suggestions, and we're recommending approval with a number
- 17 of conditions, one being generally that if there is any
- 18 additional work on the historic house, that includes
- 19 anything other than repair or replacement in kind, that
- 20 staff was removing, approved that, so that if something
- 21 comes up during work, but major changes may require an
- 22 additional work permit.
- 23 All of the windows and doors on the addition will
- 24 be wood, true or simulated divided light windows, details,
- 25 and those conditions to be approved by staff. If there is

- 1 any additional work on the historic barn, they will need to
- 2 come forward for an additional HAWP. There is a possible
- 3 future addition, where they might build another shed roof
- 4 condition on the barn.
- 5 And then the final is that the tree protection
- 6 plan be prepared by a certified arborist, that will be
- 7 implemented prior to any work. Do you have any questions?
- 8 MR. ROTENSTEIN: I have one question. Is this the,
- 9 just to jog my own memory, is this the one with the large
- 10 circular driveway we looked at --
- MS. TULLY: Yes. It's come a long way.
- MR. ROTENSTEIN: Yes, it has.
- MS. O'MALLEY: I guess I had a question on circle
- 14 22, the large tree behind the house where it has the big
- 15 circle. Is that one of the ones that will be removed?
- 16 MS. TULLY: Circle?
- MS. O'MALLEY: Circle 22, there is a tree right in
- 18 the middle of the back, between the parking area and the
- 19 addition.
- MS. TULLY: Oh, I'm looking at the wrong one.
- 21 That one? I do believe so. Let me look at -- no, actually,
- 22 it is not. It is not one of those. If you look at circle
- 23 24.
- MS. O'MALLEY: Right, I was one page short.
- MS. TULLY: I would call it little boxes around

tsh 28

1 the ones that the arborist proposed for removal. So that

- 2 would be 117, 102, 103, 112 and 114. 101, which I believe
- 3 is the one you were talking about --
- 4 MS. O'MALLEY: Right.
- 5 MS. TULLY: -- is proposed to remain.
- 6 MS. O'MALLEY: Okay. So the arborist will have
- 7 some kind of tree protection plan?
- 8 MS. TULLY: That's what I have put -- what you are
- 9 seeing is the existing conditions plan. So certainly they,
- 10 yes, we will work carefully with removal of whatever
- 11 materials there, that is fine, as a condition.
- MS. O'MALLEY: Are there any questions for staff?
- 13 Would the applicant like to come up? It's a good thing we
- 14 asked you to come up, there are so many of you. I think
- 15 we're pretty familiar with this project, so maybe you can
- 16 just, if there is anything that differs, that you would like
- 17 to point out?
- 18 MR. TALTAVULL: Sure. Yes, I think most of the
- 19 changes have been on the site. And so Mike Norton from
- 20 Haines Land Design would like to address those.
- MS. O'MALLEY: Okay.
- 22 MR. NORTON: Sure. I'm Mike Norton, again. I
- 23 think that this might be read wrong. This is the arborist's
- 24 report for the trees that are in question. We don't have
- 25 any trees proposed to be removed. This is just his

1 condition, and he said it is a candidate to be removed, if

- 2 that is what we look to do. But we don't propose to remove
- 3 any.
- 4 MR. PEEKE: Yes, I do.
- 5 MR. NORTON: Oh, you do?
- 6 MR. PEEKE: I do.
- 7 MR. NORTON: We do propose to remove some.
- 8 MR. PEEKE: The ones that he recommended.
- 9 MR. NORTON: Okay, I'm sorry, we are. Then I'll
- 10 explain those.
- MS. O'MALLEY: Well, I think now that I'm on the
- 12 right page, I can see where those, where those are.
- MR. NORTON: Right. They're on the outskirts.
- 14 They're pear and white mulberry. They are trees on the Park
- and Planning list of species that can be removed. The 33-
- 16 inch black walnut is proposed to be saved.
- MS. O'MALLEY: Which one?
- 18 MR. NORTON: The black walnut. It sits right back
- 19 there, the 33 --
- MS. O'MALLEY: That's the one in the back?
- MR. NORTON: Yes. That one is proposed to be
- 22 saved.
- 23 MS. O'MALLEY: You'll have to work carefully with
- 24 your asphalt --
- MR. NORTON: Right.

- 1 MS. O'MALLEY: -- in that area.
- 2 MR. NORTON: I have set up, contacted Park and
- 3 Planning, environmental planning section, so we have moved
- 4 forward with that tree protection plan.
- 5 MS. TULLY: Because of the size of the lot, they
- 6 will be, have to, will be required to go through an
- 7 additional review process.
- 8 MS. O'MALLEY: Are there any questions?
- 9 MS. WILLIAMS: Well, one sort of observation.
- 10 Wouldn't it make sense to, since that black walnut is one
- 11 you plan on keeping, and doing what you can to save it,
- 12 wouldn't it make sense to have it in the center of your
- 13 green roundabout thing, instead of on the edge there? I
- 14 mean why don't you extend the driveway over --
- MR. NORTON: Tree 101?
- MS. WILLIAMS: Yes.
- 17 MR. NORTON: Well, actually --
- MS. O'MALLEY: 22 is the one they are going to
- 19 actually -- circle 22 is the one you are actually planning
- 20 to, right?
- MR. NORTON: Excuse me?
- MS. WILLIAMS: I'm sorry. I was looking at the
- 23 wrong map.
- 24 MS. O'MALLEY: She was looking at the --
- MR. NORTON: The asphalt, this tar and chip that

- 1 is near that number 2, is actually on the existing driveway
- 2 that's there right now. So there aren't really impacts.
- 3 That's already been compacted.
- 4 MS. WILLIAMS: Okay.
- MR. NORTON: It's more -- yes, there are no, we
- 6 tried to keep it on the existing as much as possible,
- 7 throughout the whole site.
- 8 MS. O'MALLEY: Any other questions?
- 9 MS. WILLIAMS: I move that we approve the staff
- 10 \(\text{report for case 13/10-05A with the conditions listed in the} \)
- 11 staff report.
- MS. O'MALLEY: Is there a second? Speak up for
- 13 the recorder.
- 14\ MR. BURSTYN: Second.
- MS. O'MALLEY: That's Lee Burstyn. Everybody in
- (16) favor, raise your right hand? Unanimously approved.
- MR. NORTON: Thank you.
- MR. PEEKE: Thank you.
- MS. O'MALLEY: Thanks for working with us so long
- 20 on this. We look forward to seeing it when it's finished.
- MR. NORTON: Thank you.
- MS. O'MALLEY: So the next case that we'll hear is
- 23 3942 Washington Street, case G, staff report, please?
- MS. TULLY: Thank you. The property at 3942
- 25 Washington Street is a primary resource within the



Date: June 10, 2005

MEMORANDUM

TO:

Victor Peeke

23310 Frederick Road, Clarksburg

FROM:

Tania Tully, Senior Planner Historic Preservation Section

SUBJECT:

Historic Area Work Permit Application #383930

Your Historic Area Work Permit application for partial demolition, rear addition and major landscaping was **Approved with Conditions** by the Historic Preservation Commission at its June 8, 2005 meeting.

Prior to applying for a county building permit from the Department of Permitting Services, you must **schedule a meeting** with your assigned staff person to bring your final construction drawings in to the Historic Preservation Office at 1109 Spring Street for stamping. Please note that although your work has been approved by the Historic Preservation Commission, it must also be approved by DPS before work can begin.

When you file for your building permit at DPS, you must take with you stamped drawings and an official approval letter (given at the time of drawing stamping). These forms are proof that the Historic Preservation Commission has reviewed your project. For further information about filing procedures or materials for your county building permit review, please call DPS at 240-777-6370.

If your project changes in any way from the approved plans, either before you apply for your building permit or even after the work has begun, please contact the Historic Preservation Commission staff at 301-563-3400.

Please also note that you must arrange for a field inspection for conformance with your approved HAWP plans. Please inform DPS/Field Services at 240-777-6210 or online at http://permits.emontgomery.org of your anticipated work schedule.

Thank you very much for your patience and good luck with your project!



RETURN TO: DEPARTMENT OF PERMITTING SERVICES
255 ROCKVILLE PIKE. 2nd FLOOR, ROCKVILLE IMD 20850
240777-8370

HISTORIC PRESERVATION COMMISSIO 301/563-3400

18

APPLICATION FOR DEPT. OF PERMITT HISTORIC AREA WORK PERMIT

•	Contact Person: VICTOR PEEKE
	Daytime Phone No.: 301-349-000/
ax Account No.: 00021673	<u> </u>
ame of Property Dwner: VICTOR PEEKE	Daytime Phone No.: 301- 349-0001
ddress: PD BDX 489 L'EARILEISUNG Street Number City	
Street Number City	Staer Zip Code
ontractorr:	Phone No.:
ontractor Registration No.:	······································
gent for Owner: THOMAS TALTAVULL - ARCHITECT	Daytime Phone No.: 301-840-1847
OCATION OF BUILDING/PREMISE	
ouse Number: 23310 Street	FREDERICA ROAD
wn/City: CURICSBURG Nearest Cross Street:	
ot: Block: Subdivision:	
ber: Parcel: 31/	
Talca.	:
ART ONE: TYPE OF PERMIT ACTION AND USE	
A. CHECK ALL APPLICABLE: CHECK ALL	APPLICABLE:
☑ Construct ☐ Extend ☐ Alter/Renovate ☐ A/C ☐	🗆 Slab 🔛 Room Addition 🗀 Porch 🗀 Deck 🗀 Shed
☐ Move ☐ Install ☐ Wreck/Raze ☐ Solar ☐	Fireplace
☐ Revision ☐ Repair ☐ Revocable ☐ Fence/W	/all (complete Section 4) Other:
3. Construction cost estimate: \$ 500,000	
If this is a revision of a previously approved active permit, see Permit #	
ANT THE COMMENT FOR MELLICONOTRICATION AND FUTTING AND INC.	
ART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITION A. Type of sewage disposal: O1 [27] WSSC O2 Septic	
	03 🗀 Other:
3. Type of water supply: 01 🗹 WSSC 02 🗀 Well	03
ART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
A. Heightinches	
Indicate whether the fence or retaining wall is to be constructed on one of the form	ollowing locations:
☐ On party line/property line ☐ Entirely on land of owner	On public right of way/eesement
ereby certify that I have the authority to make the foregoing application, that the a proved by all agencies listed and I hereby acknowledge and accept this to be a co	
	monotiful the issuance of this permit.
Thomas I Witnell	1114 18 2005
Signature of owner or authorized agent	MAY 18, 2005
1.1	
pproved: (CIII) For Chairpe	erson, Historic Preservation Commission
sapproved: Signature:	Palley Date: W/4/05
polication/Permit No. 383930	ad: 5-18-05 Date Instead:

	•	
	.	
•		
	·	

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

a. Description of existing structure(s) and environmental setting, including their historical features and significance:

4E PREPERTY AT 2336 FREDER ROAD, MOLE COMMONLY KNIWN AS HAMMERHILL

A 21/2 STORY FRAME QUEEN ANNE STYLE HOME. IT IS SIGNIFICANT WITH IN THE

4AKSBULG HISTORIC DISTRICT AS ONE OF THE FEW RESIDENCES BUILT AFTER THE TOWN

45 BYPASSED BY THE RALLROAD AND AS A DEPARTURE FROM THE SIMPLER HOUSES

WAS IN THE DISTRICT THE HIGH STYLE RESIDENCE FEATURES A HIPPED ROOF

THE DORMERS ON EVERY ELEVATION, A PROJECTING ENTRY DAY AND A DETAILED

NONT PORCH. THE HOUSE WAS BUILT FOR DR. JAMES & GAMAH DEETS

13ETWEEN 1891-1900.

b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:

VE PROJECT PROPOSES TO RESTORE THE ORIGINAL EXTERIOR, REPLACE THE ASPESTAS

HIMLE ROOF WITH SYNTHETIC SLATE REMOVE THE DETERIORATED REAR ADDITION

LUA CONSTRUCT A 1/2 STORY REAR ADDITION. NEW LANDSCAPING & REDESION OF

THE CIRCUMA ORIVE AND ADD ADDITIONAL PARKING ON THE SIDES REAR. RESTORE.

AND OUTBUILDING AND REMOVE TOLL HOYSE AND SHED OUTBVILDING. THE RESTORATED

OUTDON AND SITE WORK WILL PRESERVE THE SIGNIFICANT RESOURCE, THE OPEN SPACE

2. SITEPLAN IN FRONT AND MAINTAIN THE INTEGRITY OF THE CLARKSITURE

HISTORIC. DISTRICT.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other
 fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the
 front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the percel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

PLEASE PRINT (IN BLUE OR BLACK INK) OR TYPE THIS INFORMATION ON THE FOLLOWING PAGE.
PLEASE STAY WITHIN THE GUIDES OF THE TEMPLATE, AS THIS WILL BE PHOTOCOPIED DIRECTLY ONTO MAILING LABELS.

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 23310 Frederick Road, Clarksburg Meeting Date:

leeting Date: 6/8/2005

Applicant: Victor Peeke **Report Date:** 6/1/2005

(Thomas Taltavull, Architect) **Public Notice:** 5/25/2005

Resource: Outstanding Resource

Clarksburg Historic District Tax Credit: Partial

Review: HAWP Staff: Tania Tully

Case Number: 13/10-05A

PROPOSAL: Partial demolition, rear addition, **RECOMMENDATION:**

and major landscaping Approve with Conditions

RECOMMENDATION:

Staff is recommending approval with the following condition:

- 1. Staff must approve any additional work on the historic house that includes anything other than repair or replacement in kind. Major changes may require an additional HAWP.
- 2. All windows and doors on the addition will be wood, true- or simulated-divided light windows.
- 3. Details and specs will be approved by staff.
- 4. Additional work on the historic barn that includes anything other than repair or replacement in kind will require an additional HAWP.
- 5. A tree protection plan prepared by a certified arborist will be implemented prior to any work beginning on the property.

PROJECT DESCRIPTION

ξ.

SIGNIFICANCE: Outstanding Resource within Clarksburg Historic District

STYLE: Queen Anne DATE: c.1891-1900

The property at 23310 Frederick Road, more commonly known as Hammer Hill, is a 2-½-story frame Queen Anne style house. It is significant within the Clarksburg historic district as one of the few residence built after the town was bypassed by the railroad and also as a departure from the simpler houses found throughout the district. This high-style residence features a hipped-roof with dormers on every elevation, a projecting entry bay, and an elaborately detailed front porch. Built for Dr. James and Mrs. Sarah Deets between 1891 and 1900, the house was likely designed by an architect.

Hammer Hill sits back well off of Frederick Road, roughly in the center of its 3.06 acre lot. The vacant parcel in the upper left corner of the site plan (Circle 7) is outside the historic districts, but is also owned by the Applicant. The site plan also shows the proposed extension of Stringtown Road. The house is

mostly shielded from view by mature trees and vegetation along Frederick Road and will be at a grade significantly higher than the Stringtown Road extension. The open space in front of the house is specifically noted as one of the significant green spaces within the historic district.

Early in the county's history, Clarksburg was a substantial center of commerce and transportation. John Clark surveyed the land and subdivided lots along Frederick Road in the early 1790s, yet the town's origins extended back to the mid-1700s. Michael Dowden built a hotel and tavern about 1754. A popular stop along the well-traveled Great Road between Frederick and Georgetown, Dowden's Ordinary is said to have provided lodging and entertainment for such well-known travelers as General E. Braddock, George Washington, and Andrew Jackson.

John Clark built a general store and became the community's first postmaster. The post office, established 1800, was one of the first in the county. By 1850, the town was the third most populous in the county, and the residents numbered 250 by 1879. As a major stagecoach stop between Frederick and Georgetown, Clarksburg supported several inns and taverns. By the mid-1800s, the town also included general stores, a tannery and blacksmiths, and wheelwrights. In 1879, Clarksburg had 250 residents, making it the third most populous town in the County. The Queen Anne-style house at 23310 Frederick Road, known as Hammer Hill, was built c.1891-1900 by Clarksburg physician Dr. James Deetz and his wife Sarah. The name, Hammer Hill, comes from the tract name given this land in 1752.

Clarksburg has historically been a bi-racial town. While many African Americans settled, after the Civil War, in communities separate from white settlements, freed slaves in Clarksburg built houses in and around the town. Growth in Clarksburg declined in the late 19th century, when the B & O Railroad bypassed the town for nearby Boyds. The advent of the automobile and improved roads brought something of an economic revival beginning in the 1920s. New boarding houses opened in town to accommodate the new auto tourism.

APPLICABLE GUIDELINES:

When reviewing alterations and new construction within the Clarksburg Historic District several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the *Vision of Clarksburg: A Long-Range Preservation Plan (Vision), Montgomery County Code Chapter 24A (Chapter 24A)*, and the *Secretary of the Interior's Standards for Rehabilitation (Standards)*. The pertinent information in these documents is outlined below.

Vision of Clarksburg

The *Vision* makes some of the following statements:

"Managing the preservation and protection of Clarksburg's architectural character and historic pattern...is critical to maintaining its contribution to the County's heritage." "A buffer area, adjacent to the historic district, should allow for the conservation of open space..." "The Clarksburg Historic District is a significant collection of early 19th century residential and commercial architecture along Frederick Road reflecting the town's once prominent role in trade, transportation, and industry in Montgomery County." "[T]he existing historic district [is] the "historic core' of the new town, where the primary goal is to retain, reuse, and preserve the existing resources, while allowing fro an acceptable amount of controlled infill."

Montgomery County Code; Chapter 24A

• A HAWP permit should be issued if the Commission finds that:

- 1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
- 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.

Secretary of the Interior's Standards for Rehabilitation:

- #2 The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, space and spatial relationships that characterize a property will be avoided.
- #9 New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- #10 New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

PROPOSAL:

- Rehabilitate exterior of the historic house
 - o Replace asbestos shingle roof with synthetic slate
- Add an accessible ramp to the historic house (Circle 15)
 - Wood railings
- Construct a new 1½ -story rear addition (Circles 11-15)
 - o Remove deteriorated rear ell addition
 - o Synthetic slate roof
 - o Fiber cement horizontal siding
 - o ½ round metal gutters
 - o Skylights
 - Wood simulated divided light windows
 - Wood details and trim
- Redesign the driveway and add more parking (Circle 22)
 - o Landscape the drive and parking areas (Circle 23)
 - o Tar and chip driveway and parking
 - o Sidewalks of pavers
 - o Remove five trees based on arborist's assessment (Circle 24)
- Rehabilitate historic barn
 - o Remove plywood additions
- Remove non-historic outbuildings (Circle 22)

STAFF DISCUSSION

The Commission reviewed this project as a Preliminary at its March 9, 2005 and April 27, 2005 meetings (transcripts from the April meeting begin on Circle 34). The proposal enclosed is the result of modifications made by the applicant based on comments provided by the Commission at the two prior meetings. On the whole the Commission felt that the proposed addition was appropriate in massing and scale. There was limited discussion of removing the existing rear addition or with the proposed outbuilding removals. The main topic of discussion at each meeting was the landscape plan and the amount of hardscape proposed. At the last meeting the Commission seemed generally accepting of the revised schematic site plan and was anticipating the planting scheme. The applicants also made minor changes to the rear addition as suggested by the Commission.

The proposed addition is consistent with the Preliminary Consultations and staff maintains the belief that the addition is well designed and compatible with the architecture of the historic house. The scale of the addition as seen from the side elevations is appropriately deferential and in staff's opinion, meets the Standards. In summary, the existing rear addition has been significantly altered and is structurally deficient, thus warranting its removal in this case. The outbuildings proposed for removal are not historic and the non-historic portions of the barn will be removed as part of its rehabilitation. Staff applauds the applicant for undertaking rehabilitation of the historic house and for working with staff to maintain its integrity. Work on the historic house will range from structural framing repairs to the roof and termite damaged support post and foundation beam to painting. Some of the proposed work includes installation of a new roof, gutters and downspouts, correcting water drainage, and restoration of the front porch. Staff requests that the Commission remind the applicant of the Montgomery County Historic Preservation Tax Credits that are available.


Staff recommends approval of the HAWP with the a few conditions related to details of the addition and the plans for the barn. Although the documentation provided by the applicant is unclear, conversations with staff indicate that all railings and trim will be wood. Staff is recommending a condition that allows for staff approval of the specific balusters, columns, and other such details that are selected. The current proposal for the barn involves simply removing the plywood additions and rehabilitating the existing structure. The applicant has expressed an interest in adding a new appropriate shed addition to the barn for tractor storage. This would require submittal of a new HAWP application.

STAFF RECOMMENDATION:


Staff recommends that the Commission approve with the above conditions the HAWP application as being consistent with Chapter 24A-8(b);

and with the Secretary of the Interior's Standards for Rehabilitation;


and with the general condition applicable to all Historic Area Work Permits that the applicant will present <u>3 permit sets</u> of drawings to HPC staff for review and stamping prior to submission for permits (if applicable). After issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will arrange for a field inspection by calling the DPS Field Services Office at 240-777-6370 prior to commencement of work <u>and</u> not more than two weeks following completion of work.













MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION REVIEW OF FOREST CONSERVATION EXEMPTION APPLICATION

TO: Michael Norton, Haines Land Design (fax: 301-216-9649)

FROM: Candy Bunnag (phone: 301-495-4543/ fax: 301-495-1303) DATE: 12/27/05

Environmental Planning Division

SUBJECT: Forest Conservation Exemption # 4-06148E, Hammerhill Information Received on 12/1/05

The above-referenced information has been reviewed to determine if it qualifies for an exemption from the forest conservation plan requirements. Staff has the following comments regarding the information that has been submitted:

COMMENTS: 1. Provide a signed and dated statement from the property owner that existing use is residential and that this use will continue with the proposed project.

- 2. Historic preservation staff has indicated that the submitted stormwater management concept plan has several features that are not consistent with the plan approved by the Historic Preservation Commission:
 - a. The driveway appears to be wider than the plans approved by HPC. The driveway should be no more than about 12 feet wide.
 - b. The proposed filling and grading at the front of the property does not appear to be on the HPC-approved plan.
 - c. There are no SWM facilities on the HPC-approved plan.

The SWM concept plan should be revised to be consistent with the HPC approval of the project.

- 3. Submit a tree save plan that is consistent with the HPC approval of the project and shows which large trees (24 inches and greater, dbh) will be removed or protected. Please contact Tanya Tully (301-495-3404), Historic Preservation staff, regarding HPC approval of the project. The following items need to be incorporated into the tree save plan:
 - a. Show proposed grading, limits of disturbance, and tree protection measures.
 - b. Take out areas that are noted as "possible future driveway/parking expansion" since these features have not been approved by HPC.
 - c. The tree save plan, at a minimum, should provide tree protection measures for tree nos. 5, 16, 101, 106, 107, and 109. Check with Historic
 - Preservation staff for additional trees that are required for protection. d. Preservation staff for additional trees that are required for protection. d. Order many of these trees, proposed land disturbance is very close. Limits of disturbance may need to be revised to provide adequate tree protection.
 - e. Special parking lot or walkway construction measures may be needed to protect some of the trees.
 - f. As part of the tree save plan, provide a certified arborist's recommendations on tree protection before, during, and after construction.
 - g. The arborist must sign, stamp, and date the tree save plan.

Please refer to the forest conservation exemption no., given above, on any correspondence or plan revisions related to this application.

Cc: Tanya Tully (fax: 301-563-3412)

for: 1 page




RETURN TO: DEPARTMENT OF PERMITTING SERVICES

255 ROCKVILLE PIKE, 2nd FLOOR, ROCKVILLE, MD 20850

240/777-6370

HISTORIC PRESERVATION COMMISSION 301/563-3400



APPLICATION FOR DEPT. OF PERMITT HISTORIC AREA WORK PERMIT

		•		Contact Person: VICTOR PEEKE
				Daytime Phone No.: 301-349-000/
ax Account No.: _ 4	00021	673		
lame of Property Ow	mer: <u>V/C7</u>	OR PEEKE		Daytime Phone No.: 301- 349 - 0001
address: PO	BOX 48	39 CLAR	KSBUAG	MARYLAND 2087/ Steet Zip Code
	•		•	
Contractor:				Phone No.:
ontractor Registratio				20.000
gent for Owner: Z	HOMAS	TALTAVULL -	- ARCH MECT	Daytime Phone No.: 301-840-1847
CATION OF BUIL	LDING/PREMI	SE		
ouse Number: 2	:3310		Street	FREDERICK ROAD
own/City: <u>CIA</u>	RKSBUR	6	Nearest Cross Street:	STRINGTOWN ROAD
		Subdivision:		
			·	
ART ONE: TYPE		IIVN AND USE	OUEOU ***	ADDITIONAL F.
A. CHECK ALL APP	 -	Alternative and a second		APPLICABLE:
	☐ Extend	☐ Alter/Renovate		Slab Moom Addition Porch Deck S
☐ Move	☐ Install	☐ Wreck/Raze		☐ Fireplace ☐ Woodburning Stove ☐ Single Family
Revision	☐ Repair	☐ Revocable	□ Fence/V	Vali (complete Section 4) Other:
		500,000		
C. If this is a revisio	on of a previously	y approved active permit, s	ee Permit #	
ART TWO: COM	PLETE FOR NE	W CONSTRUCTION AN	ID EXTEND/ADDITI	<u>ons</u>
A. Type of sewage	e disposal:	01 1 WSSC	02 🗌 Septic	03 🗆 Other:
B. Type of water s	supply:	01 🗹 WSSC	02 🗀 Well	03 🗆 Other:
ADT TUBER, COL	CARLETTE CALLY	EOD SENICE/DETAINING	238/ALL	<u> </u>
		FOR FENCE/RETAINING	1 VYALL	
A. Height				
B. Indicate wheth		etaining wall is to be const		
	e/property line	☐ Entirely on la	and of owner	On public right of way/easement

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

a. Description of existing structure(s) and environmental setting, including their historical features and significance:

THE PREPERTY AT 23310 FREDER ROAD, MORE COMMONLY KNOWN AS HAMMERHILL

A 21/2 STORY FRAME QUEEN ANNE STYLE HOME. IT IS SIGNIFICANT WITHIN THE

VARKSQUEE HISTORIC DISTRICT AS ONE OF THE FEW RESIDENCES BUILT AFTER THE TOWN

INS BYPASSED BY THE RALLROAD AND AS A DEPARTURE PROM THE SIMPLER HOUSE'S

FOUND IN THE DISTRICT. THE HIGH STYLE RESIDENCE FEATURES A HIPPED ROOF

11TH WORMERS ON EVERY ELEVATION, A PROJECTING ENTRY BAY AND A DETAILED

"NONT POLCH. THE HOUSE WAS BUILT FOR DR. JAMES & GARAH DEETS

13ETWEEN 1891-1900.

b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district.

THE PROJECT PROPOSES TO RESTORE THE ORIGINAL EXTERIOR, REPLACE THE ASDESTOS SHIMLE ROOF WITH SYNTHETIC SLATE REMOVE THE DETERIORATED REAR ADDITION AND CONSTRUCT A 1/2 STORY REAR ADDITION. NEW LANDERSON OF THE CIRCUMA DRIVE AND ADD ADDITIONAL PARKING ON THE SIDEL REAR. RESTORE AND OUTBUILDING AND REMOVE TOLL HOUSE AND SHED OUTBUILDING. THE RESTORATE ADDITION AND SITE WORK WILL PRESERVE THE SIGNIFICANT RESOURCE, THE OPEN SPACE SITEPLAN IN FRONT AND MAINTAIN THE INTEGRITY OF THE CLARKS BURG HISTORIC. DISTRICT.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred.

- Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other
 fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context.
 All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHDTDGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.


7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY DWNERS

For <u>ALL</u> projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addressas, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

THIS PADE INTENTIONALLY

BLANK

(au) Jolden



1) VA - 1-0 FIL PORCH EL LET CHITTED THE ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERBECATION PRIOR TO CONSTRUCTION. DO NOT SCALE DRAWING NOT FOR CONSTRUCTION Revisions 11.19.2004 EX Drawing Number HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND 2.1 EXISTING FRONT ELEVATION

8


FIL 023,000, 144 FIN. PORCHE NOTE:

ALL DIMENSIONS & RELATIONSHIPS
REQUIRE FINAL FIELD VERIFICATION
PRIOR TO CONSTRUCTION. DO NOT SCALE DRAWING NOT FOR CONSTRUCTION Revisions 11.19.2004 EX Drawing Number HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND SQ SQ EXISTING LEFT SIDE ELEVATION


FILL PORCH BL. 强力级 NOTE


ALL DIMENSIONS & RELATIONSHIPS
REQUIRE FINAL FIELD VERIFICATION
PRIOR TO CONSTRUCTION. NOT FOR CONSTRUCTION DO NOT SCALE DRAWING Revisions 11.19.2004 EX HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND Ŋ EXISTING REAR ELEVATION

(1)












(F)





B







p.2



Keith Pitchford

April 30, 2005

Mr. Victor Peeke P.O. Box 489 Clarksburg, MD 20871

Dear Victor:

This report contains several survey results regarding a select number of trees on your property at 23310 Frederick Road, Clarksburg, Maryland.

In particular, there are tree assessments, appraisals and one hazard tree evaluation. I have maintained the numbering system that was in place at the time of this survey.

I. TREE ASSESSMENTS:

#101 - Black walnut (Juglans nigra). This tree measured 33.5" of diameter at breast height (dbh) and is in good condition. The form on this tree is excellent. The only factor that detracts from an "excellent" condition rating is what appears to be an old lightning strike on the trunk. I do not feel that this will impact the tree in either health or structural integrity. It should receive a crown cleaning treatment and remain in the landscape.

#102 - Common pear (Pyrus communis). This tree measured 17.5" dbh and is in fair to poor condition. There are several defects along the main stem and leaders including significant cavities. There is also tip dieback throughout the small crown that remains. This is an older pear and certainly near the end of its lifespan. I would not recommend investing any monies into keeping this tree healthy. I believe it is a removal candidate.


#103 -- Butternut (Juglans cinerea). This tree measured 16" dbh and is in poor condition. There is very little live crown left on this tree. It is not a preservation candidate and should be removed.

#104 - Butternut. This tree measured 18" dbh and is in good condition. There are some broken limbs in the crown and a prominent basal wound. I do not feel that the basal wound represents a significant defect for this tree. It should receive a crown cleaning treatment and be retained in the landscape.

- #105 Butternut. This tree measured 14.5" dbh and is in good to fair condition. There is a sweep in the main trunk and some minor deadwood in the crown. It would benefit by a crown cleaning operation and should be retained in the landscape.
- #112 Tree-of-heaven (Ailanthus altissima). This tree measured 21" dbh and is in fair to poor condition. There is a very large vine coverage in this tree. However, these are a highly invasive species and should be removed from the landscape.
- #113 Silver maple (Acer saccharimm). This tree measured 22" dbh and is in good to fair condition. A large ivy vine has been cut which should help this tree out tremendously. One lead has broken, but a larger lateral now appears to be asserting dominance. There is also a slight lean in the trunk, but it is self-correcting. This tree should remain in the landscape.
- #114 White mulberry (Morus alba). This tree measured 24" dbh and is in fair to poor condition. There are two stems here of equal diameter. Heavy vines in the canopy have been cut recently which will help this tree. However, it may be too late. One of the main stems has been badly damaged at the base. This is not a preservation candidate and should be removed.
- #115 Sugar maple (Acer saccharum). This tree measured 37" and is in fair condition. There are multiple wounds along the trunk and several large wounds on the root flares. It is obvious that several large limbs have broken out of the crown over the past several years. There is also quite a bit of deadwood in the crown. At the very least, this tree needs to be deadwooded and cabled. I have conducted a hazard tree evaluation on this tree, including resistograph tests. This report is attached here. I am not a supporter of keeping this tree in the landscape. I believe there is too much of a hazard associated with it.
- #116 White mulberry. This tree has two large stems that measured 31.5" and 27" dbh. A third large stem has been removed in the recent past. Some of the cut-up wood from this stem is scattered under this tree. The smaller of the two stems lost its top in the recent past, but it has re-sprouted and appears to be vigorous. The remaining third stem is in better condition. I am not optimistic about the long-term prospects for this tree.

The base of the tree is decaying in many locations and the angle of lean of the stems is considerable (>15%). Even if just the healthiest stem is kept, I do not think it is viable enough to warrant keeping it in the landscape. In my opinion, it is not a preservation candidate and should be removed.

#117 - White mulberry. This tree also has two main stems. One is 26" and the other 20" dbh. The larger of the two stems is in poor condition with the





top dying back. The base of this tree is also highly decayed and weak. I do not feel that this is a preservation candidate. I believe that it should be removed.

II HAZARD TREE EVALUATION:

#115 - Sugar maple.


This tree was evaluated for structural stability in both the main trunk and root flares. The resistograph machine was used in these tests. A total of nine (9) tests were made into the tree. Five (5) of these were made into the root flares and four (4) were made into the main trunk. A diagram of the test locations is attached.

The results of these tests were rather interesting in that they were completely opposite of what I would have expected. I have enclosed a reduced copy of the resistograph tests and included all of them on one page.

Tests #1-5 on the enclosed are from the root flares. The pattern for all of these tests is encouraging in that the amplitude of the graph increases as the needle penetrates the wood. It is apparent that the differentiation of the spike marks along the graph is minimal, but this is not unusual in roots because the density of the wood is very different from the main stem. I am most concerned with the amplitude of the graph rather than the differentiation of the spike marks for roots. So, what I take from these tests is that, despite the damage to the root flares, there has been little decay activity within the root flares.

Tests #6-9 were taken on the four opposite sides of the main trunk and at breast height. There is a very obvious area of decay starting at a depth of 7" on graph #6. At the end of the graph, however, there is more sound wood. The only other pattern like this is at the end of test #8, at a depth of 16.5", where the needle starts to drop off.

My interpretation of these tests is that the main trunk and root flares are quite sound in this tree. This doesn't surprise me too much given that sugar maple is so effective at compartmentalizing wounds. My only concern with this tree is with the main stem and scaffold limbs higher in the crown. My sense is that there is not enough live crown to ensure the level of photosynthetic potential to keep this large tree healthy. It is certainly possible to remove the deadwood and add a cabling system, but I am not convinced that it will extend the useful life of this tree for more than a year or two.





Thank you for the opportunity to provide these assessments and recommendations. I have enclosed a separate letter with the appraisals. Please call with any follow-up questions.


Sincerely,

Mag 13 05 11:54a

Keith C. Pitchford

ISA Certified Arborist, MA-0178

MD Tree Expert, #589





HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

23310 Frederick Road, Clarksburg

Meeting Date:

6/8/2005

Applicant:

Victor Peeke

Report Date:

6/1/2005

ррисант.

(Thomas Taltavull, Architect)

Public Notice:

5/25/2005

Resource:

Outstanding Resource

Clarksburg Historic District

Tax Credit:

Partial

also Park & Planning hee

Review:

HAWP

Staff:

Tania Tully

Case Number:

PROPOSAL:

13/10-05A

. 15/10-05/

Partial demolition, rear addition,

RECOMMENDATION:

and major landscaping

Approve with Conditions

RECOMMENDATION:

Staff is recommending approval with the following condition:

1. Staff must approve any additional work on the historic house that includes anything other than repair or replacement in kind. Major changes may require an additional HAWP.

2. All windows and doors on the addition will be wood, true- or simulated-divided light windows.

3. Details and specs will be approved by staff.

4. Additional work on the historic barn that includes anything other than repair or replacement in kind will require an additional HAWP.

5. A tree protection plan prepared by a certified arborist will be implemented prior to any work beginning on the property.

PROJECT DESCRIPTION

SIGNIFICANCE:

Outstanding Resource within Clarksburg Historic District

STYLE:

Queen Anne

DATE:

c.1891-1900

The property at 23310 Frederick Road, more commonly known as Hammer Hill, is a 2-½-story frame Queen Anne style house. It is significant within the Clarksburg historic district as one of the few residence built after the town was bypassed by the railroad and also as a departure from the simpler houses found throughout the district. This high-style residence features a hipped-roof with dormers on every elevation, a projecting entry bay, and an elaborately detailed front porch. Built for Dr. James and Mrs. Sarah Deets between 1891 and 1900, the house was likely designed by an architect.

Hammer Hill sits back well off of Frederick Road, roughly in the center of its 3.06 acre lot. The vacant parcel in the upper left corner of the site plan (Circle 7) is outside the historic districts, but is also owned by the Applicant. The site plan also shows the proposed extension of Stringtown Road. The house is

mostly shielded from view by mature trees and vegetation along Frederick Road and will be at a grade significantly higher than the Stringtown Road extension. The open space in front of the house is specifically noted as one of the significant green spaces within the historic district.

Early in the county's history, Clarksburg was a substantial center of commerce and transportation. John Clark surveyed the land and subdivided lots along Frederick Road in the early 1790s, yet the town's origins extended back to the mid-1700s. Michael Dowden built a hotel and tavern about 1754. A popular stop along the well-traveled Great Road between Frederick and Georgetown, Dowden's Ordinary is said to have provided lodging and entertainment for such well-known travelers as General E. Braddock, George Washington, and Andrew Jackson.

John Clark built a general store and became the community's first postmaster. The post office, established 1800, was one of the first in the county. By 1850, the town was the third most populous in the county, and the residents numbered 250 by 1879. As a major stagecoach stop between Frederick and Georgetown, Clarksburg supported several inns and taverns. By the mid-1800s, the town also included general stores, a tannery and blacksmiths, and wheelwrights. In 1879, Clarksburg had 250 residents, making it the third most populous town in the County. The Queen Anne-style house at 23310 Frederick Road, known as Hammer Hill, was built c.1891-1900 by Clarksburg physician Dr. James Deetz and his wife Sarah. The name, Hammer Hill, comes from the tract name given this land in 1752.

Clarksburg has historically been a bi-racial town. While many African Americans settled, after the Civil War, in communities separate from white settlements, freed slaves in Clarksburg built houses in and around the town. Growth in Clarksburg declined in the late 19th century, when the B & O Railroad bypassed the town for nearby Boyds. The advent of the automobile and improved roads brought something of an economic revival beginning in the 1920s. New boarding houses opened in town to accommodate the new auto tourism.

APPLICABLE GUIDELINES:

When reviewing alterations and new construction within the Clarksburg Historic District several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the Vision of Clarksburg: A Long-Range Preservation Plan (Vision), Montgomery County Code Chapter 24A (Chapter 24A), and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Vision of Clarksburg

The *Vision* makes some of the following statements:

"Managing the preservation and protection of Clarksburg's architectural character and historic pattern...is critical to maintaining its contribution to the County's heritage." "A buffer area, adjacent to the historic district, should allow for the conservation of open space..." "The Clarksburg Historic District is a significant collection of early 19th century residential and commercial architecture along Frederick Road reflecting the town's once prominent role in trade, transportation, and industry in Montgomery County." "[T]he existing historic district [is] the "historic core" of the new town, where the primary goal is to retain, reuse, and preserve the existing resources, while allowing fro an acceptable amount of controlled infill."

Montgomery County Code; Chapter 24A

• A HAWP permit should be issued if the Commission finds that:

- 1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
- 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.

Secretary of the Interior's Standards for Rehabilitation:

- #2 The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, space and spatial relationships that characterize a property will be avoided.
- #9 New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- #10 New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

PROPOSAL:

- Rehabilitate exterior of the historic house
 - o Replace asbestos shingle roof with synthetic slate
- Add an accessible ramp to the historic house (Circle 15)
 - Wood railings
- Construct a new 1½ -story rear addition (Circles 11-15)
 - o Remove deteriorated rear ell addition
 - o Synthetic slate roof
 - o Fiber cement horizontal siding
 - o ½ round metal gutters
 - o Skylights
 - Wood simulated divided light windows
 - Wood details and trim
- Redesign the driveway and add more parking (Circle 22)
 - o Landscape the drive and parking areas (Circle 23)
 - o Tar and chip driveway and parking
 - Sidewalks of pavers
 - o Remove five trees based on arborist's assessment (Circle 24)
- Rehabilitate historic barn
 - o Remove plywood additions
- Remove non-historic outbuildings (Circle 22)

STAFF DISCUSSION

The Commission reviewed this project as a Preliminary at its March 9, 2005 and April 27, 2005 meetings (transcripts from the April meeting begin on Circle 34). The proposal enclosed is the result of modifications made by the applicant based on comments provided by the Commission at the two prior meetings. On the whole the Commission felt that the proposed addition was appropriate in massing and scale. There was limited discussion of removing the existing rear addition or with the proposed outbuilding removals. The main topic of discussion at each meeting was the landscape plan and the amount of hardscape proposed. At the last meeting the Commission seemed generally accepting of the revised schematic site plan and was anticipating the planting scheme. The applicants also made minor changes to the rear addition as suggested by the Commission.

The proposed addition is consistent with the Preliminary Consultations and staff maintains the belief that the addition is well designed and compatible with the architecture of the historic house. The scale of the addition as seen from the side elevations is appropriately deferential and in staff's opinion, meets the *Standards*. In summary, the existing rear addition has been significantly altered and is structurally deficient, thus warranting its removal in this case. The outbuildings proposed for removal are not historic and the non-historic portions of the barn will be removed as part of its rehabilitation. Staff applauds the applicant for undertaking rehabilitation of the historic house and for working with staff to maintain its integrity. Work on the historic house will range from structural framing repairs to the roof and termite damaged support post and foundation beam to painting. Some of the proposed work includes installation of a new roof, gutters and downspouts, correcting water drainage, and restoration of the front porch. Staff requests that the Commission remind the applicant of the Montgomery County Historic Preservation Tax Credits that are available.

Staff recommends approval of the HAWP with the a few conditions related to details of the addition and the plans for the barn. Although the documentation provided by the applicant is unclear, conversations with staff indicate that all railings and trim will be wood. Staff is recommending a condition that allows for staff approval of the specific balusters, columns, and other such details that are selected. The current proposal for the barn involves simply removing the plywood additions and rehabilitating the existing structure. The applicant has expressed an interest in adding a new appropriate shed addition to the barn for tractor storage. This would require submittal of a new HAWP application.

STAFF RECOMMENDATION:


Staff recommends that the Commission approve with the above conditions the HAWP application as being consistent with Chapter 24A-8(b);

and with the Secretary of the Interior's Standards for Rehabilitation;

and with the general condition applicable to all Historic Area Work Permits that the applicant will present <u>3 permit sets</u> of drawings to HPC staff for review and stamping prior to submission for permits (if applicable). After issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will arrange for a field inspection by calling the DPS Field Services Office at 240-777-6370 prior to commencement of work <u>and</u> not more than two weeks following completion of work.



HISTORIC PRESERVATION COMMISSION 301/563-3400



APPLICATION FOR HISTORIC AREA WORK PERMIT

Address: PD BOX Street N Contractor: Contractor Registration No.: Agent for Owner: THON COCATION OF BUILDING House Number: 2:33 Cown/City: CIARKS	VICTOR PEEK 489 CC 1AS TACTAVU. PREMISE 1 O 3 URG Subdin	ARKSBURG City L - ARCHITECT Street:		20/ 7/ p Code
ame of Property Dwner: ddress: PD BOX Street N ontractor: ontractor Registration No.: gent for Owner: THON OCATION OF BUILDING buse Number: 2'3'3 own/City: CIARKS ot: Blo	VICTOR PEEK 489 CC 1AS TACTAVU. PREMISE 1 O 3 URG Subdin	ARKSBURG City L - ARCHITECT Street:	MARYLAND 208 Staet Zij Phone No.:	7/ p Code
Address: PD BOX Street N Ontractor: Ontractor Registration No.: gent for Owner: THON OCATION OF BUILDING DUSS Number: 2 3 3 WWN/City: CLARKS Other: For	489 C.C. C.C. C.C. C.C.	ARKSBURG City L - ARCHITECT Street:	MARYLAND 208 Staet Zij Phone No.:	7/ p Code
ddress: PD BOX Street N Ontractor:	489 C.C. C.C. C.C. C.C.	ARKSBURG City L - ARCHITECT Street:	MARYLAND 208 Staet Zij Phone No.:	7/ p Code
ontractor:ontractor Registration No.: gent for Owner:	1AS TALTAVU. PREMISE 10 BURG Subdin	UL - ARCH ITECT Street	Phone No.: 301-840-184 FREDERICK ROAD	
ontractor Registration No.: gent for Owner: THON OCATION OF BUILDING louse Number: 2°33 own/City: CHOKS ot: Blo	1AS TALTAVU. PREMISE 10 BURG Subdin	L - ARCH ITECT		2 7
gent for Owner: THON OCATION OF BUILDING ouse Number: 2:3:3 own/City: CLARKS ot: Blo	PREMISE 10 BURG Subdince:Subdin	L - ARCHITECT	FREDERICA ROAD	7 7
OCATION OF BUILDING ouse Number: 2°33 own/City: CIARKS ot: Blo	/PREMISE // O // BURG Subdin	Street:	FREDERICA ROAD	
louse Number: 2:33 own/City: CIARKS ot: Blo iber: Fo	10 BVR6 pck:Subdiv	Street Nearest Cross Street:	FREDERICK ROAD	
own/City: <u>CLARKS</u> ot: Blo ber: Fo	<i>BURG</i> ck: Subdiv	Street: Nearest Cross Street:	FREDERICK ROAD	
ot: Blc iber: Fo	ck: Subdiv	Nearest Cross Street:		
ot: Blo iber: Fo	ck: Subdiv	-	STRINGTOWN ROAD	
		rision:		
ADT ONE. TYPE OF PE	lio:!	Parcel: 311		
	MIT ACTION AND HEE			
		CHECK VII	APPLICABLE:	
A. CHECK ALL APPLICABL Construct E				Deck 🗆 Shed
	extend Alter/Renovate	,.		
☐ Move ☐ h			•	Singla Family
	lepair Revocable	•	Vali (complete Section 4) Other:	
	ate: \$ 500,000			
C. If this is a revision of a p	previously approved active pe	rmit, see Permit #		
PART TWO: COMPLETE	FOR NEW CONSTRUCTION	N AND EXTEND/ADDITI	<u>ons</u>	
A. Type of sewage dispos	sal: 01 🗹 WSSC	02 🗆 Septic	03 🗆 Other:	
2B. Type of water supply:	01 🗹 WSSC	02 🗆 Well	03	
ART TUBES, COMBIET	E ONLY FOR FENCE/RETA	INING WALL		
		Helled VVALL		
IA. Heightfee				
IB: Indicate whether the f	ence or retaining wall is to be			
On party line/prope	rty line	ly on land of owner	On public right of way/easement	•

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

a. Description of existing structure(s) and environmental setting, including their historical features and significance:

HE PROPERTY AT 23416 FREDRIC ROAD, MORE COMMONLY KNOWN AS HAMMERHILL

A 21/2 STORY FRAME QUEEN ANNE STYLE HOME. IT IS SIGNIFICANT WITHIN THE

ARRESPULL HISTORIC DISTRICT AS ONE OF THE FEW RESIDENCES BUILT AFFOR THE TOWN

TO BYPASSED BY THE RAHROAD AND AS A DEPARTURE PROM THE SIMPLER HOUSE'S

WAS IN THE DISTRICT THE HIGH STYLE RESIDENCE FEATURES A HIPPED ROFE

THE DAMERS ON EVERY ELEVATION, A PROJECTING ENTRY BAY AND A DETAILED

LONT PORCH. THE HOUSE WAS BUILT FOR DR. JAMES & GARAH DEETS

13ETWEEN 1891-1900.

b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:

IE PROJECT PROPOSES TO RESTORE THE ORISINAL EXTERIOR, REPUGE THE ASDESTED

YIMLE ROOF WITH SYNTHETIC SLATE REMOVE THE DETERIORATED REAR ADDITION

LUA CONSTRUCT A 1/2 STORY REAR ADDITION. NEW LANDSCAPING & REDESION OF

HE CIRCUAN DRIVE AND ADD ADDITIONAL PARKING ON THE SIDES REAR. RESTORE

AND OUTBUILDING AND REMOVE TOLL HOUSE AND SHED OUTBYILDING. THERESTORATED

OUTBOUND AND SITE WORK WILL PRESERVE THE SIGNIFICANT RESOURCE, THE OPEN SPACE

2. SITEPLAN IN FRONT AND MAINTAIN THE INTEGRITY OF THE CLARKS BURG

HISTORIC. DISTRICT.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing end proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17", Plans on 8 1/2" x 11" paper are preferred.

- Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

. PHOTOGRAPHS


- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or lerger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including nemes, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).



8

THIS PALL NIK

(D)

AN PORCHEL FIL COLUMN THE PIC CONTRO THE 是 己 55 FH. FL 200

M Down HAMMERHILL
N HERDERICK ROAD
CLARKSBURG, MARYLAND

DO NOT SCALE DRAWING

NOT FOR CONSTRUCTION

ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERFICATION PRIOR TO CONSTRUCTION.

Revisions
11.19.2004

Carwing Tie

EXISTING LEFT SIDE ELEVATION





FIL PORCHE. FIL T. 151

NOTE:
ALL DIALENSONS & RELATIONSHPS
REQUEE FRAM FELD VERFICATION
PRIOR TO CONSTRUCTION.

DO NOT SCALE DRAWING

NOT FOR CONSTRUCTION.

Drawing Number

HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND Revisions
11.19.2004

Drawing Tide

EXISTING REAR ELEVATION

AACHTECTS
AACHTE




FIL PORCH EL

NOTE:
ALL DIRECTIONS & RELATIONSHIPS
REQUIRE FINAL RELD VERIFICATION
PRIOR TO CONSTRUCTION.
DO NOT SCALE DRAWNG
NOT FOR CONSTRUCTION

Downing Hammerhill FREDERICK ROAD CLARKSBURG, MARYLAND


Revisions
11.19.2004
10.6 Drawing Tide
EXISTING RIGHT SIDE ELEVATION

ARCHITECT MANUAL STREET ALLANDING TALLANDING ARCHITECT MANUAL STREET ARCHITECT




(J)

91)







SECOND FLOOR PLAN

1/4" = 1'-0"

ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERFICATION PRIOR TO CONSTRUCTION.

DO NOT SCALE DRAWING


NOT FOR CONSTRUCTION


W. THOMAS J. TALTAVULL ARCHITECT ZONE FUND CHICAGO

Date: 4.5.2005


Drawing Number

A1.2























April 30, 2005

Mr. Victor Peeke P.O. Box 489 Clarksburg, MD 20871

Dear Victor:

This report contains several survey results regarding a select number of trees on your property at 23310 Frederick Road, Clarksburg, Maryland.

In particular, there are tree assessments, appraisals and one hazard tree evaluation. I have maintained the numbering system that was in place at the time of this survey.

I. TREE ASSESSMENTS:

#101 - Black walnut (Juglans nigra). This tree measured 33.5" of diameter at breast height (dbh) and is in good condition. The form on this tree is excellent. The only factor that detracts from an "excellent" condition rating is what appears to be an old lightning strike on the trunk. I do not feel that this will impact the tree in either health or structural integrity. It should receive a crown cleaning treatment and remain in the landscape.

#102 - Common pear (Pyrus communis). This tree measured 17.5" dbh and is in fair to poor condition. There are several defects along the main stem and leaders including significant cavities. There is also tip dieback throughout the small crown that remains. This is an older pear and certainly near the end of its lifespan. I would not recommend investing any monies into keeping this tree healthy. I believe it is a removal candidate.

#103 - Butternut (Juglans cinerea). This tree measured 16" dbh and is in poor condition. There is very little live crown left on this tree. It is not a preservation candidate and should be removed.

#104 – Butternut. This tree measured 18" dbh and is in good condition. There are some broken limbs in the crown and a prominent basal wound. I do not feel that the basal wound represents a significant defect for this tree. It should receive a crown cleaning treatment and be retained in the landscape.

#105 - Butternut. This tree measured 14.5" dbh and is in good to fair condition. There is a sweep in the main trunk and some minor deadwood in the crown. It would benefit by a crown cleaning operation and should be retained in the landscape.

#112 - Tree-of-heaven (Ailanthus altissima). This tree measured 21" dbh and is in fair to poor condition. There is a very large vine coverage in this tree. However, these are a highly invasive species and should be removed from the landscape

#113 - Silver mapie (Acer saccharimm). This tree measured 22" dbh and is in good to fair condition. A large ivy vine has been cut which should help this tree out tremendously. One lead has broken, but a larger lateral now appears to be asserting dominance. There is also a slight lean in the trunk, but it is self-correcting. This tree should remain in the landscape.


#114 - White mulberry (Morus alba). This tree measured 24" dbh and is in fair to poor condition. There are two stems here of equal diameter. Heavy vines in the canopy have been cut recently which will help this tree. However, it may be too late. One of the main stems has been badly damaged at the base. This is not a preservation candidate and should be removed.

#115 - Sugar maple (Acer saccharum). This tree measured 37" and is in fair condition. There are multiple wounds along the trunk and several large wounds on the root flares. It is obvious that several large limbs have broken out of the crown over the past several years. There is also quite a bit of deadwood in the crown. At the very least, this tree needs to be deadwooded and cabled. I have conducted a hazard tree evaluation on this tree, including resistograph tests. This report is attached here. I am not a supporter of keeping this tree in the landscape. I believe there is too much of a hazard associated with it.

#116 – White mulberry. This tree has two large stems that measured 31.5" and 27" dbh. A third large stem has been removed in the recent past. Some of the cut-up wood from this stem is scattered under this tree. The smaller of the two stems lost its top in the recent past, but it has re-sprouted and appears to be vigorous. The remaining third stem is in better condition. I am not optimistic about the long-term prospects for this tree.

The base of the tree is decaying in many locations and the angle of lean of the stems is considerable (>15%). Even if just the healthiest stem is kept, I do not think it is viable enough to warrant keeping it in the landscape. In my opinion, it is not a preservation candidate and should be removed.

#117 - White mulberry. This tree also has two main stems. One is 26" and the other 20" dbh. The larger of the two stems is in poor condition with the





top dying back. The base of this tree is also highly decayed and weak. I do not feel that this is a preservation candidate. I believe that it should be removed.

II. HAZARD TREE EVALUATION:

#115 - Sugar maple.

This tree was evaluated for structural stability in both the main trunk and root flares. The resistograph machine was used in these tests. A total of nine (9) tests were made into the tree. Five (5) of these were made into the root flares and four (4) were made into the main trunk. A diagram of the test locations is attached.

The results of these tests were rather interesting in that they were completely opposite of what I would have expected. I have enclosed a reduced copy of the resistograph tests and included all of them on one page.

Tests #1-5 on the enclosed are from the root flares. The pattern for all of these tests is encouraging in that the amplitude of the graph increases as the needle penetrates the wood. It is apparent that the differentiation of the spike marks along the graph is minimal, but this is not unusual in roots because the density of the wood is very different from the main stem. I am most concerned with the amplitude of the graph rather than the differentiation of the spike marks for roots. So, what I take from these tests is that, despite the damage to the root flares, there has been little decay activity within the root flares.

Tests #6-9 were taken on the four opposite sides of the main trunk and at breast height. There is a very obvious area of decay starting at a depth of 7" on graph #6. At the end of the graph, however, there is more sound wood. The only other pattern like this is at the end of test #8, at a depth of 16.5", where the needle starts to drop off.

My interpretation of these tests is that the main trunk and root flares are quite sound in this tree. This doesn't surprise me too much given that sugar maple is so effective at compartmentalizing wounds. My only concern with this tree is with the main stem and scaffold limbs higher in the crown. My sense is that there is not enough live crown to ensure the level of photosynthetic potential to keep this large tree healthy. It is certainly possible to remove the deadwood and add a capling system, but I am not convinced that it will extend the useful life of this tree for more than a year or two.






Thank you for the opportunity to provide these assessments and recommendations. I have enclosed a separate letter with the appraisals. Please call with any follow-up questions.


Sincerely,

Keith C. Pitchford

1SA Certified Arborist, MA-0178


MD Tree Expert, #589
















HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

er's mailing address	Owner's Agent's mailing address	
Victor J. Peeke P. O. Box 489 Clarksburg, MD 20871	Miller, Miller & Canby Attn: James L. Thompson, Esq. 200-B Monroe Street Rockville, MD 20850	
Adjacent and confron	ting Property Owners mailing addresses	
RUDDÉN, ARIC L	and the second s	
22329 FREDERICK RD CLARKSBURG MD 20871	6125 TUCKERMAN LANE ROCKVILLE MD 20852	
TERRABROOK CLARKSBURG LLC	WATKINS, WILLIAM K & B L	
C/O NEWLAND COMMUNITIES 13777 JOHN J DELANEY DR #525 CHARLOTTE NC 28277	11610 PIEDMONT RD CLARKSBURG MD 20871	
KOSTARIS, FOTIS & E ET AL	GATEWAY COMMONS LLC	
8800 DARNESTOWN RD ROCKVILLE MD 20850	10230 NEW HAMPSHIRE AVE SILVER SPRING MD 20903-1400	
FARM DEVELOPMENT COOP LLC	. Little bestelle be	
21032 COG WHEEL WAY GERMANTOWN MD 20876-4271	SOARD OF EDUCATION 850 HUNGERFORD DR	

HISTORIC PRESERVATION COMMISSION April 27, 2005 Meeting Minutes

MS. O'MALLEY: Anyone else have any other staff items or dates to announce? Think that's it, okay. Well, then we can -- I guess we'll go ahead. Let's see. We'll go ahead with our preliminaries.

MS. WRIGHT: Yeah, there will be a staff report and then the architect is here.

MS. TULLY: Right, and the landscape architects are on their way so hopefully they will get here. Okay, the preliminary tonight is a second preliminary consultation for 23310 Frederick Road in the Clarksburg historic district, also known as Hammer Hill.

The Commission saw this project initially on March 9th and based on those comments, the applicant is back with some changes. The proposal as you know, is for partial demolition, a rear addition, driveway and parking. I'm not sure if tree removal is still actually on the books. Certainly not as -- if there is, not as much as there was with the initial landscape design.

Staff is generally supportive of the changes. The changes to the addition are relatively subtle. The most obvious changes for the most part are the addition of the wheelchair access, which was discussed but not shown last week. I mean at the last meeting. It is on the right side through a porch entrance that was originally the doctor's office entrance as opposed to coming in the front porch.

In response to Commission comments about the rear wing obscuring the historic house, it has been reduced in length by two feet. Additionally, the applicant requested that the architect make that same rear portion a bit wider which he has done which has resulted in the additional deeper, which resulted in additional height.

If you look at circles, it looks like an 8 and 11 that illustrates the changes. Yeah, circle II shows the reduction in width of the rear portion and then circle eight shows the slight increase of depth of that same portion. Again, there are relatively subtle changes of portions are still appropriate and staff is of the opinion that although it does make the rear portion a bit higher, it does separate the distance between the connector and the rear portion that makes it not seem quite as tall.

What is obvious is the major changes to the landscape plan which at this point, schematic parking and drive plan, which still has a lot of parking. The applicant still has the lease but at the request of the Commission, A, the circular drive in the front has been removed and additionally, the design is more organic and less boxy. They made an attempt to separate parking from one another and it also pushes it towards the rear of the property so it takes on a secondary role.

What is not showing at this point is the actual landscaping and vegetation suggestions. At this point, they're hoping to hear from the Commission if this layout idea will work before getting into the screening and actual plantings that they would be proposing which they definitely will be.

The materials, the only real change is that, at staff and the Commission's suggestions, rather than asphalt shingles, they will be re-roofing the historic with synthetic slate. They will be using the same product on the new house, the new addition as well. To clarify one little part, I have a note in there that the roof of the rear project -- that makes no sense. There's a little bump out there on the very back of the house, a bay window and that's what I was referring to in that comment, having a metal roof and that's just a higher design thing that I wanted to make that clear that I wasn't talking about the entire addition.

And now I have the photographs of the property if you wish to see them again. Otherwise, the architect is here. Are there any questions regarding this side of the house? Oh, one other change was on the railings of the roof, the roof decks. They're more proportional. Did you want to see the -- unless the Commissioners remember what it looked like so I'd be happy to comment. The architect.

15.

MR. TALTAVULL: I guess Comsat wasn't on the agenda tonight. Good evening. My name is Tom Tultavull. I'm the architect for Victor Peek and Mike Norton from Amy's Land Design, I believe, is on the way.

I think Tania pretty much summed up the changes that I made. I've got another additional drawing. There was some concern about the low facia on the connector part and I've got an alternative drawing that raises the facia up, which would flatten out the roof pitch a little bit. I can show you that drawing. It raises this facia up in line with the facia that connects it with.

MR. FULLER: In the alternative, you're getting it basically above a person's head if they're --

MR. TALTAVULL: I was trying to keep the height of this down and try to keep that roof at a fairly decent pitch. I think it would work out by raising this up in line. It takes away a little bit of the clumpiness, I think.

MR. FULLER: I think I like the alignment better with --

MR. TALTAVULL: You'd have to get a ladder to clean the gutter out now, I guess. That's just one option that I've changed since you've seen the last submission.

MR. FULLER: I mean personally, I think there's a lot of improvements. I mean, the main thing that I think we objected to last time, the biggest thing was the sidewalk. I think it's -- you know, I'd love to see less cars, but it certainly at least moved them all around to the rear so it's less intrusive from the front. Your driveway is now -- you're making use of the existing driveway which I think was a big issue to us.

I think the detail on the house was fairly close on to begin with. I like your alternative on the connector but you should hear that from other people. I think it's a nice project.



1 2	MS. WATKINS: I had one question about some of the site work. There's an existing barn or shed so					
3	you're taking off part of that, a little wing of it to bring the driveway around?					
4 5	MR. TALTAVULL: This is a larger barn on I guess the north side?					
6						
7	MS. WATKINS: Right.					
8 9	MR. TALTAVULL: And it was my understanding that they were going to take off, I guess it's OSB					
10	type, you can see it in the photographs.					
11 12	MS. TULLY: Right. There are non-historic plywood OSB attachments to the historic barn and that's					
13	what they would removing.					
14 15	MS. WATKINS: That's what would be coming off and then					
16 17	MS. TULLY: Right.					
18 19	MS. WATKINS: and then the driveway is wrapping where okay.					
20 21	MS. TULLY: Correct.					
22 23	MR. TALTAVULL: And I					
24 25	MS. TULLY: I can show you					
26 27	MR. TALTAVULL: I can't speak for Victor, but I think that he was also still looking for rebuilding the					
28	two sheds so you have somewhat of a tradition.					
29 30	MS. TULLY: Right, he had to come back for that but that is his eventual plan. I can show you. Do you					
31	want me to show you the pictures that we have available?					
32 33	MR. TALTAVULL: It's just on your site plan, it looks like the bar is rotated 90 degrees. I don't know if					
34	somebody has drawn it incorrectly or					
35 36	UNIDENTIFIED SPEAKER: I think showing the picture might help.					
37 38	MS. TULLY: Okay. I mean, right now, it's sort of square and when you take the additions off, it					
39	become rectangular. But maybe you'll see the picture of that house clarified.					
40	MP TAITAVIII I . I know the intention of the owner is to restore that harn and					



1 2	MR. FULLER: Historic barn status?					
3						
4	MR. TALTAVULL: Yes. And then the two sheds wings would be made an open carport but they					
5	would be restored in detail in keeping with the main barn.					
6 7	MR. BURSTYN: On the left side elevation in the foreground, are those blinko doors? Is that what that					
8	is?					
. 9 10	MS. WRIGHT: Just to finish, let's just finish the out building discussion and then we'll turn the lights					
11	back up so that we can refer to the drawing. This is the out building in question and you can see with the two					
12	shed additions, the footprint of it actually becomes a much bigger footprint. But if you remove all those					
13	additions, what you have is a rectangular building with the shorter part of the rectangular facing north-south					
14	which is what is shown in the drawing.					
15 16	MS. WATKINS: Thank you for clarifying that.					
17 18	MS. WRIGHT: Okay now, you had a question. Mr. Burstyn had a question that required looking at the					
19	drawing.					
20 21	MR. BURSTYN: Yes, he answered it. The little doors in the foreground in the middle are the cellar					
22	blinko doors.					
23 24	MR. TALTAVULL: I think they're deteriorated wood now and the owner would prefer to have the					
25	metal what I call Dorothy doors.					
26 27	MS. O'MALLEY: Do any of the other architects have comments about that connection in between, the					
28	angles, the height?					
29 30	MS. WATKINS: Mike the one with the higher eaves.					
31 32	MS. O'MALLEY: I agree.					
33 34	MS. WILLIAMS: Did you look at all at squeezing the addition a little bit and I mean, I know that in					
35	terms of the relationship of the historic building to the new constructions, I didn't have any problems, but I was					
36	interested in seeing if we could reduce the width of the wing so that from the rear elevation, more of the					
37	original building was visible. We talked about perhaps trying to pull it in a little bit. It's not apparent that it					
38	was really tightened up much.					
39	was ready digitioned up much.					
ンプ						

1	MR. TALTAVULL: Yes, what I have done on this is pulled in a foot on each direction, on each side. I					
2	think the owner's concern is that he's not quite sure. I think he's going to live in the house for a period of time					
3	as he's restoring it but he's also looking into the options for professional offices, either doctors or dentists. And					
4	I know he's been speaking with a dentist and the back section would be a place where the exam rooms would					
5	be. They talked about how it laid out in terms of getting enough space for four dentist chairs.					
6 7	MS. TULLY: It looks like everybody is here.					
8 9	MS. WILLIAMS: Well, I was just going to make a comment and apologize to the two of you that just					
10	came in and had to jump right into the meeting a lot quicker than expected.					
11 12 13 14	MR. TALTAVULL: I know your concern and I guess programmatically it's tough. I guess my main goal was in the connector wing, to keep that small and pulled away from the main building. So, in three dimensions, if you're off center in the back of the property, you know, 30 feet one way from direct, you're still					
15	going to see the main portion of the back building in realty.					
16	Obviously, if you are standing back in this area, it's going to block it, but from either side on this side,					
17	which is the main garden area is here and the entrance to the parking lot is here. I guess it was kind of a					
18	trade off.					
19 20	MS. WILLIAMS: Yeah, I mean I generally just find the addition a little bit aggressive for the house. It's					
21	just a such a great pyramidal roof cubic structure and I don't know. To me, it's done appropriately. I mean I					
22	really don't have any huge objection. Lguess Ljust wish it were a little smaller. That's all.					
23 24	MR. FULLER: Do you want to address the landscaping that you're proposing for the site?					
25 26	MR. NORTON: My name is Mike Norton. We made this rendering. It's in my boss's car because I					
27	knew he wouldn't be late. That should be here shortly.					
28	I can address the rendering of the project versus last time if you like. If you guys all have your 8.5xll.					
29	So I apologize					
30 31	MS. TULLY: Circle 19.					
3 2 33	MR. NORTON: We don't have the other one and we did look at your comments and we removed the					
34	circle driveway.					
35 36	MS. O'MALLEY: Thank you.					
3 <i>7</i> 38	MR. NORTON: We reduced the drive aisles down to 12 feet. We removed two spaces. We did come					



1	down to 14 spaces and we tried to break it up as best as possible while still keeping Mr. Peeke's seven vehicles				
2	and then I tried to intersperse parking around a loop as we have shown. I have another drawing that has like I				
3	said a rendering and it's on its way.				
4 5	MS. O'MALLEY: Just in time.				
6 7	MR. NORTON: Sure. And we'll set that up there now.				
8 9	MS. O'MALLEY. Exactly what we were just planning to cover. Thank you.				
10 11	MR. NORTON: Sure. Since the last meeting, we also did retain an arborist who is doing an evaluation				
12	of all the trees on the site. Let me step up here. And all these ones that are in this paler green are actually all				
13	trees that are staying. All the trees right now are staying on the we have proposed to stay and added some				
14	more. And that's how it had worked.				
15	We're looking at just some shrubbery screening along here a little better for the residential and just trying				
16	to kind of hide this thing and put two or three spaces in the site. We do have five spaces back here and that is				
17	our biggest block of spaces I guess you would call it and try to get this loop in here.				
18	If Mr. Peeke does go to I think they were just referring to possible dentists now, what have you. This				
19	would allow deliveries to come in right here. What we did do is try to keep as much on the existing				
20	impervious, the gravel space as possible. It's what we have right now and just bump things out a little bit.				
21	We were looking at bringing a handicapped ramp in right here on this side, you come in right there. And				
22	kind of an entrance right here, kind of a primary entrance, we're saving for keeping this entrance, the front				
23	entrance and the front as it is and then a walk around this way. That's what we're looking at right now, kind of				
24	breaking things apart and more of amebic				
25 26	MS. WATKINS: So the lot actually does the parking lot is around the trees because it appears that,				
27	not to be cynical, that some of these parking pads could be connected just, you know by part, just kind of				
28	overflow. You'd end up with a lot more parking.				
29 30	MR. NORTON: Sure. Which ones are you, which parking?				
31 32	MS. WATKINS: Right between two and three.				
33 34	MR. NORTON: Two and Three. We do have this existing tree right here and that is why we saved it,				
35	104. It is a 17-inch tree. It's a caliber tree so we did try and break things apart and stay away from those as				
36	much as possible.				
37 38	MS. WATKINS: Okay. And then back behind the five there are a row of trees on that other side that				

(39)


1	will remain?				
2	MR. NORTON: Back behind this five right here?				
4 5	MS. WATKINS: Yeah on the, yeah.				
6 7	MR. NORTON: Along this walk?				
9	MS. WATKINS: Right.				
LO L1	MR. NORTON: Yes, everything is to remain right along the property line.				
L2 L3	MR. PEEKE: There's no trees back there right now.				
L4 L5	MR. NORTON: Right. This tree right here, that's the existing tree. That's the only one back there right				
L6	now.				
L7 L8	MS. WATKINS: Okay, but I see more trees drawn there so you would propose -				
L9 20	MR. NORTON: Oh, you mean these right here? These are all proposed.				
21 22	MS. WATKINS: Okay.				
23 24	MR. NORTON: That's all proposed. The lighter green is the existing tree that is there.				
25 26	MS. WATKINS: Okay, because this is going to be easy for this parking to grow as needed and that				
27	would happen.				
28 29	MS. WRIGHT: Did you specify if there are any trees being removed?				
30 31	MR. NORTON: Currently, as we have drawn right now, there are not. That is, like I said, we do have				
32	the arborist who is doing an analysis of each tree and I gave him the grading plan. Just a preliminary grading				
33	and a preliminary sketch so he can make an analysis of what would happen if this did move forward, if these				
34	trees could be saved and how they could.				
35 36	MS. O'MALLEY: Have you considered what the material of the driveway would be?				
37 38	MR. NORTON: I believe we're still talking of a tar and chip right now?				
39 10	MR. PEEK: Tar and Chip.				





1	MR. NORTON: Yeah, a tar and chip. This is still - we're still fine tuning it and working on this, but I					
2	think they were leaning towards the tar and chip.					
3						
4 5	MS. O'MALLEY: Any other questions? I'm really pleased to see the changes that you've made on the					
6	parking and the driveway. That's a huge improvement. Well, I guess back to the time when you'll bring in your final application.					
7	your man approaction.					
8	MR. TALTAVULL: I just had one other cut quick comment. It was discussed at the last meeting in					
9	regard to this chimney. It goes through the existing dormer.					
10 11	MS. O'MALLEY: Uh-huh.					
12 13	MR. TALTAVULL: Of how the Commission felt about whether it could be removed or not?					
14 15	MR. FULLER: The chimney or the dormer?					
16 17	MR. TALTAVULL: The chimney.					
18 19	MR. FULLER: And the dormer restored.					
20 21	MR. TALTAVULL: And restore the dormer back to what I think was it's original					
22 23	MS. O'MALLEY: Would you refresh my memory about that? Was the chimney original?					
24 25	MR. TALTAVULL: No, I think					
26 27	MS. O'MALLEY: The chimney wasn't added?					
28 29	MR. TALTAVULL: Yeah, I think when they added this doctor's entrance, they built this chimney. It					
30	went up through the dormer that they just built, left it and built around it. I think the original house had two					
31	smaller chimneys, at least one of them is left. I think the original house has, looking at the framing and the					
32	roof, had a chimney near this right through here. It came down next to the not that we're proposing to					
33	remove, but I guess we were thinking at this point					
34 35	MR. FULLER: It certainly doesn't feel very natural the way it sits there.					
36 37	MS. O'MALLEY: So you're proposing to remove non-original and restore the original so that would be					
38	something we would like to support.					
39 40	MR. TALTAVULL: Okay.					





2	MS. WILLIAMS: Kind of restore the dormer.					
3 4	MR. TALTAVULL: Right.					
5 6	MS. WILLIAMS: That would be great. You'd get a tax credit too.					
7 8	MS. WRIGHT: Just one point I wanted to make just to clarify the record. Right now, you were talking					
9	about the dentist office or a doctor's office, you would have to					
10	I believe the only way that that could be considered would be through a special exception process.					
11	The zoning of the property is R200 and does allow for some non-residential professional offices but only					
12	through the special exception process. I just wanted to make sure that was clear.					
13 14	MR. FULLER: But I think it looks like they're trying to do is position themselves so they don't have to					
15	come back here.					
16	come back note.					
17	MS. O'MALLEY: All right, well then, we'll have to see you again.					
18						
19	MR. FULLER: Thank you.					
20 21	MR. TALTAVULL: Thank you.					
22 23	MR. PEEKE: Sorry, I missed the show.					
24 25	MS. O'MALLEY: You just got here in time.					
26 27	MR. BURSTYN: Do you want one more?					
28 29	MS. O'MALLEY: We have covered all the standard commission items. Then the meeting is adjourned					
30 31	(Whereupon, the meeting was concluded at 8:53 p.m.).					























FIL 02, 250 ENT COLLEGE 344 FR. PORCH FL. 151 To 161 NOTE:
ALL DIMENSIONS & RELATIONISHE'S
REQUIRE FINAL FELL VEGETCATION
PRIOR TO CONSTRUCTION.
DO NOT SCALE DRAWNG NOT FOR CONSTRUCTION EΧ Revisions 11.19.2004 Drawing Number HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND <u>1.1</u> EXISTING FRONT ELEVATION

PL CHEED JE ALFORDIST.

NOTE:
ALL DIMENSIONS & RELATIONISHPS
REQUIRE FINAL FELD VERBICATION.
PRIOR TO CONSTRUCTION.
DO NOT SCALE DRAWING
NOT FOR CONSTRUCTION

EX N

HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND Persons 11.19 2004

Toming 10b

EXISTING LEFT SIDE ELEVATION

FORMS J FALTAVUL AB C HITEET AB C HITEET BOT SEA SHADOW 301.840 1887

DESTINO RESIT SIDE ELEXATION FIL POICH IL 和凡斯 NOTE:
ALL DIMENSIONS & RELATIONSHIPS
REQUIRE FINAL FIELD VERBECATION
PRIOR TO CONSTRUCTION.
DO NOT SCALE DRAWING NOT FOR CONSTRUCTION ΕX Revisions 11.19.2004

Drawing Number ĺΩ

HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND

EXISTING RIGHT SIDE ELEVATION

FIL CREAM NO. BY N' TAL PALPL ATTIC

NOTE:
ALL DIMENSIONS & RELATIONISHPS
REQUIRE FINAL FIELD VERFICATION
PRIOR TO CONSTRUCTION.
DO NOT SCALE DRAWING
NOT FOR CONSTRUCTION


EX 5

HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND Revisions 11.19.2004

EXISTING REAR ELEVATION

.____

TOWARTA FEWOLIA



FIRST FLOOR PLAN 1/4" = 1'-0"

NOTE:

ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERIFICATION PRIOR TO CONSTRUCTION.

DO NOT SCALE DRAWING

NOT FOR CONSTRUCTION

ARENITACIE
PLAN IN ERI
PLAN IN ERI
PLAN IN ERI
PASSERVATION
THOMAS TATAVALL
AR CHISTOT
SOT 847-1947

Revisions Second preliminary


Second preliminary

Control of the Maria C

HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND

Drawing Number

A1.1



SECOND FLOOR PLAN 1/4" = 1'-0"

ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERIFICATION PRIOR TO CONSTRUCTION.


DO NOT SCALE DRAWING

NOT FOR CONSTRUCTION


T I THOMAS J. TALTAVULL AR C HITECT Date 4.5.2005

Crawing Number

A1.2



.



THOMAS J TALTAVULL ARCHITECT 301.840 1847 DURA SLATE 12 12 FIN. FL. ATTIC ½ ROUND AL GUTTERS FINL CEILING. 2nd Date 4.5.2005 FIN. FL. 2ND FINL CEILING, 1st FIN. FL. 1ST FIN. PORCH EL. ™.™ite aine a airi baite a ai baite a airi a aire a aire. STONE FOUNDATION HAMMERHILL FREDERICK ROAD CLARKSBURG, MARYLAND PROPOSED ADDITION EXISTING HOUSE PROPOSED LEFT SIDE ELEVATION ALL DIMENSIONS & RELATIONSHIPS REQUIRE FINAL FIELD VERIFICATION PRIOR TO CONSTRUCTION. DO NOT SCALE DRAWING Drawing Number NOT FOR CONSTRUCTION A2.3

(

from past appl.

HAC liked it at last
Prelim

Neduum



RETURN TO: DEPARTMENT OF PERMITTING SERVICES
255 ROCKVILLE PIKE, 2nd FLOOR, ROCKVILLE, MD 20850
240/777-6370

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

			Contact Person: 1/16/0/5	reeke
0 -			Daytime Phone No.: 301	-349-0001
Tax Account No.: 0002	1673			
Name of Property Owner: VIC	TOR PEEKE	ι".	Daytime Phone No.:	349-0001
Address: PO BOX 4	189 CLATE	1.KSBURG	MARYLAND Staet	2087/
•	•			and the second s
Contractorr:	· :	<u> </u>	Phone No.:	
Contractor Registration No.:				
Agent for Owner: THOMAS	TALTAUULL	-ARCHITECT	Daytime Phone No.: 301-	840-1847
LOCATION OF BUILDING/PREM	IISE			
House Number: 23310		Street:	FREDERICK ROP	10
Town/City: CLARKSBU.	26	Nearest Cross Street:	STRINGTOWN R	OAD
Lot: Block:	Subdivision:			
RART ONE: TYPE OF PERMIT	ACTION AND USE			· · · · · · · · · · · · · · · · · · ·
1A. CHECK ALL APPLICABLE:	NOTION AND SOL	CHECK ALL	APPLICABLE:	•
☐ Construct ☐ Extend	□ Alter/Repoyets	* 2	☐ Slab	: Devel Devl Devl
_				_
			☐ Fireplace ☐ Woodburning Stov	•
☐ Revision ☐ Repair		☐ Fence/W	/áll (complete Section 4)	er:
1B. Construction cost estimate:	,		1	
1C. If this is a revision of a previous	sly approved active permit, s	ee Permit #	,	
PART TWO: COMPLETE FOR N	EW CONSTRUCTION AN	ID EXTEND/ADDITION	ONS	
2A. Type of sewage disposal:	01 Wssc	02 🗆 Septic	03 C Other:	
2B. Type of water supply:	01 ☑ WSSC	02 🔲 Well	03	
	·			
PART THREE: COMPLETE ONL	Y FOR FENCE/RETAINING	<u> WALL</u>		
3A. Height feet	inches			
3B. Indicate whether the fence or	retaining wall is to be const	tructed on one of the fo	ollowing locations:	
On party line/property line	☐ Entirely on la	and of owner	☐ On public right of way/easeme	ent .
I hereby certify that I have the auth	ority to make the foregoing	application, that the a	pplication is correct, and that the cor andition for the issuance of this perm	nstruction will comply with plans
approved by all agencies listed and	A Landowicage and	accept this to be a ci	onalidon for the issuance of this perif.	и.
Munn !!	betten		MAY	18 2005
	vner or authorized agent		10147 1	18, 2005 Date
				· · · · · · · · · · · · · · · · · · ·
Approved:		For Chairp	erson, Historic Preservation Commiss	ion
Disapproved:	Signature:		D	ate:
Application/Permit No. 3	93930/	Nata Fil	ed: 5-/8-05 Date Issu	

SEE REVERSE SIDE FOR INSTRUCTIONS