35/13-06D 4 West Melrose St Chevy Chase Village Historic District, 35/13

FAX TRANSMITTAL SHEET

Historic Preservation Office Department of Park & Planning

Telephone Number: (301) 563-3400

Fax Number: (301)-563-3412

TO:	MANA	FAX NUMBER: 701-901-97	_
FROM:_	Michae of	XVS	
DATE:_	3/9/06		
NUMBE	R OF PAGES INCL	UDING THIS TRANSMITTAL SHEET: 6	· .
NOTE:			
·	BARTLET	T APPROVAL!	_
			_
·			-
			· .
			-
			_

MEMORANDUM

TO:

Robert Hubbard, Director

Department of Permitting Services

FROM:

Michele Oaks, Senior Planner

Historic Preservation Section, M-NCPPC

SUBJECT:

Historic Area Work Permit # 412067 Tree removal, retaining wall replacement, patio and

Date: March 9, 2006

fence installation and landscape alterations to 4 West Melrose Street, Chevy Chase

Village Historic District

The Montgomery County Historic Preservation Commission (HPC) reviewed the attached application for a Historic Area Work Permit (HAWP) at its public hearing on <u>March 8, 2006</u>. This application was **APPROVED** with a condition. The condition of approval was:

• The applicants will obtain a variance from Chevy Chase Village for proposed fence prior to installation.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED AND CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HISTORIC AREA WORK PERMIT (HAWP) CONDITIONS.

Applicant:

Edmund and Mary Bartlett

Address:

4 West Melrose Street, Chevy Chase (Chevy Chase Village Historic District)

This HAWP approval is subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will contact the Historic Preservation Office if they modify or make any alterations to the approve plans.

DPS -#8



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person Many or Ed Dartlet	T
ax Account \$10: 06454561 Daysime Priorie No.: 301-718-7288 a	801-718-1622
tame of Property Owner Edmund + Mary Bartlett Daysone Phone No. 301-718-7288 on 30	11-718-1622
18diess: 4 W. Metrose Street, Chery Chase MD 20815	
interests. Jopal Construction Co Inc Proceeds. 301-674-3888	
Contractor Registration No: MD Lisc # 16825	
Agentin Owner Katie Roberts urchitect Gayama Promo No. 703-538-4347	
COCATION OF BUILDING PREMISE	
House Humber:	
Townstity. Newwest Cross Street.	
Con Book Subposion	
tiberFolio:Parcet	
PART ONE: TYPE OF PERMIT ACTION AND USE	
1A CHECK ALL APPLICABLE. CHECK ALL APPLICABLE:	
Constitute O Extend O Attentionerse O AVC To State O South Addition O Potels O Book To Shed	
☐ Move ☐ Install Wheck/Hard ☐ Solar ☐ Fireplace ☐ Woodburning Stove ☐ Single Family	
C. Revision (Report C. Revocable V Fence/Well(complete Section 4) C. Other	
18. Construction cost estimate: \$ \$5,000	
1C. If this is a revision of a previously appraved active permit, see Fermit # NO	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITIONS	•
2A Type of Servage dispase! 91 (1) WSSC 92 (2) Septio 93 (3) Other:	
28. Type of water supply: 01 (D WSSC 92 E) Well 93 E Other:	
	· on face of
PART THREE COMPLETE ONLY FOR FENCE/RETAINING WALL 34 Height for inches 3'ictaining would + 6' wooden fence, replacing 35 Indicate whether the leave or retaining wall is to be constructed on one of the following locations: 36 Party line/property line Entirely on land of owner 30 Dn public right of wey/easement	existing wall & tence of
Same	height
© Co party line/property line Ethically on land of owner	V
To be bank with bathers are an extension of the second sec	· -
I hardwiserial that I have the evaluate to make the loregoing application, that the application is correct, and that the construction will comply with plans approved by all agencies fisted and I hereby advantingly and observing the secondary for the issuance of this permit.	
Mary T. Barklett February 15, 2	D∂6
Approved. X Rev Chairperson, Minimize Pulsafilation Commission	wi
Disepproved Signature Villa William Date 3 9/06	
1117016	

SEE REVERSE SIDE FOR INSTRUCTIONS



THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

WRITTEN DESCRIPTION OF PROJECT

<u>ځ.</u>	Description of existing structure(s) and environmental setting, including their historical features and significance:
	The existing wall between 4 W. Melrose St + 6 W. Melrose St. (Perry i)
	is in danger of falling over and needs to be replaced. The facade of
	brick and cindeblock can be improved. The existing fence is falling
	Journ, now propped up on the Perry's side. The historic significance
	of the retaining wall and fence do not lie in the aesthetics but
	in the fact that they exist at their current heights, considering
	the tojography of the land, a change in height would be
	jarring.

b. General description of project and its effect on the historic resource(s), the environmental setting, and, where explicable, the historic district:

Our project replaces the retaining wall with a structually strand to a stleetically pleasing one. It provides a brick facing on the Perry's side, running the full langth of the property, capped in flagstone. The new fence, set in the wall, is in keeping with the others surrounding 4W. Melvose St. In addition, we plan to remove a sleb of concrete + build a flagstone + brick patro, remove 2 diseased + dying trees. Those trees will be replaced by planting 7 new ones plus shrubs, siteplatic enhancing the historic t environmental resource.

Site and environmental setting, drawn to scale. You may use your plst, Your site plan must include:

- a. the scale, north errow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as waikways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred.

- a Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context.

 All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and menufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS


- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.


6. TREE SURVEY

If you are proposing construction adjacent to or termina the product of any tree 8" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the site, location, and species of each tree of at least that dimension.

1 ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS See attacked hist

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and tip codes. This list should include the owners of all lots of parcels which adjoin the barcel in question, as well as the owner(s) of lot(s) or parcel(s) which tie directly across the street/highway from the parcel in question, You can octain this information from the Department of Assessments and Taxation, 51 Monroe Street, Bockville, (301/279-1355)





POTESTANDA TOPANA TOPAN

CHART 123@ AOL. COM E DATE

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

4 West Melrose Street, Chevy Chase

Chevy Chase Village Historic District

Meeting Date: 3/8/2006

Resource:

Contributing Resource

Report Date: 3/1/2006

Review:

HAWP

Public Notice: 2/22/2006

Case Number: 35/13-06D

Tax Credit:

N/A

Applicant:

Edmond and Mary Bartlett

(Katie Roberts, Agent)

Staff:

Michele Oaks

PROPOSAL: Tree removal, retaining wall replacement, patio and fence installation and landscape

alterations

RECOMMEND: Approve

ARCHITECTURAL DESCRIPTION

SIGNIFICANCE:

Contributing Resource in the Chevy Chase Village Historic District

STYLE:

Tudor Revival

PERIOD OF SIGNIFICANCE: 1916-1927

PROPOSAL:

The applicants propose to:

- 1. Replace in-kind the existing brick wall, which encloses the left side yard of the house. The new brick wall will be installed in the same location and at the same height of the existing. The wrought iron gate will be re-used in the new wall.
- Repair and replace in-kind, as needed, the brick patio located in the left, side yard. The 2. dimensions of the patio will not increase.
- Remove a 30" diameter Norway Maple from the northeast corner of the property. The Chevy 2. Chase arborist has approved the removal of this tree.
- Remove a 15" diameter American Holly from the southeast corner of the property. The 3. Chevy Chase arborist has approved the removal of this tree.
- Install (5) new trees on the subject property, to include two (2), white Redbud trees; two (2) 4. Cryptomeria and one (1), upright magnolia tree.
- 5. Re-locate two (2), Foster Maples in the rear yard from the southeastern corner to the southwestern corner of the yard.
- Re-install 48" high, hinged, diagonal, lattice panels to shield the existing A/C units. 6.

- 7. Remove the existing concrete slab, basketball court in the rear yard (southwestern corner) and install a new, flagstone patio and walkway (from new patio to the existing rear deck). The patio's corners will be detailed with tree boxes that will house the new, white redbud trees.
- 8. Replace the existing concrete retaining wall, which runs along the western (side) property line with a new brick retaining wall of the same height.
- 9. Install a new, 6'6" fence on top of the new retaining wall to replace the existing, 6'6" stockade fence and install a new, 6'6" gate to replace the existing 6'6" gate that abuts the front plane of the house and connects to the fencing.

APPLICABLE GUIDELINES:

When reviewing alterations contributing resources within the Chevy Chase Village Master Plan Historic District two documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the Montgomery County Code Chapter 24A (Chapter 24A) and the Chevy Chase Village Guidelines adopted as part of the Amendment to the Bethesda-Chevy Chase Master Plan in 1997. The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A

A HAWP permit should be issued if the Commission finds that:

- 1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
- 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.
- 3. The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archaeological, architectural or cultural value of the historic site or historic district in which an historic resource is located.

Chevy Chase Village Guidelines

The *Guidelines* break down specific projects into three levels of review - Lenient, Moderate and Strict Scrutiny.

"Lenient Scrutiny" means that the emphasis of the review should be on issues of general massing and scale, and compatibility with the surrounding streetscape, and should allow for a very liberal interpretation of preservation rules. Most changes should be permitted unless there are major problems with massing, scale or compatibility.

"Moderate Scrutiny" involves a higher standard of review than "lenient scrutiny." Besides issues of massing, scale and compatibility, preserving the integrity of the resource is taken into account. Alterations should be designed so that the altered structure still contributes to the district. Use of compatible new materials, rather than the original building materials, should be permitted. Planned changes should be compatible with the structure's existing design, but should not be required to replicate its architectural style.

"Strict Scrutiny" means that the planned changes should be reviewed to insure that the integrity of the significant exterior architectural or landscaping features and details is not compromised. However, strict scrutiny should not be "strict in theory but fatal in fact" i.e. it does not mean that there can be no changes but simply that the proposed changes should be reviewed with extra care.

The *Guidelines* that pertain to this project are as follows:

- Fences should be subject to strict scrutiny if they detract significantly from the existing open streetscape. Otherwise, fences should be subject to moderate scrutiny if they are visible from the public right-of-way, lenient scrutiny if they are not.
- Tree removal should be subject to strict scrutiny and consistent with the Chevy Chase Village Urban Forest Ordinance.
- Lot coverage should be subject to strict scrutiny, in view of the critical importance of preserving the Village's open park-like character.

STAFF DISCUSSION:

The proposed projects will not negatively impact the existing historic integrity of the site and will be sympathetic to the architectural design of the existing house and compatible with the adjacent historic resources. This proposal meets the criteria outlined in the *Chevy Chase Village Guidelines*. Staff recommends approval.

STAFF RECOMMENDATION

Staff recommends that the Commission *approve* the HAWP application as being consistent with Chapter 24A-8(b)1, 2 and 3:

and with the Chevy Chase Village Guidelines adopted in 1997.

with the general conditions applicable to all Historic Area Work Permits that the applicant shall also present three (3) permit sets of drawings to HPC staff for review and stamping prior to submission for building permits or the commencement of the project.

Application for Historic Area Work Permit 4 W. Melrose Street, Chevy Chase, MD 20815

#7 Addresses of adjacent and confronting property owners:

Adjacent:

Mr. and Mrs. Thomas Marvaso, 2 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Thomas W. Perry, Jr., 6 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Jonathan E, Colby, 6000 Connecticut Avenue, Chevy Chase, MD 20815

Mr. and Mrs. Luis Medeiros, 3 W. Lennox St., Chevy Chase, MD 20815

Mr. and Mrs. Andrew Steinberg, 5 W. Lennox St., Chevy Chase MD 20815

Confronting:

Mr. and Mrs. P. Alexander Smith, 1 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Wilfred L. Goodwyn, III, 3 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. John J. McMackin, 5 W. Melrose St., Chevy Chase, MD 20815

The information shown hereon has been prepared without benefit of a Title Report, therefore, may not reflect all easements or encumbrances which may affect subject property.

LOT

10

Notes:

- 1) Flood zone "C" per H.U.D., panel No. 0175C.
- All property corners have been recovered or set and verified per field survey performed: June 5, 1996.

I.P.F. Indicates iron pipe found.
 I.P.S. Indicates iron pin & cap set.



100.04(SURVEY) WESTERLY 100.00 (RECORD) I.P.F. SURVER LOT 7 12,500 = (TOTAL) PATIO PT. 8 وتحصك P.B. 62 P. 5327 0,11 FRAME DECK 10.9 數 12.2 2 STORY BRICK ! FRAME NN N 67.0 5 BRICK I.P.F. EASTERLY 100.00 (RECORD) 99.97 (SURVEY)

W. MELROSE STREET


PLAT OF SURVEY LOTS 7 AND PARTS OF 6 \$8 BLOCK 43 SECTION 2


CHEVY CHASE

MONTGOMERY COUNTY, MARYLAND

Building Line and/or Flood Zone Information is taken from Available Sources and is Subject to Interpretation of Originator.

SURVEYOR'S CERTIFICATE "I HEREBY CERTIFY THAT THE INFORMATION SHOWN HEREON HAS BEEN BASED UPON A FIELD SURVEY PURSUANT TO THE DEED OR PLAT OF RECORD PROPERTY MARKERS HAVE BEEN FOUND OR PLACED AND VERIFIED TO BE IN RELATIVE AGREEMENT WITH THE RECORD INFORMATION AS	REFERENCES PLAT BK. B 2 PLAT NO. 48 (06	SNIDER & ASSOCIATES SURVEYORS - ENGINEERS LAND PLANNING CONSULTANTS 2 Professional Drive, Suite 216 Gaithersburg, Maryland 20879 301/948-5100, Fax 301/948-1286	
SHOWN." SHOWN." JEFFLEY A. FOOTE: MAYLAND PROPERTY LINE SURVEYOR REC. NO. 207	LIBER ((779 FOLIO 322	DATE OF LOCATIONS WALL CHECK: HSE. LOC.: 6-5-96 PROP. CORS.:	SCALE: 1"=30' DRAWN BY: _15. JOB NO.: 96-1676
			-





<u>(G</u>

CONCEPT PLANTS 1-23-06 DESCRIPTION DATE PLANTING PLAN

CHEVY CHASE VILLAGE

5906 Connecticut Avenue Chevy Chase, Maryland 20815 (301) 654-7300

TREE REMOVAL PERMIT

Permit Number: 1538

Date Issued: February 13, 2006 Expires: February 13, 2007

Name of Property Owner: Address of Construction:

Mr. and Mrs. Edmund Bartlett

4 West Melrose Street

Chevy Chase, Maryland 20815

Contractor:

To be determined.

WORK TO BE DONE

Number of Trees to be Removed:

Two (2)

Species:

30-inch diameter Norway Maple,

15-inch diameter American Holly.

Location:

Left side and rear yards.

SPECIAL CONDITIONS

- Work must be completed by February 13, 2007.
- All debris must be hauled away by Contractor.
- Posting of commercial signs is prohibited.

Permit Fee: \$50.00

Appeal Fee: \$0.00

Fines: N/A

Total Fees Due: \$50.00 (PAID)

THIS PERMIT MUST BE POSTED

4 West Melrose Street


Tree Removal Request


Attached pictures shown extent of damage caused by the Norway maple on the northeast side of the house.


1) Bricks have been painted, sealed and a coping put on top of the wall over the years in an attempt to stop water from getting in the wall. The tree roots continue to grow and break the wall apart. The gate will not shut anymore as the tree roots have bent the metal support.

Note the line at the bottom of the wall near the bottom hinge of the gate. The whole wall has shifted out and will need to be rebuilt from the bottom up.

- 2) The next picture shows the same break in the bottom of the wall from a side angle. You can also see that the wall of the flower bed has separated from the main wall.
- 3) As the tree has grown, it has lifted all the bricks around it. The result has been a slope towards the house that acts like a funnel for water during heavy rainstorms. In heavy rain, we have running water in our basement that comes from this spot. We need to redo this patio, put waterproofing underneath the surface, and funnel the water towards the street.
- 4) Flower bed wall inside the wall is cracked and broken by the tree roots.
- 5) Fungus has developed on the trunk of the tree. It has been shrinking recently, but would seem to indicate that the tree is under stress.










#4 Tree Rook hour booker planter behind Tree &



HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address
Mr + Mrs Edmend Bartlett	Mrs. K. tre Roberts
	3607 NGlebe Rd
Chevy Chase MD 20815	3607 NGlebe Rd Arlington VAZZZO7
Adjacent and confronting	Property Owners mailing addresses
See attackment # 7	
	·

CHEVY CHASE VILLAGE

5906 Connecticut Avenue Chevy Chase, Maryland 20815 (301) 654-7300

TREE REMOVAL PERMIT

Permit Number: 1538

Date Issued: February 13, 2006 Expires: February 13, 2007

Name of Property Owner:

Mr. and Mrs. Edmund Bartlett

Address of Construction:

4 West Melrose Street

Chevy Chase, Maryland 20815

Contractor:

To be determined.

WORK TO BE DONE

Number of Trees to be Removed:

Two (2)

Species:

30-inch diameter Norway Maple, 15-inch diameter American Holly.

Location:

Left side and rear yards.

SPECIAL CONDITIONS

- Work must be completed by February 13, 2007.
- All debris must be hauled away by Contractor.
- Posting of commercial signs is prohibited.

Permit Fee: \$50.00

Appeal Fee: \$0.00

Fines: N/A

Total Fees Due: \$50.00 (PAID)

THIS PERMIT MUST BE POSTED

The information shown hereon has been prepared without benefit of a Title Report, therefore, may not reflect all easements or encumbrances which may affect subject property.

5


LOT

10

Notes:

- 1) Flood zone "C" per H.U.D., panel No. 01756.
- All property corners have been recovered or set and verified per field survey performed: June 5, 1996.
- I.P.F. Indicates iron pipe found: I.P.S. Indicates iron pin & cap set.





W. MELROSE STREET

PLAT OF SURVEY
LOTS 7 AND PARTS OF 6 \$ 8
BLOCK 43 SECTION 2

CHEVY CHASE

MONTGOMERY COUNTY, MARYLAND

Building Line and/or Flood Zone Information is taken from Available Sources and is Subject to Interpretation of Originator.

REFERENCES SURVEYOR'S CERTIFICATE "I HEREBY CERTIFY THAT THE INFORMATION SHOWN HEREON HAS BEEN BASED UPON A FIELD SURVEY PURSUANT TO THE DEED OR PLAT OF RECORD. PROPERTY MARKERS HAVE BEEN FOUND OR PLACED AND VERIFIED TO BE IN RELATIVE AGREEMENT WITH THE RECORD INFORMATION AS SHOWN." SNIDER & ASSOCIATES SURVEYORS - ENGINEERS LAND PLANNING CONSULTANTS PLAT BK. B 2 2 Professional Drive, Suite 218 Gaithersburg, Maryland 20679 301/948-5100, Fax 301/948-1286 PLAT NO. 48 DATE OF LOCATIONS 1"=30" SCALE: LIBER 11779 WALL CHECK: DRAWN BY: J.S. HSE. LOC: 6-5-96 **FOLIO** 322 HAYLAND PROPERTY LINE SURVEYOR REC. NO. 207 JOB NO.: 96-1676 PROP. CORS.

P1	tohosai		
JOPAL CONSTRU	CTION COMPANY, INC.		
5621 Gr	Ariffith Farm Road MO LIC# 16825		
	MARYLAND 20855 (301) 330-4797 V4 LIC # 2705033492A		
Cell#301-	-674-3888 DCLIC# 01317		
PROPOSAL SUBMITTED TO Mr. & Mrs. Bar Tlett BITHER	PHONE 1-26-06		
4 West- Melvose st.	Bartlett Residence		
CITY, STATE and ZIP COUR	4 West Melrosest.		
Men chare MD ARCHITECT FOR 703.539-6126 DATE OF PLANS Kate R. berts	chery chase MD JOB PHONE		
We hereby aubmit specifications and ostimates for:			
Remove existing fence and block u	vall 3 900 =		
	starting at 3-3.5 Hou neighbors		
	12" H at street end total		
length of well aprox. 120 linear +	FT. Froting to be 24" below lowest		
Grade and 30 will Brild 7	Brok colomos 6" 4"H - 16 x 24" w/		
a Flagstone cap. Well to have a Flagstone cap. 18,000 -24,800-			
Buildnew Flagstone Terrace-steps-remove concrete-14,450-			
Bild brock planters u/ playstone cap 8400 -			
Remove brick frontwell. Build new low 12" H well + 3150 00			
Relay sun Ken brick at gete - repoint - repair existing con wall			
on a T/M Basis 2 Men 1200 per hour.			
Plantremovul - resoding - Fence, by others.			
Permits by owner - Must have access on neighbors side. Ac units.			
electrical most be moved by others.			
The propose horoby to furnish material and labor	or — complete in accordance with above specifications, for the sum of:		
Fifty four thousand seven hundred - dollars is 54,700 -,			
1/3 down pay ment - 1/3 mid - point. Remaining balance at			
completion of work.			
All material is guaranteed to be as specified. All work to be completed in a work manner according to standard practices. Any alternation or deviation from above specific methods according to standard practices. Any alternation of deviation from the property process.	cilications Construes 9		
involving oxtra costu will be executed only upon written orders, and will become a charge over and allowe the uclimate. All agreements contingent upon strikes, as or delays impand our contint. Owner to carry line, ternado and other necessary ins	accidents Attitudents		
Our workers are fully covered by Workman's Compensation Insurance.	WILLIAM TO BE I THE SCHEDISCH WITHOUT COUNTY		
Acceptance of Proposal — The above prices, specifi	illeations		

and conditions are satisfactory and are hereby accepted. You are authorized. Signature to do the work as specified. Payment will be made as cuttined above.

Date of Acceptance: ..

Signaturo ...

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

. Description of existing structure(s) and environmental setting, including their historical features and significance:
The existing wall between 4 W. Melrose St + 6 W. Melrose St. (Perry's)
is in danger of falling over and needs to be replaced. The facade of
brick and cinderblock can be improved. The existing fence is falling
down, now propped up on the Perry's side. The historic significance
of the retaining wall and fence do not lie in the agesthetics but
in the fact that they exist at their current heights, Considering
the topography of the land, a change in height would be
jarring
J = J

b. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:

Our project replaces the retaining wall with a structurally sound taes the ticulty pleasing one. It provides a brick facing on the Perry's side, running the full langth of the property, capped in flagstone. The new fence, set in the wall, is in keeping with the others surrounding 4W. Melvose St. In addition we plan to remove a slab of concrete + build a flagstone + brick patho, remove 2 diseased + dying trees. Those trees will be replaced by planting 7 new ones plus shrubs, siteplan enhancing the historic renormental resource.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, lences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 6 1/2" x 11" paper are preferred.

- a Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other lixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in telesion to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations crawlings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each lacade of existing resource, including details of the effected portions. All labels should be placed on the front of photographs.
- b. Clearly tabel photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All tabels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the discuss of any tree 6° or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the site, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS See attacked list

For ALL projects, provide an accurate list of adjacent and configuring property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the barcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, S1 Monroe Street, Rockville (301/279-1355)

Edia 6/21/99


DPS - #


HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

contact reson: Intam or La Car III.	
Daytime Phone Ho.: 301-718-7288 on 3	01-718-1622
Tex Account \$20: 06 45 45 61	
Name of Property Owner: Edmund Thary Dartiett Daytime Proce Ro. 301-718-7288 Oc 301	1-718-1622
Fully Street Hampier Chy Chase MD 20815 Street Street Chevy Chase MD 20815 Street Street Street 20 Code	
Construction Co Inc Proces No. 301-674-3888	
Contractor Registration No.: MD Lisc # 16825	
Agent to Develore Phone No.: 703-538-4343	
EQCATION OF BUILDING PREMISE	
House Womber:	
TownsCity: Nesteed Cross Street:	
Est: Subdivision	
Liber: Folio: Facel:	
PART ONE: TYPE OF PERMIT ACTION AND USE	
TAL CHECK ALL APPLICABLE. CHECK ALL APPLICABLE:	
G Construct C Extend C Alter/Renovate C AC C State C Room Addition C Porch C Deck C Shed	
☐ Move ☐ Install ☐ Wheckfried ☐ Solar ☐ Freplace ☐ Woodburning Store ☐ Single Family	
☐ Revision Repair □ Heinscattle	
18. Construction cost estimate: \$ \$\overline{T}\$, 000	
IC. Il this is a revision of a previously approved active permit, see Permit * NO	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDITIONS	
2A Type of sewage disposel 01 🔾 WSSC 02 🔾 Septic 03 🔾 Other:	
28. Type of wester supply: 01 🗆 WSSC 02 🗇 Well 03 🗇 Other:	
PARTTHREE: COMPLETE ONLY FOR FENCE AFTAINING WALL 36. Height issue inches 3' retaining wall + 6' wooden fence, replacing of the following locations: 5 ame	100 + fence of
34. Height son inches 3'retaining wall + 6' wooden fence, replacing &	xisting water
56. Indicate whether the feace or retaining wall is to be constructed on one of the following locations:	Keight
1) On party line/property line	
I hereby cently that I have the authority to make the laregoing application, that the application is correct, and that the construction will comply with plans approved by all approces listed and I bereby acknowledge and accept this to be a condition for the issuance of this pennit.	
Mary T. Bartlett February 15, 20	06
Square of conce or subscried agent	
The Market Marke	
Approved: For Chairperson, Historic Preservation Commission	
Disapproved: Signature: Care:	
Application/Perind No. 4 LOU Date Filed: Date Issued	

SEE REVERSE SIDE FOR INSTRUCTIONS






Katherine Roberts Landscape Design

ZESIDENCE

PLANTING PLAN



Katherine Roberts Landscape Design

3807 N. Globe Re Arlington, VA 222 Ph: 703-538-434 Eav: 203-538-434

T RESIDENCE Melrose St CHASE, Mo

ONCOT FLATO

L-2

Application for Historic Area Work Permit 4 W. Melrose Street, Chevy Chase, MD 20815

#7 Addresses of adjacent and confronting property owners:

Adjacent:

Mr. and Mrs. Thomas Marvaso, 2 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Thomas W. Perry, Jr., 6 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Jonathan E, Colby, 6000 Connecticut Avenue, Chevy Chase, MD 20815

Mr. and Mrs. Luis Medeiros, 3 W. Lennox St., Chevy Chase, MD 20815

Mr. and Mrs. Andrew Steinberg, 5 W. Lennox St., Chevy Chase MD 20815

Confronting:

Mr. and Mrs. P. Alexander Smith, 1 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. Wilfred L. Goodwyn, III, 3 W. Melrose St., Chevy Chase, MD 20815

Mr. and Mrs. John J. McMackin, 5 W. Melrose St., Chevy Chase, MD 20815

Proposal

IAPAI	CONSTRUC	TION	COMPANY	INC
JALVE	CONSINUC	LIUIN	COMIL VIAIT	INL.

5621 Griffith Farm Road ROCKVILLE, MARYLAND 20855 Phone: (301) 330-4797

MD LICH 16825 VA LICH 2705033492A

Ce # 301-	-674 -3888	DCLIC# 01317	
PROPOSAL SUBMITTED TO	PHONE	DATE	
Mr. FMrs Bar Tlett	NOT MANEE	1-26-06	
GITY, STATE and SIT COOPE	Bartleff	Residence	
Chew chave MD	4 west	Melroust:	
AHCHITECT FAX 703.538-6126 DATE OF FLANS	chery cha	1.00199000	
Tate Roberts We hereby submit specifications and ostimatos for:	Day one	LE MIL	
Remove existing france and block u	all	3 900-	
Brild new Drickwall 12 wide	starting at	3-3.5 Hou neighbors	
side - 2" above on owner's side to	-	, , , , , , , , , , , , , , , , , , , ,	
length of well aprox, 120 linear 1	FT. Froting to	5 be 24" below lowest	
Grade and 30 will . Brith 7	brick colours	64"4-16-24"0/	
a Flag stone cap. Well to have a Fla			
Brildnew Flagstone Terrece - ste	ps-remove	oucrete14,450-	
Bild brick planters u/ Playston		8400 —	
Remove brick frontwell. Build	men low 12"	H well + _ 3150 00	
Relay sun Ken brick at gete - repoint - repair existing you wall			
on a T/M Basis 2 Men 120	o = per hour		
Plantremovul - resoding - Fence	• ,		
Permits by owner - Must have access on neighbors side. Ac units.			
electrical most be moved by others.			
The propose hereby to furnish material and labor — complete in accordance with above specifications, for the sum of: The sum the sum of the			
Fifty four thous and seven hundred		in a balance et	
	nt. Remain	ung varance ex	
Completion of work.	okroveniik sa		
manner according to standard practices. Any allocation or deviation from above specimenting extra costs will be executed only upon written orders, and will become	cilications Authorized Of	out ?	
charge over and above the retirects. All agreements contingent upon strikes, or delays brigand our control Owner to carry tire, ternade and other necessary in Our workers are fully covered by Workman's Compensation Incurance.	accidents Note: Ti	nis proposal may be not accepted within	
2	V		
Acceptance of Propusal — The above prices, speciand conditions are satisfactory and are hereby accepted, You are a			
to do the work as specified. Payment will be made as cuttined above			
Date of Acceptanos:	Signaturo	and the second s	

4 West Melrose Street


Tree Removal Request

Attached pictures shown extent of damage caused by the Norway maple on the northeast side of the house.


1) Bricks have been painted, sealed and a coping put on top of the wall over the years in an attempt to stop water from getting in the wall. The tree roots continue to grow and break the wall apart. The gate will not shut anymore as the tree roots have bent the metal support.

Note the line at the bottom of the wall near the bottom hinge of the gate. The whole wall has shifted out and will need to be rebuilt from the bottom up.

- 2) The next picture shows the same break in the bottom of the wall from a side angle. You can also see that the wall of the flower bed has separated from the main wall.
- 3) As the tree has grown, it has lifted all the bricks around it. The result has been a slope towards the house that acts like a funnel for water during heavy rainstorms. In heavy rain, we have running water in our basement that comes from this spot. We need to redo this patio, put waterproofing underneath the surface, and funnel the water towards the street.
- 4) Flower bed wall inside the wall is cracked and broken by the tree roots.
- 5) Fungus has developed on the trunk of the tree. It has been shrinking recently, but would seem to indicate that the tree is under stress.












4 Tire. Rook have broken planter Schind Tree





HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address
Mr + Mrs Edmend Boxtlett	Mrs. Kutre Roberts
4 W. Melrose St	-13 11 Claha Dd
1 7 W. 16. 2 3 3 3 8 5	3607 NGlebe Rd
Chavy Chase MD 20815	Arlington VAZZZO7
	9
Adjacent and confronting Property Owners mailing addresses	
See attackment # 7	
	·









Katherine Roberts Landscape Design

3607 N. Glebe Road Arlington, VA 22207 Ph: 703-538-4343 Fax: 703-538-6128

A WEST MELROSE ST CHEVY CHASE, MD

CEPT PLANTS 1-23-06 L PETRMIT 2-8-06

SCRIPTION DAT

PLANTING PLAN

L-2

4 West Melrose Street

Wall Replacement Project

Attached pictures show the existing wall between our house and 6 West Melrose Street (Carter and Tom Perry).

- 1) From the street looking south. The wall is low to start and rises to approximately three feet above ground level as it traverses toward the back of the property. The wall is slightly above ground level on our side and averages three feet on the Perry's side.
- 2) The next picture shows the wall from the side of the front gate. The wall was not built wide enough to withstand the pressure of the ground from our side. The angled tree is holding up our rotted wooden fence.
- 3) This view is from the south end of the Perry's backyard looking north towards West Melrose Street. Much of the wall is exposed cinder block with a brick coping on top. Our proposed renovation has a complete brick facing on this wall. This picture also shows our wooden fence leaning into the Perry's backyard.
- 4) This picture shows the end of the wall looking back towards West Melrose Street. This wall was clearly built poorly and inexpensively. It is on an angle like this for basically it's whole length.
- 5) Our wooden fence looking north towards West Melrose Street. Many of the vertical posts are broken and many of the slats have rotted out at the bottom




1 From W. Melasse looking South



Melass St. looking South

3 View from back good of 6 W. Melnos a looking worth





4 End of Wall looking worth

\$ 2 Enlan + hothing beace booking don'th

