31/07-04 2801 Beechbank Rd Capitol View Park Historic District



HPC Stoff COD)

November 15, 2004

Mr. Alan Adler
Arbor Homes, LLC
10311 Naglee Dr.
Silver Spring, MD 20903

Dear Alan:

Attached is the specimen tree inventory with comments for the large trees on your site at 2801 Beechbank Road in Silver Spring.

I have updated the inventory that was provided with the base map regarding species and diameter. You will also notice that I have drawn in the dimensions of the critical root zones (CRZ) for the more important trees. I omitted the CRZ for a few trees that were not preservation candidates. These were trees #5, 6 & 7 which are located along the stream bank. These trees are in such poor condition that I do not feel that any special tree preservation efforts are warranted. In fact, they are not highly impacted by the future development of this parcel, but I would not recommend directing a significant portion of your tree preservation funds to these trees.

The trees with which I am most concerned include #'s 9, 10, 11, 12 & 14. They are behind the proposed addition and are in good condition. Unfortunately, the best tree of this group is #13 a pignut hickory. It is so close to the new addition, however, that it is not a realistic preservation candidate. However, these are very durable trees, so you may want to consider trying to preserve this tree, despite the low likelihood of survival.

The average CRZ loss for tree #'s 9, 10, 11 & 12 is approximately 25-30%. This is within acceptable limits for these trees, but the 30% loss for tree #9 is a bit much for a tulip poplar. I do feel, however, that despite this root loss, it is worth trying to save this tree. It has a smaller than normal crown because of the tight growing conditions. This may help with tree preservation because it may also have a smaller root system. Tree #'s 11 & 12 are oaks which are much more durable regarding root loss and I do not anticipate any major problems with these trees over the next 3-5 years.

There has already been some root loss toward your house due to recent excavation. And, I understand that the adjoining lot will be developed for a single family residence which will remove even more CRZ. However, the existing excavation has removed approximately 20% of the CRZ, and the development in the adjoining lot will remove another 10%. This 30% is really the maximum you would want to lose on a large mature

white oak. But, I think that because the tree is in such good condition, and with proper root protection measures, I do feel that we could save this tree.

If your plan for this lot still includes adding a sunken terrace off the left rear corner of the existing house, this may mean more CRZ loss and this may be too much for this tree. This really is a great tree and I would encourage you to work to preserve it. White oak is resilient to CRZ loss, and with some remedial work I do feel that we can keep it in the landscape.

Tree #2 has also been significantly damaged by the clearing operations in the adjacent lot. This is a large and unusual oak and certainly worthy of preservation efforts. I have not seen before such a large shingle oak in this area. They are considered to be quite hardy and durable. Therefore, at this point, I think it will survive this construction activity. However, I do recommend more intensive preservation efforts be made around this tree in the future.

In summary, I have noted where root pruning is recommended with a dashed line around your new addition. I have also drawn in with a solid line the area recommended for tree protection fencing. It will be very important to install tree protection fencing that cannot be easily moved and where machinery and stockpiling of materials is excluded. It will also be important to pad the exposed areas outside of this fencing, and yet still within the CRZ, throughout the construction process. And, as this project progresses, I would also like to recommend remedial treatments for the preservation candidates including tree growth regulators (TGR) and root stimulation treatments for the damaged trees. These treatments are best undertaken in the spring of next year.

This concludes the preliminary portion of the tree protection for this site. I do feel that there are some very good preservation candidates, and they are certainly worthy of some extra effort.

Thank you for the opportunity to offer these observations and recommendations. Once the final footprint of the new home is known, I will issue more detailed arboricultural specifications.

Sincerely.


Keith C. Pitchford

ISA Certified Arborist, MA-0178

MD Licensed Forester #675

MD Tree Expert #589





\$280) Beechbonk Rd Trees to removed: #13

						•	•																						•
4	3	2	-3		2806 Baec		7		13	12	11	10	8	8	7	6	5	4	3	2	-		2801 Beec		Trae *	The state of the s		The second second	
Pignut hickory	Tulip poplar	Shingle oak	Tulip poplar		bbark Rd.		White oak		Pignut hickory	White oak	Black oak	Southern red oak	Tuttp popter	Northern red oak	Northern red oak	Northern red oak	Southern red oak	Stippery elm	Tulip poplar	Shingle oak	Tulip popilar		hbenk Rd.		Common name				
Carya glabra	Lindendron fullationa	Quercus imbricaria	Lirkodenciron tulipifera			•	Quercus alba		Carya glabra	Quercus aba	Querous velutina	Querous fatoata	Lirlodendron tulipitara	Querous rubre	Quercus rubra	Quercus rubra	Querous falcata	Ulmus rubra	Liriodendron tulipitera	Querous imbricaria	Liriodendrun tulipitera				Scientific name	The state of the s	Boared by: Keith C. Plich	BEECHBANK ROAD, SI	SPECIMEN TREE SURVEY - ARBOR HOMES
Fair	Good-Exc.	Good-Exc.	Good				Good-Exc.		Good-Exc.	Good-Fair	Good-Fair	Good	Good	Good	Poor	Fair	Fair-Poor	Fair	Falt	Good-Exp	Good				Condition		ord, ISA Cer	VER SPRIN	RVEY - ARB
24	28	8	41				3 6		25	28	38	37	38	27	36	*	28	32	38	36	42						Arborist N	G MARYL	OR HOMES
24	42	8	61				45		25	36	37	\$6	2 2	33	47	43	35	23	57	47	ස				_	ن د. د	M-0178	8	
Heavy wisteria cover, declining	Heavy by cover, wisteria vine	Some minor d/w	Poison by and Eng. by on trunk				cracking at base	Major dAv, two stems, possible	Some ivy and epicormics	Lats of ivy, epicornics	LOTS of opicormics, minor div	Elevated crown, minor deadwood	Highly elevated crown	Stight lean, but OK	Poison ivy on trunk, top is dead	Bleeding cankers at base	Lost one leader, >15% lean	One large leader broken, sapsudicer	Major deadwood, sapsucker damage	Leaning, clearing in CRZ	Heavy ivy on trunk, small leaves				Conuncits	The state of the s			
	Pignut hickory Carya glabra Fair 24 24 He	Tulip poptar Lindendron tulipitara Good-Exc. 28 42 H Pignut hickory Carya glabra Fair 24 24 He	Shingle oak Quercus imbricaria Good-Exc. 26 26 Tulip poplar Liriodendron fullpillera Good-Exc. 28 42 H Pignut hickory Carye glabra Fair 24 24 He	Tulip poplar Liriodendran tulipifera Good 41 61 Pol Shingle oak Quercus imbricaria Good-Exc. 26 26 Tulip poplar Liriodendran tulipifera Good-Exc. 28 42 H Pignut hickory Carya glabra Fair 24 24 He	Tulip poplar Lirkodenchan tulipiliara Good 41 61 Pal Shingle oak Quercus imbricaria Good-Exc. 26 26 Tulip poplar Lirkodenchan tulipiliara Good-Exc. 28 42 H Pignut hickory Carya glabra Fair 24 24 He	Beechbartik Rd. Tulip poplar Linderndron tulipiflera Shingle oak Quercus imbricaria Good-Exc. 26 26 Tulip poplar Linderndron tulipiflera Good-Exc. 28 42 H Prignut hickory Carya glabra Fair 24 24 He	p poplar Liriodendron tulipifera Geod 41 61 Pol ngle oak Quercus imbricaria Good-Exc. 26 26 Pol p poplar Liriodendron tulipifera Good-Exc. 28 42 H	ite cak Quercus alba Good-Exc. 36 45 poplar Liriodendron tulipitera Good-Exc. 26 26 p poplar Liriodendron tulipitera Good-Exc. 26 26 p poplar Liriodendron tulipitera Good-Exc. 28 42 H d hickory Cerye glabra Fair 24 24 He	Itte calk Quercus alba Good-Exc. 36 45 Magnetic Alba Good-Exc. 26 26 Magnetic Linication (uliphiera Good-Exc. 28 42 Habitatory Carye glabra Fair 24 24 He	it hickory Carya plabra Good-Exc. 25 Mills calk Quercus alba Good-Exc. 36 45 Mills poplar Liriodendron tulipitara Good-Exc. 26 26 Polybor Liriodendron tulipitara Good-Exc. 26 26 Hickory Carya glabra Fair 24 24 He	ite oak Quercus aba Good-Fair 29 36 It hickory Carya plabra Good-Exc. 25 25 Ite oak Quercus alba Good-Exc. 36 45 Ite oak Quercus alba Good-Exc. 36 45 Ite oak Quercus inbricaria Good-Exc. 26 26 Ingle oak Quercus inbricaria Good-Exc. 26 26 Ite oak Quercus inbricaria Good-Exc. 28 42 H Ite oak Graya glabra Fair 24 24 He	nite oak Quercus velufina Good-Feir 30 37 i.u. iite oak Quercus aba Good-Feir 29 36 i.u. iite oak Quercus aba Good-Exc. 25 25 i.u. iite oak Quercus aba Good-Exc. 36 45 i.u. poplar Liriodendron fulipifera Good-Exc. 26 26 i.u. poplar Liriodendron fulipifera Good-Exc. 26 26 i.u. poplar Liriodendron fulipifera Good-Exc. 26 26 i.u. poplar Liriodendron fulipifera Good-Exc. 28 42 i.u. poplar Cerye glabra Fair 24 24 i.u.	en red oak Querous faloate Good 37 46 Elector oak Querous velufine Good-Fair 30 37 Lite oak Querous velufine Good-Fair 29 36 lite oak Querous alba Good-Exc. 25 25 Mite oak Querous alba Good-Exc. 36 45 Mite oak Querous alba Good-Exc. 36 45 Mite oak Querous alba Good-Exc. 36 45 Mite oak Querous imbricaria Good-Exc. 26 26 Polygie oak Querous imbricaria Good-Exc. 28 42 History Carye glabra Good-Exc. 28 42 History Carye glabra Fair 24 24 History	p poplar Linodendron fullpitlera Good 38 54 en rad oak Quercus faloata Good 37 46 Electric oak Quercus velufina Good-Fair 30 37 Lite oak Quercus alba Good-Fair 29 36 lite oak Quercus alba Good-Exc. 25 25 Mitte oak Quercus alba Good-Exc. 36 45 Mitte oak Quercus alba Good-Exc. 36 45 Mitte oak Quercus imbricaria Good-Exc. 36 45 Polygie oak Quercus imbricaria Good-Exc. 26 26 Highera Linodendron fullpitera Good-Exc. 28 42 Highera Carye glabra Fair 24 24 Highera Good-Exc. 38 42 Highera Carye glabra Fair 24 24 Highera Fair 24 Mitter Carye glabra Fair 25 Mitter Ca	m rad oak Querous rubra Good 27 33 p poplar Linodendron fullpillera Good 38 54 Eleman rad oak Querous faboata Good 37 46 Eleman rad oak Querous faboata Good-Fair 30 37 Lindany Cerya plabra Good-Fair 29 36 Lindany Cerya plabra Good-Exc. 25 25 Mille oak Querous alba Good-Exc. 36 45 Mille oak Querous alba Good-Exc. 36 45 Mille oak Querous imbricaria Good-Exc. 26 26 Polygie oak Querous imbricaria Good-Exc. 28 42 Highlight Good-Exc. 28 42 44 Highlight Good-Exc. 28 42 44 Highlight Good-Exc. 28 42 44 44 44 44 Highlight Good-Exc. 28 42 44 44 44 44 44 44 44 44 44 44	m red oak Quercus rubra Poor 38 47 Po m red oak Quercus rubra Good 27 33 p popplar Liriodendron fullpilera Good 36 54 p m red oak Quercus faloata Good 37 46 Eler net oak Quercus abba Good-Fair 30 37 14 ilite oak Quercus abba Good-Exc. 25 25 m ilite oak Quercus aba Good-Exc. 25 25 m ilite oak Quercus aba Good-Exc. 36 45 m ilite oak Quercus aba Good-Exc. 36 45 m ilite oak Quercus imbricaria Good-Exc. 36 45 p poplar Liriodendron fullpilera Good-Exc. 28 42 H ilite oak Quercus imbricaria Good-Exc. 28 42 H indoory Carya glabra Fair 24 24 He	ım red oak Quercus rubra Fair 34 42 ım red oak Quercus rubra Poor 38 47 Po ım red oak Quercus rubra Good 27 33 p poptiar Liriodendron fuliphiera Good 36 54 ite oak Quercus faloata Good-Fair 30 37 46 Ele ite oak Quercus aba Good-Fair 30 37 14 ite oak Quercus aba Good-Exc. 25 25 ithiduny Carya plabra Good-Exc. 36 45 ithiduny Garya plabra Good-Exc. 36 45 p poptiar Liriodendron fuliphiera Good-Exc. 26 26 14 p poptiar Liriodendron fuliphiera Good-Exc. 28 42 14	em red oak Quercus falcata Fair-Poor 28 35 L em red oak Quercus rubra Fair 34 42 em red oak Quercus rubra Poor 38 47 Po em red oak Quercus rubra Good 27 33 Po poplar Lifodendron fulipitera Good 36 54 Ele ek oak Quercus velutina Good-Fair 30 37 46 Ele ek oak Quercus aba Good-Fair 29 35 L ite oak Quercus aba Good-Exc. 25 25 M ite oak Quercus aba Good-Exc. 36 45 M ite oak Quercus imbricaria Good-Exc. 36 45 Pol gle oak Quercus imbricaria Good-Exc. 28 42 H indoory Carya glabra Fair 24 24 He	pary elm Ultraus rubre Fair 32 32 One m red oak Quercus falcata Fair-Poor 28 35 L m red oak Quercus rubre Fair 34 42 pm red oak Quercus rubre Poor 38 47 Poor red oak Quercus rubre Good 27 33 Poopler Lifodendron fulipitere Good 37 46 Elevic oak Quercus aba Good-Fair 29 36 14 lite oak Quercus aba Good-Fair 29 36 Lidany Cerya plabre Good-Fair 29 36 Lidany Cerya plabre Good-Exc. 25 25 Mille oak Quercus aba Good-Exc. 36 45 Poopler Lifodendron fulipitere Good-Exc. 36 45 Poopler Lifodendron fulipitere Good-Exc. 26 26 High oak Quercus imbricaria Good-Exc. 28 42 High hickory Cerya plabre Good-Exc. 28 42 High hickory Cerya plabre Fair 24 24 High hickory Cerya plabre Good-Exc. 28 42 High hickory Cerya plabre Fair 24 24 High hickory Cerya plabre Fair 25 High hickory Cerya plabre Fair 24 High hickory Cerya plabre Fair 25 High hickory	p poplar Liriodendron tulipitere Fair 38 57 Majo pary elm Liriodendron tulipitere Fair 32 32 One en red oak Quercus rubra Fair-Poor 28 35 1 m red oak Quercus rubra Fair 34 42 min red oak Quercus rubra Poor 38 47 Poor red oak Quercus rubra Good 27 33 Popplar Liriodendron tulipitera Good-Fair 29 36 Ele ck. oak Quercus aba Good-Fair 29 36 Ele de hickory Cenya plabra Good-Exc. 25 25 Mite oak Quercus aba Good-Exc. 36 45 Mite oak Quercus aba Good-Exc. 36 45 Mite oak Quercus aba Good-Exc. 36 45 Mite oak Quercus imbricaria Good-Exc. 36 42 Highlightera Cenya glabra Fair 24 24 Highlightera Cenya glabra Fair 24 Cenya Cenya glabra Fair 24 24 Highlightera Cenya glabra Fair 24 24 Highlightera Cenya glabra Fair 24 Cenya Cenya Ganda	ppoplar Liriodendron tulipifiere Fair 38 47 poplar Liriodendron tulipifiere Fair 38 57 Major pary elm Ulimus rubra Fair 32 32 One en red oak Quercus faicata Fair-Poor 28 35 1 m red oak Quercus rubra Fair 34 42 1 m red oak Quercus rubra Fair 34 42 1 poplar Liriodendron fulipifiere Good 27 33 1 ite oak Quercus aba Good-Fair 29 36 1 ite oak Quercus aba Good-Fair 29 36 1 ite oak Quercus aba Good-Exc. 25 25 Mait hickory Carya plabra Good-Exc. 36 45 Major poplar Liriodendron fulipifiera Good-Exc. 36 45 Major poplar Liriodendron fulipifiera Good-Exc. 36 45 Major poplar Liriodendron fulipifiera Good-Exc. 36 45 Popplar Liriodendron fulipifiera Good-Exc. 26 26 1 popplar Liriodendron fulipifiera Good-Exc. 26 26 1 popplar Liriodendron fulipifiera Good-Exc. 26 26 1 popplar Liriodendron fulipifiera Good-Exc. 28 42 H popplar Liriodendron fulipifiera Good-Exc. 28 42 H popplar Liriodendron fulipifiera Good-Exc. 28 42 H	popolar Liriodenctron fullpillers Good 42 63 Hagle calk Querous imbrioaria Good-Exa. 38 47 Majo poplar Liriodenctron fullpillers Fair 38 57 Majo pary elim Ultimus rubra Fair 32 32 One en red calk Querous faloata Fair 34 42 en red calk Querous rubra Fair 34 42 en red calk Querous rubra Good 27 33 47 Pc en red calk Querous rubra Good 37 46 Ele en red calk Querous rubra Good 37 46 Ele en red calk Querous velutina Good-Fair 29 36 47 Pc en red calk Querous velutina Good-Fair 29 36 Ele exk calk Querous abba Good-Fair 29 36 Ele en red calk Querous abba Good-Fair 29 36 Mite calk Querous abba Good-Exa. 25 25 Mite calk Querous imbricaria Good-Exa. 36 45 Pc poplar Liriodenctron tulipitera Good-Exa. 36 45 Pc poplar Liriodenctron tulipitera Good-Exa. 26 26 42 Hi hickory Carya glabra Good-Exa. 26 26 42 Hi hickory Carya glabra Good-Exa. 27 24 24 Hi	popler Liriodendran tulipifiers Good 42 63 Hage oak Quercus imbriceria Good-Exa. 38 47 popler Liriodendran tulipifiers Fair 38 57 Majo popler Liriodendran tulipifiers Fair 32 32 One am red oak Quercus rubra Fair 32 32 One m red oak Quercus rubra Poor 38 47 Pom red oak Quercus rubra Poor 38 47 Pom red oak Quercus rubra Good 27 33 popler Liriodendran tulipifiers Good 37 46 Ele ck. oak Quercus velufina Good-Fair 29 36 47 Pom red oak Quercus velufina Good-Fair 29 36 Ele ck. oak Quercus alba Good-Fair 29 36 Ele ck. oak Quercus alba Good-Exa. 25 25 Majo oak Quercus imbricaria Good-Exa. 36 45 Popplar Liriodendran tulipifiers Good-Exa. 36 45 Popplar Liriodendran tulipifiers Good-Exa. 36 42 Hage oak Quercus imbricaria Good-Exa. 37 42 44 Hage oak Quercus imbricaria Good-Exa. 37 42 44 Hage oak Quercus imbricaria Good-Exa. 37 42 44 Hage oak Quercus imbricaria Good-Exa. 44 42 Hage oak Quercus imbricaria Good-Exa. 44 42 Hage oak Quercus imbricaria Good-Exa. 44 44 44 Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Hage oak Quercus imbricaria Good-Exa. 44 44 Hage oak Quercus imbr	p popler Lirioderutrun fulipifiers Good 42 63 He gje oak Quercus imbricerite Good-Exa. 38 47 popler Lirioderutrun fulipifiers Feir 38 57 Mejo propler Lirioderutrun fulipifiers Feir 32 32 One min red oak Quercus rubra Fair 34 42 Promin red oak Quercus rubra Feir 34 42 Promin red oak Quercus rubra Good 27 33 47 Promin red oak Quercus velufina Good-Feir 30 35 14 Promin red oak Quercus velufina Good-Feir 30 37 46 Ele ak oak Quercus afba Good-Exa. 25 25 Mitte oak Quercus afba Good-Exa. 25 25 Mitte oak Quercus afba Good-Exa. 26 45 Mitte oak Quercus imbricaria Good-Exa. 26 46 Hite oak Quercus imbricaria Good-Exa. 26 42 Hite poplar Lirioderutran fulipifiera Good-Exa. 28 42 Hite hidany Carya glabra Fair 24 24 Hite hidany Carya glabra Good-Exa. 28 42 Hite hidany Carya glabra Fair 24 24 Hite hidany Carya glabra Good-Exa. 28 42 Hidany Carya glabra Good-Exa. 28 42 Hidany Carya glabra Good-Exa. 28 42 Hidany Carya glabra Good-Exa. 24 24 Hidany Carya glabra Good-Exa.	popplar Liriodendron tulipitara Good 42 63 Haggle oak Quercus inbriceria Good-Exx. 38 47 popplar Liriodendron tulipitara Fair 38 57 Majo popplar Liriodendron tulipitara Fair 38 57 Majo popplar Liriodendron tulipitara Fair 32 One mired oak Quercus rubra Good 28 32 One mired oak Quercus rubra Good 27 33 One mired oak Quercus rubra Good 27 33 Promite oak Quercus eluina Good-Fair 34 42 Promite oak Quercus eluina Good-Fair 29 36 54 lite oak Quercus alba Good-Fair 29 36 Mitte oak Quercus alba Good-Exc. 25 25 Majo poplar Liriodendron tulipitara Good-Exc. 36 45 Propoplar Liriodendron tulipitara Good-Exc. 36 45 Propoplar Liriodendron tulipitara Good-Exc. 26 26 Hag poplar Liriodendron tulipitara Good-Exc. 26 26 Hag poplar Cenye glabra Good-Exc. 26 26 Hag poplar Liriodendron tulipitara Good-Exc. 26 26 Hag popplar Cenye glabra Good-Exc. 26 26 Hag popplar Liriodendron tulipitara Good-Exc. 27 24 24 Hag popplar Cenye glabra Good-Exc. 28 42 Hag popplar Cenye glabra Good-Exc. 29 40 44 Hag popplar Cenye glabra Good-Exc. 29 42 4 Hag popplar Cenye glabra Good-Exc. 29 40 44 Hag popplar Cenye glabra Good-Exc. 20 40 41 Hag popplar Cenye glabra Good-Exc. 29 40 44 Hag popplar Cenye glabra Good-Exc. 29 40 44 Hag popplar	popplar Lindendrun fullpillars Good 42 63 Hagle oak Quercus inbricatis Good 27 38 47 Promited oak Quercus falcata Good 38 47 Promited oak Quercus falcata Good 38 47 Promited oak Quercus falcata Good 37 48 Elect oak Quercus falcata Good-Eac. 38 47 Promited oak Quercus falcata Good-Eac. 38 47 Promited oak Quercus falcata Good-Eac. 26 25 Mille oak Quercus alba Good-Eac. 26 25 Mille oak Quercus alba Good-Eac. 26 25 Mille oak Quercus indipitara Good-Eac. 26 26 Mille oak Quercus indipitara Good-Eac. 27 Al 61 Promite oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Hille oak Quercus indipitara Good-Eac. 28 42 Hille oak Quercus indipitara Good-Eac. 28 42 Hille	poplar Linodendron fullpiters Good 42 63 Hage poplar Linodendron fullpiters Good 42 63 Hage poplar Linodendron fullpiters Good-Exc. 38 47 popplar Linodendron fullpiters Fair 32 32 One mired oak Quercus falcets Fair 34 42 fin red oak Quercus falcets Good-Exc. 38 47 Pomired oak Quercus falcets Good 27 33 popplar Linodendron fullpiters Good-Exc. 36 54 Eleck oak Quercus falcets Good-Exc. 26 25 it it is oak Quercus falcets Good-Exc. 26 25 Mit is oak Quercus falcets Good-Exc. 26 45 Mit oak Quercus falcets Good-Exc. 26 45 Mit oak Quercus falcets Good-Exc. 36 45 Popplar Linodendron fullpiters Good-Exc. 36 45 Popplar Linodendron fullpiters Good-Exc. 36 45 Popplar Linodendron fullpiters Good-Exc. 36 42 Hage popplar Linodendron fullpiters Good-Exc. 26 26 Hage popplar Linodendron fullpiters Good-Exc. 26 42 Hage popplar Carya glabra Good-Exc. 26 42 Hage popplar Carya glabra Good-Exc. 26 42 Hage popplar Carya glabra Good-Exc. 26 42 Hage popplar Linodendron fullpiters Good-Exc. 27 24 Hage Popplar Linodendron fullpiters Good-Exc. 27 24 Hage popplar Linodendron fullpiters Good-Exc. 28 42 Hage popplar Linodendr	popler Lindendron tulpitere Good-Exc. 38 47 Heavy ivy on trunk, small lear popler Lindendron tulpitere Good-Exc. 38 47 Leaning, clearing in CRZ (n.) CRZ (n.) Comments gle oak Guercus riubra Fair 32 32 One leage leader token, sapsurater day need oak Quercus riubra Fair 34 42 Bleading centers at base in rod oak Quercus riubra Good-Exc. 38 47 Che leage leader token, sapsurater day popler Lindendron tulpitere Fair 34 42 Bleading centers at base in rod oak Quercus riubra Good 27 33 Lost one leader, >15% lean need oak Quercus riubra Good 27 33 Bleading centers at base in rod oak Quercus fatoata Good 37 44 Poison ivy on trunk, top is de m rod oak Quercus fatoata Good-Fair 29 36 Lost of epicormics, minor death rot rod oak Quercus saba Good-Fair 29 36 Lots of epicormics at history Carya plabra Good-Exc. 25 25 Some ivy and epicormics at history Carya plabra Good-Exc. 36 45 Cracking at base the oak Quercus able Good-Exc. 36 45 Cracking at base popler Lindendron tulpitera Good-Exc. 36 45 Cracking at base cracking at base fib oak Quercus inbricaria Good-Exc. 36 45 Poison ivy and Eng. Ivy on in gle oak Quercus inbricaria Good-Exc. 28 42 Heavy ind cover, dectin a history Carya plabra Fair 24 24 Heavy wisteria cover, dectin a history Carya plabra Fair 24 24 Heavy wisteria cover, dectin	BEECHBANK ROAD, SILVER SPRING, MARYLAND Propagate by: Keith C. Pitchford, ISA Cert. Antorist, MA-0178 Comments Bropher Lindenzhran fullpifere Good-Exc. 38 47 Leary by on trunk, small leave gle oak Querous inthroaris Good-Exc. 38 47 Learing, clearing in CRZ gle oak Querous faloats Feli 32 32 One large leader broken, sapsuid trans med oak Querous rubre Good-Exc. 38 47 Learing, clearing in CRZ The Bleoding canitars at base an red oak Querous rubre Good-Exc. 38 47 Learing, clearing in CRZ The Bleoding canitars at base an red oak Querous rubre Good-Exc. 38 42 Polson ivy on frunk, top is dear Thighit learn, but OK Bleoding canitars at base Good-Exc. 26 38 Alibitary Carya glebra Good-Exc. 36 Good-Exc. 36 Good-Exc. 36 Good-Exc. 36 Caracking at base Rejer daw, two sterns, possible Caracking at base Caracking at base Major daw, two sterns, possible Caracking at base Caracking at base Caracking at base Caracking at base Major day, two sterns, possible Caracking at base Caracking at care Ca

smove



HISTORIC PRESERVATION COMMISSION

Douglas M. Duncan County Executive

Julia O'Malley Chairperson

Date: April 20, 2006

MEMORANDUM

TO:

Robert Hubbard, Director

Department of Permitting Services

FROM:

Michele Oaks, Senior Planner

Historic Preservation Section, M-NCPPC

SUBJECT:

Historic Area Work Permit # 353421 for major addition and rehabilitation to existing house

The Montgomery County Historic Preservation Commission (HPC) reviewed the attached application for a Historic Area Work Permit (HAWP) at its public hearing on November 17, 2004. This application was APPROVED with conditions. The conditions of approval were:

- 1. Scheme B for the addition is approved.
- 2. The applicant will work with HPC staff on the detailing for the hyphen, terrace and new addition.
- 3. The applicant will get HPC staff approval for the new garage door prior to its installation.
- 4. The specification sheets outlining the manufacturer, model and description of product for all windows and doors, including garage, to be used in this project will be reviewed and approved at staff level. If these specification sheets do not illustrate materials and designs typically approved by the Commission and compatible with the historic structure, the staff will require that they be reviewed and approved by the Commission in a revision to the approved Historic Area Work Permit Application.
- 5. Tree protection plan for the root system of the 30' oak tree located on the adjacent lot to the north will be drafted by a certified arborist and reviewed and approved by staff prior to the project's commencement. The tree protection plan will include the use of limits-of-disturbance (LOD) fencing. For every tree to be removed, as per the submitted tree plan, one tree from Montgomery County's native species list (min. 3" caliper deciduous or 6' high evergreen) will be planted on the property prior to use and occupancy permits being issued by the Department of Permitting Services.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED AND CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HISTORIC AREA WORK PERMIT (HAWP) CONDITIONS AND MAY REQUIRE APPROVAL BY DPS OR ANOTHER TOWN GOVERNMENT AGENCY BEFORE WORK CAN COMMENCE.

Applicant:

Alan Adler

Address:

2801 Beechbank Avenue, Silver Spring (Capitol View Park Historic District)

This HAWP approval is subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will contact the Historic Preservation Office if they propose to make any alterations to the approve plans.



RETURNTO DEPARTMENT ESS/ROCKVILL

RMITTING SERVICES £ 2nd FLOOR, ROCKVILLE, MD 20850



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Removation to

existing home

WA

	Contact Person: HIDN 10 UTC
<i>5.00</i> 9	Daytime Phone No.: (20))-675 - 5349
Ex Account No.: 13-5-999-822	(20)) 445- 2522
Name of Property Owner: HIACHAUK	Daytime Phone No.: (201) 675-5349
10211 Na 101 06 1 (1	Sarlus MA 20903
Address: 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Steel Zip Code
Contractor: Arbor Homes	Phone No.: (36) 445 - 2522
Contractor Registration No.: BC-3520	
Agent for Owner: A)ow Adum.	Daytime Phone No.: (30) 495-2522
LOCATION OF BUILDING/PREMISE	
House Number: 780/	Smoot 1500, Whenh Rd
Town/City: Neerest Cross S	Great Capital View Avenue
Lot: P-15 Block: 35 Subdivision: CR	
	p. you or or pay to
Liber: Folic: Parcel:	
PART ONE: TYPE OF PERMIT ACTION AND USE	
1A. CHECKALL APPLICABLE: CHEC	IX ALL APPLICABLE:
S Construct S Extend S Alter/Renovate S A	C Slab Z Room Addition D Porch S Deck Shed
☐ Move 🖼 Install ☐ Wreck/Rage ☐ S	olar 🗵 Fireplace 🔘 Woodburning Stove 💮 Single Family
	ence/Wall (complete Section 4)
IAN NAT	and the feet decident.
1C. If this is a revision of a previously approved active permit, see Permit #	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/A	DOMININS
2A. Type of sewage disposel: 01 🗇 VySSC 02 🗆 Septic	: 03 🗆 Other:
2B. Type of water supply: 01 ₩SSC 02 ☐ Well	03
Eg. Type of traces dapping.	
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
3A. Heightisetinches	
36. Indicate whether the fence or retaining wall is to be constructed on one of	of the following locations:
☐ On party line/property line ☐ Entirely on land of owner	On public right of way/essement
I hereby certify that I have the authority to make the foregoing application, the approved by all agencies listed and I hereby acknowledge and accept this to	of the application is correct, and that the construction will comply with plans be a condition for the issuance of this permit.
3	1)
Signature of owner or guifhorized agent)	2/18/0 Y
Y WICOUDITIONS OF	Chairpesson, Historic Preservation Commission
Approved.	MA Illa Walas
Oisapproved: Signature: Signature: 35.2 1.2 1.4	ore: Illifold
Application/Permit No.: 557410	Date Filed: 7-04-04- Date Issued:

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

WRITTEN DESCRIPTION OF PROJECT

	ELICITED SECTION CONTROL CONTROL	•
	a. Description of existing structure(s) and environmental setting, including their historical features and significance:	
	LXISTING SMALL 2 Story (plus bearings + single to mily	
	withour, palcony with metal from work rolls (brockets	
	in lovely setting mentoshing wooded area to	
	b. General description of project and its effect on the historic resource(s), the environmental setting, and, where epplicable, the historic district:	· · · · · · · · · · · · · · · · · · ·
	Rear 2 story (plus parement) addition with sturio	
	Board and exterior + like kind casement windows	
	also indula a position to the inside of pricht	•
	stouture. The rear addition will require the remove	el
•	of 2 significant there on the property yet dense woo	dland exiting
<u>!</u> ,	impact on the skitting place minimizes their re	noval + it's
	Site and environmental fartiling, drawn to scale. You have use your plat. Your site plan must include: >> Pothing the addition	Athe front or left
	a. the scale, north arrow, and date; Side of the existing	home was not
	b. dimensions of all existing and proposed structures; and	ble, given the
	c. site features such as welkways, driveways, fences, ponds, streems, treah dumpsters, mechanical equipment, and landscaping. File disc	le from HPC at
3.	PLANS AND ELEVATIONS a pre Vio	us meeting. Also
	You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred.	an addition of
	a. Schemetic construction plans, with marked dimensions, indicating location, size and general type of waits, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.	the right side
	 Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriets, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each 	of the home is
	facade affected by the proposed work is required.	not Leesable
١.	MATERIALS SPECIFICATIONS	
	General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your	given the regular
	design drawings.	the energy
i,	PHOTOGRAPHS	the existing gapen
•	a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.	theat from
	b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on	Town the Town
	the front of photographs.	19Ws
5.	TREE SURVEY	
	19 you are proposing construction adjacent to or within the driptine of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you	Acovered
	must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.	Breezeway from
7.	ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS	The existily
	For ALL projects, provide an accurate list of adjacent and comforming property owners (not tenants), including names, addresses, and sig codes. This list	Stricture to the
	should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street,	proposed Addition
	Rockville, (301/279-1355).	an med all the middle
	PLEASE PRINT IN BLUE OR BLACK INKO OR TYPE THIS INFORMATION ON THE FOLLOWING PAGE. PLEASE STAY WITHIN THE GUIDES OF THE TEMPLATE, AS THIS WILL BE PHOTOCOPIED DIRECTLY ONTO MAILING LABELS.	now of the home 10
	the rear of the existing howe only wh	addition comes of
	From Land Walle only win	to what Rd.
		· · · · · ·



April 18, 2006

Mr. Alan Adler Adler Homes, LLC 10311 Naglee Drive Silver Spring, MD 20903

Dear Alan:

To: Michelle HPC

From: A. Adler

Via Fax: (301) 563-3412

3 pgs total

Please call me after you read

this, if you have a minute.

Thanks - Alow (301) 675-5349

I recently revisited your property at 2801 Beechbank Road in order to survey several of the large trees around the existing home. I brought the newest site plan for this property so that I could get a feel for the potential impacts to these trees

I want to bring to your attention that the condition ratings have changed for several trees since they were last surveyed in November, 2004. In particular, the large Black oak #10 (Querous velurina), which I understand is of concern to the Historic Commission, has declined in health from good in 2004 to fair to poor now. There is quite a bit of major deadwood in the crown and there are several bleeding cankers at the base. Both the dieback of large scaffold limbs and the presence of bleeding cankers are indicative of root rot problems. This concerns me a great deal because of the size of this tree [it measures 37" of diameter at breast height (dbh)] and the fact that the canopy is concentrated at the top of the tree. If this does have a significant level of root rot, then I feel it is a high risk for windthrow.

Your site plan shows root pruning at approximately 12' from the base of this tree. This is within the area around the tree which is termed the minimum clearance zone (MCZ). This is a zone with a radial distance equal to 6' for each inch of dbh. So, for this tree the MCZ would be 18.5'. Within this zone are found the large, woody scaffold roots which are responsible for the structural stability of the tree, as well as being the basis of the entire absorbing root system. It is always advisable to avoid cutting these roots.

Given its declining condition and the signs of potential root rot problems. I would not characterize this tree as a good preservation candidate. However, if you decide to keep it there are some treatments which I feel are necessary. The first is a risk assessment of the main root flares and trunk to assess the integrity of the wood. I could do this using my resistograph machine. This tool will give me instant feedback as to the integrity of the wood in these areas.

If the results of this test are positive, then I would recommend removing the major deadwood once the new leaves have "hardened off." Secondly, a tree growth regulator (Cambistai 2SC) should be applied in the next few weeks. This product will act to slow the vegetative growth in the tree and re-direct the tree's energy into root production. It is

viable for three years. You would also need to initiate a wood borer control program which would involve applying a preventative spray treatment to keep borers from laying eggs under the bark. There are several wood borers that will key in on this tree in its weakened condition. These are the insects which are most often responsible for the rapid decline and death of these large oaks.


I am also concerned with the long-term prognosis for the large, double-stemmed White hak (Quercus alba) to the left of the existing house. There has already experienced quite a bit of root damage from the digging done near the base in the revent past. There are some severed roots which are now exposed. These should be pruned and then buried to prevent drying. I would also recommend the Cambistat and borer control treatments for this tree as well


I feel that these are the highest priority tree care items on your site at this time. There are other tree care needs to attend to on the property, but these are the most important. Please call me with any other questions you may have. At a later date, we can discuss the needs of the remaining large trees on the property.

Sincerely,

Keith C. Pitchford

ISA Certified Arborist, MA-0178







SILVER SPRING, MARYLAND 20910

October 12, 2004

Historic Preservation Commission

The Zoning committee of the Capitol View Park Citizens Association met last night, Monday, October 11, 2004 to consider 4 HAWP applications and one subdivision review scheduled for the upcoming HPC meeting of Wednesday, October 13, 2004. It was noted that the Zoning Committee was sent copies of the HAWP(s) BUT that no staff recommendations were sent regarding these proposals. In the past Staff Recommendations have been sent out with HAWPs and it is helpful to have these recommendations sent so that the Civic Association Committee can comment on the Staff Recommendations. The HPC did send their recommendations to the applicants. Three members of the Zoning Committee took part: Mr. Duncan Tebow (acting as chairman); Ms. Carol Ireland, and Ms Betty Scott. A summary of the committee's recommendations follow in agenda order:

Case 31/06-07-04F, Alan Adler for new construction at 2801 Beechbank Rd. Mr. Adler appeared as did Ms. Rosemarie Kellinger, confronting homeowner. After presentations by Mr. Adler and questions from Ms. Kellinger the committee agreed that it recommends that an HAWP BE GRANTED in this case with no further recommendations.

Case 31/07-04G, Alan Adler for an addition at 2805 Beechbank road. Mr. Adler and Ms. Kellinger once more appearing. After Mr. Adler's presentation and Ms. Kellinger's questions and comments the committee agreed to advise HPC that the HAWP BE GRANTED IN THIS CASE WITH the FOLLOWING RECOMMENDATIONS: 1. that Mr Adler not disturb the screening row of trees (Hemlocks) on Beechbank Road at the front edge of the property and that he consult an arborist to determine if they are sustainable. In the event that they are not, he should re-plant same or similar trees to preserve the vegetative screen. 2. That in the opinion of the committee Mr. Adler has reduced the overall size of the addition appropriate to the massing of the architectural elements, especially in view of the fact that the addition is sited entirely behind the historic resource, and even though its profile overlaps the original house it will be largely

obscured by the new house next door, its distance from the front of the property, and the vegetive screen mentioned above. 3. The committee reaffirms its previous comments during the preliminary consult that Mr. Adler be allowed to construct a two level, rather than one level, "hyphen" joining the historic structure to the new addition.

Case 31/07/04H, John Brill and Patricia Monahan for new construction at 10219 Menlo Ave. Ms. Patricia Monahan appeared as did Mr. Peter Wilson, abutting homeowner. Mr. Wilson came to the meeting early and made his comments prior to the arrival of some of the others. After a presentation by Ms. Monahan and discussion by the committee the committee agreed to recommend that the applicant's HAWP BE GRANTED WITH THE FOLLOWING RECOMMENDATION: that the applicant be required to modify the foundation exposure on the front and south of the plan by the planting of screening shrubbery to diminish the effect of large expanse of parged block or concrete foundation wall, or alternatively to use a brick or stone veneer on the exposed areas of the entire foundation NOTE: The committee did not agree that the alternative design attached to the application by HPC staff was in any way an improvement over the applicant's design and if anything would block the view to the historic resource to the north at least as much if not more than the applicant's design; further the staff design is actually larger than the applicants design.

Case 31/07/04D REVISION, P. Joshua Haines for new construction at 10115 Meadowneck court. Ms. Ruta Kadanoff, homeowner at rear of the proposed construction appeared and commented. The committee was pleased that the builder had reduced the proposed house both in height and overall footprint and recommends this HAWP BE GRANTED WITH THE ROLLOWING RECOMMENDATION: that the applicant demonstrate that storm water run off from the property after construction not adversely affect adjoining historic resources (see adjoining homeowner, Mr. Malko's, comments received by e-mail and attached).

SUBDIVISION. Macon construction for subdivision of the property at 10245 Captiol View Ave. No interested parties appeared. After a short discussion the committee reaffirmed its support as stated at the time of the preliminary review and recommends APPROVAL OF THIS SUBDIVIION, reserving all further right of comment at the time of application for HAWP (s).

Respectfully submitted, Duncan E. Tebow, Acting as Chair, Zoning Committee, CVPCA

Attachment

- 10-12-04 Barrett Malko's comments to the Staff report regarding the Haines 31/07-04D Revision plan.
 - the HPC staff approval of plastic siding because it is similar to the existing houses is misstated. The Flavin, Gonsalez and Malko properties are brick and wood. HPC required the Flavin's use of wood for their addition to their historic cottage.

Wood siding would be more appropriate given, at least, three of the surrounding properties are not plastic siding. The present HPC siding standard should be met.

- 2) Footing protection from rain water runoff of the historic Flavin property is of paramount importance. Simply saying that "the applicant plans to address the water runoff and drainage issues" is not good enough. Also that the "staff encourages the applicant and the neighbors to research and address this important issue together' is also not good enough. The Applicant be directed to redirect the runoff from his property including that from his 12' access driveway. A catch basin at the north-west corner of the applicants finished driveway leading to the Meadowneck court storm water drainage system will accomplish this requirement. No research is necessary. Again, footing protection of the historic Flavin property is required as are the other surrounding properties.
- 3) There is no tree plan to visually protect the Flavin, Malko and Gonsalez properties from the applicant's design including large expanses of siding. Tree planting on these three properties would be acceptable to these three neighbors. This idea was submitted to HPC staff some time ago and should be reconsidered at this time.

FAX COVER SHEET

CAROL IRELAND 10023 Menlo Avenue Silver Spring, MD 20910-1055 (301) 588-4420

Historic Preservation Commencen

Telephone: 301563-3400

Title:

Organization:

Date: 18/13/04

Message Re HP (Hearing Wednesday
10/13/04
Capital View Park Citizens Association
pernumen datums on HAWPS

NUMBER OF PAGES SENT INCLUDING THIS COVER;

Sending FAX (301) 588-7284

Receiving FAX: 第.301563-34/2

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

2801 Beechbank Avenue, Silver Spring

Meeting Date:

10/13/04

Resource:

Review:

Contributing Resource

Report Date:

10/06/04

Capitol View Park Historic District

Public Notice:

09/27/04

Case Number: 31/07-04G

HAWP

Tax Credit:

None

Applicant: Alan Adler (Mark Hughes, Agent)

Staff:

Michele Naru

PROPOSAL: Rear Addition

RECOMMEND:

Approve with Conditions

RECOMMENDATION: Staff recommends that the Commission approve this HAWP

application with the conditions that:

The hour addition must be reduced in sige so that it does not The specification sheets outlining the manufacturer, model and description of product for windows and doors, people and garage, to be used in this new addition will be reviewed and

approved at staff level.

Tree protection plan for the root system of the 30' oak tree located on the adjacent lot to the north will be drafted by a certified arborist and reviewed and approved by staff prior to the project's commencement.

BACKGROUND: The subject project was reviewed by the Commission as a Preliminary Consultation on September 8, 2004 (transcript and drawings from the Preliminary Consultation can be found beginning on circle 18). The Commission asked the architect to study and modify the program as follows:

- 1. The majority of the Commission wanted a reduction of the hyphen to a one-story connection. Two of the Commissioners conveyed that they understood the need for the second story on the hyphen and could entertain a modified design.
- 2. The majority of the Commission wanted the western section of the new, rear addition substantially reduced in size. Commissioner O'Malley directed that the western wing beyond the plane of the original massing's side elevation be no greater than ½ of the width of the main massing.
- 3. The majority of the Commission encouraged a contemporary architectural style on the addition utilizing borrowed elements from the original house to help to differentiate the new massing from the addition.



PROJECT DESCRIPTION

SIGNIFICANCE:

Contributing Resource within Capitel View Park Historic District.

STYLE:

Mediterranean

DATE:

1917-1935

This two-story, three bay, dwelling with raised basement is located within the Capitol View Park Historic District. The main entry is located on the north (side) elevation of the house. The entry is covered with a shed roof sheathed in Spanish tile. The house is constructed in concrete and is detailed with metal casement windows and wrought iron railings. The roof is a shallow hip sheathed in Spanish tile and ornamented with an exterior end chimney also constructed of concrete. The subject lot contains several mature trees.

PROPOSAL: The subject proposal will:

- 1. Remove a portion of the foundation wall on the basement level, an existing window on the first floor and two windows on the second floor to create an entry into a new, two-story with basement, hyphen addition. The height of the hyphen will be 1' lower than existing roof height on the historic massing.
- 2. Construct a two-story rear addition with basement garage onto the new hyphen addition. This addition will be of frame construction, faced in stucco and sheathed in Spanish tile to match the existing house. The height of the addition will match the existing roof height on the historic massing. The applicant is proposing to utilize wood casement windows on the addition.
- 3. Construct a new terrace along the west elevation of the historic massing to connect the historic house to the addition.
- 4. Remove a 24" oak tree and a 24" twin oak tree from the property.

APPLICABLE GUIDELINES:

When reviewing alterations and additions to contributing resources within the Capitol View Park Master Plan Historic District two documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A

A HAWP permit should be issued if the Commission finds that:

1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.

- 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.
- 3. The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archaeological, architectural or cultural value of the historic site or historic district in which an historic resource is located.

Secretary of the Interior's Guidelines for Rehabilitation

- #2 The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.
- Distinctive materials, features, finishes and construction techniques or examples of craftsmanship that characterize a property will be preserved.
- #9 New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
- New additions and adjacent new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STATISTICS:

Current Proposal:

Existing footprint: approx 620 sq. ft.

Proposed additions footprints: approx. 1,105 sq. ft.

Total new footprint: approx. 1,725 sq. ft.

Lot size: 10,272 sq. ft.

Existing Lot coverage: 6%

Proposed Lot coverage: 16.7%

Preliminary Consultation Proposal:

Existing footprint: approx 620 sq. ft.

Proposed additions footprints: approx. 1,283 sq. ft.

Total new footprint: approx. 1,903 sq. ft.

Lot size: 10,272 sq. ft.

Existing Lot coverage: 6%

Proposed Lot coverage: 18.5%

STAFF DISCUSSION

Staff feels that the applicant and his architect have addressed and modified the plans to reflect the comments the Commission conveyed at the Preliminary Consultation.

Topic #1 The majority of the Commission wanted a reduction of the hyphen to a one-story connection. Two of the Commissioners conveyed that they understood the need for the second story on the hyphen and could entertain a modified design.

The applicant modified their original design for the hyphen to a 2-story "glassy" addition and the height of this addition is 1' lower than the existing roof height of the main massing. The last that the light of this addition is 1' lower than the existing roof height of the main massing. The last that the light of the main massing with a first plant of the original massing's side elevation be no greater than 1/2 of the width of the main massing.

This addition has been reduced in length by 10.5'. The western extension will be 14' beyond the plane of the original massing's side elevation, which is approximately 1/2 of the width of the main massing. (The width of the massing is 22'.) The width of the main massing with its baleonies and the western staircase is 28.5°.)

The object of the main massing with its baleonies and the majority of the Commission encouraged a contemporary architectural style on the addition utilizing borrowed elements from the original house to help to differentiate the new massing from the addition.

The architect modified the elevations of the new massing to reflect a more contemporary interpretation of the original architectural style. That this has been supported by

Staff would ask that the Commission require the applicant to provide, for staff approval, specification sheets outlining the manufacturer, model and description of product for the windows and doors; people and garage, to be used in this new addition. If these specification sheets do not illustrate materials and designs typically approved by the Commission and compatible with the historic structure the staff will require that they be reviewed and approved by the Commission in a revision to the approved Historic Area Work Permit Application.

Finally, staff also would ask the Commission to require a tree protection plan for the root system of the 30" oak tree located on the adjacent lot to the north. This plan must be drafted and signed by a certified arborist and submitted with or prior to the stamping of the permit sets of drawings for this project.

STAFF RECOMMENDATION:

Staff recommends that the Commission *approve with the above-stated conditions* this HAWP application as being consistent with Chapter 25A-8(b) 1, 2 and 3.

and with the Secretary of the Interior's Standards 2, 5, 9 & 10:

and with the general conditions applicable to all Historic Area Work Permits that the applicant shall also present three, (3) permit sets of drawings to HPC staff for review and stamping prior to submission for permits, and shall arrange for a field inspection by the Montgomery County Department of Permitting Services (DPS), Field Services Office, five days prior to commencement of work, and within two weeks following completion of work.

- #9 New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
- #10 New additions and adjacent new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

Topic #1 Remove a portion of the foundation wall on the basement level, an existing window on the first floor and two windows on the second floor to create an entry into a new, two-story with basement, hyphen addition. The height of the hyphen will match the existing roof height on the historic massing.

Staff does not object to the utilization of existing fenestrations to provide access to an addition. However, staff is concerned with this current design's program to alter a window on the first story, where there is an existing door that could be utilized, and altering two windows on the second story.

As the design program illustrates, the main objective of the hyphen is to provide interior access to the new addition only. As such, with stairways in both massings (historic and proposed) a one-story with basement hyphen should be sufficient and also would not require the removal of two additional windows in the second level of the main massing.

Additionally, staff would like to see that the entry from the historic massing to the hyphen be accomplished through the use of the existing door opening. Finally, staff would like to see the hyphen's design to be more "glassy" in form. This detail will provide a visual separation of the historic and proposed massings.

Topic #2 Construct a two-story rear addition onto the new hyphen addition. This addition will be of frame construction, faced in stucco and sheathed in Spanish tile to match the existing house. The height of the addition will match the existing roof height on the historic massing. The applicant is proposing to utilize wood casement windows on the addition.

Staff commends the applicant's use of compatible materials and design for this addition. The materials are compatible but not replicative (frame with stucco instead of concrete, wood windows instead of metal) and are compatible with the existing architectural style.

Staff smain concernavith the proposed addition is its size. In footprint, the addition is still will addition and the staff of the difference of the staff of the



overwhelm the original. In order to not adversely affect the character of the District, the streetscape or the architecture of the original house, staff suggests a re-design and reduction of the proposed massing so it does not exceed the western plane of the original massing (see-staff's recommendation drawings beginning on circle).

Topic #3 Construct a new (uncovered) terrace along the west elevation of the historic massing to connect the historic house to the addition.

Staff does not object to this design detail.

STAFF RECOMMENDATION:

Staff recommends that the applicant revise their plans based on the above staff discussion and the Commission's comments and then return to the Commission for a second preliminary consultation. Staff will work with the architect in the development of the revised plans if desired.

Additionally for the second preliminary consultation, staff requests specification sheets outlining the manufacturer, model and description of product for the windows and doors, people and garage, to be used in this new addition.

Finally, staff notes that this property contains several large trees, which contribute to the landscape of the historic district. For the second preliminary consultation, the applicant should submit a tree survey and protection plan to the Commission outlining the trees (larger than 6" in diameter) to be saved and protected and the trees to be removed.

Please note that the exterior and interior rehabilitation of the historic building is eligible for County (only exterior), State and possibly Federal Tax Credits.

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING [Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address	Owner's Agent's mailing address
Alan Adlery	
10311 Noglee ha	- same
5.5-md-20903	
).)-((0)	·
Adjacent and confronting	Property Owners mailing addresses
Cohen Family Partnership	Paniel milton
185 Franklin Dr.	1446 Crowell Rd
Glencoe, IL. 60022-1259	Vienna, VA. 22182-1510
(Lot 16 + P15, Bbch 35)	(20+40, Block 34)
	(20+40, 8bck 34) Lot 45, Block 34)
Ronald Isaken	Joan Lynch,
Rosemarie Kellinger	2804 Belchbonk Rd
2802 Beechbonkld.	5; be-spring, md 20910-1101
Siber Spring, Mo. 20910-1101.	
(Lot 5 & 6, Bloch 36)	(6+374, Bbolh 36)
Graeme L C.J.J. Wistow	Arbon Homes
2809 Beechbonk Rd.	
Silver Spring, and 20910-	10311 NAglee Rd
,	Siher Spring, and. 20903
(Lot 13, 86 ch 35)	(Lot 14, Bloch 35)
Duncan & Elizabeth Tebow	
9809 Capital VICW DVP.	
Silve-Spring, Md. 20910	
(Lot P11, B)sch 35)	

lie-opposed

Address:

2801 Beechbank Avenue, Silver Spring

Meeting Date:

11/17/04

Resource:

Contributing Resource

Report Date:

11/10/04

Capitol View Park Historic District

Public Notice:

11/03/04

Review:

HAWP

Case Number: 31/07-04G CONTINUED

Tax Credit:

None

Applicant: Alan Adler (Mark Hughes, Agent)

Staff:

Michele Naru

PROPOSAL: Rear Addition

RECOMMEND:

Approve with Conditions

ScheneB= tim/ Lyme.

RECOMMENDATION: Staff recommends that the Commission approve this Historic Area Work Permit (HAWP) application with the conditions that:

scheme B

The addition must be reduced in size so that it does not exceed the western plane of the existing house.

The terrace and pergola will be reduced in size so that it does not exceed beyond the western plane of the existing stairwell.

The connecting hyphen will be reduced to one-story.

Work what on hyphen terrare, and new addition detailing The specification sheets outlining the manufacturer, model and description of product for all windows and doors, including garage, to be used in this project will be reviewed and

approved at staff level. If these specification sheets do not illustrate materials and designs typically approved by the Commission and compatible with the historic structure, the staff will require that they be reviewed and approved by the Commission in a revision to

the approved Historic Area Work Permit Application.

5. Tree protection plan for the root system of the 30'loak tree located on the adjacent lot to the north will be drafted by a certified arborist and reviewed and approved by staff prior to the project's commencement. For every tree to be removed, as per the submitted tree plan, one tree from Montgomery County's native species list (min. 3" caliper deciduous or 6' high evergreen) will be planted on the property prior to use and occupancy permits being issued by the Department of Permitting Services.

(o. LDD henring BACKGROUND

The Commission as a Preliminary Consultation on September 8, 2004 reviewed a large, rear, addition to this contributing resource. The meeting concluded with the Commission asking the architect to study and modify the program as follows:

- 1. The majority of the Commission wanted a reduction of the hyphen to a one-story connection. Two of the Commissioners conveyed that they understood the need for the second story on the hyphen and could entertain a modified design.
- 2. The majority of the Commission wanted the western section of the new, rear addition substantially reduced in size. Commissioner O'Malley suggested that the western wing beyond the plane of the original massings' side elevation be no greater than ½ of the width of the main massing.
- 3. The majority of the Commission encouraged a contemporary architectural style on the addition utilizing borrowed elements from the original house to help to differentiate the new massing from the addition.

At the October 13, 2004 meeting, the Commission was presented with a HAWP application for the addition (transcripts and submitted plans begin on circle 19). The majority of the Commission wanted a redesign of the plans to include:

- 1. A significant reduction in the length of the addition. D
- 2. The proposed, two-story hyphen needs to be very transparent.
- 3. The new addition needs to be more differentiated stylistically. The height of the addition needs to be at the same height or lower.
- 4. A tree plan which identifies the existing trees 6" in diameter and larger on the lot. The plan should also delineate the trees to be saved and removed.

PROJECT DESCRIPTION

SIGNIFICANCE:

Contributing Resource within Capitol View Park Historic District.

STYLE:

Mediterranean

DATE:

1917-1935

This two-story, three-bay, dwelling (22' x 28.5' footprint) with raised basement is located within the Capitol View Park Historic District. The main entry is located on the north (side) elevation of the house. The entry is covered with a shed roof sheathed in Spanish tile. The house is constructed in concrete and is detailed with metal casement windows and wrought iron railings. The roof is a shallow hip sheathed in Spanish tile and ornamented with an exterior end chimney also constructed of concrete. The subject lot contains several mature trees.

PROPOSAL: The subject proposal will:

- 1. Remove a portion of the foundation wall on the basement level, an existing window on the first floor and two windows on the second floor to create an entry into a new, two-story with basement, hyphen addition. The height of the hyphen will be 1' lower than existing roof height on the historic massing.
- 2. Construct a two-story rear addition (17' x 48') with basement garage onto the new hyphen addition. This addition in both proposed schemes will be of frame



construction, faced in stucco and will contain a flat roof. The height of the addition in Scheme A will be approx. 6" lower than the existing roof height of the historic massing while Scheme B will match the existing roof height of the historic massing. The applicant is proposing to utilize wood casement windows in both proposals.

- 3. Construct a new terrace along the west elevation of the historic massing to connect the historic house to the addition.
- 4. Remove a 24" oak tree and a 24" twin oak tree from the property.

APPLICABLE GUIDELINES:

When reviewing alterations and additions to contributing resources within the Capitol View Park Master Plan Historic District two documents are to be utilized as guidelines to assist the

Commission in developing their decision. These documents include the Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A

A HAWP permit should be issued if the Commission finds that:

- The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
- 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.
- 3. The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archaeological, architectural or cultural value of the historic site or historic district in which an historic resource is located.

Secretary of the Interior's Guidelines for Rehabilitation

- #2 The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces and spatial relationships that characterize a property will be avoided.
- Distinctive materials, features, finishes and construction techniques or examples of craftsmanship that characterize a property will be preserved.
- Mew additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
- When additions and adjacent new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.



STATISTICS:

Existing footprint (22' x 28.5'):	627 sq. ft.
Proposed addition footprint (17' x 48'):	816 sq. ft.
Proposed hyphen (10' x 7') footprint:	70 sq. ft.
Proposed new terrace (12' x 20' and 4.5' x 10')	285 sq. ft.
Total new footprint:	1,171 sq. ft.
Total footprint (new + existing)	1,798 sq. ft.

Lot size: 10,272 sq. ft.

Existing Lot coverage: 6% Proposed Lot coverage: 17.5%

STAFF DISCUSSION

Staff feels that the applicant and his architect have addressed most of the comments the Commission conveyed at the previous HAWP hearing.

Topic #1 A significant reduction in the length of the addition.

The addition has been reduced in length by 6' since the last HAWP submittal. However, staff continues to encourage a design for the addition that does not project beyond the western plane of the existing house. The current proposed addition is 8' beyond the western plane of the existing house. Additionally, the proposed terrace with pergola projects an additional 6' beyond this addition. Therefore, staff recommends that the Commission support this proposal with the condition that the western extension of the addition not exceed the western plane of the existing house and that the terrace and pergola not exceed beyond the western plane of the existing stairwell.

Topic #2 The proposed, two-story hyphen needs to be very transparent.

The applicant modified their original design for the hyphen to a 2-story "glassy" addition and the height of this addition is 1' lower than the existing roof height of the main massing.

Staff continues to support a one-story hyphen. With stairways in both massings (historic and proposed), a one-story hyphen with basement should be sufficient and also would not require the removal of two additional windows in the second level of the main massing. Additionally, staff would like to see that the entry from the historic massing to the hyphen be accomplished through the use of the existing door opening. We will note, however, that the Commission at the last HAWP hearing supported the two-story hyphen.

Topic #3 The new addition needs to be more differentiated stylistically. The height of the addition needs to be at the same height or lower.

The architect has developed two different designs to respond to the Commissions concerns.

Staff supports the proposed Scheme B, because we feel that it successfully differentiates the addition from the original massing through the use of a more contemporary interpretation of the original architectural style.

Topic #4 A tree plan which identifies the existing trees 6" in diameter and larger on the lot. The plan should also delineate the trees to be saved and removed.


This plan is being drafted by the applicant's arborist and will be presented to the Commission at their work session.


STAFF RECOMMENDATION:


Staff recommends that the Commission approve with the above-stated conditions this HAWP application as being consistent with Chapter 25A-8(b) 1, 2 and 3.


and with the Secretary of the Interior's Standards 2, 5, 9 & 10:

and with the general conditions applicable to all Historic Area Work Permits that the applicant shall also present three, (3) permit sets of drawings to HPC staff for review and stamping prior to submission for permits, and shall arrange for a field inspection by the Montgomery County Department of Permitting Services (DPS), Field Services Office, five days prior to commencement of work, and within two weeks following completion of work.
















EXISTING 2ND FLR PLAN








7735 OLD GEORGETOWN ROAD SUTE 700 BETHESDA, MD 20814 (240)333-2001 PAX GTMARCHITECTS GEM

10.27.04

REVISION #2

Ш


EXISTING RIGHT SIDE (EAST) ELEVATION



2 PROPOSED RIGHT SIDE (EAST) ELEVATION - 'A'

ADLER RESIDENCE


10.27.04 REVISION #2



ADLER RESIDENCE

EXISTING LEFT SIDE (NEST) ELEVATION






圃

3 000

ADLER RESIDENCE

EXISTING REAR (NORTH) ELEVATION






ADLER RESIDENCE








PROPOSED RIGHT SIDE (EAST) ELEVATION - 'B'

EXISTING RIGHT SIDE (EAST) ELEVATION

ADLER RESIDENCE








ADLER RESIDENCE



1027.04



ADLER RESIDENCE

EXISTING REAR (NORTH) ELEYATION





- 1 that is -- but that's what I've kind of worked at over the
- 2 years and -- really turns out that way, so I'm looking
- 3 forward to it also.
- 4 MR. FULLER: Madam Chair --
- 5 MR. ADLER: I can't take the credit, though, for
- 6 the design. It was the architect that did that.
- 7 MR. FULLER: Madam Chair, I make a recommendation
- 8 that we approve Case 31/07-04F at 2801 Beechbank Road with
- 9 the Staff conditions -- the three Staff conditions with a
- 10 modification to Condition No. 2 that it reads, "If the plan
- 11 identifies removal of a tree larger than six inches in
- 12 diameter, the plan will be resubmitted to Staff for their
- 13 review and determination as to whether they can approve or
- 14 to bring back before the Commission."
- 15 UNIDENTIFIED FEMALE: I'll second.
- 16 MS. O'MALLEY: Any discussion? All in favor,
- 17 raise your right hand. All right, thank you very much.
- 18 That's unanimous.
- 19 We can go now to Case F. Do we have a staff
- 20 report for 2805 Beechbank Road?



- 21 'MS. NARU: It's 2801; the numbers are switched on
- 22 the agenda. I apologize for that.
- 23 Again, 2801 Beechbank Avenue. This is a
- 24 contributing resource within the Capitol View Park Historic
- 25 District. The proposal is a rear addition to this resource.

- 1 Again, the Commission reviewed this at a preliminary
- 2 consultation at its September 8th, 2004 meeting and the
- 3 transcript and drawings from this meeting can be found in
- 4 your packet. I will also note that the citizen's group did
- 5 respond in their written comments to this project as well
- 6 and I will enter that into the record.
- At the preliminary consultation, you asked the
- 8 architect to study and modify the program as follows: the
- 9 majority of the Commission wanted reduction of the hyphen to
- 10 a one story connection. Two of you conveyed that the --
- 11 they understood the need for the second story on the hyphen,
- 12 but could entertain a modified design. Secondly, the
- 13 majority of the Commission wanted a western -- the western
- 14 section of the new rear addition substantially reduced in
- 15 size. One suggestion was that the western wing not extend
- 16 beyond the plane of the original massing side elevation no
- 17 greater than half of the width of the main massing. And
- 18 thirdly, the majority of you encouraged a contemporary
- 19 architectural style on the addition utilizing borrowed
- 20 elements from the original house to help differentiate the
- 21 new massing from the addition.
- 22 Staff feels that the applicant and their
- 23 architects have not addressed many of your comments and we
- 24 feel very concerned about the proposed massing of the rear
- 25 addition. We will note that it has been reduced in length



- 1 by 10.5 feet. The western extension will be about 14 feet
- 2 beyond the plane of the original massing side elevation,
- 3 which is approximately about two-thirds of the width of the
- 4 main massing. But we feel that it still feels very linear
- 5 in footprint. We, as Staff, really want to stay firm with
- 6 our original comments in the preliminary consultation,
- 7 stating that we did not want to see the addition go beyond
- 8 that western plane and, unfortunately, it currently still
- 9 does.
- Secondly, we feel that the proposed two-story
- 11 glassy addition is -- is still way too high in terms of what
- 12 the Commission had directed the applicant. We really were
- 13 looking for a one-story hyphen. We feel that the proposed
- 14 glassiness of this addition is an improvement, but again, we
- 15 still would like to see it as a one-story.
- 16 We also would want to see the cross sections of
- 17 the glassiness to insure that all of it would be glassy and
- 18 not having a solid roof on the structure at the top of it.
- 19 We'd like to make sure that that is still glassy even at the
- 20 roof level.
- 21 And finally, we will note that the architect
- 22 addressed your concern about contemporary architectural
- 23 style in the addition and we feel that's been done very
- 24 successfully, utilized on the new interpretation in the
- 25 drawings and we feel that that is very successful.

1 The applicant and their architect are here this

- 2 evening and as you can see in my staff report, we are
- 3 recommending approval with the Conditions 1 through 4
- 4 basically outlining the concerns that I've just discussed.
- 5 MS. O'MALLEY: Thank you. Questions for Staff?
- 6 Would you state your name for the record, and did you have a
- 7 comment to make?
- 8 MR. HUGHES: Mark Hughes, GTM Architects. The
- 9 comments are thanks. We really did start with all the
- 10 comments that were made by the Commission at the last
- 11 worksession; the biggest being to pull that one wing back to
- 12 half the size of the existing old house. But when we did
- 13 that and we tried to lay out -- in effect, when we did that,
- 14 we lost a bedroom on that second level when we did that.
- And we attempted to lay out the master bedroom
- 16 suite and the standard size bedroom within that footprint
- 17 and just found it a little tight, quite honestly, so we just
- 18 -- in order just to provide a decent master bedroom suite
- 19 and decent master bathroom and a decent second bedroom on
- 20 that level, we bumped it incrementally out a little bit as
- 21 far as we thought we could without compromising the gist of
- 22 the suggestion from the Commission.
- 23 We looked at, you know, doing the one-story hyphen
- 24 and quite honestly once we lost that one bedroom on the
- 25 second level, going from four to three bedrooms on that



- 1 second level, we really thought it was necessary to maintain
- 2 that bridge across the second story so you have to -- on one
- 3 level.
- 4 Now, for the end user -- and Alan's going to be
- 5 the end user -- down the stairs and across the house and
- 6 across the other side to get to the other bedroom. And it's
- 7 always been concealed behind the house from the street. You
- 8 know, I guess we thought it was -- it was never something
- 9 that would really be noticed by anybody else --
- 10 We really did try to do all these things, but what
- 11 we thought were some straightforward simple reasons, we just
- 12 got as close as we could and submitted these plans.
- MR. ADLER: If I could just -- I'm Alan Adler, the
- 14 same one as before. We -- you know, when we had gone
- 15 through and I heard the comments that the Chairpersons had
- 16 made and I think -- was there another one? I quess there
- 17 were seven -- was there a total of seven normally, or is it
- 18 always --
- 19 MS. O'MALLEY: There are actually nine.
- 20 MR. ADLER: Oh, okay. I -- before I just knew
- 21 there -- I think there were seven or maybe eight. But I --
- 22 you know, I -- and going through and I know that I think it
- 23 was Julia, I think you had said at the end that you were
- 24 looking for -- or, hoping that whatever the front of the
- 25 existing house is in terms of the width when you're looking



- 1 at it from the street that the protrusion to the left side
- 2 for the addition be, you know, nearer half of that. And we
- 3 pushed to do that. It's not -- it's not exactly half of it,
- 4 but I think if you look just from the two elevations that we
- 5 have from the original street elevation to the proposed, and
- 6 if you just put one in front of the other, I think that -- I
- 7 mean, it looks quite significant and actually pretty
- 8 balanced.
- And so with regard to the reduction, you know we,
- 10 again, have reduced it such that we had to lose a bedroom,
- 11 so it's -- it's a three bedroom house and with regard to the
- 12 hyphen, which Mark can get into in further detail, I think
- 13 that we also -- set back or we did a little something
- 14 different with the hyphen. I guess putting the roof back up
- 15 there to somehow make --
- MR. HUGHES: Well, in a contemporary sense, we
- 17 didn't connect the hyphen roof -- we didn't extend the new
- 18 roof of the new addition to the existing roof of the old
- 19 house -- just breaks that -- with a flat roof, it breaks
- 20 that connection so there is a visual disconnect between the
- 21 old and the new.
- 22 And of course we did try to add, you know, a lot
- 23 more glass to the wall area -- but did, again, feel
- 24 compelled to keep that upper story connection to simply make
- 25 it a useful bedroom level for the end user.

- 1 MR. ADLER: If I could just kind of reiterate from
- 2 my meeting with Carol Ireland and the neighbors that they
- 3 felt that the changes, the revisions that we have made they
- 4 felt that we reduced the overall size of the addition
- 5 appropriate to the massing of the architectural elements and
- 6 then -- let's see here -- and that they were, you know, they
- 7 were, you know, in full support of the changes that we made.
- MR. HUGHES: One other item Alan didn't touch on,
- 9 but I think it has to do with the plan put forward by the
- 10 Staff. I guess we thought through the process -- on board
- 11 with the idea of the hyphen to begin with. I guess the idea
- 12 was to just sort of pull that wing all the way back and do a
- 13 much more significant addition to the house in regards to
- 14 touching and changing the house on that back elevation by
- 15 connecting a larger mass to the house. And we really feel
- 16 that this goes towards the solution here with the hyphen,
- 17 you know, lightly touches the existing house, decreases the
- 18 changes necessary to that existing house; really saves more
- 19 of the house than the solution that the Staff has put
- 20 forward.
- 21 So, from reading these Guidelines for
- 22 Rehabilitation from the Secretary of Interior, this scheme
- 23 actually seems to be better, preferable to these points that
- 24 are here on this staff --
- MS. WRIGHT: I just want to clarify, if you look



- 1 at Circle 55 on the staff report -- do you have that?
- 2 MR. HUGHES: No. Oh, wait --
- 3 MS. WRIGHT: Circle 55 on the staff report where
- 4 you see something that says staff recommendation, that is a
- 5 hyphen. Yeah, so it -- I don't think that Staff is at all
- 6 disagreeing with the hyphen concept. I think it was really
- 7 just that we thought it should be a one-story hyphen and
- 8 that the new addition should not double -- double the size
- 9 of the existing house.
- 10 MR. HUGHES: I actually have never -- we've never
- 11 seen this. I was referring to some of the sketches we've
- 12 seen --
- 13 MR. ADLER: Exactly. Actually I, as well, have --
- 14 did not see -- did not see this and it was initially when
- 15 Michele had made her original recommendations that basically
- 16 we just kind of attached on, like one would normally do if
- 17 they wanted the historic -- just kind of attach it onto the
- 18 back and not worry about how the rear looks at all, and our
- 19 whole idea was to touch it as lightly -- as lightly as
- 20 possible.
- 21 MS. WRIGHT: I think Staff certainly supports the
- 22 hyphen and these were the same drawings that were in the
- 23 preliminary consultation packet. I think our concerns are
- 24 that in lightly touching the building that the one-story
- 25 hyphen is a lighter touch than a two-story hyphen, and that



1 the addition that is added on should not be double the size

- 2 of the existing footprint.
- 3 MR. HUGHES: All right. The only -- honestly, the
- 4 only -- this -- the program and it's going to be a three
- 5 bedroom house would fit within this footprint, we would be
- 6 all for it, but it didn't really -- it doesn't. It just
- 7 really comprises --
- 8 MS. WRIGHT: Well, it does fit if you use the
- 9 existing house as a two-bedroom house, rather than turning
- 10 the second bedroom in the existing house into a walk-through
- 11 sort of hallway/deck. And by making it a one-story hyphen,
- 12 you really preserve that second bedroom in the existing
- 13 house as a bedroom.
- 14 MR. HUGHES: I don't mean to -- I don't mean to
- 15 belabor or argue the point, but it may or may not. I was
- 16 just kind of glancing at it, the fact that the stairs are in
- 17 the center of the house and -- connected hallway through
- 18 there and having a bedroom, it may work out but it may not
- 19 be as easy as you may think, I guess.
- 20 MR. ADLER: Gwen, what I, you know, did want to
- 21 say in kind of with regard to what Mark had stated just a
- 22 few minutes ago is that the reduction that we made reduced
- 23 the new addition to -- to two bedrooms and if I'm in the
- 24 master bedroom and I'm hoping to have two or three kids
- 25 soon, we have one bedroom in the addition and we have

- 1 another bedroom -- that's the second bedroom for the child
- 2 or the nursery or whatever on the -- in the original part of
- 3 the house. What we will need to do when we're upstairs in
- 4 order for me to get to my child or check, make sure that
- 5 everything is okay, I would need to go downstairs, cross
- 6 from the main structure from the addition through the
- 7 breezeway or connecting into the original house and then go
- 8 upstairs and go into the bedroom. And I just think that --
- 9 that's -- I don't think that's such a -- it makes it
- 10 difficult. I don't know how many, you know, people here
- 11 would be comfortable with that.
- 12 And also someone also had mentioned to me -- I
- 13 didn't even think of it -- but that that could cause a fire
- 14 hazard in terms of it. You know, you don't have a way out
- 15 from one part because you can't get across.
- 16 MS. NARU: I think it really just depends on how
- 17 you use the spaces. I think what Staff is trying to convey
- 18 is that on the first level, which is very typical in current
- 19 construction, you could have a master bedroom suite and
- 20 maybe a living room and then you could have your two
- 21 bedrooms upstairs, so that gives you three bedrooms. And
- 22 then a kitchen, dining, and family room in the addition that
- 23 would connect with the foyer. And certainly that could
- 24 provide three bedrooms, you know two full baths, plus
- 25 another -- you know, you could do a half bath in the



- 1 kitchen/dining room/family room area and then still even
- 2 have your -- as you proposed in your basement plan, a study
- 3 and a billiard room on your ground level as well as a
- 4 garage.

jd

- 5 So, I just -- I guess what I'm saying is you could
- 6 work the program to make it three bedrooms in the same
- 7 original massing.
- 8 MS. WRIGHT: Right. We're not trying to deny
- 9 anyone a three bedroom house. That's a reasonable request,
- 10 but, you know, I think that in the square footage there's
- 11 lots of ways to accomplish that without building an addition
- 12 that is double the size of the existing footprint.
- MR. HUGHES: Well, I would respectfully decline
- 14 there, only because the bigness of the house is very small
- 15 -- this is a very small footprint to begin with. That's the
- 16 basic problem here. When you look at the first floor, it
- 17 has the basic elements -- basic house; living room, dining
- 18 room and kitchen, entry foyer, and family room. There's
- 19 nothing extra luxurious about it. It's just a
- 20 straightforward sort of house. It's small to begin with and
- 21 '-- and maybe it's by comparison to a small -- like house you
- 22 feel as though the addition is so large, but it actually
- 23 isn't very large.
- 24 MS. WRIGHT: Why don't we let the Commission
- 25 comment.



- 1 MR. HUGHES: At 17 feet -- you know, 17 feet deep
- 2 and -- you know, I mean, we could have -- I mean, in terms
- 3 of the view from the street, you know listening to the
- 4 Commissioners and I've written down -- I don't have with me
- 5 -- what each Commissioner had felt and I think there were
- 6 one or two of them that didn't have any problem at all with
- 7 the size of the protrusion from the left looking at it from
- 8 the street, and then there were a number of them -- number
- 9 of people that said they would like to see that massing
- 10 reduced. And I know that Julie, you had said at the end
- 11 there that -- massing, so I -- we had just gotten the
- 12 impression that what the -- what the Commission was looking
- 13 for -- not the Staff, but what the Commission was looking
- 14 for -- and that's what we went for, was what the Commission
- 15 was looking for -- was a reduction in the -- in the size.
- 16 And so, you know, that's what we went ahead and did and I
- 17 think that we did -- I think it made a big difference and I
- 18 just wanted to share that.
- MS. WILLIAMS: I think you've stated this already.
- 20 The biggest problem is you have a small house and doing a
- 21 not unreasonable addition overwhelms the house. That's the
- 22 basic dilemma here. I think it is kind of an aggressive
- 23 program for such a small house and I'm just not sure that
- 24 you can accommodate the program. I'm not saying that it's,
- 25 you know, an unreasonable request, but for this particular



1 house it doesn't seem to be working. I'm not saying it

- 2 can't work architecturally, but I don't think that you have
- 3 shown us between the last preliminary and this HAWP any
- 4 significant changes or even architectural, you know,
- 5 alternatives to address the programmatic needs.
- I mean, basically you've just reduced the length
- 7 of the addition a little bit. I mean, can't we look at some
- 8 other schemes that might work better with the historic
- 9 structure that accommodates your program and the historic
- 10 house? I just don't think that there's really a good faith
- 11 effort here in trying to celebrate this historic building in
- 12 a way that doesn't become overwhelmed by the new structure.
- 13 And also, to add to that, I mean the new structure
- 14 looks quite frankly like a chalet. I mean, it looks -- it
- 15 doesn't look like a -- I mean it sort of looks like a multi-
- 16 family on that one elevation anyway -- the long elevation --
- 17 structure that I mean it doesn't seem to me to be either
- 18 necessarily, you know, good design if it's done right or a
- 19 good addition. And it just seems like there needs to be a
- 20 little bit of work to make it work together.
- MR. ADLER: I respectfully hear what you've said
- 22 and I actually -- I had thought that we did, contrary to
- 23 what the Staff has said, we actually addressed -- we looked
- 24 at and addressed a number of issues and we worked very hard
- 25 at it. Though a number of people on the Board weren't sure



- 1 what we had in terms of the addition architecturally.
- 2 speaking, that it should maybe be different from the
- 3 existing house. We had before the stucco -- that matched
- 4 exactly to look like the -- you know, to work with the
- 5 existing structure and so what we've done is we've changed
- 6 our plan around so we've given it a more contemporary look
- 7 from the outside to differentiate the old and the new. So
- 8 we addressed that point.
- 9 And we also addressed the reduction of the -- of
- 10 the left side by taking off 10 1/2 feet, which is
- 11 substantial. So, you know, we addressed that, this
- 12 protrusion to the left, we addressed the architectural
- 13 style, we've changed that so that it's completely different.
- 14 And then -- exactly, it doesn't mimic, you know, and I
- 15 think we also adjusted with regard to the hyphen, we changed
- 16 it around where there is a roof back there and we've changed
- 17 it where there's more glass and so it doesn't, I guess,
- 18 attach on so strongly. And we would have, you know, taken
- 19 off the hyphen if we didn't lose the bedrooms, but
- 20 unfortunately one thing affected the other.
- 21 MS. O'MALLEY: Can I add -- I want to ask you a
- 22 question. Thinking then about the suggestion that Staff
- 23 made of using the original house as your area where you have
- 24 two bedrooms upstairs and downstairs you have another
- 25 bedroom and a study, the den area would connect to the



- 1 foyer, then you could still have your family room and
- 2 kitchen and you wouldn't be in such need of a large
- 3 addition, because those wouldn't need to be as long. You
- 4 wouldn't need two large bedrooms upstairs on the addition
- 5 because you would have your three bedrooms and den in the
- 6 other area.
- 7 MS. ALDERSON: Can I just add to that, so you can
- 8 -- at the same time, but given that the need for this
- 9 amount, this extent of an addition to a small cottage is
- 10 driven by the need for bedrooms, I was perplexed that I
- 11 found major public spaces, including two dining rooms, two
- 12 living rooms. There seems to be program redundancy that
- 13 contradicts the need for the big space.
- 14 MR. HUGHES: We did think in last pass that we did
- 15 address that because it was -- thought this -- made it a lot
- 16 more precise plan.
- 17 MR. ADLER: We now have -- we've taken it so
- 18 instead of there were two dining rooms, which actually the
- 19 other one was going to be a small -- I mean, just an area
- 20 off of the kitchen. We now have one dining room and --
- MR. HUGHES: An eating area and a kitchen.
- MR. ADLER: And then the living room. If you're
- 23 referring to the family room as part of the living room,
- 24 then I guess we have two living areas, but it's -- with this
- 25 house, we have -- with the proposed first floor plan, we



- 1 have a living room, dining room, family room, and a kitchen.
- 2 MR. HUGHES: The eat-in kitchen; that's where you
- 3 see that they have a table, but that's --
- 4 MR. FULLER: Let me start out with a question for
- 5 Staff. The first two conditions as written, for all intents
- 6 and purposes, create a new design. What was the reason that
- 7 your recommendation was perceived and then just come back
- 8 for Staff as opposed to that they come back for a new HAWP?
- 9 Because I think this is a lot more substantial than we
- 10 typically see in terms of changes.
- MS. NARU: Just because we felt that there is room
- 12 to manipulate and work with Staff. I think that in our
- 13 mind, at least our initial drawings do give, I think,
- 14 clearer direction. So, I think if they reduced the program
- 15 to that footprint, I think it could work and I think we
- 16 could approve it at a Staff level.
- 17 MR. FULLER: The Staff sketch shows the house
- 18 going about 10 feet further to the west than the existing,
- 19 but the condition says it has to align with the west base?
- 20 MS. NARU: Right. It was just an approximate --
- 21 you know, certainly we can --
- 22 MR. FULLER: That's not something that you're
- 23 saying is hard and fast; that it can't be right there?
- MS. NARU: It's up to the Commission to give us
- 25 quidance on that.

- 1 MR. FULLER: I guess -- I think part of my
- 2 problem --
- 3 MS. NARU: We were trying to keep it in line. If
- 4 you look on Circle 56, we were trying to keep it in line
- 5 with the existing stairwell.
- 6 MR. FULLER: Understand. I quess I was in the
- 7 minority last time and I'll probably remain that way, that
- 8 from my perspective the second story's length isn't the end
- 9 of the world simply because it is so well hidden behind the
- 10 existing house. And I think you've gone in the right
- 11 direction trying to make it transparent.
- I think my biggest problem in reviewing what I see
- 13 is I believe like on your east elevation the differentiation
- 14 between the existing and the proposed really stand out. And
- 15 similar with the other elevations, in particular the south
- 16 elevation, which is the main street elevation, because
- 17 you're showing, you're rendering your roofs exactly the same
- 18 because the skin of the house looks so similar, to me
- 19 they're still reading too close together. And from my
- 20 perspective, that's one of the biggest sins of what I'm
- 21 looking at right now is that it does look like sort of just
- 22 a blown-up version of the existing house.
- I do acknowledge that you've taken 10 feet off the
- 24 length of the house, off the one end, which is almost 50
- 25 percent of what was showing on that side of the house past

- 1 the face. Yeah, I'd like to see it back a little bit more
- 2 than that. Does it have to do all the way back from my
- 3 personal perspective? I don't think it has to go all the
- 4 way back. It would be nice for it to be a little bit
- 5 tighter, but my big issue would just be the higher level of
- 6 differentiation between the houses.
- 7 And I certainly would not recommend a final
- 8 solution that had bedrooms up on one side and bedrooms up on
- 9 the other and you have to go back and forth. Either you
- 10 need to find a method of architecturally solving it that
- 11 there's enough differentiation that the link becomes light
- 12 enough that you can go across it, or you do, as was
- 13 suggested, turn one of these wings into a sleeping wing and
- 14 the other into a living quarters.
- 15 MS. WILLIAMS: I agree that if you're going to
- 16 have bedrooms on the second floor, both new and old section,
- 17 it really necessitates a second story hyphen, I mean for
- 18 safety and everything else. You have dematerialized the
- 19 second floor hyphen -- or, the two-story hyphen, so I'm not
- 20 saying a two-story hyphen couldn't work, but I think you
- 21 need to reduce the size of the addition.
- When I look at your proposed basement plan, for
- 23 instance, I just see all this unused space. If you're so in
- 24 need of another bedroom, why don't you stick your bedroom
- 25 that you have in your new wing down in the basement that



68

- 1 would actually have natural light and then pull back
- 2 entirely on that second floor wing.
- I don't know; it just seems like there's a really
- 4 inefficient use of space in the house. I just think it
- 5 could really be tightened up.
- And I think that you have made some attempts at
- 7 changing or altering the proposal in terms of its style and
- 8 in that respect, I think it has been a little bit more
- 9 successful, the hyphen is more dematerialized. I just think
- 10 it has to do with space planning and overall room
- 11 configuration that's the problem.
- MS. WATKINS: I would go ahead and agree with both
- 13 of the Commissioners who just spoke. I think the hyphen is
- 14 a necessity. I think it needs to be kept very transparent,
- 15 but I think you do need to work on your space planning. I
- 16 think it's -- and I think that it can be reduced on the west
- 17 side to at least where the stair -- it's probably about
- 18 another 10 feet.
- 19 MS. O'MALLEY: I think what you're hearing is that
- 20 you might not get this application approved. Would you be
- 21 willing to continue it and come back in?
- MR. ADLER: Yes. Although I did -- I think I'm a
- 23 little confused. Commissioner Fuller, I heard what you
- 24 said. The only thing that I didn't understand, and you were
- 25 talking in terms of -- in elevation in terms of the



- 1 distinction between the -- in terms from the architectural
- 2 style that we need to change -- I'm sorry?
- 3 MR. FULLER: My point was if you look in
- 4 particular at your south elevations and in particular if you
- 5 look at the south elevation of the existing house versus
- 6 sort of the southwest face of the new addition as rendered,
- 7 they look so similar. And I don't -- you know, if you look
- 8 on the east elevation of your house, the new addition was
- 9 very distinctly presented as other series of materials. On
- 10 the south elevation, which is the main place most people are
- 11 going to see your house, it looks the same --
- MR. ADLER: Sure.
- MR. FULLER: -- and that to me really hurts the
- 14 idea because at that point it really starts to overwhelm the
- 15 existing house. And I think that if it stands out as
- 16 different, then I think it's less of an issue how big the
- 17 house is. I still agree it should be smaller, but I just
- 18 think it -- the more it's distinct I think the less that
- 19 difference matters to me.
- MR. ADLER: Sure.
- 21 MS. ALDERSON: And I could just add to that. It
- 22 doesn't necessarily mean you need to break style and throw
- 23 it a whole different style on that side. There are a lot of
- 24 ways of treating the details that would make it read as a
- 25 different mass.



- 1 MR. ADLER: Let me ask you -- and I don't know if
- 2 this was something -- I always got the impression that we
- 3 should keep any addition at the same height or lower than
- 4 the original house. I mean, just looking at this in my
- 5 limited architectural knowledge, could the roof on either
- 6 side of the main -- of the original building looking at it
- 7 from the street, could we raise it up a little bit to break
- 8 that or can we lower it more a little bit, I mean, without
- 9 lowering -- I mean, can that be lowered by -- I don't know,
- 10 would it make a difference if we lowered it by, you know,
- 11 six inches or eight inches or raise it up on either side?
- MS. O'MALLEY: Raise --
- 13 (Discussion off the record.)
- 14 MS. ALDERSON: On the addition; not the historic.
- MR. ADLER: Would that be, I mean, favorable to
- 16 the --
- MS. O'MALLEY: That would help.
- 18 MR. ADLER: That would help, okay. I just wanted
- 19 to be able to know when we -- we, from here, the things that
- 20 we could do to make it work and have you all be comfortable
- 21 with it. So --
- MS. O'MALLEY: We have a couple of comments here.
- 23 MR. BURSTYN: I believe last time I was kind of
- 24 leaning toward the one-story hyphen, but after thinking
- 25 about the functionality of the house, I think it's important



jd 72

1 to have the two stories to connect the upper bedrooms and

- 2 also the first floor for just ease of living.
- But also I think it should be designed somewhat
- 4 the way you have it on Circle 21. I wouldn't want it to
- 5 have the feeling that it is just one continuous plane all
- 6 the way across. And other thing is, I appreciate that you
- 7 did reduce the length of the addition; however, I remember I
- 8 suggested that you could also make it a little bit shorter
- 9 by getting rid of the landing and the double stair and have
- 10 one on top of the other. So, I guess you could get rid of
- 11 another three feet in length by having a single staircase
- 12 instead of a double, if you know what I mean.
- 13 And then also -- again, when I look at Circle 21,
- 14 the proposed east elevation --
- MR. ADLER: Is that 12?
- 16 MR. BURSTYN: Oh -- yes, 12. Yes, I'm sorry.
- 17 Circle 12. It seems like the proposed east elevation on the
- 18 right, the part above the garage, just seems way, way too
- 19 busy in compared with the other one. I'm not saying that
- 20 the two should be an identical match, but it just seems like
- 21 they have all this extra stuff on it and between the two
- 22 stories you get these vertical lines in there. I don't know
- 23 what that's about and it just, when you look at it, to me it
- 24 just seems too much.
- MR. ADLER: I'm looking at it. I agree with you.



- 1 MS. WILLIAMS: I have one more comment just to
- 2 follow up on Commissioner Burstyn's suggestion about making
- 3 a single flight stair. I'm just looking at this plan and
- 4 why don't you just put the stair in the hyphen. Widen your
- 5 hyphen a little bit and then you can reduce the size of the
- 6 new wing and still accommodate your program. And you could
- 7 still make the hyphen very transparent.
- 8 MR. ADLER: That's a good idea. I mean --
- 9 MS. NARU: That would compromise a lot of the
- 10 exterior fabric by doing that. If we're making it wider, we
- 11 have another two windows that would be affected -- so I just
- 12 want --
- 13 MS. WILLIAMS: I know. I see that, but I also
- 14 think that I'd rather have --
- MS. NARU: Okay.
- MS. WILLIAMS: -- historic fabric in a way than
- 17 having a monstrous addition.
- MS. NARU: Okay.
- 19 (Discussion off the record.)
- 20 MS. WILLIAMS: I'm not saying it would work. I'm
- 21 just saying look at it, you know.
- MS. WRIGHT: Yeah, I think that -- I hope, at
- 23 least, that we're getting to a sort of consensus here that
- 24 seems like the majority of the Commissioners -- and please
- 25 correct me if I'm wrong -- feel that a two-story hyphen can



- 1 work if it's kept as glassy as possible.
- 2 I'm also hearing that essentially all the
- 3 Commissioners here still feel that there needs to be a
- 4 substantial reduction in the footprint of the proposed
- 5 addition. Is that accurate?
- 6 MR. BURSTYN: Well, if you took out the width of
- 7 the double staircase --

jd

- 8 MS. WRIGHT: I think we need to let them -- yeah,
- 9 the double staircase may be a way to accomplish it, but,
- 10 again, we need to let them figure out how to do it. But the
- 11 main message is there needs to be a substantial reduction in
- 12 the size of the footprint. Is that the two big messages to
- 13 come out of today's meeting?
- MS. O'MALLEY: When you come back, would you also
- 15 bring your site plan with the trees?
- MR. ADLER: Certainly.
- MS. O'MALLEY: Because I know there are a couple
- 18 large ones.
- 19 MR. ADLER: Certainly.
- MS. O'MALLEY: Thank you.
- MR. ADLER: Just -- if I could just ask one thing.
- 22 With regard to -- I mean, substantial; is it every -- I
- 23 mean a majority of the Board feels that it either needs to
- 24 be a substantial decrease or is it -- I mean, I don't know
- 25 if everyone on the Board felt that or a majority of the



- Board had felt that or --
- MS. WRIGHT: Let's just take a quick like little
- 3 hand poll. How many folks feel there needs to be a
- 4 substantial decrease in the footprint of the proposed
- 5 addition? If you would raise your hand.
- 6 MR. FULLER: Quantify substantial.
- 7 (Discussion off the record.)
- 8 MS. WRIGHT: -- one Commissioner was actually
- 9 bringing something in closer to the edge of the proposed
- 10 exterior staircase. There's a proposed exterior staircase
- 11 and I believe Commission Watkins mentioned that that's the
- 12 area she was looking at as the left-hand boundary. That's
- 13 not that that has to be the end-all/be-all, but that's the
- 14 level of significance that at least I was hearing.
- 15 Let's hear if they are -- if I'm hearing
- 16 correctly.
- 17 MS. ALDERSON: I was -- my thinking is that
- 18 substantial as is perceived and that mainly has to do with
- 19 the size of the length of that addition and that it might be
- 20 partially achieved by rearranging so that that you could
- 21 reduce the length of that.
- MS. WRIGHT: Yeah, I think that's what we're
- 23 saying is that, you know, this is the length, right, and so
- 24 we're talking about whether they move the staircase or do
- 25 something else, pulling that length in tighter. And the



- 1 question is how tight?
- 2 MR. FULLER: I could live with five to eight feet
- 3 more off that.
- 4 MS. WRIGHT: How do other folks feel?
- 5 MS. O'MALLEY: I think the problem is you don't
- 6 want an addition that's so much larger than the original
- 7 house. Generally, with a historic resource, you like to see
- 8 additions that are smaller than the historic resource. And
- 9 you've proposed one that's --
- 10 MS. NARU: I think Staff really needs some
- 11 guidance. If we're using the footprint of the historic
- 12 house as a basis, is it correct to say you would not want to
- 13 see it larger than the footprint of the existing house?
- 14 MR. BURSTYN: I think we have to also hone in on
- 15 the fact that the lot size and go back to the percentage of
- 16 coverage. The original house only covers six percent of the
- 17 lot, so I don't know whether --
- 18 MS. NARU: I'm looking at less restrictions here.
- 19 First of all, the lot -- you cannot go any farther back on
- 20 this property because of the rear yard setback. And then,
- of course, we're saying reduce it in width, so he's pretty
- 22 much constrained to where he is now in terms of setback on
- 23 the rear yard.
- So, what we're asking you is on the wings
- 25 extending beyond the original massing, we really need to




- 1 know how far -- because I don't want them to waste their
- 2 time, nor Staff. To clarify, we really need to know how far
- 3 beyond this --
- 4 MS. WRIGHT: We can sort of go along. We heard
- 5 from Commissioner Fuller that he's thinking five to eight
- 6 feet. We heard Commissioner Watkins saying she's looking at
- 7 essentially where the next exterior stairs are proposed.
- 8 Again, if you look at the sketch on page Circle 16 is where
- 9 I've drawn this new line pretty much.
- 10 And the other question is -- you know, as we've
- 11 heard from two Commissioners -- we you want to hear from the
- 12 other four?
- 13 MS. WILLIAMS: Yeah, I think cutting it back to
- 14 the stair makes sense or, as Staff had recommended
- 15 originally.
- MS. WRIGHT: Okay, how about Commissioner Burstyn;
- 17 do you have a quantity of cutback?
- MR. BURSTYN: Just a six-foot reduction in the
- 19 length would be fine with me by taking out the stairs.
- 20 Because I certainly wouldn't want to end up with a plan that
- 21 gives the rooms that are just too small for what the
- 22 applicant envisions. I appreciate what he's going to do
- 23 there, so six feet to me is fine.
- 24 MS. WRIGHT: Commissioner Alderson?
- 25 MS. ALDERSON: I agree with Commissioner Fuller



- 1 and Burstyn that the amount of reduction that could be
- 2 achieved by relocating this stair, reducing it six to eight
- 3 feet, would make a great difference.
- 4 MS. WRIGHT: Okay, Commissioner O'Malley?
- 5 MS. O'MALLEY: Well, I said before, cutting back
- 6 half and you cut back a third, so I'm still looking for --
- 7 MS. WRIGHT: Okay, does that give you all
- 8 direction in terms of how much of a cutback they're looking
- 9 for?
- 10 MR. HUGHES: Just about --
- MS. WRIGHT: You want an absolute consensus?
- MR. HUGHES: Right.
- MS. WRIGHT: Some of it's going to be based on you
- 14 going back and looking at the interior design, but I'm
- 15 hearing that it should be probably in the range of six --
- 16 somewhere between six feet and -- about like 10 feet or so
- 17 if you were going to move it to the staircase. So, probably
- 18 six feet at the lower end and 10 feet at the upper end,
- 19 depending on the program.
- 20 MR. HUGHES: So that is greater than half the
- 21 width of the main house.
- 22 MS. WRIGHT: Correct. One condition; yes.
- MS. O'MALLEY: All right, thank you. I hope this
- 24 is helpful.
- MR. HUGHES: Thank you very much. I appreciate





99.21.04

GTMARCHITECTS

ADLER RESIDENCE


EXISTING BOMT PLAN



2601 BEECHBANK RD. KENSINGTON, MD

HAWP# 10/19/04-12/19






04.21.04

GTMARCHITECTS

GTM

ADLER RESIDENCE






PROPOSED SOUTH ELEVATION


EXISTING SOUTH ELEVATION

HXWP#1 10/13/04 MTG









囲

PROPOSED EAST ELEVATION

EXISTING EAST ELEVATION


HAWP#1 10/13/04 MTG

ADLER RESIDENCE




7735 OLD GEORGETOWN ROAD SUITE 700
BETHESDA, MD 20814
(240)333-2001 FAX
REVISION #1
Orizion

0421.04




ADLER RESIDENCE

2801 BEECHBANK RD. KENSINGTON, MD



HAWP#1 10/13/04 MTG





囲

ADLER RESIDENCE

EXISTING NORTH ELEVATION

HAMP#1 10/13/04 MTG

GIM

FAX

GTMARCHITECTS

Date:

10/26/04

To:

Michele Naru HPC- Staff Phone:

Fax: 301-563-3412

From:

GTM Architects, Inc.

Mark Hughes

Phone: 240-333-2008 Fax: 240-333-2001

Pages (including cover sheet): 5

Project #: 04.0209

Project Name: Adler Residence, 2801 Beechbank Rd., S.S., MD


Subject: Rear Addition, revision #2

Re: For your review and comment


Michele,


We have developed two exterior 'looks' for this revision. Option #1 is the next evolution of the more abstract contemporary architectural style proposed previously. Option #2 is another contemporary version with more direct stylistic references to the original house type. What do you think? Do you, or staff, have a preference? Alan will call you to discuss in the morning.

Thanks, Mark



2403332001





89 10+2

To: Michelle HPC/Abby
From: Alon Adles (301) 443-2522 (0) (30) 675-5349 (c) BOD 445-5679 A)


pate: Mord 3, 2004 Re: 2801 Beechlanh Rd. Via: Fax Bul) 563-3412

Dear Michelle attached please find a proposed side plan to an addition to the existing home. The addition will be on the 1st ZM Floor, I will have no basement. I think that possibly the stress coment boards (4x8') would be nice + could nee some 5/4x4 -5/4×6 wood at the joints (every 4'). Windows will watch as closely as possible of existing. Height will be been than existing, but only by a little. anything else you need for the preliminohy, consult at the most 24th meeting, please Slet me wow. looking formal to working in you! Sixualy, don adher 10311 Noglet Rd

S.S. Md 20903

To Midelle APR From: A. Adlex


1/20-52





7735 OLD GEORGETOWN ROAD SUITE 700 BETHESDA, MD 20814 (240)333-2001 FAX


10.27.04 REVISION #2



ADLER RESIDENCE

10.27.04

REVISION #2



2) PROPOSED RIGHT SIDE (EAST) ELEVATION - 'A'

6

ADLER RESIDENCE

7735 OLD GEORGETOWN ROAD SUITE 700 BETHESDA, MD 20814 (240)333-2001 (240)333-2001 FAX

10.27.01 REVISION #2


PROPOSED LEFT SIDE (MEST) ELEVATION - 'A'

ADLER RESIDENCE

EXISTING LEFT SIDE (MEST) ELEVATION









ADLER RESIDENCE

EXISTING REAR (NORTH) ELEVATION






ADLER RESIDENCE

7735 OLD GEORGETOWN ROAD SUITE 700 BETHESDA, MD 20814 (240)333-2001 (240)333-2001 FAX

10.27.04 REVISION #2

EXISTING RIGHT SIDE (EAST) ELEVATION



2) PROPOSED RIGHT SIDE (EAST) ELEVATION - 'B'

ADLER RESIDENCE

7735 OLD GEORGETOWN ROAD SUTE 700 BETHESDA, MD 20814 (240)333-2001 FAX GTMARCHITECTS GTM

10,27,04 REVISION #2


2) PROPOSED LEFT SIDE (MEST) ELEVATION - ' B'

ADLER RESIDENCE


EXISTING LEFT SIDE (MEST) ELEVATION




10.27.04



ADLER RESIDENCE




10.27.04



ADLER RESIDENCE

EXISTING BSMT PLAN




ADLER RESIDENCE

EXISTING IST FLR PLAN




10,27.04


REVISION #2




ADLER RESIDENCE









GIM

GTMARCHITECTS

Date:

10/26/04

2403332001

To:

Michele Naru **HPC-Staff**

Phone:

Fax: 301-563-3412

From:

GTM Architects, Inc.

Mark Hughes

Phone: 240-333-2008 Fax: 240-333-2001

Pages (including cover sheet): 5

Project #: 04.0209

Project Name: Adler Residence, 2801 Beechbank Rd., S.S., MD


Subject: Rear Addition, revision #2


Re: For your review and comment


Michele,

We have developed two exterior 'looks' for this revision. Option #1 is the next evolution of the more abstract contemporary architectural style proposed previously. Option #2 is another contemporary version with more direct stylistic references to the original house type. What do you think? Do you, or staff, have a preference? Alan will call you to discuss in the morning.


Thanks, Mark











89 10+2

To: Michelle HPC/Abby
From: Alon Adless (301) 443-2522 (0) (30) 675-5349 (c) BOD 445-5679 (1)

pate: Mord 3, 2004


Le: 2801 Beachtanh Rd.

Via: Fax Bul) 563-3412

Dear Michelle attached please find a proposed side plan to an addition to the existing home. The addition will be on the 1st ZM Floor I will have no basement. I think that possibly the stress coment boards (4x8') would be nice & could me some 5/4x4 -5/4x6 wood at the joints (every 4'). Windows will watch as closely as possible of existing. Height will be been than extisting, but only by a little. anything else you need to the preliminating consult at the most 24th meeting, please That me wow. looking formed to working by you!

Sixually, don adler 10311 Noglet Rd 5.5. Md. 20903 To Midelle HPC Form: A. A dlex

Pg. 20-52



AUTOMATIC COVER SHEET

DATE : MAR-04-2004 04:08 PM

TO :

FAX #: 3015633412

FROM : ROSS.WICZER

FAX #: 3013098271

3 PAGES WERE SENT

(INCLUDING THIS COVER SHEET)