35/10-02A 4000 Jones Bridge Rd. (MP #35/10 - Hayes Manor) THE MARK WINKLER COMPANY

4900 SEMINARY ROAD

ALEXANDRIA VIRGINIA 22311-1811

TELEPHONE 703 578 9136

FAX 703 578 2935

ROBERT P OBRIST
SENIOR PROJECT MANAGER

Patricia D. Monday Director of Planning

12850 Middlebrook Road Suite 200
Germantown, Maryland 20876
T 301.528.4300

F 301.528.0419

c 301.922.0232

E Patricia.Monday@phra.com

Engineers. Surveyors. Planners. Landscape Architects.

Patton Harris Rust & Associates, pe Engineers. Surveyors. Planners. Landscope Architects. Bowie Gridley Architects, P.L.L.C. 1010 Wisconsin Avenue, N.W. Washington, D.C. 20007 Tel: 202-337-0888 Fax: 202-337-2626

Jonathan S. Rodvien, AIA Associate

rodvien@bowie-gridley.com

Scott R. Wolford, RLA, AICP Vice President Director of Land Development

12850 Middlebrook Road Suite 200 Germantown, Moryland 20876 T 301.528.4300 F 301.528.0419 C 301.922.0204

E Scott.Wolford@phra.com

Engineers, Surveyors, Planners, Landscape Architects.

Patton Harris Rust & Associates, pe Ingineers. Surveyors. Planners. Landscape Architects.



Howard Hughes Medical Institute

Craig A. Alexander Deputy General Counsel

4000 Jones Bridge Road Chevy Chase, Maryland 20815-6789 (301) 215-8841 • Fax (301) 215-8848 alexande@hhmi.org

ζ

Light bod finn 346 n Budaza, e estimazonara, n Budaza, estimazonara, 0,500 RS Enterest property Strong property 20.20.02 of the second Lib 3 4574 Folio 466 SPLITTINGENDS Section . Code 215 Code 251 Coches 77.77 EPORT NOTES: CTH THE INSURANCE COMPANY INSULT BURNEY: 020469 TATE, SOLY 8, 3002 AT 8,000 AM. 1 - SECTION 2 OF THE ABOVE LISTED DITL GISCHARDE THEN BETT HE OWNER WITH RESPECT TO THE STORM HEREON THUS 1-5 & 8 HAVE NOT BEEN COLLINO TO CACK OF PROTTABLE DESIGNMENTS. s arraireach den eschediches a arraireach den engeneration and the same Manor Roda . NOTES: Coverneying Detail See detail Lew Cores and other THE THE WALL FLOOD REDWARDE HATE NAVE THAT THE BAYE THE THE TAKE THE THE TAKE FROM A MALABLE SOURCES DATE TO DEEPRESANCY OF CHOCKA FOR.

SURVEYOR'S CERTIFICATE:

TO COMMODING ACTO CAND THE BOOKSHOT COMPANY AND HOMERO STREET HOWEVER

THE 12 TO CERTIFY HIGH TIME MAP OR YEAR AND THE TORNER OF ALLOW IT IS BASED WERE CHARL IN ACCOUNTED AND THROUGH STANDARD LETAR RECOMPLISHED FOR ACTA/ACTA/ACTA/AND CASE IN ACCORDING AND TRANSPERS AND APPLICATION FOR THE ACCORDING TO THE ACTIVITIES AND THE STREETS AND ACCORDING TO THE ACTIVITIES AND ACCORDING TO THE ACCORDING TO THE ACTIVITIES AND ACCORDING TO THE AC

Joffing to the transcer Joffing to the transcer as the transce 110. 440, past/

PROPERTY, DESCRIPTION

ilian)

An Institute of the surface of ground with the improvements, continues the appropriate of the continues and appropriate of the continues and appropriate of the continues and the continues of the continues o

They are in those of many sides (Lighth Enthalm) in The PRT, as discours in a semigrate measurement of the large transfer of the semigrate of

InfoRmAIN, the field GAME at a scene encourage toward at the purposing at the feet attended extraplined and founding stocks with data of time result lies stocked. If a stock is 3 degrees, 39 mountains, 30 degrees, 19 degre tenergenes from 6. Interves Cortian, et al. in Lendar Bazzan Platt, et al. of yielding digit of 120 million resoluted allowing the intervest of continued and intervest of continued and intervest of continued and intervest of the 150 million of 150 million 15 or 9,40h2 series of tand.

BURETOLD make right of papers and expose as december in 1 ter 146/4 at home tod.

Subjectively said, to the cost of regress and agrees as decorate a fixer fability of Jose 460

ALTA/ACSM LAND TITLE SURVEY #4101 MANOR ROAD LIBER 14574 FOLIO 466 THE COLUMBIA FOUNDATION PROPERTY

> BETHESDA (7th) ELECTION DISTRICT MONTGOMERY COUNTY, MARYLAND SCALE: 1" = 50' AUGUST, 2002

> > SHEET 1 OF 1



SNIDER & ASSOCIATES
SURVEYORS - ENGINEERS
LAND PLANNING CONSULTANTS

2 PROPESSIGNAL DRIVE SHIFT 218 GATHERSBUIG, MARYLAND 20070 901/948-5100 • Fax 301/948-1289

APPROVA

New Fence , Ornamental Hoop and Space style Chain Link Fence

to be removed

Gate Ropairs


TILITY AT 1-800-257-7777 LOCATION AT LEAST 48 TO BEGINNING CONSTRUCTION.


SHOWN IN MONTGOMENY COUNTY TAK ADVESSMENT (PAGE 194-45


IS RECORDED AMENIO ONE CAME RECORDS OF MICHEMOTORIC IN 1986 H 14574 AT FOUND 466

JOSRESS WHOS MATION ROAD.

Montgomery County Historic Preservation Commission









HISTORIC PRESERVATION COMMISSION

Ike Leggett

County Executive

Julia O'Malley Chairperson

February 16, 2007

Timothy Zastrow
Bartlett Tree Experts
12200 Nebel Street
Rockville, MD 20852-2687

Re: Two (2) Trees, (1) Willow Oak tree and (1) White Pine tree at 4112 Manor Road

Dear Ms. Lewis,

I have received your arborist's report dated February 7, 2007 regarding the above-referenced trees, which documents the assessment that these trees are a hazard and are in severe decline.

Therefore, due to the health and hazard of the subject trees, the Historic Preservation Commission authorizes the removal of the trees.

This letter serves as your permission to remove the trees without further review by the HPC. If you have any additional questions, please do not hesitate to contact me at 301-563-3400.

Sincerely,

Michele Oaks, Senior Planner

Historic Preservation Section, M-NCPPC





12200 NEBEL STREET, ROCKVILLE, MD 20852-2687 • (301) 881-8550 • FAX (301) 881-9063

Ms. Michelle Oakes Dept. of Planning, Historic Preservation Office M-NCPPC 8787 Georgia Avenue Silver Spring, MD 20910

February 7, 2007

Re: Tree Removal on Hayes Manor property

Dear Ms. Oakes,

Please find enclosed three (3) Tree Inspection Reports for trees located on the Hayes Manor property owned by Howard Hughes Medical Institute. One of the trees is a dying Willow Oak tree located outside the fence on the south side which should be removed for safety. The next is a large White Pine tree located near the front of the Manor that was struck by lightning this past summer. The last is a report on the English Oak that was removed for safety this past summer after being damaged in a severe storm.

Our goal is to gain permission to remove the Willow Oak and the White Pine and inform you of the loss of the English Oak. Please call me with questions or comments, 301.343.2562.

Sincerely yours,

Timothy Zastrow, Arborist

Bartlett Tree Expert Company





Howard Hughes Medical Institute Attn: Mr. Stephen Parks 4000 Jones Bridge Road Chevy Chase, MD 20815-6789 February 7, 2007

301.215.8951 301.215.8957

TREE INSPECTION REPORT

TREE: #203 Willow Oak Tree (38.0" DBH)


TREE LOCATION: Hayes Manor, south side outside of fence adjacent to 4112 Manor Road.

DATE OF INVESTIGATION: November 2nd, 2006

ARBORIST: Timothy D. Zastrow, ISA Certified Arborist #MA-0043.

FINDINGS & RECOMMENDATIONS

This Willow Oak Tree, #203, has been in decline for several years. It was exhibiting crown die-back in 2003 and was pruned for safety at that time. It now has active hypoxalon canker, extensive crown die-back and is dropping large dead limbs. It should be removed for safety.





#203 Dying Willow Oak dead upper trunk and crown.



Howard Hughes Medical Institute Attn: Mr. Stephen Parks 4000 Jones Bridge Road Chevy Chase, MD 20815-6789 February 7, 2007

301.215.8951 301.215.8957

J**-**0709

TREE INSPECTION REPORT

TREE: #116 White Pine Tree (32.4" DBH)

TREE LOCATION: Hayes Manor, right front near Manor house.

DATE OF INVESTIGATION: September 11th, 2006 & January 23rd 2007

ARBORIST: Timothy D. Zastrow, ISA Certified Arborist #MA-0043.

FINDINGS & RECOMMENDATIONS

This White Pine Tree, #116, was struck by lightning this past summer. There is visible damage to bark on the upper and mid trunk and bark beetle (*Ips sp.*) activity on 40% of the circumference at the base. While this tree is still alive as of January, 2007, due to the vascular damage from the lightning strike and the bark beetle activity it is unlikely to survive next summer. Removal is recommended.





#116 Lightning Damaged White Pine tree.





#116 - Lightning Damaged White Pine Tree with Ips beetle activity.



Howard Hughes Medical Institute Attn: Mr. Stephen Parks 4000 Jones Bridge Road Chevy Chase, MD 20815-6789

February 7, 2007

301.215.8951 301.215.8957

TREE INSPECTION REPORT

TREE: #181 English Oak Tree (39.7" DBH)

TREE LOCATION: Hayes Manor at entrance gate.

DATE OF INVESTIGATION: June 27th, 2006

ARBORIST: Timothy D. Zastrow, ISA Certified Arborist #MA-0043.

FINDINGS & RECOMMENDATIONS

English Oak Tree, #181, lost a large section equal to almost ½ its current crown in a thunderstorm on June 26th. This was in addition to a major section that was lost in 2001 (see attached report). The limb fell over the entrance to the driveway at 4112 Manor Road taking the down the phone, power and cable lines. The large wound from the new damage extended down to within 18" of the top of the old wound. In addition a 12" diameter upright branch at the top of the remaining stem failed to leaf out Spring of 2006. This indicated physiological decline. The existing poor structure, new damage, and upper crown die-back combined to make complete removal the most prudent option.



#181 English Oak - lost this large limb 6/26/06.





#181 26" diameter split stem resulting in a 12' long wound on the main stem.



#181 Large wound on main stem and fallen section of crown.







Howard Hughes Medical Institute Attn: Mr. Stephen Parks 4000 Jones Bridge Road Chevy Chase, MD 20815-6789

March 1, 2004

301.215.8951 301.215.8957

TREE INSPECTION REPORT

TREE: #181 English Oak Tree (39.7" DBH)

TREE LOCATION: Hayes Manor at entrance gate.

DATE OF INVESTIGATION: February 9th, 2004

ARBORIST: Timothy D. Zastrow, ISA Certified Arborist #MA-0043.

FINDINGS & RECOMMENDATIONS

This English Oak Tree, #181, lost a large section in a storm several year ago resulting in a large wound on the west side. It has a strong lean to the south over the neighbor's driveway and across towards Manor Drive. In late 2003 a split in the trunk developed. It is at high risk for failure and should be removed.



#181 English Oak leaning towards road.



#181 large wound from old storm damage.



#181 new crack on tension (north) side of lean. Knife blade extends 3" into tree.

MEMORANDUM

TO:

Historic Area Work Permit Applicants

FROM:

Gwen Wright, Coordinator

WW Historic Preservation Section

SUBJECT:

Historic Area Work Permit Application - Approval of Application/Release of

Other Required Permits

Enclosed is a copy of your Historic Area Work Permit application, approved by the Historic Preservation Commission at its recent meeting, and a transmittal memorandum stating conditions (if any) of approval.

You may now apply for a county building permit from the Department of Permitting Services (DPS) at 255 Rockville Pike, second floor, in Rockville. Please note that although your work has been approved by the Historic Preservation Commission, it must also be approved by DPS before work can begin.

When you file for your building permit at DPS, you must take with you the enclosed forms, as well as the Historic Area Work Permit that will be mailed to you directly from DPS. These forms are proof that the Historic Preservation Commission has reviewed your project. For further information about filing procedures or materials for your county building permit review, please call DPS at 240-777-6370.

If your project changes in any way from the approved plans, either before you apply for your building permit or even after the work has begun, please contact the Historic Preservation Commission staff at 301-563-3400.

Please also note that you must arrange for a field inspection for conformance with your approved HAWP plans. Please inform DPS/Field Services at 240-777-6210 or online @ permits.emontgomery.org of your anticipated work schedule.

Thank you very much for your patience and good luck with your project!

C:\hawpapr.wpd



THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION Office of the Chairman, Montgomery County Planning Board

November 14, 2002

ME	MO	RAND	UM

TO:

Robert Hubbard, Director

Department of Permitting Services

FROM:

Gwen Wright, Coordinator

Historic Preservation

SUBJECT:

Historic Area Work Permit 35/10-02A

#290723

The Montgomery County Historic Preservation Commission has reviewed the attached application for a Historic Area Work Permit. This application was:

		-
v	Amman	\sim
X	Approve	

T '	
Deni	\sim
1 12 111	

Approved with Conditions:

and subject to the general conditions that 1) HPC Staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT

Applicant:

Howard Hughes Medical Institute

4000 Jones Bridge Road Chevy Chase, MD 20815

RE: Hayes Manor @ 4101 Manor Road





HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

				Contact Letzon: DE	spiren rarks	
				Daytime Plione No.:	301-215-89 <u>5</u>	51
Tax Account No.:	0042542	2				
Name of Property Own	er: Howar	d Hughes Med	lical Inst.	Daytime Phone No.:	301-215-89	51
				MD Steet		
	treet Number		City	Steet	201_222_76	Zip Cade
Contractor: Actic	n Fabri	cators & Ere	ectors Inc.	Phone No.:	301-322-70	
Contractor Registratio	n No.: MD .	Contractor I	License # 14	3//38		•
	Stephen	Parks		Daytime Phone No.:	<u>301–215–895</u>	51
Address:	DING/PHEMI	SF.				
House Number:			Street:	Manor Road		•
· -				Connecticut	Avenue	·
			: <u>Hayes Manc</u>			
		6 Paice				
PART ONE: TYPE	DF PERMIT AC	TION AND USE				
IA. CHECK ALL APP	UCABLE:		CRECK VITV	PPLICABLE:		
Construct	☐ Extend	☐ Alter/Renovate		Slab (Room Ad	ddition 🔲 Porch	☐ Deck ☐ Shed
Move	🔀 Install	☑ Wreck/Raze	Solar □	l Fireplace [] Woodbur	ning Stove	Single Family
[] Revision		_	X Fence/W	all (complete Section 4)	Other:	
18. Construction cos	i estimatei S	63,500				
tC. If this is a revisio	n of a previously	approved active primit,	see Permit #			
PART TWD: COM	PLETE FOR NE	WCONSTRUCTIONA	ND EXTEND/AUDITIO	NS		
ZA. Type of sewage				03 Other:		
ZB. Type of water s				03 Other:		
		FOR FENCE/RETAININ	IG WALL			
JA. Height6	leet0	inches				
38. Indicate whether	er the tence or re	etaining wall is to be con	structed on one of the la	llowing locations:		
∰ On party line	property line	🖾 Entirely an	land of owner	Ki On public right of wa	ay/easement	
			· · · · · · · · · · · · · · · · · · ·			
i hereby certify that i	liave the authories listed and	city to make the foregoin I pereby acknowledge at	g appronunt, that the n of accept this to be a co	pplication is correct, and the indition for the issuance of	int the construction w this permit.	ili compiy with plans
1, 1	,					
Sted	<u>~ /</u>	I links			10/23/0	2
	Signature of over	ner or authorized agent			/ / Dat	· .
	(i					
ybbioseq:,	-4		For Chairpo	rson, Historic Preservation	i Commission	112102
Disapproved:		Signature:		1/12/2/2	Date: / /	112/00
Application/Permit N	o.: <u>C</u>	X10120	Day Fil	Valsalp -	ls sued:	
Falir 6/21/99		SEE REVE	RSE SIDE FUT	STRUCTIONS		•
				# T		

1. WRITTEN DESCRIPTION OF PROJECT

L	Description of existing structure(s) and environmental setting including their historical features and significance: Hayes Manor, Circa 1762, a two-and-a-half story, five bay by two bay
	structure, is considered one of the finest Georgian style manor houses
	in Maryland, with exceptionally fine brick work outside and woodwork
	fashioned with great craftmanship inside. Situated on 9.44 acres, Hayes
	Manor is surrounded by stately, mature walnut, hickory and oak trees,
	boxwood garden, and bowling green. (Master Plan Site 35/10)

6. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district

(1) Repair, straighten & paint the original ironwork of both entrance gates to preserve the historic character of the gates and pediments.

(2) Enclose the west & south boundaries of the property. (3) Remove an old chain link fence on the west boundary. (4) Remove one Walnut tree at the left pediment of the west gate, as recommended by HPC staff, because the tree roots could damage the gate pediment.

2. SITE PLAN

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date:
- b, dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping,

J. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11° x 17° Plans on 8 1/2° x 11° paper are preferred.

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- 5. Elevations (lacades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context.
 All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each lacade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the percel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

EXPEDITED HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

4101 Manor Road

Meeting Date:

11/13/02

Applicant:

Howard Hughes Medical Institute

Report Date:

11/6/02

Resource:

(Stephen Parks, Agent)

Public Notice:

10/30/02

Review:

HAWP

Hayes Manor

Tax Credit:

No

Site Number:

35/10-02A

Staff:

Robin D. Ziek

PROPOSAL: Install wrought iron fencing along south and west perimeter of property; install new operable entry gate at south entry drive; remove one walnut tree adjacent to the left

wing of the west gate to avoid damage to the historic brick wall.

RECOMMEND:

Approval

DATE OF CONSTRUCTION: 1762

SIGNIFICANCE: X Individual *Master Plan* Site

Within a Master Plan Historic District

Primary Resource Contributing Resource

Non-Contributing/Out-of-Period Resource

ARCHITECTURAL DESCRIPTION: Two story brick Georgian house, with later additions. The property has significant interior woodwork accredited to William Buckland. There is a continuous drive through the property, with brick entry features at the south and west entrances, and wrought iron gates spanning between the brick. In addition, when the property immediately to the south of the historic property was subdivided, an additional drive was added just east of the south brick entry, and the historic entrance was abandoned for daily use.

PROPOSAL: The central offices for the Howard Huges Medical Institute sit on the property immediately to the east of Hayes Manor. Their existing property is currently enclosed with metal picket fencing (see Circle 14). The Ornamental Hoop and Spear type fencing measures 72" in height. As HHMI has recently purchased Hayes Manor, they would like to install the same metal fencing around the historic site. A new operable gate would be installed at the south entrance. The iron gate at the west entrance will be repaired and repainted. An existing chain link fence along the west boundary of the property will be removed and replaced with the wrought iron type of fencing (see Circle //). Along the west edge of the property, the fencing will follow a rough diagonal, going from the corner of existing fencing on the HHMI property immediately to the north of Haves

rough diagonal, going from the corner of existing fencing on the HHMI property immediately to the north of Hayes Manor, to the historic brick gates at the west entrance (see Circle \P). A "volunteer" walnut tree (21 "DBH) which has grown up adjacent to the west gates will be removed (see Circle $\mathcal B$). This tree is encroaching on the historic brick wall and will cause future damage.

RECOMMENDATION: X Approval Approval with conditions:

Approval is based on the following criteria from Chapter 24A of the Montgomery County Code, Section 8(b): The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:

- _X_ 1. The proposal will not substantially alter the exterior features of an historic site, or historic resource within an historic district; or
- X 2. The proposal is compatible in character and nature with the historical, archaeological, architectural or cultural features of the historic site, or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or

and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work <u>and</u> not more than two weeks following completion of work.







HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

	Contact Person: Stephen Parks
	Daytime Phone No.: <u>301-215-8951</u>
Tax Account No.: 00425422	
Name of Property Owner: Howard Hughes Medical Inst.	Daytime Phone No.: 301-215-8951
Address: 4000 Jones Bitidge Rd. Chevy Chas	se MD. 20815-6789
Street Number City Combacton: Action Fabricators & Erectors Inc.	Sieet Zip Code No.: 301-322-7600
Contractor Registration No.: MD. Contractor License # 1	
Agent for Owner: <u>Stephen Parks</u> Address:	Daysime Phone No.: 301-215-8951
LOCATION OF BUILDING/PHEMISE	
House Number: 4101 Street	Manor Road
Town/City: Chevy Chase Nearest Cross Street	Connecticut Avenue
Lot: P Block: 212 Subdivision: Hayes Mai	nor
Liber: <u>14574</u> Folio: <u>466</u> Parcel: <u>C18</u>	
PART ONE: TYPE OF PERMIT ACTION AND USE	· · · · · · · · · · · · · · · · · · ·
	1 ADDUCADUS.
	LAPPLICABLE:
	[] Slab [] Room Addition Porch Deck Shed
	[] Fireplace 1] Woodburning Stove
	Wall (complete Section 4) Uther.
18. Construction cost estimate: \$ 63,500	
1C. If this is a revision of a previously approved active permit, see Permit #	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/ADDIT	IIONS
7A. Type of sewage disposal: 01 €1 WSSC 02 1,1 Septic	03 † Dilier:
2D. Type of water supply: 01 🖒 WSSC 02 🕕 Well	03 Diher:
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
JA. Height 6 leet 0 inches	
38. Indicate whether the fence or retaining wall is to be constructed on one of the	following Incations:
(X) On party line/property line 🔯 Entirely on land of owner	X) On public right of way/easement
Thereby certify that I have the authority to make the foregoing application, that the approved by fill agencies listed and I reachy accommodage and accept this to be a full accept the second of the	
Approved:For Chair	rperson, Historic Preservation Commission
Disapproved: Signature:	Date:
Application/Pernit No.: 290723 Date	Filed: 10/23/07 Date la sued:

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

1	Description of existing structure(s) and environmental setting, including their historical features and significance:
	Hayes Manor, Circa 1762, a two-and-a-half story, five bay by two bay
	structure, is considered one of the finest Georgian style manor houses
	in Maryland, with exceptionally fine brick work outside and woodwork
	fashioned with great craftmanship inside. Situated on 9.44 acres, Hayes
	Manor is surrounded by stately, mature walnut, hickory and oak trees,
	boxwood garden, and bowling green. (Master Plan Site 35/10)

6. General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district
(1) Repair, straighten & paint the original ironwork of both entrance gates to preserve the historic character of the gates and pediments.
(2) Enclose the west & south boundaries of the property. (3) Remove an old chain link fence on the west boundary. (4) Remove one Walnut tree at the left pediment of the west gate, as recommended by HPC staff, because the tree roots could damage the gate pediment.

2. SITE PLAN

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b., dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

J. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a formal no larger than 11"x 17". Plans on 8 1/2"x 11" paper are preferred.

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resourcets! and the proposed work.
- 5. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context.
 All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must like an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the percel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

PLEASE PRINT (IN BLUE OR BLACK INK) OR TYPE THIS INFORMATION ON THE FOLLOWING PAGE.
PLEASE STAY WITHIN THE GUIOES OF THE TEMPLATE. AS THIS WILL BE PHOTOCOPIED DIRECTLY ONTO MAILING LABELS.



HAWP APPLICATION: MAILING ADDRESSES FOR NOTICING

[Owner, Owner's Agent, Adjacent and Confronting Property Owners]

Owner's mailing address

Howard Hughes Medical Inst. 4000 Jones Bridge Road Chevy Chase, MD 20815 Owner's Agent's mailing address

Stephen D. Parks Howard Hughes Medical Institute 4000 Jones Bridge Road Chevy Chase, Md 20815

Adjacent and confronting Property Owners mailing addresses

Columbia Country Club 7900 Connecticut Avenue Chevy Chase, MD 20815-5938 John J. & K.C. Barry 4004 Manor Road Chevy Chase, MD 20815

Edward M. & S. M. Prince 8519 Longfellow Place Chevy Chase, MD. 20815

Columbia Foundation 7900 Connecticut Avenue Chevy Chase, MD 20815 - 5938

Sara G. & M.H. Dent 4112 Manor Road Chevy Chase, MD 20815

graddresses; noticing table

Materials Specifications

Scope:

Fabricate and install approximately 1300 linear feet of new Ornamental Hoop and Spear type fence 72" high to include repairs to two existing double drive gates. New materials to be the same as or equal to existing on job site.

Materials to be as follows:

All Pickets shall be $\frac{1}{2}$ " round welded to (3) 1 $\frac{1}{2}$ x $\frac{1}{2}$ x 1/8" steel channels. All welds shall be from the non-exposed underside of machine punched channels.

Fence style shall be picket hoop with picket in center of hoop. Each picket shall have a welded decorative spear. Spacing of pickets shall not exceed 4".


All corner, end and line posts shall be 2 ½" square spaced not to exceed 6'6" on center with welded drive anchors for additional support. Gate posts shall be 4" square tubular steel set in 18" x 42" concrete footers with welded drive anchors.

Total fabrication and installation to be of welded construction. All welds are shipped, exposed welds are ground smooth. New materials shall be cleaned, primed and shall receive (2) coats of green paint.

Remove existing drive gates, shop repairs to include replacement of rusted or missing steel, straighten as feasible, sand blast steel – prime, paint and reinstall.

Remove and haul Old Fence





SURVEYOR'S CERTIFICATE:

MEALTH LAND TITLE INSURANCE COMPANY AND HOWARD HUGHES MEDICAL

THIS IS TO CERTIFY THAT THIS MAP OR PLAT AND THE SURVEY ON WHICH IT IS BASED WERE MADE IN ACCORDANCE WITH "MANIMUM STANDARD DETAR REQUIREMENTS FOR A LIA/ACSM LAND TILLE SHARENS", WORTHLY ESTANDARDS AND AND STANDARD AND AND THIS HIS SHAREND AND ADDRESS (TEMPORADES) AND ADDRESS AND ACQUIREMENT TO THE ACCURACY STANDARDS AS ADDRESS AND ACQUIREMENT TO THE ACCURACY STANDARDS AS ADDRESS AND ACQUIREMENT AND IN EFFECT ON THE DATE OF THIS CERTIFICATION, UNDESSIGNED FURTHER CERTIFICATION, AND APPOINTS SURVEY PRESIDENT, WARREST AND ACQUIREMENTS FOR SURVEY VERSIONS WERE COMPANIENTS FOR SURVEY VERSIONS AND ACQUIREMENTS FOR SURVEY VERSIONS AND AND THE SURVEY VERSIONS AND THE DESTRUCTION AND APPOINTS FOR ALL AND SURVEY PROPERTY.

JEFFREY A. FOSTER
PROPERTY LINE SURVEYOR
MO. REG. #587



ADC MAP PAGE 36, GRID SCALE: 1" = 2990'

PROPERTY DESCRIPTION

All that place or percel of ground, with the Improvements, adsements and appurtenances thereunto belonging, situate, lying and being in the County of Montgomery, State of Moryland being described as follows, to wit:

Port of a linet of land called "CLEM CRIVINGE" or "NATES", as described in a consequence from Jerme D Guers to General I., Danklo by deed shotel May 17. 1857 in The JA. 31 of Fails 316; and port of a conveyance from Mermon B. Frest, et au. to Ernest S. Johnston, et u.e. by Deed cates May 12. 1881 in Liber 2847 and Fails 60; both recorded among the Land Reards of Montgomery County, Monyland, and being more portiourarly described per a current survey as shown heroon; no statures.

GEODIVICO TRE TALLE ST o store mouveant found or the boginning of the first oforestall according to the month, these are stored to the boginning of the first oforestall according to the month, and the store of the first of the BEGINNING FOR THE SAME at a stone manument found at the baginning of the first aforesaid

TOCETHER WITH right of ingress and egress as described in Liber 14574 of Folia 465.

SUBJECT HOWEVER, to the dobt of incress and energy or described in Liber 14574 at Folio 466 Subject to any and all canditions of record.

ALTA/ACSM LAND TITLE SURVEY #4101 MANOR ROAD LIBER 14574 FOLIO 466 THE COLUMBIA FOUNDATION PROPERTY

BETHESDA (7th) ELECTION DISTRICT MONTGOMERY COUNTY, MARYLAND SCALE: 1" = 50' AUGUST, 2002

SHEET I OF 1



SNIDER & ASSOCIATES SURVEYORS · ENGINEERS LAND PLANNING CONSULTANTS 2 PROFESSIONAL ORIVE, SUITE 216 GAITHERSBURG, MARYLAND 20879 301/948-5100 · Fax 301/948-1286

DRAFTING ENGNEERING PROJECT


CALL "MISS UTILITY" AT 1-800-257-7777 FOR UTILITY LOCATION AT LEAST 48 HOURS PRIOR TO BEGINNING CONSTRUCTION.

3. PROPERTY ADDRESS #4101 MANOR RDAD.


4. PROPERTY IS RECORDED AMONG THE LAND RECORDS OF MONTGOMERY COUNTY IN LIBER 145/4 AT FOLIO:466. 5. THE TYPE AND NATURE OF ALL THE LITHINGS SHOWN HEREIN HAS BEEN ESTABLISHED BY ONSITE OBSERVATIONS AND FIELD LOCADON AND MAS NOT BEEN MERRIED WITH UNLITY RECORDS ON PLANS EXCEPT AS PROVIDED BY CLIENT.

> DATE REVISION ADDITIONAL IMPROVEMENTS









SURVEYOR'S CERTIFICATE:

TO: COMMONWEALTH LAND TITLE HISDIANCE COMPANY AND HOWARD HUGHES MEDICAL RISTITUTE.

THIS IS TO CERTETY THAT THIS MAP OR FLAT AND THE SURVEY ON WHICH IT IS BASED THERE MADE IN ACCORDANCE WITH THANKING STANDARD GETAIL RECURRENCITY FOR ALTA/ACSU LAND THE SURVEY'S, JOHNTY CSTANDARD AND ADDRESS AND MEST WITH 1999, AND INCLUDES THEMS 1,2,3,4 ((3),8,10,11(6),11(6)). IT IS OF MADE TO "THEREOF, PURSUANT TO THE ACCURATOR STANDARDS AS ADDRESS OF WITH A THANK AND ACCURATOR STANDARDS AS ADDRESS OF WITH A THANK AND ADDRESS AND ACSULARD STANDARDS AS ADDRESS AND ASSULAND AND REPORT OF THE DATE OF THIS CERTIFICATION, WORKERS AND ASSULAND FOR THE PROPERTY FALLO PROCEDURES. IN THE "HIMMUM ANGLE, DISTANCE AND CLOSURE REQUIREMENTS FOR SURVEY HEASUREMENTS WHICH CONTROL LAND BOUNDARIES FOR ALTA/ACEM LAND TITLE SURVEYS." FOR MALE

Jeffry A. FOSTER

JEFFREY A. FOSTER

PROPERTY CINE SURVEYOR

100. REG. 19587



PROPERTY DESCRIPTION

All that picts or sorted of yound, with the improvements, elegaments and appurtunances thurwish bettering, situate, lying and being in the County of Managamery, State of Maryland, being described as follows, for with:

Port of a loct; of load across "TE,EAH DRIBONE" or "HAYES", so accorded in a compared born Johns of John D. General T. Marche by season served log; 17, 1802 or John A. 33, or Fall-3/B; and goal of a compared from Neumon B. Frest, of tax to Eneral S. Johnston, at us, by Dece Casted May 12, 1861 in Liber 2487 and Fallo SB); bath recented among the Lond Records of Martigemery County, Maryland, and being more particularly discribed per a current survey os shown highers. To (Islabrus:

BECININIO FOR THE SAME at a statue menument found at the beginning at the first chiorsaid conveyance and running theme with port of the first fine threath. (1) North 2 degrees 19 minutes 30 seconds first 130,50? Keet to a pipe found of thus and of the 5th or tost line of a conveyance and running theme, at 12 to 1 a pipe found of thus and of the 5th or tost line of a conveyance train 6. Thomas blanks, at 12 to 1 a pipe found of thus and of the 5th or tost line of a conveyance train 6. The first 34th threath 130,000 to 1 a pipe found of thus and 5th or 15th 34th 130,000 to 1 a pipe found of the 5th 34th 130,000 to 1 a pipe found of the solid blanks of the 5th 34th 130,000 to 1 a pipe found of the 5th 34th 130,000 to 1 a pipe found of the 5th 34th 130,000 to 1 a pipe found of the 6th 34th 130,000 to 1 a pipe found of the opin found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 5th 130,000 to 1 a pipe found of the 6th 130,000 to 1 a pipe found thereo (3) activity 6th 4 degrees 35 minutes 10 seconds 5th 150,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (3) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (4) activity 6th 130,000 to 1 a pipe found the 6th 130,000 to 1 a pipe found thereo (3) act Eng. thence arming with the remainder of sold line (12) North 19 degrees 56 minutes 31 seconds Wast 282.99 feet to the place of biglinning, containing 411,133.5 square feet of land or 9,4383 acres of land,

TOGETHER With faint of lacress and coress as sesented in Liber 16574 at Falia 460. SUBJECT.HOMEVER, to the right of ingress and egress as described in Liner 14574 at Folio 466.

Subject to any and all conditions of record.

ALTA/ACSM LAND TITLE SURVEY #4101 MANOR ROAD LIBER 14574 FOLIO 466 THE COLUMBIA FOUNDATION PROPERTY

> BETHESDA (7th) ELECTION DISTRICT MONTGOMERY COUNTY, MARYLAND SCALE: 1" = 50' AUGUST, 2002

> > SHEET | OF |



SNIDER & ASSOCIATES SURVEYORS · ENGINEERS
LAND FLANNING CONSULTANTS 2 PROFESSIONAL DRIVE, SUITE 216 GAITHERSBURG, MARYLAND 20879

301/948-5100 • Fax 301/946-1288 ENCINCERING DRAF BHO

"MISS UTILITY" AT 1-800-257-7777
UTILITY LOCATION AT LEAST 48
RS PRIOR TO BEGINNING CONSTRUCTION.

5. THE TYPE AND NATURE OF ALL THE UNITIES SHOWN HEREON HAS BEEN ESTABLISHED BY DUSITE COSERVATIONS AND FIELD LOCATION AND HAS NOT BEEN MERIFED WITH UTILITY RECORDS OR PLANS EXCEPT AS PROVIDED BY CLERT.

Gate Repairs


New Fence, Ornamental Hoop and Spear style

DATE

Chain Link Fence


to be removed





SNIDER, & ASSOC., INC.

6



Photos

- Entry gate, as viewed from Manor Rd.
- Manor Road Gate from property
- West Gate (View from Columbia Country Club)
- Chain Link fence on portion of West boundary to be removed
- Typical fence, to match existing at Howard Hughes Medical Institute



Entry gate, as viewed from Manor Rd.
Ironwork to be straightened, repaired, sand-blasted, primed and painted



Typical fence, to match existing at Howard Hughes Medical Institute



West Gate (View from Columbia Country Club)

(HPC staff has indicated roots of the walnut tree to the left of the gate may damage the masonry foundation and should be removed.)



Chain Link fence on portion of West boundary to be removed




FAX TRANSMITTAL SHEET

Historic Preservation Office Department of Park & Planning


Fax Number: (301)-563-3412

Telephone Number: (301) 563-3400

TO: Dieter Willcomm FAX NUMBER: 301.215.8957
TO: Dieter Willcomm FAX NUMBER: 301.215.8957 FROM: Zolin Zek
DATE: 9.18.02
NUMBER OF PAGES INCLUDING THIS TRANSMITTAL SHEET:
NOTE:
As Reguested -



SNIDER, & ASSOC., INC.





	RODIN ZIEK		301.563.34	08
		Mark Winkler a	703 578 7	798
·	Bob Obrist	((703-578-	1136
}	SCOTT WOLFORD	PHRA	301. 528.	4300
	PATRIGA MONDAY	PHRA	301.528.4	3 <i>0</i> 0
	CRAIG ALEXANDER	The state of the s	INSTITUTE 30/-1	15-8841
	JONATHAN RODVIEN	BONIE GRIDLEY A	echitects 20	2.337.0888
	GWEN WRIGHT	MNCPPC	(301) 563 -	3400
	11 1 ₁ 1•			
	1			
	•			
]. ;			
• • • • • • • • • • • • • • • • • • •			Advantage - Advantage	



October 23, 2002

Department of Permitting Services 255 Rockville Pike, 2nd Floor Rockville, MD 20850

To Whom It May Concern:

Please find enclosed an application for a Historic Area Work Permit (HAWP) for work to be performed at the Hayes Manor, recently acquired by the Howard Hughes Medical Institute.

By enclosing this designated historic site, it is our hope to protect the character of the Manor House, enhance the grounds and secure the property.

We appreciate your review of this HAWP and look forward to meeting with the Historic Preservation Commission on November 13, 2002.

Sincerely,

Stephen D. Parks

Associate Director, Facilities

SDP:pb Enclosures

Index

- 1) Application For Historic Area Work Permit
- 2) Site Plan (Reduced to 8 ½ x 11")
- a. Schematic Construction Plansb. Elevation (sketch and typical photo)
- 4) Materials Specifications
- 5) Photographs
- 6) Tree Survey and Photo
- 7) Adresses of Adjacent and Confronting Property Owners