5415 Mohican Road, Bothesola
[Ind Preliminary Consultation]
Master Phn Strat 35/29, Biltzhy Castle

Apendaticx

153 1/3 Series File Folders

www.pendaflex.com 10% P4 MADE IN USA

2nd Preliminary Consultation MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 5415 Mohican Road, Bethesda Meeting Date: 10/12/11

Applicant: Ross McNair and Alison Taylor Report Date: 10/5/11

Resource: Master Plan Site #35/29, Baltzley Castle Public Notice: 9/28/11

Review: 2nd Preliminary Consultation Tax Credit: Partial

Case Number: N/A Staff: Josh Silver

PROPOSAL: Construction of addition and garage and other alterations

STAFF RECOMMENDATION

Staff recommends that the applicants make revisions to the plans based on comments and feedback from the HPC and staff and return for a Historic Area Work Permit.

PROPERTY DESCRIPTION

SIGNIFICANCE: Master Plan Site #35/29, Baltzley Castle

STYLE: Eclectic

DATE: 1890

ARCHITECTURAL HISTORY

The following was excerpted from Places from the Past: The Tradition of Gardez Bien in Montgomery County, Maryland.

This large stone house is one of three residences built by the twin brothers Edwin and Edward Baltzley for their proposed Glen Echo community. In keeping with their vision of a Rhineland on the Potomac, the brothers conceived of the castle theme for their residences. The Baltzleys hired Philadelphia architect Theophilus Parsons Chandler to design the house, which likely served as a model for the proposed community. Chandler also designed Glen Echo Chautauqua's Amphitheater (no longer standing). The Baltzley Castle has a crenelated porte-cochere, round three-story tower, stone bracketed cornices, red slate roof with terra cotta cresting, and tall, corbelled chimneys. The house is constructed of granite from local quarries that the Baltzleys operated. A prolific inventor, Edwin Baltzley made his fortune on a patented mechanical eggbeater. The brothers, beginning in 1888, purchased over 900 acres and platted the Glen Echo Heights subdivision (with a whimsical street plan resembling the human cranium). A disastrous 1890 fire at the Baltzley's Glen Echo Cafe and rumors of malaria put an end to the Baltzley's real estate business. Edward and Laura Baltzley owned the Baltzley Castle until 1892, and Edwin resided here from 1897, owning the house until his death in 1919.

BACKGROUND

On July 13, 2011 the HPC held a Preliminary Consultation hearing for the proposed construction of a one and two story side addition, three car detached garage, glass dormer replacement and other alterations at

56

The HPC provided the following comments in response to the applicant's proposal:

| PROPOSED CHANGE | HPC COMMENTS | nt's proposal: HPC RECOMMENDATIONS | | |
|--------------------|--|---|--|--|
| ADDITION | Support for removal of the existing one story non-original lean-to addition to accommodate an alternative design for a side addition on the right side elevation Support for the construction of a contemporary style side addition Consideration needs to be given to the scale of the additions parts Addition is too high and large Explore alternative roof forms and materials. | Focus on the dichotomy between the larger window sizes on the existing house versus smaller window sizes proposed for the side addition Look more closely at the bigger scale of the historic massing and take cues from its scale when developing the new proposal Pull addition back from the tower to allow it to read as fully independent from the tower section. No physical attachment between the front tower of historic massing and new addition. Reduce size of the addition Use flat roof system. Possible material types include rubber membrane or green roof. Provide floor plans for 2nd Preliminary Consultation review with HPC | | |
| FRONT PORCH | Consensus the proposed fixed glass pieces were a feasible option. Questions about the installation method of the glass and access door between the porch and grade need to be addressed before returning for a 2 nd Preliminary Consultation | Provide more detail about the proposed installation method of the glass and door. | | |
| GLASS DORMER | Support as proposed. | No recommended changes. | | |
| GARAGE | Location must comply with established setback requirements for the property Size and scale too large Angled roof problematic No standing seam metal roof. | Determine appropriate setback Reduce size Majority supported two car garage design. Some support for two car garage with open carport Design should be consistent with the revised design for the side addition Use an alternative roof form and materials. | | |

PROPOSAL

The applicants are proposing to:

Kitchen addition:

Remove the existing one story lean-to addition and construct a 13 ft x 27 ft kitchen addition on the east side of the existing resource, and to the rear of the square turret. The design is structural steel "C" channels and columns forward of the doors and windows. The roof structure is flat with 20 ounce flat seam copper roofing. The lower level is a walk out facing MacArthur Boulevard. All corners and trim will be clad to match the window cladding. The roof will align with the main section of the Porte Cochere at the rear which sits approximately 1- 1/2 ft below the 2nd floor window sills. An existing deteriorated stone retaining wall on the right side of the existing house that serves as a partial foundation for the one story lean-to addition will be removed to create buildable area for the proposed kitchen addition.

Non reflective glass front porch:

Install curved, 9/16 tempered, full view, fixed, non-reflective glass. There will be no operating windows, screens or mullions. One all glass door will provide access to the stairs. The glass pieces will be set behind the decorative wood brackets that currently brace the roof structure.

Glass dormer replacement:

Replace the existing 3rd floor glass dormer on the left side elevation with a wood, full view, fixed glass window. Proposed modifications include measures to adjust the framing for proper water drainage to prevent future damage.

Detached garage:

Construct a 2 car detached garage and 1 car carport set off the rear and right side property lines 5 feet. The rear and right side walls will be concrete retaining walls as the garage is set into the slope. The structure will match the proposed kitchen addition in height and with the steel beams and columns forward of the garage doors and wall sheathing. The wood garage doors will be outward swinging carriage doors and the roof is to match the kitchen addition as a flat roof structure with copper flat seam roofing. The wood doors, trim and panels will be painted the color of the kitchen addition.

Geo Thermal Wells:

The vertical drilled geo thermal wells will be in the rear yard, beside the driveway and set off the property line five feet. There are no site features disturbed as a result of the installation.

Generator:

A natural gas generator, measuring 48 x 26 x 29 will be sited in the rear right side yard. The proposed generator will be set off the house 12 feet and property line 17 feet. No site features are disturbed as a result of the installation.

APPLICABLE GUIDELINES

When reviewing alterations and new construction to a Master Plan site several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include Montgomery County Code Chapter 24A (Chapter 24A) and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A-8:

- (a) The commission shall instruct the director to deny a permit if it finds, based on the evidence and information presented to or before the commission that the alteration for which the permit is sought would be inappropriate, inconsistent with or detrimental to the preservation, enhancement or ultimate protection of the historic site or historic resource within an historic district, and to the purposes of this chapter.
- (b) The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:
 - (1) The proposal will not substantially alter the exterior features of an historic site or historic resource within an historic district; or
 - (2) The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter; or
 - (3) The proposal would enhance or aid in the protection, preservation and public or private utilization of the historic site or historic resource located within an historic district in a manner compatible with the historical, archeological, architectural or cultural value of the historic site or historic district in which an historic resource is located; or
 - (4) The proposal is necessary in order that unsafe conditions or health hazards be remedied; or
 - (5) The proposal is necessary in order that the owner of the subject property not be deprived of reasonable use of the property or suffer undue hardship; or
 - (6) In balancing the interests of the public in preserving the historic site or historic resource located within an historic district, with the interests of the public from the use and benefit of the alternative proposal, the general public welfare is better served by granting the permit.
- (c) It is not the intent of this chapter to limit new construction, alteration or repairs to any one period or architectural style.
- (d) In the case of an application for work on an historic resource located within an historic district, the commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value of surrounding historic resources or would impair the character of the historic district. (Ord. No. 9-4, § 1; Ord. No. 11-59.)

Secretary of the Interior's Standards for Rehabilitation:

Standard #1: A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces and spatial relationships.

Standard #9: New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.



Standard #10: New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

STAFF DISCUSSION

Staff commends the applicants' ongoing rehabilitation efforts at the site. Staff did a site visit to the property on September 30, 2011 and observed a considerable amount of completed rehabilitation work at the property. The most noticeable improvements were the in-kind roof replacement, porch repairs and repointing work.

One story side addition:

Staff supports the proposed removal of the existing non-original, one-story side elevation lean-to addition. The proposed demolition would not remove any character-defining features and have minimal impact to the historic massing. The removal of this addition is consistent with the HPC recommendation at the 1st Preliminary Consultation.

Construction of two story side addition:

Staff supports the construction of a two story side addition at the subject property as submitted. The HPC generally requires additions to be placed at the rear of a historic structure to minimize the visual impact of new construction on the primary façade. Staff supports a side addition in this case because this resource has two primary elevations: the south, with its ornate façade viewed from MacArthur Boulevard, and the north, possessing the formal entrance for visitors to Baltzley Castle.

The proposed addition redesign responds directly to the HPC's feedback provided at the 1st Preliminary Consultation. The addition is placed behind and completely independent from the front tower and the issue of scale and expression has been addressed by using a more vertical window order and contemporary building design. The roof system was flattened to avoid competing with the 2nd floor and tower windows and a basic floor plan is provided to assist the HPC in their review of the revised plans.

The removal of the non-original lean-to addition and construction of the proposed two story addition will require the removal of an existing L-shaped stone retaining wall. The retaining wall currently serves as a partial foundation for the lean-to addition the HPC said could be removed at the 1st Preliminary Consultation and also helps retain the existing grade change of the property. Staff performed a field inspection to document the condition of wall and judge its significance to the historic environmental setting of the site. Staff documented a partially collapsed wall in certain locations and significant deterioration such a loose and/or removed stones. Staff also determined the wall is likely contemporaneous with the existing lean-to addition which is not original to the house. Staff supports the complete removal of the wall as a result of these observations, finding that the wall is not a character-defining feature to the site and its removal would not substantially alter an original feature of the site.

Front porch:

Staff supports the proposed installation of non-reflective glass in the openings of the front porch. The proposed installation of full view, fixed, non-operable glass sections behind the decorative wood brackets will have negligible impact on the structure and is consistent with Secretary of the Interior Standard's for Rehabilitation #1, 9 & 10. The applicant has provided additional details about the installation method of the glass and door to assist the HPC with their review of the proposal.

The proposed installation of non-reflective glass still allows the front porch to be used as a functional living space. The proposed installation method of the glass behind the decorative brackets does not destroy historic materials, features and or spatial relationships that characterize the property. The



proposed work if removed in the future would not disturb the essential form and integrity of the front porch.

Staff supports the proposed repairs, rebuilding and/or replacement in-kind to features and decorative elements on the front porch. The applicants have secured high resolution historic photos of the front porch to assist them with reconstructing damaged and missing elements.

Glass dormer replacement:

Staff supports the proposed glass dormer replacement. The HPC had no concern with replacing the dormer at the 1st Preliminary Consultation because of the features deteriorated condition. The proposed design is respectful of the existing design while using a construction method that will prevent future water infiltration and deterioration to the interior of the structure.

Construction of two car/one car carport detached garage:

Staff supports the proposed construction of a two car garage with a single detached car port. The redesign responds to the HPC's feedback and is now compatible with the proposed two story addition and uses a flat roof form. The mass of the garage is broken up by the addition of a detached one car carport which helps mitigate its size. Furthermore, the proposed garage location, set within the existing ground slope coupled with the flat roof design should help mitigate some of the size and height concerns on the adjacent property. The applicants have confirmed the redesign complies with the properties established setbacks.

Geo Thermal Wells and Generator Installation

Staff supports the proposed installation of geo thermal wells and one generator at the property. The proposed installations will have negligible impact on the environmental setting.

STAFF RECOMMENDATION

Staff recommends that the HPC provide the applicants with guidance on the following items:

- 1. Construction of two story side addition
- 2. Front porch alterations
- 3. Construction of two-car detached garage and single carport.

Staff recommends that the applicants make revisions to the plans based on comments and feedback from the HPC and staff and return for a Historic Area Work Permit.



DPS - #8



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: Ross Manlace

Daytime Phone No.: 301-219-0380

| | | Daytime Phone No.: 30 | T-514-03 | 80 |
|--|---|--|---|-------------|
| Tax Account No.: 00508301 | | | | |
| Name of Property Owner: ROSS Menkey | 118+ 2 | 70/ March phistal | 915-105 | 0880 |
| Address: 5415 Mo Hicam | City B | n accord | N 80 8 CV | <u> </u> |
| Contractor: ONNER | | Phone No.: | | |
| Contractor Registration No.: 124 264 | · | | | |
| Agent for Owner: | | Daytime Phone No.: | | |
| LOCATION OF BUILDING/PREMISE | | | | |
| House Number: 5415 moltice | Street: _ | RD | | |
| Town/City: Betheron | Vearest Cross Street: | MacARH | arly zu | |
| Lot: Block: Subdivision: | Seetio | M / Plen | echo Ho | rt Hai |
| Liber: 2697 Folio: 135 Parcet | | | | |
| PART ONE: TYPE OF PERMIT ACTION AND USE | | - | | _ |
| 1A. CHECK ALL APPLICABLE: | CHECK ALL A | PPLICABLE: | | |
| ⑤ Construct ☐ Extend ☐ Alter/Renovate | □ AC □ | Slab | ☐ Porch ☐ Deck ☐ She | ed ' |
| ☐ Move ☐ Install ☐ Wreck/Raze | ☐ Solar ☐ | Fireplace | e Single Family | |
| ☐ Revision | ☐ Fence/Wa | If (complete Section 4) 🔲 Oti | er: | |
| 18. Construction cost estimate: \$ | | | · | |
| 1C. If this is a revision of a previously approved active permit, see | Permit # | | | |
| PART TWO: COMPLETE FOR NEW CONSTRUCTION AND | EVTEND/ADDITIO | 16 | | |
| | 02 Septic | | • | • |
| | 02 🗀 Septic | 03 🗆 Other: | <u> </u> | _ |
| 20. Type of Water Supply. | OZ WES | us of duter. | | |
| PART THREE: COMPLETE ONLY FOR FENCE/RETAINING | VALL | | | |
| 3A. Height feet inches | | | | |
| 38. Indicate whether the fence or retaining wall is to be constru | cted on one of the folk | owing locations: | | |
| ☐ On party line/property line ☐ Entirely on land | l of own er | On public right of way/easems | भारे | • |
| I hereby certify that I have the authority to make the foregoing at approved by all agencies listed and I hereby acknowledge and a suppose of the suppose of | plication, that the app ccept this to be a con | nlication is correct, and that the coddition for the issuance of this perm | nstruction will comply with plan it. Date | |
| Approved: | For Chairpers | on, Historic Preservation Commiss | ion | — |
| Disapproved: Signature: | | 0: | ste: | _ |
| Application/Permit No.: | Date Filed | : Date issu | ed: | |

SEE REVERSE SIDE FOR INSTRUCTIONS

(7)

Silver, Joshua

From:

Silver, Joshua

Sent:

Wednesday, September 21, 2011 10:00 AM

To:

'RossMcNair@aol.com'

Subject:

RE: Baltzley Castle Preliminary Consultation

Thanks, Ross.

From: RossMcNair@aol.com [mailto:RossMcNair@aol.com]

Sent: Wednesday, September 21, 2011 8:37 AM

To: Silver, Joshua

Subject: Baltzley Castle Preliminary Consultation

PRELIMINARY CONSULTATION Baltzley Castle 5415 Mohican Rd

WRITTEN DESCRIPTION OF WORK

Kitchen addition:

We propose to remove the existing one story porch and construct a 13 ft x 27 ft kitchen addition on the east side of the Baltzley Castle, to the rear of the square turret. The design is structural steel "C" channels and columns forward of the doors and windows. The roof structure is flat with 20 ounce flat seam copper roofing. The lower level is a walk out facing MacArthur Blvd. All corners and trim will be clad to match the window cladding. The roof will align with the main section of the Porte Cochere approximately 1- 1/2 ft below the 2nd floor window sills.

Non reflective glass front porch:

The existing front porch is open to the elements. This has caused significant damage to the floor system and the stone structure. MacArthur Blvd and Clara Barton Parkway are now main commuter highways with its resulting traffic noise pollution. We propose to install curved, 9/16 tempered, full view, fixed, non- reflective glass. There will be no operating windows, screens or mullions and one all glass door providing access to the stairs. The glass will be set behind the decorative wood brackets that currently brace the roof structure.

Detached garage:

We propose a 2 car detached garage and 1 car carport set off the rear and right side property lines 5 feet. The rear and right side walls will be concrete retaining walls as the garage is set into the slope. The structure will match the proposed kitchen addition in height and with the steel beams and columns forward of the garage doors and wall sheathing. The wood garage doors will be out swing carriage doors and the roof is to match the kitchen addition as a flat roof structure with copper flat seam roofing. The wood doors, trim and panels will be painted the color of the kitchen addition.

Geo Thermal Wells:

The vertical drilled geo thermal wells will be in the rear yard, beside the driveway and set off the property line five ft. There are no site features disturbed as a result of the installation.

Generator:



The natural gas generator is a Kohler 20RES, measuring 48 x 26 x 29. It is set off the house 12 feet and property line 17 ft. No site features are disturbed as a result of the installation.

HAWP APPLICATION: MAILING ADDRESSES FOR NOTIFING

OWNER'S MAILING ADDRESS

5/28/2011

J. Ross McNair, Alison Taylor 7600 Cabin Rd Cabin John MD 20818

ADJACENT AND CONFRONTING PROPERTY OWNERS MAILING ADDRESSES

Miguel Otero

5301 Mohican Rd Bethesda MD 20816

Alexander Wohl 5303 Mohican Rd Bethesda MD 20816

Matthew Byrne 5405 Mohican Rd Bethesda MD 20816

William Barlow 5311 Mohican Rd Bethesda MD 20816

Ned Miltenberg 5410 Mohican Rd Bethesda MD 20816

Joy Brown 5408 Mohican Rd Bethesda MD 20816

Nathaniel Kendall 5420 Mohican Rd Bethesda MD 20816

James Ross 5425 Mohican Rd Bethesda MD 20816 Chris White 5409 Mohican Rd Bethesda MD 20816

Miklos Gaal 5407 Mohican Rd Bethesda MD 20816

Stephen Seeber 5309 Mohican Rd Bethesda MD 20816

Patrick Gates 5421 Mohican Rd Bethesda MD 20816

John Lentz 5424 Mohican Rd Bethesda MD 20816


Whittington Lewis 5404 Mohican Rd Bethesda MD 20816

William Coolidge 5423 Mohican Rd Bethesda MD 20816

Philip Warker 5428 Mohican Rd Bethesda MD 20816









tymd.gov/ims/mcgmaps/viewer.htm

5/28/2011











(13)





HOOM TENIT SKIL FIXE









5415 MOHICAN ROAD MACARTHUR BLVD. ELEVATION PRELIMINARY DEBIGN - 8CH#2

ARCHAEON, INC.
Architects & Planners
7503 MacArthur Blvd. Cabin John, MD 2081b
(NOI) 229-2201 (301) 229-7465 FA WWW.ARCHAFON.COM




MACARTHUR BLVD. ELEVATION




















5415 MOHICAN ROAD L SIDE ELEVATION PRELIMINARY DESIGN - SCH# ARCHAEON, INC.

7503 MacArthur Blvd., Cabin John, MD 20818










CONTRACTOR CO.



EXISTING MODEL FLODE

EALSTING ATTIC FLOOR

IST PRELIMITHARY CONSULTATION






5415 MOHICAN ROAD SIDE ELEVATION PRELIMINARY DEBIGN ARCHAEON, INC.


Architects & Planners

7503 MacArthur Blvd., Cebin John, MD 20818






KENIZED BLAN
















5415 MOHICAN ROAD FRONT PORCH DETAIL - PARTIAL L'SIDE ELEVATION ARCHAEON, INC


7501 Mandathur Blid Cable to Atlanta





(EB) Seem 1/4-110

IST PRELIMENTAL CONSUCRITION






5415 MOHICAN ROAD ELEVATIONS PRELIMINARY DESIGN ARCHAEON, INC.

WISI CAMALY LIEVANCH

IST PRELIMINABILITATI











ARCHAEON, INC






REVISED PLAN






REVISED PLAN




REVISED PLAN








5415 Mohican Road, Betheada North view







5415 Mohican Road, Bethesda



5415 Mohican Road, Bethesda


West view




STONE WALLS At forch






















(43)




KitcHEM Appition





GLEBN HONZE



01/31/2011 12:09












September 30, 2011 Site Visits










Proposed garage location



HPC Meeting Transcript July 13, 2011



| 1 | MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION |
|--|--|
| 2 | |
| 3 | X |
| | PRELIMINARY CONSULTATION - : |
| 4 | 5415 Mohican Road : |
| 5 | x |
| 6 | : HISTORIC AREA WORK PERMIT - : |
| | 900 Olney-Sandy Spring Road : |
| 7 | : X |
| 8 | : PRELIMINARY CONSULTATION - : |
| 9 | 10806 Keswick Street : |
| 10 | : x |
| | |
| 11 | A meeting in the above-entitled matter was held or |
| | |
| 12 | July 13 2011 commencing at 7.34 p m in the MRO |
| 12 13 | July 13, 2011, commencing at 7:34 p.m., in the MRO |
| | July 13, 2011, commencing at 7:34 p.m., in the MRO Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland |
| 13 14 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland |
| 13 | |
| 13 14 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland |
| 13 14 15 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN |
| 13 14 15 16 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: |
| 13 14 15 16 17 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN |
| 13 14 15 16 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS |
| 13 14 15 16 17 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler |
| 113 114 115 116 117 118 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler Jorge Rodriguez |
| 13 14 15 16 17 18 19 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler |
| 13 14 15 16 17 18 19 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler Jorge Rodriguez M'Lisa Whitney William Kirwan John Jessen |
| 13 14 15 16 17 18 19 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler Jorge Rodriguez M'Lisa Whitney William Kirwan John Jessen Paul Treseder |
| 13 14 15 16 17 18 19 20 21 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler Jorge Rodriguez M'Lisa Whitney William Kirwan John Jessen |
| 13 14 15 16 17 18 19 20 21 22 23 | Auditorium at 8787 Georgia Avenue, Silver Spring, Maryland 20910, before: COMMISSION CHAIRMAN Leslie Miles COMMISSION MEMBERS Sandra Heiler Jorge Rodriguez M'Lisa Whitney William Kirwan John Jessen Paul Treseder |

Deposition Services, Inc.
12321 Middlebrook Road, Suite 210
Germantown, MD 20874
Tel: (301) 881-3344 Fax: (301) 881-3338
info@DepositionServices.com www.DepositiorServices.com

ALSO PRESENT:

Scott Whipple, Staff Supervisor Anne Fothergill, Staff Josh Silver, Staff

APPEARANCES

| STATEMENT OF: | • | | | PAGE |
|-------------------------------------|---|--|--|----------|
| Ross McNair | , | | | 13 |
| Matt Bonifant | | | | 56 |
| Robert Reinhardt Gerilee Bennett | | | | 70 |
| June 8th minutes Staff items | | | | 80 80 |

- 1 37/03-11GG at 7309 Piney Branch Road in Takoma Park with the
- 2 added condition that the final rail design be approved and
- 3 reviewed at the staff level.
- 4 MS. MILES: Is there a second?
- 5 MR. CORATOLA: I second.
- 6 MS. MILES: All in favor, please raise your right
- 7 hand? The vote is unanimous. If this was one of your
- 8 applications, these are approved. You are free to go. You
- 9 can contact staff tomorrow by telephone to find out your
- 10 next steps. Their contact information is in your staff
- 11 report. And thank you for preparing applications that we
- 12 could approve so expeditiously.
- We're going to go slightly out of turn now. We
- 14 should be hearing case J, but I understand the applicant is
- 15 not here. So if the preliminary for 5415 Mohican Road, if
- 16 the applicants are here we would like to move towards that.
- 17 Please come and sit at the desk, or at the table.
- 18 If you would just depress the large oval button on
- 19 the mike and let go of it.
- 20 MR. SILVER: Would you like a quick staff report?
- 21 MS. MILES: Yes, I would. I'm sorry.
- MR. SILVER: That's quite all right.
- 23 MS. MILES: I arrived a little late tonight, and I
- 24 have to get my head back on top of my shoulders. Please
- 25 proceed staff.

- 1 MR. SILVER: Why don't we go ahead and do a quick
- 2 staff report.
- 3 MS. MILES: Yes, indeed.
- 4 MR. SILVER: 5415 Mohican Road is an individually
- 5 designated master plan site referred to as the Baltzley
- 6 Castle. The proposal is to do a one-story side addition and
- 7 construction of a two story -- excuse me. They want to
- 8 construct a two-story side addition, alterations to the
- 9 front porch which include enclosing the front porch using a
- 10 full view fixed nonreflective glass, and there is also some
- 11 repair and restoration work to the existing front porch roof
- 12 and columns and/or replacement in kind in some places.
- 13 The third floor on the left side of the structure
- 14 behind the turret is what's referred to as a glass dormer,
- 15 and the applicant wishes to replace the existing glass
- 16 dormer on the left side elevation with a wood full view
- 17 fixed glass window.
- The current condition of the dormer is severely
- 19 deteriorated, and has caused major water damage infiltration
- 20 into the plaster, original plaster on the interior of the
- 21 house. And the intention of the design is to prevent this
- 22 damage.
- 23 The proposal also includes construction of a
- 24 three-car detached garage set off the rear and right side
- 25 property lines and builds into the existing topography that

- 1 is in that section of the property.
- 2 Staff is, as the staff report indicates, is
- 3 generally supportive of the applicants proposal for the one-
- 4 story side addition. This part of it is an existing
- 5 building or I should say feature on the side. It's referred
- 6 to in the designation as a later addition section, but as a
- 7 lean-to and the proposed work constitutes a combination of
- 8 routine maintenance and sympathetic alterations. It was
- 9 enclosed at an unknown date.
- The replacement of the tongue and groove siding
- 11 with full view wood insulated glass windows and doors does
- 12 not alter any character defining features. As I said, this
- 13 has been altered and enclosed, and the proposed glazing
- 14 provides a concentration of visual transparency that pays
- 15 respect to what was originally a simple covered space with
- 16 no walls.
- 17 Staff also supports the two-story side addition.
- 18 As the staff report says, the HPC generally requires
- 19 additions to be placed at the rear of the historic house to
- 20 minimize visual impact on new construction and the primary
- 21 facade.
- When the applicant came to the Commission for
- 23 review of the roof project, which turned into a roof
- 24 replacement project, the staff report, as this staff report
- 25 indicates, is that this structure should be considered to

- 1 have two primary facades, the formal entrance or the formal
- 2 front that faces MacArthur and a formal entrance that would
- 3 greet people. So a side addition staff feels is appropriate
- 4 for this property.
- 5 Staff does recommend eliminating the clear story
- 6 window feature from the roof of the addition to help
- 7 preserve more of an unobstructed view of the second floor
- 8 right side facade. As it is proposed now, those windows
- 9 obstruct the view of the original second floor windows on
- 10 the historic massing, particularly if you are looking at
- 11 this from the right side. That clear story is separated.
- But staff was looking to try to gauge a way to bring
- 13 the perceived scale of this down a little bit, and finds
- 14 that that may help that. The applicant is definitely open
- 15 to having this conversation with the Commission at this
- 16 preliminary stage for different solutions.
- 17 Staff supports the front porch nonreflective glass
- 18 installation. It feels it will have a negligible impact on
- 19 the structure and is consistent with the Secretary of the
- 20 Interior standards that glass would still allow the front
- 21 porch to be used as a functional living space and the
- 22 proposed installation method would be behind the decorative
- 23 brackets which define that front porch area by not
- 24 destroying the historic materials and features and
- 25 relationships that characterize the property.

- 1 Staff also supports the proposed repairs and
- 2 rebuilding or replacement in kind of features and decorative
- 3 elements on the front porch. The applicants have secured
- 4 high resolution historic photos on the front porch to assist
- 5 them with reconstruction damage to missing elements.
- 6 Staff supports the glass dormer, alterations. The
- 7 existing dormer contains evidence, as I said, of extensive
- 8 water damage on the interior. I have some photos that I can
- 9 go to in just a minute. And the proposed design is
- 10 respectful of the existing design while using a construction
- 11 method that will prevent future water infiltration and
- 12 deterioration into the interior of the structure.
- 13 Lastly, staff supports the construction of the
- 14 three-car detached garage set off the property line. The
- 15 garage is cited into the existing topography to help lessen
- 16 its perceived scale and size. The proposed scale, the
- 17 proposed garage takes its material cues from the historic
- 18 massing, and is compatible with the proposed two-story side
- 19 addition and alterations to the one-story lean-to.
- 20 So there is these five talking points that I know
- 21 the applicant is looking to get some feedback on, and that
- 22 I'd like to ask the Commission to provide some, their
- 23 position on.
- 24 Before I forget, you did, I did email a letter.
- 25 The applicant received this letter as well, from the

- 1 neighbor at 5407 Mohican Road in response to the applicant's
- 2 proposal. And I told the -- he is unable to attend tonight,
- 3 and I let him know that I would enter that into the record
- 4 so that you have received that.
- I'll go through a couple of quick slides here and
- 6 answer any questions. I think it's worth pointing out the
- 7 house to the right, just to refresh your memory, is also
- 8 individually designated master plan site, which the
- 9 applicant also owns that house as well. It's referred to as
- 10 the R.A. Charles House.
- 11 One thing, I think it's worth noting on this
- 12 particular photo, is how the topography, as obviously this
- 13 is on MacArthur, slopes down towards the Potomac so you can
- 14 see where this two-story addition is proposed is going to
- 15 sort of go into the landscape there a little bit. And as
- 16 promised, the glass dormer conditions. That's all I have.
- MS. MILES: Thank you, Josh. That was well worth
- 18 hearing. And again, I'm sorry for, I did breeze right by.
- 19 Does anyone have any questions for staff?
- MS. HEILER: Josh, could you go back to the aerial
- 21 photo and just point out where the garage would go?
- 22 MR. SILVER: Mr. McNair, you can kind of correct
- 23 me here, but sort of over in this general area, I would say,
- 24 roughly, is that an approximation?
- MR. McNAIR: The house there, the left corner is

- 1 11 feet up. The property line angles to 37 feet up, the
- 2 property line. So the garage would be -- this is where we
- 3 are proposing.
- 4 MR. SILVER: Thanks.
- 5 MS. MILES: Any other questions for Josh?
- 6 MS. WHITNEY: Josh, the second home that the owner
- 7 owns is the one behind it or two the right of it?
- 8 MR. SILVER: To the right.
- 9 MS. WHITNEY: So not the one next to the proposed
- 10 garage?
- 11 MR. SILVER: Right there.
- MS. WHITNEY: Okay. Thank you.
- MS. MILES: I just want to clarify, I'm not sure
- 14 what you're referring to, Commissioner, the white roofed
- 15 structure is another house, but the darker structure is
- 16 actually an existing garage on the parcel.
- MS. WHITNEY: Thank you. I actually had not
- 18 recognized that that was a structure.
- 19 MR. SILVER: Yes, it's a non-historic garage.
- 20 MR. McNAIR: In answer to your question --
- 21 MR. SILVER: If you are going to speak --
- 22 actually, why don't we hold on for just a minute.
- MS. MILES: Yes. Yes.
- 24 MR. SILVER: Just wait one minute.
- MS. WHITNEY: And the non-historic garage will be

- 1 demolished?
- 2 MR. SILVER: It's actually on the adjacent
- 3 property, and that would be an excellent question when it's
- 4 time for questions for that. But it is not on this property
- 5 where you are considering this preliminary consultation.
- 6 MS. WHITNEY: Thank you.
- 7 MR. KIRWAN: Josh, the one-story side addition
- 8 that is being restored, do we know anything about what that
- 9 structure was originally? It looks like it had stone
- 10 columns. It might have been a porch or it looks like it had
- 11 been infilled at some time?
- MR. SILVER: Mr. McNair I'm sure will be able to
- 13 answer that in more detail when the time comes. It was
- 14 open, though, at one point.
- MR. KIRWAN: Okay.
- MR. SILVER: So, you know, some sort of
- 17 utilitarian type purpose, but it was open. It was not
- 18 enclosed.
- MR. WHIPPLE: Probably most recently it was used
- 20 as sort of a pantry or cold storage of some sort, but I
- 21 believe the applicant provided a photograph where it almost
- 22 looks as though there was an old automobile parked under it.
- 23 So at one point it was open.
- 24 MS. MILES: Do you have another question?
- 25 MS. WHITNEY: And Josh, one more time, can you

- 1 humor me by going through the slides one last time, please?
- MR. SILVER: That's it.
- MS. MILES: If there are no other questions for
- 4 staff, please turn on your microphone, identify yourself,
- 5 and you can either speak for seven minutes or you can just
- 6 respond to questions. However you would like to handle it.
- 7 MR. McNAIR: Ross McNair. I'll be living at 5415
- 8 Mohican Road. In page 10 of the packet there's a site plan.
- 9 Let me locate where the garage goes. If I have a limited
- 10 time, I think I'd rather answer any questions or comments
- 11 that people have.
- MS. MILES: Why don't you begin by answering the
- 13 questions that have already been asked about the original
- 14 use of the lean-to and historical purpose, and, you know,
- 15 timing of this construction or anything else you can tell us
- 16 about that?
- MR. McNAIR: The one-story structure was not
- 18 original to the building. Everything that they did when
- 19 they were building this as they were pocketing into the
- 20 stone. For this structure, there are just metal ties that
- 21 connect everything. So it's not original, just like the
- 22 porte cochere is not original, but it was added a long time
- 23 ago, so it's been there for a long time.
- MS. MILES: Okay. Thank you. Does anyone else
- 25 have any questions for the applicant? Paul.

- 1 MR. TRESEDER: I have a question about the
- 2 proposed glass on the porch. That would just be a single
- 3 sheet of glass with no mullions or anything?
- 4 MR. McNAIR: What it would be is curved glass
- 5 following the shape of the existing porch. It would be
- 6 insulated glass, no -- but solid glass. So it would be a
- 7 framework in a curve, no mullions, no dividers, no operating
- 8 windows, nothing to obstruct the view. And we can order a
- 9 special kind of glass which is called a nonreflective glass.
- 10 MR. CORATOLA: The glass will be behind the
- 11 structure or is it going to be in line with the stone
- 12 columns? What's the placement of the glass?
- 13 MR. McNAIR: The stone is about 15 inches wide,
- 14 and then in the center of that there are these brackets. So
- 15 the glass work would occur behind the brackets, so that all
- 16 of the decorative brackets that act as bracing would still
- 17 be exposed.
- 18 MR. SILVER: Page 15 of your staff report might be
- 19 helpful, Commissioner Coratola.
- 20 MS. MILES: I'm actually going to ask a question
- 21 of staff. Josh, can you respond to one of the issues raised
- 22 by the neighbor who said that the setback is insufficient.
- 23 What is your understanding about this?
- 24 MR. SILVER: I don't have any information. That
- 25 was news to me when I received this letter. I think it was

- 1 yesterday I received it, or actually the day before. But I
- 2 mean, Mr. McNair will be required to comply with the
- 3 setbacks that DPS has for this property.
- 4 MS. MILES: Do you have any information about
- 5 this, Mr. McNair?
- 6 MR. McNAIR: Yes. The way that the DPS code reads
- 7 is anything in excess of 24 feet for every two feet wider
- 8 you have to have two feet more of a setback. So there are
- 9 several options. One is to pull the back of the house off
- 10 the property line, increasing the five-foot accessory
- 11 building setback. Another option would be to have a two-car
- 12 garage and a one-car carport. Another option could be to
- 13 have two separate structures, one 24 feet and one 12 foot.
- 14 MS. MILES: So in other words, you are
- 15 acknowledging that you cannot place the garage were you've
- 16 got it sited on the site plan, based upon the design?
- MR. McNAIR: It needs to pull off the rear
- 18 property line, or I just -- if we just make a carport --
- 19 MS. MILES: I need to point out, that is not the
- 20 design that we're looking at. That's your extra story one,
- 21 right? You don't want that. That's the one that you took
- 22 out of the packet?
- 23 MR. SILVER: So the packet actually has both, but
- 24 the one that you are reviewing tonight, and staff reviewed,
- 25 is the one without the clear story windows.

- 1 MS. MILES: What you're holding up is one with the
- 2 clear story windows. You might want to use the one that
- 3 doesn't have that.
- 4 MR. McNAIR: Okay. I thought Josh had said he had
- 5 had this one in?
- 6 MR. SILVER: It is in there, but it was
- 7 inadvertently included on page 16. Page 17 of the staff
- 8 report is the one that is being discussed tonight, which is
- 9 without the clear story window.
- 10 MR. McNAIR: Okay. Whichever plan, I could have
- 11 -- as long as you don't have a front wall and a rear wall
- 12 that goes all the way up to the structure, then it's a
- 13 carport. So it's an open structure. So we can site the
- 14 building where we've shown on the site plan.
- 15 MS. MILES: So you're saying that it would be your
- 16 intention to redesign this structure so that it would be two
- 17 garage spaces, one open space, and then it would remain at
- 18 that location? Or would it be your intention to make it
- 19 smaller? What is your intention?
- 20 MR. McNAIR: I thought that's what the purpose of
- 21 tonight's meeting was, was to kind of go over what it is
- 22 that you all would like to see?
- 23 MS. MILES: Well, I'm asking, what are you asking
- 24 us to review? Are you asking us to, because now we don't
- 25 have anything that reflects what you are actually asking

- 1 for. The site plan is either incorrect or the design is
- 2 incorrect. So I'm asking you which thing you are asking us
- 3 to consider? And then we'll give you feedback on that.
- 4 MR. McNAIR: So I think there are three options.
- 5 One is to have a two-car enclosed garage, and then have open
- 6 bays on the front and the back so that you can see through
- 7 it. So then it would look just like this. Imagine just
- 8 removing the garage door door. So that's one option. The
- 9 other option is to pull it off of the property line.
- 10 MS. MILES: I know what the options are. I'm
- 11 asking you what thing you want us to consider?
- MR. McNAIR: Maybe an open carport for the third
- 13 bay?
- 14 MS. MILES: All right. And not the design that
- 15 has the clear story window above, but the one-story with the
- 16 standing seam roof, correct?
- MR. McNAIR: Well, I would prefer the clear story,
- 18 but if you all don't want that and you want a solid roof,
- 19 then I'll build a solid roof.
- 20 MS. MILES: Okay. All right. Does anyone else
- 21 have any questions for the applicant or for staff?
- MR. RODRIGUEZ: Yes. I want to go back to the
- 23 enclosing of the round porch, and I would call it a round
- 24 porch. It's very hard to read the details but I suppose the
- 25 glass is going to be inserted in the existing masonry so the

- 1 glass is not only curved but has round but lower corners?
- MR. McNAIR: Correct.
- 3 MR. RODRIGUEZ: And once it's inserted in that
- 4 structure, how supportive of that structure, is any
- 5 modifications, changes to the masonry of the existing porch
- 6 necessary?
- 7 MR. McNAIR: No.
- 8 MR. RODRIGUEZ: And then you are saying that it is
- 9 just a pane of glass. I assume somewhere there is going to
- 10 be a door, because there is a stair leading to that, and
- 11 that door needs a frame, so that is not the same look as the
- 12 simple pane of glass, is that correct?
 - MR. McNAIR: Yes. Tucked over on the right hand
 - 14 side, there's a flight of stairs that go down. So there
 - 15 would be a door there.
 - MR. RODRIGUEZ: Yes. To be honest, it's very hard
 - 17 to give you feedback with so little details. I'm trying to
 - 18 imagine what it is, but I cannot see it with the information
 - 19 I have.
 - 20 MS. MILES: Any other questions for the applicant?
 - 21 MR. JESSEN: I guess I have a question. Sorry if
 - 22 this is redundant. The glass you talked about, the curved
 - 23 glass, are those full sheets of glass?
 - MR. McNAIR: Correct.
 - 25 MR. JESSEN: There are no bricks? You would see

- 1 no seam work at all?
- 2 MR. McNAIR: Right.
- 3 MR. JESSEN: That's a large sheet.
- 4 MR. McNAIR: And expensive.
- 5 MR. JESSEN: Thank you.
- 6 MS. WHITNEY: Mr. McNair, had you considered other
- 7 locations for the garage? I mean, do you want a three-car
- 8 garage, but you can't actually put a three-car garage in
- 9 that spot. Had you considered other places on the property?
- MR. McNAIR: Yes. Really, I probably have 30
- 11 different sketches on garage locations. The reason this
- 12 location works the best is because there is a 10-foot grade
- 13 difference between the Charles house and the Baltzley
- 14 Castle. So I can have concrete retaining walls on the side
- 15 in the back, so this garage just tucks into the hill.
- MS. MILES: Are there any other questions that
- 17 relate to either the garage or to the glass?
- 18 MS. HEILER: I hope this isn't redundant. Can you
- 19 describe to us again what the section which will have the
- 20 door is going to look like? Is it glass with an embedded
- 21 door frame. You know, what's above the door?
- 22 MR. McNAIR: I could have a door panel that goes
- 23 all the way up, so it would be a glass panel, a door panel,
- 24 and a glass panel. Or I could put a header over it and have
- 25 it so it's a smaller door.

- 1 MS. HEILER: So there is some place in that one
- 2 section there's a door jamb, is that right, for the glass
- 3 door?
- 4 MR. McNAIR: There would be some weather striping
- 5 on the glass, probably more analogous to a frameless shower
- 6 door.
- 7 MS. HEILER: And what do the hinges attach to?
- 8 MR. McNAIR: The glass.
- 9 MR. HEILER: Okay.
- 10 MR. RODRIGUEZ: Yes, I still don't get the whole
- 11 door issue because you have also two brackets on that bay,
- 12 so I assume the door is going to be farther back, way
- 13 farther back, so the door swings off, away from the
- 14 brackets, I assume.
- MR. McNAIR: There's going to be a bracket on,
- 16 there's a bracket on the right and there's a bracket on the
- 17 left, and there's a clear section in the center. So the
- 18 door would be in the center.
- 19 MR. RODRIGUEZ: So to go back, then we have four
- 20 bays which will have this pane of glass we've not seen or
- 21 anything else, but we have one bay that will have some
- 22 framing, some joints, some seams, because they are necessary
- 23 for the door, and you have the hardware and you have all
- 24 these other pieces that will come there.
- 25 MR. McNAIR: There's a number of different ways

- 1 that we could build this. We could build it with curved
- 2 tempered glass, have hinges on and the door swings, just
- 3 like a frameless shower door. I could use the same frame
- 4 material and I could have it so that there is one pane of
- 5 glass framed, a door, another pane of glass framed. I'm
- 6 pretty open on the design for how to make the door work.
- 7 MR. RODRIGUEZ: The issue or the question has to
- 8 do with you're proposing one direction for the rest of the
- 9 porch, and when you come to the door, that changes
- 10 completely. And I know from my point of view, I'm trying to
- 11 understand what you're proposing on one side will be
- 12 compatible with the other. And that's what the nature of
- 13 the questions are trying to understand that.
- 14 MR. McNAIR: Okay. It would be better to have a
- 15 door coming out of that porch, but if the door itself is a
- 16 big issue, I could just have the glass return back to the
- 17 house. The window coming out of the living room onto that
- 18 porch, which is also right there by the door, raises up, and
- 19 that's a walk through window. So if the whole thing hinges
- 20 on having a door or not having a door in this glassed area,
- 21 I could just have it all glass and no door.
- MS. MILES: Can'I ask you to respond to a question
- 23 that Commissioner Whitney raised before you were on the
- 24 record? Do you intend to demolish the garage on the
- 25 adjoining parcel? I would just point out to the people who

- 1 don't necessarily know that these two houses were built
- 2 simultaneously by two brothers, and that they are
- 3 separately, individually designated, and they are two
- 4 separate parcels, but they are similar houses and they
- 5 relate to each other. And I'm curious to know how the
- 6 garage on the other parcel is going to eventually be
- 7 treated.
- 8 MR. McNAIR: We're using the one and a half car
- 9 garage which is shown right there, that brown structure, as
- 10 a storeroom right now, a staging area. It's our intent to
- 11 take that down. And I need to come back and talk -- we
- 12 haven't done any work with Charles yet, but there is a lot
- of work that the Charles House needs. So we'll be having
- 14 discussions on that one, also. But it's not a very
- 15 attractive garage. So we would like to take it down.
- MS. MILES: It's not attractive. You said it's a
- 17 one and a half car garage. Is it only one and a half cars
- 18 large? It looks quite substantial to me.
- 19 MR. McNAIR: It's only about 12 feet wide, and
- 20 then it's deep, but there are columns. So you can only get
- 21 one car in it.
- MS. MILES: Thank you. Are there any questions
- 23 that --
- MR. RODRIGUEZ: Yes, I'm sorry. Regarding the
- 25 porch, I wanted to ask if we can move to the other parts?

- 1 MS. MILES: Has everyone who has got questions
- 2 about the garage or the glass had their guestions raised and
- 3 answered? All right. Let's talk about the addition then.
- 4 MR. RODRIGUEZ: So the one-story addition is
- 5 basically a reconstruction of a structure that is there, if
- 6 I understand correctly?
- 7 MR. McNAIR: Correct.
- 8 MR. RODRIGUEZ: Okay. And that structure more or
- 9 less follow the same lines of the house, has the same
- 10 detail, the correlation and the top of the tiles, the terra
- 11 cotta decorative elements at the ridge as the rest of the
- 12 house, correct?
- MR. McNAIR: The structural part of that one-story
- 14 stays. We're repointing the stone pillars. We're replacing
- 15 the roof in a red slate roof. I'm putting copper elements
- 16 on the hips as they come down; and on the ridge, we've got
- 17 terra cotta caps. So all of that is going to look like it
- 18 did when it was originally built.
- 19 MR. CORATOLA: But you're going to change the
- 20 infill? Between the columns, you're putting new glass in?
- 21 MR. McNAIR: Correct.
- 22 MS. MILES: Are there any other questions about
- 23 the reconstruction of the one-story addition? Are there
- 24 any questions about the proposed two-story addition?
- MS. HEILER: Yes. The staff had recommended doing

- 1 away with the clear story window, which I would tend to
- 2 agree with. If you do, what will be -- will your roof be
- 3 similar to the roof on the one-story addition, or how is
- 4 that, what's your plan for that roof?
- 5 MR. McNAIR: I can make it similar. I thought you
- 6 generally wanted to have something that was an addition read
- 7 so that it was different. I was thinking about putting on
- 8 either a copper or a red painted field applied metal roof.
- 9 MR. HEILER: That's the same as you were proposing
- 10 for the garage?
- 11 MR. McNAIR: Correct.
- MS. MILES: I have a question. What is the
- 13 footprint of the house in square foot, the existing house?
- 14 Approximately?
- 15 MR. McNAIR: It jogs in and out on one side, it's
- 16 23 feet on the other side, it's 27, and the overall width is
- 17 about 55.
- 18 MS. MILES: So you would say it's what?
- MR. McNAIR: Probably 55 times 25.
- 20 MS. MILES: I'm really bad at math. Can you just
- 21 tell me what you think that is?
- MR. SILVER: Commissioner Treseder has got his
- 23 smart phone to provide you with help.
- MS. MILES: So about 1600 square feet?
- MR. TRESEDER: 13, close to 14.

- 1 MS. MILES: 1400 square feet. Okay. You didn't
- 2 submit a floor plan or a proposed floor plan. I would like
- 3 to know whether it would be possible to achieve your program
- 4 without constructing the addition. I know you intend to put
- 5 a kitchen in the addition.
- I've been through this house and I know there are
- 7 a lot of rooms on the first floor, but frankly, it's hard
- 8 for me to remember. So I think it would be helpful to see
- 9 some kind of floor plan design to understand why this is
- 10 necessary.
- 11 And I guess I would ask you also what kind of
- 12 standing seam metal roof are you intending to put on the
- 13 garage and on the addition if the clear story window is not
- 14 favored by the majority of the Commissioners?
- 15 MR. McNAIR: It would be the same roof whether we
- 16 had the clear story or not, but we would do a field built
- 17 metal roof, standing seam.
- 18 MS. MILES: Okay. Do you have a floor plan that
- 19 you can share with us?
- 20 MR. McNAIR: I don't think I, I don't think I
- 21 brought a floor plan. The problem I'm trying to get a
- 22 kitchen within the inside of the space is, there's a very
- 23 grand entrance with a curved wall. You're not going to be
- 24 able to put a kitchen there.
- There's a living room to the right. There's a

- 1 large dining room, and then the space where the existing
- 2 kitchen is, there is a powder room, there's a kitchen,
- 3 there's a staircase to the basement. There's the door to go
- 4 outside.
- 5 MS. MILES: Which is the lean-to?
- 6 MR. McNAIR: Yes. It's just, it's a small space.
- 7 I need a larger kitchen.
 - 8 MS. MILES: I'm just trying to get a sense of that
 - 9 need. Does anybody else have any questions that relate to
- 10 the two-story proposed addition?
- 11 MR. RODRIGUEZ: Yes. I have a question. One of
- 12 the key features of these houses are the two towers, the
- 13 very tall one and the other that looks more like maybe
- 14 cantilever and then flat with crenellation. So I would say
- 15 the round tower and the other is like the square tower.
- MR. McNAIR: Okay.
- MR. RODRIGUEZ: Can you explain why you're
- 18 proposing to close part of that tower with that two-story
- .19 addition? What is the intent there? You need more space
- 20 and there is no other solution? Because when I look at the
- 21 back of the house, the proximity of the addition to that
- 22 feature seems to be something that I would like to know more
- 23 in detail.
- 24 MR. McNAIR: I don't know if I quite understood
- 25 the question. The kitchen addition would go up to the --

- 1 what the plan was, is to come back like eight inches from
- 2 that corner so that that element still shows.
- 3 MR. RODRIGUEZ: Yes, but the question is more
- 4 about what is the intention with the addition? You are
- 5 trying to capture as much space as you need. I can
- 6 understand that. But what is, what is the purpose of the
- 7 addition as it relates to the house, what you're trying to
- 8 do?
- 9 MR. McNAIR: It's a kitchen, so we're trying to
- 10 add a kitchen.
- 11 MS. MILES: Can I ask what you're planning to put
- 12 into the existing one-story addition?
- MR. McNAIR: It's a breakfast room. We found some
- 14 six-by-eight beams up in the attic. We're going to cut
- 15 those down. We're going to make a farmer's table. So we're
- 16 going to build a breakfast room in the one-story, put the
- 17 main kitchen in the addition, and then put like a back
- 18 kitchen and bathroom and pantries in the back kitchen. So
- 19 the back kitchen is more of a clean up kitchen, and the
- 20 front kitchen is more of a prep kitchen.
- MS. MILES: Thank you.
- 22 MS. WHITNEY: And the second story for this, this
- 23 is a two-story addition. It's not a two-story kitchen.
- 24 What is the, the second story is what?

- 1 MR. McNAIR: The grade is a very steep grade, so
- 2 the floor line of the kitchen and the floor line of this
- 3 existing structure match. The second part is really the
- 4 basement. So it ties in with this door that's over on the
- 5 side. So one of the reasons that we have the addition going
- 6 out is so that the addition and the basement connect, so
- 7 that like here --
- 8 MS. MILES: Mr. McNair, you are no longer on the
- 9 record. If you could maybe ask for the pointer from the
- 10 staff.
- 11 MR. SILVER: Perhaps if you look at circle 12, I
- 12 think is the point that Mr. McNair is trying to address.
- MS. MILES: We're looking at the elevation, the
- 14 northeast elevation.
- MR. McNAIR: So the finished floor of the kitchen,
- 16 and the finished floor of the breakfast room is going to be
- 17 the same. The two-story part is going underneath it.
- 18 MS. MILES: Could you speak into the microphone
- 19 Mr. McNair. I don't think that our transcriber can hear
- 20 you.
- MR. McNAIR: Okay. So the two-story, it's
- 22 basically a basement with a story above it.
- MS. WHITNEY: When I envision two-story, it's
- 24 ground level and then a level above. So I'm envisioning a
- 25 two-story addition to be two floors?

- 1 MR. McNAIR: No.
- 2 MS. WHITNEY: Okay. All right.
- 3 MR. McNAIR: This is a basement with --
- 4 MS. WHITNEY: Okay.
- 5 MR. McNAIR: -- a floor above it.
- 6 MS. WHITNEY: Okay.
- 7 MR. McNAIR: And then one of the reasons that the
- 8 addition goes out where it is, is back here underneath this
- 9 window there's a door that goes into the basement. So we
- 10 were wanting to have the additional basement part tie into
- 11 that so that we can use that door to get into the basement
- 12 without having to go back outside.
- 13 MR. TRESEDER: I have a question. Are you going
- 14 to be, are you showing this stone, and obviously the stone
- 15 is a very critical aspect of this house, and I believe it is
- 16 granite, isn't it? Aren't these blocks granite?
- 17 MR. McNAIR: Yes.
- MR. TRESEDER: Are you going to be able to like,
- 19 are you salvaging some existing stone to match it on this
- 20 addition, or do you feel that you'll be able to get a pretty
- 21 close match? Because it's obviously a very important thing
- 22 to have a match?
- MR. McNAIR: All the stone was locally quarried.
- 24 We can get matching stone. There's also a stone retaining
- 25 wall that comes in, because of this steep grade, coming from

- 1 that column forward, there is stone. And then going from
- 2 this column on the MacArthur Boulevard side, back to the
- 3 house, there is also stone. So we're going to be able to
- 4 capture the stone that's there, and we'll be able to match
- 5 the stone pretty well.
- 6 MR. TRESEDER: So it would be a combination of old
- 7 and new stone, but either way you feel comfortable you can
- 8 get a good match?
- 9 MR. McNAIR: Correct.
- 10 MS. MILES: Are you proposing to take the stones
- 11 out of the existing walls, the retaining walls in order to
- 12 use them for the addition?
- 13 MR. McNAIR: There's a retaining -- well, the
- 14 stones have to come out for the addition. Right now there
- 15 is a small retaining wall that goes from that column
- 16 forward. So we can use those stones.
- MS. MILES: But I would suggest to you that you
- 18 are going to have a lot of resistance to removing anything
- 19 that doesn't have to be removed in order to achieve the
- 20 footprint of anything we would be approving. Existing stone
- 21 walls are part of this individually designated historic
 - 22 site.
 - 23 Are there any other questions that relate to the
 - 24 proposed two-story addition?
 - 25 MR. CORATOLA: Yes, I have one. On the side

- 1 elevation, there's a vertical stone element. Is that a
- 2 fireplace, a chimney, or --
- 3 MR. McNAIR: It's meant to look like a chimney.
- 4 The range in the hood goes right there. So I'll be using
- 5 that as a chimney for the exhaust for the range hood.
- 6 MS. HEILER: I have another question. Is it the
- 7 floor levels in the two-story new addition and the one-story
 - 8 addition, the floors are the same, is that right, or is
 - 9 there a step down from the two-story?
- MR. McNAIR: No, no, the floor of the basement
- 11 will be the same. The floor of the first floor will be the
- 12 same.
- MS. HEILER: But the ceilings then, the kitchen
- 14 will have a higher ceiling than the one-story addition?
- MR. McNAIR: Yes.
- MS. HEILER: Okay.
- 17 MR. McNAIR: This structure right here has a
- 18 seven-foot six-inch ceiling.
- MS. HEILER: Okay. Thank you.
- 20 MS. MILES: If there are no other questions, we
- 21 will begin to offer you comments. I gather there are no
- 22 other questions. Mr. McNair, if you want to turn off your
- 23 microphone, we are going to be giving you our feedback. I'm
- 24 going to ask the Commissioners to respond to the issues that
- 25 were raised by the staff packets. And the first question

- 1 is, the appropriateness of restoring and repairing the one-
- 2 story addition, which is proposed to become a breakfast
- 3 room.
- 4 The construction of a two-story side addition
- 5 which is drawn with clear story windows, so please respond
- 6 to both the scale, the massing, the materials, and that
- 7 second story of window.
- 8 The enclosure of the front porch, meaning the
- 9 MacArthur Boulevard side curved porch with nonreflective
- 10 glass and the issues that were raised in terms of access
- 11 through a door which we don't have a design for.
- The replacement of the glass dormer with an
- 13 alteration so that it will not be as it is now, and will be
- 14 better sealed against weather. And the construction of the
- 15 proposed three-car detached garage, which we've had
- 16 discussion about being either too close to the property line
- 17 or needs to be altered so as to have only two bays and one
- 18 open space.
- 19 So if everyone could please respond to all of
- 20 those issues, and I'm going to begin with Ms. Heiler, to my
- 21 left.
- MS. HEILER: Yes. I'm completely in favor of the
- 23 restoration of the one-story side addition. I think that's
- 24 a great idea. The two-story side addition I agree with the
- 25 staff that the clear story window is a problem.

- I think also that the fact that you would have to
- 2 remove stones from the retaining wall to build it, it's
- 3 'probably a nonstarter'. Matching the stone I'm not sure is
- 4 such a great idea anyway since we'd like it to be
- 5 distinguished from the original structure. So possibly a
- 6 different material is better anyway. And I know you are
- 7 planning the roof will not look like the original structure,
- 8 that's good.
- 9 I think the stone running up between the windows
- 10 as a sort of fake fireplace looks a little odd, and it
- 11 doesn't look functional. If it were, it certainly is not a
- 12 chimney that matches the rest of the house. So I think
- 13 trying to match the stone, probably not being able to, is a
- 14 problem, and maybe it's not a great idea to match the stone
- 15 anyway. Otherwise, I don't have a problem with a two-story
- 16 addition as long as it doesn't have a clear story roof that
- 17 interferes with the view of the windows above.
- 18 I think the front porch alterations could be a
- 19 great solution, but without actually seeing the design,
- 20 especially of the door in that end, I can't really comment
- 21 on it.
- The glass dormer replacement sounds like a great
- 23 idea, and the construction of the three-car detached garage,
- 24 it seems like a reasonable location. Clearly, you can't
- 25 have a three-car garage in that location. Possibly two cars

- 1 and the carport, something there, but without seeing the
- 2 actual proposal, I couldn't comment. I think the location
- 3 is fine. And the design without the clear story window
- 4 seems appropriate.
- 5 MS. MILES: Thank you. Commissioner Whitney.
- 6 MS. WHITNEY: I'll try not to repeat too much of
- 7 Commissioner Heiler's comments. The one-story addition, I
- 8 agree that the existing structure needs to be replaced.
- 9 The construction of the two-story side addition, I
- 10 am not supportive of the clear story windows. It's non-
- 11 complementary to the structure and interferes with the
- 12 fenestration of the original structure. I would like to see
- 13 it, this two-story side addition reduced as much as
- 14 possible. Granted, large houses need lots of kitchens, but
- 15 it's just becoming too large of a footprint, and I would
- 16 prefer to see it reduced in size.
- 17 The front porch, I admit that I am having a
- 18 terribly difficult time envisioning what your vision is for
- 19 this. The picture that you have painted in my mind, I
- 20 cannot support that. It seems a very modern attachment to a
- 21 highly historic structure, and would just quite simply seem
- 22 out of place. But perhaps if you come back with something
- 23 that we can visualize a little more than your vision, we
- 24 would be happy to reconsider that. I would be happy to
- 25 reconsider that.

- 1 The glass dormer replacement, such a pity that
- 2 that fell apart, and yes, it does need to be replaced. And
- 3 the concept you have for that is fine.
- The two-story, the two-car detached garage, I
- 5 can't consider it a three car, because the three car is
- 6 impossible in that place. I would like to see the roof
- 7 reduced as much as possible, the roof line reduced as much
- 8 as possible to minimize the affect on the view, and would
- 9 again encourage you to look in other places to place that
- 10 two-car garage. Those are my comments.
- 11 MR. TRESEDER: I would agree with Commissioner
- 12 Heiler and Commissioner Whitney on both items on the one-
- 13 story addition.
- 14 Regarding the kitchen addition, I don't have a big
- 15 problem with an addition, per se, in that location. I would
- 16 encourage the applicant to do additional studies of the roof
- 17 line because I feel that the roof line is sort of competing
- 18 with the existing lean-to roof, and there are other
- 19 precedents in the house that could be picked up, that would
- 20 be less competitive.
- 21 And I also think, and this is something that
- 22 Commissioner Rodriguez was, I think, implying, is that the
- 23 additional also affects the clarity of the square tower.
- 24 The square tower now rises up out of the ground floor plan.
- 25 And by inserting this addition in the corner, it obscures

- 1 the clarity of that tower. And I suspect there is an
- 2 architectural solution to it, so it's not, I don't think
- 3 it's an unsolvable problem, but I think that's what I would
- 4 recommend to be studied.
- 5 Let's see. A third bullet point, if I can find it
- 6 here --
- 7 MS. MILES: The glass dormer.
- 8 MR. TRESEDER: The glass --
- 9 MR. RODRIGUEZ: That's stating an option.
- 10 MR. TRESEDER: Yes, I am sort of -- I'm basically
- 11 okay with it, but I sort of agree with Commissioner Whitney,
- 12 that I would be interested to see more information about it
- 13 and understand its function more. It's a sound facing
- 14 exposure. You're going to get incredible heat gain through
- 15 there, but I guess there are technical ways around that.
- And then the glass dormer, I agree with
- 17 Commissioner Heiler that that could be carefully modified to
- 18 function properly.
- 19 And then my opinion on the garage is, again, I
- 20 think that in principal I don't have a big problem with it,
- 21 although I think it will have to be reduced in size in order
- 22 to conform to zoning, but again, I would urge you to study
- 23 possible other roof designs, even again, the house has a
- 24 precedent of balustrades, flat roof with balustrades, flat
- 25 roofs with crenellations. It doesn't necessarily have to be

- 1. a hipped roof. And that could reduce it's mass even more
- 2 without impairing its functionality.
- 3 MS. MILES: Garage? Okay.
- 4 MR. TRESEDER: That was the --
- 5 MS. MILES: I'm sorry. My apologies. Thank you.
- 6 MR. RODRIGUEZ: Okay. How I see it, you have a
- 7 house, this rectangular body, more or less anchored by these
- 8 two towers, a round tower, a square tower, rotated. Then
- 9 you have these round portion in the center. And to this
- 10 house some time ago somebody added the porch and then they
- 11 added this little room on the side.
- 12 What I find that what you're trying to tell us is,
- 13 I cannot find what is styling all these things together. I
- 14 think the way it's presented, and the little information
- 15 that we have, I see trying to repair things, but I don't see
- 16 that there is a unifying theme here to try to understand
- 17 what you want to do.
- 18 The house is a beautiful house. It's a house that
- 19 has definitely a very powerful presence in the landscape, so
- 20 any element that you would add to that, it has to be very
- 21 carefully done.
- 22 And what I find is that to talk about the
- 23 restoration of this little porch addition, I find that going
- 24 through the restoration to maintain the features that are
- 25 there because it was there, it's not a clear intention. So

- 1 my question is, and then adding more to it with a different
- 2 shape, another type of windows, another type of organization
- 3 and formal definition is, I just find it a little bit
- 4 contradictory.
- 5 So what I would recommend is that I will look at
- 6 the porch. I mean, the porch ceiling is so low, why not
- 7 consider that this becomes a must unifying project that
- 8 contains the porch and the addition, but the addition is a
- 9 lot smaller and doesn't come and prevent the tower to rise
- 10 from the ground.
- 11 This house reads from below. This house was
- 12 designed to be seen from the river. So you have this very
- 13 vertical scale of the house. And when you start adding
- 14 things to the elements that are defining the verticality of
- 15 the house, you start taking away from the value of the
- 16 house.
- 17 And I think it does something that I just cannot
- 18 support. I will not support the addition and the basement,
- 19 ground floor addition as presented. The addition has to be
- 20 a lot smaller, and it has to be a lot lower in scale.
- 21 The other part that I find completely
- 22 contradictory is the window treatment. The window
- 23 treatments are not keeping and not even looking at the house
- 24 precludes what to do. You are bringing in windows with very
- 25 close mullions, you know, separations between them. And

- 1 that's nowhere in the house.
- 2 So I think either you go one direction is, you do
- 3 a completely modern addition, something that we can look and
- 4 it's Unitarian (utilitarian?), defined, doesn't need to have
- 5 the same roof, can be a flat roof, can be something that is
- 6 done and defined for your needs, but a lot smaller.
- 7 Or you take the clues from house, so there is
- 8 basically either you contrast completely or you take clues
- 9 from the house. But the way it's presented in the drawings
- 10 that we have in front, I just think we are seeing two things
- 11 come together, and one is an apple, the other is an orange,
- 12 and they are not talking to each other, basically.
- 13 That's for point one and two. The front porch
- 14 alterations, I think for me the devil is in the details, so
- 15 without details it's very hard for me to give you a clear
- 16 comment. What I can tell you is what you're proposing is a
- 17 very modern approach, and then the idea is, and I think in a
- 18 lot of the houses that you will see in Italy that you have
- 19 these houses, they are 500-600 years old and whatever
- 20 intervention, new intervention is extremely modern and is
- 21 done on purpose.
- 22 So either it is very modern and we get the details
- 23 very clearly defined, and we address all the issues with
- 24 doors, frames, and things, and that becomes the theme, or
- 25 the porch becomes the theme. The issue of restoration it

- 1 probably becomes the theme of the garage. It's very hard
- 2 for me to define really by elegance or not. I have my
- 3 issues in terms of we don't know the details of how this is
- 4 going to maintain the integrity of the structure, the
- 5 framing, the masonry is going to be very hard for me to give
- 6 you an opinion.
- 7 But I can see the value, and I can see, and I can
- .8 imagine what it will be. But again, for me it's a very
- 9 modern aesthetics. And as I said it again, I will encourage
- 10 you to go forward for it, but doing it very well done, so
- 11 with details that are clearly defined and that they contrast
- 12 to the house so we can weigh it.
- And then the glass dormer, the glass dormer I
- 14 don't think is original to the house. That was something
- 15 somebody did in a moment. I think it's a repair and I take
- 16 it more for a repair. I think the location of that dormer
- 17 really is very weak in terms of the massing of the house.
- 18 It sits between two, a chimney and a tower. But it's a
- 19 repair and I take it as a repair, so I don't have no
- 20 comments regarding that.
- Then with the garage, I think as from what I see
- 22 in the drawings, I cannot support it. I think the garage
- 23 needs to be scales down. One recommendation I will do is I
- 24 will say, yes, that you consider that this is a somewhat
- 25 underground garage, so basically I would put a green roof, a

- 1 flat roof, so I make it disappear completely, so it doesn't.
- 2 compete with the house. It's much lower and it's much
- 3 smaller. It is really sized for the three cars maximum,
- 4 nothing else, probably a small storage room in the back.
- 5 But my reaction when I see the garage is, if I
- 6 compare the garage to the footprint of the house, it's
- 7 almost half of the house. So it's an issue in the site plan
- 8 that jumps immediately. And then you have the issues that
- 9 you have to address with the stone. But if the garage is
- 10 much lower, it probably is a green roof, half of it covered
- 11 by dirt would be probably a much successful intervention, in
- 12 my opinion.
- 13 MR. KIRWAN: Commissioner Rodriguez and I are of
- 14 the same mind on the first two points. For me, the one-
- 15 story addition is fine by itself, if you are going to
- 16 restore and renovate that piece. I don't have any issue
- 17 with that.
- 18 Where it comes into -- where I have a difficulty
- 19 with it is when you add this two-story addition next to it.
- 20 I won't repeat all the same reasons that Commissioner
- 21 Rodriguez and I have for that. It's the way these two
- 22 things join together, and are really incompatible with each
- 23 other.
- I would actually be supportive of taking this one-
- 25 story addition down, and doing a new addition on the side of

- 1 the house. And because the one-story addition is not
- 2 original to the house, take it down, do a new two-story
- 3 addition on the house that is more appropriate to add onto
- 4 this type of resource.
- 5 The other issue for me in the design you proposed
- 6 is the scale of it. I think it's too small a scale,
- 7 actually. All these bits and pieces and small scale
- 8 windows, when you look at, as Commissioner Rodriguez
- 9 described, when you look at what this house is about, it's
- 10 this main block that has this beautifully intricate roof,
- 11 and then it has these -- and these towers that are really
- 12 wonderful.
- 13 And it has these two things that are attached to
- 14 it, these two one-story to two-story pieces, if you include
- 15 the basement. And-they are very large scale. They have
- 16 large openings and they have flat roofs. And I would
- 17 encourage you to look at that kind of architecture for this
- 18 addition, if you are to pursue an addition that takes down
- 19 the one-story shed and adds something onto that side.
- 20 And I think one of the reasons why I also
- 21 encourage sort of the rethinking of those side additions is
- 22 that tower, that it's in -- your two-story addition is
- 23 encroaching upon. I think that's a mistake. I think it
- 24 really should be pulled back from that tower so that tower
- 25 can remain fully expressed all the way down to the ground,

- 1 as opposed to the encroachment that you have shown on the
- 2 drawings.
- I also, you know, I don't have a problem with the
- 4 stone as a material choice for this. I think another way of
- 5 looking at this design is going to lead to a different
- 6 approach to the overall design. And stone may be an
- 7 appropriate material there. I don't support a standing seam
- 8 metal roof on the addition of this house. I think that
- 9 could be a real mistake.
- Again, I support a flat roof, which would be more.
- $11 < ext{in}$ keeping with the other two roofs that are on the one-
- 12 story pieces attached to the house.
- 13 · On the front porch alterations, like the others, I
- 14 think I agree to them in general concept. I think we really
- 15 are going to need to see a lot more detail, particularly
- 16 about that door, to really understand how that finished
- 17 product is going to look.
- 18 The glass dormer replacement, I'm fine with that.
- 19 The three-car garage I think is too large for the site. I
- 20 think it should be a two-car garage. When you look at the
- 21 site plan and you sort of sketch out what the size of a two-
- 22 car garage will be, it will be about the same size as a
- 23 porte cochere on the front of the house. And I think that's
- 24 a more appropriate scale as a freestanding element.
- I think there are some very interesting ideas

- 1 about pushing that garage into the hill and burying it, are
- 2 interesting. I am concerned about a standing seam metal
- 3 roof approach again, because prefinished roofs are
- 4 difficult.
- 5 We don't control color. And there are some really
- 6 bad prefinished roof colors out there, and you know, I'm
- 7 sure you have very good taste in the way you are approaching
- 8 a lot of this work, but we don't have any control over that.
- 9 So I'm a little concerned about that as a material choice
- 10 for the roof.
- And I also am concerned in the way it's detailed
- 12 now, the way that the garage is pushed into the angled side
- 13 yard. It creates sort of a canted side wall to the garage.
- 14 And the way you've detailed the roof now, I think that's
- 15 going to be very unresolved. I think we're going to end up
- 16 with this very strange end of your roof where that canted
- 17 angle is.
- 18 So with this very traditional hipped roof on top
- 19 of this garage with canted angle to the garage, it's going
- 20 to result in a strange condition on that roof. You're going
- 21 to have a very funny, you know, awkward geometry there. So
- 22 I think, again, a two-car garage, if it's not going to be
- 23 buried under the hill and has its own roof to it, should be
- 24 pulled away from that. It should not have an angled side to
- 25 it. It should be a square-shaped two-car garage.

- 1 MR. CORATOLA: Well, I agree with everything that
- 2 Commissioner Rodriguez and Commissioner Kirwan had to say
- 3 about the additions. The side additions, the idea of
- 4 tearing down the existing lean-to and incorporating that
- 5 into a larger side addition, the contemporary elements, I
- 6 think would work well in this application, studying
- 7 different materials. I agree with the comments about trying
- 8 to match the stone. It might be difficult, so you're
- 9 definitely going need to look at the details on that.
- The front porch, again, contemporary details,
- 11 studying the details, how the glass fits in those openings,
- 12 or maybe it doesn't sit in the openings. So it's slightly
- 13 removed from there.
- Definitely need to look at how you handle that
- 15 door. I think the door you are talking about is sort of
- 16 like a Herculite commercial storefront, where it's a
- 17 frameless door, but there are framed components to it, so
- 18 that it will have an effect. So I think you are going to
- 19 really need to study how that door works.
- 20 As far as the repair of the dormer, I mean, it's a
- 21 repair and, you know, I'm in favor of that.
- 22 As far as the garage, I agree the scale is too
- 23 large as you currently have it. I agree that the angle is a
- 24 little odd shaped for this, and you will have issues with
- 25 that roof line, as Commissioner Kirwan said.

- 1 If there is a necessity for a three-car covered
- 2 scenario that a two-car covered, you know, that picks up the
- 3 roof lines of the house or is buried and then a carport or a
- 4 lean-to to that, just to change the scale, you know, if you
- 5 are changing roof lines, that will reduce a visual scale as
- 6 well. And that's all I need to say.
- 7 MR. JESSEN: My view on this is, we have five
- 8 elements that you are adding or working with on this
- 9 project, and they are all very different. They seem to have
- 10 different materials, different applications, different roof,
- 11 different windows, and a bit of a different language for
- 12 each piece.
- 13 And I think it would be helpful just to step back,
- 14 perhaps, and take maybe a fresh look at a design that has a
- 15 little bit more continuity between the elements. And I
- 16 would concur with many of the comments that we heard
- 17 earlier.
- 18 I'm not opposed to the glass on the porch. A
- 19 modern insertion I think is, could be appropriate. I think
- 20 the details are really important. But it doesn't really
- 21 relate to the other things that you are doing, but it could.
- 22 I think you could look at all five of these
- 23 elements as one holistic design. They are different
- 24 locations on the site, but they could have a similar
- 25 language that isn't necessarily the historic architecture

- 1 that you have. It could be a departure from that, or it
- 2 could be in keeping with it. Your choice.
- 3 But it seems like those elements should be not
- 4 five separate pieces then being added, and the effect being
- 5 it just kind of waters down the house. But it could
- 6 actually, they could communicate in a similar language and
- 7 be a bit more of the holistic design. So I kind of view it
- 8 from continuity, I think is important.
- 9 And then the kitchen addition, the two-story
- 10 addition, I am concerned about it engaging the square tower.
- 11 And I think you've heard that a few times. I think that's
- 12 a real problem.
- 13 If it's possible to put the kitchen in the lean-
- 14 to, if that gives you enough space, I think that would be
- 15 ideal. If it's not, I would favor what we've heard here is
- 16 an idea where that's removed and one addition is put on the
- 17 side, where maybe you can have your breakfast room and your
- 18 kitchen, but in one addition, instead of having two add-ons,
- 19 on that side. I think that would be much better.
- 20 As for the garage, I think it is too big. I don't
- 21 have an issue with that location. I just think it's too
- 22 big. And the glass dormer, I don't really have a concern
- 23 with that.
- 24 MR. WHIPPLE: Chairman Miles, perhaps before you
- 25 sum up, do you want to give the four Commissioners who

- 1 preceded Commissioner Kirwan an opportunity to express their
- views on demolishing the one-story addition?
- 3 MS. MILES: Do you want -- that's an excellent
- 4 question. Do you all have anything you would like to say in
- 5 reaction, Commissioner Whitney, Commissioner Heiler?
- 6 MS. HEILER: Actually, I think that is a great
- 7 idea, since it isn't original, and it gives you enough space
- 8 there to put the addition that you want without having two
- 9 little things stuck out on the side.
- 10 MS. MILES: Thank you. Commissioner Treseder?
- MR. TRESEDER: I don't feel strongly either way.
- MS. MILES: Thank you. Okay. Anne, I'm going to
- 13 ask if you can please put up the slide from the aerial, or
- 14 Josh, whoever has control.
- MR. SILVER: Could you hand that to me, please.
- 16 MR. RODRIGUEZ: Can I add one little thing?
- MS. MILES: Certainly.
- 18 MR. RODRIGUEZ: I would recommend that you go to
- 19 the National Cathedral. The Cathedral added a very large
- 20 garage. And you will see that from that garage there are a
- 21 few small very modern glass and steel pavilions that come
- 22 out. And that's all that you see of the garage.
- 23 But I think that would give you a good idea that
- 24 there is a type of intervention that can be, that is very
- 25 respectful of the context where it is, but doesn't need to

- 1 mimic it. And I would suggest start around and you will see
- 2 these pieces. They are very well designed, and they look
- 3 very well in the environment and the scale.
- 4 MS. MILES: Thank you, Commissioner Rodriguez. I
- 5 asked that this slide be put up because this is no longer
- 6 the context. This is the context. All of the trees between
- 7 this house and the Richards House going down the Palisade to
- 8 McArthur Boulevard, they are almost all gone. So you can
- 9 now see all of this extremely, excruciatingly clearly from
- 10 McArthur Boulevard. So I just wanted to make that point.
- 11 I'm going to absolutely second everything that
- 12 Commissioner Rodriguez and Commissioner Kirwan said. I
- 13 thought that was very well stated. I agree that the most
- 14 appropriate thing to do would be to take down the later
- 15 addition and to create something that is integrated.
- 16 My concern that nobody else raised is, if we
- 17 permitted you to build an addition on the side of this
- 18 house, you would have to cut into the existing stone wall.
- 19 And I think that is a very painful thing to contemplate.
- 20 And if you, instead, essentially demolish this later
- 21 addition and do all of your work off of that. There will be
- 22 no need to create a permanent hole in the exterior of the
- 23 stone house.
- 24 I think the design you are showing us for the two-
- 25 story addition is too large and it's too tall and the

- 1 materials are problematic, and particularly the windows.
- 2 think both fenestration design and tightness of the windows
- 3 are just too modern and not sympathetic. I don't think the
- 4 standing seam metal roof is appropriate.
- I think that if you are going to build something
- 6 that's two-story next to the one-story, it needs to
- 7 completely step down, aside from the clear story window. I
- 8 think it needs to be lower, buried, and definitely pulled
- 9 back from that turret that is such a strong element.
- I don't have enough information to have an opinion
- 11 about the glass for the porch. Although I don't have an
- 12 issue with the idea, I don't know enough. I don't see
- 13 enough. I don't have an issue with the dormer.
- The garage is too big and it's too tall, and it's
- 15 got site problems. I have a concern with building a second
- 16 garage, when there is an existing garage, although not on
- 17 this parcel, within this historic context. And I think this
- 18 is best resolved with a two-car garage that is largely
- 19 buried. I think that's exactly how it should be treated. I
- 20 wrote buried, but I think a green roof and buried is even a
- 21 better solution. It should largely vanish, and your
- 22 neighbors should not have to see it.
- 23 So that is my reaction. And I think you've had a
- 24 lot of feedback and go forth and redesign and we'll see you
- 25 again. Do you have any questions for us?

- 1 MR. McNAIR: No.
- 2 MS. MILES: Okay, then. Yes.
- 3 MR. McNAIR: I would love to take down the one-
- 4 story addition that is on the side and build one space that
- 5 would have the kitchen and the breakfast room.
- 6 MS. MILES: Okay. Good. I'm glad we've made a
- 7 suggestion that you find useful, and that I think that will
- 8 be a better solution. I think there is unanimity, that that
- 9 would be -- I guess Paul would be good either way, but
- 10 largely unanimity that that would be a better solution.
- MR. McNAIR: Okay.
- MS. MILES: All right. Thank you. We're going to
- 13 go back to our skipped agenda item then, which is item J of
- 14 the historic area work permit applications. It's the
- 15 railing installation for 900 Olney-Sandy Spring Road, Sandy
- 16 Spring. And do we have a staff report?
- 17 MS. FOTHERGILL: Yes. This is an outstanding
- 18 resource in the Sandy Spring history district. And some of
- 19 you may be familiar with the building because they've
- 20 recently had a different historic area work permit
- 21 application before you.
- It was the Montgomery Mutual Fire Insurance
- 23 Company headquarters, and it's a circa 1904 building, and
- 24 there have been two additions to the building on the south
- 25 and east sides. But here is a photo of the building taken

HPC Preliminary Consultation Notes for 5415 Mohican Road, Bethesda July 13, 2011

ADDITION

Consensus the existing one story lean-to addition could be removed to accommodate an alternative design for a side addition on the right side elevation.

Support for the construction of a <u>contemporary</u> style side addition. Consideration needs to be given to the scale of the additions parts. Comments focused on the dichotomy between the larger size of windows on the existing house and smaller windows proposed for the side addition.

Addition is too large

Explore alternative roof forms

Recommendations:

Look more closely at the bigger scale of the historic massing and take cues from its scale when developing new proposal.

Pull addition back from the tower to allow it to read as fully independent from any new construction. No physical attachment between the front tower of historic massing and new addition.

Reduce size of the addition to make project approvable when submitted as a Historic Area Work Permit (HAWP)

Use flat roof system. Possible material types include rubber membrane or green roof.

Provide floor plans for 2nd Preliminary Consultation review with HPC

FRONT PORCH ALTERATIONS

Consensus the proposed fixed glass pieces were a feasible option. Questions about the installation method of the glass and access door between the porch and grade.

Recommendation:

Provide more detail about the proposed installation method of the glass and specifically the door.

GLASS DORMER REPLACEMENT

Support as proposed.

Recommendation:

No changes recommended.

GARAGE

Location must comply with established setback requirements for the property. Size/scale too large. Angle problematic. No standing seam metal roof.

Recommendations:

Determine appropriate setback. Reduce size. Two car garage appropriate for site. Some support for two car garage with open carport. Design should be consistent with the revised design for the side addition. Use an alternative roof form and material.

7/11/2011

Miklos Gaal & Courtney Roberts 5407 Mohican Road Bethesda MD 20816

Mr Scott Whipple, Historic Preservation Supervisor Ms Anne Fotherfill, Planning Coordinator Mr Joshua Silver, Senior Planner Historic Preservation Section, M-NCPPC 8787 Georgia Avenue Silver Spring MD 20910

Historic Preservation Commission

In reference to Ross McNair and Allison Taylor's request for a preliminary consultation for a side addition, new garage and other alterations at 5415 Mohican Road, Bethesda MD 20816. Resource: Master Plan Site #35/29, Baltzley Castle.

We are opposed to both the new side side addition and the garage. We have no opinion on the other changes requested.

Our property, 5407 Mohican Road, is northwest of and directly adjacent to the Baltzely Castle. We enjoy a view of Macarthur Blvd, the Potomac River and across to the Virginia side of the river via the "sight line" that exists between the two castles at 5415 and 5417 Mohican Road. This view has existed from when the castles were built as our property is at a higher elevation than the castles.

Our opposition to the new side addition is threefold:

1) This new structures will "close off" some our long-standing view of the Potomac River. We have personally enjoyed this view since we've owned our property, and this view has existed since our house was built in 1960. We recognize that the view is only available during the late fall, winter, and early spring when the

5407 Mohican Road

- leaves are off the trees. However, this is the time of year when the view of the Potomac is most welcome and we are often on our deck and in our yard enjoying our view of the majestic Potomac.
- 2) The proposed addition appears to be very close to the property line between the castles and no mention is made of the required setbacks in the request for consultation.
- 3) Destroying our view of the Potomac will negatively affect our properties' value. When we purchased the property we were willing to pay more for the view. Real Estate agents confirm that subsequent purchasers will also be willing to pay more for a view of the Potomac.

Our opposition to the garage is sixfold:

- 1) The proposed set back of five feet is insufficient per MC regulations. Our understanding of Montgomery County development standards is that accessory buildings in excess of 24 feet in length (which this garage appears to be) require an additional set back based on the length (2 feet of setback for each additional 2 feet of length). Further our understanding is that structures which are taller than 15 feet (which this appears to be) require addition set back also (2 feet for each additional foot in height). We believe that the minimum set back should be at least 10 feet and possibly more depending on the actual size of the garage.
- 2) The garage will ENTIRELY "close off" the long-standing, existing view of the Potomac River. We have enjoyed this view since we've owned our property, and this view has existed since our house was built in 1960. We recognize that the view is only during the late fall, winter, and early spring. However, this is the time when the view of the Potomac is most welcome and we are often on our deck and yard looking over the majestic Potomac. Please see attached photos for your reference.
- 3) The additional setbacks required by code will have the effect of moving the garage further into the sightline and eliminating an even larger portion of our view. We could wind up in a situation where the garage becomes the only thing we can view from our back deck.
- 4) We would then have TWO different garages, capable of garaging five cars adjacent to our back deck and closing off a corner of our property and making our deck space appear to be part of a parking lot. Our lot is small and our back yard almost non-existent; therefore we live extensively on our back deck. We eat outside frequently and we enjoy the spaciousness we currently have.
- 5) The current garage for 5417 (an adjacent historic structure which is also owned by Ross McNair or his construction company) is actually on our property line and the garage's eaves slightly overhang our property. While discussing changes to this adjacent property are out of scope of the current request, the hemmed in feeling we would get from having two structures in close proximity to our deck and where we eat most weekends and some evenings would be intolerable and must be considered in the broader context.
- 6) Destroying our view of the Potomac will negatively affect our properties' value. When we purchased the property we were willing to pay more for the view. Real Estate agents confirm that subsequent purchasers will also be willing to pay more for a view of the Potomac.

Photos to illustrate our position:

Photo 1. The Red Box highlights where we "see" our view of the Potomac River.



Photo 2. Where the Garage and Side Addition will obstruct our view:



We ask that the Historic Planning Commission also consider our 50+ year view of the Potomac River and its foliage when making recommendations. We ask that you instruct Mr McNair and Ms Taylor to:

- 1) Limit the impact the new addition will have on our view by reducing its height and reducing its incursion into the gap (sight lines) between the two castles.
- 2) Resite the proposed garage so it follows all applicable setback requirements and
- 3) Considerably reduce the height of the garage so it does not block our view of the Potomac River.

We would also like to see if there is a way to remove the non conforming garage on 5417 Mohican Road, or at least get it situated so it does not sit on our property line, and follows current set back requirements.

We invite you to come see the view and get a sense for the impact these changes will make from our back deck. Please call Miklos Gaal on 301-787-9225 to schedule the visit.

Miklos Gaal & Courtney Roberts Homeowners 5407 Mohican Road

SONY

Date

BAKZLEY CASTLE

S4 15 MOHIGAN (20

Betheson Mo Aporthion

1/02-51-6