



## Historic Preservation Commission

100 Maryland Avenue, Rockville, Maryland 20850-279-1327-279-8097

51 Monroe Street, Rm. 1009 Rockville, MD 20850

# APPLICATION FOR HISTORIC AREA WORK PERMIT


NAME	1.1	11	/	
	E OF PROPERTY OWNER WARN (Controct/Purchaser), 772 5 12	ER MEMORIAL	TELEPHONE NO. 301/949-	2900
ADOF	RESS 10123 LONNEO	TICUT AVE, K	(Include Area Code) ENSINGTON MD STATE	20895
LONT	TRACTOR S.A. CARR	CITY SON	STATE TELEPHONE NO. 301/97	7-9636
	, ·	CONTRACTOR REGISTRATION		
PLAN	SPREPAREO BY CHARL	ES CLASTNER	TELEPHONE NO. 34946-3	427
		REGISTRATION NUMBER	N/A	
LOCA	ATION OF BUILDING/PREMISE	19 7		TOTED WOE
House	Number	Street VEC VE	SCRIPTION OF PRO	FOTED IVE
Town	/City	Electi		t DIDE
Neare:	st Cross Street			
Lot	Block	Subdivision	· 	
Liber_	Folio			
1A.	TYPE OF PERMIT ACTION: (circle Construct Extend/Add	e one) _Alter/Renovate Repair	Circle One: A/C Slab Porch Deck Fireplace Shed	Room Addition Solar Woodburning Sto
	Wreck/Raze Move Install		Fence/Wall (complete Section 4 Other	) LIGHTING
1B.	CONSTRUCTION COSTS ESTIMA	TES 600 00		PARKING L
1C.	IF THIS IS A REVISION OF A PRE	EVIOUSLY APPROVEO ACTIVE PE	RMIT SEE PERMIT #	
1D. 1E.	INDICATE NAME OF ELECTRIC IS THIS PROPERTY A HISTORICA	UTILITY COMPANY PET	<u> </u>	•
4A.		hes	i	
		t		
1 hors			that the application is correct, and that the co be a condition for the issuance of this permit.	onstruction will comply w
plans	Mary Dutte.	Clerk of Lession	2 February 20	2, 1988
Sign	* * * * * * * <sup>/</sup> * * * * * * * * * * * * * * * * * * *	******	Dack)  7 ebruary & o	2, 1988 e
Sign	10VED X 24A8(b)(1) *	**************************************	**************************************	*****
Sign **** APPR	PPROVED	For Chairperson, Historic Preserva Signature Muluta H	**************************************	*****
Sign APPR DISAL	* * * * * * * <sup>/</sup> * * * * * * * * * * * * * * * * * * *	For Chairperson, Historic Preserva Signature Nobella H	**************************************	/88
Sign APPR DISAL APPL OATE	PPROVED X 24A8(b)(1) F  PPROVED  ICATION/PERMIT NO: HAW  E FILEO: E ISSUED:	For Chairperson, Historic Preserva Signature Nutruta (4)	otion Commission  Oate 3/18/  FILING FEE: \$  PERMIT FEE: \$  BALANCE \$	/88
Sign APPR DISAL APPL OATE	PPROVED X 24A8(b)(1) F PPROVED	For Chairperson, Historic Preserva Signature Nubuta H  P 4 - 88	Oate 3/18/	/88
Sign APPR DISAI APPL OATE OATE	PPROVED X 24A8(b)(1) PPROVED THAW  ICATION/PERMIT NO: HAW  E FILEO: E ISSUED: ERSHIP CODE:	For Chairperson, Historic Preserva  Signature  P 4-88  SEE REVERSE SIDE FO	FILING FEE: \$ PERMIT FEE: \$ BALANCE \$ RECEIPT NO: FEE WA	/88 
Sign APPR DISAI APPL OATE OATE	PPROVED X 24A8(b)(1) PPROVED THAW  ICATION/PERMIT NO: HAW  E FILEO: E ISSUED: ERSHIP CODE:	For Chairperson, Historic Preserva  Signature  P 4-88  SEE REVERSE SIDE FO	FILING FEE: \$ PERMIT FEE: \$ BALANCE \$ RECEIPT NO: FEE WA	/88 
Sign **** APPR DISAI APPL OATE OATE	PPROVED X 24A8(b)(1) PPROVED THAW  ICATION/PERMIT NO: HAW  E FILEO: E ISSUED: ERSHIP CODE:	For Chairperson, Historic Preserva  Signature  P 4-88  SEE REVERSE SIDE FO	FILING FEE: \$ PERMIT FEE: \$ BALANCE \$ RECEIPT NO: FEE WA	/88 

#### DESCRIPTION OF PROPOSED WORK:

Warner Shurch has only one primary parking facility which is located directly across Connecticut Ave. from the church. The location of the lot alone has been a concern of the congretation for some time. The traffic at that point on Connecticut Ave. is heavy most hours of the day. However, appeals to State authorities foa a traffic light at the intersection of Connecticut Ave. and Washington St. have repeatedly been denied on the argument that the traffic exiting onto Connecticut Ave. from Washington St. does not meet minimum volume standards to justify a traffic light. We continue to get this response even after the traffic death of a church member at that intersection a year ago while she was crossing Connecticut Ave. to the parking lot. We have, however, been awarded a small concession- a crossing guard at-Washington St. during Sunday morning worship time.


While we continue to explore some means to assure safe crossing of people to and from our parking lot, another of our concerns is for the safety and security of people using that parking facility for attending church activities after dark. Warner is a very active church with many activities scheduled almost every day and evening of the week. The reluctance of people attending evening activities to use a darkened parking facility located across a busy uncontrolled thorofare, is understandable. The resula, of course, is saturated curbside parking in the residential areas along Washington and Calvert Sts. adjacent to the church property, which brings frequent complaints from local residents.

In order to encourage the night-time use of our parking lot by at least providing a sense of safety and security to our congregation, we propose to install a dusk-to-dawn lighting system in the lot, described as follows:



CONNECTICUT AVE.

-> TO KENSINGTON





## **Historic Preservation Commission**

PROMPE Sign

100 Maryland Avenue, Rockville, Maryland 20850 279-1327

121 Montes in Model (1914 - 1917) Matrice Military (1914 - 1917)

# APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #					
NAME OF PROPERTY OWNER	Jan Jan Barrell	TELEPHONE NO.			
(Contract/Purchaser)		(Include Area Code)			
ADDRESS	TY	STATE	ZIP		
CONTRACTOR	x* *	TELEPHONE NO.	· · · · · · · · · · · · · · · · · · ·		
<b>4</b> .	CONTRACTOR REGISTRATION	N NUMBER			
PLANS PREPARED BY		TELEPHONE NO.	· · · · · · · · · · · · · · · · · · ·		
,	DECICED ATION NUMBER	(Include Area Code)			
	nediainAiluN Number	and the second s			
LOCATION OF BUILDING/PREMISE	, :				
House Number	Street	and the first of the second			
Tiouse Number	Ullest	V ( 1883)	A Company		
Town/City	Electi	on District			
Nearest Cross Street					
Let Block	Subdivision				
LOI BIOCK	20001A121011				
Liber Folio	Parcel				
1A. TYPE OF PERMIT ACTION: (circle or Construct Extend/Add A Wreck/Raze Move Install	Iter/Renovate Repair Revocable Revision	Circle One: A/C Slab Porch Deck Fireplace Shed S Fence/Wall (complete Section 4) Other	Solar Woodburning Stove		
	ILITY COMPANY SITE? UCTION AND EXTEND/ADDITI	ONS 2B. TYPE OF WATER SUPPLY 01 ( ) WSSC 02 ( ) Well			
03 ( ) Other		03 ( ) Other			
PART THREE: COMPLETE ONLY FOR FENG 4A. HEIGHT feet inches 4B. Indicate whether the fence or retaining 1. On party line/Property line 2. Entirely on land of owner 3. On public right of way/easement _	s g wall is to be constructed on one o				
plans approved by all agencies listed and I herel	by acknowledge and accept this to		1 10		
Signature of owner or authorized agent (agen	t must have signature notarized on	back) Date			
APPROVED X 24A 8(b)(1)	For Chairperson, Historic Preserve	ation Commission	· * * * * * * * * * * * * * * * * * * *		
DISAPPROVED	Signature Kalenta	Vala Date 3/18	188		
APPLICATION/PERMIT NO: HAW DATE FILED: DATE ISSUED:	104-88	FILING FEE: \$ PERMIT FEE: \$ BALANCE \$			
OWNERSHIP CODE:		RECEIPT NO: FEE WAI	VED:		

SEE REVERSE SIDE FOR INSTRUCTIONS

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION

 	<del></del>		 	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · ·	 
•						
			 	- , . ,		
<del> </del>		· · · · · · · · · · · · · · · · · · ·	 			
 .'						 
		(- <b>)</b> -				
					•	
		-				
	:					

(If more space is needed, attach additional sheets on plain or lined paper to this application)

ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.


MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE: HISTORIC PRESERVATION COMMISSION
100 MARYLAND AVENUE
ROCKVILLE, MARYLAND 20850

#### DESCRIPTION OF PROPOSED WORK:

Warner Church has only one primary parking facility which is located directly across Connecticut Ave. from the church. The location of the lot alone has been a concern of the congretation for some time. The traffic at that point on Connecticut Ave. is heavy most hours of the day. However, appeals to State authorities foa a traffic light at the intersection of Connecticut Ave. and Washington St. have repeatedly been denied on the argument that the traffic exiting onto Connecticut Ave. from Washington St. does not meet minimum volume standards to justify a traffic light. We continue to get this response even after the traffic death of a church member at that intersection a year ago while she was crossing Connecticut Ave. to the parking lot. We have, however, been awarded a small concession- a crossing guard at Washington St. during Sunday morning worship time.

While we continue to explore some means to assure safe crossing of people to and from our parking lot, another of our concerns is for the safety and security of people using that parking facility for attending church activities after dark. Warner is a very active church with many activities scheduled almost every day and evening of the week. The reluctance of people attending evening activities to use a darkened parking facility located across a busy uncontrolled thorofare, is understandable. The resuld, of course, is saturated curbside parking in the residential areas along Washington and Calvert Sts. adjacent to the church property, which brings frequent complaints from local residents.

In order to encourage the night-time use of our parking lot by at least providing a sense of safety and security to our congregation, we propose to install a dusk-to-dawn lighting system in the lot, described as follows:



Churchenz lot



These plans have been submitted by Warner Memorial Presbytenia Church They propose a lighting system for their existing parting but Please review for our next meeting on March 7.

Salomon 2/25/88 I would like to see a picture of the type of lamp & especially the type of "shield" they're going to use.

Saul 2/26/88 approve

Birchber I a great that Intue of the can park is necessary but agree with more solven that a slike I with the see that type Tamp, etc. They intude to restall. More own wild I spiriting per my operation at all Times, or only when the activities warrent it? I hamperstee 3/1/88 Home seen

Little - Will this lighting disturb the adjacent neighbor? Otherwisa I approve. 3-7-88


Dempster- light should be shelded to reduce impact to surround residential properties , approve. 3/1/88.

#### DESCRIPTION OF PROPOSED WORK:

Warner Church has only one primary parking facility which is located directly across Connecticut Ave. from the church. The location of the lot alone has been a concern of the congretation for some time. The traffic at that point on Connecticut Ave. is heavy most hours of the day. However, appeals to State autgorities foa a traffic light at the intersection of Connecticut Ave. and Washington St. have repeatedly been denied on the argument that the traffic exiting onto Connecticut Ave. from Washington St. does not meet minimum volume standards to justify a traffic light. We continue to get this response even after the traffic death of a church member at that intersection a year ago while she was crossing Connecticut Ave. to the parking lot. We have, however, been awarded a small concession- a crossing guard at Washington St. during Sunday morning worship time.

While we continue to explore some means to assure safe crossing of people to and from our parking lot, another of our concerns is for the safety and security of people using that parking facility for attending church activities after dark. Warner is a very active church with many activities scheduled almost every day and evening of the week. The reluctance of people attending evening activities to use a darkened parking facility located across a busy uncontrolled thorofare, is understandable. The resuld, of course, is saturated curbside parking in the residential areas along Washington and Calvert Sts. adjacent to the church property, which brings frequent complaints from local residents.

In order to encourage the night-time use of our parking lot by at least providing a sense of safety and security to our congregation, we propose to install a dusk-to-dawn lighting system in the lot, described as follows:



CONNECTICUT AVE.

### MONTGOMERY COUNTY HISTORIC PRESERVATION COMMISSION

### LOCAL ADVISORY COMMITTEE REVIEW FORM

#### EXTERIOR ALTERATIONS

I.	Location of property
	a. Located within the Joun of Rensinglinistoric district.
in si	b. This is a Master Plan/Atlas historic district (circle one).
	c. Address of Property: 10123 Commentant and
	d. Property owner's name, address and phone number:
	Warner Memorial Presly Church
•	
	(h) 9777636 (w) Church offen 9463427
	e. Is this property a contributing resource within the historic district? Yes No
	f. On a map of the district locate this property and any adjacent historic resources. Will this work impact other contributing historic resources? Yes No
II.	Description of work proposed
• • •	a. Briefly describe proposed work:
•	two dusk - to - down lighting
r	Joles for parking lot
	b. Is this work on the front, rear, or side of the structure?
	N A-
	c. Is the work visible from the street?
-	MA CONTRACTOR
- Andrews	d. What are the materials to be used?
	e. Are these materials compatible with existing materials? How? If

a. Approval of Work
1. Which criteria found in the Ordinance for Historic Preservation (Sec. 24A-8-b of the Montgomery County Code) does this work meet?
(t)
<ol> <li>What conditions, if any, must be met in order for the proposed work to meet the above criteria? (example: the proposed windows should be double hung to conform with existing windows)</li> </ol>
lighting must not disturb the adjaint
organisation of the control of the c
b. Disapproval of Work
<ol> <li>On what grounds is disapproval recommended? Refer to Sec.</li> <li>24A-8.</li> </ol>
. A LA A B LE BLE BLE LELLE DE BERTINGES E GELLE GENERAL DE LA CONTROPORT DE PLUM DE LA CONTROPORT DE LA CON
ನಿಷ್ಟು ಅಂತರ ಕರ್ಷ ವೃಧಕ ಕ್ಷಾನಿಕ್ಕಳು ಪ್ರಕ್ಷಿಕೆ ಕಥೆಕರು ಅಂತರ ಸಂಪರ್ಧ ಕರ್ಮ ಸಂಪರ್ಧ ಕರ್ಮ ಸಂಪರ್ಧ ಸಂಪರ್ಧ ಸಂಪರ್ಧ ಸಂಪರ್ಧ ಸಂ
2. How could this proposal be altered so as to be approved?
IV. Additional comments
en de la companya de La companya de la co
Date on which application received: 44 22 1988
Date on which application received:
Date of LAC meeting at which application was reviewed: March 7.1988
Form completed by: A august Title: Menture 1517
Member of: Lensmoton & AC
That I de lavo

III.Recommendation of the Local Advisory Committee