14/59-94A 9000 Brink Road Master Plan Site #14/59



MEMORANDU	<u>M</u>
TO:	Robert Hubbard, Acting Chief Division of Development Services and Regulation Department of Environmental Protection
FROM:	Gwen Marcus, Historic Preservation Coordinator Design, Zoning, and Preservation Division M-NCPPC
SUBJECT:	Historic Area Work Permit
DATE:	March 25, 1994
cation wa	pproved Denied
	pproved with Conditions:
<i>,</i> -	and first attempt up an afthewindows; if beyond repair, submit
that mogrish	rindow sample of unit pury to installation.
applicants	should first attempt upair of installation - replacing only the and other siding that is bleyond repair.
The Build	ing Permit for this project should be issued conditional rance to the approved Historic Area Work Permit.
Applicant	: Charles W. Small, J. & Chris Leonard
Address:	9000 Brink Road
	by the share and (Rochers)

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION
8787 Georgia Avenue • Silver Spring, Maryland 20910-3760

<u>MEMORANDUM</u>

TO:

Historic Area Work Permit Applicants

FROM:

Gwen Marcus, Historic Preservation Coordinator

Design, Zoning, and Preservation Division

M-NCPPC

SUBJECT:

Historic Area Work Permit Application - Approval of

Application/ Release of Other Required Permits

DATE:

March 25,1994

Enclosed is a copy of your Historic Area Work Permit application, approved by the Historic Preservation Commission at its recent meeting, and a memorandum stating conditions (if any) of approval.

You may now apply for a county building permit from the Department of Environmental Protection (DEP), at 250 Hungerford Drive, Second Floor, in Rockville. Please note that although your work has been approved by the Historic Preservation Commission, it must also be approved by DEP before work can begin.

When you file for your building permit at DEP, you must take with you the enclosed forms, as well as the Historic Area Work Permit that will be mailed to you directly from DEP. These forms are proof that the Historic Preservation Commission has reviewed your project. For further information about filing procedures or materials, please call DEP at 217-6370.

If your project changes in any way from the approved plans, either before you apply for your building permit or even after the work has begun, please contact the Historic Preservation Commission staff at 495-4570.

Thank you very much for your patience and good luck with your project!





Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Maryland 20850 217-3625

APPLICATION FOR HISTORIC AREA WORK PERMIT

TAX ACCOUNT #	- 1 053 1501
NAME OF PROPERTY OWNER Charles WSmalls.	TELEPHONE NO. 301-255-1539
Co. wher (Contract/Purchaser) Chris Loomed	(Include Area Code)
ADDRESS 9884 Mainst POROX 46 Durascus ma	md 208/2
ADDRESS 9884 Mainst PORS 46 Durascus md. CONTRACTOR JOE +I CONSTRUCTION	TELEPHONE NO. 501-953-2470
CONTRACTOR REGISTRA	ATION NUMBER 12578 TELEPHONE NO. 301-253-1554
PLANS PREPAREO BY Charles WSom/Kle.	TELEPHONE NO. 301-253-1554
	(Include Area Code)
REGISTRATION NUMBER	
LOCATION OF BUILDING/PREMISE	5 I
House Number 9000 Street Brink K	2d
Town/City Gaithersburg	Election Oistrict
Nearest Cross Street Goshen	
	= Meadows
Liber 9557 Folio Parcel	<u> </u>
1A. TYPE OF PERMIT ACTION: (circle one)	Circle One: A/C Slab (Room Addition)
Construct Extend/Add Alter/Renovate Repair	Porch Oeck Fireplace Shed Solar Woodburning Stove
	Fence/Wall (complete Section 4) Other
_	
1B. CONSTRUCTION COSTS ESTIMATE \$ 30,000	VE PERMIT SEE PERMIT #
1C. IF THIS IS A REVISION OF A PREVIOUSLY APPROVED ACTI	VE PERMIT SEE PERMIT #
10. INDICATE NAME OF ELECTRIC UTILITY COMPANYFCP	<u> </u>
1E. IS THIS PROPERTY A HISTORICAL SITE? Yes	
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTENO/A	
2A. TYPE OF SEWAGE OISPOSAL	2B. TYPE OF WATER SUPPLY
01 () WSSC 02 (>> Septic 03 () Other	01 () WSSC 02 (≯) Well 03 () Dther
US () Other	US (/ Dillet
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
4A. HEIGHTfeetinches	
4B. Indicate whether the fence or retaining wall is to be constructed on	one of the following locations:
1. On party line/Property line	
2. Entirely on land of owner	<u> </u>
3. On public right of way/easement	(Revocable Letter Required).
	ation, that the application is correct, and that the construction will comply with
plans approved by all agencies listed and I hereby acknowledge and accept t	his to be a condition for the issuance of this permit.
0 / 11/ 1 10//	12 1 1 1004
Chall sharly	rracch 1, 1717
Signature of owner or authorized agent (agent must have signature notarized	march 1, 1994 red on back) Oate
	,
APPROVEO A CANADA For Chairperson, Historic P	reservation Commission
	Max 625 0014
DISAPPROVED Signature	Date Marh 25, 1974
all KOKO CALE	
APPLICATION/PERMIT NO: 140505 90105	FILING FEE:\$
OATE ISSUED.	
DATE ISSUEO:OWNERSHIP CODE:	
OTHERDINI OUDL.	REE WAIVEU:






20'6" 9'6"×b' Bathan (Lx99 11'×10' Muster Bathroom 11,6"×14,1 Timber Framed Second Floo Plan Master 19121×14'0" Bedram 60, H (3) 2) 14'4"×15'4" 6 Timber France 5:#:73 Room Master Bedroom Fraposed Double 2"x10" Headers over all Window opening 2001 Don't How Die Die 32.30 -1" T+G Pareling 15'4"x 18'0" Bedroom 12'0" 32,6,1 APPROVED
Montgomery County
Historic Preservation Commission


Your Parket Damascus nd. 20872 PO Box 46 9884 main 9t Chatks wo Small yr.

Roof Profile front of house

APPROVED
Montgomery County
Historic Preservation Commission

\$ 200 g	N D D
NA TON	4 3
46	120
4-7-7-7-8 dows	19 19





SUPPLEMENTAL APPLICATION FOR HISTORIC AREA WORK PERMIT **REQUIRED ATTACHMENTS**

PROPERTY:

9000 Brink Road; Lot 8, Fertile Meadows Subdivision, per Plat Book 171 at Plat 19214

OWNERS:

Charles Small, Jr.

(301) 253-1012

Chris Leonard

(301) 330-8982

Submitted: March 1, 1994

9000 Brink Road/C. Small and C. Leonard Page One

ATTACHMENT 1: Written Description of Project

Description of existing structures and environmental setting. 1a. including their historical features and significance:

Fertile Meadows is an excellent example of a late 18th century farm house. The property is associated with the Riggs family, prominent in

Montgomery County history.

In 1743 Benjamin Wallingford was granted the land upon which Fertile Meadows now sits, calling it "Benjamin's Square". Some years later the land was resurveyed and a mill was built where the road from Laytonsville to Clarksburg crosses Goshen Branch, providing the nearby town with its name, Goshen Mills. Joshua Pigman came into possession of a part of the Resurvey on Benjamin Square and it is believed that he built the Fertile

Meadows house on the hill overlocking the mill sometime before 1792. In that year he sold the land, and improvements, and the house passed throuseveral owners before being purchased by George Washington Riggs in 1819. George Riggs was a self-made man. He started out as a silversmith i Georgetown and soon had a thriving business. In 1820, the year after he purchased Fertile Meadows, he had a license to be a storekeeper in Montgomery County, and eventually he moved to Baltimore where he became an exporter in the lucrative tobacco trade. He purchased several other largements at rects of land in the county.

expensive tracts of land in the county.

Several other parties owned Fertile Meadows before the Counselmans bought it in 1934. Lee Counselman had been a finance expert in Detroit a had helped organize several auto firms. Mrs. Counselman had been a fashio model.

Fertile Meadows in 1934 had been spared the threat of "modernization and the Counselmans successfully retained its primitive atmosphere while making the house livable.

The name "Fertile Meadows" came from a small tract which made up part of the original farm.

The house is a one-and-one-half story structure, the west end of which is frame; the east end is brick on the first floor and frame above. At the east end is a one-story brick chimney with a free-standing stack. frame section has an internal chimney where it adjoins the brick wing, and an external one-story chimney on the west end, with a narrow, free-standing stack. The frame section is five bays with a central doorway and a fourlight transom. The windows are nine-over-nine double hung sash. To "A" roof is broken by three dormer windows on the main facade. The The steep sheathing is clapboard and the cornice boxed with an ogee bed molding.

the gable sides, there is a fascia with a wide bead.

The brick section has a two-bay facade, and is a half level lower than the main house. The east bay was a door but has been altered into a window

There is one dormer on the north slope of the roof.

In plan, the brick wing is one room with a corner boxed staircase. mantel has been removed. The second floor has been divided into several

rooms; all have simple detailing.

The main house has a central hall with flanking parlors. The east room is divided from the hall by a vertically beaded board partition along which the staircase rises. The boarding continues around the east room as wainscotting. The fireplace has a jack arch over the opening; a molding surrounds the opening and above is a shelf with a bed molding. To the north of the fireplace is an open cupboard with butterfly shelves and an enclosed cupboard.

The room is plastered, The west room has a plaster partition wall. with a chair rail. The fireplace has a wood surround with a molding around the outside edge. The frieze is plain; the shelf has a deep bed molding above a row of fretwork. The corner posts and plates are exposed in this room as well as the hall and east room; the posts and plate have a quirked bead on the exposed edge.

quirked bead on the exposed edge.

On the second floor, there are two rooms on either side of the hall. The partition walls are vertical beaded boards. The east room has a small fireplace; the west room none. The door to the west room is six panelled and the walls plastered. The east room has a door of three beaded boards. The mantel shelf is attached to the wall. The chair rail is a double beaded board with an astragal in the center. The door frames are moldings applied to the partition walls.

Doors throughout the house have six raised ranges and from the content of the partition walls.

Doors throughout the house have six raised panels and iron hardware. Hinges are rat-tail in the main rooms, H or HL for the secondary rooms and strap on the exterior doors. The floors are wide boards.

The wing to the south was added by the previous owners, Mr. Mrs. Counselman. Near the house is a small log smokehouse with an external brick smokestack. The gable ends have horizontal weatherboarding.

1b:

General Description of project and its impact on the historic resources and environmental setting:

Description:

- Replace deteriorated exterior wood and siding with like kind.
- Replace deteriorated chimney on far right of house to meet inspection standards.

 (An inspection revealed this structure does not meet fire safety standards.)
- Replace broken and missing windows and deteriorated window boards with like kind.
- Replace window shutters with like kind, wooden shutters. Currently, some shutters are missing and those remaining are in poor repair.
- Replace deteriorated gutters with like kind.
- Replace missing doors with wooden doors in keeping with the historic nature of the house. Currently temporary doors and boarding are in place for security purposes.
- Replace current roof with cedar shake roofing to restore it to its original state of existence.
- Extend the roof line on the backside of the house (interior of "L" shape) in order to connect previous additions, improving the continuity and flow both of the home's exterior and interior. The proposed addition is a two story, 12W x 20L foot extension which would allow accessibility to areas of the house on the first and second floor and accommodate a half bath on the first floor and a full bath on the second floor. Currently there is no bath on the first floor and no bath designated for the two bedrooms located on the second floor. (See drawings.)
- Extend backside roof line between two existing dormer windows located on the second floor to add continuity with the proposed extension.
- Rebuild smokehouse as closely as possible to its original structure.
- Replace barn windows and boards.

Impact:

The proposed project does not affect the frontage or facade of the property. Therefore, the only impact on the site will be a cosmetic improvement of its appearance. As the attached drawings show, it is our goal to restore this property to its most optimum state, while improving the continuity and flow of the home. Previous additions currently restrict accessibility to many areas, limiting its liveability.

2b.

ATTACHMENT 2: Statement of project intent

2a. Proposed design in terms of scale, massing, materials, details:

We are proposing a 12' x 20' addition, two stories in height, to be tucked into the rear corner between the main house and rear wing and expansion of the dormers adjoining the addition area.

Proposed design of addition will not extend above existing roof lines. Addition will blend with existing house in materials and details. Addition will only be visible from rear of property and will not overwhelm the mass of the structure.

The relationship of the design to the existing resources:

The size of the structure will only be increased by 15 percent to accommodate a 12 x 20 addition.

All work to be completed on the front facade of the property is cosmetic in nature and will not alter existing resources, with the exception of the cedar shake roof which will restore the roof to its original appearance.

The project will not be visible from the front of the existing structure.

The addition is designed to increase the continuity of the home and will resolve the problem with bathroom usage.

2c. The way in which the proposed work conforms to the specific requirements of the Ordinance (Chapter 24)

The proposed work conforms to all related requirements of the Ordinance.

9000 Brink Road/C. Small C. Leonard Page Four

ATTACHMENT 3: Project Plan (see site plan) Page 5A of drawings.

ATTACHMENT 4: Tree Survey

There are no trees within the project area.

ATTACHMENT 5: Design Features (see drawings) Pages 5B, 5C & 5D

ATTACHMENT 6: Facades (see drawings) Pages 5E & 5F

ATTACHMENT 7: Materials Specifications (for addition and roof)

Wood clapboard siding
Stone veneer on foundation
Half round O.G. type aluminium gutters
Wooden true divided light windows and door
Roofing material to be cedar shakes
Wood facias, soffits, corner boards and crown molding

9000 Brink Road/C. Small C. Leonard Page Five

ATTACHMENT 8: Photos of Resources (see photos)

ATTACHMENT 9: Photos of Context (see photos)


ATTACHMENT 10: Addresses of Adjacent Property Owners


Robert R. & C.A.S. Michael 8921 Brink Road Gaithersburg, Maryland 20882 (Lot 3, Blk T, Goshen Estates)


Mark Moholt 8908 Brink Road Gaithersburg, Maryland 20882 (Lot 6, Fertile Meadows)


Springbrook At Fertile Meadows 15950 Derwood Road Rockville, Maryland 20855 (8920 Brink Road, Lot 7, Fertile Meadows) (9010 Brink Road, Lot 9, Fertile Meadows)


William R. Gorman Jr. 15901 Green Meadow Road Gaithersburg, Maryland 20879 (All remaining lots in Fertile Meadows)















































- 1) Charles W. Small, A. 9884 Main Street P.O. Box 46 Damascue, MD. 2087Z
- (2) Chie Gonard 3362 N. Diekerson St. Arlington, VA. 22207

Robert R. & C.A.S. Michael 8921 Brink Road Gaithersburg, Maryland 20882 (Lot 3, Blk T, Goshen Estates)

Mark Moholt
8908 Brink Road
Gaithersburg, Maryland 20882
(Lot 6, Fertile Meadows)

Springbrook At Fertile Meadows
15950 Derwood Road
Rockville, Maryland 20855
(8920 Brink Road, Lot 7, Fertile Meadows)
(9010 Brink Road, Lot 9, Fertile Meadows)

William R. Gorman Jr.
15901 Green Meadow Road
Gaithersburg, Maryland 20879
(All remaining lots in Fertile Meadows)

(2) Jeff + San Miskin 8820 Huntmaster Guthersburg, MD. 2088Z applicants

adjacent

3 interested

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 9000 Brink Road Meeting Date: 03/23/94

Resource: Fertile Meadows HAWP: Alterations / Addition

(<u>Master Plan</u>Site #14/59)

Case Number: 14/59-94A Tax Credit: Yes/Partial

Public Notice: 03/09/93 Report Date: 03/16/94

Applicant: Charles W. Small, Jr. Staff: Patricia Parker

& Chris Leonard

PROPOSAL: Bathroom Addition/Repair/ RECOMMEND: Approval w/

Rebuild smokehouse condition(s)

This application follows a preliminary consultation before the Commission on February 23, 1994 on a proposal to build a two story 12' by 20' rear addition, rebuild the smokehouse, build a picket fence around the cemetery and replace missing features on Master Plan Site #14/59, Fertile Meadows (copy attached). This work is proposed as part of the applicants' intent to fully restore the 1790's frame and brick farmhouse and use the property as a residence.

Fertile Meadows, a property formerly associated with the Riggs family, contains 3.3 acres including a corncrib/barn, meat house and family cemetery. It was just recently purchased by its present owners, Charles W. Small, Jr. and Chris Leonard.

At the preliminary consultation, Commissioners recommended that the applicants provide more detailed drawings in order that the HPC could carefully review the proposal to add a two story addition at the rear of the property. Commissioners felt a two-story addition is possible; but it should occur below the existing roofline with minimal alteration to the rear facade.

The Commissioners felt they could not approve a new dormer on the front facade, as this would be a historically undocumented change to a <u>Master Plan</u> Site. They also felt that existing windows should be repaired; not replaced. The Commissioners would require a fence to be installed - to mark and preserve the existing cemetery. The roofing material may be cedar shakes rather than metal. Many of the other proposed improvements were of a nature that a HAWP would not be required. The applicants were informed that they did not need an approved HAWP to perform ordinary maintenance or to replace existing historic fabric with **exactly matching** materials.

At an earlier meeting on July 7, 1993, the HPC discussed a subdivision proposal involving Fertile Meadows and forwarded certain recommendations to the Planning Board to provide protection for the property (copy attached).

STAFF DISCUSSION/BACKGROUND

Staff feels that this application should be approved. Staff applauds the applicants on their proposal to both restore the property and place it in immediate residential use. The applicants have expressed a desire to restore the property with care and attention deserving of a <u>Master Plan</u> Site. Staff feels that the overall concept of the addition and alterations are consistent with the Secretary of the Interior's Standards for Rehabilitation. Therefore, the focus of the discussion of this application shall be with attention to detail.

The applicants propose a 12' x 20' rear block addition of wood clapboard to match the main house, two stories in height, to be tucked into the rear ell between the main house and wing. The proposed addition would be to ease existing difficult circulation patterns. The house presently has only one bath on the second floor. First floor guests must go through the dining room and kitchen and up the back stair to get to the bath. The drawings indicate the proposed use of half-round ogee type aluminum gutters, 3" round aluminum downspouts, wood clapboard siding and wood windows with 6/6 true divided light.

The proposal further includes a change in ceiling height in the master bedroom at the second level effected through combining and expanding two existing dormers on the rear elevation. Staff feels that the addition which occurs below the ridge of the main block and is continuous across the area enclosing the master bedroom is approvable. The drawing is a bit confusing - possibly because there is no valley indicated to show the area involving the changed dormers as an ell extension confined to the second floor of the two story addition. The applicants propose change to the dormers as a solution for a very low ceiling height in the master bedroom. The dormers would be clad in wood clapboard siding (matching the siding of the main block) with wood windows 6/6 true divided light.

The applicants indicate in the proposal the intent to match new windows in the addition with the existing windows. However, staff feels that it is important for the applicants to submit a manufacturer's sample of the proposed windows. Staff can then determine whether the windows are identical in size, configuration and muntin profile.

Likewise, staff feels that the proposal to replace any other windows in the structure requires submission of specifications and a manufacturer's sample. Repair of existing fabric is preferable; rather than replacement. Staff needs to know, window-by-window, what the applicants propose for alteration. Staff sug-

gests that the applicants submit a plan to include a window schedule with each window numbered. The window schedule would list the proposed treatment keyed to the drawings.

The proposal indicates that the applicants intend to replace the barn windows. Repair of the windows should be attempted first. If the windows can not be repaired; then replacement may be necessary. Again, the applicants should submit specifications and a manufacturer's sample to determine compatibility.

The applicants have included in their application replacement of existing historic fabric with like kind materials, i.e. exterior wood and wood siding, wood window jambs, wood window shutters, ogee aluminum gutters, missing wood doors and barn boards. The applicants do not need an approved HAWP to replace the materials with exactly matching materials. Much of this work falls under ordinary maintenance. Staff is however pleased that the applicants have chosen to include a full report of all work proposed for the historic property.

As a note of caution, staff would recommend that the applicants confine the replacement of exterior wood and wood siding to only those boards that are beyond repair for both the main house and the barn.

The HPC discussed the change in existing roofing material with the applicants at the preliminary consultation. HPC Commissioners generally agreed that the house when built probably had a cedar shake roof; and not the corrugated metal roofing it has at present. Therefore the applicants' proposal to install a cedar shake roof can be approved.

The applicants propose rebuilding the masonry chimney at the end of the living room to conform to present building code requirements. Standard brick is proposed. Staff feels that the rebuilding of the chimney to the same height, cap design and built to match the other chimneys can be approved.

Staff feels that the 12' \times 12' smokehouse can be rebuilt using photographic documentation and re-using any logs in good condition. In fact, some of the remaining logs may help to determine the building technique used to build the smokehouse at that time.

The proposed project does not indicate any grade changes or removal of live trees. The proposal does include a fence to enclose, mark and preserve the cemetery. Other than the rebuilding of the chimney and re-roofing, all change is confined to the rear of the property.

STAFF RECOMMENDATION

Staff feels that the proposed project does not affect the principal facade of Fertile Meadows. Staff feels that the appli-

cants have kept the proposed addition small and that it does not negatively impact on the historic site. Further, that there are no trees or landscape specimens involved in the proposal. Therefore, with the following conditions, staff recommends that the Commission find the proposal consistent with the purposes of Chapter 24A-8(b)1:

The proposal will not substantially alter the exterior features of an historic site, or historic resource within an historic district;

and with the Secretary of the Interior's Standards for Rehabilitation #1, #2, #3, #6, #9 and #10:

A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment;

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided;

Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historic development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken;

Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence;

New additions, exterior alterations, or related new con struction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectureal features to protect the historic integrity of the property and its environment; and


New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired;

and with the following condition(s):

1. The applicants should first attempt repair of the window jambs and window units. If windows and/or framing in any of the

structures are beyond repair, the applicant should submit specifications and actual manufacturer's window samples prior to approval of the application.

- 2. The applicants shall submit a window schedule indicating the proposed treatment for each window for all structures. This schedule should be keyed to the drawings.
- 3. The applicants shall attempt to first repair historic fabric replacing only the clapboard and other siding that is beyond repair.



Historic Preservation Commission

51 Monroe Street, Suite 1001, Rockville, Maryland 20850 217-3625

APPLICATION FOR HISTORIC AREA WORK PERMIT

NAME OF PROPERTY OWNER	arksWmall(r.	TELEPHONE NO. 30 1-25	3- <i> 534</i> _
Wher (Contract/Purchaser) Chris	s hearned	(Include Area Code)	
ADDRESS 9884 Mainst PORO	146 Darroscus Ma	md	20872
CONTRACTOR Joe + I cons	truetion	TELEPHONE NO. 301-953	-2470
DIVINACION	CONTRACTOR REGISTRATI	ON NUMBER 12578	e de la companya de l
LANS PREPARED BY Charle	sword Nr.	TELEPHONE NO. 301-25	3-1554
approximately a local angular superference of the section of the section of	REGISTRATION NUMBER	(Include Area Code)	
LOCATION OF BUILDING/PREMISE			
House Number 9000	Street Brink Rd	and the second s	Annual and the second s
Town/City Gaithersbur	•••	ction District	E. William St. Communication
Nearest Cross Street Goshen	· · · · · · · · · · · · · · · · · · ·		
Lot 8 Block	Subdivision <u>Fertile</u>	Meadows	
Liber Folio	Parcel		
IA. TYPE OF PERMIT ACTION: (Construct Extend/Add	Alter/Renovate W. Repair	Circle One: A/C Slab Porch Deck Fireplace She Fence/Wall (complete Section 4) (_
	nstall Revocable Revision	Fence/Wall (complete Section 4) 1	otner
IB. CONSTRUCTION COSTS EST	IMATES 30,000	<u> </u>	
	• •		
1C IF THIS IS A DEVISION OF A	PREVIOUSLY APPROVED ACTIVE	PERMIT SEE PERMIT #	
IC IF THIS IS A DEVISION OF A	PREVIOUSLY APPROVED ACTIVE RIC UTILITY COMPANY Percent	PERMIT SEE PERMIT #	
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT	RIC UTILITY COMPANY #	PERMIT SEE PERMIT #	
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO	RIC UTILITY COMPANY TEPCO RICAL SITE? YES	•	
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C	RIC UTILITY COMPANY HEPCO RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI	TIDNS	
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C ZA. TYPE OF SEWAGE DISPOSA	RIC UTILITY COMPANY HEPCO RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI	TIDNS 2B. TYPE DF WATER SUPPLY	·
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT 01 () WSSC 02 (>4)	RIC UTILITY COMPANY HEPCO RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀) W	·
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSA	RIC UTILITY COMPANY HEPCO RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI	TIDNS 2B. TYPE DF WATER SUPPLY	·
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSAL 01 () WSSC 02 (>= 03 () Other PART THREE: COMPLETE ONLY FO	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀) W	·
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSAL 01 () WSSC 02 (> 03 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL Linches	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (×) W(03 () Other	·
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSAL 01 () WSSC 02 (> 03 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet Indicate whether the fence or r	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other	·
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT O1 () WSSC O2 (> O3 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet Indicate whether the fence or r 1. On perty line/Property line	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other	·
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C A. TYPE OF SEWAGE DISPOSA O1 () WSSC O2 (> O3 () Other PART THREE: COMPLETE ONLY FO AA. HEIGHTfeet Indicate whether the fence or r 1. On party line/Property line 2. Entirely on land of owner.	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL Linches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (x/) Wi 03 () Other	elt
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C A. TYPE OF SEWAGE DISPOSA O1 () WSSC O2 (> O3 () Other PART THREE: COMPLETE ONLY FO AA. HEIGHTfeet Indicate whether the fence or r 1. On party line/Property line 2. Entirely on land of owner	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (x/) Wi 03 () Other	elt
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO A. TYPE OF SEWAGE DISPOSAT O1 () WSSC O2 (> O3 () Other	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (x/) Wi 03 () Other	all
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT O1 () WSSC O2 (> O3 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet 1. On party line/Property line 2. Entirely on land of owner 3. On public right of way/ease	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other e of the following locations: (Revocable Letter Required).	ell
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT 01 () WSSC 02 (> 03 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet 4B. Indicate whether the fence or r 1. On perty line/Property line 2. Entirely on land of owner . 3. On public right of way/ease	RIC UTILITY COMPANY FEACE RICAL SITE? YES ONSTRUCTION AND EXTEND/ADDI L Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 WI 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per	he construction will comply wi
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT OI () WSSC O2 (> O3 () Other	RIC UTILITY COMPANY RICAL SITE? ONSTRUCTION AND EXTEND/ADD Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on ement prity to make the foregoing application I hereby acknowledge and accept this	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per	he construction will comply wi
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT OI () WSSC O2 (>CO O3 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet 1. On party line/Property line 2. Entirely on land of owner . 3. On public right of way/ease I hereby certify that I have the authorized ager Signature of owner or authorized ager	RIC UTILITY COMPANY RICAL SITE? ONSTRUCTION AND EXTEND/ADD Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on ement prity to make the foregoing application I hereby acknowledge and accept this at (agent must have signature notarized)	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per march /	he construction will comply wi
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT O1 () WSSC O2 (>C) O3 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet 1. On party line/Property line 2. Entirely on land of owner . 3. On public right of way/ease I hereby certify that I have the authorized ager Signature of owner or authorized ager	RIC UTILITY COMPANY RICAL SITE? ONSTRUCTION AND EXTEND/ADD Septic R FENCE/RETAINING WALL inches etaining wall is to be constructed on on ement prity to make the foregoing application I hereby acknowledge and accept this	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per march /	he construction will comply w
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSA 01 () WSSC 02 (> 03 () Other	RICAL SITE?	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (x) Woods (x) Other	he construction will comply wi
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW C 2A. TYPE OF SEWAGE DISPOSA 01 () WSSC 02 (> 03 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHTfeet 4B. Indicate whether the fence or r 1. On party line/Property line 2. Entirely on land of owner . 3. On public right of way/ease I hereby certify that I have the author plans approved by all agencies listed and Signature of owner or authorized ager APPROVED	RICAL SITE?	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 (x) Woods (x) Other	the construction will comply wimit.
IC. IF THIS IS A REVISION OF A ID. INDICATE NAME OF ELECT IE. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT OF A COMPLETE ONLY FO INDICATE OF A COMPLETE ONLY FO	RICAL SITE?	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 W 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per March / on back) rvation Commission Oate	he construction will comply wi mit.
1C. IF THIS IS A REVISION OF A 1D. INDICATE NAME OF ELECT 1E. IS THIS PROPERTY A HISTO PART TWO: COMPLETE FOR NEW CO 2A. TYPE OF SEWAGE DISPOSAT 01 () WSSC 02 (> 03 () Other PART THREE: COMPLETE ONLY FO 4A. HEIGHT feet 1. On party line/Property line 2. Entirely on land of owner 3. On public right of way/ease I hereby certify that I have the author plans approved by all agencies listed and Signature of owner or authorized ager Signature of owner or authorized ager APPROVED	RICAL SITE?	TIDNS 2B. TYPE DF WATER SUPPLY 01 () WSSC 02 🔀 Will 03 () Other e of the following locations: (Revocable Letter Required). n, that the application is correct, and that to be a condition for the issuance of this per on back) rvation Commission Oate FILING FEE: \$	he construction will comply wi mit.

ATTACHMENT 1: Written Description of Project

Description of existing structures and environmental setting. 12. including their historical features and significance:

- Fertile Meadows is an excellent example of a late 18th century farm house. The property is associated with the Riggs family, prominent in

أواله أأوع المعمولين

Montgomery County history.
In 1743 Benjamin Wallingford was granted the land upon which Fertile Meadows now sits, calling it "Benjamin's Square". Some years later the land was resurveyed and a mill was built where the road from Laytonsville to Clarksburg crosses Goshen Branch, providing the nearby town with its name, Goshen Mills. Joshua Pigman came into possession of a part of the Resurvey on Benjamin Square and it is believed that he built the Fertile Meadows house on the hill overlooking the mill sometime before 1792. In that year he sold the land, and improvements, and the house passed through several owners before being purchased by George Washington Riggs in 1819.

George Riggs was a self-made man. He started out as a silversmith i Georgetown and soon had a thriving business. In 1820, the year after he purchased Fertile Meadows, he had a license to be a storekeeper in Montgomery County, and eventually he moved to Baltimore where he became an exporter in the lucrative tobacco trade. He purchased several other larg

expensive tracts of land in the county.

Several other parties owned Fertile Meadows before the Counselmans bought it in 1934. Lee Counselman had been a finance expert in Detroit a had helped organize several auto firms. Mrs. Counselman had been a fashio

model Fertile Meadows in 1934 had been spared the threat of "modernization retained its primitive atmosphere while and the Counselmans successfully retained its primitive atmosphere while making the house livable.

The name "Fertile Meadows" came from a small tract which made up part of the original farm.

The house is a one-and-one-half story structure, the west end of which is frame; the east end is brick on the first floor and frame above. At the east end is a one-story brick chimney with a free-standing stack. The frame section has an internal chimney where it adjoins the brick wing, and an external one-story chimney on the west end, with a narrow, free-standing stack. The frame section is five bays with a central doorway and a fourlight transom. The windows are nine-over-nine double hung sash. The steep "A" roof is broken by three dormer windows on the main facade. The sheathing is clapboard and the cornice boxed with an ogee bed molding. On the gable sides, there is a fascia with a wide bead.

The brick section has a two-bay facade, and is a half level lower than the main house. The east bay was a door but has been altered into a window

There is one dormer on the north slope of the roof.

In plan, the brick wing is one room with a corner boxed staircase. mantel has been removed. The second floor has been divided into several

rooms; all have simple detailing.

The main house has a central hall with flanking parlors. The east room is divided from the hall by a vertically beaded board partition along which the staircase rises. The boarding continues around the east room as wainscotting. The fireplace has a jack arch over the opening; a molding surrounds the opening and above is a shelf with a bed molding. To the north of the fireplace is an open cupboard with butterfly shelves and an enclosed cupboard.

The west room has a plaster partition wall. The room is plastered. with a chair rail. The fireplace has a wood surround with a molding around the outside edge. The frieze is plain; the shelf has a deep bed molding above a row of fretwork. The corner posts and plates are exposed in this room as well as the hall and east room; the posts and plate have a

quirked bead on the exposed edge.

On the second floor, there are two rooms on either side of the hall. The partition walls are vertical beaded boards. The east room has a small fireplace; the west room none. The door to the west room is six panelled and the walls plastered. The east room has a door of three beaded boards. The mantel shelf is attached to the wall. The chair rail is a double beaded board with an astragal in the center. The door frames are moldings applied to the partition walls.

Doors throughout the house have six raised panels and iron hardware. Hinges are rat-tail in the main rooms, H or HL for the secondary rooms and



1b:

General Description of project and its impact on the historic resources and environmental setting:

Description:

- Replace deteriorated exterior wood and siding with like kind.
- Replace deteriorated chimney on far right of house to meet inspection standards.

 (An inspection revealed this structure does not meet fire safety standards.)
- Replace broken and missing windows and deteriorated window boards with like kind.
- Replace window shutters with like kind, wooden shutters. Currently, some shutters are missing and those remaining are in poor repair.
- Replace deteriorated gutters with like kind.
- Replace missing doors with wooden doors in keeping with the historic nature of the house. Currently temporary doors and boarding are in place for security purposes.
- Replace current roof with cedar shake roofing to restore it to its original state of existence.
- Extend the roof line on the backside of the house (interior of "L" shape) in order to connect previous additions, improving the continuity and flow both of the home's exterior and interior. The proposed addition is a two story, 12W x 20L foot extension which would allow accessibility to areas of the house on the first and second floor and accommodate a half bath on the first floor and a full bath on the second floor. Currently there is no bath on the first floor and no bath designated for the two bedrooms located on the second floor. (See drawings.)
- Extend backside roof line between two existing dormer windows located on the second floor to add continuity with the proposed extension.
- Rebuild smokehouse as closely as possible to its original structure.
- Replace barn windows and boards.

Impact:

The proposed project does not affect the frontage or facade of the property. Therefore, the only impact on the site will be a cosmetic improvement of its appearance. As the attached drawings show, it is our goal to restore this property to its most optimum state, while improving the continuity and flow of the home. Previous additions currently restrict accessibility to many areas, limiting its liveability.

ATTACHMENT 2: Statement of project intent

2a. Proposed design in terms of scale, massing, materials, details:

We are proposing a 12' x 20' addition, two stories in height, to be tucked into the rear corner between the main house and rear wing and expansion of the dormers adjoining the addition area.

Proposed design of addition will not extend above existing roof lines. Addition will blend with existing house in materials and details. Addition will only be visible from rear of property and will not overwhelm the mass of the structure.

2b. The relationship of the design to the existing resources:

The size of the structure will only be increased by 15 percent to accommodate a 12 x 20 addition.

All work to be completed on the front facade of the property is cosmetic in nature and will not alter existing resources, with the exception of the cedar shake roof which will restore the roof to its original appearance.

The project will not be visible from the front of the existing structure.

The addition is designed to increase the continuity of the home and will resolve the problem with bathroom usage.

2c. The way in which the proposed work conforms to the specific requirements of the Ordinance (Chapter 24)

The proposed work conforms to all related requirements of the Ordinance.

ATTACHMENT 3: Project Plan (see site plan) Page 5A of drawings.

ATTACHMENT 4: Tree Survey

There are no trees within the project area.

ATTACHMENT 5: Design Features (see drawings) Pages 5B, 5C & 5D

ATTACHMENT 6: Facades (see drawings) Pages 5E & 5F

ATTACHMENT 7: Materials Specifications (for addition and roof)

Wood clapboard siding
Stone veneer on foundation
Half round O.G. type aluminium gutters
Wooden true divided light windows and door
Roofing material to be cedar shakes
Wood facias, soffits, corner boards and crown molding

9000 Brink Road C. Leonard Page Five

ATTACHMENT 8: Photos of Resources (see photos)

ATTACHMENT 9: Photos of Context (see photos)


ATTACHMENT 10: Addresses of Adjacent Property Owners


Robert R. & C.A.S. Michael 8921 Brink Road Gaithersburg, Maryland 20882 (Lot 3, Blk T, Goshen Estates)

Mark Moholt 8908 Brink Road Gaithersburg, Maryland 20882 (Lot 6, Fertile Meadows)

Springbrook At Fertile Meadows 15950 Derwood Road Rockville, Maryland 20855 (8920 Brink Road, Lot 7, Fertile Meadows) (9010 Brink Road, Lot 9, Fertile Meadows)

William R. Gorman Jr. 15901 Green Meadow Road Gaithersburg, Maryland 20879 (All remaining lots in Fertile Meadows)





Page 58

Date March I,

Scale &"- "0"


Fertile Meadous

Charles WSmal


9884 Main St.

PO Box 46


Damascus Md




Second Floor Plan








Existing Right Side Elevation



Proposed Right Side Elevation with Addition

Page SF
Date murch
Scale \$">1"C
Fertile Meador
Chorks WS N
9884 main 5
Po Box 46

Trenmering



Po

SUPPLEMENTAL APPLICATION FOR HISTORIC AREA WORK PERMIT **REQUIRED ATTACHMENTS**

PROPERTY:


9000 Brink Road; Lot 8, Fertile Meadows Subdivision, per Plat Book 171 at Plat 19214


OWNERS:


Charles Small, Jr. (301) 253-1012


Chris Leonard (301) 330-8982


Submitted: March 1, 1994


























Commission of the State of the























HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 9000 Brink Road Meeting Date: 02/23/94

Resource: Fertile Meadows Preliminary Consultation

Case Number: N/A Tax Credit: Yes/Partial

Public Notice: 02/09/93 Report Date: 02/16/94

Applicant: Charles W. Small, Jr. Staff: Patricia Parker

& Chris Leonard

PROPOSAL: Addition/Alterations/ RECOMMEND: Further study

Rebuild smokehouse

(Master Plan Site #14/59)

This application is to obtain the Commission's recommendations on 1) the full restoration of Fertile Meadows (Master Plan Site #14/59); 2) a new rear ell-shaped addition; 3) the addition of a dormer window on the front facade; 4) a proposal for new landscaping; and 5) the rebuilding of a seriously neglected outbuilding - the smokehouse - to its earlier condition.

Fertile Meadows was just recently purchased by Charles Small, Jr. and Chris Leonard. It is a 1790 frame and brick house, formerly associated with the Riggs family. The property, of 3.3 acres includes a corncrib/barn, meat house and family cemetery.

The HPC discussed a subdivision proposal involving this Master Plan site on July 7, 1993 (copy attached). At that meeting, the HPC forwarded recommendations to the Planning Board to approve the subdivision proposal but with certain protections for Fertile Meadows. The HPC recommended that the subdivision proposal address the following concerns: 1) the environmental setting be enlarged to 3.3 acres for the main house and outbuildings; 2) protection of the vista of the main house through the creation of a building restriction line on an adjacent lot #3 3) protection of as many cedars as possible along the frontage of the property and the addition of cedars at the entrance to the driveway; 4) monitor the design of the new house adjacent to the property on Lot #1; and most importantly, post and protect all openings for the house and barn.

The applicants now seek the Commission's input on ways to protect and enhance the historicity of the property.

STAFF DISCUSSION

Staff applauds the applicants for their immediate attention to the restoration of Fertile Meadows and its appurtenances. The applicants have listed various suggested improvements to the property. Staff considers many to fall under the category of ordinary maintenance. The applicants do not need an approved HAWP to replace roofs, gutters, trim, lights and exterior doors and windows with **exactly matching** materials. Nor does the applicant need an approved HAWP for ordinary maintenance.

However, other parts of the proposal do fall within the purview of this Commission's approval. They are:

One - Proposed addition and new dormer: The applicants intend to submit an HAWP for this property, with carefully prepared and detailed drawings to show the addition. However, for discussion purposes, the applicants want the Commission to inform them of parameters that should be considered in the building of an addition to the historic property.

Staff feels that a rear ell-shaped addition is possible for this property provided that the size and mass of the addition is appropriate. Another issue will be the evaluation of the proposed connection of new construction to the old. New work should be differentiated from the old.

The applicants submitted an outline showing the footprint of the structure including the proposed 22' wide by 12' deep two-story addition and the proposed dormer expansion. Note: Staff is very concerned about the applicants' proposal to construct a two-story addition. Staff feels that any new addition should be below the existing roofline - even though this addition is completely to the rear of the property.

Staff feels that the applicants should submit interior floor plans and full elevations of all building facades. These drawings should differentiate work proposed from the existing. Staff is reticent to recommend approval of the addition without this information.

Windows in the proposed addition should have a configuration similar to the existing structure. Materials should match the existing as closely as possible.

Two - Removal of a dead tree: The applicants must provide a letter from an arborist certifying that the tree is dead. If that information is provided, it will not be necessary for the Commission to review the proposal.

Three - Replacement of windows: The proposal to replace windows in a structure of this period requires close scrutiny. The proposed window unit must be the same in configuration and muntin profile and thickness. Windows should be wood double-hung

of true divided light set in wood framing. The configuration of the windows must be the same as the existing, in most cases, 9/9. They must be **exactly** the same as the 1790's windows.

The applicants propose to replace windows and openings with in-kind materials. Staff will require a sample window from the manufacturer for approval. Staff has included an ACHS Summary Form for description.

Four - New roofing: Staff feels that the roof may have been cedar shake. Staff will require the applicants to provide documentation. If such documentation is not available, then we encourage the owners to provide metal roofing. Staff reminds the applicants that tax credits are available for approved restoration efforts.

<u>Five</u> - Rebuilding the smokehouse: Staff is pleased to see within this proposal that the applicants have chosen to rebuild the smokehouse. The applicants have indicated their desire to find the appropriate species and proper sizes of logs to rebuild the structure. They have also researched log construction techniques. Staff is not certain whether the applicants intend to hire construction professionals or take on the task themselves.

 $\underline{\text{Six}}$ - Landscaping proposals - The applicants should submit a landscaping plan, with schedules so that staff can evaluate any proposals for new plantings.

The applicants propose to replace missing boards and windows in the barn structure. Applicants have indicated to staff that they intend to replace in-kind. Therefore, no HAWP will be necessary to address this issue.

STAFF RECOMMENDATION

In the staff's judgement, the majority of the proposal is not problematic. Much of the proposal includes work for which no HAWP will be necessary. However, staff feels the proposal describing the two-story addition and the addition of a dormer window on the front facade requires further study. The staff would be pleased to review detailed plans and elevations with material specifications for these two projects.

Secondly, staff must be provided with a sample window unit from the manufacturer for approval of the proposal to replace the 1790's windows.

January 24, 1994

Ms. Patricia Parker
Design Zoning and Preservation
8787 Georgia Ave.
Silver Spring, MD 20910

Dear Ms. Parker:

This letter is written to request a preliminary hearing on February 9, 1994, for the restoration and renovation of the property located at 9000 Brink Road. The property is recorded as Lot 8 in the subdivision known as Fertile Meadows as per Plat Book 171 at Plat 19214.

As the attached proposed restoration/renovation activities and drawings show, it is our goal to restore this property to its most optimum state, while improving its continuity and flow. Previous additions currently restrict accessibility to many areas, limiting its liveability.

Thank you for your consideration in this matter. Please let us know if you have any recommendations or need more information.

Sincerely,

Charles Small, Jr. (301) 253-1012

Chris Leonard (301) 330-8982

Attachments

Proposed Restoration/Renovation Activities

Property:

9000 Brink Road; Lot 8, Fertile Meadows Subdivision, per Plat Book 171 at

Plat 19214


• Immediately remove a dead tree which is currently a hazard due to its proximity to the front of the house.

- Replace deteriorated exterior wood and siding with like kind.
- Replace deteriorated chimney on far right of house to meet inspection standards.

 (All chimneys were inspected, and this particular one was the only one that did not meet fire safety standards.)
- Replace windows and window boards with like kind. Several window are broken and the wood is deteriorated in many areas. Replacement windows, while similar in appearance the original windows, will provide improved insulation in the interest of energy conservation.
- Replace window shutters with like kind, wooden shutters. Currently, some shutters are missing and those remaining are in poor repair.
- Replace deteriorated gutters with like kind.
- Replace missing doors with wooden doors in keeping with the historic nature of the house. Currently temporary doors and boarding are in place for security purposes.
- Replace current roof with historic-type cedar shake roofing. We have been told that this particular home had a cedar shake roof at one time. The current tin roof is in need of repair, and we feel as though a cedar shake roof would add greatly to the preservation of the home to its most attractive state of existence.
- Extend the roof line on the backside of the house (interior of "L" shape) in order to connect previous additions, improving the continuity and flow both of the home's exterior and interior. The proposed addition is a two story, 12W x 22L foot extension which would allow accessibility to areas of the house on the first and second floor and accommodate a half bath on the first floor and a full bath on the second floor. Currently there is no bath on the first floor and no bath designated for the two bedrooms located on the second floor. (See drawing.)
- Extend backside roof line between two existing dormer windows located on the second floor to add continuity with the proposed extension. (See drawing.)

Proposed Restoration/Renovation Property: 9000 Brink Road Page Two


- Add one dormer window to the far left of the front of the house which would match existing windows and provide improved continuity to the home's exterior.
- Install small shrubbery and landscaping to improve the appearance of the property.
- Rebuild smokehouse, as requested by the historical society.
- Replace barn windows and boards.




Proposed-Dermer Expansion Proposed Addition

Real Elevation

 (θ)



Right Side Elevation



ACHS SUMMARY FORM

)
•

Name: Fertile Meadows

2.	Planning Area/Site Number: 1	4/59	3. M-NCPPC Atlas Reference: Map 8 Coordinate C-10
4.	Address: 9000 Brink Rd. Laytonsville, Md.		
5.	Classification Summary .		
	Category building Ownership private Public Acquisition N/A Status occupied Accessible no Present use private resi	dence	Previous Survey Recording MNCPPC Title and Date: Historic Sites Invent 1976 Federal State x County x Local
6.	Date: c. 1790	7. Orig	inal Owner: Joshua Pigman
8.	Apparent Condition		
	a. excellent b.	altered	c. original site

9. Description: The house is a $l\frac{1}{2}$ story structure, the west end of which is frame; the east end is brick on the first floor and frame above. At the end is a one-story brick chimney with a free-standing stack. The frame s tion has an internal chimney where it adjoins the brick wing, and and ext nal one-story chimney on the west end, with a narrow, free-standing stack The frame section is five bays with a central doorway and a four-light tr The windows are nine-over-nine double-hung sash. The steep "A" roc broken by three dormer windows on the main facade. The sheathing is clar board and the cornice boxed with an ogee bed molding. On the gable sides there is a fascia with a wide bead.

The brick section has a two-bay facade, and is a half level lower th the main house. The east bay was a door but has been altered into a wind There is one dormer on the north slope of the roof.

Near the house is a small log smokehouse with an external brick smok stack. The gable ends have horizontal weatherboarding.

The Fertile Meadows is an excellent example of a later 18th century farm house. The property is associated with the Riggs family, prominent Montgomery County history.

In 1743 a large tract was granted to Benjamin Wallingford and befor ϵ 1792 Joshua Pigman bought the land and built a house on a hill overlookir a mill.

That year he sold the land. The house had several owners before bei

purchased by George Washington Riggs in 1819.

George Riggs was a self-made man. He started out as a silversmith i Georgetown and soon had a thriving business. In 1820, the year after he purchased Fertile Meadows, he had a license to be a storekeeper in Montgo County, and eventually he moved to Baltimore where he became an exporter the lucrative tobacco trade. He purchased several other large, expensive tracts of land in the county.

George gave his son Remus a small farm in 1859 and in 1864 sold him acres, including Fertile Meadows. Remus farmed the land while selling of parcels, and in 1901 gave the remaining 60 acres to his wife. His son Ge sold the house in 1912. It changed hands several times before being bou

by Lee Counselman, a finance expert from Detroit.
11. Researcher and date researched: Donald M. Leavitt/7/79 Mike Dwyer/Arch. I

12. Compiler: Gail Rothrock 13. Date Compiled: 10/79 14. Des

7 DESCRIPTION

CONDITION

CHECK ONE

CHECK ONE

TEXCELLENT

_DETERIORATED

_UNALTERED

LORIGINAL SITE

__GOOD

 _MOVED DATE___

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The house is a one-and-one-half story structure, the west end of whi is frame; the east end is brick on the first floor and frame above. At t east end is a one-story brick chimney with a free-standing stack. The frame section has an internal chimney where it adjoins the brick wing, ar an external one-story chimney on the west end, with a narrow, free-standistack. The frame section is five bays with a central doorway and a four-light transom. The windows are nine-over-nine double hung sash. The standard roof is broken by three dormer windows on the main facade. The sheathing is clapboard and the cornice boxed with an ogee bed molding. On the gable sides, there is a fascia with a wide bead.

The brick section has a two-bay facade, and is a half level lower the main house. The east bay was a door but has been altered into a wind There is one dormer on the north slope of the roof.

In plan, the brick wing is one room with a corner boxed staircase. mantel has been removed. The second floor has been divided into several rooms; all have simple detailing.

The main house has a central hall with flanking parlors. The east room is divided from the hall by a vertically beaded board partition alor which the staircase rises. The boarding continues around the east room a wainscotting. The fireplace has a jack arch over the opening; a molding surrounds the opening and above is a shelf with a bed molding. To the north of the fireplace is an open cupboard with butterfly shelves and an enclosed curboard.

The west room has a plaster partition wall. The room is plastered, with a chair rail. The fireplace has a wood surround with a molding around the outside edge. The frieze is plain; the shelf has a deep bed molding above a row of fretwork. The corner posts and plates are exposed in this room as well as the hall and east room; the posts and plate have quirked bead on the exposed edge.

On the second floor, there are two rooms on either side of the hall The partition walls are vertical beaded boards. The east room has a smalfireplace; the west room none. The door to the west room is six panelle and the walls plastered. The east room has a door of three beaded board. The mantel shelf is attached to the wall. The chair rail is a double beaded board with an astragal in the center. The door frames are moldin applied to the partition walls.

Doors throughout the house have six raised panels and iron hardware Hinges are rat-tail in the main rooms, H or HL for the secondary rooms a strap on the exterior doors. The floors are wide boards.

The wing to the south has been added by the present owners.

Near the house is a small log smokehouse with an external brick smokestack. The gable ends have horizontal weatherboarding.

PERIOD

工1700-1799

__1800-1899

_1900-

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

1020\$2231.

_PREHISTORIC _ARCHEOLOGY-PREHISTORIC __COMMUNITY PLANNING __1400-1499 __ARCHEOLOGY-HISTORIC __AGRICULTURE _1500-1599 _1600-1699 **XARCHITECTURE**

__COMMERCE

__COMMUNICATIONS

_CONSERVATION _ECONOMICS __EDUCATION

__INDUSTRY

__INVENTION

The state of the s

_LAW __UTERATURE _MILITARY __MUSIC

__LANDSCAPE ARCHITECTURE

SCULPTURE _SQCIAL/HUMANITARIA _THEATER

__RELIGION

_SCIENCE

_ENGINEERING _EXPLORATION/SETTLEMENT

__PHILOSDPHY __POLITICS/GOVERNMENT

_TRANSPORTATION A_OTHER (SPECIFY) Local Histor

SPECIFIC DATES c. 1790

__ART

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Fertile Meadows is an excellent example of a late 18th century far The property is associated with the Riggs family, prominent in house.

Montgomery County history.

In 1743 Benjamin Wallingford was granted the land upon which Ferti Meadows now sits, calling it "Benjamin's Square". Some years later the land was resurveyed and a mill was built where the road from Laytonsvil to Clarksburg crosses Goshen Branch, providing the nearby town with its name, Goshen Mills. Joshua Pigman came into possession of a part of th Resurvey on Benjamin Square and it is believed that he built the Fertil Meadows house on the hill overlooking the mill sometime before 1792. that year he sold the land, and improvements, and the house passed thr several owners before being purchased by George Washington Riggs in 181

George Riggs was a self-made man. He started out as a silversmith Georgetown and soon had a thriving business. In 1820, the year after h purchased Fertile Meadows, he had a license to be a storekeeper in Mont gomery County, and eventually he moved to Baltimore where he became an exporter in the lucrative tobacco trade. He purchased several other la

expensive tracts of land in the county.

He gave his son Remus a small farm in 1859, 3 and in 1864 sold to his for \$1 all 288 acres of "Goshen Farm and Mills", a parcel that included Fertile Meadows. Although Remus owned the mills he did not run them a Fertile Meadows. Although Remus owned the mills he did not run them a instead farmed. As he grew older he sold off pieces of the land until 1901 when he gave the remaining 60 acres to his wife in consideration o "her promise to take care of me and provide for me for and during my natural life". 5 After Remus' death his son George lived in the house before selling it in 1912.


Several other parties owned Fertile Meadows before the Counselmans bought it in 1934. Lee Counselman had been a finance expert in Detroit had helped organize several auto firms. Mrs. Counselman had been a fash:

model. Fertile Meadows in 1934 had been spared the threat of "modernizati and the Counselmans successfully retained its primitive atmosphere whil making the house livable.


The name "Fertile Meadows" came from a small tract which made up part of the original farm. FOOTNOTES:

- 1. Land Records of Montgomery County, Md., E/167, (4/13/1792).
- 2. Ibid., V/19, (11/13/1819).
 3. Ibid., JGH 7/512, (8/30/1859).
 4. Ibid., EBP 1/97, (2/19/1864).


5. Ibid., TD 17/195. (5/31/1901). 6. Ibid., 230/204. (10/15/1912). CONTINUE ON SEPARATE SHEET IF NECESSARY







Fertile Meadows #14/59 South & West Elevations






















HISTORIC PRESERVATION COMMISSION STAFF REPORT

SITE: Master Plan Site #14/59

<u>DATE:</u> July 7, 1993

Fertile Meadows

CASE NUMBER: #1-88023

TYPE OF REVIEW: Subdivision

PREPARED BY: Patricia Parker

PROPERTY ADDRESS: 9000 Brink

Road

BACKGROUND/DISCUSSION:

This subdivision plan proposes the creation of three lots of 2.3 to 4.3 acres each, including Master Plan Site #14/59, Fertile Meadows - a historic house, appurtenances and cemetery (all on one lot) located on the south side of Brink Road near the Goshen Branch of the Great Seneca Creek Valley. Five lots, further to the east and separated from the historic site by realigned Goshen Road, were previously approved by the Planning Board and houses are currently being constructed on the lots.

Fertile Meadows is a 1790 frame and brick house, associated with the Riggs family (a prominent farming and mercantile family in Montgomery County), with accompanying corncrib/barn, meat house and family cemetery. Fertile Meadows was placed on the Master Plan in 1984 with the entire parcel of 91.38 acres as an environmental setting, to be reduced at the time of subdivision. The HPC reviewed an earlier subdivision proposal in February, 1988 and recommended a combination of three lots as a reduced setting north of the future Goshen Road realignment. This triangular shaped piece would be bounded by the new Goshen Road, Brink Road, and the Goshen Branch stream valley (see attached memo).

On July 8, 1992 the HPC reviewed a Historic Area Work Permit involving the relocation of the corncrib/barn on the property, but the applicant withdrew this proposal before any vote. The staff recommendation was against relocation of the barn because of its value to the site. No mention was made about the deteriorated condition of the meathouse. The Staff Report further recommends "the best preservation plan for this site would be to keep all the resources, including the cemetery, grouped on one lot."

This current subdivision request proposes reducing the environmental setting of Fertile Meadows to 2.3 acres as defined by existing fence lines and including the house, barn, meathouse and cemetery on one lot. It also proposes creating a lot on either side of the historic resource on the south side of Brink Road. The historic setting would have frontage on both Brink

Road and the new Goshen Road (although all structures would be oriented to Brink Road), and all elements of the historic resource would be located on the same parcel. A stream valley buffer would wind across Lot 1, the rear of Lot 2 (the lot containing Fertile Meadows) and portions of the remaining lots.

The County's Department of Transportation (DOT) is requiring substantial road improvements to Brink Road as a condition of this subdivision. The improvements to Brink Road will have a major impact on the setting for Fertile Meadows - specifically, removal of the existing driveway leading to the historic house from Brink Road and replacement with a shared driveway accessing Brink Road further to the east, pavement widening on the north and south shoulders of Brink Road in front of the site, and intrusion into the existing line of cedar trees (see attached plan.) The applicant has worked with DOT and is proposing a retaining wall in front of the historic house as a means of mitigating some of the impact of the road improvements.

Development of the 4.3 acre lot to the west of Fertile Meadows (Lot #1) is also of concern - it is a particularly sensitive area due to the topography of the site and the row of large cedar trees planted along Brink Road which provide a screen and windbreak for the historic site. Access to all the lots would be a shared driveway, and this driveway would have to cut across the front of the historic property to get to Lot #1. The front of the house on Lot #1 will face the historic house, with a vista toward the rear across the stream valley. The new house may be larger than the 1-1/2 story historic resource; but because of the topography, the new house will be placed at a lower elevation.

Finally, the condition of maintenance of the historic site is very poor. In addition to the main house being open and accessible to vandals, the deterioration of the log meathouse, from photos taken in 1984, shows an example of serious neglect which needs to be rectified. The meathouse is a significant part of the setting, and should be restored.

ISSUES:

There are several issues of importance in review of this subdivision proposal. First, the location of a new building restriction line on Lot #3 would require the house to be moved farther southeast behind the line and would maintain a vista for the historic house to Brink Road with less intrusion (see attached plan).

The length of the retaining wall should be increased to adequately protect existing and new cedars to be planted. This wall would help to maintain the existing screening along Brink Road which is an important aspect of the character and setting of the historic property.



The existing driveway entrance from Brink Road to the historic site (which will be closed) should be sensitively filled in and augmented with additional cedars planted at the entrance. The driveway is important to the historic setting, as is preservation of the row of cedars which lines Brink Road. The Secretary of the Interior's Standards #1 and #2 address the issue of altering the site:

A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

Another very important issue is that the house and its appurtenances should be adequately protected. During a recent field visit, staff noted that the house was open and accessible to vandals, window openings had no weather protection, and excessive vegetation and debris has accumulated around the barn/corn crib and house. As noted above, the meathouse is in a state of collapse.

Finally, it would be appropriate to decrease the size of Lot #1 at the streambed and add acreage to Lot #2 by angling southward. This would strengthen the environmental setting and add to its openness by maintaining the semi-rural environment of the house. Due to its proximity and the land topography, the architectural design of the new house on Lot #1 should be fully described so as to ensure that it will complement Fertile Meadows as much as possible.


STAFF RECOMMENDATIONS:


Based on the issues discussed above, staff recommends approval of this subdivision plan with the following conditions:

- o Enlarge Lot #2 to include as much as 1 additional acre for a setting of approximately 3.3 acres for <u>Master Plan</u> Site #14/59 Fertile Meadows, including the house, barn/corncrib, log meathouse and family cemetery.
- O Create a building restriction line on Lot #3, with the new house moved farther to the southeast.
- o Protect all possible cedars along property fronting on Brink Road. This may mean extending the proposed retaining wall to the west as necessary.



- O Add a minimum of two cedars (with size to be set by M-NCPPC Landscape Architect) to the right of driveway entrance as you face Lot #2.
- o Post and protect (board-up) all openings for house and barn. Remove all debris and overgrown vegetation for protection of outbuildings and house.
- o Provide staff with a description of the new house to be built on Lot #1 so as to complement Fertile Meadows. The new house will be very visible from the historic house. This requirement should be met because of the promixity of the new house to the historic setting and land topography.





July 28, 1993

MEMORANDUM

TO:

Joe Davis

Malcolm Shaneman

Development Review Division

FROM:

Gwen Marcus, Historic Preservation Coordinator Patricia Parker, Historic Preservation Planner

Design, Zoning, and Preservation


SUBJECT: Preliminary Plan #1-88023, Fertile Meadows

On July 14, 1993, the Historic Preservation Commission (HPC) met and reviewed several plans of subdivisions involving identified historic resources. This memo summarizes the Commission's concerns on a subdivision which affects <u>Master Plan</u> Site #14/59, Fertile Meadows, and are as follows:


Preliminary Plan #1-88023, Fertile Meadows, which involves <u>Master Plan</u> Site #14/59, Fertile Meadows has been recommended by the HPC for approval with the following conditions:


- 1. All historic structures on the property must be stabilized and maintained to avoid further deterioration. All openings of all structures shall be protected. Debris and overgrown vegetation shall be removed and all improvements shall be posted.
- 2. Lot #2, which includes the historic house, barn/corncrib, log meathouse and family cemetery, must be enlarged to approximately 3.3 acres.
- 3. A building restriction line must be created on Lot #3, east of Lot #2, and should be located starting at the rear corner of the barn/corncrib and angling northeast approximately 45 degrees to the front of the site. This line will revise the proposed location for new construction on Lot #3 (see attached drawing).
- 4. To the extent possible, all existing cedars along the property fronting on Brink Road, shall be protected. This may mean extending the retaining wall to the west, and/or moving the joint driveway to the east as necessary.


- 5. A minimum of two cedars (with size set by M-NCPPC Land-scape Architect) shall be added to the right of the driveway entrance as you face Lot #2.
- 6. Historic preservation planning staff must be provided with a description of the new house to be built on Lot #1 because of land topography and because of the proximity of the new house to the historic setting.



BRINK ROAD -PROPOSED ROAD CROSS SECTIONS







January 24, 1994

Ms. Patricia Parker
Design Zoning and Preservation
8787 Georgia Ave.
Silver Spring, MD 20910

Dear Ms. Parker:

This letter is written to request a preliminary hearing on February 9, 1994, for the restoration and renovation of the property located at 9000 Brink Road. The property is recorded as Lot 8 in the subdivision known as Fertile Meadows as per Plat Book 171 at Plat 19214.

As the attached proposed restoration/renovation activities and drawings show, it is our goal to restore this property to its most optimum state, while improving its continuity and flow. Previous additions currently restrict accessibility to many areas, limiting its liveability.

Thank you for your consideration in this matter. Please let us know if you have any recommendations or need more information.

Sincerely,

Charles Small, Jr. (301) 253-1012

Chris Leonard (301) 330-8982

Attachments

Proposed Restoration/Renovation Activities

Property: 9000 Brink Road; Lot 8, Fertile Meadows Subdivision, per Plat Book 171 at Plat 19214

- Immediately remove a dead tree which is currently a hazard due to its proximity to the front of the house.
- Replace deteriorated exterior wood and siding with like kind.
- Replace deteriorated chimney on far right of house to meet inspection standards.

 (All chimneys were inspected, and this particular one was the only one that did not meet fire safety standards.)
- Replace windows and window boards with like kind. Several window are broken and the wood is deteriorated in many areas. Replacement windows, while similar in appearance the original windows, will provide improved insulation in the interest of energy conservation.
- Replace window shutters with like kind, wooden shutters. Currently, some shutters are missing and those remaining are in poor repair.
- Replace deteriorated gutters with like kind.
- Replace missing doors with wooden doors in keeping with the historic nature of the house. Currently temporary doors and boarding are in place for security purposes.
- Replace current roof with historic-type cedar shake roofing. We have been told that this particular home had a cedar shake roof at one time. The current tin roof is in need of repair, and we feel as though a cedar shake roof would add greatly to the preservation of the home to its most attractive state of existence.
- extend the roof line on the backside of the house (interior of "L" shape) in order to connect previous additions, improving the continuity and flow both of the home's exterior and interior. The proposed addition is a two story, 12W x 22L foot extension which would allow accessibility to areas of the house on the first and second floor and accommodate a half bath on the first floor and a full bath on the second floor. Currently there is no bath on the first floor and no bath designated for the two bedrooms located on the second floor. (See drawing.)
- Extend backside roof line between two existing dormer windows located on the second floor to add continuity with the proposed extension. (See drawing.)

Proposed Restoration/Renovation Property: 9000 Brink Road Page Two

- Add one dormer window to the far left of the front of the house which would match existing windows and provide improved continuity to the home's exterior.
- Install small shrubbery and landscaping to improve the appearance of the property.
- Rebuild smokehouse, as requested by the historical society.
- Replace barn windows and boards.

front Elevation


Real Elevation

Proposed Addition

Proposed Dormer Expension


raposed Addition

Right Side Elevation



CURRENT PROPOSAL

200 No.



HISTORIC PRESERVATION COMMISSION STAFF REPORT

SITE: Master Plan Site #14/59

<u>DATE:</u> July 7, 1993

Fertile Meadows CASE NUMBER: #1-88023

TYPE OF REVIEW: Subdivision

<u>PREPARED BY:</u> Patricia Parker <u>PROPERTY ADDRESS:</u> 9000 Brink

Road

BACKGROUND/DISCUSSION:

This subdivision plan proposes the creation of three lots of 2.3 to 4.3 acres each, including Master Plan Site #14/59, Fertile Meadows - a historic house, appurtenances and cemetery (all on one lot) located on the south side of Brink Road near the Goshen Branch of the Great Seneca Creek Valley. Five lots, further to the east and separated from the historic site by realigned Goshen Road, were previously approved by the Planning Board and houses are currently being constructed on the lots.

Fertile Meadows is a 1790 frame and brick house, associated with the Riggs family (a prominent farming and mercantile family In Montgomery County), with accompanying corncrib/barn, meat house and family cemetery. Fertile Meadows was placed on the Master Plan in 1984 with the entire parcel of 91.38 acres as an environmental setting, to be reduced at the time of subdivision. The HPC reviewed an earlier subdivision proposal in February, 1988 and recommended a combination of three lots as a reduced setting north of the future Goshen Road realignment. This triangular shaped piece would be bounded by the new Goshen Road, Brink Road, and the Goshen Branch stream valley (see attached memo).

On July 8, 1992 the HPC reviewed a Historic Area Work Permit involving the relocation of the corncrib/barn on the property, but the applicant withdrew this proposal before any vote. The staff recommendation was against relocation of the barn because of its value to the site. No mention was made about the deteriorated condition of the meathouse. The Staff Report further recommends "the best preservation plan for this site would be to keep all the resources, including the cemetery, grouped on one

This current subdivision request proposes reducing the environmental setting of Fertile Meadows to 2.3 acres as defined by existing fence lines and including the house, barn, meathouse and cemetery on one lot. It also proposes creating a lot on either side of the historic resource on the south side of Brink Road. The historic setting would have frontage on both Brink

Road and the new Goshen Road (although all structures would be oriented to Brink Road), and all elements of the historic resource would be located on the same parcel. A stream valley buffer would wind across Lot 1, the rear of Lot 2 (the lot containing Fertile Meadows) and portions of the remaining lots.

The County's Department of Transportation (DOT) is requiring substantial road improvements to Brink Road as a condition of this subdivision. The improvements to Brink Road will have a major impact on the setting for Fertile Meadows - specifically, removal of the existing driveway leading to the historic house from Brink Road and replacement with a shared driveway accessing Brink Road further to the east, pavement widening on the north and south shoulders of Brink Road in front of the site, and intrusion into the existing line of cedar trees (see attached plan.) The applicant has worked with DOT and is proposing a retaining wall in front of the historic house as a means of mitigating some of the impact of the road improvements.

Development of the 4.3 acre lot to the west of Fertile Meadows (Lot #1) is also of concern - it is a particularly sensitive area due to the topography of the site and the row of large cedar trees planted along Brink Road which provide a screen and windbreak for the historic site. Access to all the lots would be a shared driveway, and this driveway would have to cut across the front of the historic property to get to Lot #1. The front of the house on Lot #1 will face the historic house, with a vista toward the rear across the stream valley. The new house may be larger than the 1-1/2 story historic resource; but because of the topography, the new house will be placed at a lower elevation.

Finally, the condition of maintenance of the historic site is very poor. In addition to the main house being open and accessible to vandals, the deterioration of the log meathouse, from photos taken in 1984, shows an example of serious neglect which needs to be rectified. The meathouse is a significant part of the setting, and should be restored.

ISSUES:

There are several issues of importance in review of this subdivision proposal. First, the location of a new building restriction line on Lot #3 would require the house to be moved farther southeast behind the line and would maintain a vista for the historic house to Brink Road with less intrusion (see attached plan).

The length of the retaining wall should be increased to adequately protect existing and new cedars to be planted. This wall would help to maintain the existing screening along Brink Road which is an important aspect of the character and setting of the historic property.

The existing driveway entrance from Brink Road to the historic site (which will be closed) should be sensitively filled in and augmented with additional cedars planted at the entrance. The driveway is important to the historic setting, as is preservation of the row of cedars which lines Brink Road. The Secretary of the Interior's Standards #1 and #2 address the issue of altering the site:

A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

Another very important issue is that the house and its appurtenances should be adequately protected. During a recent field visit, staff noted that the house was open and accessible to vandals, window openings had no weather protection, and excessive vegetation and debris has accumulated around the barn/corn crib and house. As noted above, the meathouse is in a state of collapse.

Finally, it would be appropriate to decrease the size of Lot #1 at the streambed and add acreage to Lot #2 by angling southward. This would strengthen the environmental setting and add to its openness by maintaining the semi-rural environment of the house. Due to its proximity and the land topography, the architectural design of the new house on Lot #1 should be fully described so as to ensure that it will complement Fertile Meadows as much as possible.

STAFF RECOMMENDATIONS:

Based on the issues discussed above, staff recommends approval of this subdivision plan with the following conditions:


- o Enlarge Lot #2 to include as much as 1 additional acre for a setting of approximately 3.3 acres for <u>Master Plan</u> Site #14/59 Fertile Meadows, including the house, barn/corncrib, log meathouse and family cemetery.
- o Create a building restriction line on Lot #3, with the new house moved farther to the southeast.
- o Protect all possible cedars along property fronting on Brink Road. This may mean extending the proposed retaining wall to the west as necessary.


- o Add a minimum of two cedars (with size to be set by M-NCPPC Landscape Architect) to the right of driveway entrance as you face Lot #2.
- o Post and protect (board-up) all openings for house and barn. Remove all debris and overgrown vegetation for protection of outbuildings and house.
- o Provide staff with a description of the new house to be built on Lot #1 so as to complement Fertile Meadows. The new house will be very visible from the historic house. This requirement should be met because of the promixity of the new house to the historic setting and land topography.

Front of house To be changed to sotopinas 11A pritad pritzix Aroposed Root Expansion, Detect lives

Roof Frofile

Dotrozens my. Fertile meadows Charleswearth. Great mainst. Po Box 46 400 500 1994 101 = 14 400





9000 Brink Road/C. Small and C. Leonard Page Five

ATTACHMENT 8: Photos of Resources (see photos)

ATTACHMENT 9: Photos of Context (see photos)

ATTACHMENT 10: Addresses of Adjacent Property Owners

Robert R. & C.A.S. Michael 8921 Brink Road Gaithersburg, Maryland 20882 (Lot 3, Blk T, Goshen Estates)

Mark Moholt 8908 Brink Road Gaithersburg, Maryland 20882 (Lot 6, Fertile Meadows)

Springbrook At Fertile Meadows 15950 Derwood Road Rockville, Maryland 20855 (8920 Brink Road, Lot 7, Fertile Meadows) (9010 Brink Road, Lot 9, Fertile Meadows)

William R. Gorman Jr. 15901 Green Meadow Road Gaithersburg, Maryland 20879 (All remaining lots in Fertile Meadows)







