23/57 Falling Green . 1986 -No #

· · · ·



# Montgomery County Covernment

June 12, 1986

Richard T. and L. M. White 3601 Gillis Falls Road Mt. Airy, Maryland 21771

> Survey No.: CR-86-482 Location: 4501 Olney-Latyonsville Rd Date of Inspection: 6/6/86 Inspected By: Michael T. Denney

#### Dear Mr. & Mrs. White:

and the second second

「「「「「「「「「「「「「」」」」」

Our records show that you are the owner of the above referenced property which has been designated an historic site by the Maryland National Capital Park and Planning Commission and is identified as site number 23-57 on the Master Plan for Historic Preservation. This property is protected by Chapter 24A of the Montgomery County Code titled "Preservation of Historic Resources."

An inspection of the property revealed conditions which constitute <u>Demolition by Neglect</u> as defined in Chapter 24A and must be corrected to arrest further deterioration of this valuable historic resource. In Section 24A-9, <u>"Demolition by Neglect"</u> is the failure to provide ordinary and necessary maintenance and repair to an historic site or an historic resource within an Historic District, whether by negligence or willful neglect, purpose or design, by the owner or any party in possession of such a site, which results in any of the following conditions:

- 1. The deterioration of exterior features so as to create or permit a hazardous or unsafe condition to exist.
- 2. The deterioration of exterior walls, roofs, chimneys, windows, the lack of adequate waterproofing, or deterioration of interior features or foundations which will or could result in permanent damage, injury or loss of or to the exterior features.

This is a Notice and Order to correct Demolition by Neglect. Attached to this letter and identified as Addendum "A", consisting of 2 page(s), dated 6/12/86, is a listing and explanation of the exact nature of the repairs, maintenance, and remedial action necessary to stabilize this structure and prevent further deterioration. All repairs must commence and be satisfactorily completed by 7/30/86. This Addendum constitutes a part of this Notice and Order and is incorporated by reference.

> Department of Housing and Community Development Division of Code Enforcement and Home Improvement

Richard T. & L.M. White June 12, 1986 Page 2

In the event the corrective action specified in this Notice and Order is not completed by 7/30/86, the Director of the Department of Housing and Community Development will institute, perform and complete the necessary remedial work to prevent deterioration by neglect. The expenses incurred for such work, labor, and materials shall be a lien against the property, and draw interest at the highest legal rate; the amount to be amortized over a period of ten (10) years subject to a public sale if there is a default in payment.

Furthermore, failure to fully comply with this Notice and Order shall constitute a violation of Chapter 24A of the Montgomery County Code and subject you to a \$250 fine. Each day a violation continues to exist shall constitute a separate offense.

Should you wish to appeal the results of this Notice and Order, you must file within ten (10) days, a written request for a hearing before the Historic Preservation Commission, 100 Maryland Avenue, Room 412, Rockville, Maryland 20850.

Please feel free to telephone or visit our office if you have any questions regarding this Notice and Order. When you reply, please use the above location. We will be happy to assist you in any way possible including referral to public or private agencies offering assistance.

Sincerely.

Michael T. Denney Inspector

MTD:mmr:1126R

#### CERTIFIED

S. C. N. SPAR

cc: Historic Preservation Commission

11

ADDENDUM "A" LIST OF VIOLATIONS

## 4501 Olney-Laytonsville Road

#### June 12, 1986

## EXTERIOR

くれる「「「「「「「」」」 いっています。

の日本のなどの「中国のない」

2

- 1. Repair or replace the deteriorated wood steps on the front porch and the side addition porch steps. Replace all defective, rotted, deteriorated, splintered or broken wood. All repairs must be made in a workmanlike manner to provide structural soundness and prevent further deterioration.
- Repair the deteriorated porch roof. The roof must be free of all deteriorated wood and must be structurally sound and free of leaks. Montgomery County Code 1984, Section 26-8(c). (Front & rear addition)
- 3. Repair/replace the deteriorated porch floors, columns, rails, soffits and piers. The entire floor areas of all porches are rotted with broken, missing or deteriorated floor boards. The brick piers supporting the front porch have missing, broken or cracked bricks with crumbling mortar joints and the piers are collapsing. Replace all defective or missing masonry material and repoint piers to provide structural soundness.
- 4. Repair or replace the deteriorated, loose, or leaking components of the gutter and downspout system and remove any obstructions as necessary to provide a system that will properly conduct storm water away from the structure. Montgomery County Code 1984, Section 26-8(f). (All sides, including porches and additions)
- 5. Replace the missing area of slate on the roof. All repair work must adequately secure the replacement roofing material and prevent water from entering the dwelling. Montgomery County Code 1984, Section 26-8(a).
- Repair or replace roof covering materials and/or flashings to stop entry of water into structure. Montgomery County Code 1984, Section 26-8(a). (Main house & rear addition)
- Repair or replace the deteriorated exterior trim. All trim must be maintained in a sound condition, free from rotting or splitting. Repair or replace the deteriorated soffits, facia boards, window and door frames and sills and all decorative trim. Montgomery County Code 1984, Section 26-8(g).

111

#### 4501 Olney-Laytonsville Road

10-10-10

このまたいのでも、こので、「「「「「」」

「「「ない」」を行きたいとないので、「ない」で、

# June 12, 1986

 Paint exterior trim, doors, windows and/or wood siding, soffits, facia boards, and any/all decorative trim. Scrape and remove all loose and deteriorated paint before painting. Montgomery County Code 1984, Section 26-8(g).

.2.


- Repair/replace defective or missing brick. There are numerous missing, cracked or broken bricks in portions of the side and rear walls. Replace and repoint missing/defective brick.
- The foundation walls are deteriorated and missing mortar between joints. Replace any missing foundation material and repoint entire foundation wall.
- Both of the chimneys are deteriorated with missing mortar and cracked or missing bricks. Replace defective, cracked or broken bricks and repoint chimneys. (All sides)
- 12. Repair or replace the deteriorated areas of the siding on all sides of the house and rear addition. The replacement siding must closely match the original and must be properly installed in order to provide a weathertight exterior surface. Montgomery County Code 1984, Section 26-8(a).
- 13. Replace the missing, broken or cracked window glass. Montgomery County Code 1984, Section 26-8(b).

In the event this property should become unoccupied, you must erect a perimeter fence to prevent vandalism and unlawful casual entry. It must be an eight (8) foot high, barbed wire topped, chain link fence and must extend around the entire perimeter of the structure, fifteen feet from the base of the foundation walls.


All the violtions listed in Addendum "A" must be corrected in accordance with Montgomery County Code 1984, Section 24A-6, which requires that you obtain an "Historic Area Work Permit".


For your information, enclosed are an Information Sheet on Historic Area Work Permits and definitions of "ordinary maintenance" and "substantial alteration".

MTD:mmr:0526S



12/98






OLNEY COMMUNITY PARK

•••

. .



Dec. 15, 1928 Meeting of Olvery Boys + Girls (Cus Den Dunsio Dio Nisio Jan 8-12,000 / Dev. Kight. They have 24

Montomerv	Historic Preservation ( Accol Them
	/ n/cm/a + 1 cm
Covernment	100 Maryland Avenue, Rockville, N Gradow for the definition of the
Gverninen	<u> </u>
1997 (* 1997) 1997 (* 1997) 1997 (* 1997) 1997 (* 1997) 1997 (* 1997)	
APPLICATION FOR	
• • • • • • • • • •	
HISTORIC AREA W	
TAX ACCOUNT # 722683	
	HARD T. WHITE TELEPHONE NO. 301-831-7474
(Contract/Purchaser) AODRESS <i>Gillis F</i>	(Include Area Code) <u>ALLS Rd. MT. Airy MARYLAND</u> 21771 STATE ZIP
CONTRACTOR	CITY / STATE ZIP TELEPHONE NO.
	CONTRACTOR REGISTRATION NUMBER
PLANS PREPARED BY	TELEPHONE NO (Include Area Code)
	REGISTRATION NUMBER
LOCATION OF BUILDING/PREMISE	· · · · · · · · · · · · · · · · · · ·
	Street OLNEY-LAYTONSUILLE Road Acut # 722683
	LAND Election District
	TAL CLASSIFICATION 70_
Nearest Cross Street	·····································
	$C_{\text{Parcel}} = \frac{3.22}{2}$
Liber <u>4026</u> Folio <u>637</u>	Parcel
Wreck/Raze Move Instal 1B. CONSTRUCTION COSTS ESTIMA	TES CONSIGNATION OF A
1B. CONSTRUCTION COSTS ESTIMA 1C. IF THIS IS A REVISION DF A PRI 1D. INDICATE NAME OF ELECTRIC	
1B. CONSTRUCTION COSTS ESTIMA 1C. IF THIS IS A REVISION DF A PRI 1D. INDICATE NAME OF ELECTRIC 1E. IS THIS PROPERTY A HISTORIC.	TE\$ EVIOUSLY APPROVED ACTIVE PERMIT SEE PERMIT # UTILITY COMPANY AL SITE?Y < S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONSE  2A.    TYPE OF SEWAGE DISPOSAL	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS	TE \$  24.0 You want to be a construction of the permit of the permitting of the
1B. CONSTRUCTION COSTS ESTIMA 1C. IF THIS IS A REVISION DF A PRI 1D. INDICATE NAME OF ELECTRIC 1E. IS THIS PROPERTY A HISTORIC. PART TWO: COMPLETE FOR NEW CONS 2A. TYPE OF SEWAGE DISPOSAL 01 () WSSC 02 () SI 03 () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Sugar () Other    PART THREE: COMPLETE ON LY FOR FE    4A.  HEIGHT feetinc	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  {} WSSC  02  {} SI    03  {} Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () St    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () St    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Su    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  {} WSSC  02  {} Str    03  {} Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Su    03  () Other	TE \$
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONST    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Sugar    PART THREE: COMPLETE ON LY FOR FE    4A.  HEIGHTfeetinc    4B.  Indicate whether the fence or retain    1.  On party line/Property line    2.  Entirely on land of owner    3.  On public right of way/easemen    I hereby certify that I have the authority    plans approved by all agencies listed and I here    Mayour M.	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS'    2A.  TYPE OF SEWAGE DISPOSAL    01  {} WSSC  02  {} Si    03  {} Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONST    2A.  TYPE OF SEWAGE DISPOSAL    01  () WSSC  02  () Str    03  () Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS:    2A.  TYPE OF SEWAGE DISPOSAL    01  {} WSSC  02 {} St    03  {} Other	TE S
1B.  CONSTRUCTION COSTS ESTIMA    1C.  IF THIS IS A REVISION DF A PRI    1D.  INDICATE NAME OF ELECTRIC    1E.  IS THIS PROPERTY A HISTORIC.    PART TWO: COMPLETE FOR NEW CONS:    2A.  TYPE OF SEWAGE DISPOSAL    01  {} WSSC  02 {} St    03  {} Other	TE S

	THE	FOLLOWING	ITEMS	MUST BI	E COMPLETED	AND THE	REQUIRED	DOCUMENTS	MUST	ACCOMPANY	THIS	
APPI	ICATI	ON CON	5 <sup>*</sup>	$\{[f_{i}]_{i\in I}\}_{i\in I}$					문문	÷	1.1	

and the second second

DESCRIPTION OF PROPOSED WORK: (including composition, color and texture of materials to be used:)

1. install a metal bilco cellar door entrance

2. remove the deteriorating rear porch

3. repoint brick and replace missing brick

4. install a new fibergalss shake roof

(If more space is needed, attach additional sheets on plain or lined paper to this application)

ATTACH TO THIS APPLICATION (2) COPIES OF: SUCH SITE PLANS (lot dimensions, building location with dimensions, drives, walks, fences, patios, etc. proposed or existing) and/or ARCHITECTURAL DRAWINGS (floor plans, elevations, etc.), PHOTOGRAPHS OF THE AREA AFFECTED, as are necessary to fully describe the proposed work.

. . !

\$ 150

191

175

2

MAIL OR DELIVER THE APPLICATION AND ALL REQUIRED DOCUMENTS TO THE: HISTORIC PRESERVATION COMMISSION 100 MARYLAND AVENUE

1.1

ROCKVILLE, MARYLAND 20850 A state of the sta

# CONDITIONS OF PERMIT:

- 1. Vine growing up the side of the house must be removed.
- 2. Repointing of brick shall be done with a mixture approved by staff.
- 3. All brick, wood trim, and any other items to be replaced must be replaced with identical materials.