31/7-05F 9706 Capitol View Ave Capitol View Park Historic District

589 OZG8 19706 CapitalView Ave 1) New fort door - soproved stamped plans - slow existing-(Z) 2nd floor sitting room constructed as 2 perch (3) Window have differt much Pallery (4) Sidne all horizontal (5) Owler window braids fout doer Trent perch design slightly cliffent (F) Reffert window states 51365 if places. (8) Bunp-out (portso sport) 9 Garage 1 dors Central spoarones is good. IS looks

s- rud U Sides - wood? lo en cupola re-cons CAD come of wood

2 @ back 3 9 to BC

FAX TRANSMITTAL SHEET Montgomery County Department of Park and Planning Historic Preservation Section

Telephone Number (301) 563-3400

Fax Number (301) 563-3412

TO: Spiro Gioldasis

FAX NUMBER: 301-589-0768

FROM: Tania Tully

DATE: February 16, 2006

Number of pages including this transmittal sheet: 2

RE: 6 Post

6 Post Office Road, HAWP Application

NOTE:

Please review the attached work items and sign the application.

FAX TRANSMITTAL SHEET Montgomery County Department of Park and Planning Historic Preservation Section

Telephone Number (301) 563-3400

Fax Number (301) 563-3412

TO: Spiro Gioldasis

FAX NUMBER: 301-589-0768

FROM: Tania Tully

DATE: February 16, 2006

Number of pages including this transmittal sheet: 3

RE: 9

9706 Capitol View Avenue, Retroactive HAWP

NOTE:

Please review the attached work items and sign the application.

Additional Questions:

- Are you still planning on installing a railing on the front porch? If so, it must be wood.
- The porch floor was approved as wood. Has that been completed yet?































SCALE: 1/4" = 1'-0"

(4)






NORTHEAST ELEVATION OF PORCH

SCALE: 1/4" = 1'-0"

APPROVED

Montgomery County

Historic Preservation Commission



M,



Go Back View Map **New Search** Ground <u>Rent</u>

Account Identifier:

District - 13 Account Number - 00996438

Owner Information

Owner Name:

GIOLDASIS, SPIRO P

Use:

RESIDENTIAL

Principal Residence: YES

Mailing Address:

9706 CAPITOL VIEW AVE

SILVER SPRING MD 20910-1028

Deed Reference:

1) /29209/ 769

2)

Location & Structure Information

Premises Address

9706 CAPITOL VIEW AVE **SILVER SPRING 20910-1028** **Legal Description**

CAPITOL VIEW PARK

Мар О	Grid Parcel	Sub District	Subdivision	Section	Block Lot	Assessment Area	Plat No:
HP62	N556		5		P37	1	Plat Ref:
		To	wn				
C	T A	_					

Special Tax Areas Ad Valorem

38 Tax Class

Primary Struc	cture Built	Enclosed Area	Property Land Area	County Use	
1908	3	956 SF 9,240.00 SF		111	
Stories	Basement		Туре	Exterior	
1	NO		STANDARD UNIT	FRAME	

Value Information

	Base Value			sessments
	Value	As Of	As Of	As Of
		01/01/2004	07/01/2005	07/01/2006
Land:	59,960	119,920		
Improvements:	88,260	152,460		
Total:	148,220	272,380	230,992	272,380
Preferential Land:	0	0	0	0

Transfer Information

Seller: WOLFE, DON M	Date: 02/07/2005	Price: \$239,000
Type: IMPROVED ARMS-LENGTH	Deed1: /29209/ 769	Deed2:
Seller: WOLFE, DON M	Date: 04/01/2003	Price: \$0
Type: NOT ARMS-LENGTH	Deed1: /23456/ 97	Deed2:
Seller: ABSECON ASSOCIATES	Date: 11/15/2002	Price: \$0
Type: NOT ARMS-LENGTH	Deed1: /22283/ 193	Deed2:

Exemption Information

Partial Exempt Assessments	Class	07/01/2005	07/01/2006
County	000	0	0
State	000	0	Ō
Municipal	000	0	0
		2	



Go Back View Map **New Search Ground Rent**

Account Identifier:

District - 13 Account Number - 00995514

Owner Information

Owner Name:

GIOLDASIS, SPIRO

Use:

COMMERCIAL

Mailing Address:

9103 KINGSBURY DR

Deed Reference:

Principal Residence: NO

1) /31339/ 671

SILVER SPRING MD 20910-4258

2)

Location & Structure Information

Premises Address

6 POST OFFICE RD SILVER SPRING 20910 **Legal Description**

CAPITOL VIEW PARK

Map Grid Parcel

Subdivision Sub District Section **Block Lot Assessment Area** HP62 N579 P37 5 Town

Plat Ref:

Special Tax Areas

Ad Valorem

Tax Class

Property Land Area

County Use

Plat No:

Primary Structure Built 1918

Land:

Total:

Improvements:

Preferential Land:

Enclosed Area 2,010 SF

6,766.00 SF

637

Stories

Basement

Type

Exterior

Value Information

Base	value	Phase-in Assessments			
. Value	As Of	As Of	As Of		
	01/01/2004	07/01/2005	07/01/2006		
135,300	162,300				
88,200	102,600				
223,500	264,900	251,100	264,900		
'n	· 0	'n	Λ		

Transfer Information

Seller: ABSECON ASSOCIATES **Date:** 11/30/2005 **Price:** \$250,000

Deed2: Type: NOT ARMS-LENGTH **Deed1:** /31339/ 671 Seller: IVANOR CORP Date: Price: \$0 05/18/2000 **Type:** NOT ARMS-LENGTH Deed1: /18093/ 755 Deed2:

Seller: 11/03/1975 Price: \$47,000 Date:

Deed1: / 4707/ 521 Type: IMPROVED ARMS-LENGTH Deed2:


Exemption Information


Partial Exempt Assessments	Class	07/01/2005	07/01/2006
County	000	0	0
State	000	0	0
Municipal	000	0	0

Tax Exempt:

NO

Special Tax Recapture:





NORTHEAST ELEVATION OF PORCH

SCALE: 1/4" = 1'-0"

APPROVED

Montgomery County

Historic Preservation Commission



Date: July 14, 2005

MEMORANDUM

TO:

Robert Hubbard, Director

FROM:

Tania Tully, Senior Planner

Historic Preservation Section

SUBJECT:

Historic Area Work Permit #389246

Stamped drawing in Tania's offer 7/22/05

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **Approved with Conditions.**

- 1. Tree protection plan prepared by a certified arborist will be provided to staff and implemented Onsite prior to any work beginning on the property.
- 2. The rear patio will be concrete pavers rather than a slab.
- 3. The windows will be wood simulated divided light windows, which contain muntins that are permanently bonded to the interior and exterior of the insulating glass simulating a divided light appearance.
- 4. The pitch of the southwest gables will be revised to be consistent with the gable on the front of the house.
- 5. Minor detail changes and refinements will be provided to and approved by staff prior completion of the permit drawings.
- 6. The applicant will present 3 permit sets of drawings to HPC staff for review and stamping prior to submission for other required permits.
- 7. The site/grading/landscape plan will be submitted to staff and brought back to the HPC as a new HAWP or formal revision to this HAWP. The plan should indicate, at the minimum, any necessary retaining walls, locations and materials of the driveway and walkways.
- 8. No tree removal has been approved at this time.

The HPC staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Applicant:

Spiro Gioldasis

9201 Colesville Road, Suite 100 Silver Spring, MD 20910

Property Address:

9706 Capitol View Avenue, Silver Spring

This HAWP approval is subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online at http://permits.emontgomery.org prior to commencement of work http://permits.emontgomery.org





DPS - #6

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: SAINO GIOLDASIA

Davine Phone No. 443-745-3940

neracion.	······································		en e	Ph	one No.:			and the species flowers are "Mill are of the "Mill	Count M
intractor Registration (lis								
ent for Owner		and the second s		Daytime Ph	one No	~			
CATION OF BUILD	ING/PHEM	ISE			****	, , , , , , , , , , , , , , , , , , ,			egarbonigatis.
suse Number 🛒 🧣	1706	CAPITOL	- UIEW	* NHO	ut	management and the first of the		**************************************	CARLOR TO THE PARTY OF THE PART
water Sich	VER	SPHÜG	Nearest Cross Stree	FORES	T a	EN	/ S	thin my	VY 1
t	Block,	Subdivision	**************************************			and the court of the state of	one control of the second of t	*****************	nondered.
367	Folio	Pace		The second secon				e med and a conjugate inspect open pages as the sequence field	** - **
ART ONE TYPE OF	PERMIT A	CTION AND USE		and the second finance of the second	na gant, ning ing pi nggala gas som ex faracoma	And the second seco	+ ************************************	10000000000000000000000000000000000000	hauphillibyro _d
A. CHÇCK ALL APPLIQ	ABLL.		CHECK A	il applicable					
Lassingt	(: Extend	Alter/Bonavate	X/NO	C) Slab	☐ Saom Add	ition [] [meh [Deck Dis	ihed
May(🗙 lostali	L. Westkäller	☐ Solar	[] Freebace	□ Woedburn	ng Stove	C	Simple Family	ý
: Revented	🗡 нерад	L. Revocable	Ti fence	:AVall (complete S	ection 4)	Other:		.^	
B. Contraction cost o	rstimate: S			angles had a hit in the real of the country	and the second of the second o	***************************************	***************************************	·	en 1 111
" If this is a revision.	al a pievious	ly approved active permit,	see Ferand #	g-g-g-g-g-g-arter (Marter ber ger _{g-g} -g-arter (Marter berger)	· · · · · · · · · · · · · · · · · · ·	an a			- ATTENDANCE
aki iwo: compu	HIE FOR N	EW CONSTRUCTION A	ND EXTEND/ADD	ITIONS			***** *******************************	0001100110100194-1-201110111111111111111111111111111111	environe (Marie Constitution)
n Type of servage t	kspesal.	GT (C) WSSC	07 (1 Suppo	63 🗀 :	Osher,	e weeren en oord een oord op gegen to	to any company or common the state of	**************************************	
ives of water sup	gniy:	OF 13: WESC	Ω II Well						
ART TRUES - COM	HATTYF (IMES	<u>(FOR FENCEMETAÍNI)</u>	ii. Wali		-	T SOMEONE WAS AND A STREET,		***************************************	nt-states ear-species
A Health .			Andrew Control of the						
		setameng walk is to be con	estructed an one of th	ie followity locati	nas:				
Uniparty line/u			lend of ewaci		itic riight of wa	//easemeal			
	, angle and another some	no monte circular es expensivos mentro de la composição d	dagagagagagagagagagagagagagagagagagagag		anne et and the	A the country		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	***************************************
леней» п <mark>етах</mark> авас і в розокой бу у ў адеяся	ove the dulif District of	priky to make the foregov I i minsty arknowledge a	ed accept that to be ed accept that to be	re abbarcation for th a condition for th	e issuance of	e une consun Unis premit	ACTAONI NAM	compry with a	unos
//	<i>!</i> //	//-				dal	2/2/	-	
Offer !	Ale 1	lan				6/28	725	· ·	
~ / ·	Supplement of a	Kener ar auchtgrand againt				•	: Uste		

SEE REVERSE SIDE FOR INSTRUCTIONS

(5)



Date: July 14, 2005

MEMORANDUM

TO:

Spiro Giodasis

9201 Colesville Road, Suite 100

Silver Spring, MD 20910

FROM:

Tania Tully, Senior Planner

Historic Preservation Section

SUBJECT:

Historic Area Work Permit Application #389246 (9706 Capitol View Avenue)

Your Historic Area Work Permit application for Alterations was <u>Approved with Conditions</u> by the Historic Preservation Commission at its July 13, 2005 meeting.

Prior to applying for a county building permit from the Department of Permitting Services, you must schedule a meeting with your assigned staff person to bring your final construction drawings in to the Historic Preservation Office at 1109 Spring Street for stamping. Please note that although your work has been approved by the Historic Preservation Commission, it must also be approved by DPS before work can begin.

When you file for your building permit at DPS, you must take with you stamped drawings and an official approval letter (given at the time of drawing stamping). These forms are proof that the Historic Preservation Commission has reviewed your project. For further information about filing procedures or materials for your county building permit review, please call DPS at 240-777-6370.

If your project changes in any way from the approved plans, either before you apply for your building permit or even after the work has begun, please contact the Historic Preservation Commission staff at 301-563-3400.

Please also note that you must arrange for a field inspection for conformance with your approved HAWP plans. Please inform DPS/Field Services at 240-777-6210 or online at http://permits.emontgomery.org of your anticipated work schedule.

Thank you very much for your patience and good luck with your project!



FAX TRANSMITTAL SHEET

Montgomery County Department of Park and Planning Historic Preservation Section

Telephone Number (301) 563-3400

Fax Number (301) 563-3412

TO: Spiro Gioldasis

FAX NUMBER: 301-589-0768

FROM: Tania Tully

DATE: November 21, 2005

Number of pages including this transmittal sheet:

RE:


9706 Capitol View Avenue

NOTE: Attached is the memo with the revised approval.

1 vote: Should shown.


Concrete Pavers prown.

John of 24



NOTE: THIS LOCATION IS VALID FOR 180 DAYS FROM THE DATE ON THE PLAN.

and to be used for determining property lines. Property corner Markers Not guaranteed by this location NOTE: This location for this near



MR. SPIRO GIOLDASIS 9201 COLESVILLE ROAD SILVER SPRING, MARYLAND 20910

PHONE

443-745-9340

FAX

301-589-0768

RE: RESIDENTIAL LANDSCAPING 9706 CAPITOL VIEW AVENUE SILVER SPRING, MARYLAND LANDSCAPE: PRICE ALTERNATES

DEAR MR. GIOLDASIS:

E PROPOSE TO COMPLETE THE LANDSCAPING ON THE ABOVE REFERENCED PROJECT NOT COMPLETE ACCORDANCE WITH PLANS AND SPECIFICATIONS AS FOLLOWS:

QUANTITY	PLANT NAME	SIZE	<u>UNIT</u>	TOTAL
7	NELLIE STEVENS HOLLY	6-7'	\$420.00	\$2,940.00
3	YOSHINO CRYPTOMERIA	6-7'	\$300.00	\$900.00
2	KWANZAN CHERRY	8-10'	\$350.00	\$700.00
1	OCTOBER GLORY MAPLE	2.5-3"CAL.	\$450.00	\$450.00
3	HEMLOCK	6-7'	\$240.00	\$720.00
1	WEEPING CHERRY	8-10'	\$360.00	\$360.00
21	LEYLAND CYPRESS	5-6'	\$165.00	\$3,465.00
5	CHINA GIRL HOLLY	2-2.5'	\$65.00	\$325.00
12	COMPACTA HOLLY	18-24"	\$40.00	\$480.00
30	AZALEA	15-18"	\$35.00	\$1,050.00
-8	DENSA YEW	18-24"	\$65.00	\$520.00
4	CHERRY LAUREL	3'	\$90.00	\$360.00
10	SCARLET LEADER COTONEASTER	18-24"	\$35.00	\$350.00
80	BIG BLUE LIRIOPE	1 GAL	\$7.00	\$560.00
12	CUBIC YARDS MULCH		\$35.00	<u>\$420.00</u>
				\$13,600,00

PLANTING-PEAT-FERTILIZER-STAKING - ONE YEAR CONDITIONAL GUARANTEE

TOTAL	

APPROVED

Montgomery County

Historic Preservation Commission

PLEASE STAR(*) AND TOTAL WORK TO BE COMPLETED.

NOTE: PATIO, WALKS, FOUNTAIN NOT INCLUDED

ALTERNATES, AS NEEDED, UNIT PRICE PREVAILS

- A. 800 SQUARE YARDS SOD @ \$7.25 PER SQUARE YARD = \$5,800.00
- B. 800 SQUARE YARDS SEED @ \$3.50 PER SQUARE YARD = \$2,800.00
- C. SITE PREPARATION @ \$40.00 PER WORKER HOUR

LANDSCAPE D. S DEVELOPMENT CO.

D. SCREENED TOPSOIL @ \$75.00 PER CUBIC YARD

16307 Carrs Mill Road

Woodbine, MD 21797ERMS - USUAL

410-442-2033 APPLICABLE TAXES ADDITIONAL

BALT. 410-442-2033 VA. 301-924-2486 D.C. 301-854-6100 FAX 301-854-6481

ΠΔ	TE:				
-		 	 	 	

LANDSCAPE DEVELOPMENT COMPANY

_____JAMES,W. WARD, JR., C.E.O.

November 8, 2005

MEMORANDUM

TO:

Julia O'Malley, Chair

Historic Preservation Commission

FROM:

Tania Tully, Senior Planner

Historic Preservation Section

SUBJECT:

HPC Case No. 31/07-05F, 9706 Capitol View Avenue

At the July 13, 2005 HPC Meeting, the Commission conditionally approved porch alterations and 2nd level additions to the above non-contributing resources in the Capitol View Park Historic District. One of the conditions stated that the applicant return with a site/grading/landscape plan indicating any necessary retaining walls, locations and materials of the driveway, and walkways.

Attached are the required items that staff will present as a Staff Item at the end of the November 16, 2005 HPC Meeting. You are receiving these in advance because the materials were received prior to the staff report packets being mailed. This is unusual, but fortuitous. Staff will be requesting the authority to approve the plans at the staff level. The plans indicate the following:

- Change the material of the existing driveway from broken asphalt to concrete pavers.
- Add a curved concrete paver walkway.
- Construct a 2' high stuccoed retaining wall along the east property line
- Construct a 2' high 14' long stuccoed retaining wall along the north side of the driveway that includes a short set of stairs.
- The grade will be lowered 8" in the area of the walkway and front steps in order to direct water away from the house.
- In addition to new plantings, new topsoil will be added to the site.
- No trees are proposed for removal.

November 21, 2005

Mr. Reggie Jetter Department of Permitting Services 255 Rockville Pike, 2nd Floor Rockville, Maryland 20850-4166

Re:

Historic Area Work Permit # 389246

9706 Capitol View Avenue, Silver Spring, MD

Outstanding Resource within the Capitol View Park Master Plan Historic District

Dear Mr. Jetter:

I am writing regarding proposed changes to the previously approved HAWP (HPC# 31/07-05F). The Montgomery County Historic Preservation Commission (HPC), at the November 16, 2005 HPC meeting, has approved the landscape and hardscape design (condition of prior approval) and retaining walls (new work item). A description of the approved items is attached.

<u>Please utilize this letter as formal approval for this revision.</u> Thank you for your assistance in this matter. If you have any questions, please do not hesitate to contact staff at 301-563-3400.

Sincerely,

Tania Georgiou Tully

Historic Preservation Planner

cc: Spiro Gioldasis

November 8, 2005

MEMORANDUM

TO:

Julia O'Malley, Chair

Historic Preservation Commission

FROM:

Tania Tully, Senior Planner Historic Preservation Section

SUBJECT:

HPC Case No. 31/07-05F, 9706 Capitol View Avenue

At the July 13, 2005 HPC Meeting, the Commission conditionally approved porch alterations and 2nd level additions to the above non-contributing resources in the Capitol View Park Historic District. One of the conditions stated that the applicant return with a site/grading/landscape plan indicating any necessary retaining walls, locations and materials of the driveway, and walkways.

Attached are the required items that staff will present as a Staff Item at the end of the November 16, 2005 HPC Meeting. You are receiving these in advance because the materials were received prior to the staff report packets being mailed. This is unusual, but fortuitous. Staff will be requesting the authority to approve the plans at the staff level. The plans indicate the following:

- Change the material of the existing driveway from broken asphalt to concrete pavers.
- Add a curved concrete paver walkway.
- Construct a 2' high stuccoed retaining wall along the east property line
- Construct a 2' high 14' long stuccoed retaining wall along the north side of the driveway that includes a short set of stairs.
- The grade will be lowered 8" in the area of the walkway and front steps in order to direct water away from the house.
- In addition to new plantings, new topsoil will be added to the site.
- No trees are proposed for removal.



Date: July 14, 2005

MEMORANDUM

TO:

Robert Hubbard, Director

FROM:

Tania Tully, Senior Planner Historic Preservation Section

SUBJECT:

Historic Area Work Permit #389246

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **Approved with Conditions**.

- 1. Tree protection plan prepared by a certified arborist will be provided to staff and implemented onsite prior to any work beginning on the property.
- 2. The rear patio will be concrete pavers rather than a slab.
- 3. The windows will be wood simulated divided light windows, which contain muntins that are permanently bonded to the interior and exterior of the insulating glass simulating a divided light appearance.
- 4. The pitch of the southwest gables will be revised to be consistent with the gable on the front of the house.
- 5. Minor detail changes and refinements will be provided to and approved by staff prior completion of the permit drawings.
- 6. The applicant will present 3 permit sets of drawings to HPC staff for review and stamping prior to submission for other required permits.
- 7. The site/grading/landscape plan will be submitted to staff and brought back to the HPC as a new HAWP or formal revision to this HAWP. The plan should indicate, at the minimum, any necessary retaining walls, locations and materials of the driveway and walkways.
- 8. No tree removal has been approved at this time.

The HPC staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Applicant:

Spiro Gioldasis

9201 Colesville Road, Suite 100 Silver Spring, MD 20910

Property Address:

9706 Capitol View Avenue, Silver Spring

This HAWP approval is subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online at http://permits.emontgomery.org prior to commencement of work and not more than two weeks following completion of work

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION ŀ HISTORIC PRESERVATION COMMISSION 2 3 MS. O'MALLEY: Next, we'll hear Case D, 9706 Capital View 4 Avenue. Is there a staff report? 5 MS. TULLY: Yes. 9706 Capitol View Avenue is a non-contributing 6 resource in the Capitol View historic district. Although it was 7 constructed around 1908, it is nearly unrecognizable at that old of a 8 building. 9 The existing cladding is a mixture of plywood batten on board 10 and asbestos shingles, although there is evidence of vertical beading bead 11 board underneath. I'm just going to move quickly and take you around the 12 site. This would be the front. 13 The house sits essentially on a corner lot, although it is the 14 same street on both sides of the corner. The adjacent properties include 15 the -- excuse me, the Forest School Country Store to the southeast and 16 also, there is the castle directly south of it. Additionally, there is a 17 contributing resource across the way. Here are some streetscape shots. 18 You can see it sits on that tight. Here are the other shots. 19 This would be the country store and this is the other, the 20 contributing resource that is nearby and I didn't get a picture of the 21 castle. These are at least a few of the shots. This really demonstrated 22 the alterations that have occurred to the property and its roof. It's kind 23 of strange. This is an existing shed on the property and it will, actually 24 25 is proposed to be torn down as part of this project. Although it is -- well, part of the reason is because it is 26 The property line is there where the buildings are attached and 27 so that is certainly one of the issues. It is proposed for demolition. 28 The proposal for the project are a couple of things. There are 29 some -- well, actually, I'm sorry, I'm going to back up. I want to go back 30 to the front. One of the proposals is to remove this existing enclosed 31 porch and replace it with a more compatible open porch and staff really 32 doesn't have any concerns with that. 33 Additionally, there is a proposed -- there are -- the big bulk 34 of the project are the rear additions and that involves removing existing 35 additions and then putting in something with a second story so essentially 36 that versus -- again, these are staff, crew. What representation by no 37

2

1 means of any architectural excellence there, but it gives you a rough idea

- 2 of where we will be going on here, from the adjacent property, so you can
- 3 see again, from here..
- And there will also be some tree removal. The applicant is
- 5 here. He can talk a little bit more about that and you should have seen on
- 6 -- at your chairs, the plat he provided tonight as well.
- 7 Staff is, you know, generally supportive of the project. It is
- 8 a non-contributing resource. Certainly the porch helps with the
- 9 compatibility to the district and with a few suggestions, staff also
- 10 believe that the additions are also compatible to the district as well.
- 11 A couple of the suggestions that we have regard the massing that
- 12 be -- I mean the character of the house is very -- well, why don't I go
- 13 over my staff conditions? One is being that a tree protection plan. There
- 14 is a certified arborist and that is primarily considering there are some
- 15 rather large trees.along the property line.
- Additionally, a grading and/or landscape plan to be provided
- 17 with a memo showing any necessary retaining walls and location of materials
- 18 and driveways and walkways. That was not included in the application.
- There is a proposed small little patio proposed. The pavers
- 20 under the slab are suggested and additionally, that the windows be both
- 21 simulated, divided windows as is typical. I didn't speak to the architect
- 22 yet. They are proposing that but it wouldn't hurt to hear it again on the
- 23 application. So, this is more of a clarification and if there are any
- 24 minor requirements, they can be approved at the staff levels, perhaps
- 25 including staff suggestion of having one of the additions like not be flush
- 26 with the house and in a standard condition. I didn't ask if there are any
- 27 questions.
- MS. ALDERSON: Just one?
- MS. TULLY: Sure.
- 30 MS. ALDERSON: Is the applicant willing to consider the addition
- 31 of openings to the walls where you have suggested to bring more balance to
- 32 that proportion of window to wall?
- 33 MS. TULLY: No. I'm not certain.
- 34 MS. ALDERSON: -- on the northwest.
- 35 MS. TULLY: Why don't we bring him up and ask him.
- 36 MS. O'MALLEY: Any other questions for staff? Could the
- 37 applicant come up, please?

- 1 MR. GIOLDASIS: Good evening.
- 2 MS. O'MALLEY: Good evening. State your name for the record.
- 3 MR. GIOLDASIS: Spiro Gioldasis and I'm the owner of the house.
- 4 It will be just basically windows all around and it's going to have the
- 5 same form as what it was.
- 6 MS. ALDERSON: Are you comfortable --
- 7 MR. GIOLDASIS: Absolutely.
- 8 MS. ALDERSON: -- with the suggestion here -- okay. Because I
- 9 thought that was one of the most helpful things about the changes is that
- 10 there's more of a balance.
- 11 MR. GIOLDASIS: Exactly.
- 12 MS. ALDERSON: In the proportion of windows to wall.
- MR. GIOLDASIS: Right.
- 14 MS. ALDERSON: One question. One the southwest elevation as
- 15 I've seen here, there is one wall in the addition, the right addition as
- 16 you face it, that is the second story. It's a blank wall and is there a
- 17 reason that needs to be blank or is that --
- 18 MR. GIOLDASIS: No.
- 19 MS. ALDERSON: -- another wall you would
- 20 consider --
- MR. GIOLDASIS: It will have a window.
- MS. ALDERSON: Terrific.
- MR. GIOLDASIS: Yes. It will have one there.
- MS. ALDERSON: And the only, just one last --
- 25 MS. WRIGHT: I think we need to clarify because on the plans,
- 26 that's a walk-in closet, so it may not have a window.
- MS. ALDERSON: Which --
- 28 MS. WRIGHT: You're looking on circle 8.
- 29 MS. TULLY: Actually, give the applicant a minute to take a look
- 30 at that. I just realized that he did not get the staff report and when I
- 31 faxed him the staff report today, I didn't include the two drawings.
- 32 MS. ALDERSON: I'm looking at circle 25.
- 33 MS. TULLY: Right. So he is seeing that for the first time I
- 34 just realized so he may need a minute to get oriented.
- MS. O'MALLEY: Well, her drawings are on the street side.
- 36 Apparently, that's on the street side.
- 37 MS. TULLY: Even if you look at circle 25 --

- 1 MS. ALDERSON: It said the southwest elevation that he's
- 2 completing concealed from view.
- 3 MS. TULLY: Right.
- 4 MS. WRIGHT: The part that is next to the garage. That big
- 5 white square is the roof of the two car garage that's on the right hand
- 6 side of that drawing. It's the back roof of the garage?
- 7 MS. TULLY: Yes.
- 8 MS. WRIGHT: And then if you at plans, circle 24, that area
- 9 directly next to the garage is a walk-in closet and bathroom on the second
- 10 floor. So, it probably would be hard to put in windows.
- MS. ALDERSON: I see. But that is an area that less visible
- 12 anyway then.
- MS. WRIGHT: Very much so. It's hidden almost entirely by the
- 14 house next door.
- MS. ALDERSON: Okay. My principal concern is the house next
- 16 door is also historic?
- MS. TULLY: Yes.
- MS. ALDERSON: Okay. So it would be visible from there, but not
- 19 from the street.
- MS. O'MALLEY: So adding that interior, two story addition,
- 21 interior to the lot, pretty much uses up all of your backyard?
- MR. GIOLDASIS: Yes.
- MS. O'MALLEY: Is that right?
- MR. GIOLDASIS: No. It does not. It does not use but
- 25 basically, it borders on the house because before it was a mismatch. I do
- 26 not know if you have any drawings from before but that small corner in the
- 27 back, it wasn't done very well. It wasn't even out so now, it's even. It
- 28 shows very nice. It will be very nicely done.
- 29 MS. O'MALLEY: And where is the patio? Is that laid down on one
- 30 of our plans that you mentioned?
- MR. GIOLDASIS: It will be right outside on the side of that
- 32 same area.
- 33 MS. TULLY: You can see the patio circle 24. It's on the left.
- 34 MS. ALDERSON: Going to the -- oh, okay. Oh, I see, next to the
- 35 dining room.
- 36 MS. TULLY: Correct.
- 37 MS. O'MALLEY: Okay. And this is still --

```
MS. ALDERSON: And you're comfortable with the condition to use
1
    the -- I think you suggested use pavers you said in the covering?
2
 3
               MR. GIOLDASIS:
                               Yes.
                              Now, my other question was about the grading,
 4
               MS. O'MALLEY:
    particularly around the part that you're going to have as a garage entrance
 5
 6
    and the front porch: What have you been thinking about for that area?
 7
    looks like the grade actually is higher than the porch now:
               MR. GIOLDASIS: Yes It is. What I was planning to do right
 8
    where the garage ends on the bottom side, I was going to put a retaining
 9
     wall and them steps down to go to the -- to dig in a little wit to the
10
    other dirt that's blocking so it won't go into the patio; into the porch so
11
     it's going to be lower. So part of the retaining wall on top of the
12
    parking.
13
               MS. O'MALLEY: So then, Tania, would he be coming back with
14
    plans for driveway and grading and --
15
               MS. TULLY: Well, it's up to you. I have it as a condition to
16
    be approved by staff, but if the Commission would rather it come back to
17
    them, then that can also be the case. Is there a cause for a second
18
19
    condition?
               MS. O'MALLEY: Is there a driveway that actually comes in there
20
21
    now?
               MR. GIOLDASIS: Yes. There is actually a quest one for the
22
23
    front, along the bottom side of the property.
24
               MS. O'MALLEY: But you wouldn't close off the one at the bottom
25
    end?
                               If you think I should close it, I will close it.
26
               MR. GIOLDASIS:
                              Well, traffic-wise, I don't know which is the
27
               MS. O'MALLEY:
    better place to come out of that courtyard.
28
29
               MR. GIOLDASIS:
                               I know. It's very lethal.
                              But I don't think the lot is big enough to
30
               MS. O'MALLEY:
    support a driveway on either side. Then you would be --
31
                               But on the top of the property, a driveway does
32
               MR. GIOLDASIS:
            I personally think the bottom side is better, than on the curve at
33
    exist.
34
    the top.
               MS. O'MALLEY: Well if you had a driveway there, where would it
35
36
    lead?
               MR. GIOLDASIS:
37
                               Huh?
```

```
MS. O'MALLEY: If you had a driveway at the bottom, where would
 1
 2
    it go? It wouldn't go to the garage then?
               MR. GIOLDASIS: No. It wouldn't go to the garage.
 3
               MS. WRIGHT: It sounds like the driveway may be complicated
 4
    enough that you're willing to come back to the HPC because I guess the
 5
    question really would be if you have a driveway that doesn't lead to the
 6
    garage, is the garage actually a garage or is it a room? And where would
7.
    the parking exactly be for the building?
 8
               MR. GIOLDASIS: The parking, as I said, should be where it is,
9
    at this moment. So, if you think that I should have it on the bottom then
10
    I do not disagree. I will put it on the bottom and just have that garage,
11
    now an existing garage, as an extra storage space.
12
               MS. O'MALLEY: Well, I would think it would be best to have it
13
14
    as it historically has been.
               MR. GIOLDASIS: Right.
15
               MS. O'MALLEY: So that you would have the drive at the top and
16
    close off the lower area.
17
18
               MR. GIOLDASIS: Okay.
               MS. O'MALLEY: But I do agree that those items, particularly the
19
20
    grading and the walkways and there was some mention of tree removal?
               MR. GIOLDASIS: Yes. There is, I believe three trees on the
21
    top, outside at the top of top of the southeast that are around the
22
23
    property line.
               MS. O'MALLEY: Between your driveway or between the garage?
24
25
               MR. GIOLDASIS: No. It's actually on the southeast elevation
    where -- I'm sorry. I'm sorry. It's between my property and Forest Glen -
26
    - it would have to be the post office, the historic post office.
27
               MS. WRIGHT: Could you look at circle 11 in that packet and
28
    there's a photograph?
29
                                     It's on the bottom side.
30
               MR. GIOLDASIS: Yes.
               MS. WRIGHT: Okay. Which of the trees in that photograph are
31
    you talking about?
32
33
               MR. GIOLDASIS: Those two trees there. Those two.
               MS. WRIGHT: Including the very large one?
34
35
               MR. GIOLDASIS: Yes.
               MS. ALDERSON: Is there a compelling need to remove it?
36
               MR. GIOLDASIS: The large tree is on a slope that the neighbor
37
```

- 1 that has the property on top is like concerned about the tree falling on
- 2 his property.
- 3 MS. ALDERSON: Well, I wouldn't have concern about that at this
- 4 point. I think that any tree of that size, we would need information from
- 5 an arborist if we were going to permit removal.
- 6 MS. TULLY: That's actually one of the trees that I had in mind
- 7 when I was talking about the tree protection plan.
- 8 MS. WRIGHT: So it does sound like if you have sufficient
- 9 information to approve the building plans, we could act on that but that
- 10 there are a number of questions about the grading, landscaping, tree
- 11 removal and paving plans and that that might need to come back as a
- 12 subsequent historic area work permit.
- 13 MS. O'MALLEY: Well, and I think part of the problem involved
- 14 with that is that we would want to see -- we always ask for tree protection
- 15 plans in place before construction begins. So, you would need to have your
- 16 fencing protection around those trees before you got your bulldozers into
- 17 the site or any other construction equipment, dumpsters or material trucks
- 18 so that they wouldn't be too close to the trees.
- MS. ALDERSON: You could pursue your permit but not beginning
- 20 construction until the protection is in place.
- MR. GIOLDASIS: All right.
- MS. O'MALLEY: It sounds as though most of the Commissioners are
- 23 all right with the actual construction. Did you have any questions?
- MS. ANAHTAR: We were trying to figure out whether the roofs are
- 25 correct the way that you're showing them. We're looking at the rear
- 26 elevation and the side elevation.
- MS. TULLY: Which circle?
- 28 MS. ANAHTAR: Circle 8, I believe. Yes.
- MS. TULLY: It was very confusing. Staff looked at it quite a
- 30 bit as well. I think it is -- it really is correct, though.
- 31 MS. O'MALLEY: One of the pages clarified it, oh circle 19.
- 32 There is some kind of cricket that goes down between or no incline.
- MS. ANAHTAR: Okay. Circle 19.
- 34 MS. TULLY: As I understand it, there is -- you're looking at
- 35 structural damage with your roof and so a lot of the existing roof will get
- 36 rebuilt. Is that correct?
- 37 MR. GIOLDASIS: Right.

- 1 MR. FULLER: I have a question.
- MS. O'MALLEY: All right, go ahead while they are studying the
- 3 plans.
- 4 MR. FULLER: On circle 13, the top picture, northeast elevation
- 5 looking south, is that a fire hydrant in front of the retainer wall? This
- 6 is a clarification item.
- 7 MR. GIOLDASIS: It might be by the the top picture on --
- 8 MR. FULLER: On circle 13, the top picture. It seems to be a
- 9 fire hydrant and behind it, there's a retainer. It looks like a retainer
- 10 wall or is that a --
- MS. O'MALLEY: Wasn't that -- didn't you have some kind of
- 12 plastic stuck in there to keep the dirt from washing out?
- 13 MR. GIOLDASIS: On the right-hand side of the picture?
- MS. O'MALLEY: Yes. The top picture to the right. Do you see
- 15 the fireplug there?
- MR. GIOLDASIS: No.
- MS. TULLY: Isn't it on the left? Are you calling it circle 16?
- MS. O'MALLEY: Circle 13.
- MR. FULLER: The top picture?
- MS. TULLY: Yes, right in the middle. There is a fire hydrant,
- 21 a sort of bottom kind of thing or a fire hydrant and then there, I think
- 22 it's just a temporary retaining wall.
- 23 UNIDENTIFIED SPEAKER: Silt fencing.
- MS. O'MALLEY: Silt fencing.
- MS. ALDERSON: Oh. Okay.
- MS. O'MALLEY: It's not a retaining wall.
- 27 UNIDENTIFIED SPEAKER: It's silt fencing.
- MR. GIOLDASIS: Oh, this here, yeah. Oh, that's for the soil.
- MS. O'MALLEY: For the dirt?
- 30 MR. GIOLDASIS: Yeah, for the dirt.
- 31 MS. ALDERSON: And that's part of the bomb jurisdiction that
- 32 you're looking at?
- 33 MR. GIOLDASIS: Right.
- MR. DUFFY: I have a question. On circle -- what is this, 8 --
- 35 circle 8, we're both architects and we're both having trouble reading these
- 36 drawings which could be a couple of things. Maybe we should be doing
- 37 something else. What is marked the southwest elevation at the top of --

- 1 MR. GIOLDASIS: Which page now?
- 2 MR. DUFFY: Circle 8.
- 3 MR. GIOLDASIS: Okay.
- 4 MR. DUFFY: The drawing shows there is a gable in the center and
- 5 this ridge, is it roughly the same height as the roof is lateral to it?
- 6 Now, on circle 19, which is the roof planner on the left side, it shows
- 7 that the ridges don't meet but that the roofs are left and right of the
- 8 gable in circle 8, are lower. Which drawing is correct or whatever? Are
- 9 either of them correct or both of them? The elevation and the roof pitch
- 10 don't match.
- MR. GIOLDASIS: I wish I had these plans earlier before so I
- 12 could meet with my architect so, I cannot answer your question.
- MR. DUFFY: The drawings are somewhat difficult to read
- 14 particularly with northwest and southwest being mislabeled without the
- 15 floor plans having a north arrow, without a site plan especially. I don't
- 16 -- you know, the project doesn't really bother me, but I can't really
- 17 understand what it is and I'm being asked to view with the documentation
- 18 that I have.
- 19 I don't know if anyone else feels likewise especially the site
- 20 plan and all. It's difficult to really judge very well without that.
- MS. WRIGHT: You're saying on circle 8, the drive at the top
- 22 shows the two area where it says, new addition, see plan. New addition,
- 23 see plan. And then when you look at the roof plan, it appears that those
- 24 two new additions and also, frankly, when you look, I think, at the lower
- 25 drawings on circle 8, it looks like those two new shallow gables coming in
- 26 at a lower level than the existing roof, so that the southwest elevation
- 27 drawing should reflect those shaded roof areas being lower than the central
- 28 roof area.
- MR. GIOLDASIS: Probably.
- 30 MS. TULLY: I think, in fact, that it may be that what you're
- 31 seeing, the existing roof, or the existing side gables or are both labeled
- 32 existing roof?
- MR. GIOLDASIS: On the top of 8, you mean?
- MS. TULLY: Yes.
- MR. DUFFY: Well, my point is that this can't be touching
- 36 exactly or, maybe it's the other way around but this and this are kind of
- 37 two different circles.

. 10

1 MS. WRIGHT: If the roof plan on circle 19 is sort of consistent

- 2 with the lower drawings on circle 8 --
- 3 MR. DUFFY: That's right.
- 4 MS. WRIGHT: If the upper drawing, let's call the southwest
- 5 elevation or circle 8 is inconsistent and you can see the existing roof in
- 6 this photograph. It's that gray roof with the ridge line that runs from
- 7 the front of the house to the back house. Because you can see up on the
- 8 screen.
- And the new addition would have a gable similar to the one
- 10 that's one the left that you see that would connect into that roof, but the
- ll question is does it connect in with the ridge lines meeting or does it
- 12 connect in at a slope slightly lower than the existing ridge line? And the
- 13 roof plans seem to show a lower level.
- 14 MS. ALDERSON: I would only venture one observation. Because the
- 15 property is so altered, I could
- 16 accept either, but as far as integrating with what remains, the older
- 17 building, I think the steeper pitch that takes it closer to the ridge is
- 18 more sympathetic with the historic massing, much more sympathetic. That's
- 19 a much, much shallower, more like a ranch house ridge.
- 20 So if that is an option to use the steeper high gable and have
- 21 it then join the ridge so that they come together, I think that's going to
- 22 be a more integrated design. It works better with what survives of the
- 23 historic fabric.
- MS. O'MALLEY: Do you understand what she means?
- MR. GIOLDASIS: Yes. Yes. I do.
- MS. ALDERSON: It would be sort of like the side gables would be
- 27 like that center cable that's there now.
- 28 MS. WRIGHT: And it would mean that the southwest elevation as
- 29 currently drawn on circle 8 would be accurate and your architect would need
- 30 to redraw the northwest and southeast elevations on circle 8 to show a
- 31 steeper gable that connects with the existing roof line. They would also
- 32 have to alter their roof plan.
- 33 MS. ALDERSON: It would make the rear of this house more
- 34 consistent of the front facade even though it is not visible from the
- 35 public right away, it would, I think, improve that facade from the view of
- 36 other historic buildings that will hook onto it.
- MS. O'MALLEY: Does that help you, Commissioner Duffy?

```
1
              MR. DUFFY: Yes.
 2
               MS. ALDERSON: And are you comfortable with that condition?
3
               MR. GIOLDASIS:
                               Yes.
                              Then I guess the question is, is staff
               MS. ALDERSON:
 4
     comfortable or are the other commissioners comfortable that, with that
 5
     condition, we could approve the plans and have it resolved at staff level
 6
      th the landscaping details to be brought back to the commission?
 7
                           Staff is comfortable with that.
 8
               MS. TULLY:
9
                                 It would make more sense.
               MR. DUFFY: Yes.
10
               MS. O'MALLEY: Do you want to make a motion?
               MS. ALDERSON:
                              I would like to make a motion that we approve
11
    application, with the conditions listed by staff adding to that revision of
12
    the southwest gables to be more consistent with the pitch of those on the
13
    front and that necessary landscape refinals will be brought back to the
14
     Commission with the other details to be worked out at staff
15
    building itself.
16
               MS. O'MALLEY: Could I ask that you note that we have not
17
18
    approved any tree removal?
                              Yes. I would like to include in that
19
               MS. ALDERSON:
     driveway modification and tree removal are not yet been approved at thi
20
     time, lacking sufficient information and that we would encour
21
22
      eservation of the cherry tree.
23
                               Is there a second?
               MS. O'MALLEY:
24
               MR. FULLER:
                              I second.
               MS. O'MALLEY: All right. All in favor of that motion?
25
26
               MR. GIOLDASIS:
                               Thank you.
                              Good luck. We'll look forward to seeing you
27
               MS. O'MALLEY:
28
    again.
29
               MR. GIOLDASIS: Thank you.
```



PLANT HEALTH CARE PROGRAM
Prepared for Spiro Gividasis Date 9-27-05
Prepared for Spiro Giuldasis Date 9-27-05 Service Address 9706 Capital View Nee
Phone Email

SAVA YREE.	Service A	uddress 400	6 Capital Vi	ew / ve	
he Tree and Shrub Care Company	Phone		Email		
o protect your valuable landscape, Satest technology in insect and disease indegradable and many have active in	control. Consistent with our comm	nitment to outdo	alth Care Program or excellence, all	n that incorp products use	orates the ed are fully
BASIC PROGRAM	•				
R1-Horticultural Oil Treatment: Only at the prevents harmful insents from emerginal mological sources as the active ingred	ting, such as Adelaids, Mealy Bug and	f Shales - Impument	t may siclude prort	icis denved 🦠	<u> </u>
RI-Spring Foliar Treatment: Treats en useds such as aphids, plant bugs and le	ty hatching, teal-eating insects such :	as carerphan , Lo	opers and Sawlers		
R0-2nd Spring Foliar Treatment: Treats	heavy copulations of leaf-eating inse	os nochra meg	odars		
74-Summer Foliar Treatment: Protects rdudino Adeigids, Beetles, Mites, Webwo			r warm weather is	RECTS	
R5-2nd Summer Foliar Treatment: Tre	als second broad of insects that profé	notice through a diese	weather sections M	lites.	
Scales and Whitelly. SPECIALINSTRUCTIONS: Leave Spread a T SPECIALTY TREATMENTS	e Wood chip mul CR2 of Tre		be		
Meni Soil Treatment: CLEarly CLA	Aid O Late Season Target:				
Fost si	3				
Disease Treatment: (please circle one)		iegralež _	applications @		
Hemlock Woolly Adelgid: (please sirch		Third	applications (d)		
other) CambisTaT / Arbon	Balance	1	applications @	75600	7.56
Other: 12"+18" ChesTAUT	and Sy" Silve M	hole	applications@		
Other:		·	applications@		
SavATree utilizes ArborHealth , our essential micro and macro nutrients. A development. ArborKelp is also availal	rborKelp*, our exclusive sea-kelp ba ble in a more concentrated form for a	ased biostimulan specialty use.	t is included to en	hance root	
-	Recommended usage: g.	•	izae 🖬 Ecto 🖨 Ur Iditives:		
to the second					
/vbcrHealth* Fertilization - Fall	Recommended usage:g	allana i fili arih			
	tecommended usageg		izae u Ecio u Oi iditives:		
ArborKelo* Biostimulant	2/火		. THE LOCAL COST IS NOT RELEASE IN THE SECOND OF		3849
	Recommended usage: SOO g	alions <i>Mysiorrhi</i> Va ou -	izae 🗆 Ecto 🔁 Ur	tiversa:	207
IN T IS CRESIDED TOTAL	400 31 3110 1 M	V. Otrerad	IGRIVOS:		
INTEGRATED TICK PROGR	AM				
			•		
Tick Treatment(s) Q Lawn & Ecotone	☐ Ecotone Only:		treatments @		
SUPPLEMENTAL TREATME					
U Fail Deer Repellent - Taste repellent					
Deer Repellent - Odor repellent used					
Deer Off Q Fall Q Winter Q Spring					
☐ Antidesiccant - Protects susceptible	evergreens from winter our a moist	une russ	treatments (g		
Special Instructions:	PRODUCTION OF SOME STATE	steally rene in a	r vavien nearmo	ris vear after	jegr. Any
Service MAR DE CANCELLED AT 21	r TME by contacting usit or to is	approation (man)	e you for your our	contentanto	ence in sa.
ARBORIST	0,		David N Weslo Mobile 301-34 Fax 301-680-8	13-1522	5800 X24
MOBILE	FAX	EMAIL	Email: dnwesl	ey a savarret	e.com

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 9706 Capitol View Avenue, Silver Spring Meeting Date: 07/13/05.

Applicant: Spiro Gioldasis Report Date: 06/30/05

Resource: Non-Contributing Resource **Public Notice:** 06/26/05

Capitol View Park Historic District

Tax Credit: Partial

Staff: Tania Tully

Case Number: 31/07-05F

PROPOSAL: Porch alterations and 2nd level addition.

RECOMMENDATION:
Approve with conditions

STAFF RECOMMENDATION

HAWP

Review:

Staff is recommending approval with the following conditions:

• Tree protection plan prepared by a certified arborist will be provided to staff and implemented onsite prior to any work beginning on the property.

• A grading / landscape plan will be provided to and approved by staff. This should indicate, at the minimum, any necessary retaining walls, locations and materials of the driveway and walkways.

• The rear patio will be concrete pavers rather than a slab.

• The windows will be wood simulated divided light windows, which contain muntins that are permanently bonded to the interior and exterior of the insulating glass simulating a divided light appearance.

• Minor detail changes and refinements will be provided to and approved by staff prior completion of the permit drawings.

• The applicant will present 3 permit sets of drawings to HPC staff for review and stamping prior to submission for permits.

PROPERTY DESCRIPTION

SIGNIFICANCE: Non-Contributing Resource

DATE: c.1908

9706 Capitol View Avenue is located at the southern tip of the Capitol View Historic District at a 90-degree bend in the road. The house sits on .21 acres and is visible from all directions except the south. The lot slopes down towards the north with a grade change of approximately 4 feet.

The house, though constructed c.1908, is nearly unrecognizable as an old building (Photos begin on Circle 11). The cladding is a mixture of plywood batten on board and asbestos shingles, and there is visible evidence of vertical beadboard underneath. It is evident from the form that the building has evolved over time. It consists of a 2 level central gable front block two rooms deep with a 2 level single room addition on each side. There is a 1-story addition on each side of the rear piece and an attached garage on the south. There is a small shed in the rear yard that is attached to a building on the adjacent property. Onsite it is difficult to determine the location of the property line.

Immediately adjacent properties include Fowler's Market/Forest Glen Country Store to the southeast (6 Post Office Road) and the Castle directly south (10 Post Office Road) – both Outstanding resources – and a Contributing 1 ½ story vernacular dwelling on the northwest at 9708 Capitol View Avenue. The lot is essentially un-landscaped with a number of large trees at the property lines.

DISTRICT INFORMATION

Significance

Capitol View Park is an example of a railroad community, which developed gradually over 100 years. The community's origin is representative of a number of railroad suburbs which developed following the opening of the Metropolitan Branch B&O. Most Capitol View structures possess little distinction as architectural entities. When grouped, however, these resources are a contiguous visual architectural example of suburban development styles.

Historic Information

Capitol View Park is a railroad community begun in 1887 when Mary and Oliver Harr purchased and subdivided land along the B&O's Metropolitan Branch between Forest Glen and Kensington. The community's name came from the view of the Capitol dome afforded by the upper stories of some of the early houses. Because of the growth of trees in intervening years, this view is no longer possible. Capitol View Park, however, continues to retain the scenic, rural setting which attracted its first inhabitants from Washington. Narrow, country lanes wind between large lots, the average of which is 12,000 square feet. Farmer Thomas Brown built a house in the post-Civil War era, before the railroad bisected his farm. Set back on a long curving driveway, Brown's dwelling still stands, known as the Case House, at 9834 Capitol View Avenue.

Unlike the homogenous suburban developments that make up a great deal of Montgomery County, Capitol View Park is a picturesque blend of many architectural styles dating from the 1890s to the 1980s. The community represents the architectural history of Montgomery County over the last century. The first houses built in Capitol View Park were designed in the Queen Anne style, characterized by their picturesque rooflines, large scale, numerous porches, and variety of building materials, including clapboard and fishscale shingles. Notable Queen Anne-style houses, built in the 1880s and 1890s, are found on Capitol View Avenue, Meredith Avenue, Lee Street, and Menlo Avenue. Residents built Colonial Revival style dwellings beginning in the 1890s. These dwellings feature classical details including cornices with entablatures, heavy window molding, and large round porch columns. Colonial Revival-style houses are found on Capitol View Avenue and Grant Avenue.

By the turn of the twentieth century, smaller-scale houses were becoming popular. Designed to harmonize with natural settings, these structures have a horizontal emphasis and were painted in natural tones. This group includes Bungalow- and Craftsman-style houses built from 1900 into the 1920s. Early examples are found on Stoneybrook Drive, Meredith Avenue, and Capitol View Avenue.

The pace of growth in Capitol View Park continued at a constant rate until the 1940s when a construction boom added nearly 50 houses to the community. Since then, houses have been added at a more leisurely rate, continuing the pattern of diversity that characterizes Capitol View Park.

APPLICABLE GUIDELINES

When reviewing alterations and new construction within the Capitol View Park Historic District several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the Approved & Adopted Sector Plan for Capitol View & Vicinity (Sector Plan), Montgomery County Code Chapter 24A (Chapter 24A), and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A

- A HAWP permit should be issued if the Commission finds that:
 - 1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
 - 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.
- In the case of an application for work on a historic resource located within a historic district, the Commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value surrounding historic resources or would impair the character of the historic district.

Secretary of the Interior's Standards for Rehabilitation:

- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

PROPOSAL

Replace enclosed front porch with an open porch
Remove existing 1-story rear additions
Construct a 2-story rear addition on each side of the existing 2-level rear block
Add a small rear patio
Replace two windows on the front elevation beneath porch
The existing asphalt roofs will be replaced in-kind (tax credit eligible)

Materials:

Porch – Wood railing

Stone veneer foundation Standing seam metal roof Permacast structural columns Slate porch floor Additions – Horizontal and board and batten Hardi Board siding to match the width & profile of the existing siding

Asphalt shingle roof.

Parged foundation

Windows – Wood double-hung Simulated Divided Light. – Likely Pella Architect Series Most existing windows will remain.

STAFF DISCUSSION

It is evident from a visit to the site why this property is a non-contributing resource. Except for the windows, there is little evidence of historic fabric or architectural details. The proposal presented in the application does nothing to make this dwelling more non-contributing and in the case of the porch, adds to its compatibility with the district. The proposal removes the existing enclosed porch and replaces it with an open porch more suited to a residence (Circle 7).

The additions are at the rear of the property and only minimally increase the lot coverage (Circle 8). The heights are equal to the existing side "wings" and lower than the main block of the house. Overall, the additions are compatible with the existing house and district. Staff's only concern is the northwest elevation, which will appear rather large and flat. The character of the house is one of symmetry paired with slight projections and the use of heavy trim. The northwest elevation would be more in character if the addition projected approximately 1 foot and additional windows were placed in the upper level. This would help break up the long expanse and further the feeling of the building having evolved over time. Staff also suggests that the trim around the new windows be wider. A minor suggestions is that the siding on the lower half of the addition by the garage be changed to horizontal like the other addition. Staff suggestions are illustrated on Circles 24 and 25.

In summary, with a few tweaks to the details and slight modification of the massing, staff finds that the proposal is in keeping with the appropriate review guidelines as applied to non-contributing resources. Suggested conditions for approval are listed on Circle 1. A site plan will be provided at the Worksession.

STAFF RECOMMENDATION:

Staff recommends that the Commission approve the HAWP application as being consistent with Chapter 24A-8(b)(1) & (2):

and with the Secretary of the Interior's Standards for Rehabilitation.

and provided the conditions listed on Circle 1 are met;

and with the general condition applicable to all Historic Area Work Permits that the applicant will present <u>3 permit sets</u> of drawings to HPC staff for review and stamping prior to submission for permits (if applicable). After issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will arrange for a field inspection by calling the DPS Field Services Office at 240-777-6370 prior to commencement of work <u>and</u> not more than two weeks following completion of work.





DPS -#

HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: SPINO GIOLDASIA

Daytime Phone No. 443-745-3940


ex Account the taken of Ecoperty Osyana SPU vigues 9201 COLE store theories	sville lloa	0 SWE	x spany	M) 20	910 In Code	Su
arrens rensums	and the second s	Service and a form of the service and	Phone No.		A GE VALAN	an elgen and those took young
ontractor Registration Ga.	•					
gent ice Openes	an et a la l	agen reaggraphic serve are no server and a self-thirty the little	Daysime Phone No	· Acceptance and the second se	To the second se	
OCATION OF BUILDING PREM	AISE					graven physiology (and the state of the stat
louse Number 9706	CHITOL	VIEW	Whome			
OWNER SILVER	SPUNG	earest Cross Street	POLETT	GUEN /	SEM IN	カンク
st Slack	Subdivision	· · · · · · · · · · · · · · · · · · ·		en en Primer (primeprimer), programmente, france, ingentente () . Standard (s., fordansia) and service of		feficien a teach accom
perFolio	Parcel:	sas i rai tein	and the relief of the temperature from the temperature to the temperat	mante modernmanger generalistis entre		
ART DNE: TYPE OF PERMIT	ACTION AND USE			·	***************************************	ativist de agricultura de
ia. Eneckall applicable.		CHECK AL	LAPPLICABLE:			
Congress L. Extend	** After/Removate	KA10	□ Slab □ Ben	m Addition 🔲 Parch	□ Deck □	Shed
Move 🔀 Install	Winck/Hara	. Solar	O Freeloce - O Wee	dauming Stove	□ Single fn	imily
: Reviews × Mapag	l Reviceble	T: Frace,	Wat reomplete Section 4) Diher:		
ir - Bibis io a revienn al a pieviai PAN 1WO: COMPLETCEOF					construction of the second of	che was ware
in Type of servege (#spose)	or in west	07 (1 Septic	63 🛄 Other, "		TOOM OF A STREET	
18 Type of water sumply	at 🗇 mase	02 LT Well	03 i ^m Other.		reactive transactions of agreements of the contractions of the contraction of the contrac	
ART THREE: COMPLETE ON	LY FOR FENCE/ILTAÍNING	WALL			9449888	secel-alian (Trofoce) recooniu
the Height						
ile—hole, at evalether the feace o	e retaining wall is to be constr	acted on one of the	tolioveng ionations			
Calgarty line/praperty (or	e Entrely en la	nd of owner	Ton public right	of wayleasement		
Appresed	thrilev to make the localisms of locality auknowledge and	rocent this to be a	ancheation is correct, condition for the issue.	$6/28/\varepsilon$,	th place
Disapproved	Segnature	an ton an annual mantante estimate est		Dete:		
Audicoronal erms Ive		Espain	Filed:	Date Issued		

SEE REVERSE SIDE FOR INSTRUCTIONS


 $\widehat{(5)}$



District - 13Account Number - 00996438




Property maps provided courtesy of the Maryland Department of Planning ©2004. For more information on electronic mapping applications, visit the Maryland Department of Planning web site at www.mdp.state.md.us/webcom/index.html




NORTHEAST ELEVATION OF PORCH


SCALE: 1/4" = 1'-0"


(4)




(A)











(II)











locking 5 on capital View







(14)








N Corner





2ND FLOOR LIGHTING/DEVICE PLAN

SCALE: 1/4" = 1'-0"

9706 CAPITOL VIEW AVE. SILVER SPRING, 4D


08/09/05

SHEE: MINGER


1ST FLOOR LIGHTING/DEVICE PLAN


SCALE: 1/4" = 1'-0"
















(7)







Staff Sugsestions $\langle E \rangle$ Ali (E) STUDY $\langle A \rangle$ FAMILY RM BEDRM #1 SITTING RM (E) EXISTING CONCRETE - HAMDRAIL @ 32" AFF BATHRM $\langle \overline{\mathsf{A}} \rangle$ SEE OWG A-5 FOR REPLACEMENT OF EXISTING FRAMING CLOS (D) GUARDRAIL @ 42" AFF PICKETS 1 X 1 @ 4" GC POSTS 3 X 3 @ 4" OC STAIRS OPEN TO BELO 0 0 (E) $\langle A \rangle$ BATHRM PORCH ∕/IN CLOSET (14) CONCRETE PAYIO $\langle \mathtt{A}
angle$ DINING RM BEDRM #2 $\langle E \rangle$ $\langle A \rangle$ $\langle A \rangle$ $\langle A \rangle$ $\langle B \rangle$ 5" CONCRETE SLAB ON GRADE W/ 1.4 Y 1.4, 6 X 5 WWF ON 95% COMPACTED EARTH DIMENSIONAL FLOOR PLAN LEGEND GARAGE ATTIC OVER GARAGE NEW INTERIOR NON-BEARING WALL EXISTING WALL TO REMAIN 1 DOOR NUMBER/TYPE PARTITION TYPE $\langle \overline{A} \rangle$ WINDOW TYPE SEAL типпи EXISTING DOOR & FRAME TO REMAIN 05/59/05 1ST FLOOR DIMENSIONAL PLAN 2ND FLOOR DIMENSIONAL PLAN FRANCE HOUSE SCALC: 1/4" = 1'-0" SCALE: 1/4" - 1'-0" toff, annahe.



toch Slate parch floor. Avi 301 963 1044 201 943 5521 wood rail - good stendy sem motal ray - ok Permacest Structural Columns Herdie Siding Stand be smooth Sile Plan Rail detail or cond. w Photos Existing Cond. - Elevations Inset Pickets Spiro Har 3940 443/745 3940 New Window Info aiold sig Project Lescrip. Remove a Rebuild part Forch -301 589.

2nd floor rear addition/rebuilding a partie of 1st level anciete rear pulio Replace 2 windows on fant under porch the factorRe build

Small Mirrors in Liter 7 Small Increase u footpuil

PHONE LOG

DONE	DATE	TIME	NAME	NUMBER	NOTES
	1				
-	*				
	*	1		· •	
					•
	•				
		7	•		
					·
					•
				•	
				•	
,					
		,		-	




























































































(4)





(Q)
























NORTHEAST ELEVATION OF PORCH SCALE: 1/4" = 1'-0"

06/09/05



Click here for a plain text ADA compliant screen.



Maryland Department of Assessments and Taxation MONTGOMERY COUNTY Real Property Data Search

Go Back View Map New <u>Search</u> **Ground** Rent

Account Identifier:

District - 13 Account Number - 00996438

Owner Information

Owner Name:

GIOLDASIS, SPIRO P

Use: Principal RESIDENTIAL

Residence:

Mailing Address: 9706 CAPITOL VIEW AVE

SILVER SPRING MD 20910-1028

Deed Reference:

1) 2)

YES

Location & Structure Information

Premises Address

9706 CAPITOL VIEW AVE SILVER SPRING 20910-1028 **Legal Description**

CAPITOL VIEW PARK

Plat No: Map Grid Parcel **Sub District Subdivision** Section **Block Lot** Assesment Area Plat Ref: P37 HP62 N556 5

Special Tax Areas

Town **Ad Valorem**

Tax Class 38

Primary Structure 1908		Enclosed Area 956 SF	Property Land Area 9,240.00 SF	County Use 111
Stories	Basement		Туре	Exterior
1	NO		STANDARD UNIT	FRAME
-	,,,			

Value Information

Base **Value Phase-in Assessments** Value As Of As Of 01/01/2004 07/01/2004 07/01/2005

Land: Improvements:

Preferential Land:

Total:

59,960 119,920 88,260

152,460 148,220 272,380

189,606 0 230,992

Transfer Information

Seller: WOLFE, DON M Type: IMPROVED ARMS-LENGTH	Date: 02/07/2005 Deed1:	Price: \$239,000 Deed2:
Seller: WOLFE, DON M Type: NOT ARMS-LENGTH	Date: 04/01/2003 Deed1: /23456/ 97	Price: \$0 Deed2:
Seller: ABSECON ASSOCIATES Type: NOT ARMS-LENGTH	Date: 11/15/2002 Deed1: /22283/ 193	Price: \$0 Deed2:

Exemption Information

Partial Exempt Assessments	Class	07/01/2004	07/01/2005	
County	000	0	0	
State	000	0	0	•
Municipal	000	0	0	
-				

Tax Exempt: Exempt Class:

NO

Special Tax Recapture:

* NONE *

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

W	RITTEN DESCRIPTION OF PROJECT
¥.	Description of existing structure(s) and environmental setting, including their historical features and significance:
b.	General description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:
S	<u>TEPLAN</u>
\$.	te and environmental potting, drawn to scale. You may use your plat. Your site plan must include:
8.	the scale, north arrow, and date;
b	dimensions of all existing and proposed structures; and
€.	site features such as welkways, driveways, tences, pends, streams, trash dumpsters, mechanical equipment, and landscaping.
P	LANS AND FLEVATIONS
M	on must submit 2 copies of plans and elevations in a format no larger than 11" x 12". Plans on 8 1/2" x 11" paper are preferred.
ð	Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
b	Elevations (fecades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.
ţ,	NATERIALS SPECIFICATIONS
	eneral description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on you estign drawings.
p	HOTOGRAPHS
а	Clearly labeled photographic prints of each facede of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
b	Clearly label photographic prints of the resource as viewed from the public right of-way and of the adjoining properties. All labels should be placed of the front of photographs.
3	REE SURVEY
	you are proposing construction adjacent to be existing the creative of any tree 6° or larger in diameter (at approximately 4 feet above the ground), you
11	tust file an accurate tree sorvey identifying the size, location, and species of each tree of at least that dimension.

F. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and conhonling property owners (not tenants), including names, addresses, and zip codes. This list should include the awners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Backwith (2017)79-13551



Date: July 14, 2005

MEMORANDUM

TO:

Spiro Giodasis

9201 Colesville Road, Suite 100

Silver Spring, MD 20910

FROM:

Tania Tully, Senior Planner

Historic Preservation Section

SUBJECT:

Historic Area Work Permit Application #389246 (9706 Capitol View Avenue)

Your Historic Area Work Permit application for Alterations was <u>Approved with Conditions</u> by the Historic Preservation Commission at its July 13, 2005 meeting.

Prior to applying for a county building permit from the Department of Permitting Services, you must **schedule a meeting** with your assigned staff person to bring your final construction drawings in to the Historic Preservation Office at 1109 Spring Street for stamping. Please note that although your work has been approved by the Historic Preservation Commission, it must also be approved by DPS before work can begin.

When you file for your building permit at DPS, you must take with you stamped drawings and an official approval letter (given at the time of drawing stamping). These forms are proof that the Historic Preservation Commission has reviewed your project. For further information about filing procedures or materials for your county building permit review, please call DPS at 240-777-6370.

If your project changes in any way from the approved plans, either before you apply for your building permit or even after the work has begun, please contact the Historic Preservation Commission staff at 301-563-3400.

Please also note that you must arrange for a field inspection for conformance with your approved HAWP plans. Please inform DPS/Field Services at 240-777-6210 or online at http://permits.emontgomery.org of your anticipated work schedule.

Thank you very much for your patience and good luck with your project!

HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

9706 Capitol View Avenue, Silver Spring

Meeting Date:

07/13/05

Applicant:

Spiro Gioldasis

Report Date:

06/30/05

Resource:

Non-Contributing Resource

Public Notice:

06/26/05

Capitol View Park Historic District

Tax Credit:

Partial

Review:

HAWP

Staff:

Tania Tully

Case Number:

31/07-05F

PROPOSAL:

Porch alterations and 2nd level addition.

Approve with conditions

STAFF RECOMMENDATION

RECOMMENDATION:

aff is recommending approval with the following conditions:

Tree protection plan prepared by a certified arborist will be provided to staff and implemented onsite prior to any work beginning on the property.

A grading / landscape plan will be provided to and approved by staff. This should indicate, at the minimum, any necessary retaining walls, locations and materials of the driveway and walkways.

The rear patio will be concrete pavers rather than a slab.

The windows will be wood simulated divided light windows, which contain muntins that are permanently bonded to the interior and exterior of the insulating glass simulating a divided light appearance.

Minor detail changes and refinements will be provided to and approved by staff prior completion

of the permit drawings.

The applicant will present 3 permit sets of drawings to HPC staff for review and stamping prior to

PROPERTY DESCRIP

to be consisted

SIGNIFICANCE:

Non-Contributing Resource

DATE:

c.1908

9706 Capitol View Avenue is located at the southern tip of the Capitol View Historic District at a 90degree bend in the road. The house sits on .21 acres and is visible from all directions except the south. The lot slopes down towards the north with a grade change of approximately 4 feet.

The house, though constructed c.1908, is nearly unrecognizable as an old building (Photos begin on Circle 11). The cladding is a mixture of plywood batten on board and asbestos shingles, and there is visible evidence of vertical beadboard underneath. It is evident from the form that the building has evolved over time. It consists of a 2 level central gable front block two rooms deep with a 2 level single room addition on each side. There is a 1-story addition on each side of the rear piece and an attached garage on the south. There is a small shed in the rear yard that is attached to a building on the adjacent property. Onsite it is difficult to determine the location of the property line.

Immediately adjacent properties include Fowler's Market/Forest Glen Country Store to the southeast (6 Post Office Road) and the Castle directly south (10 Post Office Road) – both Outstanding resources – and a Contributing 1 ½ story vernacular dwelling on the northwest at 9708 Capitol View Avenue. The lot is essentially un-landscaped with a number of large trees at the property lines.

DISTRICT INFORMATION

Significance

Capitol View Park is an example of a railroad community, which developed gradually over 100 years. The community's origin is representative of a number of railroad suburbs which developed following the opening of the Metropolitan Branch B&O. Most Capitol View structures possess little distinction as architectural entities. When grouped, however, these resources are a contiguous visual architectural example of suburban development styles.

Historic Information

Capitol View Park is a railroad community begun in 1887 when Mary and Oliver Harr purchased and subdivided land along the B&O's Metropolitan Branch between Forest Glen and Kensington. The community's name came from the view of the Capitol dome afforded by the upper stories of some of the early houses. Because of the growth of trees in intervening years, this view is no longer possible. Capitol View Park, however, continues to retain the scenic, rural setting which attracted its first inhabitants from Washington. Narrow, country lanes wind between large lots, the average of which is 12,000 square feet. Farmer Thomas Brown built a house in the post-Civil War era, before the railroad bisected his farm. Set back on a long curving driveway, Brown's dwelling still stands, known as the Case House, at 9834 Capitol View Avenue.

Unlike the homogenous suburban developments that make up a great deal of Montgomery County, Capitol View Park is a picturesque blend of many architectural styles dating from the 1890s to the 1980s. The community represents the architectural history of Montgomery County over the last century. The first houses built in Capitol View Park were designed in the Queen Anne style, characterized by their picturesque rooflines, large scale, numerous porches, and variety of building materials, including clapboard and fishscale shingles. Notable Queen Anne-style houses; built in the 1880s and 1890s, are found on Capitol View Avenue, Meredith Avenue, Lee Street, and Menlo Avenue. Residents built Colonial Revival style dwellings beginning in the 1890s. These dwellings feature classical details including cornices with entablatures, heavy window molding, and large round porch columns. Colonial Revival-style houses are found on Capitol View Avenue and Grant Avenue.

By the turn of the twentieth century, smaller-scale houses were becoming popular. Designed to harmonize with natural settings, these structures have a horizontal emphasis and were painted in natural tones. This group includes Bungalow- and Craftsman-style houses built from 1900 into the 1920s. Early examples are found on Stoneybrook Drive, Meredith Avenue, and Capitol View Avenue.

The pace of growth in Capitol View Park continued at a constant rate until the 1940s when a construction boom added nearly 50 houses to the community. Since then, houses have been added at a more leisurely rate, continuing the pattern of diversity that characterizes Capitol View Park.

APPLICABLE GUIDELINES

When reviewing alterations and new construction within the Capitol View Park Historic District several documents are to be utilized as guidelines to assist the Commission in developing their decision. These documents include the Approved & Adopted Sector Plan for Capitol View & Vicinity (Sector Plan), Montgomery County Code Chapter 24A (Chapter 24A), and the Secretary of the Interior's Standards for Rehabilitation (Standards). The pertinent information in these documents is outlined below.

Montgomery County Code; Chapter 24A

- A HAWP permit should be issued if the Commission finds that:
 - 1. The proposal will not substantially alter the exterior features of a historic site or historic resource within a historic district.
 - 2. The proposal is compatible in character and nature with the historical archaeological, architectural or cultural features of the historic site or the historic district in which a historic resource is located and would not be detrimental thereto of to the achievement of the purposes of this chapter.
- In the case of an application for work on a historic resource located within a historic district, the Commission shall be lenient in its judgment of plans for structures of little historical or design significance or for plans involving new construction, unless such plans would seriously impair the historic or architectural value surrounding historic resources or would impair the character of the historic district.

Secretary of the Interior's Standards for Rehabilitation:

- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportions, and massing to protect the integrity of the property and its environment.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

PROPOSAL

- · Replace enclosed front porch with an open porch
- •Remove existing 1-story rear additions
- Construct a 2-story rear addition on each side of the existing 2-level rear block
- · Add a small rear patio
- Replace two windows on the front elevation beneath porch
- *The existing asphalt roofs will be replaced in-kind (tax credit eligible)

Remove ?

Sheed

Tree Romova

Materials:

Porch -

Wood railing

Stone veneer foundation Standing seam metal roof Permacast structural columns

Slate porch floor

retaining wall

Additions – Horizontal and board and batten Hardi Board siding to match the width & profile of the existing siding

Asphalt shingle roof.

Parged foundation

Windows – Wood double-hung Simulated Divided Light. – Likely Pella Architect Series Most existing windows will remain.

STAFF DISCUSSION

It is evident from a visit to the site why this property is a non-contributing resource. Except for the windows, there is little evidence of historic fabric or architectural details. The proposal presented in the application does nothing to make this dwelling more non-contributing and in the case of the porch, adds to its compatibility with the district. The proposal removes the existing enclosed porch and replaces it with an open porch more suited to a residence (Circle 7).

The additions are at the rear of the property and only minimally increase the lot coverage (Circle 8). The heights are equal to the existing side "wings" and lower than the main block of the house. Overall, the additions are compatible with the existing house and district. Staff's only concern is the northwest elevation, which will appear rather large and flat. The character of the house is one of symmetry paired with slight projections and the use of heavy trim. The northwest elevation would be more in character if the addition projected approximately 1 foot and additional windows were placed in the upper level. This would help break up the long expanse and further the feeling of the building having evolved over time. Staff also suggests that the trim around the new windows be wider. A minor suggestions is that the siding on the lower half of the addition by the garage be changed to horizontal like the other addition. Staff suggestions are illustrated on Circles 24 and 25.

In summary, with a few tweaks to the details and slight modification of the massing, staff finds that the proposal is in keeping with the appropriate review guidelines as applied to non-contributing resources. Suggested conditions for approval are listed on Circle 1. A site plan will be provided at the Worksession.

STAFF RECOMMENDATION:

Staff recommends that the Commission approve the HAWP application as being consistent with Chapter 24A-8(b)(1) & (2):

and with the Secretary of the Interior's Standards for Rehabilitation.

and provided the conditions listed on Circle 1 are met;

and with the general condition applicable to all Historic Area Work Permits that the applicant will present <u>3 permit sets</u> of drawings to HPC staff for review and stamping prior to submission for permits (if applicable). After issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant will arrange for a field inspection by calling the DPS Field Services Office at 240-777-6370 prior to commencement of work <u>and</u> not more than two weeks following completion of work.







HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: SPINO GIONASIA

Daytime Phone No. 443-745-3940

				Phone No.:	The second second is the second secon
				Daytime Prioric No :	**************************************
OCATION OF BUI	LDING/PREM	ISE -AA	(بم ا	1.5.5	
cess Number	4706	CAPITOL	- VIEWet	AVGOUE	CALA IADASTY
				POPELL CREY	
PARTONI: TYPE	, , , , , , , , , , , , , , , , , , , ,	CTION AND USE		4 Press 52+ 6 PSI W.	
ia cueckallapi		~		APPLICABLE	Figure Figure Figure
_3 Construct		X Assey Benovele	`	 ○ Slate	
Move		Vheck/Barr		Walf (complete Section 4) Units	
: Revided		F. Resposible	,		The state of the s
					The state of the s
 (a) (b) (1980) (b) (c) (c) (c) (c) (d) 					
PARTIWO: CON	APLETE FOR N	EW CONSTRUCTION A	NO EXTENO/ADDIT	IONS	agencember 1880 1879 (September 1881 1990) 1880 (1880) 1880 (1880) 1880 (1880) 1880 (1880) 1880 (1880) 1880 (1
PARTIWO: CON	MPLETE FOR N	A MOITQURTENOO WEE	NO EXTENO/ADOLT 07 (*! Septic	IONS 83 口 Juhes,	
PART IWO: CON	ΛΡ <u>UET(FOR N</u> pa dispesal:	A MOITQURTENOO WEE	NO EXTENO/ADOLT 07 (*! Septic	IONS	
PART IWO: CON 26 Yopé of sérvas 28 Ingrid system	MPLETÇ FOR N pa disposal: euspiy	A MOITQURTENOO WEE	NO EXTEND/ADDIT 07 (*) Septic 02 (*) Well	IONS 83 口 Juhes,	
PART IWO: CON 24 - Typi of sewer 28 - Typi of wein 28 - Typi of wein PART THREE: CO	MPLETÇ FOR N pa disposal: euspiy	IEW CONSTRUCTION A 01 VISSC 01 J VISSC YFOR FENCEMETAINIA	NO EXTEND/ADDIT 07 (*) Septic 02 (*) Well	IONS 83 口 Juhes,	
PART IWO: COM TO TOP OF SEWAY TO THE SEWAY THE SEWAY	MPLETE FOR N per disposal; supply: SMPLETE ONL inet	IEW CONSTRUCTION A 01 VISSC 01 J VISSC YFOR FENCEMETAINIA	NO EXTENO/ADDIT 0? (1 Septic 02 (2 We4	IONS 63 [] Other, 03 [] Other:	


SEE REVERSE SIDE FOR INSTRUCTIONS




Maryland Department of Assessments and Taxation MONTGOMERY COUNTY Real Property Data Search

Go Back View Map New Search

District - 13Account Number - 00996438



Property maps provided courtesy of the Maryland Department of Planning ©2004. For more information on electronic mapping applications, visit the Maryland Department of Planning web site at www.mdp.state.md.us/webcom/index.html




WOOD PAIL


GRACE 1-1


NORTHEAST ELEVATION OF PORCH

SCALE: 1/4" = 1'-0"


(4)
























(F)



N Cornel







2ND FLOOR LIGHTING/DEVICE PLAN

SCALE: 1/4" = 1'-0"


1ST FLOOR LIGHTING/DEVICE PLAN
SCALE: 1/4" = 1"-0"








9708 CAPTOL VIEW AVE. PPOLECT VEVES







(7)







State Suggestions $\langle E \rangle$ 1-3 (Ē) . STUDY $\langle \underline{\mathbf{A}} \rangle$ BEDPM #1 FAMILY RH $\langle \mathbf{A} \rangle$ $\langle E \rangle$ EXISTING CONCRETE HANDRAIL 9 32" AFF \parallel_{\odot} BATHRM $\langle A \rangle$ KITCHEN $\langle {f E} \rangle$ ₹<u>Ā</u>) SEE DWG A-5 FOR PEPLACEMENT OF EXISTING FRAMING cLos $\langle c \rangle$ STAIRS OPEN TO BELO MASTER BEDPU 0 EXISTING FOYER $\langle E \rangle$ BATHRM CLOS(15) W/IN CLOSET 14 CONCESTE $\langle \mathtt{A}
angle$ DIMING RM DAY RM REDRM #2 (E) $\langle A \rangle$ $\langle A \rangle$ $\langle B \rangle$ $\langle A \rangle$ 5" CONCRETE SLAB ON GRADE W/ 1.4 Y 1.4, 5 X 5 WWF ON 95% COMPACTED FARTH DIMÉNSIONAL FLOOR PLAN LEGEND GARAGE ATTIC OVER GARAGE NEW INTERIOR MON-BEARING WALL ① DOOR NUMBER/TYPE PARTITION TYPE $\langle A \rangle$ WINDOW TYPE EXISTING DOOR & FRAME TO REMAIN NEW DOOR 01/09/05 <u> 181 FLOOR DIMENSIONAL PLAN</u> 2ND FLOOR DIMENSIONAL PLAN TRAINES MARIE SCALL: 1/4" = 1'-0" SCALE: 1/4" - 1"-0" THE CHARLE






TRANSMITTAL SHEET

Historic Preservation Office Department of Park & Planning

Telephone Number: (301) 563-3400	Fax Number: (301) 563-3412
TO: Spiro Gioldasis	FROM: ANTA
301 589 0768	Tucky
DATE: 7/13/05	5 po W
NOTE: Here is the staff	report for
torights meeting.	
v	

NOTE : THIS LOCATION IS VALID FOR 180 DAYS FROM THE DATE ON THE PLAN.


NOTE: This location for title purposes only - not to be used for determining property lines. Property corner Markers Not guaranteed by this location



)

NOTE : THIS LOCATION IS VALID FOR 180 DAYS FROM THE DATE ON THE PLAN.

NOTE: This location for title purposes only - not to be used for determining property lines. Property corner Markers Not guaranteed by this location





SILVER SPRING, MARYLAND 20910

Historic Preservation Commission July 13, 2005

Attn: Tania Tully
HAWP 31/7-05F

On July 11, the Historic review committee presented to the Capitol View Park Citizen's Association executive board meeting a proposal for porch alterations and a 2nd level addition at 9706 Capitol View avenue. This property is a Non-contributing resource which is in poor condition. The board was pleased that improvements will be made to this property which sets near the south entrance to our Historic district.

A site plan is needed to address planting and placement of the driveway. The Board agrees with HPC staff that windows need to be added to the Northwest portion of the structure.

The property is between two Outstanding resources and a contributing vernacular dwelling and this proposal will enhance these properties especially when they too have renovations.

The Executive Board concurs with HPC staff recommendations of approval with conditions.

Betsy Tebow, President Capitol View Park Citizens Association

Carol Ireland, Co-chair
Duncan Tebow, Co-chair
Capitol View Park Historic Review Committee

