# ROBIN

37/3-01KK 7063 Carroll Avenue (Takoma Park Historic District)



### THE ROLYN COMPANIES

- Construction Consulting
- Disaster Restoration
- General Contracting

### Timothy L. LeBon

301/468-1553 ext. 609 • Fax: 301/468-6744 • Toll Free: 800/808-1553 E-mail: tlebon@rolyncompanies.com 12312 Wilkins Avenue • Rockville, Maryland 20852

		Date:_		
<u>MEMORAN</u>	NDUM	_		
TO:	Robert Hubbard, Director Department of Permitting Services	ä		
FROM:	Gwen Wright, Coordinator Historic Preservation			
SUBJECT:	Historic Area Work Permit			
	oproved (NOTE CHANGES Moproved with Conditions:			
<del></del> -			17.	
	aff will review and stamp the construction g permit with DPS; and	drawings pri	or to the appl	cant's applying
11.4	DING PERMIT FOR THIS PROJECT SH CE TO THE APPROVED HISTORIC AI		The second secon	
Applicant:	BRUNO MUKENDI			
Address: =	2013-5			

and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online @ permits. emontgomery.org prior to commencement of work and not more than two weeks following completion of work.

.



MONTGOMERY COUNTY
DEPARTMENT OF PERMITTING SERVICES
255 Rockville Pike, 2<sup>nd</sup> Floor
Rockville, Maryland 20850-4166

## **NOTICE OF VIOLATION**

FOR MONTGOMERY COUNTY, MARYLAND the undersigned issuer, being duly authorized, st	'
On, Taylace 24 03 the recipient of this NOTICE, TSHIABUKU	E MUKENDI
who represents the permittee/defendant, TSHIABUKILE MU	KENDI
Lenning 2 union	
is notified that a violation of Montgomery County Code, Section: 24A-6/a) (7)	
exists at: 7063 CARRICL AVE TAKOMA PARK	mD
Location	Case # 199909382
The violation is described as: Removed The Transition Dur	ends Carting son
The violation is described as: Removed the front our  FREE OFFICIALS A HISTORIC AREA WITH	16 PERMIT
	TO THE RESERVE TO THE PARTY OF
The following corrective action(s) must be performed immediately as directed,	NAME OF TAXABLE
AND WIRE PERMIT	
	Topic Argentina in the second in the second
See attached inspection Report(s) for additional violations and/or required com-	motion setting
	A ST WARMAN
An inspection fee of \$ 82.50 is required in addition to any application fee(s).	
Compliance Time: Re-inspection Date(s): Permit Number:	Code/Edition:
"我们就是我们的,我们就没有一个人,我们就是我们的,我们就没有一个人,我们就没有一个人,我们就没有一个人,我们就没有一个人。""我们就是我们的,我们就会没有一个	
Failure to comply with this notice will result in the Issuance of one or more \$500.	00 civil citations.
A STOP WORK ORDER Is also issued this date at the above referenced project. All co these premises must cease immediately. Only those activities required to correct violations m is required to resume construction.	
ISSUED BY: HETE HRYCAIC RELEASING	1-29:03
Printed Name Signature.	Dale
Phone No	
RECEIVED BY:	C. Date
	1-29-02
Phone No Sent by Registered Mail/Return Receipt On:	- P
RECIPIENT'S SIGNATURE ACKNOWLEDGES RECEIPT OF A COPY OF THIS NOTI	CF OF VIOLATION

This Notice may be appealed to the Montgomery County Board of Appeals within 30 days of the issue date. The Board of Appeals is located in the Council Office Building, 100 Maryland Ave., Room 217, Rockville, MD 20850, telephone (240) 777-6600.



### ON

760

4	Date: 2-5-03
MEMORA]	<u>NDUM</u>
ГО:	Robert Hubbard, Director Department of Permitting Services
FROM:	Gwen Wright, Coordinator Historic Preservation
SUBJECT:	Historic Area Work Permit  DPS PERMIT# 294437 F
application f	omery County Historic Preservation Commission has reviewed the attached for an Historic Area Work Permit. This application was:
A <sub>1</sub>	pproved (NOTE CHANGS MARKED ON DRAWINGS)
A <sub>J</sub>	pproved with Conditions:

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Address: 70103 CARROLL AVE. TAKORIA FREK HO

and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online @ permits. emontgomery.org prior to commencement of work and not more than two weeks following completion of work.



### DEPARTMENT OF PERMITTING SERVICES

Douglas M. Duncan County Executive

Robert C. Hubbard Director

# COMMERCIAL BUILDING CONSTRUCTION INSPECTION REQUIREMENTS

In order to improve service, and to facilitate the scheduling of inspection requests, please use the inspection codes listed to the left of each inspection type for scheduling the inspections required for new construction, renovations and additions.

When calling for inspections, please have the address to be inspected (as it appears in the premise address section of your permit), the permit number and the type of inspection required.

### REMINDER

- 1. All inspection requests for the following workday must be called in before 12:00 Noon.
- 2. Multi-Family Buildings and swimming pools are considered Commercial Structures.
- Alterations not requiring new foundations or structural framing.

  These types of alterations are normally identified as alterations related to tenant spaces.

### CODES

1. 070 (Walls) 071 (Ceiling)

1st Inspection: close-in of walls, ceilings and shafts.

This inspection must be conducted after all firestopping, mechanical, plumbing and electrical rough-ins are completed. None of the above elements shall be concealed until the building inspector conducts the

close-in inspection.

2. 251

2nd Inspection: Final inspection.

This inspection is conducted after all work per approved plans and

specifications is completed.

### II. NEW CONSTRUCTION AND ADDITIONS

A. 255

Pre-Construction Conference:

Before commencing the construction, the owner or his/her designee shall call (240) 777-6210 to schedule a pre-construction meeting for the purpose of discussing the County's inspection requirements, approved plans and related matters. It may require principal parties to the construction process attend this meeting during which an Inspector will represent the Department of Permitting Services (DPS).

Notice: Failure to schedule a pre-construction meeting before commencing construction may result in the issuance of a civil citation.

# MONTGOMERY COUNTY DEPARTMENT OF PERMITTING SERVICES COMMERCIAL BUILDING REVIEW

MONTOOME APPROVED DIV. OF BUILDING

Project: 7063 Carroll Avenue

Codes: MBRC/2000 IBC

ADAAG 1994/COMAR 1995

Reviewer: Robin Ferro

Phone: 240-777-6250/FAX 240-777-6241

**Building Information:** 

Use Group: R-2

Permit #: 294437

Date: 12/30/02

Const. Type: VB

Sprinklered: no

Floor Area: 300 5

Height: 1 story/ft.

Plan review based on Maryland Building Rehabilitation Code, category of work is addition.

- 1. IBC 1003.2.12 & NFPA 7.2.2.4.6 Guards: Guardrails shall be at least 42 inches in height measured vertically above the leading edge of the tread or adjacent walking surface which is locate more than 30 inches above the floor or grade below.
- 2. IBC 1003.3.3.3 & NFPA 7.2.2.2.1(a) Stair treads and risers: Stair riser heights shall be 7" maximum and 4 "minimum. Stair tread depths shall be 11" minimum.
- 3. IBC 1003.3.3.11.1 & NFPA 7.2.2.4.5 Handrail Height: Handrail height measured above stair tread nosing, or finish surface of ramp slope, shall be uniform, not less than 34 " and nor more than 38".
- 4. IBC 1003.3.3.11.3 & NFPA 7.2.2.4.5(4) Handrail graspability. Handrails with a circular cross section shall have an outside diameter of at least 1.25 inches (32 mm) and not greater than 2 inches (51 mm) or shall provide equivalent graspability. If the handrail is not circular, it shall have a perimeter dimension of at least 4 inches (102 mm) and not greater than 6.25 inches (159 mm) with a maximum cross-section dimension of 2.25 inches (57 mm). Edges shall have a minimum radius of 0.125 inch (3.2 mm).
- 5. IBC 1003.3.3.11.5 & NFPA 7.2.2.4.5 (6) Handrail extensions: Where handrails are not continuous between stair flights, the handrail shall extend horizontally at least 12 inches beyond the top riser and continue to a slope for the depth of one tread beyond the bottom riser.

- 6. 056 <u>Walls Masonry (Interior Walls)</u>: All rebars must be in place. Clean out holes to remain open until inspection.
- 7. Walls Reinforced Concrete (Exterior Foundation Walls): All rebars must be in place at time of inspection.
- 8. 057 <u>Walls Reinforced Concrete (Interior Walls)</u>: All rebars must be in place at time of inspection before placing concrete.
- 9. 065 <u>Parging, Waterproofing, Dampproofing</u>: All debris must have been removed from perimeter of foundation at time of inspection.
  - a. Concrete Walls Heavy tar applied to all areas where form ties will be below grade. Inspection to occur prior to application of sprayed or mopped tar.
  - b. Masonry Walls All parging complete. Inspection to occur prior to sprayed or mopped tar.
- 10. 066 Location Wall Check: Upon completion of the foundation walls or perimeter footings and before any construction is placed upon such foundation walls or footings obtain two copies of a location plat certified by a land surveyor showing the actual location of the building with respect to property lines and existing buildings or structures on the same lot. A professional engineer entitled to practice in Maryland may provide such certification only where property lines and corners are already existing and determined on the ground.
- 11. 070 Wall Close-In or Interior Framing or Concealment: All firestopping and all mechanical, electrical and plumbing rough-in must be in place prior to inspection.

  Note: If structural steel is involved all certification as to steel assembly and connections are due at this time, prior to inspection.
- 12. O71 Ceiling Close-in: All plumbing, electrical, and mechanical rough-ins are to be complete at this inspection. If plenum, all items to be placed in plenum area are to be in place at the time of this inspection. All required draftstops and firestopping are to be complete. If drop-in suspended ceiling is used, all gridwork is to be complete and secured.
- 13. 072 <u>Columns Reinforced Concrete</u>: All formwork and rebars to be in place prior to inspection and placing of concrete.
- 14. 069 <u>Structural Concrete Slabs</u>: All formwork, sleaves and rebar installations to be in place prior to inspection and placing of concrete.
- 15. O58 Structural Steel Assembly (S): This Special Inspection includes the determination that members are properly located sized, and in accordance with approved plans; checking of setting of anchor bolts and base plates; determining that members are plumb.

COUNTY ; NOTED ONSTRUCTION CONTROLS CONSTRUCTION PECATETIANS OF THE BESIDNES RAMING CONTROLS (\$46) 777-8810 RED SON LIBER A PROCONSTRUCTION BELIEFED RESPECTOR.

LIFEURE TO DO SO MAY REFULT IN A CIVIL CITATION FER CHOTION FER CHOTION 645 (H) OF THE SUILDING CODE OF MONTCOMERY COUNTY.

7063 CARROLL AVENUE TAKOMA PARK, MD 20912 (MONTGOMERY COUNTY)

PROPOSED FRONT PORCH REPLACEMENT DUE TO VEHICLE DAMAGE

CONTRACTOR:

ROLYN CONSTRUCTION COMPANY 2312 WILKING AVENUE ROCKVILLE, MD 20852

DRAWN BY:

REESE DESIGN LTD.

15 TYGART COURT

GAITHERSBURG, MD 20879

DATE: NOVEMBER 25, 2002 SCALE: A"=1-0" CODE ANALYSIS

USE GROUP - R2

TIPE CONST. - 500

FULLY SUPPRESSED - NO

FILLY SUPPRESSED -

REMARKS: (SCOPE OF WORK)
REMOVE & REPLACE EXISTING WOOD
PORCH. ALL MATERIALS TO BE
LIKE KIND AND QUALITY AS
EXISTED. FLOOR AREA TO
BE 300 SO FT. AS EXISTED.

MONTGOMERY COUNTY
DIVISION OF SUIDING CONSTRUCTION

Those plans are conditionally approved in accordance with any correction notes on plans. The building permit is fidence to construct in accordance with advoted code and does not waive any order requirements not note; during plan review. Issuance of permit does not prevent field inspectors from ordering corrections to meet codes when iscues are noted during inspections.

Approvals: Arch. PRF Life Salety. RFF
Struct. AM Mech. N/A Elec. N/A

Permit Number: 294437


APPROVED


Montgomery County


Historic Preservation Commission

12/5/03

294437(F)







COUNTY NOTED ONSTRUCTION COTTO OT: (240) 777-8819 AUDISCHILLULE A PROCONSTRUCTION LETTING WITH THE PIELD INSPECTOR.

FALURE TO DO SO MAY REFULL IN A CIVIL CITATION PER ABOTION

7063 CARROLL AVENUE TAKOMA PARK, MD 20912 (MONTGOMERY COUNTY)

PROPOSED FRONT PORCH REPLACEMENT DUE TO VEHICLE DAMAGE

CONTRACTOR:

ROLYN CONSTRUCTION COMPANY 12312 WILKING AVENUE ROCKVILLE, MD 20852

DRAWN BY:

REESE DESIGN LTD. 15 TYGART COURT GAITHERSBURG, MD 20879

DATE: NOVEMBER 25, 2002 SCALE: 4 = 1-0"

8-123 (H) OF THE BUILDING CODE OF MONTCOLLERY COUNTY. CODE ANALYSIS USE GROUP - R2 THE CONST. - 52 ILLY SUPPRESSED - HID RANGE HAND/ALER-300 SQ. FT.

REMARKS: (SCOPE OF WORK) REMOVE & REPLACE EXISTING WOOD FORCH ALL MATERIALS TO BE LIKE KIND AND QUALITY AS

MONTGOMERY COUNTY DIVISION OF BUILDING CONSTRUCTION


These plans are conditionally approved in accordance with any correction roles on plans. The building per is fluence to construct in accordance with adepted a and does not walvo any code receivements that note: during blan review. Issuance of permit does not prevent field inspectors from ordering corrections to meet couled when iscues are noted during inspections


Approvals: Arch. RF Life Saisty. KFF


Struct. AM Mech. N/A Elec. N/A

Permit Number: 294437

294437(F)









### DEPARTMENT OF PERMITTING SERVICES

Douglas M. Duncan
County Executive

Robert C. Hubbard

Director

# COMMERCIAL BUILDING CONSTRUCTION INSPECTION REQUIREMENTS

In order to improve service, and to facilitate the scheduling of inspection requests, please use the inspection codes listed to the left of each inspection type for scheduling the inspections required for new construction, renovations and additions.

When calling for inspections, please have the address to be inspected (as it appears in the premise address section of your permit), the permit number and the type of inspection required.

### REMINDER

- 1. All inspection requests for the following workday must be called in before 12:00 Noon.
- 2. Multi-Family Buildings and swimming pools are considered Commercial Structures.
- Alterations not requiring new foundations or structural framing.

These types of alterations are normally identified as alterations related to tenant spaces.

### **CODES**

1. 070 (Walls)

1st Inspection: close-in of walls, ceilings and shafts.

071 (Ceiling)

This inspection must be conducted after all firestopping, mechanical, plumbing and electrical rough-ins are completed. None of the above elements shall be concealed until the building inspector conducts the

close-in inspection.

2. 251

2nd Inspection: Final inspection.

This inspection is conducted after all work per approved plans and

specifications is completed.

### II. <u>NEW CONSTRUCTION AND ADDITIONS</u>

A. 255

Pre-Construction Conference:

Before commencing the construction, the owner or his/her designee shall call (240) 777-6210 to schedule a pre-construction meeting for the purpose of discussing the County's inspection requirements, approved plans and related matters. It may require principal parties to the construction process attend this meeting during which an Inspector will represent the Department

of Permitting Services (DPS).

Notice: Failure to schedule a pre-construction meeting before commencing construction may result in the issuance of a civil citation.

# MONTGOMERY COUNTY DEPARTMENT OF PERMITTING SERVICES COMMERCIAL BUILDING REVIEW

MONTOUME APPROVED DIV. OF BUILDING

Project: 7063 Carroll Avenue

Codes: MBRC/2000 IBC ADAAG 1994/COMAR 1995

Reviewer: Robin Ferro

Phone: 240-777-6250/FAX 240-777-6241

Permit #: 294437 Date: 12/30/02

**Building Information:** 

Use Group: R-2

Const. Type: VB

Sprinklered: no

Floor Area: 300 €

Height: 1 story/ft.

Plan review based on Maryland Building Rehabilitation Code, category of work is addition.

- 1. IBC 1003.2.12 & NFPA 7.2.2.4.6 Guards: Guardrails shall be at least 42 inches in height measured vertically above the leading edge of the tread or adjacent walking surface which is locate more than 30 inches above the floor or grade below.
- 2. IBC 1003.3.3.3 & NFPA 7.2.2.2.1(a) Stair treads and risers: Stair riser heights shall be 7" maximum and 4 "minimum. Stair tread depths shall be 11" minimum.
- 3. IBC 1003.3.3.11.1 & NFPA 7.2.2.4.5 Handrail Height: Handrail height measured above stair tread nosing, or finish surface of ramp slope, shall be uniform, not less than 34 " and nor more than 38".
- 4. IBC 1003.3.3.11.3 & NFPA 7.2.2.4.5(4) Handrail graspability. Handrails with a circular cross section shall have an outside diameter of at least 1.25 inches (32 mm) and not greater than 2 inches (51 mm) or shall provide equivalent graspability. If the handrail is not circular, it shall have a perimeter dimension of at least 4 inches (102 mm) and not greater than 6.25 inches (159 mm) with a maximum cross-section dimension of 2.25 inches (57 mm). Edges shall have a minimum radius of 0.125 inch (3.2 mm).
- 5. IBC 1003.3.3.11.5 & NFPA 7.2.2.4.5 (6) Handrail extensions: Where handrails are not continuous between stair flights, the handrail shall extend horizontally at least 12 inches beyond the top riser and continue to a slope for the depth of one tread beyond the bottom riser.

- 6. 056 <u>Walls Masonry (Interior Walls)</u>: All rebars must be in place. Clean out holes to remain open until inspection.
- 7. 054 <u>Walls Reinforced Concrete (Exterior Foundation Walls)</u>: All rebars must be in place at time of inspection.
- 8. 057 <u>Walls Reinforced Concrete (Interior Walls)</u>: All rebars must be in place at time of inspection before placing concrete.
- 9. O65 Parging, Waterproofing, Dampproofing: All debris must have been removed from perimeter of foundation at time of inspection.
  - a. Concrete Walls Heavy tar applied to all areas where form ties will be below grade. Inspection to occur prior to application of sprayed or mopped tar.
  - b. Masonry Walls All parging complete. Inspection to occur prior to sprayed or mopped tar.
- 10. 066 Location Wall Check: Upon completion of the foundation walls or perimeter footings and before any construction is placed upon such foundation walls or footings obtain two copies of a location plat certified by a land surveyor showing the actual location of the building with respect to property lines and existing buildings or structures on the same lot. A professional engineer entitled to practice in Maryland may provide such certification only where property lines and comers are already existing and determined on the ground.
- 11. 070 Wall Close-In or Interior Framing or Concealment: All firestopping and all mechanical, electrical and plumbing rough-in must be in place prior to inspection.

  Note: If structural steel is involved all certification as to steel assembly and connections are due at this time, prior to inspection.
- 12. O71 Ceiling Close-in: All plumbing, electrical, and mechanical rough-ins are to be complete at this inspection. If plenum, all items to be placed in plenum area are to be in place at the time of this inspection. All required draftstops and firestopping are to be complete. If drop-in suspended ceiling is used, all gridwork is to be complete and secured.
- 13. O72 <u>Columns Reinforced Concrete</u>: All formwork and rebars to be in place prior to inspection and placing of concrete.
- 14. 069 <u>Structural Concrete Slabs</u>: All formwork, sleaves and rebar installations to be in place prior to inspection and placing of concrete.
- 15. O58 Structural Steel Assembly (S): This Special Inspection includes the determination that members are properly located sized, and in accordance with approved plans; checking of setting of anchor bolts and base plates; determining that members are plumb.



### DEPARTMENT OF PERMITTING SERVICES

Douglas M. Duncan County Executive

Robert C. Hubbard *Director* 

# HISTORIC AREA WORK PERMIT

IssueDate:

11/1/2001

Permit No:

262303

Expires: X Ref: Rev. No:

**Approved With Conditions** 

THIS IS TO CERTIFY THAT:

BRUNO MUKENDI

12613 STRATFORD GARDEN DRIVE

SILVER SPRING MD 20904

HAS PERMISSION TO:

**CONSTRUCT** 

PERMIT CONDITIONS:

HANDICAP RAMP/PARTIAL PAVING/PARKING

PREMISE ADDRESS

7063 CARROLL AVE

TAKOMA PARK MD 20912-

LOT 1

PERMIT FEE:

BLOCK 16

PARCEL

ZONE

LIBER FOLIO

\$0.00

ELECTION DISTRICT

3 PLATE

GRID

SUBDIVISION

TAX ACCOUNT NO.:

**COLESVILLE OUTSIDE** 

HISTORIC MASTER: HISTORIC ATLAS:

Y

HISTORIC APPROVAL ONLY BUILDING PERMIT REQUIRED

Director, Department of Permitting Services

Phone: (240) 777-6370



### DEPARTMENT OF PERMITTING SERVICES

Douglas M. Duncan County Executive

Robert C. Hubbard Director

### HISTORIC AREA WORK **PERMIT**

IssueDate:

11/6/2001

Permit No:

262705

Expires: X Ref: Rev. No:

**Approved With Conditions** 

THIS IS TO CERTIFY THAT:

**BRUNO MUKENDI** 

12613 STAFFORD GARDEN SILVER SPRING MD 20904

HAS PERMISSION TO:

**CONSTRUCT** 

PERMIT CONDITIONS:

handicapped ramp

PREMISE ADDRESS

7063 CARROLL AVE

TAKOMA PARK MD 20912-

LOT 1

PERMIT FEE:

BLOCK

PARCEL

ZONE

**LIBER FOLIO** 

\$0.00

16 ELECTION DISTRICT

**PLATE** 

**GRID** 

**SUBDIVISION** 

TAX ACCOUNT NO.:

COLESVILLE OUTSIDE


HISTORIC MASTER: HISTORIC ATLAS:

Y

HISTORIC APPROVAL ONLY **BUILDING PERMIT REQUIRED** 

Director, Department of Permitting Services

Phone: (240) 777-6370



APPROVED

Montgomery County

Historic Preservation Commission (10/3//9/)

Histo

STUP

6 LASEL MTL OPT. MTC. OPT. MT. OPT. MTC. OPT REI-1ARKS B LABEL B LABEL to basel म्मान्त्र निदर्भ HARDIARRE 정자 CLOSET DOOR A S KEY LOCK Key Lack y S KEY 100 X 0 SCHEDILE PROM E Uso 0 X TT タだ。 1000x ۲۲ Y F Soci SIZE Door 2°×68 23 x68 25×68 26×68 24 x 608 2°× 68 \$9×% **Ø**₹ 1 4 Ŋ WD. Holloy Conf WO. FIBER CAR WO Hollald call 119. MBER CONE DESCRIPTION WO THER CORE WO FIBER COLEB IN THINK 尼子 S Ð

(0/31/01 reviewed by HPC First Dar altertions have Not been 504

SYSTEM DESCRIPTION

GA FILE NO. FC 5420

# WOOD JOISTS, GYPSUM WALLBOARD

<sup>5</sup>/<sub>8</sub>/<sup>1</sup> type X gypsum wallboard or veneer base applied at right angles to 2 x 10 wood joists 16 ° 0.c. with 6d coated nais 1<sup>3</sup>/<sub>8</sub>/ long 0.0915 \*sham; 1/4\* heads, 6° 0.c. Joists Supporting 1\* nominal wood sub and finish floor, or 18/2\* plywood finished floor long edges 1 & G and 13/2\* interior plywood with exterior glue subfloor perpendicular to joists with joints staggered.

SKETCH AND DESIGN DATA

Approx. Ceiling Weight. 21/2 pst Fire Test. UL R3501-5, 9, 7-15-52 UL R1319-2, 3, 6-5-52 Design L 501 ULC Design M500 Sound Test See FC 5410 IIC & Test. 32 (66 C & P) NGC 5032, 7-19-66

15' 240 & SCALOOOR ASSEMBLY


Montgomery County
Historic Preservation Commission
(10|31|01)

EXHIBIT 1.

**ENTRY DOORS** 


### **MILLWORK**

Orepac Millwork



6-Panel Exterior Fir Door Slab

Orepac Millwork



EXISTING

FRONT DOOR |

N

### **ENTRY DOORS**

### **MILLWORK**




### **Orepac Millwork**



XPropose d

**Orepac Millwork** 

Existing




RIGHT SIDE DOOR EXISTING

### 6-Panel Exterior Fir Door Slab

1 3/4-in. thick. Beveled raised panels. Dowel construction. 4 1/2-in. wide stiles. Unfinished.

Size In.	Mfr. No.	SKU	Price Each
32 x 80	NW-2130-2/8	378554	\$139.00
36 x 80	NW2130-3/0	378571	145.00



### Exterior Paneled Fix Door Slab with Lite

1 3/4-in. thick. Vertical grain. Single glass. 4 1/2-in. stiles. Dowel construction. Unfinished.

Size .	Lite Style	Mfr. No.	SKU	Price Each
12 x 80	Fan	F-2/8 2020 3/4	378926	\$169.00
36 x 80	Fan	NW-2020-3/0	378960	174.00



### **Exterior Fir French Door Slab**

1 3/4-in. thick solid wood. 15 lites. Dowel construction. Unfinished.


Size In.	Mfr. No.	sĸù	Price Each
30 x 80	F-2/6 1515EXT	105511	\$144.00
32 x 80	F-2/8 1515EXT	105538	144.00
36 x 80	NW-1515-3/0	105546	149.00

Not All Products Available in All Markets




# EXHIBIT 3

# PROPOSED



REAR DOOR PROPOSED



REAR DEOR - EXISTING

### MONTGOMERY COUNTY DEPARTMENT OF PARK AND PLANNING

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

8787 Georgia Avenue Silver Spring, Maryland 20910-3760

March 11, 2002

### **MEMORANDUM**

TO:

Robert Hubbard, Director

Department of Permitting Services

FROM: Gwen Wright, Coordinator Historic Preservation

SUBJECT: Historic Area Work Permit 37/3-01 /4 Revision

The Montgomery County Historic Preservation Commission has reviewed the attached application for a Historic Area Work Permit. This application was:

Approved	Denied <u>X</u>	Approved with Conditions
----------	-----------------	--------------------------

- The front door will not be replaced, but will be repaired. 1.
- The applicant to work with staff and DPS to determine what is required under the building 2. codes. If possible, the rear door will be repaired rather than replaced. If an agreement cannot be reached with the applicant and staff, the applicant will return to the HPC.
- 3. The applicant to work with staff and DPS to determine what is required under the building codes. If possible, the right side door should be repaired rather than replaced. If so required by DPS, the door may be replaced but the new door shall match the existing door in style and material. A solid door, without glazing, is permissible. If an agreement cannot be reached with the applicant and staff, the applicant will return to the HPC.
- 4. The front porch will be repaired in kind, and ceramic tile will not be installed.
- 5. The applicant will work with staff on the recessed porch lighting. The use of lights on the wall by the front door would also be permissible.

and subject to the general conditions that 1) HPC Staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS; and 2) after issuance of Montgomery County Department of Permitting Services (DPS) permit, applicant to arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work and not more than two weeks following completion of work.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Bruno Mukendi at 7063 Carroll Avenue, Takoma Park, MD 20912 Applicant:

### HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

7063 Carroll Avenue

Meeting Date:

2/27/02

Applicant:

Bruno Mukendi

Report Date:

2/20/02

Resource:

Takoma Park Historic District

Public Notice:

2/13/02

Review:

HAWP

Tax Credit:

Project Number:

37/3-01KK REV

Staff:

Robin D. Ziek

PROPOSAL:

Replace doors; extend paving by 10', install ceramic tile floor on front porch,

install recessed lights on porch.

**RECOMMEND**: Approval with Conditions:

1. The front door will not be replaced, but will be repaired.

2. The rear door will not be replaced, but will be repaired.

3. The right side door may be replaced, if so required by DPS, but the new door shall match the existing door in style and material. A solid door, without glazing, is permissible.

4. The front porch will be repaired in kind, and ceramic tile will not be installed.

5. The applicant will work with staff on the recessed porch lighting. The use of lights on the wall by the front door would also be permissible.

### PROJECT DESCRIPTION

SIGNIFICANCE:

Contributing Resource in the Takoma Park Historic District

STYLE:

Craftsman

DATE:

c1910

The applicant was approved for a HAWP on October 24, 2001. This 2-1/2 story frame house is sided with stucco. The property is zoned commercial and has several apartments now. The applicant has talked about making this a B&B. The previous HAWP addressed parking and accessibility needs. The applicant had thought that the front door needed to be fire-rated, but has subsequently learned that it doesn't need to be fire-rated (see Circle ).

### **PROPOSAL**

The applicant proposes to replace the front door (see Circle 5-7), the existing right side door (see Circle 3), and the rear door (see Circle 3). In addition, he

writed on white to the construct of the construction of the con

(

would like to increase the parking area by no more than 10' at the rear (see Circle / O). In addition, he notes that the front porch floor is wood, and is in need of repair. He proposes to replace the wood floor with ceramic tile. Finally, the applicant proposes to install recessed lighting on the front porch. The applicant has been told that the side door has to be fire-rated, as it is part of the stairway/egress system. The back door doesn't have to be fire-rated, although the applicant is concerned that the width comply with ADA, as the handicapped ramp leads to this rear door.

### **STAFF DISCUSSION**

The applicant should replace original fabric only when the materials are beyond repair, or when required under local health/safety codes.

### DOORS:

Staff notes that the existing **front door** is a typical Craftsman-style door. Most notable is the use of a tall row of vertical panels beneath the glazed portion. This door should be repaired rather than replaced. The design of the proposed new front door is incompatible with the site.

Both the existing **right side door** and the **rear door** are also typical early 20<sup>th</sup> century paneled door, with horizontal panels and ½-lights. The applicant proposes a 6-paneled door more typical of Colonial Revival for the side door replacement, and a 4-paneled door with a faux fanlight (see Circle 5, 9). Neither style of replacement door is compatible with the Craftsman style of the house.

The **rear door** does not have to be fire-rated, and this door should be repaired rather than replaced. The ADA width is 32" and this door opening provides 34" clear (information from the applicant).

The **right side door** is included in a fire egress sequence, and apparently doesn't meet the code requirements. As the code varies depending on the number of occupants of the building, the layout, the construction, and the presence or absence of sprinklers, staff does not feel qualified to comment on this request with regard to code requirements. In terms of historic preservation, staff notes that this existing door is the same type of door as the rear door, and *should be retained if this will meet the building code requirements*. If the swing on this door simply needs to be reversed, the door should be repaired and re-hung. If the door needs to be fire-rated, the new door should match the style of the existing door.

### PORCH:

Deterioration of wood floors on front porches is a maintenance requirement for anyone with such a porch. Typical maintenance repairs are best done on a yearly cycle. If the porch is deteriorated, the porch and the flooring should be repaired in kind. Tax credits from the local, state and, in this case, federal levels are all available to the applicant to assist with these normal

maintenance costs. The proposed use of ceramic tile would be inconsistent with the resource, and incompatible with the historic district, and should not be pursued.

The proposed use of recessed lighting in the ceiling of the porch is acceptable in theory. The applicant should provide more information to the commission as to the location and number of lights. More typical would be lights attached to the wall at the door, to light the entrance. The applicant might wish to consider this.

### **STAFF RECOMMENDATION**

Staff recommends, with the following Conditions, that the Commission find this proposal consistent with the purposes of Chapter 24A-8(b)2:

The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site, or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;

and with Secretary of the Interior's Standards for Rehabilitation #2:

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

### CONDITIONS:

- 1. The front door will not be replaced, but will be repaired.
- 2. The rear door will not be replaced, but will be repaired.
- 3. The right side door may be replaced, if so required by DPS, but the new door shall match the existing door in style and material. A solid door, without glazing, is permissible.
- 4. The front porch will be repaired in kind, and ceramic tile will not be installed.
- 5. The applicant will work with staff on the recessed porch lighting. The use of lights on the wall by the front door would also be permissible.

and subject to the general condition that the applicant shall present 3 permit sets of drawings to HPC staff for review and stamping prior to submission for building permits (1 set for HPC files) and that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work and not more than two weeks following completion of work.

Bruno Mukendi 7063 Carroll Avenue Takoma Park, MD 20912

February 11, 2002

Mrs. Roben D. Ziek Historic Preservation Planner MCDPP- Historic Preservation Section Silver Spring, MD 20910

Dear Mrs. Ziek:

This is in reference to the on-going renovation work at 7063 Carroll Avenue, Takoma Park. I would like to request the authorization to carry out the following work.

### 1. Replace the existing front door

The existing front door needs to be replaced by a fire-rated door. Both the existing and the proposed doors are shown in Exhibit 1.

### 2. Replace the existing right side door

The right side exterior door has to be replaced by a fire-rated door. Exhibit 2 shows the existing and the proposed doors.

### 3. Replace the rear door.

I want to replace the existing rear door which is too old by a new door. The existing and the proposed doors are shown in Exhibit 3.

### 4. Paving

Due to the size of the ramp and in order to allow more traffic flexibility in the rear parking, I need to extend the paving to up to 10 feet. I still have a lot of space. (See Exhibit 4).

### 5. Front Porch

The existing porch is made in wood and most of it has been damaged. I want to replace the wood by ceramic tile. I also want to put recess lights in the porch.

Please do not hesitate to contact me should you have any questions. My telephone number is (301) 270-8232.

Sincerely.

. Bruno Mukendi

Owner

# EXHIBIT 1

### ENTRY DOORS


### MILLWORK




Orepac Millwork

Orepac Millwork

EXISTING



6-Panel Exterior Fir Door Slab



FRONT DOOR EXISTING.

Bruno Mukendi 7063 Carroll Avenue Takoma Park, MD 20912

February 19, 2002

Mrs. Robin D. Ziek Historic Preservation Planner MCDPP- Historic Preservation Section Silver Spring, MD 20910

Dear Mrs. Ziek:


I understand that the front door does not need to be fire rated. In this case, I submit the attached proposed front door for consideration. It would be economical to keep both options (this proposal and the previous one) open.

Sincerely,

T. Bruno Mukendi

Owner

# PROPOSED FRONT DOR



Door J71 shown

Available at The Home Depot

7063 Carroll Arenny Takoma Park, MD 20912

### **ENTRY DOORS**

### **MILLWORK**

# 唱


### **Orepac Millwork**



XInoposed

### **Orepac Millwork**

Existing



Size 32 ) 36 )


2-I

1 3/

### 6-Panel Exterior Fir Door Slab

1 3/4-in, thick. Beveled raised panels. Dowel construction, 4 1/2-in, wide stiles. Unfinished.

Size In.	Mfr. No.	SKU	Price Each
32 x 80	NW-2130-2/8	378554	\$139.00
36 x 80	NW2130-3/0	378571	145.00





### Exterior Paneled Fir Door Slab with Lite

1 3/4-in. thick. Vertical grain. Single glass. 4 1/2-in. stiles.

Dowel construction. Unfinished.

Size In.	Lite Style	Mfr. No.	SKU	Price Each
32 x 80	Fan	F-2/8 2020 3/4	378926	\$169.00
× 00	Fan	NW-2020-3/0	378960	174.00



1 3/4-in, thick solid wood. 15 lites. Dowel construction. Unfinished.


Size In.	Mfr. No.	SKU	Price Each
30 x 80	F-2/6 1515EXT	105511	\$144.00
32 x 80	F-2/8 1515EXT	105538	144.00
36 x 80	NW-1515-3/0	105546	149.00

Not All Products Available in All Markets




# EXHIBIT 3

# PROPOSED




REAR DOOR PROPOSED



REAR DOOR - EXISTING
34" wide

ADA stipulates 32" usatch.
(4.13)




VYFHUIS & ASSOCIATES
LAND SURVEYORS, ENGINEERS, PLANNERS
3112 RHODE ISLAND AVENUE, NE.
WASHINGTON DISTRICT OF COLUMBIA

(10)


Eclectic Houses.

America countries to



//






Poplar

Knotty Pine


Becky Fink, Machinist Company Employee Since 1983 On Craftsmanship

As A Machinist, I Make Parts For Doors Out Of A Variety Of Woods. Each wood species has its own characteristics, and some are not easy to machine. I run these woods on a moulder. This machine cuts the various profile designs for the L.C. Schmidt Signature Door Series.

The moulder is very precise—with a tolerance of 10/1000 of an inch. You can barely see 10/1000 of an inch! Here at CDC, people have worked for years to achieve that kind of precision. I never imagined any company would put so much time into perfecting their product before I worked here. But since then, I've discovered that craftsmanship isn't. something you master, it's something that you're always striving to learn.



Pine CDC-732 Half Louver



VYFHUIS & ASSOCIATES
LAND SURVEYORS, ENGINEERS, PLANNERS
3112 RHODE ISLAND AVENUE, NE.
WASHINGTON DISTRICT OF COLUMBIA

M



#### MONTGOMERY COUNTY DEPARTMENT OF PARK & PLANNING

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

8787 Georgia Avenue Silver Spring, Maryland 20910-3760

October 26, 2001

N	1E	M	OR	$\mathbf{AN}$	ND.	UM

TO:

Robert Hubbard, Director

Department of Permitting Services

Gwen Wright, Coordinator Historic Preservation

SUBJECT:

Historic Area Work Permit 37/3-01KK

The Montgomery County Historic Preservation Commission has reviewed the attached application for a Historic Area Work Permit. This application was:

<u>X</u>	Approved	Denied	Approved with Conditions:
----------	----------	--------	---------------------------

and subject to the general conditions that 1) HPC Staff will review and stamp the construction drawings prior to the applicant's applying for a building permit with DPS; and 2) after issuance of Montgomery County Department of Permitting Services (DPS) permit, applicant to arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work and not more than two weeks following completion of work.

#### THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE APPROVED HISTORIC AREA WORK PERMIT (HAWP).

Applicant:

Bruno Mukendi

12613 Stafford Garden Silver Spring, MD 20904

RE: 7063 Carroll Avenue, Takoma Park Historic District





DPS - #8

## HISTORIC PRESERVATION COMMISSION 301/563-3400

## APPLICATION FOR HISTORIC AREA WORK PERMIT

	Contact Person: 15120140 140 1681111
•	Daytime Phone No.: <u>(301)</u> 270 - 8232
Tax Account No.:	
Name of Property Owner: PSUNG [AUKISUD]	Daytime Phone No.: 2/301/270 - 8232
Address: 1243 STRAFFER GRANDER City	35. MD. 2090V
Street Number City	Staet Zip Code
Contractorr:	Phone No.:
Contractor Registration No.:	
Agent for Owner: KEI 7h O. Prade's	Daytime Phone No.: 202-882-3389
LOCATION OF BUILDING/PREMISE	
House Number: 7063 CANA / Town/City: 724617/2 //  Nearest Cross	Street CANON AVE
Inwn/City TAKOIDA PL Nearest Cross	Street TUCIP RVG
Lot:/ Block:/ Subdivision:	011001.
Liber: Folio: Parcel:	
i dite.	
PART ONE: TYPE OF PERMIT ACTION AND USE	,
1A. CHECK ALL APPLICABLE: CHE	CK ALL APPLICABLE:
IZ Construct ☐ Extend ☐ Alter/Renovate ☐ A	VC □ Slab □ Room Addition □ Porch □ Deck □ Shed
☐ Move ☐ Install ☐ Wreck/Raze ☐ S	Solar
☐ Revision ☐ Repair ☐ Revocable ☐ F	Fence/Wall (complete Section 4) Uther: H.C. RAMP  FORTICE PRINCIP
1B. Construction cost estimate: \$/	PARTICL PAVINGS
1C. If this is a revision of a previously approved active permit, see Permit #_	X/B
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND/A	DUITIONS
2A. Type of sewage disposal: 01 🗆 WSSC 02 🗀 Septi	
2B. Type of water supply: 01 ☐ WSSC 02 ☐ Well	
zb. Type of water supply.	03
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
3A. Heightfeetinches	
3B. Indicate whether the fence or retaining wall is to be constructed on one	of the following locations:
☐ On party line/property line ☐ Entirely on land of owner	☐ On public right of way/easement
I hereby certify that I have the authority to make the foregoing application, the approved by all agencies listed and I hereby acknowledge and accept this to	at the application is correct, and that the construction will comply with plans be a condition for the issuance of this permit.
Lota DRella	SEP-7-0/
Signature of owner or authorized agent	Date
111	
711	Chairperson, Historic Preservation Commission
Disapproved: Signature:	Date: /0/29/0/
Application/Permit No:	Date Filed: Date Issued:

	REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.
1.	WRITTEN DESCRIPTION OF PROJECT
	a. Description of existing structure(s) and environmental setting, including their historical features and significance:

	he house is Victorian style. In the bulk, there is
6	decle and a line backing and with three parking
_5	fects, one if while is hunderafe fushing line is
4	no emition was produced that the this
$\rightarrow$	ion the Might
$-\Pi$	
C	al description of project and its effect on the historic resource(s), the environmental setting, and, where applicable, the historic district:
Gener	al description of project and its effect on the historic resource(s), the environmental setting, and, where approache, the historic district.
<del></del>	Build an handicap ramp with rices
=	Build an hardical Bango The acco
	·
_	

#### 2. SITE PLAN

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

#### 3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred.

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

#### 4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

#### 5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

#### 6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

#### 7. AOORESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/high/way from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

PLEASE PRINT (IN BLUE OR BLACK INK) OR TYPE THIS INFORMATION ON THE FOLLOWING PAGE.
PLEASE STAY WITHIN THE GUIDES OF THE TEMPLATE, AS THIS WILL BE PHOTOCOPIEO OIRECTLY ONTO MAILING LABELS.

7063 Carroll Avenue Takoma Park, MD 20912

October 3, 2001

Mrs. Roben D Ziek Historic Preservation Planner MCDPP Silver Spring, MD

Dear Mrs. Ziek:

Please find attached my neighbors, property and mailing addresses. I believe that the addresses in the application I submitted yesterday are only property addresses.

Please do not hesitate to contact me should you have any questions.

Sincerely,

Bruno Mukendi (301) 270-8232

## EXPEDITED HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address: 7063 Carroll Avenue Meeting Date: 10/24/01 Applicant: Bruno Mukendi Report Date: 10/17/01 Resource: Takoma Park Historic District Public Notice: 10/10/01 Review: **HAWP** Tax Credit: No Project Number: 37/3-01KK Staff: Robin D. Ziek PROPOSAL: Install additional parking at rear, provide handicapped ramp at rear **RECOMMEND**: Approval **DATE OF CONSTRUCTION:** ca. 1910s SIGNIFICANCE: Individual Master Plan Site X Within a Master Plan Historic District Primary Resource

**ARCHITECTURAL DESCRIPTION:** 2-1/2 story Craftsman frame structure, with stucco siding and wood trim. Commercially zoned property.

X Contributing Resource

Non-Contributing/Out-of-Period Resource

**PROPOSAL:** The applicant proposes to provide additional parking at the rear. The lot is flat, and there are no trees in the immediate vicinity. The applicant also proposes to build a wood handicapped ramp to the rear door, that would be similar to the handicapped ramp on the adjacent property (Savory).

**RECOMMENDATION:** <u>X</u> Approval Approval with conditions:

Approval is based on the following criteria from Chapter 24A of the Montgomery County Code, Section 8(b): The commission shall instruct the director to issue a permit, or issue a permit subject to such conditions as are found to be necessary to insure conformity with the purposes and requirements of this chapter, if it finds that:

X 1. The proposal will not substantially alter the exterior features of an historic site, or historic resource within an historic district; or



RETURN TO: DEPARTMENT OF PERMITTING SERVICES
255 ROCKVILLE PIKE, 2nd FLOOR, ROCKVILLE, MD 20850
240/777-6370

DPS - #8

## HISTORIC PRESERVATION COMMISSION 301/563-3400

# APPLICATION FOR HISTORIC AREA WORK PERMIT

			Contact P	erson: BRUHO	lankeno1	
			Daytime I	ع - حب 2   Phone No.: <u>  30</u> /	1270-8232	
Tax Account No.:				<del></del>		
Name of Branch Owner Rich	NO MUKEN	101	Davtime F	Phone No. 2/30	1/270-823	2
Address: /243 57 Street Number	Tracker 1 to C	response	35. M	7 ·	20801	
Street Number	THE GIVE V	City		Staet	Zip Code	
Contractorr:				Phone No.:		
Contractor Registration No.:						
Agent for Owner: KE17h				Phone No.: 202-	882-338	
LOCATION OF BUILDING/PREM			<i>a</i> .			
House Number: 7063 Town/City: 74KG19A	CANAL '	Street	:	my/ plus	·	
Town/City: TAKOIDA	PL	Nearest Cross Street	:	CIP AVG		
Lat: / Black:	/6 Subdivision	n:				
Liber: Folio:						
PART ONE: TYPE OF PERMIT A	CTION AND LISE					
1A. CHECK ALL APPLICABLE:	OTTOM AND OSE	CHECK AI	<u>L applicable</u> :			
	☐ Alter/Renovate		☐ Slab	_	□ Berch □ Dock (	Chad
	_				□ Porch □ Deck t	
☐ Move ☐ Install	☐ Wreck/Raze		•	☐ Woodburning Stov	•	•
•	☐ Revocable	☐ Fenc <b>e</b> /	Wall (complete)	Section 4) 🔲 Oth	PARTIC PAVI	<b>Λ</b> ζ¬
1B. Construction cost estimate: \$						
1C. If this is a revision of a previous	y approved active permit,	see Permit #	H/12			
PART TWO: COMPLETE FOR NI	W CONSTRUCTION A	ND EXTEND/ADDIT	IONS			
2A. Type of sewage disposal:	01 □ WSSC	02 🗌 Septic	<b>03</b> C	Other:		
2B. Type of water supply:	01 🗆 WSSC	02 🗌 Well				
						_
PART THREE: COMPLETE ONLY	FOR FENCE/RETAININ	IG WALL				
3A. Heightfeet	inches					
3B. Indicate whether the fence or i	etaining wall is to be cons	structed on one of the	following locati	ions:		
On party line/property line	☐ Entirely on	land of owner	☐ On put	olic right of way/easem	ent	
I hereby certify that I have the autho	neity to make the foregoing	a application, that the	application is	porroat, and that the en	netruotion will comply wil	h plans
approved by all agencies listed and						n pians
0	,	, ,			/	
	SIO DING	162		3UP	- 7-0/	
Signature of ow	mer or authorized agent				Date	
Approved:		For Chair	nerson Historia	c Preservation Commiss	sian	
		i vi cilali	porson, maidri	_		
Disapproved:	Signature:			ں	ate:	

Application/Permit No.: \_

## THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

	The same of the sa	
RITTEN DESCRIPTION OF PROJECT	returns,	San
Description of existing structure(s) and environmental setti	ng including their historical features and significa	ince.
The house in Victoria		Luch, there is
a decle and a los	backtyand with	three parking
spots, one of white	1 13 handicato	earling They
of no emiltoniant	in wroslern He	it can/arise
hour Ha Inopil		
		· · · · · · · · · · · · · · · · · · ·
	· · ·	
General description of project and its effect on the historic re	esource(s), the environmental setting, and, where	applicable, the historic district:
- Levelor addition	ed harbine she	ots in the rear of
- Develop add too	up ramp inthe	ots in the rear if I
	1 7 7	Proceedings of the second of the

#### 2. SITE PLAN

1.

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as walkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landscaping.

A Commence of the Commence of

#### 3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17". Plans on 8 1/2" x 11" paper are preferred,

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context.
  All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

#### 4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

**多维**历人的特别的 健康 现实 100 电管

The second of the company of the

#### 5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- b. Clearly label photographic prints of the resource as viewed from the public right-of-way end of the adjoining proparties, All labels should be placed on the front of photographs.

The state of the s

#### 6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at epproximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

#### ~7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addressas, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

(4)

#### **OWNER AND NEIGHBORS ADDRESSES**

#### <u>Owner</u>

#### **PROPERTY ADRESS**

#### **MAILING ADDRESS**

7063 Carroll Avenue

Bruno Mukendi

12613 Stratford Garden Drive Silver Spring, MD 20904

#### Neighbors

#### **PROPERTY ADDRESS**

#### **MAILING ADRESS**

7071 Carroll Avenue

Sickler Andrew, 5320Ijamsville RD, Ijamsville, MD 21754

7057 Carroll Avenue

Aron Peter

7212 Willow Avenue

Takoma Park, MD 20912-4323

514 Tulip Avenue

Silberman, Lawrence S 14118 Old Columbia Pike Burtonsville, MD 20866-1722



#### MONTGOMERY COUNTY DEPARTMENT OF PARK & PLANNING

### THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

8787 Georgia Avenue Silver Spring, Maryland 20910-3760

September 25, 2001

Mr. Reggie Jetter Department of Permitting Services 255 Rockville Pike - 2nd Floor Rockville, MD 20850

Dear Mr. Jetter:

Mr. Bruno Mukendi, at 7063 Carroll Avenue in Takoma Park will be on the October 24, 2001 agenda for the Historic Preservation Commission. The HPC will be reviewing a proposal for new exterior doors, and for a handicapped ramp at the back of the building, and for additional parking on site.


As the HPC does not review any interior work, we would support a review at this time, without any delay for the HPC review, of any interior work which will a need a permit from DPS.

If I can be of further assistance, please do not hesitate to call me at (301) 563-3408.

Robin D. Ziek


Sincerely yours.

Historic Preservation Planner



VICINITY MAP







9 RMS = APARKILLO SPACES

VYFHUIS & ASSOCIATES
LAND SURVEYORS, ENGINEERS, PLANNERS
3112 RHODE ISLAND AVENUE,NE.

(8)





SIGN TO 13E 71.0" HIGH

# PLAN SITE


AVENUE CARROLL 7063


PARING SPACE PER PER PARING

RMS = 9PARKLING SPACES


ADDITION TO PARK B. F. GILBERT'S TAKOMA

PLAT NO. 2 Maryland County TOT 1, BLK. 10; Montgomery Date: Aug. 17, Ol = 20 Scale".















# HAWP APPLICATION: MAILING ADDRESSES FOR NOTICING [Owner, Owner's Agent, Adjacent and Confronting Property Owners] Owner's mailing address Owner's Agent's mailing address 12613 Stratford Garden & Silver Spring, Mo 2090 C Adjacent and confronting Property Owners mailing addresses Mr. Sickler, Andrew 707/ Carroll Avenue Takoma Park, MD 209/2 7057 Carrell Avenue Takoma Park, MD20912 My ARON, PETER Mr. Siberman, Laurence 514 Tulip Avenue Takoma Park, MD20912 g\addresses\ noticing table

Photography front loss Maries.






EDITEDITATION.


LEFT SIDE 7063 Carroll Avenue




,




Right Side 7063 (arnoll Avenue








.



Back Side 7063 Cernoll Avenue





FRONT SIDE
7063 CARROLL AVENUE