



Surveyor's Certificate

I hereby certify that the plan shown hereon is correct; that it is a survey of Lot 1, Block A, Sligo Park Hills, Section 1 as delineated on a plat recorded among the Land Records of Montgomery County, Maryland in Plat Book 4 as Plat 377.

The improvements shown hereon were located by a transit-tape survey and, except as otherwise shown, there are no visible encroachments.

Property markers have been found or placed where indicated hereon.

The area contained within the bounds of this survey is 8,262 square feet.

December 7, 1971 *James J. Demma*
 James J. Demma
 Professional Land Surveyor, Md. #7695

SCANNED

Plat of Survey
 Lot 1, Block A, Sligo Park Hills
Madeline M. Coumbe Property
 Sligo Avenue ~~Urban Park~~
 Election District 13 ~ Montgomery County, Maryland
 Scale: 1" = 40' November, 1971
Oyster, Imus & Associates, Inc.
 Civil Engineers • Land Planners • Land Surveyors
 2419 Reecie Drive • Wheaton, Maryland • 949-2011

Field
 Draft: *JK*
 Check: *PK*

1G58-C-2

SLIGO AVE. NEIGHBORHOOD PARK

B 112