

#### HISTORIC PRESERVATION COMMISSION

Marc Elrich
County Executive
Chair

Date: 1/28/2025

#### **MEMORANDUM**

TO: Rabbiah Sabbakhan

Department of Permitting Services

FROM: Laura DiPasquale

Historic Preservation Section

Maryland-National Capital Park & Planning Commission

SUBJECT: Historic Area Work Permit #1098121- Partial demolition and construction of new rear addition

The Montgomery County Historic Preservation Commission (HPC) has reviewed the attached application for a Historic Area Work Permit (HAWP). This application was **approved with three (3) conditions** at the January 8, 2025 HPC meeting:

- 1. The 4-inch edge of the concrete and flagstone patio is concealed below grade or clad in flagstone to match the patio surface.
- 2. The applicant submits details of the proposed flagstone material and edge treatment to staff for final approval.
- 3. The applicant provides a replanting plan for two new trees to staff for final approval.

The HPC staff has reviewed and stamped the attached submission materials.

THE BUILDING PERMIT FOR THIS PROJECT SHALL BE ISSUED CONDITIONAL UPON ADHERENCE TO THE ABOVE APPROVED HAWP CONDITIONS AND MAY REQUIRE APPROVAL BY DPS OR ANOTHER LOCAL OFFICE BEFORE WORK CAN BEGIN.

Applicant: Mark & Maureen Shaheen; Chris Lapp, Architect

Address: 3934 Baltimore Street, Kensington

This HAWP approval is subject to the general condition that the applicant will obtain all other applicable Montgomery County or local government agency permits. After the issuance of these permits, the applicant must contact this Historic Preservation Office if any changes to the approved plan are made. Once work is complete, the applicant will contact Laura DiPasquale at 301-495-2167 or <a href="mailto:laura.dipasquale@montgomeryplanning.org">laura.dipasquale@montgomeryplanning.org</a> to schedule a follow-up site visit.





# **APPLICATION FOR** HISTORIC AREA WORK PERMIT HISTORIC PRESERVATION COMMISSION 301.563.3400

DATE ASSIGNED\_\_\_\_

HAWP#\_\_

FOR STAFF ONLY:

#### **APPLICANT:**

Name:		E-	mail:	
Address:				Zip:
Daytime Phone:		Та	x Account No.:	
AGENT/CONTACT (i	if applicable)	<b>):</b>		
Name:		E-	mail:	
Address:		Ci	ty:	Zip:
Daytime Phone:		Co	ontractor Regist	tration No.:
LOCATION OF BUIL	.DING/PREM	ISE: MIHP # of Historic P	roperty	
Is there an Historic I map of the easeme Are other Planning a (Conditional Use, Va supplemental inforn	Preservation/l nt, and docum and/or Hearin riance, Record nation.	Land Trust/Environmentanentation from the Easen g Examiner Approvals /Rd Plat, etc.?) If YES, include	Individual Site I al Easement on nent Holder sup eviews Require de information	the Property? If YES, include a porting this application.  d as part of this Application? on these reviews as
Building Number:		Street:		
Town/City:		Nearest Cross S	treet:	
Lot:	Block:	Subdivision:	Parcel:	
for proposed work be accepted for re  New Construct Addition Demolition Grading/Exca I hereby certify that and accurate and t	k are submitted	ted with this applicationall that apply:  Deck/Porch Fence Hardscape/Landscap Roof  Ithority to make the foregraction will comply with p	n. Incomplete She Sol Tre De Wir Oth Soing applicatio lans reviewed a	ed/Garage/Accessory Structure

Description of Property: Please describe the building and landscape features, or other significant features of the propert	d surrounding environment. Include information on significant structures, ty:
Description of Work Proposed: Please give an overview	of the work to be undertaken:
	APPROVED
REVIEWED	Montgomery County
y Laura DiPasquale at 1:40 pm, Jan 28, 2025	Historic Preservation Commission
	1/ 4/3 0 <del>-</del> 2
	Karen Bulit

Work Item 1:	
Description of Current Condition:  Propose	ed Work:
Work Item 2:	
REVIEWED  By Laura DiPasquale at 1:40 pm, Jan 28, 2025	APPROVED  Montgomery County  Historic Preservation Commission   Kare Walk
Work Item 3:	
Description of Current Condition:  Propose	ed Work:

## **Arborist Report**

### Prepared by:

Name: Rock Creek Tree, Turf & Landscape – John Miller

Certification Number: Maryland LTE #1944 & ISA Certified Arborist MA-7241A

**Date of Inspection:** December 17<sup>th</sup>, 2024

Client Name: Maureen Shaheen

Location: 3934 Baltimore St. Kensington, MD 20895

#### **Introduction:**

• **Purpose of Report:** To assess the condition/health, structure, and risks associated with the two tree(s) on customer's property that may be impacted by upcoming construction at the property.

• **Scope of Work:** This report is based on a visual inspection conducted from the ground and does not include soil testing or internal decay analysis unless otherwise stated.

#### Tree #1 - Sugar Maple:

• **Species:** Sugar Maple

- **Location:** The subject tree is located on the upper left side of the backyard between the driveway and back left corner of home.
- **Dimensions:** The subject tree has a dbh (diameter at breast height) of 21.5 inches.
- Tree Condition/Visible Defects: The tree canopy is in overall fair condition but does have multiple damaged branches and minor dead wood within upper interior of crown. The tree does possess a notable decay pocket at the root flare, girdling roots, and damage on the lower portion of the main stem.
- **Root Zone Condition:** The subject tree has very limited rootzone with the existing asphalt driveway abutting the left side of tree and the existing patio and foundation of home being located only 8 to 9 feet away from the base of tree.
- **Recommendation:** Potential impacts of construction aside, with the subject tree having significant decay at the base of root flare and limited root zone (encompassed by hard surfaces of asphalt driveways, patio, and homes foundation) it is advised the tree pro-actively removed This recommendation is based on the fact that both the customers home and neighbor's property including driveways, all fall within the potential target zone in the event of failure.

### **REVIEWED**

By Laura DiPasquale at 1:55 pm, Jan 28, 2025


#### **APPROVED**

Montgomery County

Historic Preservation Commission

Karen Bulit

<sup>\*</sup>Pictured on following page are photos of the Maple tree:






#### Tree #2 -Multi-Stem Holly Tree:

- **Species:** American Holly
- **Location:** The subject tree is also located on the upper left side of the backyard between the existing asphalt driveway and patio on the back left side of home.
- **Dimensions:** The subject tree has a dbh (diameter at breast height) of 19.5 inches (includes both stems measured individually at breast height)
- **Tree Condition/Visible Defects:** The tree is also in fair condition. No major defects noted with exception of potential for future issues to develop in relation to included bark at union of stems (Which should be monitored).
- Root Zone Condition: The existing site conditions are less than ideal with subject tree having a very limited rooting zone based on its location within the confined landscape bed between existing driveway/patio and foundation of customers home.
- **Recommendation:** Given the existing site conditions already being less than ideal for long-term survival/vitality and the impacts of the proposed construction only further degrading root zone, it is therefore advised that the tree be pro-actively removed. It is also important to note, that the location of the tree in proximity to the existing structure currently requires a significant amount of routine pruning to maintain reasonable clearance for home and roof line furthermore, even with proper pruning notable amounts of tree related debris (leaf, fruit, and twig debris) accumulating on roof surfaces, within gutters, and around homes foundation are an issue.

#### \*Photos of Holly:







**Disclaimer:** This report is based on a visual inspection and represents the arborist's professional opinion. It does not guarantee the absolute safety or survival of the tree(s).

**Rock Creek Tree, Turf & Landscape LLC** 17520 Bowie Mill Rd. Rockville, MD 20855


Licensed Tree Expert #001944 MHIC #106511 ISA MA-5879A 301-580-6023 (Office) www.rockcreektree.com



#### EXISTING SECOND FLOOR PLAN



EXISTING BASEMENT FLOOR PLAN



## **REVIEWED**

By Laura DiPasquale at 1:37 pm, Jan 28, 2025

APPROVED

Montgomery County

Historic Preservation Commission

Kare Warling

EXISTING FIRST FLOOR PLAN

SCALE: 1/8" = 1'-0"

EXISTING FLOOR PLANS



By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**

Montgomery County

**Historic Preservation Commission** 

Kare Bulit

SCALE: 1/8" = 1'-0"

EXISTING FRONT ELEVATION





By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**

**Montgomery County** 

Historic Preservation Commission

Kare Bulit

SCALE: 1/8" = 1'-0"

EXISTING RIGHT ELEVATION

3934 BALTIMORE STREET KENSINGTON, MD 20895





By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**

Montgomery County

**Historic Preservation Commission** 

Kare Bulit

SCALE: 1/8" = 1'-0"

EXISTING REAR ELEVATION







By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**


**Montgomery County** 

**Historic Preservation Commission** 


Karen Bulit

SCALE: 1/8" = 1'-0"

EXISTING LEFT ELEVATION



COPYRIGHT 2024, CLAUDE C. LAPP ARCHITECTS, LLC.




SCALE: 1/8" = 1'-0"

3934 BALTIMORE STREET KENSINGTON, MD 20895 **OUTLINE WITH DIMENSIONS** 

RENDERING ONLY: DIMENSIONS MAY VARY





By Laura DiPasquale at 1:37 pm, Jan 28, 2025

WINDOW	SCHEDU	JLE	
PELLA LIFESTYLE SE	RIES, CLAD-WOOD WINDO	WS	
TYPE	FRAME SIZE	UNIT	QTY
DOUBLE-HUNG	2'-9" x 5'-5"	3365	1
	PELLA LIFESTYLE SE	TYPE FRAME SIZE	PELLA LIFESTYLE SERIES, CLAD-WOOD WINDOWS  TYPE FRAME SIZE UNIT

### **APPROVED**

Montgomery County

**Historic Preservation Commission** 

Kare Bulit

SCALE: 1/8" = 1'-0"

PROPOSED FRONT ELEVATION

3934 BALTIMORE STREET KENSINGTON, MD 20895





DOOR SCHEDULE						
MANUFACTURER:	NUFACTURER: PELLA LIFESTYLE SERIES, CLAD-WOOD DOORS					
LABEL	TYPE	OPENING	UNIT	QTY		
1	SINGLE PATIO	2'-8" x 6'-8"	3280	1		

WINDOW SCHEDULE						
MANUFACTURER: PELLA LIFESTYLE SERIES, CLAD-WOOD WINDOWS						
LABEL	TYPE	FRAME SIZE	UNIT	QTY		
В	CASEMENT	1'-9" x 3'-11"	2147	3		
С	TRANSOM	2'-1" x 1'-2"	2514	4		
D	DOUBLE-HUNG	2'-1" x 4'-11"	2559	4		
Е	TRANSOM	2'-8" x 1'-2"	3214	1		

By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**

**Montgomery County** 


**Historic Preservation Commission** 

Kare Bulit

SCALE: 1/8" = 1'-0"

3934 BALTIMORE STREET KENSINGTON, MD 20895 PROPOSED RIGHT ELEVATION





## 

	WINDOW	SCHED	ULE		
MANUFACTURER: PELLA LIFESTYLE SERIES, CLAD-WOOD WINDOWS					
LABEL	TYPE	FRAME SIZE	UNIT	QTY	
E	TRANSOM	2'-8" x 1'-2"	3214	1	
F	TRANSOM	2'-9" x 1'-2"	3314	6	
G	DOUBLE-HUNG	2"-9" x 5"-11"	3371	6	

### **REVIEWED**

By Laura DiPasquale at 1:37 pm, Jan 28, 2025

### **APPROVED**

**Montgomery County** 

**Historic Preservation Commission** 

Karen Bulit

SCALE: 1/8" = 1'-0"

3934 BALTIMORE STREET

KENSINGTON, MD 20895

PROPOSED REAR ELEVATION





By Laura DiPasquale at 1:37 pm, Jan 28, 2025

DOOR SCHEDULE						
MANUFACTURER:	PELLA LIFESTYLE SERIES, CLAD-WOOD DOORS					
LABEL	TYPE	OPENING	UNIT	QTY		
2	SINGLE PATIO	3'-0" × 6'-8"	3680	1		


	WINDOW	SCHED	ULE	
MANUFACTURER:	PELLA LIFESTYLE S	ERIES, CLAD-WOOD WIND	00WS	
LABEL	TYPE	FRAME SIZE	UNIT	QTY
F	TRANSOM	2'-9" x 1'-2"	3314	1
G	DOUBLE-HUNG	2°-9" x 5'-11"	3371	1
Н	TRANSOM	3'-0" x 1'-11"	3623	4

listoric Preservation Commission

Karen Bulit



OUTDOOR KITCHEN ELEVATION



SCALE: 1/8" = 1'-0"

3934 BALTIMORE STREET KENSINGTON, MD 20895 PROPOSED LEFT ELEVATION











#### **ASPHALT SHINGLE ROOF**


### **METAL ROOF**


### **SIDING**











**WINDOWS AND DOORS** 



