

and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the Montgomery County DPS Field Services Office at 240-777-6210 or online @ permits. emontgomery.org prior to commencement of work and not more than two weeks following completion of work.

Address: 7112 Heple Ave, Takima Park MD 2091-





DPS - #8


# HISTORIC PRESERVATION COMMISSION 301/563-3400

# APPLICATION FOR HISTORIC AREA WORK PERMIT

	Contact Person: TM DOUGLAS
	Daytime Phone No.: 202, 208, 7963
Tax Account No.: 01057785	
Name of Property Owner: Say Smat Dox 4/2	Daytime Phone No.: 202, 208, 7763
Address: 7112 Mzyle Are. Tzkina Pa	
Contractorr:	Phone No.:
Contractor Registration No.:	
Agent for Owner:	Daytime Phone No.:
LOCATION OF BUILDING/PREMISE	
House Number: 7/12 Mark Arc	Street Mayle Are
House Number: 7/12 Most Arc.  Town/City: 12k(nn2 Pek Nearest Cros.  Lot: 25 121 Block: 4 Subdivision: 72k	s Street: Thip
Lot: 25 p. 126 Block: 4 Subdivision: 72kg	ome Pirke
Liber: 13524 Folio: 3/2 Parcel: 13-25	1057785
PART ONE: TYPE OF PERMIT ACTION AND USE	,
	IECK ALL APPLICABLE:
	A/C [] Slab [] Room Addition ☐ Porch ☐ Deck [X]*Shed
	Solar C Fireplace Woodburning Stove Single Family
•	Fence/Wall (complete Section 4) Dther:
tte and	
10. If this is a revision of a previously approved active permit, see Permit #	
To. If this is a revision of a previously approved device permit, one i entire w	ı
PART TWO: COMPLETE FOR NEW CONSTRUCTION AND EXTEND	/ADDITIONS
2A. Type of sewage disposal: 01 ☐ WSSC 02 ☐ Se	otic 03 [ ] Other:
2B. Type of water supply: 01 LJ WSSC 02 [.] Wa	(f) 03 (C) Other:
PART THREE: COMPLETE ONLY FOR FENCE/RETAINING WALL	
3A. Heightfeetinches	
3B. Indicate whether the fence or retaining wall is to be constructed on on	e of the following locations:
① On party line/property line ① Entirely on land of owner	[] On public right of way/easement
	that the application is correct, and that the construction will comply with plans
approved by all agencies listed and I hereby acknowledge and accept this	to be a condition for the issuance of this permit.
	2/20/21
Signature of owner or authorized agent	8/4/U/
Approved:	or Chairperson, Historic Preservation Commission
Disapproved: Signature:	Date:
Application/Permit No.: 257578	ate Filed: 3 30 0 Date Issued:

**SEE REVERSE SIDE FOR INSTRUCTIONS** 

Edit 2/4/98



Date: 7. 10. 95

Scale: 1" = 40'

Plat Book: A

Plat No.: 3

Work Order: 95-1527





Meridian Surveys, Inc. 2401 Research Boulevard Rockville, MD 20850 (301) 840-0025 Address: 7/12 MAPLE AVENUE


District: 13


Jurisdiction: May Toppy EPY COUNTY, MP.


NO TITLE REPORT FURNISHED















5 of 5

SUMMERWOOD e-mail: design@summerwood.com www.summerwood.com


### **Representative Pictures of Structure Features**




General view of style




Double door




Single Door and Single Window





**Double Window** 



APPROVED

Montgomery County

Historic Preseryation Commission

#### HISTORIC PRESERVATION COMMISSION STAFF REPORT

Address:

7112 Maple Avenue

Meeting Date:

9/24/01

Applicant:

Jim and Janet Douglass

Report Date:

9/17/01

Resource:

Takoma Park Historic District

Public Notice:

9/10/01

Review:

HAWP

Tax Credit:

No

District Number:

37/3-01GG

Staff:

Robin D. Ziek

PROPOSAL:

Demolish existing garage. Construct new garden shed.

RECOMMEND: Approval

#### PROJECT DESCRIPTION

RESOURCE: Contributing Resource in Takoma Park Historic District

STYLE: Four Square-Gabled

DATE: c 1900-1920

The 2-1/2 story frame house has a wrap-around porch. The garage sits in the rear NW corner of the property. The garage appears to have originally been a 2-car concrete block structure, with stone-faced quoins. At some point, the roof of this structure must have collapsed, and a small 1-car structure was built using two walls of the original structure (see Circle /6, 17 ). The remaining walls of the original structure were retained as a storage enclosure.

#### **PROPOSAL**

The applicant proposes demolish the concrete garage and enclosure at the rear of the property. The area would be cleared, and a new garden shed would be built in approximately the same vicinity (see Circle 7,8). The County's setbacks have changed since the old garage was built, and the new structure would be set 8' from the property lines. The building would measure 18' x 12' (see Circle 9-15).

#### STAFF DISCUSSION

The original garage is essentially in ruins. Restoration of this structure would actually amount to a reconstruction because of the loss of integrity. The proposed new garden shed is of an appropriate scale, massing and uses appropriate materials for the district.

#### **STAFF RECOMMENDATION**

Staff recommends that the Commission find this proposal consistent with the purposes of Chapter 24A-8(b)2:

The proposal is compatible in character and nature with the historical, archeological, architectural or cultural features of the historic site, or the historic district in which an historic resource is located and would not be detrimental thereto or to the achievement of the purposes of this chapter;

and with Secretary of the Interior's Standards for Rehabilitation #2:

The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

and subject to the general condition that, after issuance of the Montgomery County Department of Permitting Services (DPS) permit, the applicant arrange for a field inspection by calling the DPS Field Services Office at (301) 217-6240 prior to commencement of work and not more than two weeks following completion of work.





# HISTORIC PRESERVATION COMMISSION 301/563-3400

# APPLICATION FOR HISTORIC AREA WORK PERMIT

			Contact Person:	III DOUGE	15
			Daytime Phone No.:	202, 208,	7963
Tax Account No.: 0/05 77	85		_		,
Name of Property Owner:	Inst Douglas		Daytime Phone No.:	202, 208.7	963
Address: 7112 Mzyle Are Street Number	Tekoma	PLK	M Staet	>	209/2_ Zin Code
Contractorr:			Phone No.:		<b>,</b>
Contractor Registration No.:					
Agent for Owner:			Daytime Phone No.:		
LOCATION OF BUILDING/PREMISE					
	E dec	Street:	Mode he		
Town/City: Tak ima Pak	Neare:	st Cross Street:	THIS		
House Number: 7/12 Mags Town/City: T2k Can 2 Pake Lot: 25 pal 26 Block: 4	Subdivision	Zkomz P	ide	NAME OF TAXABLE PARTY.	
Liber: 13524 Folio: 3/2	- Parcel: /3	-25-1057	 7785		
PART ONE: TYPE OF PERMIT ACTIO	N AND USE	CHECK ALL AD	DI LOADI E		
1A. CHECK ALL APPLICABLE:	LAN Ø	CHECK ALL AP		· · · · · · · · · · · · · · · · · · ·	Commence Arthur
	Alter/Renovate			Addition	
•	Wreck/Raze			urning Stove	•
•	Revocable			Dther:	
1B. Construction cost estimate: \$	,				
1C. If this is a revision of a previously app	roved active permit, see Per	mit #			
PART TWO: COMPLETE FOR NEW C	ONSTRUCTION AND EXT	END/AODITION	<u>s</u>		
2A. Type of sewage disposal: 01	□ WSSC 02 [	☐ Septic	03 🗍 Other:		
2B. Type of water supply: 01	□ WSSC 02 [	☐ Well	03 🗆 Other:		
PART THREE: COMPLETE ONLY FOR	FENCE/RETAINING WAL	<u>.                                    </u>			
3A. Heightfeet	inches				
3B. Indicate whether the fence or retain	ing wall is to be constructed	on one of the follo	wing locations:		
On party line/property line	Entirely on land of o	wner	On public right of	way/easement	
I hereby certify that I have the authority t approved by all agencies listed and I her					ill comply with plans
M				8/3/0/	
Signature of owner of	authorized agent			/ <b>Y</b> * Dat	le
Approved:		For Chairners	on, Historic Preservati	on Commission	
Disapproved:	Signature:	o. ommpers	Thorong Frederikati	Date:	•
Application/Permit No.: 257	578	Date Filed:	8 30/01	Date Issued:	

**SEE REVERSE SIDE FOR INSTRUCTIONS** 

3

Richard and Laurie O'Connor 7110 Maple Ave. Takoma Park MD 20192

Robert and Ellen Ginsburg 7129 Maple Ave. Takoma Park MD 20191

Steven Hoggard & Daphna Rubin 7109 Cedar Ave. Takoma Park MD 20192

Blair Brown & Susan Gerone 7107 Cedar Ave. Takoma Park MD 20192

## **Application for Historic Area Work Permit**

Jim & Janet Douglas 7112 Maple Ave. Takoma Park MD 20912

#### 1. Written Description of Project

#### A. Removal of old shed/garage.

Structure to be removed sits at the rear of the subject property on the corner of the rear (West) and side (North) property lines. See attached site plans and Photos #1 and #2. This structure is a 20X20 foot structure of three concrete block walls (the fourth wall is a combination of wood doors and an open area) sitting on a slab. See Photos generally. Exact age of structure is unknown, but presumably it was constructed contemporaneously with the house (estimated date of construction: 1910). Aside from the block walls the structure appears to be constructed of scrap wood. The front gable is pieced together pieces of plywood, the middle wall includes an old door (non-functional), and the roof and joists are miscellaneous dimensions. One hypothesis is that at one time the roof spanned the full structure.

Condition of structure is extremely poor. The block walls are lifted and cracked (presumably by the immediately adjacent tree). See Photos #6-11. The roof is in extremely poor condition, with several leaks (bicycles and other items have to be protected with tarps). The front double doors are coming off their hinges and no long shut. At this time the structure provides no security for garden and recreation items stored there and minimal protection from the elements. Plexiglas was added to the door and north side window openings by the current owners to provide a modicum of physical and weather protection.

The structure is barely visible from the street in either summer or winter. See Photos #3 and #4. However, the structure sits immediately adjacent to rear of properties at 7116 Maple and 7109 Cedar and would be reasonably called an eyesore to both of those properties.

Repair/renovation of the structure is not feasible. The broken slab and block walls cannot be repaired and the continued growth of the tree will further damage the walls and slab. Furthermore, the structure adversely affects the critical root zone of the tree.

#### B. Replacement Structure

Owners propose to replace the shed with a new a 12X18 foot wooden shed sitting approximately 8 feet from rear and side property lines. See attached site plans.

This structure will be sided with rough cut cedar and have a double door facing the house (as the current structure does). The peaked roof matches that of the house and surrounding houses. Asphalt shingles to match house (as nearly as possible) will be used.

The structure is a partially prefabricated kit. Drawings are attached, as are representative pictures of the general style and features. A hand-drawn sketch of the structure is also attached.

Overall this structure is designed to blend tastefully with the surrounding area, to be unintrusive in the rear of the property, and to provide physical and weather security.

Construction will take place within the critical root zone of a majestic white oak tree (visible in several of the attached photos). A permit to work within the critical root zone of the tree is pending with the City of Takoma Park.

#### 2. Site Plans

See attached.

#### 3. Plans and Elevations

Two copies of plans and elevations are attached.

#### 4. Materials Specifications

Exterior siding will be rough-cut cedar and will remain unpainted.

#### 5. Photographs

Several photographs of the current structure, including view from Maple Ave., are included and referenced in description of project above.


Representative pictures of the type of structure (showing siding, doors, windows) are attached.

#### 6. Tree Survey

The attached site plans show the location of a mature white oak, under which the structure will sit.

#### 7. Names and Addresses of Adjacent and Confronting Property Owners

Roland and Marguita Halstead 7116 Maple Ave. Takoma Park MD 20912



COCATION DRAWING

MAPLE AVENUE

LOT 25 AND PART OF LOT 26 BLOCK A

#### Surveyor's Certification

I hereby certify that the survey shown hereon is correct to the best of my knowledge and that, unless noted otherwise, it has been prepared utilizing description of record. This survey is not a boundary survey and the location or existence of property corners is neither guaranteed nor implied. Fence lines, if shown, are approximate in location. This property does not lie within a 100 year flood plain according to FEMA insurance maps unless otherwise shown hereon. Building restriction lines shown as per available information.

Stephen J. Wenthold, Maryland RLS Reg. No. 10767

NOTE: This plat is of benefit to a consumer only insofar as it is required by a lender or a title Insurance company or its agent in connection with contemplated transfer, financing or refinancing. This plat is not to be relied upon for the establishment or location of fences, garages, buildings, or other existing or future Improvements. This plat does not provide for the accurate identification of property boundary lines, but such identification may not be required for the transfer of title or securing financing or refinancing.

Date: 7.10.95
Scale: /" = 40'
Plat Book:
Plat No.:
Work Order: 95-1527


MS
----

Meridian Surveys, Inc. 2401 Research Boulevard Rockville. MD 20850 (301) 840-0025


Address: 7112	MAPLE AVE	ENUE
District:		
Jurisdiction: Moss	TOOMERY C	OUNTY, MP.

NO TITLE REPORT FURNISHED











L-1+2

Left & Right Side Elevations. N.T.S.

Mr.	Jim	Douglas
7112	Manl	e Avenue

7112 Maple Avenue Takoma Park, MD 20912, USA

DATE	August 1st, 2001	
SCALE	S.E.D.	
NWARC	N.T.S. ( Not To Scale. )	
SHEET	2 of 5	
	3 01 3	

Custom Cabana 12' 0" x 18' 0"





#### Summerwood Products Inc.

733 Progress Avenue Toronto, ON. M1H 2W7 416.498.9379 Fax 416.498.2454

SUMMERWOOD e-mail: dssign@summerwood.com


U.	ME VISIONS/NOTES
	I
-	











Front Elevation.

N.T.S.

Mr. Jim Douglas 7112 Maple Avenue Takoma Park, MD 20912, USA


DATE	August 1st, 2001	
SCALE	5.E.D.	
DRAWN	N.T.S. ( Not To Scale	:_)
SHEET	2 of 5	

Custom Cabana 12'0" x 18'0"



#### Summerwood Products Inc.

733 Progress Avenue Toronto, ON. M1H 2W7 416.498.9379 Fax 416.498.2454



Mr. Jim Douglas

7112 Maple Avenue Takoma Park, MD 20912, USA

UATE	August 18t 2001	
SCALE	S D.	
DZAWN	N.T.S. ( Not To Scale. )	
SHEET	5 of 5	
	- v <sub>J</sub> -	

12' 0" x 18' 0" Floor Plan




Summerwood Products Inc. 733 Progress Avenue Toronto, ON, M1H 2W7 416,498,9379 Fax 416,498,2454

	-		
Ĺ			


### **Representative Pictures of Structure Features**




General view of style




Double door



Single Door and Single Window





**Double Window** 

- Astalsast ass (send most ass sa) ,8 LOIL report Wat

**Photo #1:** View from middle of backyard, winter; 7109 Cedar in background.



**Photo #2:** Aerial view from 3<sup>rd</sup> floor of house






Photo #3: View from street, winter.



**Photo #4:** View from top of drive (near garbage cans in Photo #3), summer.



Photo #5: Front of structure; maximum closure of doors due to warped frame, support



**Photo #6:** Detail of old window in left (south) wall in Photo #5



**Photo #7:** Aerial view looking North, showing open/covered areas and broken wall above south window.



**Photo #9:** North wall (facing 7116 Maple), showing broken wall above and below north window.



Photo #11: Rear (west) wall facing 7109 Cedar showing broken wall (lower middle of picture).



**Photo #8:** North wall (facing 7116 Maple), showing broken wall above north window.



**Photo #10:** View from southwest (7109 Cedar) showing broken wall above south window and broken wall on west wall (south side).





Photo #12: Interior of covered portion, looking at window on south side. Light above window is from holes in roof. Column to right of blue tarp necessary to support roof.



**Photo #14:** Interior roof; light showing in middle of photo is holes in roof




Photo #13: Rear wall showing crack



Robin

7129 Maple Ave. Takoma Park, MD 20912-4418

17 September 2001

Montgomery County Historic Preservation Commission c/o The Maryland-National Capital Park and Planning Commission c/o Montgomery County Department of Park & Planning 8787 Georgia Ave. Silver Spring, MD 20910-3760

Re: HPC Case No. 37/3-01GG

Dear Historic Preservation Commission:

We are writing in favor of the application for an Historic Area Work Permit (HAWP) for garage demolition and shed construction at 7112 Maple Ave., Takoma Park, MD 20912.

Our residential property at 7129 Maple is directly across the street from the property in question. Every day, for 29 years, we have had to see the dilapidated garage at 7112 Maple.

That decaying structure has not been used as a garage for all these decades. It has no aesthetic, historic, or utilitarian value. It is a blot on the Historic District.

The proposal of the present owners, Jim and Janet Douglass, to demolish the old structure and construct a shed are excellent. The result will be of positive value to this section of the Takoma Park Historic District. Please grant their request for a HAWP.

Sincerely,

Robert Ginsberg & Dr. Ellen S. Ginsberg